

JBS&G 63888 | 159,727

L070 Hazardous Materials Advice, REF6, RPA Hospital Rev A

11 June 2024

Zach Foster CPB Contractors Via email: Zach.Foster@cpbcon.com.au

Hazardous Materials Summary and Advice – REF6, Royal Prince Alfred Hospital Redevelopment, Camperdown, NSW

Dear Zach,

1. Introduction

JBS&G Australia Pty Ltd (JBS&G) was engaged by CPB Contractors (CPB, the client) to provide hazardous materials advice in relation to the proposed construction works to Level 6 of Building 89, identified as 'REF6', as part of the broader Royal Prince Alfred (RPA) Hospital Redevelopment, Camperdown, NSW (the site).

JBS&G completed a hazardous building materials survey (HBMS) of the broader RPA Hospital redevelopment site in August 2023 (JBS&G 2023¹) which is included as **Attachment C**. The client has requested this hazardous materials advice specific to the proposed REF6 redevelopment area, based on the findings in JBS&G 2023. It is noted that since the production of JBS&G 2023, there have been no changes to legislation, codes of practice and other guidance documents in relation to the identification, management and removal of hazardous building materials.

The proposed REF6 redevelopment works will comprise the following:

- Removal of the existing Level 6 Mechanical Plant with make good works;
- Penetration for new services within the plant room;
- Building interface works to the existing adjacent campus buildings where impacted;
- Construction of new structure for lightweight steel roof, gutter, fascia works and associated aluminium walkway systems;
- Construction of new façade enclosure to plant room with a steel frame and metal stud framing;
- New façade system with the inclusion of a Solid Aluminium Cassette Cladding and Acoustic louvres; and
- New construction of fire rated walls.

Plans of the proposed REF6 redevelopment works, specific to this hazardous materials advice, are included as **Attachment B**.

¹ Hazardous Building Materials Survey, Main Works Package, Royal Prince Alfred Hospital Redevelopment, Missenden Road, Camperdown, NSW. JBS&G Australia Pty Ltd, Ref: 63888/153,198 Rev A, 16 August 2023 (JBS&G 2023)





2. Hazardous Materials Status

With reference to JBS&G 2023, a summary of the hazardous materials identified within the Level 6 redevelopment area is as follows:

- Non-asbestos containing fibre cement sheeting (L6-A07) was identified to the external wall cladding to the B63 plant room.
- Non-asbestos containing fibre cement sheet debris (L6-A08) was identified within the gutters to the roof.
- Non-asbestos containing felt membrane (L6-A09) was identified to the flat roof sections underlying the surface pebble layer.
- Non-asbestos containing putty sealant (L6-A10) was identified to the external timber windows to Building 63, accessed from the flat roof area.
- Lead based orange paint (L6-L02, 3.3% w/w) was identified to the vent pipes to the external aspect of Building 63, accessed from the flat roof area.
- Non-lead based brown paint (L6-L03, <0.01% w/w) was identified to the external vent grill to the Building 63 plant room.
- A number of hot water systems were located on the roof and are assumed to contain internal synthetic mineral fibre (SMF) insulation.
- Metal cased pipework associated with the air conditioning units was located on the roof and is assumed to contain internal SMF insulation lagging.
- Fluorescent light fittings were identified to the external roof area and are suspected to contain PCB capacitors.

3. Conclusions

Based on the findings of JBS&G 2023, specific to the proposed REF6 development area, and with reference to the **Limitations** included as **Attachment A**, JBS&G conclude the following:

- No asbestos containing materials were identified at the time of JBS&G 2023;
- Lead based paints and assumed SMF insulation materials were identified at the time of JBS&G 2023 and must be appropriately managed and/or removed in accordance with AS4361.2-2017² and NOHSC:2006(1990)³; and
- Assumed PCB containing capacitors were identified within fluorescent light fittings at the time of JBS&G 2023 and must be appropriately handled and removed in accordance with ANZECC 1997⁴.

Should any additional suspected hazardous materials be observed during or prior to demolition works, works should cease until a suitably qualified occupational hygienist can assess the suspected hazardous material and provide appropriate recommendations for management and/or removal.

² Australian Standard 4361.2 (2017) Guide to Hazardous Paint Management - Part 2: Lead Paint in Residential, Public and Commercial Buildings (AS4361.2-2017)

³ National Occupational Health and Safety Commission's National Code of Practice for the Safe Use of Synthetic Mineral Fibres, [NOHSC:2006(1990)]

⁴ Australian and New Zealand Environment Conservation Council's Identification of PCB containing Capacitors: An information booklet for Electricians and Electrical Contractors, (ANZECC 1997)



Should you require clarification, please contact the undersigned on 02 8245 0300 or by email slumsden@jbsg.com.au.

Yours sincerely:

l

Stuart Lumsden Senior OHM Consultant JBS&G Australia Pty Ltd

Attachments:

- A) Limitations
- B) Client Provided Plans
- C) Hazardous Building Materials Survey JBS&G 2023

Reviewed/Approved by:

Michael Samuel Principal JBS&G Australia Pty Ltd



Attachment A Limitations

This report has been prepared for use by the client who has commissioned the works in accordance with the project brief only, and has been based in part on information obtained from the client and other parties. The report has been prepared specifically for the client for the purposes of the commission, and no warranties, express or implied, are offered to any third parties and no liability will be accepted for use or interpretation of this report by any third party.

The advice herein relates only to this project and all results conclusions and recommendations made should be reviewed by a competent person with experience in environmental investigations, before being used for any other purpose. This report should not be amended in any way without prior approval by JBS&G, or reproduced other than in full including all attachments as originally provided to the client by JBS&G.

Sampling and chemical analysis of environmental media is based on appropriate guidance documents made and approved by the relevant regulatory authorities. Conclusions arising from the review and assessment of environmental data are based on the sampling and analysis considered appropriate based on the regulatory requirements or agreed scope of work.

Limited sampling and laboratory analyses were undertaken as part of the investigations undertaken, as described herein. Conditions between sampling locations and media may vary, and this should be considered when extrapolating between sampling points. Chemical analytes are based on the information detailed in the site history. Further chemicals or categories of chemicals may exist at the site, which were not identified in the site history and which may not be expected at the site.

Changes to the conditions may occur subsequent to the investigations described herein, through natural processes or through the intentional or accidental addition of contaminants. The conclusions and recommendations reached in this report are based on the information obtained at the time of the investigations.

This report does not provide a complete assessment of the environmental status of the site, and it is limited to the scope defined herein. Should information become available regarding conditions at the site including previously unknown sources of contamination, JBS&G reserves the right to review the report in the context of the additional information.



Attachment B Client Provided Plans







P01 - EXISTING PHOTO 1





EXISTING PHOTO

P02 - EXISTING PHOTO 2





P03 - EXISTING PHOTO 3



DRAWN	DESIGN
CC	CC
CHECKED	APPRO
RG/CY	CY
SCALE @ B1 As indicated	
DRAWING NO.	
RPA-ARC-JAC-DRG-E	W3-7031



Attachment C Hazardous Building Materials Survey – JBS&G 2023



CPB Contractors Pty Ltd Hazardous Building Materials Survey

Main Works Package, Royal Prince Alfred Hospital Redevelopment Missenden Road, Camperdown, NSW

> 16 August 2023 63888/153,198 (Rev A) JBS&G Australia Pty Ltd

CPB Contractors Pty Ltd

Hazardous Building Materials Survey

Main Works Package, Royal Prince Alfred Hospital Redevelopment Missenden Road, Camperdown, NSW

> 16 August 2023 63888/153,198 (Rev A) JBS&G Australia Pty Ltd



Table of Contents

Abbr	eviatio	ons		v
1.	Intro	duction		1
	1.1	Backgro	und	1
	1.2	Objectiv	'es	2
	1.3	Hazardo	ous Materials Survey Limitations	3
	1.4	Previous	s Hazardous Material Assessments	4
2.	Meth	nodology .		5
	2.1	Hazardo	ous Materials	5
		2.1.1	Asbestos Containing Materials and Asbestos Containing Dust	5
		2.1.2	Lead Based Paint	5
		2.1.3	Lead Containing Dust	5
		2.1.4	Polychlorinated Biphenyls	5
		2.1.5	Synthetic Mineral Fibres	6
	2.2	Inaccess	ible Areas	6
3.	Site [Descriptio	n	7
	3.1	Main Ho	ospital Building (B63, B64, B75, B77 and B89)	8
		3.1.1	Level 1	8
		3.1.2	Level 2	9
		3.1.3	Level 3	9
		3.1.4	Level 4	10
		3.1.5	Level 5	13
		3.1.6	Level 6	15
		3.1.7	Level 7	18
	3.2	Gate Ho	use Building	19
4.	Resu	lts		20
Ξ.	4.1	Hazardo	us Materials	20
		4.1.1	Asbestos Containing Materials	20
		4.1.2	Asbestos Containing Dust	24
		4.1.3	Lead Containing Dust	24
		4.1.4	Lead Based Paints	25
		4.1.5	Polychlorinated Biphenyls	26
		4.1.6	Synthetic Mineral Fibres	26
	4.2	Inaccess	ible Areas	26
5.	Conc	lusions an	nd Recommendations	28
	5.1	Hazardo	bus Materials	28
		5.1.1	Asbestos Containing Materials	28



		5.1.2	Lead Containing Dust	.28
		5.1.3	Lead Based Paints	.29
		5.1.4	Polychlorinated Biphenyls	.29
		5.1.5	Synthetic Mineral Fibres	.29
	5.2	Inaccess	ible Areas	.29
	5.3	Unexpec	ted Finds	.29
6.	Limita	ations		.30

List of Tables

Table 4.1: Asbestos Results Summary Table	20
Table 4.2: Asbestos Dust Results Summary Table	24
Table 4.3: Lead Dust Results Summary Table	24
Table 4.4: Lead Paint Results Summary Table	25

List of Figures

Figure 1	Site Location
Figure 2	Site Layout

Appendices

Appendix A	Hazardous Materials Register
Appendix B	Photographs
Appendix C	Laboratory Analysis Reports and Chain of Custody Documentation
Appendix D	Client Provided Floor Plans



Abbreviations

Term	Definition
AC	Asbestos Cement
ACM	Asbestos Containing Material
ACD	Asbestos Containing Dust
ANZECC	Australian and New Zealand Environment Conservation Council
AMP	Asbestos Management Plan
COC	Chain of Custody
NSW EPA	New South Wales Environmental Protection Authority
FA	Friable Asbestos
HIL	Health Investigation Levels
HSL	Health Screening Levels
JBS&G	JBS&G Australia Pty Ltd
LAA	Licenced Asbestos Assessor
LCD	Lead Containing Dust
LOR	Limit of Reporting
LP	Lead Paint
NATA	National Association of Testing Authorities, Australia
NEPC	National Environmental Protection Council
NEPM	National Environmental Protection Measure
РСВ	Polychlorinated Biphenyls
PPE	Personal Protective Equipment
SMF	Synthetic Mineral Fibre
SWNSW	SafeWork New South Wales
WHS (WH&S)	Workplace Health and Safety



1. Introduction

1.1 Background

JBS&G Australia Pty Ltd (JBS&G) was engaged by CPB Contractors Pty Ltd (CPB, the client) to undertake a hazardous building materials survey (HBMS) of the structures associated with the Main Works Package of the Royal Prince Alfred (RPA) Hospital Redevelopment, located at RPA Hospital, Missenden Road, Camperdown, NSW (the site). The site location and layout are shown on **Figure 1** and **Figure 2** respectively.

It is understood that the Main Works Package comprises predominantly internal refurbishments to the internal areas of the Main Hospital Building and demolition of selected areas. These areas are shown on client provided figures included as **Appendix D**.

At the request of the client, the HBMS was restricted to the highlighted areas only (**Appendix D**) and are identified as follows:

- Main Hospital Building comprising Building 63 (B63), Building 64 (B64), Building 75 (B75), Building 77 (B77) and Building 89 (B89) across the following areas:
 - Level 1 undercroft areas and fire pump room;
 - Level 2 north lift foyer, toilets, offices, car park storerooms, fire control room, northern portion of Medical Training and Administration Unit (MTAU), and external façade;
 - Level 3 Birthing Centre, north lift and entry foyer, Delivery Unit, Neonatal Intensive Care Unit (NICU), Intensive Care Unit (ICU), ICU offices/administration, atrium and external façade;
 - Level 4 Staff Gymnasium, storerooms, Clinical Education Centre, various plant rooms, north lift foyer and stairs, Medical Records, Digital Health and Innovation, Radiology offices, Department of Anaesthetics, Café balcony and façade;
 - Level 5 Emergency Department, Radiology, main corridors and lift foyers, Women's and Children's Ambulatory Care, Women's and Children's Health Administration, Anti and Post Natal Wards, and Laboratory;
 - Level 6 Nuclear Medicine, plant rooms, external roof, Cardiac Catheter Laboratory, Coronary Care Unit (CCU), north lift foyer and corridors, Cardiology Ward, Cardiothoracic/Vascular Ward, Renal Ward;
 - Level 7 Nuclear Medicine, external roof, and plant rooms.
- Gate House Building located adjacent the Main Hospital Building on the corner of Missenden Road and Lambie Dew Drive.

A number of previous asbestos and hazardous materials assessments have been undertaken at the site. The most recent investigation reports were completed by Environmental Monitoring Services Pty Ltd (EMS) in September 2020 and Sydney Environmental Group Pty Ltd (SEG) in August 2022. The EMS and SEG reports were provided to JBS&G prior to undertaking this HBMS (refer **Section 1.4**)

Based on the review of the EMS and SEG reports, a number of data gaps were identified including the assessment of asbestos only in the EMS reports, in addition to inaccessible areas, height access restrictions and assumptions made about the composition of materials in all previous EMS and SEG reports. Additionally, it is noted that the previous assessments were non-destructive inspections while the site was still operational and did not include any destructive sampling methods.



This HBMS was requested to re-assess the data gaps identified in the previous hazardous materials assessments and undertake a destructive HBMS (where possible) of the buildings to assist with the refurbishment phase of the proposed site redevelopment works.

The structures were inspected for the following hazardous materials during the HBMS:

- Asbestos containing materials (ACMs);
- Asbestos containing dust (ACD);
- Lead based paints (LP);
- Lead containing dust (LCD);
- Synthetic mineral fibres (SMF); and
- Polychlorinated biphenyls (PCB).

Due to the occupied/operational nature of the buildings, a fully destructive HBMS could not be completed. A range of sampling and investigation techniques were implemented to gain as much information as possible, whilst not creating or posing a potential risk to site staff and future occupants as a result of the intrusive sampling during the HBMS works.

This advice presents the outcomes of the inspection of the proposed demolition and redevelopment areas undertaken by JBS&G personnel and provides recommendations on requirements for the management and/or removal of identified hazardous materials in accordance with regulations and guidance in force at the time of the inspection.

This report should be read in its entirety including all associated attachments, including the Limitations provided in **Section 1.3** and **Section 6**.

1.2 Objectives

The objective of the HBMS was to determine the presence, quantity and condition of any hazardous materials within the buildings prior to proposed demolition and/or refurbishment works.

The HBMS and production of this report have been undertaken in accordance with the requirements of:

- Work Health and Safety Act (2011);
- Work Health and Safety Regulation (2017);
- How to Safely Remove Asbestos Code of Practice, SafeWork NSW, (2022) (SWNSW 2022a);
- *How to Manage and Control Asbestos in the Workplace Code of Practice*, SafeWork NSW (2022) (SWNSW 2022b);
- Australian Standard 4361.2 (1998) *Guide to Lead Paint Management Part 2: Residential and Commercial Buildings* (AS4361.2-1998);
- Australian Standard 4361.2 (2017) *Guide to Hazardous Paint Management Part 2: Lead Paint in Residential, Public and Commercial Buildings* (AS4361.2-2017);
- National Occupational Health and Safety Commission's *National Standard for Synthetic Mineral Fibres* [NOHSC:1004(1990)];
- National Occupational Health and Safety Commission's *National Code of Practice for the Safe Use of Synthetic Mineral Fibres*, [NOHSC:2006(1990)];
- Australian and New Zealand Environment Conservation Council's *Identification of PCB-containing Capacitors: An information booklet for Electricians and Electrical Contractors*, (ANZECC 1997); and



• NSW EPA Waste Classification Guidelines Part 1: Classifying Waste (NSW EPA 2014).

1.3 Hazardous Materials Survey Limitations

Whilst all reasonable care has been taken by JBS&G during the completed HBMS, this report is limited due to:

- Only safely accessible areas of the site were surveyed.
- Access restrictions to operational areas such as energised services, gas, air conditioning/heating, pressurised vessels, chemical lines etc.
- Potential materials located in areas in which they could not reasonably be envisaged or anticipated.
- Limited access to internal building components e.g., set floor, walls, ceiling cavities etc., in which case only representative areas were inspected with the hand tools available to the JBS&G consultants for destructive investigation.
- Access restrictions to areas above 3 metres or any area deemed inaccessible without the use of specialised equipment.
- Access to restrictions to areas of structures where the structural integrity for the floor and/or ceiling has been compromised.
- Service pits, confined spaces, voids, cavities within the building structure and internal areas of plant and equipment that could not be safely accessed.

It should be noted that buildings built between the 1930s - 1980s may have general occurrences of ACMs in areas which are not readily accessible with the hand tools available for the survey. These areas and materials include, inter alia:

- Fibre Cement Sheeting (FCS) used as packing to bearers and joists in the underfloor void or as boxing/shuttering to concrete formwork;
- FCS packing between window/door frames and timber studs; and
- Compressed FCS underneath tiled floor areas.

Whilst all care is taken by the consultants to uncover hidden materials, not all areas can be accessed within the allowable timeframe without more industrial (power) tools. As such, only minor destructive sampling techniques were employed to gain access. Consequently, without substantial demolition of the building, it is not possible to guarantee that every source of hazardous material has been detected. JBS&G recommends that areas inaccessible during the survey be inspected as the demolition progresses. If suspected hazardous materials are observed, confirm the presence or absence of hazardous materials through laboratory testing.

In the event suspected hazardous materials are identified during strip out or demolition which are not included in this report, JBS&G recommends that works should cease and an assessment of the materials undertaken by a competent person for further appropriate recommendations.

No one section or part of a section of this report is to be taken as giving an overall idea of this report. Each section is to be read in conjunction with the whole of this report, including the appendices and attachments.



1.4 Previous Hazardous Material Assessments

A number of previous hazardous materials assessments have been completed at the site, however, full access was not available to all structures during these previous investigations. The findings of the previously completed investigations at the site are detailed in the following documents:

- Hazardous Building Materials Survey Building 63, Albert Pavilion (A Block), RPA Hospital, Camperdown NSW (SEG 2022a) Reference Number: 1284-HBMS-08-100822.v1f;
- Hazardous Building Materials Survey Building 64, Administration Building, RPA Hospital, Camperdown NSW (SEG 2022b) Reference Number: 1284-HBMS-07-260722.v1f;
- Hazardous Building Materials Survey Portion Building 75 and 89 Main Hospital and Clinical Services, RPA Hospital, Camperdown NSW (SEG 2022c) Reference Number: 1284-HBMS-11-130922.v1f; and
- Asbestos Register Building 63 Albert Pavilion, RPA Hospital, Camperdown NSW (EMS 2020) Report Number EMS20 8044.

The findings of the reports listed above have been incorporated into this report where relevant.



2. Methodology

2.1 Hazardous Materials

2.1.1 Asbestos Containing Materials and Asbestos Containing Dust

Representative samples of suspected ACMs and ACDs were collected where possible and placed into a zip-lock bags. These were subsequently delivered to a NATA accredited laboratory for analysis using polarised light microscopy in conjunction with dispersion staining techniques. Similar materials to those analysed or other materials known to contain asbestos from the consultant's experience (e.g. Electrical backing boards, corrugated asbestos cement roofs and older fibre cement sheeting) or materials not accessible may also be assumed to contain asbestos as per the relevant Code of Practice.

At the time of inspection, the following details were recorded:

- Location;
- Type of material;
- Accessibility;
- Condition;
- Friability; and
- Volume/dimensions.

2.1.2 Lead Based Paint

Australian Standard AS4361.2 (2017) *Guide to Hazardous Paint Management - Part 2: Lead Paint in Residential, Public and Commercial Buildings* defines lead paints as those in which the lead content (calculated as lead metal) is in excess of 0.1 percent by weight of the dry film. This can be determined by field spot tests, laboratory testing or the use of portable X-ray fluorescence (XRF) field tests.

JBS&G utilises XRF technology as a screening tool for the identification of lead based paints in the field. Any detection of lead (i.e. greater than 0.05 mg/cm²) was adopted for the assessment of lead based paints for this investigation with representative samples collected where possible and delivered to a NATA accredited laboratory for analysis using inductively coupled plasma optical emission spectrometry (ICP-OES).

2.1.3 Lead Containing Dust

Representative samples of accumulated or settled dust were collected and delivered to a NATA accredited laboratory for analysis via ICP-MS. A conservative assessment criteria was adopted for this investigation given the potential for human exposure and the readily disturbed and uncontained nature of accumulated or settled dust.

Concentrations of lead within accumulated or settled dust were compared against the health investigation level (HIL) for commercial/industrial sites of 1,500 mg/kg as outlined in National Environment Protection Measure (NEPC 2013) guidelines.

2.1.4 Polychlorinated Biphenyls

Old fluorescent light fittings and other appliances which may contain capacitors containing PCB dielectric oil are identified by inspection and evaluation with the consultant's experience of similar light fittings and appliances. Alternatively, where possible and when it was safe to do so, a representative light fitting was opened to reveal the capacitor and the make and model recorded to be compared against the ANZECC (1997) list of PCB containing capacitors.



2.1.5 Synthetic Mineral Fibres

SMF containing materials were either sampled as per the asbestos methodology or assumed to contain SMF from the consultant's experience of similar materials.

2.2 Inaccessible Areas

As per SWNSW 2022b, any areas not accessible must be recorded as such. Where hazardous materials are suspected to be contained within inaccessible areas, these shall be documented in this report and the associated Hazardous Materials Register (**Appendix A**).



3. Site Description

The HBMS was conducted between 14 and 29 June 2023 by Stuart Lumsden, one of JBS&G's experienced hazardous materials surveyors and a SafeWork NSW Licensed Asbestos Assessor (LAA 001140). Stuart was assisted by Jordan Gomez, one of JBS&G's experienced hazardous materials surveyors.

The broader RPA hospital campus was divided into an east and west portion by Missenden Road. The west portion was bound by Dunblane Street to the north, Missenden Road to the east, and Lambie Dew Drive to the north, Carillon Avenue to the south, and Hospital Road to the west. The east portion was bound by Lambie Dew Drive to the north, Sydney University to the east, St Andrew's College to the south, and Missenden Road to the west.

The HBMS assessment areas were restricted to the proposed refurbishment and demolition areas associated with the RPA Hospital Redevelopment Main Works Package (refer **Appendix D**), specifically:

- Main Hospital Building comprising B63, B64, B75, B77 and B89 across the following areas:
 - Level 1 undercroft areas and fire pump room;
 - Level 2 north lift foyer, toilets, offices, car park storerooms, fire control room, northern portion of Medical Training and Administration Unit (MTAU), and external façade;
 - Level 3 Birthing Centre, north lift and entry foyer, Delivery Unit, Neonatal Intensive Care Unit (NICU), Intensive Care Unit (ICU), ICU offices/administration, atrium and external façade;
 - Level 4 Staff Gymnasium, storerooms, Clinical Education Centre, various plant rooms, north lift foyer and stairs, Medical Records, Digital Health and Innovation, Radiology offices, Department of Anaesthetics, Café balcony and façade;
 - Level 5 Emergency Department, Radiology, main corridors and lift foyers, Women's and Children's Ambulatory Care, Women's and Children's Health Administration, Anti and Post Natal Wards, and Laboratory;
 - Level 6 Nuclear Medicine, plant rooms, external roof, Cardiac Catheter Laboratory, Coronary Care Unit (CCU), north lift foyer and corridors, Cardiology Ward, Cardiothoracic/Vascular Ward, Renal Ward;
 - Level 7 Nuclear Medicine, external roof, and plant rooms.
- Gate House Building located adjacent the Main Hospital Building on the corner of Missenden Road and Lambie Dew Drive;

At the time of inspection, the Main Hospital Building was occupied and an operational hospital facility, with the Gate House Building vacant and unoccupied.

The type, location, friability, accessibility, and approximate quantities of identified and suspected hazardous materials are provided in the Hazardous Materials Register in **Appendix A**.

Photographs taken during the HBMS are presented in Appendix B.

A summary of the observations made during the HBMS is included in the following sections.



3.1 Main Hospital Building (B63, B64, B75, B77 and B89)

The proposed refurbishment and demolition areas associated with the RPA Hospital Redevelopment Main Works Package comprised selected areas of B63, B64, B75, B77 and B89.

B63 and B64 comprised multi storey heritage structures that were constructed in circa 1904 and 1882 respectively. The eastern portion of B64 was demolished to facilitate the construction of the multi storey B75 in the 1970s. B63, B64 and B75 have all undergone significant refurbishments since their construction.

B77 and B89 were more recent redevelopments at RPA Hospital and comprised the multi storey Clinical Services Building (CSB) with construction of Stage 1 (B89) completed circa 2006 and Stage 2 (B77) complete circa 2009.

3.1.1 Level 1

The Level 1 assessment area comprised three undercroft areas within B89 and the fire pump room within B75.

A summary of the significant observations made during the HBMS is as follows:

- The undercroft areas comprised concrete ceilings and exposed soil floor with mechanical plant, including pipework and ducting, running through them.
- The fire pump room comprised concrete floor and ceiling and cement block walls, with mechanical plant including the hydrant pump, pipework and ductwork.
- Non-asbestos containing cream vermiculite (L1-A01) was identified as fire proofing to the ductwork throughout the northeast undercroft area;
- Non-asbestos containing grey vermiculite (L1-A02) was identified as fire proofing to the ductwork throughout the northeast undercroft area;
- Non-asbestos containing fibre cement pipe (L1-A03) was identified within the southeast undercroft area;
- Non-asbestos containing gaskets (L1-A04) was identified to the pipework and pumps within the fire pump room;
- Non-asbestos containing millboard (L1-A05) was identified to the upper north wall within the fire pump room;
- Non-lead based red paint (L1-L01, 0.04% w/w) was identified to the hydrant pipework throughout the north undercroft area;
- Non-lead based red/brown paint (L1-L02, <0.01% w/w) was identified to the soil pipework within the southeast undercroft area;
- Lead-based red/blue paint (L1-L03, 6.6% w/w) was identified to the pumps within the fire pump room;
- Fluorescent lights were identified throughout and are suspected to contain PCB capacitors, however, a detailed inspection was not possible due to the supply of live electricity;
- Assumed SMF insulation was identified to packing pillows within the wall and ceiling penetrations throughout;
- Assumed SMF insulation was identified to pipework throughout; and
- Assumed SMF insulation was identified to the ductwork within the fire pump room.



3.1.2 Level 2

The Level 2 assessment area comprised the north lift foyer, offices and toilets, portions of the internal north carpark and associated storerooms, northern portion of the MTAU, and the fire control room, all within B89.

A summary of the significant observations made during the HBMS is as follows:

- The north lift foyer, offices and toilets comprised concrete floors with various floor coverings, fixed plasterboard and suspended tile ceilings, and plasterboard, fibre cement sheet and cement rendered masonry walls;
- The north carpark and associated storerooms comprised concrete floors and ceilings;
- The northern portion of the MTAU comprised concrete floors with carpet and vinyl floor coverings, plasterboard walls, and suspended tile ceilings;
- The fire control room comprised concrete floor and ceiling, and concrete block walls;
- Non-asbestos containing blue vinyl sheeting (L2-A01) was identified to flooring throughout the north lift foyer and corridor;
- Non-asbestos containing fibre cement sheeting (L2-A02) was identified to wall lining throughout the toilets;
- Non-asbestos containing vermiculite insulation (L2-A03) was identified to the pipework throughout the carpark and storerooms;
- Non-asbestos containing mastic (L2-A04) was identified to the wall expansion joint within the internal carpark;
- Non-asbestos containing mastic (L2-A05) was identified to the wall expansion joint within the fire control room;
- Non-lead based cream paint (L2-L01, <0.01% w/w) was identified to the walls throughout the fire control room;
- Non-asbestos containing black mastic (EM-01) was identified to the external wall expansion joint adjacent the carpark entry;
- Non-asbestos containing black mastic (EM-02) was identified to the external wall expansion joint adjacent the bottom of the carpark entry ramp;
- Non-asbestos containing grey mastic (EM-03) was identified to the external precast concrete wall expansion joint;
- Fluorescent lights were identified throughout and are suspected to contain PCB capacitors, however, a detailed inspection was not possible due to the supply of live electricity; and
- Assumed SMF materials were identified throughout the assessment area in various forms as follows:
 - Suspended ceiling tiles;
 - Insulation packing pillows to wall and ceiling penetrations; and
 - \circ $\;$ Insulation to pipework and ducting.

3.1.3 Level 3

The Level 3 assessment area comprised the Birthing Centre, north lift and entry foyer, Delivery Unit, Neonatal Intensive Care Unit (NICU), Intensive Care Unit (ICU), ICU offices/administration, atrium and external façade all within B89.



A summary of the significant observations made during the HBMS is as follows:

- The assessment area comprised concrete floors with various floor coverings, fixed plasterboard and suspended tile ceilings, and plasterboard, fibre cement sheet and cement rendered masonry walls;
- Non-asbestos containing fibre cement sheeting (L3-A01) was identified to walls of the toilets in the north foyer.
- Non-asbestos containing fibre cement sheeting (L3-A02) was identified to the wall panels of the atrium;
- Various coloured non-asbestos containing vinyl sheeting was identified throughout the Level 3 assessment area and are identified as follows:
 - Light blue vinyl sheeting (L3-A03) to the floors of the cleaners and dirty utility rooms within ICU;
 - Cream vinyl sheeting (L3-A04) to the walls of the cleaners and dirty utility room within ICU;
 - White vinyl sheeting (L3-A05) to the floor of the kitchen within ICU administration;
 - Light grey vinyl sheeting (L3-A06) to the floors throughout the ICU including corridors, storerooms and patient rooms;
 - Mottled blue vinyl sheeting (L3-A07) to the floors throughout the ICU including corridors, storerooms and patient rooms; and
 - Green vinyl sheeting (L3-A09) to the floors of the staff stations and corridors throughout the ICU.
- Non-asbestos containing fibre cement sheeting (L3-A08) was identified to the walls of the toilets, cleaners' rooms and dirty utility rooms throughout the ICU;
- Lead concentrations within settled dust below the adopted site criteria (L3-LD01, 130 mg/kg) was identified within the ICU administration ceiling cavity. This dust was also found not to contain asbestos (L3-AD01).
- Lead concentrations within settled dust below the adopted site criteria (L3-LD02, <5 mg/kg) was identified within the Neonatal ICU ceiling cavity. This dust was also found not to contain asbestos (L3-AD02).
- Fluorescent lights were identified throughout and are suspected to contain PCB capacitors, however, a detailed inspection was not possible due to the supply of live electricity.
- Assumed SMF materials were identified throughout the assessment area in various forms as follows:
 - Suspended ceiling tiles;
 - Insulation to flexible air conditioning ducting within ceiling cavities;
 - \circ $\;$ Insulation packing pillows to wall and ceiling penetrations; and
 - o Internal insulation to instant and standard hot water systems.

3.1.4 Level 4

The Level 4 assessment area comprised the Staff Gymnasium, storerooms and Clinical Education centre within B63, small plant room and staff lift foyer in B75, and north lift foyer and stairs, Medical Records, Digital Health and Innovation, Radiology offices, Department of Anaesthetics, Café balcony and façade, and various plant rooms in B89.



A summary of the significant observations made during the HBMS is as follows:

- The Staff Gymnasium, storerooms and Clinical Education centre within B63 comprised concrete floors with various floor coverings, fixed plasterboard and suspected tile ceilings, and plasterboard and cement rendered masonry walls.
- The small plant room and staff lift foyer in B75 comprised concrete floors, exposed concrete ceilings, and exposed and cement rendered masonry walls.
- The north lift foyer and stair, Medical Records, Digital Health and Innovation, and Departments of Anaesthetics in B89 comprised concrete floors with various floor coverings, fixed and suspended tile ceilings, and a combination of plasterboard, fibre cement and cement rendered masonry walls.
- The Café balcony and external façade comprised a concrete slab floor, pebblecrete and cement rendered walls with a plasterboard ceiling;
- The plant rooms comprised concrete floors, concrete ceiling and a mixture of exposed brick, plasterboard and cement rendered walls;
- Non-asbestos containing mastic (L4-A01) was identified to the base of the Air Handling Unit (AHU) within the small plant room in B75;
- Asbestos containing mastic (L4-A02) was identified to the flange joint of the yellow AHU within the small plant room in B75;
- Asbestos containing gaskets (L4-A03) were identified to the chilled water pipework throughout the small plant room in B75;
- Non-asbestos containing fibre cement sheeting (L4-A04) was identified to the upper in-fill panels of the columns within the staff lift foyer in B75;
- Various coloured non-asbestos containing vinyl sheeting was identified throughout the Level 4 assessment area and are identified as follows:
 - Beige vinyl sheeting (L4-A05) to the floors throughout the main corridor and service corridors in B89;
 - Black vinyl sheeting (L4-A06) to the floor throughout the main corridor in B89;
 - Blue vinyl sheeting (L4-A07) to the floor of the utility rooms in B89;
 - White vinyl sheeting (L4-A08) to the walls of the utility rooms in B89;
 - Light grey vinyl sheeting (L4-A18) to the floor throughout the Café;
 - Blue vinyl sheeting (L4-A20) to the floor throughout the server room within Digital Health and Innovation in B89;
 - Blue vinyl sheeting (L4-A22) to the floor of the male/female changeroom of the Radiology offices in B89;
 - White vinyl sheeting (L4-A23) to the floor of the kitchen within the Radiology offices in B89; and
 - Green vinyl sheeting (L4-A26) to the floors throughout B63 assessment areas.
- Non-asbestos containing fibre cement sheeting (L4-A09) was identified to the walls throughout the utility room and staff toilets of the main corridor in B89;
- Non-asbestos containing fibre cement sheeting (L4-A10) was identified to the riser cabinet in the service corridor in B89;



- Non-asbestos containing mastic (L4-A11) was identified to the vertical expansion joints to the south wall of the service corridor in B89;
- Non-asbestos containing vermiculite fire proofing (L4-A12) was identified to the columns, ceiling and ductwork throughout the B89 plant room;
- Non-asbestos containing millboard (L4-A13) was identified to the floor, wall and ceiling penetrations and to the ductwork throughout B89 plant room;
- Non-asbestos containing fibre cement sheeting (L4-A14) was identified to the north wall of the south B89 plant room, located adjacent Department of Anaesthetics;
- Non-asbestos containing fibre cement sheeting (L4-A15) was identified to the wall linings of the north B89 plant room, located adjacent the glass stairwell;
- Non-asbestos containing cream mastic sealant (L4-A16) and black mastic sealant (L4-A17) were identified to the external façade expansion joints, accessed from the Café balcony;
- Asbestos containing millboard (L4-A19) was identified to the internal core of the fire doors throughout the B75 plant room. All fire doors within the B75 assessment area should be assumed to contain asbestos;
- Non-asbestos containing fibre cement sheeting (L4-A21) was identified to the walls of the male/female toilets within the changerooms of the Radiology Offices in B89;
- Non-asbestos containing fibre cement sheeting (L4-A24) was identified to the walls throughout the Anaesthetic offices in B89;
- Non-asbestos containing vermiculite (L4-A25) was identified to the fireproofing of the structural steel framework within the ceiling cavity of the storerooms in B63;
- Non-asbestos containing hessian lagging (L4-A27) was identified to the copper pipework to the Air Flow Unit within the B75 plant room;
- Lead concentrations within settled dust below the adopted site criteria (L4-LD01, 510 mg/kg) was identified to the floor surface within the air plenum associated with the B75 plant room. This dust was also found not to contain asbestos (L4-AD01).
- Lead concentrations within settled dust below the adopted site criteria (L4-LD02, 100 mg/kg) was identified within the main corridor ceiling cavity in B89. This dust was also found not to contain asbestos (L4-AD02).
- Non-lead based paint (L4-L01, 0.02% w/w) was identified to the cable trays within the B75 plant room;
- Non-lead based yellow paint (L4-L02, <0.01% w/w) was identified to AHU within the B75 plant room;
- Lead based green paint (L4-L03, 2.9% w/w) was identified to the steam humidifier within the B75 plant room;
- Non-lead based red paint (L4-L04, 0.03% w/w) was identified to the hydrant and sprinkler pipework throughout the main B89 plant room;
- Non-lead based orange paint (L4-L05, <0.01% w/w) was identified to the electrical cabinets within the main B89 plant room;
- Non-lead based cream paint (L4-L06, 0.09% w/w) was identified to the cement rendered walls of the storerooms in B63;



- Non-lead based white paint (L4-L07, 0.06% w/w) was identified to the timber windows within the storerooms in B63;
- Lead based green paint (L4-L08, 0.32% w/w) was identified to the metal pillars and door frames within the storerooms in B63;
- Lead based beige paint (L4-L09, 3.8% w/w) was identified to the concrete ceiling (within the ceiling cavity) within the storerooms in B63;
- Fluorescent lights were identified throughout and are suspected to contain PCB capacitors, however, a detailed inspection was not possible due to the supply of live electricity.
- Assumed SMF materials were identified throughout the assessment area in various forms as follows:
 - Suspended ceiling tiles;
 - o Insulation to flexible air conditioning ducting within ceiling cavities;
 - Insulation to pipework throughout;
 - o Insulation packing pillows to wall and ceiling penetrations; and
 - o Internal insulation to instant and standard hot water systems.

3.1.5 Level 5

The Level 5 assessment area comprised the Laboratory in B77, the Emergency Department in B63 and B75, Radiology in B75 and B89, public corridors in B75 and B89, and lift foyers, Women's and Children's Ambulatory Care, Women's and Children's Health Administration, and Anti and Post Natal Wards in B89.

A summary of the significant observations made during the HBMS is as follows:

- The Laboratory within B77 comprised concrete floors with various floor coverings, plasterboard and cement rendered masonry walls, and fixed plasterboard and suspended tile ceilings;
- The Emergency Department, Radiology and public corridors in B75 and B89 comprised concrete floors with various floor coverings, fixed plasterboard and suspended tile ceilings, and a combination of plasterboard, fibre cement sheet and cement rendered masonry walls;
- The lift foyers, Women's and Childrens Ambulatory Care and Women's and Childrens Health Administration in B89 comprised concrete floors with various floor coverings, fixed plasterboard and suspended tile ceilings, and a combination of plasterboard, fibre cement sheet and cement rendered masonry walls;
- Various coloured non-asbestos containing vinyl sheeting was identified throughout the Level 5 assessment area and are identified as follows:
 - Beige vinyl sheeting (L5-A01) to the floor throughout the main corridor in B89;
 - Black vinyl sheeting (L5-A02) to the floor throughout the main corridor in B89;
 - Black vinyl sheeting (L5-A04) the floor of the northwest corridor in B89;
 - Cream vinyl sheeting (L5-A06) to the walls of the utility rooms, storerooms and cleaners' rooms throughout the Anti and Post Natal wards in B89;
 - Light blue vinyl sheeting (L5-A07) to the floors of the sink areas, staff rooms, kitchens, utility rooms and cleaners' rooms within the Anti and Post Natal wards in B89;



- Mottled blue vinyl sheeting (L5-A08) to the floors throughout the Anti and Post Natal wards in B89;
- Green vinyl sheeting (L5-A15) to the floors of the Radiology booking desk reception area in B89;
- Red vinyl sheeting (L5-A17) to the floors throughout Radiology waiting room in B89;
- Dark blue vinyl sheeting (L5-A22) to the floors throughout the Children's and Adults Emergency Departments in B63 and B75;
- Light grey vinyl sheeting (L5-A23) to the floors of the isolation room and bathroom in Emergency Department in B63;
- Dark grey vinyl sheeting (L5-A24) to the floors throughout the main corridors associated within the Emergency Department in B63; and
- Dark grey with white speckle vinyl sheeting (L5-A25) to the floors throughout resuscitation area in Emergency Department in B75;
- Non-asbestos containing fibre cement sheeting (L5-A03) was identified to the walls throughout the northern bathrooms in B89;
- Non-asbestos containing fibre cement sheeting (L5-A05) was identified to the walls throughout the bathrooms adjacent B75 central lifts;
- Non-asbestos containing fibre cement sheeting (L5-A09) was identified to the walls throughout the bathrooms, cleaners' and utility rooms in the Anti and Post Natal wards in B89;
- Non-asbestos containing millboard insulation (L5-A10) was identified to the electrical risers and floor penetrations in B89;
- Non-asbestos containing vermiculite insulation (L5-A11) was identified to the ductwork within the ceiling cavity of the Anti and Post Natal wards in B89;
- Non-asbestos containing fibre cement sheeting (L5-A12) was identified to the walls throughout the unisex changeroom/bathrooms in B89;
- Asbestos containing millboard (L5-A13) was identified to the core of the double fire door within the corridor adjacent the Radiology reception area, located within B75. All fire doors within B75 should be assumed to contain asbestos;
- Non-asbestos containing fibre cement sheeting (L5-A14) was identified to the walls to the staff bathroom within the Radiology reception area;
- Non-asbestos containing grey mastic (L5-A16) was identified to the brick wall expansion joint within the central corridor riser in Radiology;
- Non-asbestos containing black mastic (L5-A18) was identified to the fire door within the pathology area in B89;
- Non-asbestos containing fibre cement sheeting (L5-A19) was identified to the walls throughout the doffing ward within the Children's Emergency Department in B63;
- Non-asbestos containing fibre cement sheeting (L5-A20) was identified to walls throughout the doffing ward main corridor within the Children's Emergency Department in B63;
- Non-asbestos containing fibre cement sheeting (L5-A21) was identified to the walls throughout the plaster room, toilets and waiting room within the Emergency Department in B63;



- Lead concentrations within settled dust below the adopted site criteria (L5-LD01, 100 mg/kg) was identified within the B89 main corridor ceiling cavity. This dust was also found not to contain asbestos (L5-AD01).
- Lead concentrations within settled dust below the adopted site criteria (L5-LD02, 40 mg/kg) was identified within the Anti and Post Natal Ward ceiling cavity in B89. This dust was also found not to contain asbestos (L5-AD02).
- Lead concentrations within settled dust below the adopted site criteria (L5-LD03, 310 mg/kg) was identified within the Pathology ceiling cavity in B89. This dust was also found not to contain asbestos (L5-AD03).
- Lead based red paint (L5-L01, 0.49% w/w) was identified to the fire hydrant reel and door/frames within the Emergency Department;
- Non-lead based pink paint (L5-L02, 0.08% w/w) was identified to the columns and walls throughout the Emergency Department;
- Lead based cream/olive paint (L5-L03, 3.5% w/w) was identified to the original cement rendered walls within the Emergency Department ceiling cavity in B63;
- Lead based cream paint (L5-L04, 5.4% w/w) was identified to the cement rendered walls throughout the fire stairs in B63;
- Lead based green paint (L5-L05, 7.5% w/w) with cream undercoat was identified to the fire stair railing in B63;
- Lead based dark blue paint (L5-L06, 3.5% w/w) was identified to the arches, staff room and main corridors in the Emergency Department in B63;
- Lead based white paint (L5-L07, 1.8% w/w) was identified to the windowsills, frames and timber windows throughout the Emergency Department in B63;
- Fluorescent lights were identified throughout and are suspected to contain PCB capacitors, however, a detailed inspection was not possible due to the supply of live electricity.
- Assumed SMF materials were identified throughout the structure in various forms as follows:
 - Suspended ceiling tiles;
 - Insulation to flexible air conditioning ducting within ceiling cavities;
 - Insulation to pipework throughout;
 - o Insulation packing pillows to wall and ceiling penetrations; and
 - o Internal insulation to instant and standard hot water systems.

3.1.6 Level 6

The Level 6 assessment area comprised Nuclear Medicine and external roof area in B63, Cardiac Vascular Day Stay in B75, and plant rooms, external roof, Cardiac Catheter Laboratory, Coronary Care Unit (CCU), north lift foyer and corridors, Cardiology Ward, Cardiothoracic/Vascular Ward, Renal Ward in B89.

A summary of the significant observations made during the HBMS is as follows:

• Nuclear Medicine within B63 comprised concrete floors with various floor coverings, cement rendered masonry walls, and fixed and suspended tile ceilings;



- Cardiac Vascular Day Stay in B75, Cardiac Catheter Laboratory, CCU, north lift foyer and corridors, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward in B89 comprised concrete floors with various floor coverings, fixed plasterboard and suspended tile ceilings, and plasterboard, fibre cement sheet and cement rendered masonry walls;
- Non-asbestos containing fibre cement sheeting (L6-A01) was identified to the walls throughout north toilets in B89;
- Various coloured non-asbestos containing vinyl sheeting was identified throughout the Level 6 assessment area and are identified as follows:
 - Mottled blue vinyl sheeting (L6-A02) to the floors throughout Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward in B89;
 - Light blue vinyl sheeting (L6-A03) to the floors throughout sink areas, utility rooms, cleaners and kitchens within the Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward in B89;
 - Brown vinyl sheeting (L6-A04) to the walls throughout the utility rooms, storerooms and cleaner's rooms within the Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward in B89; and
 - Grey vinyl sheeting (L6-A13) to the floors of the kitchenette and laboratory within Nuclear Medicine in B63;
- Non-asbestos containing fibre cement sheeting (L6-A05) was identified to the walls throughout the bathrooms, showers, toilets, cleaners and utility rooms within the Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward in B89;
- Non-asbestos containing mastic (L6-A06) was identified to the wall expansion joint within the fire stairs in B89;
- Non-asbestos containing fibre cement sheeting (L6-A07) was identified to the external wall cladding to the B63 plant room;
- Non-asbestos containing fibre cement sheeting debris (L6-A08) was identified withing the guttering to the roof, adjacent the plant room in B63;
- Non-asbestos containing felt membrane (L6-A09) was identified to the flat roof sections underlying the surface pebble layer in B89;
- Non-asbestos containing putty (L6-A10) was identified to the external timber windows to B63 (accessed from the roof);
- Non-asbestos containing bituminous membrane (L6-A11) was identified to the surface membrane layer of the west roof located between B63 and B64. It is noted that in SEG 2022b, an asbestos containing fibrous membrane was identified underlying the surface nonasbestos containing layer (refer sample B64-L6-ROOF-ASB01). A representative sample of the underlying membrane layer was unable to be collected at the time of inspection without damaging the waterproofing integrity of the membrane, therefore, the asbestos containing membrane as identified in SEG 2022b, is still assumed to be present;
- Non-asbestos containing fibre cement sheeting (L6-A12) was identified to the staff toilet walls within the Cardiac Vascular Day Stay in B75;
- Non-asbestos containing fibrous material (L6-A14) was identified to the double brick wall cavity within the plant room in B63;



- Asbestos containing mastic sealant (L6-A15) was identified to the old timber windows within the small laboratory storage room in Nuclear Medicine within B63;
- Non-asbestos containing vermiculite insulation (L6-A16) was identified to the AHUs throughout plant room in B63;
- It is noted that assumed asbestos containing lagged pipework was identified within a storeroom adjacent to but outside of the Nuclear Medicine assessment area in B63. These assumed asbestos lagged pipes were observed to extend into Level 7 above and Level 5 below, however, were unable to be located on these levels. There is the potential for additional asbestos lagged pipework to be concealed within the assessment areas located across B63;
- Lead concentrations within settled dust below the adopted site criteria (L6-LD01, 49 mg/kg) was identified within the B89 main corridor ceiling cavity. This dust was also found not to contain asbestos (L6-AD01).
- Lead concentrations within settled dust below the adopted site criteria (L6-LD02, 56 mg/kg) was identified within the Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward ceiling cavity in B89. This dust was also found not to contain asbestos (L6-AD02).
- Lead concentrations within settled dust below the adopted site criteria (L6-LD03, 26 mg/kg) was identified within the Cardiac Vascular Day Stay ceiling cavity in B75. This dust was also found not to contain asbestos (L6-AD03).
- Non-lead based red paint (L6-L01, 0.01% w/w) was identified to the hydrant and sprinkler pipework throughout B89;
- Lead based orange paint (L6-L02, 3.3% w/w) was identified to the external vent pipes to B63;
- Non-lead based brown paint (L6-L03, <0.01% w/w) was identified to the external vent grill to the B63 plant room;
- Lead based white paint (L6-L04, 5.3% w/w) was identified to the external timber windows to B63;
- Lead based blue paint (L6-L05, 0.11% w/w) was identified to the AHUs and ductwork within the B63 mechanical plant room;
- Lead based green/cream paint (L6-L06, 1.1% w/w) was identified to the masonry walls within the B63 mechanical plant room;
- Lead based cream paint (L6-L07, 2.0% w/w) was identified to the brick walls within the B63 plant room;
- Lead based white paint (L6-L08, 3.0% w/w) was identified to the internal timber within in Nuclear Medicine in B63;
- Fluorescent lights were identified throughout and are suspected to contain PCB capacitors, however, a detailed inspection was not possible due to the supply of live electricity.
- Assumed SMF materials were identified throughout the structure in various forms as follows:
 - Suspended ceiling tiles;
 - o Insulation to flexible air conditioning ducting within ceiling cavities;
 - Insulation to pipework throughout;
 - Insulation to roof sarking;



- Insulation packing pillows to wall and ceiling penetrations; and
- Internal insulation to instant and standard hot water systems.

3.1.7 Level 7

The Level 7 assessment area comprised Nuclear Medicine in B63, and external roof and plant rooms in B89.

A summary of the significant observations made during the HBMS is as follows:

- Nuclear Medicine comprised three rooms with various floor coverings, fixed plasterboard and suspended tile ceilings, and plasterboard and cement rendered masonry walls;
- The plant rooms comprised concrete floors, corrugated metal sheet roof and metal panel clad walls;
- Non-asbestos containing vermiculite insulation (L7-A01) was identified to the ductwork within the B89 plant room;
- Non-asbestos containing millboard insulation (L7-A02) was identified as fireproofing panels to the ductwork and penetrations within the B89 plant room;
- Non-asbestos containing mastic sealant (L7-A03) was identified to the ductwork flange joints within the B89 plant room;
- Non-asbestos containing mastic (L7-A04) was identified to the wall expansion joint within the B89 plant room;
- Non-asbestos containing vermiculite insulation (L7-A05) was identified to the fire door core (2002 plate) within the B89 plant room;
- Non-asbestos containing felt membrane (L7-A06) was identified to the flat roof sections underlying the surface pebble layer in B89;
- Various coloured non-asbestos containing vinyl sheeting was identified throughout the Level 7 assessment area and are identified as follows:
 - Cream vinyl sheeting with grey speckle (L7-A07) to the flooring throughout the glass stairs in B89;
 - Blue speckled vinyl sheeting (L7-A09) to the floor throughout Nuclear Medicine in B63;
 - Orange vinyl sheeting (L7-A10) throughout X-ray room within Nuclear Medicine in B63; and
 - White vinyl sheeting (L7-A11) to lower splash walls throughout Nuclear Medicine in B63;
- Non-asbestos containing mastic (L7-A08) perimeter sealant was identified to the glass stairs and landings in B89;
- Lead concentrations within settled dust below the adopted site criteria (L7-LD01, 190 mg/kg) was identified to the floor of the B89 plant room. This dust was also found not to contain asbestos (L7-AD01).
- Lead based orange paint (L7-L01, 4.3 w/w) was identified to the electrical switchboard cabinets throughout the B89 plant room;
- Non-lead based high visibility yellow paint (L7-L02, <0.01% w/w) was identified to trip hazards throughout the B89 plant room;
- Non-lead based red paint (L7-L03, 0.05% w/w) was identified to the sprinkler/hydrant pipework throughout the B89 plant room;



- Lead based green paint (L7-L04, 0.15% w/w) was identified to the generators within the B89 plant room;
- Non-lead based grey paint (L7-L05, <0.01% w/w) was identified to the fire stair handrails in B89;
- Non-lead based blue paint (L7-L06, 0.03% w/w) was identified to the glass staircase steel frame within B89;
- Fluorescent lights were identified throughout and are suspected to contain PCB capacitors, however, a detailed inspection was not possible due to the supply of live electricity.
- Assumed SMF materials were identified throughout the structure in various forms as follows:
 - Suspended ceiling tiles;
 - Insultation to wall and roof sarking;
 - Insulation to flexible air conditioning ducting within ceiling cavities;
 - Insulation to pipework throughout;
 - Insulation packing pillows to wall and ceiling penetrations; and
 - Internal insulation to instant and standard hot water systems.

3.2 Gate House Building

The Gate House Building was located on the corner of John Hopkins Drive and Missenden Road. The single storey structure comprised a corrugated steel sheet roof, exposed brick walls, fibre cement sheet ceiling, and a concrete slab floor.

A summary of the significant observations made during the HBMS is as follows:

- Non-asbestos containing putty (GH-A01) was identified to the external timber windows;
- Asbestos containing fibre cement sheeting (GH-A02) was identified to the eaves;
- Non-asbestos containing blue vinyl tiles (GH-A03) were identified to the floor;
- Asbestos containing fibre cement sheeting (GH-A04) was identified to the ceiling;
- Non-lead based white paint (GH-L01, <0.01% w/w) was identified to the timber windows;
- Non-lead based white paint (GH-L02, 0.09% w/w) was identified to the internal brick walls;
- Fluorescent lights were identified throughout and are suspected to contain PCB capacitors, however, a detailed inspection was not possible due to the supply of live electricity.
- Assumed SMF internal insulation was identified to the 'Zip hydrotap' within the kitchenette.



4. Results

4.1 Hazardous Materials

All identified hazardous materials are recorded in the Hazardous Materials Register in **Appendix A** with relevant photographs in **Appendix B**. NATA accredited laboratory analysis reports and chain of custody are provided in **Appendix C**.

4.1.1 Asbestos Containing Materials

ACM were identified by testing at an accredited NATA laboratory and/or visual inspection using the experience of the hazardous materials surveyor. A summary of the results of laboratory testing for asbestos are provided in **Table 4.1** below.

Sample ID	Lab ID	Sample Location	Results	Observed Condition
Level 1 – Ma	in Building			
L1-A01	S23-Jn0069842	Northeast undercroft area, fireproofing to ductwork – cream vermiculite	No asbestos detected	N/A
L1-A02	S23-Jn0069843	Northeast undercroft area, fireproofing to ductwork – grey vermiculite	No asbestos detected	N/A
L1-A03	S23-Jn0069844	Southeast undercroft area – fibre cement pipe	No asbestos detected	N/A
L1-A04	S23-Jn0069845	Fire pump room, pipework and pumps – gasket	No asbestos detected	N/A
L1-A05	S23-Jn0069846	Fire pump room, upper north wall – millboard	No asbestos detected	N/A
Level 2 – Ma	in Building			
L2-A01	S23-Jn0069850	North lift foyer and corridor, floor – blue vinyl sheeting	No asbestos detected	N/A
L2-A02	S23-Jn0069851	Toilets, walls – fibre cement sheeting	No asbestos detected	N/A
L2-A03	S23-Jn0069852	Carpark and storerooms, pipework – vermiculite insulation	No asbestos detected	N/A
L2-A04	S23-Jn0069853	Internal carpark area, wall expansion joint – grey mastic	No asbestos detected	N/A
L2-A05	S23-Jn0069854	Fire control room, wall expansion joint – mastic	No asbestos detected	N/A
EM-01	S23-JI0019870	Adjacent carpark entry, wall expansion joint – black mastic	No asbestos detected	N/A
EM-02	S23-JI0019871	Carpark entry ramp, external wall expansion joint – black mastic	No asbestos detected	N/A
EM-03	S23-JI0019872	External precast concrete, wall expansion joint – grey mastic	No asbestos detected	N/A
Level 3 – Ma	in Building			
L3-A01	S23-Jn0069856	B89, north foyer, toilets, walls – fibre cement sheeting	No asbestos detected	N/A
L3-A02	S23-Jn0069857	Atrium, wall panels – fibre cement sheeting	No asbestos detected	N/A
L3-A03	S23-Jn0069858	B89, ICU, cleaners and dirty utility rooms, floor – light blue vinyl sheeting	No asbestos detected	N/A
L3-A04	S23-Jn0069859	B89, ICU, cleaners and dirty utility room, walls – cream vinyl sheeting	No asbestos detected	N/A
L3-A05	S23-Jn0069860	B89, ICU Administration, kitchen, floor – white vinyl floor sheeting	No asbestos detected	N/A
L3-A06	S23-Jn0069861	B89, ICU, corridors, storerooms and patient rooms, floor – light grey vinyl sheeting	No asbestos detected	N/A
L3-A07	S23-Jn0069862	B89, ICU, corridors, storerooms and patient rooms, floor – mottled blue vinyl sheeting	No asbestos detected	N/A
L3-A08	S23-Jn0069863	B89, ICU, toilets, cleaners and dirty utility rooms, walls – fibre cement sheeting	No asbestos detected	N/A
L3-A09	S23-Jn0069864	B89, ICU, staff stations and corridors, floor – green vinyl sheeting	No asbestos detected	N/A
<u>Level 4 – Ma</u>	in Building			
L4-A01	S23-Jn0069869	B75, plant room, base of AHU – mastic	No asbestos detected	N/A



Sample ID	Lab ID	Sample Location	Results	Observed Condition
L4-A02	S23-Jn0069870	B75, plant room, yellow AHU and ductwork, flange joints – mastic	Chrysotile Asbestos	Non-Friable
L4-A03	S23-Jn0069871	B75, plant room, chilled water pipework – gasket	Chrysotile Asbestos	Non-Friable
L4-A04	S23-Jn0069872	B75, lift foyer, upper wall infill panels – fibre cement sheeting	No asbestos detected	N/A
L4-A05	S23-Jn0069873	B89, main and service corridors, floor – beige vinyl sheeting	No asbestos detected	N/A
L4-A06	S23-Jn0069874	B89, main corridor, floor – black vinyl sheeting	No asbestos detected	N/A
L4-A07	S23-Jn0069875	B89, utility rooms, floor – blue vinyl sheeting	No asbestos detected	N/A
L4-A08	S23-Jn0069876	B89, utility rooms, walls- white vinyl sheeting	No asbestos detected	N/A
L4-A09	S23-Jn0069877	B89, main corridor, utility room and staff toilets, walls – fibre cement sheeting	No asbestos detected	N/A
L4-A10	S23-Jn0069878	B89, service corridor, riser cabinet – fibre cement sheeting	No asbestos detected	N/A
L4-A11	S23-Jn0069879	B89, service corridor, south wall, expansion joint – mastic	No asbestos detected	N/A
L4-A12	S23-Jn0069880	B89, main plant room, columns, ceiling and ducting – vermiculite	No asbestos detected	N/A
L4-A13	S23-Jn0069881	B89, main plant room, ducting and penetrations – millboard	No asbestos detected	N/A
L4-A14	S23-Jn0069882	B89, south plant room, north wall – fibre cement sheeting	No asbestos detected	N/A
L4-A15	S23-Jn0069883	B89, north plant room, wall lining – fibre cement sheeting	No asbestos detected	N/A
L4-A16	S23-Jn0069884	B89, external façade, wall expansion joint – cream mastic	No asbestos detected	N/A
L4-A17	S23-Jn0069885	B89, external façade, wall expansion joint – black mastic	No asbestos detected	N/A
L4-A18	S23-Jn0069886	B89, Café, floor – light grey vinyl sheeting	No asbestos detected	N/A
L4-A19	S23-Jn0069887	B75, plant room, fire doors, internal core – millboard	Chrysotile and Amosite Asbestos	Friable
L4-A20	S23-Jn0069888	B89, Digital, Health and Innovation, server room, floor – blue vinyl sheeting	No asbestos detected	N/A
L4-A21	S23-Jn0069889	B89, Radiology Offices, male/female toilets within changeroom, walls – fibre cement sheeting	No asbestos detected	N/A
L4-A22	S23-Jn0069890	B89, Radiology Offices, male/female toilets, floor – blue vinyl sheeting	No asbestos detected	N/A
L4-A23	S23-Jn0069891	B89, Radiology Offices, kitchen, floor – white vinyl sheeting	No asbestos detected	N/A
L4-A24	S23-Jn0069892	B89, Anaesthetic offices, toilet walls – fibre cement sheeting	No asbestos detected	N/A
L4-A25	S23-Jn0069893	B63, storerooms, ceiling cavity, fireproofing to steel framework – Vermiculite insulation	No asbestos detected	N/A
L4-A26	S23-Jn0069894	B63, floor throughout – green vinyl sheeting	No asbestos detected	N/A
L4-A27	S23-Jn0069990	B75, plant room, Air Flow Unit, pipework – hessian lagging	No asbestos detected	N/A
Level 5 – Ma	in Building			
L5-A01	S23-Jn0069908	B89, main corridor, floor – beige vinyl sheeting	No asbestos detected	N/A
L5-A02	S23-Jn0069909	B89, main corridor, floor – black vinyl sheeting	No asbestos detected	N/A
L5-A03	S23-Jn0069910	B89, north bathrooms, walls – fibre cement sheeting	No asbestos detected	N/A
L5-A04	S23-Jn0069911	B89, north west corridor, floor – black vinyl sheeting	No asbestos detected	N/A
L5-A05	S23-Jn0069912	B75, adjacent lift foyer, toilets, walls – fibre cement sheeting	No asbestos detected	N/A
L5-A06	S23-Jn0069913	B89, Anti and Post Natal wards, utility rooms, store rooms and cleaners, walls – cream vinyl sheeting	No asbestos detected	N/A



Sample ID	Lab ID	Sample Location	Results	Observed Condition
L5-A07	S23-Jn0069914	B89, Anti and Post Natal wards, sink areas, staff rooms, kitchens, utility rooms and cleaners, floor –	No asbestos detected	N/A
L5-A08	S23-Jn0069915	B89, Anti and Post Natal wards, floor throughout – mottled blue vinyl sheeting	No asbestos detected	N/A
L5-A09	S23-Jn0069916	B89, Anti and Post Natal wards, toilets, bathrooms, cleaners and utility, walls – fibre	No asbestos detected	N/A
L5-A10	S23-Jn0069917	B89, electrical risers, floor penetrations – millboard	No asbestos detected	N/A
L5-A11	S23-Jn0069918	B89, Anti and Post Natal wards, ceiling cavity, fireproofing to ductwork – vermiculite insulation	No asbestos detected	N/A
L5-A12	S23-Jn0069960	B89, unisex changeroom/toilet, wall linings – fibre cement sheeting	No asbestos detected	N/A
L5-A13	S23-Jn0069961	B75, Radiology, main corridor adjacent reception, double fire doors, internal core – millboard	Chrysotile and Amosite Asbestos	Friable
L5-A14	S23-Jn0069962	B75, Radiology, reception area, staff toilet, walls – fibre cement sheeting	No asbestos detected	N/A
L5-A15	S23-Jn0069963	B89, Radiology, booking desk reception area, floor – green vinyl sheeting	No asbestos detected	N/A
L5-A16	S23-Jn0069964	B89, Radiology, central portion, riser in corridor, wall expansion joint – grey mastic	No asbestos detected	N/A
L5-A17	S23-Jn0069965	B89, Radiology, waiting room, staff desk platform, floor – red vinyl sheeting	No asbestos detected	N/A
L5-A18	S23-Jn0069966	B89, Pathology, fire door – black mastic	No asbestos detected	N/A
L5-A19	S23-Jn0069967	B63, Children's Emergency Department, doffing ward, storeroom 1, wall lining – fibre cement sheeting	No asbestos detected	N/A
L5-A20	S23-Jn0069968	B63, Children's Emergency Department, children's play area corridor, wall lining – fibre cement sheeting	No asbestos detected	N/A
L5-A21	S23-Jn0069969	B63, Emergency Department, waiting area, plaster room and toilets, wall lining – fibre cement sheeting	No asbestos detected	N/A
L5-A22	S23-Jn0069970	B63, Emergency Department, utility rooms, floor – dark blue vinyl sheeting	No asbestos detected	N/A
L5-A23	S23-Jn0069971	B63, Emergency Department, quarantine room/toilet, floor – light grey vinyl sheeting	No asbestos detected	N/A
L5-A24	S23-Jn0069972	B63, Emergency Department, main corridor, floor – dark grey vinyl sheeting	No asbestos detected	N/A
L5-A25	S23-Jn0069973	B75, Emergency Department, resuscitation area, floor – dark grey speckle vinyl sheeting	No asbestos detected	N/A
<u>Level 6 – Ma</u>	<u>iin Building</u>			
L6-A01	S23-Jn0069923	B89, north toilets, walls – fibre cement sheeting	No asbestos detected	N/A
L6-A02	S23-Jn0069924	B89, Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward, floor– mottled blue vinyl sheeting	No asbestos detected	N/A
L6-A03	S23-Jn0069925	B89, Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Wards, sink areas, utility rooms, cleaners and kitchen, floor – light blue vinyl sheeting	No asbestos detected	N/A
L6-A04	S23-Jn0069926	B89, Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward, utility rooms, store room areas and cleaners, walls – brown vinyl sheeting	No asbestos detected	N/A
L6-A05	S23-Jn0069927	B89, Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward, bathrooms, showers, toilets, cleaners and utility rooms, walls – fibre cement sheeting	No asbestos detected	N/A



Sample ID	Lab ID	Sample Location	Results	Observed Condition
L6-A06	S23-Jn0069928	B89, fire stairs – wall expansion joint	No asbestos detected	N/A
L6-A07	S23-Jn0069929	B63, mechanical plant room, external wall cladding – fibre cement sheeting	No asbestos detected	N/A
L6-A08	S23-Jn0069930	B63, roof guttering, debris – fibre cement sheeting	No asbestos detected	N/A
L6-A09	S23-Jn0069931	B89, flat roof, underlying surface pebble layer – felt membrane	No asbestos detected	N/A
L6-A10	S23-Jn0069932	B63, external timber windows – putty	No asbestos detected	N/A
L6-A11	S23-Jn0069933	Between B63 & B64, west roof, surface waterproofing membrane – bituminous membrane	No asbestos detected	N/A
L6-A12	S23-Jn0069982	B75, Cardiac Vascular Bay, staff toilets, walls – fibre cement sheeting	No asbestos detected	N/A
L6-A13	S23-JI0019831	B63, Nuclear Medicine, kitchenette and laboratory floor – grey vinyl sheeting	No asbestos detected	N/A
L6-A14	S23-JI0019832	B63, plant room, wall cavity – fibrous material	No asbestos detected	N/A
L6-A15	S23-JI0019833	B63, Nuclear Medicine, small laboratory storage room, timber windows – mastic	Chrysotile Asbestos	Non-Friable
L6-A16	S23-JI0019834	B63, plant room, AHUs – vermiculite insulation	No asbestos detected	N/A
<u>Level 7 – Ma</u>	<u>in Building</u>			
L7-A01	S23-Jn0069944	B89, plant room, fireproofing to ductwork – vermiculite insulation	No asbestos detected	N/A
L7-A02	S23-Jn0069945	B89, plant room, fireproofing panels to ductwork and penetrations – millboard insulation	No asbestos detected	N/A
L7-A03	S23-Jn0069946	B89, plant room, sealant to ductwork flange joints – mastic	No asbestos detected	N/A
L7-A04	S23-Jn0069947	B89, plant room, expansion joints in concrete block walls – mastic	No asbestos detected	N/A
L7-A05	S23-Jn0069948	B89, plant room, fire doors, internal core – vermiculite insulation	No asbestos detected	N/A
L7-A06	S23-Jn0069949	B89, flat roof, beneath surface pebble layer, waterproofing membrane – felt membrane	No asbestos detected	N/A
L7-A07	S23-Jn0069950	B89, glass staircase, floor – cream vinyl sheeting with speckle	No asbestos detected	N/A
L7-A08	S23-Jn0069951	B89, glass staircase, perimeter sealant – mastic	No asbestos detected	N/A
L7-A09	S23-JI0019837	B63, Nuclear Medicine, floor throughout – blue speckled vinyl sheeting	No asbestos detected	N/A
L7-A10	S23-JI0019838	B63, Nuclear Medicine, X-ray room, floor – orange vinyl sheeting	No asbestos detected	N/A
L7-A11	S23-JI0019839	B63, Nuclear Medicine, lower splash walls – white vinyl sheeting	No asbestos detected	N/A
Gate House				
GH-A01	S23-Jn0070037	External, windows – putty	No asbestos detected	N/A
GH-A02	S23-Jn0070038	Eaves – fibre cement sheeting	Chrysotile Asbestos	Non-Friable
GH-A03	S23-Jn0070039	Internal, floor – blue vinyl floor tiles	No asbestos detected	N/A
GH-A04	S23-Jn0070040	Ceiling – fibre cement sheeting	Chrysotile Asbestos	Non-Friable



4.1.2 Asbestos Containing Dust

Representative dust samples were collected throughout the site. A summary of the results of the laboratory testing for asbestos are provided in Table 4.2 below.

Sample ID	Lab ID	Sample Location	Results	Observed Condition				
<u>Level 1 – Main Building</u>								
No dust samples were taken at the time of inspection.								
Level 2 – Main Building								
No dust samples were taken at the time of inspection.								
<u>Level 3 – Main Building</u>								
L3-AD01	S23-Jn0069865	B89, ICU Administration, ceiling cavity – settled dust	No asbestos detected	N/A				
L3-AD02	S23-Jn0069866	B89, NICU, ceiling cavity – settled dust	No asbestos detected	N/A				
Level 4 – Main Building								
L4-AD01	S23-Jn0069895	B75, plant room, air plenum, floor – settled dust	No asbestos detected	N/A				
L4-AD02	S23-Jn0069896	B89, main corridor, ceiling cavity – settled dust	No asbestos detected	N/A				
<u>Level 5 – Main Building</u>								
L5-AD01	S23-Jn0069921	B89, main corridor, ceiling cavity – settled dust	No asbestos detected	N/A				
L5-AD02	S23-Jn0069922	B89, Anti and Post Natal wards, ceiling cavity – settled dust	No asbestos detected	N/A				
Level 6 – Main Building								
L6-AD01	S23-Jn0069934	B89, main corridor, ceiling cavity – settled dust	No asbestos detected	N/A				
L6-AD02	S23-Jn0069935	B89, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward, ceiling cavity – settled dust	No asbestos detected	N/A				
L6-AD03	S23-Jn0069983	B75, Cardiac Vascular Day Stay, ceiling cavity – settled dust	No asbestos detected	N/A				
Level 7 – Main Building								
L7-AD01	S23-Jn0069952	B89, plant room, floor – settled dust	No asbestos detected	N/A				
Gate House								
No dust samples were taken at the time of inspection.								

Table 4.2: Asbestos Dust Results Summary Table

4.1.3 Lead Containing Dust

Representative dust samples were collected throughout the site. A summary of the results of the laboratory testing for lead are provided in Table 4.3 below.

Table 4.3: Lead Dust Results Summary Table								
Sample ID	Lab ID	Sample Location	Results	Observed Condition				
Level 1 – Main Building								
No dust samples were taken at the time of inspection.								
Level 2 – Main Building								
No dust samples were taken at the time of inspection.								
Level 3 – Main Building								
L3-LD01	S23-Jn0069867	B89, ICU Administration, ceiling cavity – settled dust	130 mg/kg	N/A				
L3-LD02	S23-Jn0069868	B89, NICU, ceiling cavity – settled dust	<5 mg/kg	N/A				
Level 4 – Main Building								
L4-LD01	S23-Jn0069897	B75, plant room, air plenum, floor – settled dust	510 mg/kg	N/A				
L4-LD02	S23-Jn0069898	B89, main corridor, ceiling cavity – settled dust	100 mg/kg	N/A				
Level 5 – Main Building								
L5-LD01	S23-Jn0069919	B89, main corridor, ceiling cavity – settled dust	100 mg/kg	N/A				
L5-LD02	S23-Jn0069920	B89, Anti and Post Natal wards, ceiling cavity – settled dust	40 mg/kg	N/A				
Level 6 – Main Building								
L6-LD01	S23-Jn0069936	B89, main corridor, ceiling cavity – settled dust	49 mg/kg	N/A				
L6-LD02	S23-Jn0069937	B89, Cardiology Ward, Cardiothoracic/Vascular Ward and Renal Ward, ceiling cavity – settled dust	56 mg/kg	N/A				


Sample ID	Lab ID	Sample Location	Results	Observed Condition								
L6-LD03	S23-Jn0069984	B75, Cardiac Vascular Day Stay, ceiling cavity – settled dust	26 mg/kg	N/A								
Level 7 – Ma	iin Building											
L7-LD01	S23-Jn0069953	B89, plant room, floor – settled dust	190 mg/kg	N/A								
Gate House	Gate House											
No dust sam	No dust samples were taken at the time of inspection.											

4.1.4 Lead Based Paints

Representative paint samples were collected throughout the site for laboratory testing. A summary of the results of laboratory testing for lead are provided in **Table 4.4** below.

Sample ID	Lab ID	Sample Location	Results	Observed Condition
Level 1 – Ma	in Building			
L1-L01	S23-Jn0069847	North undercroft area, hydrant pipework – red paint	0.04% w/w (Non-lead based paint)	N/A
L1-L02	S23-Jn0069848	North undercroft area, soil pipework – red/brown paint	<0.01% w/w (Non-lead based paint)	N/A
L1-L03	S23-Jn0069849	Fire pump room, pumps – red/blue paint	6.6% w/w (Lead based paint)	Poor
<u>Level 2 – Ma</u>	<u>iin Building</u>			
L2-L01	S23-Jn0069855	Fire control room, walls – cream paint	<0.01% w/w (Non-lead based paint)	N/A
<u>Level 3 – Ma</u>	<u>iin Building</u>			
No paint sam	nples were taken a	at the time of inspection.		
<u>Level 4 – Ma</u>	<u>iin Building</u>			
L4-L01	S23-Jn0069899	B75, plant room, cable trays – orange paint	0.02% w/w (Non-lead based paint)	N/A
L4-L02	S23-Jn0069900	B75, plant room, AHU – yellow paint	<0.01% w/w (Non-lead based paint)	N/A
L4-L03	S23-Jn0069901	B75, plant room, steam humidifier – green paint	2.9% w/w (Lead based paint)	Fair
L4-L04	S23-Jn0069902	B89, main plant room, hydrant and sprinkler pipework – red paint	0.03% w/w (Non-lead based paint)	N/A
L4-L05	S23-Jn0069903	B89, main plant room, electrical cabinets – orange point	<0.01% w/w (Non-lead based paint)	N/A
L4-L06	S23-Jn0069904	B63, storerooms, cement rendered walls – cream paint	0.09% w/w (Non-lead based paint)	N/A
L4-L07	S23-Jn0069905	B63, storerooms, timber windows – white paint	0.06% w/w (Non-lead based paint)	N/A
L4-L08	S23-Jn0069906	B63, storerooms, metal pillars/door frames – green paint	0.32% w/w (Lead based paint)	Fair
L4-L09	S23-Jn0069907	B63, storerooms, concrete ceiling (within ceiling cavity) – white paint	3.8% w/w (Lead based paint)	Poor
Level 5 – Ma	in Building			
L5-L01	S23-Jn0070191	B63, Emergency Department, fire hydrant and door/frames – red paint	0.49% w/w (Lead based paint)	Good
L5-L02	S23-Jn0069976	B63, Emergency Department, concrete columns and walls – pink paint	0.08% w/w (Non-lead based paint)	N/A
L5-L03	S23-Jn0069977	B63, Emergency Department, ceiling cavity, riser cement rendered walls – cream/olive paint	3.5% w/w (Lead based paint)	Poor
L5-L04	S23-Jn0069978	B63, fire stairs, cement rendered walls – cream paint	5.4% w/w (Lead based paint)	Fair
L5-L05	S23-Jn0069979	B63, fire stairs, railings – green paint with cream underlay	7.5% w/w (Lead based paint)	Fair
L5-L06	S23-Jn0069980	B63, Emergency Department, arches, staff rooms and main corridor – dark blue paint	3.0% w/w (Lead based paint)	Fair

Table 4.4: Lead Paint Results Summary Table



Sample ID	Lab ID	Sample Location	Results	Observed Condition
L5-L07	S23-Jn0069981	B63, Emergency Department, window sill, frames and timber windows – white paint	1.8% w/w (Lead based paint)	Fair
<u>Level 6 – Ma</u>	<u>in Building</u>			
L6-L01	S23-Jn0069938	B89, hydrant and sprinkler pipework – red paint	0.01% w/w (Non-lead based paint)	N/A
L6-L02	S23-Jn0069939	B63, roof, external vent pipes – orange paint	3.3% w/w (Lead based paint)	Poor
L6-L03	S23-Jn0069940	B63, roof, external vent grill to plant room – brown paint	<0.01% w/w (Non-lead based paint)	N/A
L6-L04	S23-Jn0069941	B63, external timber windows – white paint	5.3% w/w (Lead based paint)	Poor
L6-L05	S23-Jn0069942	B63, mechanical plant room, AHUs and ductwork – blue paint	0.11% w/w (Lead based paint)	Fair
L6-L06	S23-Jn0069943	B63, mechanical plant room, masonry walls– green/cream paint	1.1% w/w (Lead based paint)	Fair
L6-L07	S23-JI0019836	B63, plant room, double brick walls – cream paint	2.0% w/w (Lead based paint)	Fair
L6-L08	S23-JI0019837	B63, internal timber windows – white paint	3.0% w/w (Lead based paint)	Poor
Level 7 – Ma	in Building			
L7-L01	S23-Jn0069954	B89, plant room, electrical switchboard cabinets – orange paint	4.3% w/w (Lead based paint)	Good
L7-L02	S23-Jn0069955	B89, plant room, high visibility trip hazard paint throughout – yellow paint	<0.01% w/w (Non-lead based paint)	N/A
L7-L03	S23-Jn0069956	B89, sprinkler/hydrant pipework – red paint	0.05% w/w (Non-lead based paint)	N/A
L7-L04	S23-Jn0069957	B89, plant room generators – green paint	0.15% w/w (Lead based paint)	Fair
L7-L05	S23-Jn0069958	B89, fire stair handrails – grey paint	<0.01% w/w (Non-lead based paint)	N/A
L7-L06	S23-Jn0069959	B89, glass staircase, steel frame – blue paint	0.03% w/w (Non-lead based paint)	N/A
Gate House				
GH-L01	S23-Jn0070041	External, timber windows/frames – white paint	<0.01% w/w (Non-lead based paint)	N/A
GH-L02	S23-Jn0070042	Internal, brick walls – white paint	0.09% w/w	N/A

4.1.5 Polychlorinated Biphenyls

Detailed inspection of capacitors in light fittings could not be undertaken due to the electricity supply to the fittings being active. Therefore, PCB containing capacitors are assumed to be present within the older light fittings throughout the site.

4.1.6 Synthetic Mineral Fibres

Suspected SMF materials were identified in various forms throughout the site. Full details of all identified SMF materials are provided in the Hazardous Materials Register (**Appendix A**). The typical forms of SMF identified are summarised below:

- Suspended ceiling tiles;
- Insulation to fixed and flexible air conditioning ducting;
- Insulation to pipework;
- Insulation packing pillows to wall and ceiling penetrations;
- Insulation to wall and roof sarking; and
- Internal insulation to instant and standard hot water systems.



4.2 Inaccessible Areas

Although no specific assessment areas were classified as inaccessible areas, due to the operational nature of the hospital, there was restricted access to some staff and patient areas, primarily within high risk areas of the hospital including the Emergency Department and Intensive Care Units.



5. Conclusions and Recommendations

Based on the scope of this assessment and with reference to the limitations included in **Section 6**, the following conclusions are made with respect to the Hazardous Materials Survey completed.

5.1 Hazardous Materials

Identified and suspected hazardous materials were observed throughout the site as a result of visual identification and laboratory analysis.

The following recommendations are made for the removal of the identified hazardous materials to potentially mitigate harmful effects as a result of the proposed works program. The person with management or control of the site, must ensure so far as is reasonably practicable that the identified hazardous materials are removed prior to the commencement of demolition works.

The identified and suspected hazardous materials are presented in the Hazardous Materials Register included as **Appendix A**.

5.1.1 Asbestos Containing Materials

Friable and Non-friable ACM has been identified in various forms throughout the surveyed areas of the site. Prior to the commencement of demolition works, it is recommended that the following work is undertaken:

- A Class A licensed asbestos removalist shall be engaged to remove all asbestos containing materials as identified in the Hazardous Materials Register (**Appendix A**). Removal and disposal of non-friable asbestos materials shall be undertaken in accordance with the *Work Health and Safety Act* (2011), *Work Health and Safety Regulation* (2017) and SWNSW 2022a.
- A notification to remove friable asbestos shall be submitted to SafeWork NSW by the engaged Class A contractor prior to works commencing. No asbestos removal works should commence until receipt of the accepted notification to remove friable asbestos from SafeWork NSW.
- An asbestos removal control plan is to be developed by the engaged Class A licensed asbestos removalist prior to the removal works, outlining the specific removal methodologies and control measures necessary to minimise any risk from exposure to asbestos.
- Asbestos waste and asbestos impacted waste materials shall be disposed of to an appropriately licensed landfill in accordance with NSW EPA 2014.
- Asbestos air monitoring must be undertaken by the independent Licensed Asbestos Assessor (LAA) during all friable asbestos removal works and is also strongly recommended to be undertaken during non-friable asbestos removal activities.
- Following completion of the friable and non-friable asbestos removal works within assessment area, a clearance inspection shall be undertaken by the independent LAA to ensure that all the asbestos containing materials identified in the Hazardous Materials Register (**Appendix A**) have been removed to a satisfactory industry standard.
- Following the completion of the clearance inspection, a clearance certificate shall be issued by the LAA to confirm that the identified friable and non-friable asbestos hazards have been successfully removed and that each structure is suitable for proposed demolition works to commence.

5.1.2 Lead Containing Dust

No elevated levels of lead in dust above the adopted site criteria were identified at the site.



5.1.3 Lead Based Paints

The lead based paints, as identified in Hazardous Materials Register (**Appendix A**), ranged in condition from poor to good and should be managed in accordance with the AS4361.2-2017. Where peeling or deteriorated they should be removed under controlled conditions by an experienced contractor prior to demolition. Stable lead based paints adhered to building fabric can be disposed as general solid waste in accordance with NSW EPA 2014, provided care is taken to minimise any potential for paint flakes to be dispersed onto ground surfaces and building and demolition waste is not proposed to be recycled.

Where building and demolition wastes are proposed to be recycled that are impacted by lead paints, the lead paints must be stripped prior to off-site disposal. The removed lead paint waste must be disposed of as hazardous waste in accordance with NSW EPA 2014.

5.1.4 Polychlorinated Biphenyls

All old fluorescent light fittings throughout the site are to be treated as containing PCB capacitors unless further investigation confirms otherwise. These light fittings should be removed and disposed of as Scheduled Waste or re-inspected once safe access can be provided to confirm the presence or absence of PCB capacitors.

5.1.5 Synthetic Mineral Fibres

The synthetic mineral fibres encountered during this inspection were generally contained and deemed to be low risk. These SMF materials can be removed with the building and demolition waste with care taken not to generate fibres. Appropriate PPE is recommended including the use of P2 respirator as minimum and appropriate removal methodology as outlined in [NOHSC: 1004(1990)] and [NOHSC: 2006(1990)].

5.2 Inaccessible Areas

Areas inaccessible during the current HBMS should be inspected by a suitably qualified competent person prior to any works commencing. Suspected ACM should be sampled by a suitably qualified competent person prior to any works commencing.

5.3 Unexpected Finds

Any materials deemed to be consistent with those detailed in the Hazardous Materials Register that have not been previously identified should be assumed to have the same content and be treated accordingly.

Should any additional suspected hazardous materials be observed during or prior to demolition works, works should cease until a suitably qualified occupational hygienist can assess the suspected hazardous material and provide appropriate recommendations for management and/or removal.



6. Limitations

This report has been prepared for use by the client who has commissioned the works in accordance with the project brief only, and has been based in part on information obtained from the client and other parties.

The advice herein relates only to this project and all results conclusions and recommendations made should be reviewed by a competent person with experience in environmental investigations, before being used for any other purpose.

JBS&G accepts no liability for use or interpretation by any person or body other than the client who commissioned the works. This report should not be reproduced without prior approval by the client, or amended in any way without prior approval by JBS&G, and should not be relied upon by other parties, who should make their own enquiries.

Sampling and chemical analysis of environmental media is based on appropriate guidance documents made and approved by the relevant regulatory authorities. Conclusions arising from the review and assessment of environmental data are based on the sampling and analysis considered appropriate based on the regulatory requirements.

Limited sampling and laboratory analyses were undertaken as part of the investigations undertaken, as described herein. Ground conditions between sampling locations and media may vary, and this should be considered when extrapolating between sampling points. Chemical analytes are based on the information detailed in the site history. Further chemicals or categories of chemicals may exist at the site, which were not identified in the site history and which may not be expected at the site.

Changes to the subsurface conditions may occur subsequent to the investigations described herein, through natural processes or through the intentional or accidental addition of contaminants. The conclusions and recommendations reached in this report are based on the information obtained at the time of the investigations.

This report does not provide a complete assessment of the environmental status of the site, and it is limited to the scope defined herein. Should information become available regarding conditions at the site including previously unknown sources of contamination, JBS&G reserves the right to review the report in the context of the additional information.



Figures







Appendix A Hazardous Materials Register

JBS&G

JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL		
Level 1	-	-		-			_	-					
Asbestos Conta	ining Materials												
No Asbestos Cor	No Asbestos Containing Materials were identified at the time of inspection												
No Asbestos De	No Asbestos Detected												
L1-A01	Northeast undercroft area, fireproofing to ductwork	Cream vermiculite	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
L1-A02	Northeast undercroft area, fireproofing to ductwork	Grey vermiculite	1	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
L1-A03	Southeast undercroft area	Fibre cement pipe	2	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
L1-A04	Fire pump room, pipework and pumps	Gasket	3	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
L1-A05	Fire pump room, upper north wall	Millboard	4	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Lead Based Pair	ıts												
L1-L03	Fire pump room, pumps	Red/blue paint	5	Yes	-	6.6% w/w	Poor	10 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Non-Lead Based	l Paints												
L1-L01	North undercroft area, hydrant pipework	Red paint	6	Yes	-	0.04% w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 1											
L1-L02	North undercroft area, soil pipework	Red/brown paint	-	Yes	-	<0.01% w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Polychlorinated	Biphenyls (PCBs)										
Detailed inspect	ion of light fittings could nc	ot be undertaken due to activ		Undertake detailed inspection following isolation of electricity supply, <u>OR</u> Handle in accordance with ANZECC 1997	14/6/23 – 29/6/23 JBS&G SL/JG/RS						
Synthetic Miner	ral Fibres (SMF)										
-	Pipework, throughout	Insulation	-	Yes	Bonded	Assumed SMF	Good	>50 lin. m	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
-	Wall and ceiling penetrations, packing pillows	Insulation	-	Yes	Bonded	Assumed SMF	Good	10 m²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
-	Fire pump room, ductwork	Insulation	-	Yes	Bonded	Assumed SMF	Good	100 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	





JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL			
Level 2														
Asbestos Conta	Asbestos Containing Materials													
No Asbestos Containing Materials were identified at the time of inspection.														
No Asbestos Detected														
L2-A01	North lift foyer and corridor, floor	Blue vinyl sheeting	7	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L2-A02	Toilets, walls	Fibre cement sheeting	8	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L2-A03	Carpark and storerooms, pipework	Vermiculite insulation	9	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L2-A04	Internal carpark area, wall expansion joint	Grey mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L2-A05	Fire control room, wall expansion joint	Mastic		Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
EM-01	Adjacent carpark entry, wall expansion joint	Black mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
EM-02	Carpark entry ramp, external wall expansion joint	Black mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
EM-03	EM-03 External precast joint Grey mastic - Yes - No Asbestos Detected - - No further action required 14/6/23 - 29/6/23 JBS&G SL/JG/RS													
Lead Based Paints														
No lead based p	paints were identified at the	time of inspection.												



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL		
Level 2													
Non-Lead Based	Non-Lead Based Paints												
L2-L01	Fire control room, walls	Cream paint	10	Yes	-	< 0.01 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Polychlorinated	Biphenyls (PCBs)												
Detailed inspecti	ion of light fittings could no	t be undertaken due to activ	e electricity su	pply. All light fit	tings should be	assumed to contain PCBs.			Undertake detailed inspection following isolation of electricity supply, <u>OR</u> Handle in accordance with ANZECC 1997	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Synthetic Miner	al Fibres (SMF)												
-	Pipework	Lagging/Insulation	-	Yes	Bonded	Assumed SMF	Good	>50 lin.m	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
-	Ceilings, suspended tiles	Ceiling tiles	11	Yes	Bonded	Assumed SMF	Good	250 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
-	Wall and ceiling penetrations, packing pillows	Insulation	-	Yes	Bonded	Assumed SMF	Good	10 m²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			





JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL			
Level 3														
Asbestos Contai	Asbestos Containing Materials													
No Asbestos Containing Materials were identified at the time of inspection.														
No Asbestos Detected														
L3-A01	B89, north foyer, toilets, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L3-A02	Atrium, wall panels	Fibre cement sheeting	12	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L3-A03	B89, ICU, cleaners and dirty utility rooms, floor	Light blue vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L3-A04	B89, ICU, cleaners and dirty utility room, walls	Cream vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L3-A05	B89, ICU Administration, kitchen, floor	White vinyl floor sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L3-A06	B89, ICU, corridors, storerooms and patient rooms, floor	Light grey vinyl sheeting	13	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L3-A07	B89, ICU, corridors, storerooms and patient rooms, floor	Mottled blue vinyl sheeting	13	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L3-A08	B89, ICU, toilets, cleaners and dirty utility rooms, walls	Fibre cement sheeting	14	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L3-A09	B89, ICU, staff stations and corridors, floor	Green vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L3-AD01	B89, ICU Administration, ceiling cavity	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL		
Level 3	-	-			-			-		-			
L3-AD02	B89, NICU, ceiling cavity	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Lead Containing	g Dust												
L3-AD01	B89, ICU Administration, ceiling cavity	Settled dust	-	Yes	-	130 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
L3-AD02	B89, NICU, ceiling cavity	Settled dust	-	Yes	-	<5 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Lead Based Pair	nts												
No Lead Based I	No Lead Based Paints were identified at the time of inspection												
Polychlorinated	Polychlorinated Biphenyls (PCBs)												
Detailed inspect	tion of light fittings could no	t be undertaken due to activ	e electricity su	pply. All light fit	ttings should be	e assumed to contain PCBs.			Undertake detailed inspection following isolation of electricity supply, <u>OR</u> Handle in accordance with ANZECC 1997	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Synthetic Mine	ral Fibres (SMF)												
-	Kitchens and kitchenettes, instant hot water systems	Internal insulation	15	Yes	Bonded	Assumed SMF	Good	3 units	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
-	Ceilings, throughout	Ceiling tiles	16	Yes	Bonded	Assumed SMF	Good	>400 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
-	Wall and ceiling penetrations, packing pillows	Insulation	-	Yes	Bonded	Assumed SMF	Good	10 m²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
-	Pipework throughout	Lagging/Insulation	-	Yes	Bonded	Assumed SMF	Good	>100 lin.m.	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 3	-										
-	Ceiling cavities, fixed and flexible air conditioning ducting	Insulation	-	Yes	Bonded	Assumed SMF	Good	>100 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 4		-		-	-	-	-	-			-
Asbestos Conta	ining Materials										
L4-A02	B75, plant room, yellow AHU and ductwork, flange joints	Mastic	17/18	Yes	Non-Friable	Chrysotile Asbestos	Fair	<1m²	Remove prior to refurbishment by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A03	B75, plant room, chilled water pipework	Gasket	19/20	Yes	Non-Friable	Chrysotile Asbestos	Fair	<1m ²	Remove prior to refurbishment by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A19	B75, plant room, fire doors, internal core	Millboard	21	Yes	Friable	Chrysotile and Amosite Asbestos Detected	Fair	2m ²	Remove prior to refurbishment by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
As per L4-A19	B75, all fire doors, internal core	Millboard	-	Yes	Friable	Assumed Asbestos	Fair	Unknown	All fire doors throughout B75 assumed to contain asbestos. Remove prior to refurbishment by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
No Asbestos De	etected										
L4-A01	B75, plant room, base of AHU	Mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A04	B75, lift foyer, upper wall infill panels	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A05	B89, main and service corridors, floor	Beige vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A06	B89, main corridor, floor	Black vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A07	B89, utility rooms, floor	Blue vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A08	B89, utility rooms, walls	White vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A09	B89, main corridor, utility room and staff toilets, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 4	-	-	-	-	-		_	-			
L4-A10	B89, service corridor, riser cabinet	Fibre cement sheeting	22	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A11	B89, service corridor, south wall, expansion joint	Mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A12	B89, main plant room, columns, ceiling and ducting	Vermiculite insulation	23	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A13	B89, main plant room, ducting and penetrations	Millboard insulation	24	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A14	B89, south plant room, north wall	Fibre cement sheeting	26	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A15	B89, north plant room, wall lining	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A16	B89, external façade, wall expansion joint	Cream mastic	27	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A17	B89, external façade, wall expansion joint	Black mastic	27	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A18	B89, Café, floor	Light grey vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A20	B89, Digital, Health and Innovation, server room, floor	Blue vinyl sheeting	28	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A21	B89, Radiology Offices, male/female toilets within changeroom, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A22	B89, Radiology Offices, male/female toilets, floor	Blue vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.		MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 4				-			-				
L4-A23	B89, Radiology Offices, kitchen, floor	White vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A24	B89, Anaesthetic offices, toilet walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A25	B63, storerooms, ceiling cavity, fireproofing to steel framework	Vermiculite insulation	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A26	B63, floor throughout	Green vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-A27	B75, plant room, Air Flow Unit, pipework	Hessian	25	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-AD01	B75, plant room, air plenum, floor	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-AD02	B89, main corridor, ceiling cavity	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Lead Containing	g Dust	-	-	-	-	-	-	-	-	-	-
L4-LD01	B75, plant room, air plenum, floor	Settled dust	-	Yes	-	510 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-LD02	B89, main corridor, ceiling cavity	Settled dust	-	Yes	-	100 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Lead Based Pair	nts										
L4-L03	B75, plant room, steam humidifier	Green paint	29	Yes	-	2.9% w/w	Fair	30 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.		



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 4	_	-	_	-	-	-	-	-		-	-
L4-L08	B63, storerooms, metal pillars/door frames	Green paint	30	Yes	-	0.32% w/w	Fair	100 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-L09	B63, storerooms, concrete ceiling (within ceiling cavity	White paint	31	Yes	-	3.8% w/w	Poor	200 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Non-Lead Based	l Paints										
L4-L01	B75, plant room, cable trays	Orange paint	-	Yes	-	0.02 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-L02	B75, plant room, AHU	Yellow paint	-	Yes	-	<0.01 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-L04	B89, main plant room, hydrant and sprinkler pipework	Red paint	-	Yes	-	0.03 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-L05	B89, main plant room, electrical cabinets	Orange paint	-	Yes	-	<0.01 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-L06	B63, storerooms, cement rendered walls	Cream paint	-	Yes	-	0.09 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L4-L07	B63, storerooms, timber windows	White paint	-	Yes	-	0.06 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL			
Level 4	-			-				-						
Polychlorinated	Biphenyls (PCBs)													
Detailed inspect	ion of light fittings could no	t be undertaken due to activ		Undertake detailed inspection following isolation of electricity supply, <u>OR</u> Handle in accordance with ANZECC 1997	14/6/23 – 29/6/23 JBS&G SL/JG/RS									
Synthetic Miner	thetic Mineral Fibres (SMF)													
-	Kitchens and kitchenettes, instant hot water systems	Internal insulation	32	Yes	Bonded	Assumed SMF	Good	4 units	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
-	Ceilings, throughout	Ceiling tiles	33	Yes	Bonded	Assumed SMF	Good	>500 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
-	Wall and ceiling penetrations, packing pillows	Insulation	-	Yes	Bonded	Assumed SMF	Good	10 m²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
-	Pipework throughout	Lagging/Insulation	-	Yes	Bonded	Assumed SMF	Good	>100 lin.m.	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
-	Ceiling cavities, fixed and flexible air conditioning ducting	Insulation	-	Yes	Bonded	Assumed SMF	Good	>200 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS				



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 5	-			-	-		-	-			
Asbestos Conta	ining Materials										
L5-A13	B75, Radiology, main corridor adjacent reception, double fire doors, internal core	Millboard	34	Yes	Friable	Chrysotile and Amosite Asbestos Detected	Fair	6 m²	Remove prior to refurbishment by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
As per L5-A13	B75, all fire doors, internal core	Millboard	-	Yes	Friable	Assumed Asbestos	Fair	Unknown	All fire doors throughout B75 assumed to contain asbestos. Remove prior to refurbishment by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
No Asbestos De	tected										
L5-A01	B89, main corridor, floor	Beige vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A02	B89, main corridor, floor	Black vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A03	B89, north bathrooms, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A04	B89, north west corridor, floor	Black vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A05	B75, adjacent lift foyer, toilets, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A06	B89, Anti and Post Natal wards, utility rooms, store rooms and cleaners, walls	Cream vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A07	B89, Anti and Post Natal wards, sink areas, staff rooms, kitchens, utility rooms and cleaners, floor	Light blue vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A08	B89, Anti and Post Natal wards, floor throughout	Mottled blue vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 5		-							- -		
L5-A09	B89, Anti and Post Natal wards, toilets, bathrooms, cleaners and utility, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A10	B89, electrical risers, floor penetrations	Millboard insulation	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A11	B89, Anti and Post Natal wards, ceiling cavity, fireproofing to ductwork	Vermiculite insulation	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A12	B89, unisex changeroom/toilet, wall linings	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A14	B75, Radiology, reception area, staff toilet, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A15	B89, Radiology, booking desk reception area, floor	Green vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A16	B89, Radiology, central portion, riser in corridor, wall expansion joint	Grey mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A17	B89, Radiology, waiting room, staff desk platform, floor	Red vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A18	B89, Pathology, fire door	Black mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A19	B63, Children's Emergency Department, doffing ward, storeroom 1, wall lining	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A20	B63, Children's Emergency Department, children's play area corridor, wall lining	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A21	B63, Emergency Department, waiting area, plaster room and toilets, wall lining	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 5	-	-	-	-			-	-			
L5-A22	B63, Emergency Department, utility rooms, floor	Dark blue vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A23	B63, Emergency Department, quarantine room/toilet, floor	Light grey vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A24	B63, Emergency Department, main corridor, floor	Dark grey vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-A25	B75, Emergency Department, resuscitation area, floor	Dark grey speckle vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-AD01	B89, main corridor, ceiling cavity	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-AD02	B89, Anti and Post Natal wards, ceiling cavity	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Lead Containing	g Dust										
L5-LD01	B89, main corridor, ceiling cavity	Settled dust	-	Yes	-	100 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-LD02	B89, Anti and Post Natal wards, ceiling cavity	Settled dust	-	Yes	-	40 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Lead Based Pair	nts		-	-	-		-	-		-	-
L5-L01	B63, Emergency Department, fire hydrant and door/frames	Red paint	35	Yes	-	0.49% w/w	Good	100 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 5			-	-	-					-	
L5-L03	B63, Emergency Department, ceiling cavity, riser cement rendered walls	Cream/olive paint	36	Yes	-	3.5% w/w	Poor	50 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-L04	B63, fire stairs, cement rendered walls	Cream paint	37	Yes	-	5.4% w/w	Fair	100 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-L05	B63, fire stairs, railings	Green paint with cream underlay	37	Yes	-	7.5% w/w	Fair	20 m ²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L5-L06	B63, Emergency Department, arches, staff rooms and main corridor	Dark blue paint	38	Yes	-	3.0% w/w	Fair	400 m ²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 5			-	-	_	-	-	-			
L5-L07	B63, Emergency Department, window sill, frames and timber windows	White paint	39	Yes	-	1.8% w/w	Fair	100 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Non-Lead Based	d Paints										
L5-L02	B63, Emergency Department, concrete columns and walls	Pink paint	-	Yes	-	0.08 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Polychlorinated	l Biphenyls (PCBs)	-	-	-	-		-	-	-	-	-
Detailed inspect	tion of light fittings could nc	ot be undertaken due to activ	e electricity su	ıpply. All light fit	tings should be	e assumed to contain PCBs.			Undertake detailed inspection following isolation of electricity supply, <u>OR</u> Handle in accordance with ANZECC 1997	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Synthetic Mine	ral Fibres (SMF)								•	•	•
-	Kitchens and kitchenettes, instant hot water systems	Internal insulation	40	Yes	Bonded	Assumed SMF	Good	5 units	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
-	Ceilings, throughout	Ceiling tiles	41	Yes	Bonded	Assumed SMF	Good	>500 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
-	Wall and ceiling penetrations, packing pillows	Insulation	-	Yes	Bonded	Assumed SMF	Good	10 m²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
-	Pipework throughout	Lagging/Insulation	-	Yes	Bonded	Assumed SMF	Good	>200 lin.m.	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
-	Ceiling cavities, fixed and flexible air conditioning ducting	Insulation	42	Yes	Bonded	Assumed SMF	Good	>300 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 6				-	-		-	-		-	
Asbestos Conta	ining Materials										
L6-A15	B63, Nuclear Medicine, small laboratory storage room, timber windows	Mastic	43	Yes	Non-Friable	Chrysotile Asbestos Detected	Fair	5 m²	Remove prior to refurbishment by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
B64-L6-ROOF- ASB01 (SEG 2022b)	Between B63 & B64, flat roof, waterproofing membrane underlying non-ACM surface membrane	Bituminous membrane	46	Yes	Non-Friable	Chrysotile Asbestos	Fair	80 m²	Remove prior to refurbishment by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
-	B63, storeroom adjacent Nuclear Medicine, pipework	Insulation lagging	44	Yes	Friable	Assumed Asbestos	Fair	15 lin.m (visible)	Assumed asbestos lagged pipework observed within a storeroom adjacent the Nuclear Medicine assessment area. There is the potential for additional asbestos lagged pipework to be concealed within the assessment areas located across B63. Remove prior to refurbishment by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
No Asbestos De	tected	•		-				<u>•</u>	•	·	
L6-A01	B89, north toilets, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A02	B89, Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/ Vascular Ward and Renal Ward, floor	Mottled blue vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A03	B89, Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/ Vascular Ward and Renal Wards, sink areas, utility rooms, cleaners and kitchen, floor	Light blue vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 6	-	-					-				
L6-A04	B89, Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/ Vascular Ward and Renal Ward, utility rooms, store room areas and cleaners, walls	Brown vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A05	B89, Cardiac Catheter Laboratory, CCU, Cardiology Ward, Cardiothoracic/ Vascular Ward and Renal Ward, bathrooms, showers, toilets, cleaners and utility rooms, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A06	B89, fire stairs	Wall expansion joint	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A07	B63, mechanical plant room, external wall cladding	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A08	B63, roof guttering, debris	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A09	B89, flat roof, underlying surface pebble layer	Felt membrane	45	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A10	B63, external timber windows	Putty	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A11	Between B63 & B64, west roof, surface waterproofing membrane	Bituminous membrane	46	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A12	B75, Cardiac Vascular Bay, staff toilets, walls	Fibre cement sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A13	B63, Nuclear Medicine, kitchenette and laboratory floor	Grey vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 6		-	-	-	-		-	-			
L6-A14	B63, plant room, wall cavity	Fibrous material	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-A16	B63, plant room, AHUs	Vermiculite insulation	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-AD01	B89, main corridor, ceiling cavity	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-AD02	B89, Cardiology Ward, Cardiothoracic/ Vascular Ward and Renal Ward, ceiling cavity	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-AD03	B75, Cardiac Vascular Day Stay, ceiling cavity	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Lead Containing	Dust										
L6-LD01	B89, main corridor, ceiling cavity	Settled dust	-	Yes	-	49 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-LD02	B89, Cardiology Ward, Cardiothoracic/ Vascular Ward and Renal Ward, ceiling cavity	Settled dust	-	Yes	-	56 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-LD03	B75, Cardiac Vascular Day Stay, ceiling cavity	Settled dust		Yes	-	29 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Lead Based Pain	ts	-	-	-	_		-	-	-		
L6-L02	B63, roof, external vent pipes	Orange paint	47	Yes	-	3.3% w/w	Poor	10 lin. m.	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



DATE OF CONTROL

ACTION &/OR

REMOVAL

DATE OF LAST

INSPECTION (INCL.

COMPANY NAME

JBS&G SAMPLE NO. LOCATION MATERIAL DESCRIPTION PHOTO NUMBER AREA? FRIABILITY ANALYTICAL RESULT

										AND INITIALS)	
Level 6											
L6-L04	B63, external timber windows	White paint	48	Yes	-	5.3% w/w	Poor	50 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-L05	B63, mechanical plant room, AHUs and ductwork	Blue paint	49	Yes	-	0.11% w/w	Fair	100 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-L06	B63, mechanical plant room, masonry walls	Green/cream paint	50	Yes	-	1.1% w/w	Fair	100 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
L6-L07	B63, plant room, double brick walls	Cream paint	51	Yes	-	2.0% w/w	Fair	200 m ²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	

MATERIAL

CONDITION

APPROX.

QUANTITY

ACTION REQUIRED



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL		
Level 6	-		-	-	-		-						
L6-L08	B63, internal timber windows	White paint	52	Yes	-	3.0% w/w	Poor	50 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Non-Lead Based Paints												B63, inte	
L6-L01	B89, hydrant and sprinkler pipework	Red paint	-	Yes	-	0.01 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
L6-L03	B63, roof, external vent grill to plant room	Brown paint	-	Yes	-	<0.01 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Polychlorinated	Polychlorinated Biphenyls (PCBs)												
Detailed inspect	Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings could not be undertaken due to active electricity supply. All light fittings should be assumed to contain PCBs. Detailed inspection of light fittings should be assumed to contain PCBs. Detailed inspection of light fittings should be assumed to contain PCBs. Detailed inspection of light fittings should be assumed to contain PCBs.												
Synthetic Miner	al Fibres (SMF)								-	-			
-	Kitchens and kitchenettes, instant hot water systems	Internal insulation	53	Yes	Bonded	Assumed SMF	Good	3 units	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
-	Ceilings, throughout	Ceiling tiles	54	Yes	Bonded	Assumed SMF	Good	>500 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
-	Wall and ceiling penetrations, packing pillows	Insulation	-	Yes	Bonded	Assumed SMF	Good	10 m²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
-	Pipework throughout	Lagging/Insulation	-	Yes	Bonded	Assumed SMF	Good	>200 lin.m.	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS			



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Level 6	-	-									
-	Ceiling cavities, fixed and flexible air conditioning ducting	Insulation	-	Yes	Bonded	Assumed SMF	Good	>300 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
-	Roof sarking	Insulation	-	Yes	Bonded	Assumed SMF	Good	400 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL			
Level 7	-		2	-			-	-						
Asbestos Conta	Asbestos Containing Materials													
No Asbestos Containing Materials were identified at the time of inspection.														
No Asbestos Detected														
L7-A01	B89, plant room, fireproofing to ductwork	Vermiculite insulation	55	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L7-A02	B89, plant room, fireproofing panels to ductwork and penetrations	Millboard insulation	56	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L7-A03	B89, plant room, sealant to ductwork flange joints	Mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L7-A04	B89, plant room, expansion joints in concrete block walls	Mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L7-A05	B89, plant room, fire doors, internal core	Internal insulation	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L7-A06	B89, flat roof, beneath surface pebble layer, waterproofing membrane	Felt membrane	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L7-A07	B89, glass staircase, floor	Cream vinyl sheeting with speckle	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L7-A08	B89, glass staircase, perimeter sealant	Mastic	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L7-A09	B63, Nuclear Medicine, floor throughout	Blue speckled vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				
L7-A10	B63, Nuclear Medicine, X-ray room, floor	Orange vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS				



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL		
Level 7	-		_	-	-				-				
L7-A11	B63, Nuclear Medicine, lower splash walls	White vinyl sheeting	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
L7-AD01	B89, plant room, floor	Settled dust	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Lead Containing Dust													
L7-LD01	B89, plant room, floor	Settled dust	-	Yes	-	190 mg/kg	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Lead Based Pain	Lead Based Paints												
L7-L01	B89, plant room, electrical switchboard cabinets	Orange paint	57	Yes	-	4.3% w/w	Good	20 m ²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
L7-L04	B89, plant room generators	Green paint	58	Yes	-	0.15 w/w	Fair	30 m²	Remove loose and flaking paint prior to refurbishment by an experienced hazardous materials removal contractor in accordance with AS4361.2-2017. Remaining paint well adhered to the building materials may be demolished if care is taken not to spread paint flakes to surrounding areas.	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
Non-Lead Based	l Paints												
L7-L02	B89, plant room, high visibility trip hazard paint throughout	Yellow paint	-	Yes	-	<0.01 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			
L7-L03	B89, sprinkler/hydrant pipework	Red paint	-	Yes	-	0.05 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS			



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL	
Level 7												
L7-L05	B89, fire stair handrails	Grey paint	-	Yes	-	<0.01 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS		
L7-L06	B89, glass staircase, steel frame	Blue paint	-	Yes	-	0.03 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS		
Polychlorinated	Polychlorinated Biphenyls (PCBs)											
Detailed inspect	ion of light fittings could no	t be undertaken due to activ		Undertake detailed inspection following isolation of electricity supply, <u>OR</u> Handle in accordance with ANZECC 1997	14/6/23 – 29/6/23 JBS&G SL/JG/RS							
Synthetic Miner	ral Fibres (SMF)											
-	Kitchens and kitchenettes, instant hot water systems	Internal insulation	59	Yes	Bonded	Assumed SMF	Good	2 units	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS		
-	Ceilings, throughout	Ceiling tiles	-	Yes	Bonded	Assumed SMF	Good	>100 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS		
-	Wall and ceiling penetrations, packing pillows	Insulation	-	Yes	Bonded	Assumed SMF	Good	10 m²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS		
-	Pipework throughout	Lagging/Insulation	-	Yes	Bonded	Assumed SMF	Good	>100 lin.m.	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS		
-	Ceiling cavities, fixed and flexible air conditioning ducting	Insulation	-	Yes	Bonded	Assumed SMF	Good	>100 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS		
-	B89, plant room, roof and wall sarking	Insulation	60	Yes	Bonded	Assumed SMF	Good	400 m ²	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS		
Hazardous Materials Register (Rev A) **RPA Hospital Redevelopment – Main Works** RPA Hospital, Missenden Road, Camperdown NSW **Gate House Building** Date of Production – 16th August 2023



JBS&G SAMPLE NO.	LOCATION	MATERIAL DESCRIPTION	PHOTO NUMBER	ACCESSIBLE AREA?	FRIABILITY	ANALYTICAL RESULT	MATERIAL CONDITION	APPROX. QUANTITY	ACTION REQUIRED	DATE OF LAST INSPECTION (INCL. COMPANY NAME AND INITIALS)	DATE OF CONTROL ACTION &/OR REMOVAL
Gate House				-	-		-	-			-
Asbestos Conta	ining Materials										
GH-A02	Eaves	Fibre cement sheeting		Yes	Non-Friable	Chrysotile Asbestos	Poor	20 m²	Remove prior to demolition by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
GH-A04	Ceiling	Fibre cement sheeting		Yes	Non-Friable	Chrysotile Asbestos	Fair	30 m²	Remove prior to demolition by a Class A licensed removal contractor in accordance with SWNSW 2022a.	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
No Asbestos De	tected										
GH-A01	External, windows	Putty	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
GH-A03	Internal, floor	Blue vinyl floor tiles	-	Yes	-	No Asbestos Detected	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Non-Lead Based	l Paints										
GH-L01	Timber windows/frames	White paint	-	Yes	-	<0.01 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
GH-L02	Internal brick walls	White paint	-	Yes	-	0.09 % w/w	-	-	No further action required	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Polychlorinated	Biphenyls (PCBs)		-	-	-		-	-		-	-
Detailed inspect	ion of light fittings could no	it be undertaken due to activ	e electricity su	ıpply. All light fit	ttings should be	e assumed to contain PCBs.			Undertake detailed inspection following isolation of electricity supply, <u>OR</u> Handle in accordance with ANZECC 1997	14/6/23 – 29/6/23 JBS&G SL/JG/RS	
Synthetic Mine	ral Fibres (SMF)										
-	Kitchenette, instant hot water system	Internal insulation	-	Yes	Bonded	Assumed SMF	Good	1 unit	Remove in accordance with NOHSC:2006 (1990)	14/6/23 – 29/6/23 JBS&G SL/JG/RS	



Appendix B Photographs



Photo 1: Level 1 – Northeast undercroft, Non-asbestos containing vermiculite fireproofing to ductwork,



Photo 2: Level 1 – Southeast undercroft, Non asbestos containing fibre cement pipe



Photo 3: Level 1 – Fire pump room, Non asbestos containing gasket to pipework/pumps



Photo 4: Level 1 – Fire pump room, Non-asbestos containing millboard to the upper north wall



Photo 5: Level 1 – Fire pump room, Lead based red paint to pumps



Photo 6: Level 1 – North undercroft, Non-lead based red paint to hydrant pipework





Photo 7: Level 2 – North lift foyer and corridor, Non asbestos containing blue vinyl sheeting to floor



Photo 8: Level 2 - Toilets, Non asbestos containing fibre cement sheeting to walls



Photo 9: Level 2 – Carpark storerooms, Non asbestos containing vermiculite insulation to pipework and air con ducting



Photo 10: Level 2 - Fire control room, Non-lead based cream paint to walls



Photo 11: Level 2 - Assumed SMF insulation to the ceiling tiles throughout



Photo 12: Level 3 – B89 Atrium, Non asbestos containing fibre cement sheeting to wall panels

			© JBS	© JBS&G
Source:			Appendix B: Photographs	raphs
			Client: CPB Contractors	
			Project: RPA Hospital Redevelopment Main Works Hazmat	
0 Original Issue - Rev Description	JG Drn.	15/8/2023 Date	Job No: 63888 File Name: App B - Photo Log	



Photo 13: Level 3 – B89, ICU, Non asbestos containing light grey and mottled blue vinyl sheeting to floor



Photo 14: Level 3 – B89, ICU toilets, Non asbestos containing fibre cement sheeting to walls



Photo 15: Level 3 – B89, ICU kitchen, Internal SMF insulation to Zip hydrotap



Photo 16: Level 3 – B89, ICU Admin, Assumed SMF insulation to ceiling tiles



Photo 17: Level 4 – B75 plant room, Asbestos containing mastic to yellow AHU



Photo 18: Level 4 - B75 plant room, Asbestos containing mastic to ductwork





Photo 19: Level 4 - B75 plant room, Asbestos containing gasket to chilled water pipework



Photo 20: Level 4 - B75 plant room, Asbestos containing gasket to chilled water pipework



Photo 21: Level 4 – B75 plant room, Asbestos containing millboard core to fire doors



Photo 22: Level 4 - B89 service corridor, Non asbestos containing fibre cement sheeting to riser cabinet



Photo 23: Level 4 - B89 main plant room, Non asbestos containing vermiculite insulation to columns, ceiling and ducting



Photo 24: Level 4 - B89 main plant room, Non asbestos containing millboard insulation

						© JBS&G
-	Sour	ce:			GJBS &	Appendix B: Photographs
F					Client: CPB Contractors	
ļ					Project: RPA Hospital Red	evelopment Main Works Hazmat
ł	0 Rev	Original Issue - Description	JG Drn.	15/8/2023 Date	Job No: 63888	File Name: App B - Photo Log



Photo 25: Level – B75 main plant room, Non asbestos containing hessian within air flow unit



Photo 26: Level 4 – B89 south plant room, Non asbestos containing fibre cement sheeting to the north wall



Photo 27: Level 4 - Non asbestos containing cream and black mastic to the external façade panels



Photo 28: Level 4 – B89, Digital, Health and Innovation, Non asbestos containing blue vinyl floor to the server room



Photo 29: Level 4 - B75 plant room, Lead based green paint to the air plenum



Photo 30: Level 4 – B63, Lead based green paint to door frames and pillars





Photo 31: Level 4 – B63, storerooms, Lead based white paint to the concrete ceiling within ceiling cavity



Photo 32: Level 4 – Assumed SMF insulation to the hot water units throughout



Photo 33: Level 4 – Assumed SMF insulation to the ceiling tiles throughout



Photo 34: Level 5 – B75 Radiology, main corridor, Asbestos containing internal millboard to the double fire doors



Photo 35: Level 5 – B63 Emergency Department, Lead based red paint to hydrant and door/frames



Photo 36: Level 5 – B63 Emergency Department – Lead based cream/olive paint to the riser walls in ceiling cavity





Photo 37: Level 5 - B63, Lead based cream and green paint to the cement rendered walls and the railings to stairwell



Photo 38: Level 5 - B63 Emergency Department, Lead based dark blue paint to the arches throughout the main corridor and staff rooms



Photo 39: Level 5 - B63 Emergency Department, Lead based white paint to the timber windows



Photo 40: Level 5 – Assumed SMF internal insulation to the hot water unit's throughout



Photo 41: Level 5 - Assumed SMF internal insulation to the ceiling tiles throughout



Photo 42: Level 5 - Assumed SMF insulation to the flexible air con ducting and pipework

© JBS&G





Photo 43: Level 6 – B63 Nuclear Medicine, Asbestos containing mastic to the timber windows in the small laboratory store room



Photo 44: Level 6 – B63 store room adjacent Nuclear Medicine, Assumed asbestos containing lagged pipework



Photo 45: Level 6 – B89 Roof – Non-asbestos containing felt membrane beneath pebbles



Photo 46: Level 6 – B63/B64 West Roof – Asbestos containing bituminous waterproofing membrane underlying the surface non asbestos containing bituminous membrane



Photo 47: Level 6 – B63, Lead based orange paint to the external vent pipes



Photo 48: Level 6 – B63, Lead based white paint to the external timber windows

					© JBS&G
:	Source:			JBS&C	Appendix B: Photographs
F				Client: CPB Contractors	
ļ				Project: RPA Hospital Red	evelopment Main Works Hazmat
┢	0 Original Issue -	JG	15/8/2023 Data	Job No: 63888	File Name: App B - Photo Log



Photo 49: Level 6 - B63 Mechanical Plant Room, Lead based blue paint to the AHUs and ductwork



Photo 50: Level 6 - B63 Mechanical Plant Room, Lead based green/cream paint to the masonry walls



Photo 51: Level 6 - B63 Plant Room, Lead based cream paint to the double brick walls



Photo 52: Level 6 - B63 Nuclear Medicine, Lead based white paint to the internal timber windows

Source:



Photo 53: Level 6 - Assumed SMF internal insulation to the hot water units throughout



Photo 54: Level 6 - Assumed SMF internal insulation to the ceiling tiles throughout



© JBS&G



Photo 55: Level 7 – Plant Room, Non asbestos containing vermiculite insulation



Photo 56: Level 7 – Plant Room, Non asbestos containing millboard insulation



Photo 57: Level 7 – Plant Room, Lead based orange paint to the electrical cabinets



Photo 58: Level 7 - Plant Room, - Lead based green paint to the generators



Photo 59: Level 7 – Assumed SMF internal insulation the hot water units throughout



Photo 60: Level 7 - Assumed SMF insulation sarking to the roof and walls





Photo 61: Gate House Overview



Photo 62: Gate House – Asbestos containing fibre cement sheeting to the eaves



Photo 63: Gate House – Asbestos containing fibre cement sheeting to the ceiling

Sc	urce:				JBS&C	Appendix B: Photographs
F					Client: CPB Contractors	
					Project: RPA Hospital Rede	velopment Main Works Hazmat
_ C	Original Issue	-	JG	15/8/2023	Joh No: 62888	File Name: Ann B. Dhota Lag
Re	v Description		Drn.	Date	JUD INU. 03008	File Name: Арр Б - Photo Log

© JBS&G



Appendix C Laboratory Analysis Reports and Chain of Custody Documentation

lage 1 of 9



PROJECT NO.: 63888						U	ABO	RAT	ORY R	ATC	INO				-	-	10.0			-		
PROJECT NAME: RPA HOSPITA	L - MAIN BL	JILDING				S	AM	PLER	S: Stu	art L	umsr	len/h	ordan	Gon	07	-	-					
DATE NEEDED BY: STANDARD	TAT					0	CLE	VEL:	NEPM	(201	3)	ieny a	n wan	Gui	ICL		_					
PHONE: Sydney: 02 8245 03	00 Perth:	08 9488 010	0 Brisbar	ne: 07 3112 2688	History -					1002												
SEND REPORT & INVOICE TO: (1) adminnsw	@jbsg.com.au	; (2) <u>slums</u> d	len@jbsg.com.au; (3) jgomez(@jbsg.com	au;																
COMMENTS / SPECIAL HANDLING / STO	RAGE OR DISPOS	SAL:				Г	T	1		T	TT	1	TT	T	T		T	TT	TY	PE OF	1	
																			AS AP	BESTOS	4	
1						ß															1	
1						ដ្រ													IC F			
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	ASBE	LEAD					2							Diaman	NEPM/WA		
L1-A01	Material	28/6/23		1 x bag		x	1			+	+ +		+ +	-	+		-	+-+	+		NOTES:	
L1-A02	Material	28/6/23		1 x bag		x	1			-	+-+			-	-	-	-	++		+		
L1-A03	Material	28/6/23		1 x bag		x	1	-		+			+ +		+			++	+			
L1-A04	Material	28/6/23		1 x bag		x	1		_	+	+ +		+ +	-	-		-	++		+-		
L1-A05	Material	28/6/23		1 x bag		x	1		-	+			+	-	+		-	++	+			
L1-L01	Paint	28/6/23		1 x bag			x			+	+		+ +	-		-	-	++	-	+		
L1-L02	Paint	28/6/23		1 x bag			x		-		+	-	+	+	+ +	+	+	++	+	+		
L1-L03	Paint	28/6/23		1 x bag			x			+-			++		+		+	++	-	+		
L2-A01	Material	28/6/23		1 x bag		x	ŕ-					-	++	+			+	+++		+		
L2-A02	Material	28/6/23		1 x bag		X				+	+		++	+	+	-		++	+	+		
L2-A03	Material	28/6/23		1 x bag		X				+-			+				+	++	-	+		
L2-A04	Material	28/6/23		1 x bag		x	1			1		-	++	+-			+	++		+		
L2-A05	Material	28/6/23		1 x bag		X				+	+	-11	+			+	+-	+++	-	+		
L2-L01	Paint	28/6/23		1 x bag			x			-	+			+		+	+	++	+	+		
L3-A01	Material	28/6/23		1 x bag		X				+-				+-			+	++	-	+		
L3-A02	Material	28/6/23		1 x bag		X				+			+	+			1	+		+		
L3-A03	Material	28/6/23		1 x bag		X			-	1						-	-	+-+		+		
L3-A04	Material	28/6/23		1 x bag		X				+		+	++	+		-	-			+-1		
L3-A05	Material	28/6/23		1 x bag		X				1				+	+	+	+	\vdash		+		
RELINQUISHED BY	1:			METHOD OF SHIPMENT:	_			_	RECE	IVED	BY:			_		-	SOP	PEPEI	VINC	100	CC CANNA	
NAME: Stuart Lymsden DATE: 70	16/23	CONSIG	NMENT NOTE	ENO.		NA	ME:	R	ein	no.	« 1		4	CÖÖL	R SEA	L-Ye		10	. Int	act,	Broken	
OF: JBS&G G	101-1	TRANSP	ORT CO.			DA	TE:	¢	in	_	Y		i.	coou	D TEA	n K	A	-				
NAME: DATE:		CONSIG	NMENT NOTE	ENO.		NA	ME:	~			DA1	E:		COOL	ER SEA	L – Ye		10	., In	tact	Broken	
OF:		TRANSP	ORT CO			-1								COOL	R TEN	1P	deg	:				
IMSO FormsO13 - Chain of Custody - G	istic; J = Soli Jar; ieneric	B = Glass Bottle; I	ł = Nitric Acid P	rsvd.; C = Sodium Hydroxide Prsvd; VC =	Hydrochloric	Acid	Prsvo	Vial;	VS = Sul	furic A	cid Prsv	d Vial; S	= Sulfur	ic Acid	Prsvd;	z = Zino	Prsvd	; E = ED	TA Prs	/d; 5 T :	= Sterile Bottle; O = Othe	er

1003655

lage 2059 \$JBS&G

PROJECT NO.: 63888						LA	ABO	RA	TORY BA	TCH	NO.:									
PROJECT NAME: RPA HOSPIT	AL - MAIN BU	ILDING				SA	AMI	PLE	RS: <mark>Stua</mark>	rt Lui	msde	n/Jord	lan Ge	mez						
DATE NEEDED BY: STANDARD	TAT					Q	CLE	VEL	: NEPM (2013)										
PHONE: Sydney: 02 8245 0	300 Perth: (08 9488 010	0 Brisba	ne: 07 3112 2688						_	_		_	_	_				_	
SEND REPORT & INVOICE TO:	(1) adminnsw(@jbsg.com.au	; (2) slums	den@jbsg.com.au; (3) jgomez@	@jbsg.com	au;								-				-	and the second second	
COMMENTS / SPECIAL HANDLING / ST	ORAGE OR DISPOS	AL:				BESTOS	9	3										AS AN NOLLOGI	PEOF BESTOS BALYSIS	
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	ASE	LEA												NEPM	NOTES:
L3-A06	Material	28/6/23		1 x bag		х														
L3-A07	Material	28/6/23		1 x bag		X														
L3-A08	Material	28/6/23		1 x bag		X														
L3-A09	Material	28/6/23		1 x bag		x														
L3-AD01	Dust	28/6/23		1 x bag		x														
L3-AD02	Dust	28/6/23		1 x bag		X														
L3-LD01	Dust	28/6/23		1 x bag			X													
L3-LD02	Dust	28/6/23		1 x bag			X													
L4-A01	Material	28/6/23		1 x bag		х														
L4-A02	Material	28/6/23		1 x bag		х														
L4-A03	Material	28/6/23		1 x bag		х														
L4-A04	Material	28/6/23		1 x bag		X														
L4-A05	Material	28/6/23		1 x bag		X														
L4-A06	Material	28/6/23		1 x bag		X														
L4-A07	Material	28/6/23		1 x bag		х														
L4-A08	Material	28/6/23		1 x bag		X														
L4-A09	Material	28/6/23		1 x bag		х														
L4-A10	Material	28/6/23		1 x bag		X														
L4-A11	Material	28/6/23		1 x bag		х	T													
RELINQUISHED	BY: A lalan		4	METHOD OF SHIPMENT:					RECE	IVED B	Y:				1.1.1.1	FC	R RECE	IVING	LAB	JSE ONLY:
NAME: Stuart Lumsden DATE: OF: JBS&G	29/6/23	CONSI	SNMENT NO	DTE NO.		N D O	AME ATE: F:	E: :					C	DOLER	SEAL -	Yes dej	No g C	ven lit	ntact .	name Broken and and a
NAME: DATE: OF:		CONSI	SNMENT NO	DTE NO.		N. O	AME F:	E:			DATI	:	0	DOLER	SEAL -	Yes	No		ntact	arman Broken annanan
Container & Preservative Codes: P =	Plastic; J = Soli Jar	; B = Glass Bottle;	N = Nitric Aci	d Prsvd.; C = Sodium Hydroxide Prsvd; VC	: = Hydrochio:	ic Aci	d Prs	svd V	al; VS = Su	turic Ac	d Prsvo	r Vial; 5 =	Sulfuric	Acid Pi	svd; Z =	ZINC Prs	vd; E = E	DTA Pr	svd; S	i = stenie Bottle; O = Other

Page 3 of 9



PROJECT NO.: 63888						LA	ABC	ORA	TORY BA	TCH	NO.:				-							
PROJECT NAME: RPA HOSP	ITAL - MAIN BU	ILDING				S/	AM	PLE	RS: Stua	rt Lui	msde	n/Jord	lan G	iome	?Ż							
DATE NEEDED BY: STANDA	RD TAT					Q		EVEI	: NEPM (2013)	C				_							
PHONE: Sydney: 02 8245	0300 Perth: 0	08 9488 010	0 Brisba	ne: 07 3112 2688														_			_	
SEND REPORT & INVOICE TO	D: (1) adminnsw@	@jbsg.com.au	; (2) <u>slums</u>	den@ibsg.com.au; (3) _igomez@	Dibsg.com	.au;															_	
COMMENTS / SPECIAL HANDLING /	STORAGE OR DISPOS	AL:				BESTOS	AD	2												VPE OF ISBEST(INALYS	F OS SIS V/W	
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	R		3												80	E	NOTES:
L4-A12	Material	28/6/23		1 x bag		Х																
L4-A13	Material	28/6/23		1 x bag		х																
L4-A14	Material	28/6/23		1 x bag		Х																
L4-A15	Material	28/6/23		1 x bag		х																
L4-A16	Material	28/6/23		1 x bag		x																
L4-A17	Material	28/6/23		1 x bag		X																
L4-A18	Material	28/6/23		1 x bag		x																
L4-A19	Material	28/6/23		1 x bag		x																
L4-A20	Material	28/6/23		1 x bag		x																
L4-A21	Material	28/6/23		1 x bag		x	T							1							T	
L4-A22	Material	28/6/23		1 x bag		X																
L4-A23	Material	28/6/23		1 x bag	-	x	1												\square		T	
L4-A24	Material	28/6/23		1 x bag		X																
L4-A25	Material	28/6/23		1 x bag		х																
L4-A26	Material	28/6/23		1 x bag		X	1															
L4-AD01	Dust	28/6/23		1 x bag		X																
L4-AD02	Dust	28/6/23		1 x bag		X															Т	
L4-LD01	Dust	28/6/23		1 x bag			X															
L4-LD02	Dust	28/6/23		1 x bag			X															
RELINQUISH	ED BY: / /			METHOD OF SHIPMENT:					RECE	IVED B	Y:						FO	R REC	EIVIN	GLA	B US	E ONLY:
NAME: Stuart Lumsden DATE	29/6/25	CONSI	GNMENT NO	DTE NO.		N D O	NAM DATE DF:	IE: E:						COOLI	er se/ er tei	VL – Ye VIP	deg	No	51¥A7	Intaci	it	Broken
NAME: DATE	5	CONSIG	SNMENT NO	DTE NO.		N O	VAM DF:	IE:			DATE				er se/ er tei	VL - Ye	deg	No	10221	Intac	ct	Broken
Container & Preservative Codes:	P = Plastic; J = Soli Jar;	; B = Glass Bottle;	N = Nitric Aci	id Prsvd.; C = Sodium Hydroxide Prsvd; VC	= Hydrochior	nc Aci	cid Pr	rsvd \	/ial; VS = Su	ITURIC AC	d Prsva	i Vial; S	sulfu	ic Acid	Prsvd;	z = Zin	IC Prs	(d; E =	LUTA	rrsvd;	: 51 =	Sterile Bottle; U = Other

Page 4 of 9



PROJECT NO.: 63888						LA	ABC	RATO	ORY BA	TCH	NO.:								-		
PROJECT NAME: RPA HOSPITA	AL - MAIN BU	ILDING				SA	M	PLERS	5: Stua	rt Lui	msde	n/Jor	dan (iome	Z						
DATE NEEDED BY: STANDARD	TAT					Q	C LE	VEL:	NEPM (2013)											
PHONE: Sydney: 02 8245 03	00 Perth: 0	08 9488 0100) Brisba	ne: 07 3112 2688																	
SEND REPORT & INVOICE TO: (1) adminnsw(@jbsg.com.au	; (2) <u>slums</u>	den@jbsg.com.au; (3) jgomez@	Djbsg.com.	au;									Venter				-	-	
COMMENTS / SPECIAL HANDLING / STO	RAGE OR DISPOS	AL:				S													TYPE C ASBEST ANALY	JF TOS /SIS	
SAMOLE ID	MATRIX	DATE	TIAAE		Ph	ASBESTC	FAD												DENTIFICATIO	EPM/WA	
	ININ CRIM	DAIL	S IIVIC		_	-	-		_	+-+		-	_	+-		-		+		4	NOTES:
L4-L01	Paint	28/6/23		1 x bag			X	-		+-+			_			+			_+	\rightarrow	
L4-L02	Paint	28/6/23		1 x bag			X			+		-									
L4-L03	Paint	28/6/23		1 x bag	_		X	-			_					-		-		_	
L4-L04	Paint	28/6/23		1 x bag			Х												$ \downarrow \downarrow$		
L4-L05	Paint	28/6/23		1 x bag		_	Х				_	_		_		-		-			
L4-L06	Paint	28/6/23		1 x bag			Х								9F						
L4-L07	Paint	28/6/23		1 x bag			Х														
L4-L08	Paint	28/6/23		1 x bag			Х														
L4-L09	Paint	28/6/23		1 x bag			X														
L5-A01	Material	28/6/23		1 x bag		х															
L5-A02	Material	28/6/23		1 x bag		х															
L5-A03	Material	28/6/23		1 x bag		х														Т	
L5-A04	Material	28/6/23		1 x bag		х															
L5-A05	Material	28/6/23		1 x bag		х															
L5-A06	Material	28/6/23		1 x bag		х															
L5-A07	Material	28/6/23		1 x bag		х															
L5-A08	Material	28/6/23		1 x bag		х															
L5-A09	Material	28/6/23		1 x bag		х															
L5-A10	Material	28/6/23		1 x bag		Х															
RELINQUISHED	3Y: 111- 1			METHOD OF SHIPMENT:					RECE	IVED B	Y:						FOR R	ECEIVI	NG LA	BU	SE ONLY:
NAME: Stuart Lumsden DATE:	29/6/27	CONSIG	ONMENT NO	DTE NO.		D/ O/	AMI ATE	E: ::					4	:00LI	R SEAL	- Yes.	No deg C	*******	Intac	ct	w Broken
NAME: DATE:		CONSIG	SNMENT NO	DTE NO.		N/ Ol	AMI F:	E:			DAT	5:			R SEAL	- Yes.	deg C	******	Inta	ict	Broken
Container & Preservative Codes: P = I	Plastic; J = Soll Jar	; B = Glass Bottle;	N = Nitric Acie	d Prsvd.; C = Sodium Hydroxide Prsvd; VC	= Hydrochlor	c Aci	id Pr	svd Via	; VS = Su	furic Ac	id Prsva	i Viai; S	= Sulfur	ic Acid	Prsvd; Z	= Zinc	Prsvd; E	= EDTA	Prsvd	l; ST :	= Sterile Bottle; O = Other

Page 5 of 9



PROJECT NO.: 63888						LA	ABC	RAT	ORY BA	TCH N	0.:										
PROJECT NAME: RPA HOSP	TAL MAIN BU	ILDING				SA	AM	PLEF	RS: Stuar	rt Lun	nsden	/Jord	an G	ome	t						
DATE NEEDED BY: STANDAR	RD TAT					Q	C LE	VEL	: NEPM (7	2013)											
PHONE: Sydney: 02 8245	0300 Perth: (08 9488 010	0 Brisbar	ne: 07 3112 2688																	
SEND REPORT & INVOICE TO	: (1) adminnsw(jbsg.com.au	; (2) <u>slumsc</u>	den@ibsg.com.au; (3)_igomez(@jbsg.com.	<u>au</u> ;															
COMMENTS / SPECIAL HANDLING / S	TORAGE OR DISPOS	AL:				BESTOS	AD												TYPE ASBE ANAL	OF STOS YSIS WM/M	
SAMPLE ID	MATRIX	DATE	ŢĪME	TYPE & PRESERVATIVE	Ph	AS	Ē												IDEN	NEPO	NOTES:
L5-A11	Material	28/6/23		1 x bag		Х															
L5-AD01	Dust	28/6/23		1 x bag		Х															
L5-AD02	Dust	28/6/23		1 x bag		Х															
L5-LD01	Dust	28/6/23		1 x bag			Х														
L5-LD02	Dust	28/6/23		1 x bag			Х														
L6-A01	Material	28/6/23		1 x bag		х															
L6-A02	Material	28/6/23		1 x bag		Х															
L6-A03	Material	28/6/23		1 x bag		х															
L6-A04	Material	28/6/23		1 x bag		х															
L6-A05	Material	28/6/23		1 x bag		х														\square	
L6-A06	Material	28/6/23		1 x bag		х															
L6-A07	Material	28/6/23		1 x bag		х															
L6-A08	Material	28/6/23		1 x bag		х															
L6-A09	Material	28/6/23		1 x bag		х															
L6-A10	Material	28/6/23		1 x bag		х														\square	
L6-A11	Material	28/6/23		1 x bag		х															
L6-AD01	Dust	28/6/23		1 x bag		Х															
L6-AD02	Dust	28/6/23		1 x bag		х														Π	
L6-LD01	Dust	28/6/23		1 x bag			х														
RELINQUISHE	D BY: /			METHOD OF SHIPMENT:					RECE	VED BY	:						FOR RE	CEIVI	NGL	ABU	SÈ ONLY:
NAME: Stuart Lumsden DATE: OF: JBS&G	29/6/23	CONSIC	SNMENT NO	TE NO.		N. Da	IAME ATE: IF:	E: :					C	Dolei Dolei	R SEAL -	- Yes.	No leg C	43+63+7P\$	linta	ct	Broken
NAME: DATE:		CONSIG	SNMENT NO	TE NO.		N. O	IAME IF:	E:			DATE		C	DOLEI	R SEAL -	- Yes.	leg C	45+++++	Inti	aet	Broken massimus
Container & Preservative Codes: P	= Plastic; J = Soii Jar;	8 = Glass Bottle;	N = Nitric Acid	Prsvd.; C = Sodium Hydroxide Prsvd; VC	= Hydrochlori	c Aci	id Prs	vd Vi	al; VS = Sulf	uric Acia	Prsvd	Vial; S =	Sulfuric	Acid F	rsvd; Z =	Zinc I	rsvd; E	= EDTA	Prsve	d; ST :	= Sterile Bottle; O = Other



PROJECT NO.: 63888						LA	ABC	RAT	ORY BA	TCH N	0.:										
PROJECT NAME: RPA HOSP	ITAL - MAIN BU	ILDING				SA	AM	PLE	RS: Stua	rt Lum	sden	/Jord	an G	omez							
DATE NEEDED BY: STANDA	RD TAT					Q	CLE	VEL	NEPM (2013)											
PHONE: Sydney: 02 8245	0300 Perth: (08 9488 010	0 Brisba	ne: 07 3112 2688								_	-			-					
SEND REPORT & INVOICE TO	D: (1) adminnsw(@jbsg.com.au	i; (2) <u>slums</u>	den@jbsg.com.au; (3) jgomez(@ibsg.com	<u>au;</u>													-		
COMMENTS / SPECIAL HANDLING /	STORAGE OR DISPOS	AL:				BESTOS	AD												ASBES ANAL	OF STOS YSIS WWW	
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	S	<u> </u>												IDEN	NEPI	NOTES:
L6-LD02	Dust	28/6/23		1 x bag			Х														
L6-L01	Paint	28/6/23		1 x bag			X														
L6-L02	Paint	28/6/23		1 x bag			X														
L6-L03	Paint	28/6/23		1 x bag			X														
L6-L04	Paint	28/6/23		1 x bag			х														
L6-L05	Paint	28/6/23		1 x bag			X														
L6-L06	Paint	28/6/23		1 x bag			X														
L7-A01	Material	28/6/23		1 x bag		X															
L7-A02	Material	28/6/23		1 x bag		х															
L7-A03	Material	28/6/23		1 x bag		х															
L7-A04	Material	28/6/23		1 x bag		х															
L7-A05	Material	28/6/23		1 x bag		х													\square		
L7-A06	Material	28/6/23		1 x bag		x															
L7-A07	Material	28/6/23		1 x bag		x	1											-	Π		
L7-A08	Material	28/6/23		1 x bag		x	1												\square		
L7-AD01	Dust	28/6/23		1 x bag		x	1														
L7-LD01	Dust	28/6/23		1 x bag			X												\square		
L7-L01	Paint	28/6/23		1 x bag			X												\square		
L7-L02	Paint	28/6/23		1 x bag			X												\square		
RELINQUISH	ED BY:		himan	METHOD OF SHIPMENT:				-	RECE	VED BY:	-	dramer dan		-locas-l-	100		FOR RI	CEIVI	NGL	AB U	SE ONLY:
NAME: Stuart Lumsden DATE	29/6/23	TRANS	GNMENT NO	TE NO.		N. D. O	AM ATE F:	E: :			DATE		G	DOLER	SEAL -	Yes.	teg C	******	Inta	act	Broken
OF:	:; D = Diactic: = Soil lar	TRANS	PORT CO	1 E NU.	'= Hydrochlor	O In Aci)F:		al: \/S = Suit	furic Acid	DATE:	/ial· 5 –	C	DOLER	TEMP	- 195. 	leg C	= FDT		d. ST	a Starile Bottle: O = Other
Contrading of Fredering Codes.		- olass partic,							-,, •=			and a -	- an er fe	. surver t							



PROJECT NO.: 63888						LA	ABO	ATOR	YBAT	CH NO	.:								
PROJECT NAME: RPA HOS	PITAL - MAIN BU	JILDING				SA	AMP	LERS: S	Stuart	Lums	den/J	orda	n Gon	nez					
DATE NEEDED BY: STAND	ARD TAT					Q	C LE	EL: NE	PM (20	13)									
PHONE: Sydney: 02 824	5 0300 Perth:	08 9488 010	0 Brisban	ie: 07 3112 2688															
SEND REPORT & INVOICE T	O: (1) adminnsw	@jbsg.com.au	; (2) slumsd	en@ibsg.com.au; (3) igomez(@jbsg.com.a	au;	,												
COMMENTS / SPECIAL HANDLING	/ STORAGE OR DISPOS	SAL:				BESTOS	AD											TYPE OF ASBESTO ANALYS	25 15
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	ASI	Ē											IDEN	NOTES:
L7-L03	Paint	28/6/23		1 x bag			х												
L7-L04	Paint	28/6/23		1 x bag			Х												
L7-L05	Paint	28/6/23		1 x bag			Х												
L7-L06	Paint	28/6/23		1 x bag			Х												
				U			1					-							
		-					1					-							
		_				+	1		++	-			+					-	
						-	+		+			-	+					-	
						-	-		++				+ +						
							-		+-+					++			+	-	
							+		+	_			+ +	+			+-		
						_	+		++										
							+		+-+				+-+-	++			+-		
							-		+-+			_	+-+					-	
						_	-		+-+			_							
					_		-		+	_									
					_		-		+-+	_				_	_		_		
							-	-		_							-	_	
																			- NACE
RELINQUISH NAME: Stuart Lumsden DAT OF: JBS&G	HED BY: TE: 29/6/23	CONSI	GNMENT NOT	METHOD OF SHIPMENT:		N. Di O	AME ATE: F:		RECEIVI	D BY:			coc	ILER SEA	iL – Yes. /IP	FOR RI		IG LAB	USE ONLY:
NAME: DAT	re:	CONSI	GNMENT NOT	fe no.		N. O	AME F:			D	ATE:		coc	LER SEA	1L – Yes. /IP	deg C	*******	Intac	t, Broken ,
Container & Preservative Codes	: P = Plastic; J = Soll Ja	r; B = Glass Bottle;	N = Nitric Acid	Prsvd.; C = Sodium Hydroxide Prsvd; VC	C = Hydrochlorid	c Aci	id Prsv	d Vial; VS	i = Sulfu	lc Acid P	rsvd Via	l; S = Su	alfuric Ac	id Prsvd;	Z = Zinc	Prsvd; E	= EDTA	Prsvd;	ST = Sterile Bottle; O = Other

Nage 8 of 9



PROJECT NO.: 63888								LABORATORY BATCH NO.:												
PROJECT NAME: RPA HOSPITA	L – MAIN BU	ILDING				SA	AMI	PLER	S: Stua	rt Lun	nsder	n/Jord	lan Go	omez						
DATE NEEDED BY: STANDARD	TAT					QC LEVEL: NEPM (2013)														
PHONE: Sydney: 02 8245 03	00 Perth: (08 9488 010	0 Brisb	ane: 07 3112 2688																
SEND REPORT & INVOICE TO: (1) adminnsw(@jbsg.com.au	; (2) <u>slum</u>	sden@jbsg.com.au; (3) jgomez@	Dibsg.com.	au;		-			•								_	
comments/special HANDLING/STORAGE OR DISPOSAL: Samples to be sent separately from Sydney Office						BESTOS	AD											ASBES ANALY NO	OF TOS YSIS WWW	
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	AS	E											IDEN	NEPI	NOTES:
L5-A12	Material	28/6/23		1 x bag	(Х														
L5-A13	Material	28/6/23		1 x bag		Х														
L5-A14	Material	28/6/23		1 x bag		х														
L5-A15	Material	28/6/23		1 x bag		Х														
L5-A16	Material	28/6/23		1 x bag		Х														
L5-A17	Material	28/6/23		1 x bag		Х														
L5-A18	Material	28/6/23		1 x bag		Х										_				
L5-A19	Material	28/6/23		1 x bag		Х														
L5-A20	Material	28/6/23		1 x bag		Х														
L5-A21	Material	28/6/23		1 x bag		х														
L5-A22	Material	28/6/23		1 x bag		Х														
L5-A23	Material	28/6/23		1 x bag		х														
L5-A24	Material	28/6/23		1 x bag		х														
L5-A25	Material	28/6/23		1 x bag		х														
L5-AD03	Dust	28/6/23		1 x bag		х														
L5-LD03	Dust	28/6/23		1 x bag			Х													
L5-L02	Paint	28/6/23		1 x bag			Х													
L5-L03	Paint	28/6/23		1 x bag			х													
L5-L04	Paint	28/6/23		1 x bag			х													
RELINQUISHED B	Y:			METHOD OF SHIPMENT:					RECE	VED BY	': ':					FOR	RECEIV	ING LA	BUS	SÉ ONLY:
NAME: Stuart Lumsden DATE: OF: JBS&G	ra/6/2	- 7 CONSI TRANS	GNMENT N PORT CO.	OTE NO.		N/ D/ Ol	AME ATE: F:						CC	COOLER SEAL - Yes No Intact Broken COOLER TEMP deg C						
NAME: DATE: CONSIGNMENT NOTE NO. OF: TRANSPORT CO						NAME: DATE: COOLER SEAL Yes No					Storilo Bottles O = Other									
Container or meservative coues: P = P	inatic, a = ao(i Jar)	, o - Glass bottle;	- HOULD AL	an i i stul, c - sourain nyaroxide risvu, vo	~ nyarounion		M 119	- W VIC	ij vo - odl	an io more		10, 3 -	Junuiru	CUM FIS	الک = ۲ راده	15 F13VU		111240	9919	- sterne bottle, V = Villel



PROJECT NO.: 63888								LABORATORY BATCH NO.:												
PROJECT NAME: RPA HOSPITAL	- MAIN BUI	LDING				SAMPLERS: Stuart Lumsden/Jordan Gomez														
DATE NEEDED BY: STANDARD 1	TAT					QC LEVEL: NEPM (2013)														
PHONE: Sydney: 02 8245 0300 Perth: 08 9488 0100 Brisbane: 07 3112 2688																				
SEND REPORT & INVOICE TO: (1) adminnsw@)jbsg.com.au	(2) <u>slum</u>	sden@jbsg.com.au; (3)_jgomez@	ibsg.com,	au;														
comments/special handling/storage or disposal: Squple, to be sent separately from Sydney office						BESTOS	AD											ASBE ANA ANA	OF ISTOS	
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	S	E											IDEN	NEPI	NOTES:
L5-L05	Paint	28/6/23		1 x bag			Х													
L5-L06	Paint	28/6/23		1 x bag			Х													
L5-L07	Paint	28/6/23		1 x bag			х													
L6-A12	Material	28/6/23		1 x bag		X														
L6-AD03	Dust	28/6/23		1 x bag		X														
L6-LD03	Dust	28/6/23		1 x bag			X											-		
						_				-						1	++			
						_										-		-		
						-	1	++-					+ +		+			+		
							1	+					+ +		+ +		++	-		
· · · · · · · · · · · · · · · · · · ·							-	++-			+		+ +					+		
		1				_	-	+-+-			+ +	_	+ +	-	+ +		++	+		
							-				+		-	-	++		+	+	\square	
						_	-					_			+ +			-		
						_	-	++			+	_		_	+	_		_		
						-	-	+++-				_			+		++-	-		
						_	-	+	+						+-+			_		
						-		+-+-				_			+-+					
						_	<u> </u>	++-	$\left \right $	_	\vdash	_		_	+	_		_		
						-							_						-	
RELINQUISHED BY NAME: Stuart Lumsden DATE: OF: JBS&G	r: 29/6/23	CONSIC	ORT CO.	METHOD OF SHIPMENT:		NA DA OF	AME ATE:	R	ECEIVE	D BY:			CO	OLER S	EAL - Ye	FOR	RECE! No	/ING L	AB U: Ict	SE ONLY: Broken
NAME: DATE: CONSIGNMENT NOTE NO.						NAME: DATE: COOLER SEAL - Yes No Intact Broken						Broken								
Container & Preservative Codes: P = Plastic; J = Soil Jar; B = Glass Bottle; N = Nitric Acid Prsvd.; C = Sodium Hydroxide Prsvd; VC = Hydrochioric Acid Prsvd Vial; VS = Sulfuric Acid Prsvd Vial; S = Sulfuric Acid Prsvd; ST = Zinc Prsvd; ST = Sterile Bottle; O = Other										sterile Bottle; O = Other										

.



Eurofins Environment Testing Australia Pty Ltd

ABN: 50 005 085 521												
Melbourne	Geelong	Sydney	Canberra	Brisbane	Ne							
6 Monterey Road	19/8 Lewalan Street	179 Magowar Road	Unit 1,2 Dacre Street	1/21 Smallwood Place	1/2							
Dandenong South	Grovedale	Girraween	Mitchell	Murarrie	May							
VIC 3175	VIC 3216	NSW 2145	ACT 2911	QLD 4172	Tel:							
Tel: +61 3 8564 5000	Tel: +61 3 8564 5000	Tel: +61 2 9900 8400	Tel: +61 2 6113 8091	Tel: +61 7 3902 4600	NAT							

www.eurofins.com.au

EnviroSales@eurofins.com

Eurofins ARL Pty Ltd Eurofins Environment Testing NZ Ltd ABN: 91 05 0159 898 NZBN: 9429046024954

Melbourne	Geelong	Sydney	Canberra	Brisbane	Newcastle	Perth	Auckland	Christchurch
6 Monterey Road	19/8 Lewalan Street	179 Magowar Road	Unit 1,2 Dacre Street	1/21 Smallwood Place	1/2 Frost Drive	46-48 Banksia Road	35 O'Rorke Road	43 Detroit Drive
Dandenong South	Grovedale	Girraween	Mitchell	Murarrie	Mayfield West NSW 2304	Welshpool	Penrose,	Rolleston,
VIC 3175	VIC 3216	NSW 2145	ACT 2911	QLD 4172	Tel: +61 2 4968 8448	WA 6106	Auckland 1061	Christchurch 7675
Tel: +61 3 8564 5000	Tel: +61 3 8564 5000	Tel: +61 2 9900 8400	Tel: +61 2 6113 8091	Tel: +61 7 3902 4600	NATA# 1261	Tel: +61 8 6253 4444	Tel: +64 9 526 4551	Tel: +64 3 343 5201
NATA# 1261 Site# 1254	NATA# 1261 Site# 25403	NATA# 1261 Site# 18217	NATA# 1261 Site# 25466	NATA# 1261 Site# 20794	Site# 25079 & 25289	NATA# 2377 Site# 2370	IANZ# 1327	IANZ# 1290

Sample Receipt Advice

Company name:	JBS & G Australia (NSW) P/L
Contact name:	Stuart Lumsden
Project name:	RPA HOSPITAL-MAIN BUILDING
Project ID:	63888
Turnaround time:	5 Day
Date/Time received	Jun 29, 2023 2:45 PM
Eurofins reference	1003655

Sample Information

- A detailed list of analytes logged into our LIMS, is included in the attached summary table. 1
- All samples have been received as described on the above COC.
- COC has been completed correctly. 1
- N/A Attempt to chill was evident.
- Appropriately preserved sample containers have been used. 1
- All samples were received in good condition.
- Samples have been provided with adequate time to commence analysis in accordance with the relevant holding times.
- Appropriate sample containers have been used.
- Sample containers for volatile analysis received with zero headspace. 1
- Split sample sent to requested external lab. X
- X Some samples have been subcontracted.
- N/A Custody Seals intact (if used).

Notes

L5-L01 Received as extra sample, not on COC. Placed on HOLD please confirm.

Contact

If you have any questions with respect to these samples, please contact your Analytical Services Manager:

Andrew Black on phone : (+61) 2 9900 8490 or by email: AndrewBlack@eurofins.com

Results will be delivered electronically via email to Stuart Lumsden - slumsden@jbsg.com.au.

Global Leader - Results you can trust



Certificate of Analysis

Environment Testing

JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000



NATA Accredited Accreditation Number 1261 Site Number 18217

Accredited for compliance with ISO/IEC 17025–Testing NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.

Attention: Report Project Name Project ID Received Date Date Reported	Stuart Lumsden 1003655-AID RPA HOSPITAL-MAIN BUILDING 63888 Jun 29, 2023 Jul 10, 2023
Methodology: Asbestos Fibre Identification	Conducted in accordance with the Australian Standard AS 4964 – 2004: Method for the Qualitative Identification of Asbestos in Bulk Samples and in-house Method LTM-ASB-8020 by polarised light microscopy (PLM) and dispersion staining (DS) techniques. NOTE: Positive Trace Analysis results indicate the sample contains detectable respirable fibres.
Unknown Mineral Fibres	Mineral fibres of unknown type, as determined by PLM with DS, may require another analytical technique, such as Electron Microscopy, to confirm unequivocal identity. NOTE: While Actinolite, Anthophyllite and Tremolite asbestos may be detected by PLM with DS, due to variability in the optical properties of these materials, AS4964 requires that these are reported as UMF unless confirmed by an independent technique.
Subsampling Soil Samples	The whole sample submitted is first dried and then passed through a 10mm sieve followed by a 2mm sieve. All fibrous matter greater than 10mm, greater than 2mm as well as the material passing through the 2mm sieve are retained and analysed for the presence of asbestos. If the sub 2mm fraction is greater than approximately 30 to 60g then a sub-sampling routine based on ISO 3082:2009(E) is employed. NOTE: Depending on the nature and size of the soil sample, the sub-2 mm residue material may need to be sub-sampled for trace analysis, in accordance with AS 4964-2004.
Bonded asbestos- containing material (ACM)	The material is first examined and any fibres isolated for identification by PLM and DS. Where required, interfering matrices may be removed by disintegration using a range of heat, chemical or physical treatments, possibly in combination. The resultant material is then further examined in accordance with AS 4964 - 2004. NOTE: Even after disintegration it may be difficult to detect the presence of asbestos in some asbestos-containing bulk materials using PLM and DS. This is due to the low grade or small length or diameter of the asbestos fibres present in the material, or to the fact that very fine fibres have been distributed intimately throughout the materials. Vinyl/asbestos floor tiles, some asbestos-containing sealants and mastics, asbestos-containing epoxy resins and some ore samples are examples of these types of material, which are difficult to analyse.
Limit of Reporting	The performance limitation of the AS 4964 (2004) method for non-homogeneous samples is around 0.1 g/kg (equivalent to 0.01% (w/w)). Where no asbestos is found by PLM and DS, including Trace Analysis, this is considered to be at the nominal reporting limit of 0.01% (w/w). The NEPM screening level of 0.0001% (w/w) is intended as an on-site determination, not a laboratory Limit of Reporting (LOR), per se. Examination of a large sample size (e.g. 500 mL) may improve the likelihood of detecting asbestos, particularly AF, to aid assessment against the NEPM criteria. Gravimetric determinations to this level of accuracy are outside of AS 4964 and hence NATA Accreditation does not cover the performance of this service (non-NATA results shown with an asterisk). NOTE: NATA News March 2014, p.7, states in relation to AS 4964: "This is a qualitative method with a nominal reporting limit of 0.01% " and that currently in Australia "there is no validated method available for the quantification of asbestos". This report is consistent with the analytical procedures and reporting recommendations in the NEPM and the WA DoH.



Project NameRPA HOSPITAL-MAIN BUILDINGProject ID63888Date SampledJun 28, 2023Report1003655-AID

Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
L1-A01	23-Jn0069842	Jun 28, 2023	Approximate Sample 27g / 80x50x10mm Sample consisted of: Brown vermiculite fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L1-A02	23-Jn0069843	Jun 28, 2023	Approximate Sample 4g / 60x40x7mm Sample consisted of: Grey fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L1-A03	23-Jn0069844	Jun 28, 2023	Approximate Sample 1g / 20x10x2mm Sample consisted of: Grey layered fibre cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L1-A04	23-Jn0069845	Jun 28, 2023	Approximate Sample <1g / 40x7x5mm Sample consisted of: Black rubber sheet	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L1-A05	23-Jn0069846	Jun 28, 2023	Approximate Sample 2g / 40x20x3mm Sample consisted of: Brown vermiculite fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L2-A01	23-Jn0069850	Jun 28, 2023	Approximate Sample 1g / 30x10x2mm Sample consisted of: Blue flexible vinyl tile, fibrous backing and amber glue	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L2-A02	23-Jn0069851	Jun 28, 2023	Approximate Sample 3g / 30x15x3mm Sample consisted of: Grey fibre plaster material and off-white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L2-A03	23-Jn0069852	Jun 28, 2023	Approximate Sample 8g / 90x40x7mm Sample consisted of: Brown/ gold vermiculite plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.



Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
L2-A04	23-Jn0069853	Jun 28, 2023	Approximate Sample 2g / 40x15x7mm Sample consisted of: Grey sealant material	No asbestos detected. No trace asbestos detected.
L2-A05	23-Jn0069854	Jun 28, 2023	Approximate Sample <1g / 15x7x5mm Sample consisted of: Grey sealant material	No asbestos detected. No trace asbestos detected.
L3-A01	23-Jn0069856	Jun 28, 2023	Approximate Sample 1g / 30x20x3mm Sample consisted of: Brown layered fibre cement material and off- white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L3-A02	23-Jn0069857	Jun 28, 2023	Approximate Sample <1g / 15x7x2mm Sample consisted of: Brown fibre plaster cement material and off- white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L3-A03	23-Jn0069858	Jun 28, 2023	Approximate Sample 3g / 40x15x2mm Sample consisted of: Blue flexible vinyl sheet and amber glue	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.
L3-A04	23-Jn0069859	Jun 28, 2023	Approximate Sample 2g / 20x10x2mm Sample consisted of: Cream/ off-white semi brittle vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L3-A05	23-Jn0069860	Jun 28, 2023	Approximate Sample 2g / 30x15x2mm Sample consisted of: Cream semi brittle vinyl sheet, amber glue and fibrous backing	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L3-A06	23-Jn0069861	Jun 28, 2023	Approximate Sample 1g / 20x20x2mm Sample consisted of: Cream/ grey semi brittle linoleum material	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.
L3-A07	23-Jn0069862	Jun 28, 2023	Approximate Sample 3g / 50x20x2mm Sample consisted of: Blue semi flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L3-A08	23-Jn0069863	Jun 28, 2023	Approximate Sample <1g / 10x10x2mm Sample consisted of: Brown fibre plaster cement material and white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L3-A09	23-Jn0069864	Jun 28, 2023	Approximate Sample 2g / 30x10x2mm Sample consisted of: Green flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L3-AD01	23-Jn0069865	Jun 28, 2023	Approximate Sample <1g Sample consisted of: Dust particles, fragments paint flakes plastic, wood residue, soft fibrous material, metals and organic debris	No asbestos detected at the reporting limit of 0.01% w/w. Organic fibre detected. No trace asbestos detected.
L3-AD02	23-Jn0069866	Jun 28, 2023	Approximate Sample 5g / 50x40x5mm Sample consisted of: White fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.



Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
L4-A01	23-Jn0069869	Jun 28, 2023	Approximate Sample 1g / 20x5x2mm Sample consisted of: Grey sealant material	No asbestos detected. No trace asbestos detected.
L4-A02	23-Jn0069870	Jun 28, 2023	Approximate Sample 1g / 25x10x2mm Sample consisted of: Grey clayey mastic material	Chrysotile asbestos detected.
L4-A03	23-Jn0069871	Jun 28, 2023	Approximate Sample <1g / 5x2x2mm Sample consisted of: Grey gasket material	Chrysotile asbestos detected.
L4-A04	23-Jn0069872	Jun 28, 2023	Approximate Sample 2g / 30x12x5mm Sample consisted of: Grey layered fibre cement material and white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L4-A05	23-Jn0069873	Jun 28, 2023	Approximate Sample 3g / 50x7x2mm Sample consisted of: Yellow flexible vinyl sheet, white plaster and amber glue	No asbestos detected. No trace asbestos detected.
L4-A06	23-Jn0069874	Jun 28, 2023	Approximate Sample 3g / 40x20x2mm Sample consisted of: Black flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L4-A07	23-Jn0069875	Jun 28, 2023	Approximate Sample 1g / 20x12x2mm Sample consisted of: Blue flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L4-A08	23-Jn0069876	Jun 28, 2023	Approximate Sample 1g / 30x20x2mm Sample consisted of: Off-white semi brittle vinyl sheet, plaster and amber glue	No asbestos detected. No trace asbestos detected.
L4-A09	23-Jn0069877	Jun 28, 2023	Approximate Sample <1g / 10x10x2mm Sample consisted of: Brown fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L4-A10	23-Jn0069878	Jun 28, 2023	Approximate Sample <1g / 10x8x2mm Sample consisted of: Grey fibre plaster cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L4-A11	23-Jn0069879	Jun 28, 2023	Approximate Sample 6g / 60x12x10mm Sample consisted of: Yellow sealant material and foam like material attached	No asbestos detected. No trace asbestos detected.
L4-A12	23-Jn0069880	Jun 28, 2023	Approximate Sample 5g / 40x20x7mm Sample consisted of: Grey fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L4-A13	23-Jn0069881	Jun 28, 2023	Approximate Sample 4g / 30x20x7mm Sample consisted of: White/ gold vermiculite fibro plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.



Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
L4-A14	23-Jn0069882	Jun 28, 2023	Approximate Sample <1g / 10x8x2mm Sample consisted of: Brown fibre plaster material and off-white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L4-A15	23-Jn0069883	Jun 28, 2023	Approximate Sample <1g / 12x10x3mm Sample consisted of: Brown fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L4-A16	23-Jn0069884	Jun 28, 2023	Approximate Sample 1g / 20x12x8mm Sample consisted of: Yellow sealant material	No asbestos detected. No trace asbestos detected.
L4-A17	23-Jn0069885	Jun 28, 2023	Approximate Sample 1g / 20x10x5mm Sample consisted of: Black sealant material	No asbestos detected. No trace asbestos detected.
L4-A18	23-Jn0069886	Jun 28, 2023	Approximate Sample 1g / 30x25x2mm Sample consisted of: Grey flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L4-A19	23-Jn0069887	Jun 28, 2023	Approximate Sample <1g / 8x5x2mm Sample consisted of: White fibre plaster material	Chrysotile and amosite asbestos detected.
L4-A20	23-Jn0069888	Jun 28, 2023	Approximate Sample 2g / 40x25x2mm Sample consisted of: Blue/ brown flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L4-A21	23-Jn0069889	Jun 28, 2023	Approximate Sample <1g / 12x10x5mm Sample consisted of: Grey fibre plaster cement material and white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L4-A22	23-Jn0069890	Jun 28, 2023	Approximate Sample 1g / 20x12x2mm Sample consisted of: Blue flexible linoleum and amber glue	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.
L4-A23	23-Jn0069891	Jun 28, 2023	Approximate Sample 1g / 20x10x2mm Sample consisted of: White flexible vinyl sheet, plaster and amber glue	No asbestos detected. No trace asbestos detected.
L4-A24	23-Jn0069892	Jun 28, 2023	Approximate Sample <1g / 8x7x2mm Sample consisted of: Brown fibre plaster cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L4-A25	23-Jn0069893	Jun 28, 2023	Approximate Sample 4g / 50x40x7mm Sample consisted of: Brown / gold vermiculite plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L4-A26	23-Jn0069894	Jun 28, 2023	Approximate Sample 5g / 70x20x2mm Sample consisted of: Green flexible vinyl sheet , plaster and amber glue	No asbestos detected. No trace asbestos detected.



Client Sample ID	Eurofins Sample Date Sampled Sample Description		Sample Description	Result
L4-AD01	23-Jn0069895	Jun 28, 2023	Approximate Sample 14g Sample consisted of: Dust particles, fragments of soft fibrous material, plastic, plaster, paint flakes and sand	No asbestos detected at the reporting limit of 0.01% w/w. Synthetic mineral fibre detected. Organic fibre detected. No trace asbestos detected.
L4-AD02	23-Jn0069896	Jun 28, 2023	Approximate Sample <1g Sample consisted of: Dust particles, fragments of soft fibrous material and plaster in powder form	No asbestos detected at the reporting limit of 0.01% w/w. Organic fibre detected. No trace asbestos detected.
L5-A01	23-Jn0069908	Jun 28, 2023	Approximate Sample 2g / 40x10x2mm Sample consisted of: Yellow flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L5-A02	23-Jn0069909	Jun 28, 2023	Approximate Sample 1g / 30x10x2mm Sample consisted of: Black flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L5-A03	23-Jn0069910	Jun 28, 2023	Approximate Sample <1g / 12x8x2mm Sample consisted of: Brown fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L5-A04	23-Jn0069911	Jun 28, 2023	Approximate Sample 2g / 30x15x2mm Sample consisted of: Black flexible linoleum and amber glue	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.
L5-A05	23-Jn0069912	Jun 28, 2023	Approximate Sample 1g / 15x10x3mm Sample consisted of: Brown fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L5-A06	23-Jn0069913	Jun 28, 2023	Approximate Sample 1g / 30x20x2mm Sample consisted of: Off-white semi brittle vinyl sheet	No asbestos detected. No trace asbestos detected.
L5-A07	23-Jn0069914	Jun 28, 2023	Approximate Sample 1g / 35x12x2mm Sample consisted of: Blue flexible linoleum and amber glue	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.
L5-A08	23-Jn0069915	Jun 28, 2023	Approximate Sample 1g / 25x15x2mm Sample consisted of: Blue flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L5-A09	23-Jn0069916	Jun 28, 2023	Approximate Sample 5g / 50x25x5mm Sample consisted of: Brown fibre plaster material and off-white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L5-A10	23-Jn0069917	Jun 28, 2023	Approximate Sample 3g / 50x40x7mm Sample consisted of: Gold/ white vermiculite fibro plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L5-A11	23-Jn0069918	Jun 28, 2023	Approximate Sample 3g / 60x25x5mm Sample consisted of: Grey fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.



Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
L5-AD01	23-Jn0069919	Jun 28, 2023	Approximate Sample 1g Sample consisted of: Dust particles, fragments of soft fibrous material, plaster in powder form and fragments	No asbestos detected at the reporting limit of 0.01% w/w. Synthetic mineral fibre detected. Organic fibre detected. No trace asbestos detected.
L5-AD02	23-Jn0069920	Jun 28, 2023	Approximate Sample 2g Sample consisted of: Dust particles, fragments of soft fibrous material, fibre plaster material, paint flakes and plaster in powder form	No asbestos detected at the reporting limit of 0.01% w/w. Synthetic mineral fibre detected. Organic fibre detected. No trace asbestos detected.
L6-A01	23-Jn0069923	Jun 28, 2023	Approximate Sample 2g / 40X12X5mm Sample consisted of: Grey layered fibre cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L6-A02	23-Jn0069924	Jun 28, 2023	Approximate Sample 2g / 20x20x2mm Sample consisted of: Blue flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L6-A03	23-Jn0069925	Jun 28, 2023	Approximate Sample 1g / 30x10x2mm Sample consisted of: Blu flexible linoleum and amber glue	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.
L6-A04	23-Jn0069926	Jun 28, 2023	Approximate Sample 2g / 15x10x2mm Sample consisted of: Cream semi brittle vinyl tile and amber glue	No asbestos detected. No trace asbestos detected.
L6-A05	23-Jn0069927	Jun 28, 2023	Approximate Sample <1g / 12x8x2mm Sample consisted of: Brown fibre plaster cement material and off- white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L6-A06	23-Jn0069928	Jun 28, 2023	Approximate Sample 1g / 15x8x5mm Sample consisted of: Grey sealant material	No asbestos detected. No trace asbestos detected.
L6-A07	23-Jn0069929	Jun 28, 2023	Approximate Sample 1g / 30x10x3mm Sample consisted of: Grey compressed fibre cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L6-A08	23-Jn0069930	Jun 28, 2023	Approximate Sample 40g / 90x40x5mm Sample consisted of: Grey layered fibre cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L6-A09	23-Jn0069931	Jun 28, 2023	Approximate Sample 3g / 90x30x2mm Sample consisted of: Black carpet underlay	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L6-A10	23-Jn0069932	Jun 28, 2023	Approximate Sample 15g / 50x15x7mm Sample consisted of: Yellow mastic material	No asbestos detected. No trace asbestos detected.



Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result			
L6-A11	23-Jn0069933	Jun 28, 2023	Approximate Sample 1g / 30x10x7mm Sample consisted of: Black rubber sheet fragments and amber glue	No asbestos detected. No trace asbestos detected.			
L6-AD01	23-Jn0069934	Jun 28, 2023	Approximate Sample <1g / 25x10x1mm Sample consisted of: Grey fluffy fibrous material	No asbestos detected. Organic fibre detected. No trace asbestos detected.			
L6-AD02	23-Jn0069935	Jun 28, 2023	Approximate Sample 1g Sample consisted of: Dust particles fragments of soft fibrous material, paint flakes, plaster in powder form, compressed fibrous material and organic debris	No asbestos detected at the reporting limit of 0.01% w/w. Organic fibre detected. No trace asbestos detected.			
L7-A01	23-Jn0069944	Jun 28, 2023	Approximate Sample 14g / 80x50x10mm Sample consisted of: Brown vermiculite plaster material	No asbestos detected. No trace asbestos detected.			
L7-A02	23-Jn0069945	Jun 28, 2023	Approximate Sample 3g / 40x15x5mm Sample consisted of: Brown/ gold vermiculite fibro- plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.			
L7-A03	23-Jn0069946	Jun 28, 2023	Approximate Sample <1g / 7x5x2mm Sample consisted of: Off-white sealant material	No asbestos detected. No trace asbestos detected.			
L7-A04	23-Jn0069947	Jun 28, 2023	Approximate Sample 2g / 30x7x5mm Sample consisted of: Grey sealant material	No asbestos detected. No trace asbestos detected.			
L7-A05	23-Jn0069948	Jun 28, 2023	Approximate Sample <1g / 20x10x2mm Sample consisted of: Brown fibre plaster insulation material	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.			
L7-A06	23-Jn0069949	Jun 28, 2023	Approximate Sample 1g / 20x15x2mm Sample consisted of: Black fibrous material	No asbestos detected. Organic fibre detected. No trace asbestos detected.			
L7-A07	23-Jn0069950	Jun 28, 2023	Approximate Sample 2g / 30x15x2mm Sample consisted of: Grey flexible in linoleum material	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.			
L7-A08	23-Jn0069951	Jun 28, 2023	Approximate Sample 1g / 20x10x3mm Sample consisted of: Grey sealant material	No asbestos detected. No trace asbestos detected.			
L7-AD01	23-Jn0069952	Jun 28, 2023	Approximate Sample 1g Sample consisted of: Dust particles, fragments of soft fibrous material, foam like material, plaster in powder form and organic debris	No asbestos detected at the reporting limit of 0.01% w/w. Organic fibre detected. No trace asbestos detected.			
L5-A12	23-Jn0069960	Jun 28, 2023	Approximate Sample 3g / 35x15x3mm Sample consisted of: Grey layered fibre cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.			



Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result			
L5-A13	23-Jn0069961	Jun 28, 2023	Approximate Sample 1g / 25x15x2mm Sample consisted of: White fibre plaster material	Chrysotile and amosite asbestos detected.			
L5-A14	23-Jn0069962	Jun 28, 2023	Approximate Sample <1g / 12x10x2mm Sample consisted of: Grey fibre plaster cement material	No asbestos detected. No trace asbestos detected.			
L5-A15	23-Jn0069963	Jun 28, 2023	Approximate Sample 3g / 20x15x2mm Sample consisted of: Green flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.			
L5-A16	23-Jn0069964	Jun 28, 2023	Approximate Sample 1g / 30x7x2mm Sample consisted of: Grey sealant material	No asbestos detected. No trace asbestos detected.			
L5-A17	23-Jn0069965	Jun 28, 2023	Approximate Sample 1g / 20x10x2mm Sample consisted of: Red flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.			
L5-A18	23-Jn0069966	Jun 28, 2023	Approximate Sample 1g / 15x10x2mm Sample consisted of: Yellow flexible linoleum and black/ blue fibrous backing	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.			
L5-A19	23-Jn0069967	Jun 28, 2023	Approximate Sample <1g / 10x8x2mm Sample consisted of: Grey fibre plaster cement material and off-white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.			
L5-A20	23-Jn0069968	Jun 28, 2023	Approximate Sample <1g / 20x5x2mm Sample consisted of: Grey fibre plaster cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.			
L5-A21	23-Jn0069969	Jun 28, 2023	Approximate Sample <1g / 10x8x2mm Sample consisted of: Grey fibre plaster cement material and pink coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.			
L5-A22	23-Jn0069970	Jun 28, 2023	Approximate Sample 2g / 15x10x2mm Sample consisted of: Blue flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.			
L5-A23	23-Jn0069971	Jun 28, 2023	Approximate Sample 1g / 12x8x2mm Sample consisted of: Grey flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.			
L5-A24	23-Jn0069972	Jun 28, 2023	Approximate Sample 5g / 40x20x2mm Sample consisted of: Green flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.			
L5-A25	23-Jn0069973	Jun 28, 2023	Approximate Sample <1g / 12x8x2mm Sample consisted of: Grey flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.			



Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result			
L5-AD03	23-Jn0069974	Jun 28, 2023	Approximate Sample 1g Sample consisted of: Dust particles, fragments of metals, soft fibrous material, plaster in fragments and powder form and organic debris	No asbestos detected at the reporting limit of 0.01% w/w. Synthetic mineral fibre detected. Organic fibre detected. No trace asbestos detected.			
L6-A12	23-Jn0069982	Jun 28, 2023	Approximate Sample <1g / 10x8x2mm Sample consisted of: Grey fibre plaster cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.			
L6-AD03	23-Jn0069983	Jun 28, 2023	Approximate Sample <1g / 20x12x2mm Sample consisted of: White fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.			



Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description

Asbestos - LTM-ASB-8020 Asbestos - LTM-ASB-8020

Testing Site	Extracted	Holding Time			
Sydney	Jul 10, 2023	Indefinite			
Sydney	Jul 10, 2023	Indefinite			

ABN: 50 005 085 521									ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954				
web: www.eurofins.com.au email: EnviroSales@eurofins.com			Melbourne 6 Monterey Roa Dandenong Sou VIC 3175 Tel: +61 3 8564 NATA# 1261 Si	Geelong Sydney d 19/8 Lewalan Street 179 Magc ith Grovedale Girraweet VIC 3216 NSW 214 5000 Tel: +61 3 8564 5000 Tel: +61 2 it# 1254 NATA# 1261 Site# 25403 NATA# 1.			gowar Road en 45 2 9900 8400 1261 Site# 1821		erra ,2 Dac ell 2911 61 2 6 ⁻ # 1261	Brisbane Newcastl re Street 1/21 Smallwood Place 1/2 Frost Murarrie Mayfield V QLD 4172 Tel: +61 2 113 8091 Tel: +61 7 3902 4600 NATA# 12 Site# 25466 NATA# 1261 Site# 20794 Site# 250	le Drive West NSW 2304 2 4968 8448 261 79 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
	Company Name: Address:	JBS & G Au Level 1, 50 Sydney NSW 2000	istralia (NSW Margaret St) P/L			O R Pl Fa	rder N eport hone: ax:	lo.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
ļ	Project Name: Project ID:	RPA HOSP 63888	ITAL-MAIN E	BUILDING							Eu	urofins Analytical Ser	vices Manager : A	ndrew Black
Sample Detail							Asbestos Absence /Presence	Lead	Lead (% w/w)					
S	ydney Laboratory ·	- NATA # 1261	Site # 18217	7		Х	X	х	Х					
External Laboratory										-				
	Sample ID	Sample Date	Time	Matrix										
1	L1-A01	Jun 28, 2023		Building Materials	S23-Jn0069842		x							
2	L1-A02	Jun 28, 2023		Building Materials	S23-Jn0069843		x							
3	L1-A03	Jun 28, 2023		Building Materials	S23-Jn0069844		x							
4	L1-A04	Jun 28, 2023		Building	S23-Jn0069845		x							
5	L1-A05	Jun 28, 2023		Building	S23-Jn0069846		x							
6	L1-L01	Jun 28, 2023		Paint	S23-Jn0069847				х	1				
7	L1-L02	Jun 28, 2023		Paint	S23-Jn0069848		1	1	Х	1				
8	L1-L03	Jun 28, 2023		Paint	S23-Jn0069849				х	1				
9	L2-A01	Jun 28, 2023		Building Materials	S23-Jn0069850		x]				
		Fine	ABN: 50 005 085 521	ent Testing Australia	a Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	NZBN: 942904602495	nent Testing NZ Ltd 4
-----	--	--	--	--	---	---	----------------------------	--	--	---	---	--	---	--
web	b: www.eurofins.com.au ail: EnviroSales@eurofins.	com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 254	Sydney 179 Mag Girrawee NSW 214 Tel: +61 403 NATA# 1	owar Ro en 45 2 9900 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitch ACT : Tel: + 7 NATA	erra I,2 Dac ell 2911 -61 2 6 \# 126'	Brisbane ore Street 1/21 Smallwood Place Murarrie QLD 4172 113 8091 Tel: +61 7 3902 4600 1 Site# 25466 NATA# 1261 Site# 20794	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
	Company Name: Address:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				O Re Pl Fa	rder N eport hone: ax:	No.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
	Project Name: Project ID:	RPA HOSF 63888	PITAL-MAIN BUILD	NG							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Sy	/dney Laboratory -	NATA # 1261	I Site # 18217		000054	Х	X	Х	X	_				
) L2-A02	Jun 28, 2023	Mate	erials	009821		X			_				
11	L2-A03	Jun 28, 2023	Build	ling S23-Jn0 prials	0069852		x							
12	2 L2-A04	Jun 28, 2023	Build	ling S23-Jn(0069853		x							
13	3 L2-A05	Jun 28, 2023	Build	ling S23-Jn(0069854		x			-				
14	L2-L01	Jun 28, 2023	Pain	t S23-Jn	0069855				х	-				
15	5 L3-A01	Jun 28, 2023	Build	ling S23-Jn(0069856		x							
16	6 L3-A02	Jun 28, 2023	Build	ling S23-Jn(0069857		x			-				
17	′ L3-A03	Jun 28, 2023	Build	ling S23-Jn(0069858		x							
18	3 L3-A04	Jun 28, 2023	Build	ling S23-Jn(0069859		x							
19) L3-A05	Jun 28, 2023	Build Mate	ling S23-Jn(rials	0069860		x]				

		fine	ABN: 50 005 085 52	iment Testing 1	g Australia Pty I	Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	NZBN: 942904602495	nent Testing NZ Lto 4
web: w email:	ww.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 500 NATA# 1261 Site# 1	Geelong 19/8 Lewa Grovedale VIC 3216 D Tel: +61 3 254 NATA# 12	Syd alan Street 179 Gin NS 8564 5000 Tel 261 Site# 25403 NA	dney 9 Magowa rraween 6W 2145 I: +61 2 9 TA# 126	ar Roa 900 84 1 Site#	ad 400 # 18213	Canb Unit 1 Mitche ACT 2 Tel: + 7 NATA	erra ,2 Dacr ell 2911 61 2 61 # 1261	Brisbane e Street 1/21 Smallwood Place Murarrie QLD 4172 13 8091 Tel: +61 7 3902 4600 Site# 25466 NATA# 1261 Site# 2075	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 24 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Cc Ac	mpany Name: dress:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/ Margaret St	L				Or Re Pr Fa	der N eport none: x:	lo.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pr Pr	oject Name: oject ID:	RPA HOSF 63888	PITAL-MAIN BUIL	.DING								E	urofins Analytical Ser	vices Manager : A	ndrew Black
		S	ample Detail				Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 126 [,]	1 Site # 18217				Х	Х	х	х					
20	L3-A06	Jun 28, 2023	Bu Ma	iilding aterials	S23-Jn00698	861		х			-				
21	L3-A07	Jun 28, 2023	Bu Ma	iilding aterials	S23-Jn00698	862		Х			-				
22	L3-A08	Jun 28, 2023	Bu Ma	iilding aterials	S23-Jn00698	863		Х							
23	L3-A09	Jun 28, 2023	Bu Ma	iilding aterials	S23-Jn00698	864		х							
24	L3-AD01	Jun 28, 2023	Du	ıst	S23-Jn00698	865	Х								
25	L3-AD02	Jun 28, 2023	Du	ıst	S23-Jn00698	866		Х							
26	L3-LD01	Jun 28, 2023	Du	ıst	S23-Jn00698	867			Х						
27	L3-LD02	Jun 28, 2023	Du	ıst	S23-Jn00698	868			Х						
28	L4-A01	Jun 28, 2023	Bu	ilding aterials	S23-Jn00698	869		х							
29	L4-A02	Jun 28, 2023	Bu	uilding aterials	S23-Jn00698	870		х]				
30	L4-A03	Jun 28, 2023	Bu	uilding aterials	S23-Jn00698	871		х							

•		fine	ABN: 50 005 085 521	ent Testing Austral	ia Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	NZBN: 942904602495	nent Testing NZ Ltd 4
web: email	www.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 125	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 4 NATA# 1261 Site# 25	Sydney 179 Mag Girrawee NSW 21) Tel: +61 5403 NATA# 1	owar Ro n 45 2 9900 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitch ACT : Tel: + 7 NATA	erra I,2 Dac ell 2911 -61 2 6 ⁻ \# 1261	Brisbane tre Street 1/21 Smallwood Place Murarrie QLD 4172 113 8091 Tel: +61 7 3902 4600 1 Site# 25466 NATA# 1261 Site# 20794	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
C A	ompany Name: ddress:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				O Re Pl Fa	rder N eport hone: ax:	No.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pi Pi	oject Name: oject ID:	RPA HOSF 63888	PITAL-MAIN BUILD	ING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syc	Iney Laboratory	- NATA # 1261	Site # 18217	r 000 l		X	X	Х	x					
31	L4-A04	Jun 28, 2023	Mate	erials	10069872		X			_				
32	L4-A05	Jun 28, 2023	Buile Mate	ding S23-Jr erials	10069873		х							
33	L4-A06	Jun 28, 2023	Build	ding S23-Jr erials	10069874		x							
34	L4-A07	Jun 28, 2023	Build	ding S23-Jr erials	n0069875		x			_				
35	L4-A08	Jun 28, 2023	Build	ding S23-Jr erials	n0069876		x							
36	L4-A09	Jun 28, 2023	Build	ding S23-Jr erials	า0069877		x							
37	L4-A10	Jun 28, 2023	Build	ding S23-Jr erials	n0069878		x			-				
38	L4-A11	Jun 28, 2023	Build	ding S23-Jr erials	n0069879		x			1				
39	L4-A12	Jun 28, 2023	Build	ding S23-Jr erials	n0069880		x]				
40	L4-A13	Jun 28, 2023	Build	ding S23-Jr	n0069881		Х							

•		fine	ABN: 50 005 085 521	nent Testing Austr	alia Pty Ltd							ABN: 91 05 0159 898	NZBN: 942904602495	nent Testing NZ Ltd 4
web: web: web: web: web: web: web: web:	www.eurofins.com.au EnviroSales@eurofins	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 125	Geelong 19/8 Lewalan Stree Grovedale VIC 3216 Tel: +61 3 8564 50 NATA# 1261 Site#	Sydney et 179 Mag Girrawee NSW 21 000 Tel: +61 25403 NATA# 1	owar Ro en 45 2 9900 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitch ACT : Tel: + 7 NATA	erra ,2 Daci ell 2911 61 2 61 \# 1261	Brisbane re Street 1/21 Smallwood Place Murarrie QLD 4172 113 8091 Tei: +61 7 3902 4600 Site# 25466 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Ca Aa	ompany Name: Idress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				O Re Pl Fa	rder N eport hone: ax:	lo.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pr Pr	oject Name: oject ID:	RPA HOSF 63888	PITAL-MAIN BUILD	DING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217	dia a	h-0000004	X	X	Х	X	-				
40	L4-A13	Jun 28, 2023	Mat	erials	JU0069881					-				
41	L4-A14	Jun 28, 2023	Buil Mat	ding S23- erials	Jn0069882		х			_				
42	L4-A15	Jun 28, 2023	Buil Mat	ding S23- erials	Jn0069883		x							
43	L4-A16	Jun 28, 2023	Buil Mat	ding S23- erials	Jn0069884		x							
44	L4-A17	Jun 28, 2023	Buil	ding S23- erials	Jn0069885		x			-				
45	L4-A18	Jun 28, 2023	Buil	ding S23- erials	Jn0069886		x			-				
46	L4-A19	Jun 28, 2023	Buil	ding S23- erials	Jn0069887		x			-				
47	L4-A20	Jun 28, 2023	Buil	ding S23- erials	Jn0069888		x			1				
48	L4-A21	Jun 28, 2023	Buil	ding S23- erials	Jn0069889		x			1				
49	L4-A22	Jun 28, 2023	Buil	ding S23-	Jn0069890		Х]				

Note: Melbourne Dandenong South VIC 3175 Tel: +613 3664 5000 Gelong 198 Lewise Landenong South VIC 3175 Tel: +613 3664 5000 Sydney Tel: +613 3664 5000 Canberra UIC 12 Darce B VIC 3175 Tel: +613 2466 NATA# 1261 Newcastle Mutaria Newcastle VIC 3175 Tel: +613 3664 5000 Perth Address Company Name: JBS & G Australia (NSW) P/L Address: Seed 5000 Tel: +613 3664 5000 Tel: +613 3664 5000 NATA# 1261 Site# 20794 Sit#	Auckland Christchurch 35 ORorke Road 43 Detroit Drive Penrose, Rolleston, Auckland 1061 Christchurch 7675 14 Tel: +64 9 526 4551 Tel: +64 3 343 520 IANZ# 1327 IANZ# 1290 Jun 29, 2023 2:45 PM Jul 6, 2023 5 Day Stuart Lumsden I Services Manager : Andrew Black
Company Name: JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000 Order No.: Report #: No: 1003655 Phone: Received: 02 8245 0300 Project Name: RPA HOSPITAL-MAIN BUILDING Project ID: 63888 Eurofins Analytical Se	Jun 29, 2023 2:45 PM Jul 6, 2023 5 Day Stuart Lumsden
Project Name: RPA HOSPITAL-MAIN BUILDING Project ID: 63888 Eurofins Analytical Se Sample Detail	Il Services Manager : Andrew Black
Sample Detail	
Sydney Laboratory - NATA # 1261 Site # 18217 X X X X X	
Materials	
50 L4-A23 Jun 28, 2023 Building Materials S23-Jn0069891 X	
51 L4-A24 Jun 28, 2023 Building Materials S23-Jn0069892 X	
52 L4-A25 Jun 28, 2023 Building Materials S23-Jn0069893 X	
53 L4-A26 Jun 28, 2023 Building S23-Jn0069894 X	
54 L4-AD01 Jun 28, 2023 Dust S23-Jn0069895 X	
55 L4-AD02 Jun 28, 2023 Dust S23-Jn0069896 X	
56 L4-LD01 Jun 28, 2023 Dust S23-Jn0069897 X	
57 L4-LD02 Jun 28, 2023 Dust S23-Jn0069898 X	
58 L4-L01 Jun 28, 2023 Paint S23-Jn0069899 X	
59 L4-L02 Jun 28, 2023 Paint S23-Jn0069900 X	
60 L4-L03 Jun 28, 2023 Paint S23-Jn0069901 X	
61 L4-L04 Jun 28, 2023 Paint S23-Jn0069902 X	

•		fine	ABN: 50 005 085 521	nent Testing Aust	ralia Pty Ltd							ABN: 91 05 0159 898	NZBN: 942904602495	ient Testing NZ Ltd 4
web: v email:	ww.eurofins.com.au EnviroSales@eurofins	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 12	Geelong 19/8 Lewalan Stre Grovedale VIC 3216 Tel: +61 3 8564 50 54 NATA# 1261 Site#	Sydney et 179 Mag Girrawee NSW 214 000 Tel: +61 # 25403 NATA# 1	owar Ro n 45 2 9900 8 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitche ACT 2 Tel: + 7 NATA	erra ,2 Dacr ell 2911 61 2 61 # 1261	Brisbane re Street 1/21 Smallwood Place Murarrie QLD 4172 13 8091 Tel: +61 7 3902 4600 Site# 25466 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Co Ao	ompany Name: Idress:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	lo.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pr Pr	oject Name: oject ID:	RPA HOSF 63888	PITAL-MAIN BUILI	DING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217			X	x	х	x	4				
62	L4-L05	Jun 28, 2023	Pai	nt S23-	-Jn0069903				X	-				
63	L4-L06	Jun 28, 2023	Pai	nt S23-	-Jn0069904				X	-				
64	L4-L07	Jun 28, 2023	Pai	nt S23-	-Jn0069905				X	-				
65	L4-L08	Jun 28, 2023	Pai	nt S23	-Jn0069906				X	-				
67	L5-A01	Jun 28, 2023	Bui	ding S23-	-Jn0069907 -Jn0069908		x		^	-				
68	L5-A02	Jun 28, 2023	Bui Ma	ding S23- erials	-Jn0069909		x							
69	L5-A03	Jun 28, 2023	Bui Ma	ding S23- erials	-Jn0069910		x							
70	L5-A04	Jun 28, 2023	Bui Ma	ding S23- erials	-Jn0069911		x			-				
71	L5-A05	Jun 28, 2023	Bui Ma	ding S23- cerials	-Jn0069912		x			-				
72	L5-A06	Jun 28, 2023	Bui Ma	ding S23- erials	-Jn0069913		X							
13	L5-AU7	Jun 28, 2023	Bui	aing S23	-JNUU69914		X			J				

•	ouro	fine	Eurofins Environ	nent Testing Austra	lia Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environn NZBN: 942904602495	nent Testing NZ Lto 4
web: w email:	ww.eurofins.com.au	.com	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 500 54 NATA# 1261 Site# 2	Sydney 179 Mag Girrawee NSW 214 0 Tel: +61 5403 NATA# 1	owar Ro n 45 2 9900 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitche ACT 2 Tel: + 7 NATA	erra ,2 Dacre ell 2911 61 2 611 # 1261 \$	Brisbane 9 Street 1/21 Smallwood Place Murarrie QLD 4172 13 8091 Tel: +61 7 3902 4600 Site# 25466 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
Co Ad	mpany Name: dress:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				O Ro Pi Fa	rder N eport none: ax:	lo.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pro Pro	oject Name: oject ID:	RPA HOSF 63888	PITAL-MAIN BUILI	DING							E	urofins Analytical Serv	vices Manager : A	ndrew Black
		S	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217			Х	X	х	х					
			Mat	erials										
74	L5-A08	Jun 28, 2023	Bui Mai	ding S23-J erials	n0069915		X							
/5	L5-A09	Jun 28, 2023	Mat	erials	n0069916		Х							
76	L5-A10	Jun 28, 2023	Bui Mat	ding S23-J erials	n0069917		x							
77	L5-A11	Jun 28, 2023	Bui Mat	ding S23-J erials	n0069918		x							
78	L5-AD01	Jun 28, 2023	Dus	st S23-J	n0069919	Х	Х							
79	L5-AD02	Jun 28, 2023	Dus	st S23-J	n0069920	Х								
80	L5-LD01	Jun 28, 2023	Dus	st S23-J	n0069921			Х						
81	L5-LD02	Jun 28, 2023	Dus	st S23-J	n0069922			х						
82	L6-A01	Jun 28, 2023	Bui Ma	ding S23-J erials	n0069923		x							
83	L6-A02	Jun 28, 2023	Bui Mat	ding S23-J erials	n0069924		х							
84	L6-A03	Jun 28, 2023	Bui	ding S23-J	n0069925		Х							

•		fine	ABN: 50 005 085 521	ent Testing Austra	lia Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	NZBN: 942904602495	nent Testing NZ Ltd 4
web: email	www.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 125	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 500 64 NATA# 1261 Site# 2	Sydney 179 Mag Girrawee NSW 21 0 Tel: +61 25403 NATA# 1	owar Ro en 45 2 9900 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitch ACT : Tel: + 7 NATA	erra I,2 Dac ell 2911 •61 2 6′ A# 1261	Brisbane tre Street 1/21 Smallwood Place Murarrie QLD 4172 113 8091 Tel: +61 7 3902 4600 I Site# 25466 NATA# 1261 Site# 20794	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
C A	ompany Name: ddress:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				O Re Pl Fa	rder N eport hone: ax:	No.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pi Pi	roject Name: roject ID:	RPA HOSF 63888	PITAL-MAIN BUILD	NG							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syc	Iney Laboratory	- NATA # 1261	Site # 18217		-0000005	Х	X	Х	X	-				
04	LO-AU3	Jun 28, 2023	Mate	erials	10069925	-				_				
85	L6-A04	Jun 28, 2023	Build	ding S23-J erials	n0069926		X							
86	L6-A05	Jun 28, 2023	Buile Mate	ding S23-J erials	n0069927		x							
87	L6-A06	Jun 28, 2023	Buil Mate	ding S23-J erials	n0069928		x							
88	L6-A07	Jun 28, 2023	Build	ding S23-J erials	n0069929		x							
89	L6-A08	Jun 28, 2023	Build	ding S23-J erials	n0069930		x			-				
90	L6-A09	Jun 28, 2023	Build	ding S23-J erials	n0069931		x							
91	L6-A10	Jun 28, 2023	Build	ding S23-J erials	n0069932		x							
92	L6-A11	Jun 28, 2023	Build	ding S23-J erials	n0069933		x]				
93	L6-AD01	Jun 28, 2023	Dus	t S23-J	n0069934		Х							

		fine	ABN: 50 005 085 521	ent Testing Australia	Pty Ltd							ABN: 91 05 0159 898	NZBN: 942904602495	nent Testing NZ Lto 4
web: w email:	ww.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 125	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 i4 NATA# 1261 Site# 254	Sydney 179 Mag Girrawee NSW 214 Tel: +61 03 NATA# 1	owar Ro en 45 2 9900 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitch ACT : Tel: + 7 NATA	erra I,2 Dac ell 2911 -61 2 61 A# 1261	Brisbane N re Street 1/21 Smallwood Place 1/ Murarrie M QLD 4172 T 113 8091 Tel: +61 7 3902 4600 N Site# 25466 NATA# 1261 Site# 20794 S S	Vewcastle //2 Frost Drive Mayfield West NSW 2304 fel: +61 2 4968 8448 VATA# 1261 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Co Ad	mpany Name: dress:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				O Ri Pi Fa	rder N eport hone: ax:	No.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pro Pro	oject Name: oject ID:	RPA HOSF 63888	PITAL-MAIN BUILD	VING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		S	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Sydı	ney Laboratory	- NATA # 126	I Site # 18217			Х	X	х	X					
94	L6-AD02	Jun 28, 2023	Dus	t S23-Jn0	069935	Х								
95	L6-LD01	Jun 28, 2023	Dus	t S23-Jn0	069936			Х						
96	L6-LD02	Jun 28, 2023	Dus	t S23-Jn0	069937			Х						
97	L6-L01	Jun 28, 2023	Pair	nt S23-Jn0	069938				Х					
98	L6-L02	Jun 28, 2023	Pair	nt S23-Jn0	069939				X					
99	L6-L03	Jun 28, 2023	Pair	nt S23-Jn0	069940				X	1				
100	L6-L04	Jun 28, 2023	Pair	nt S23-Jn0	069941				X					
101	L6-L05	Jun 28, 2023	Pair	nt S23-Jn0	069942				X					
102	L6-L06	Jun 28, 2023	Pair	nt S23-Jn0	069943				Х					
103	L7-A01	Jun 28, 2023	Buil Mat	ding S23-Jn0 erials	069944		x			_				
104	L7-A02	Jun 28, 2023	Buil Mat	ding S23-Jn(erials	069945		x							
105	L7-A03	Jun 28, 2023	Buil Mat	ding S23-Jn0 erials	069946		x							
106	L7-A04	Jun 28, 2023	Buil Mat	ding S23-Jn(erials	069947		x							

	fine	Eurofins Environm ABN: 50 005 085 521	ent Testing Australi	a Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environn NZBN: 942904602495	n <mark>ent Testing NZ Ltd</mark> 4
web: www.eurofins.com.au email: EnviroSales@eurofi	u ins.com	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 4 NATA# 1261 Site# 25	Sydney 179 Mag Girrawee NSW 214 Tel: +61 403 NATA# 1	owar Ro n 15 2 9900 8 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitch ACT 2 Tel: + 7 NATA	erra ,2 Dacre ell 2911 61 2 611 # 1261 3	Brisbane e Street 1/21 Smallwood Place Murarrie QLD 4172 13 8091 Tel: +61 7 3902 4600 Site# 25466 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 94 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
Company Name: Address:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L) Margaret St				O Ri Pi Fa	rder N eport hone: ax:	lo.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Project Name: Project ID:	RPA HOSI 63888	PITAL-MAIN BUILD	ING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
	s	Sample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Sydney Laborator	y - NATA # 126	1 Site # 18217			Х	X	Х	х					
107 L7-A05	Jun 28, 2023	Build Mate	ding S23-Jn erials	0069948		x							
108 L7-A06	Jun 28, 2023	Build	ding S23-Jn erials	0069949		x							
109 L7-A07	Jun 28, 2023	Build	ding S23-Jn erials	0069950		х							
110 L7-A08	Jun 28, 2023	Build	ding S23-Jn erials	0069951		х							
111 L7-AD01	Jun 28, 2023	Dust	t S23-Jn	0069952	Х								
112 L7-LD01	Jun 28, 2023	Dust	t S23-Jn	0069953			Х						
113 L7-L01	Jun 28, 2023	Pain	t S23-Jn	0069954				Х					
114 L7-L02	Jun 28, 2023	Pain	t S23-Jn	0069955				Х					
115 L7-L03	Jun 28, 2023	Pain	t S23-Jn	0069956				Х					
116 L7-L04	Jun 28, 2023	Pain	t S23-Jn	0069957				Х					
117 L7-L05	Jun 28, 2023	Pain	t S23-Jn	0069958				Х					
118 L7-L06	Jun 28, 2023	Pain	t S23-Jn	0069959				Х					
119 L5-A12	Jun 28, 2023	Build	ding S23-Jn	0069960		Х							
	1		I		1	1	1		I				

•		fine	ABN: 50 005 085 521	ent Testing Aust	tralia Pty Ltd							ABN: 91 05 0159 898	NZBN: 942904602495	nent Testing NZ Ltd 4
web: v email:	www.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 125	Geelong 19/8 Lewalan Stre Grovedale VIC 3216 Tel: +61 3 8564 5 4 NATA# 1261 Site:	Sydney eet 179 Mag Girrawee NSW 214 5000 Tel: +61 : # 25403 NATA# 1	owar Ro n 45 2 9900 8 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitch ACT 2 Tel: + 7 NATA	erra ,2 Dacr ell 2911 61 2 61 # 1261	Brisbane re Street 1/21 Smallwood Place Murarrie QLD 4172 113 8091 Tel: +61 7 3902 4600 Site# 25466 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 94 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Ca Aa	ompany Name: Idress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	lo.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pr Pr	oject Name: oject ID:	RPA HOSP 63888	'ITAL-MAIN BUILD	ING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		S	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217			Х	X	Х	Х	_				
120	L5-A13	Jun 28, 2023	Mate Build	erials ding S23	3-Jn0069961		x			-				
121	L5-A14	Jun 28, 2023	Build	ding S23	3-Jn0069962		x			-				
122	L5-A15	Jun 28, 2023	Build	ding S23 prials	3-Jn0069963		x			-				
123	L5-A16	Jun 28, 2023	Build	ding S23 erials	3-Jn0069964		х							
124	L5-A17	Jun 28, 2023	Build Mate	ding S23 erials	3-Jn0069965		x							
125	L5-A18	Jun 28, 2023	Build Mate	ding S23 erials	3-Jn0069966		x							
126	L5-A19	Jun 28, 2023	Build Mate	ding S23 erials	3-Jn0069967		x			-				
127	L5-A20	Jun 28, 2023	Build Mate	ding S23 erials	3-Jn0069968		x			-				
128	L5-A21	Jun 28, 2023	Build Mate	ding S23 prials	3-Jn0069969		Х							

		fine	ABN: 50 005 085 521	ient Testing Australia								ABN: 91 05 0159 898	NZBN: 942904602495	4
web: ww email: E	ww.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 125	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 4 NATA# 1261 Site# 254	Sydney 179 Mag Girrawee NSW 214 Tel: +61 403 NATA# 1	owar Ro n 15 2 9900 8 261 Site	oad 8400 e# 1821	Canb Unit 1 Mitche ACT 2 Tel: + 7 NATA	erra I,2 Dacre ell 2911 -61 2 61 A# 1261	Brisbane 2 Street 1/21 Smallwood Place Murarrie QLD 4172 13 8091 Tel: +61 7 3902 4600 Site# 25466 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Cor Ado	npany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	No.: #:	1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pro Pro	ject Name: ject ID:	RPA HOSF 63888	PITAL-MAIN BUILD	ING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Sydn	ey Laboratory	NATA # 1261	Site # 18217			X	x	х	x					
129	L5-A22	Jun 28, 2023	Build	ding S23-Jn0 erials	0069970		x							
130	L5-A23	Jun 28, 2023	Build	ding S23-Jn	0069971		x							
131	L5-A24	Jun 28, 2023	Build	ding S23-Jn	0069972		x							
132	L5-A25	Jun 28, 2023	Build	ding S23-Jn	0069973		x							
133		lun 28, 2023	Dust	t S23- Ini	1060074	x								
134	L5-LD03	Jun 28, 2023	Dust	t \$23-Jil	1069974	~		x						
135	15-102	Jun 28, 2023	Pain	t S23-Jn	069976				x					
136	15-103	Jun 28, 2023	Pain	it S23-In	069977				X					
137	15-104	Jun 28, 2023	Pain	t \$23-Jn	069978				x					
138	1.5-1.05	Jun 28, 2023	Pain	t \$23- In/	069979				x					
139	15-106	Jun 28, 2023	Pain	t \$23- In/	069980				x					
140	15-107	Jun 28, 2023	Pain	t \$23- In	0069981				x					
1 1 1	L6-A12	Jun 28, 2023	Build	ting \$23- In(1060082	1	V							

			Eurofins Environ ABN: 50 005 085 521	Inment Testing Australia Pty Ltd 21										Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954		
web: www.eurofins.com.au		Melbourne Geelong 6 Monterey Road 19/8 Lewalan Street Dandenong South Grovedale VIC 3175 VIC 3216 Tel: +61 3 8564 5000 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254 NATA# 1261 Site# 2540		Sydne alan Street 179 M e Girraw NSW : 38564 5000 261 Site# 25403 NATA	Sydney 179 Magowar Road Girraween NSW 2145 Tel: +61 2 9900 8400 403 NATA# 1261 Site# 18		Canberra Unit 1,2 Dacre Street Mitchell ACT 2911 00 Tel: +61 2 6113 8091 18217 NATA# 1261 Site# 25		Brisbane et 1/21 Smallwood Place Murarrie QLD 4172 91 Tel: +61 7 3902 4600 25466 NATA# 1261 Site# 20794		Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290			
Co Ad Pro	ompany Name: Idress: oject Name:	JBS & G Au Level 1, 50 Sydney NSW 2000 RPA HOSP	ustralia (NSW) P/I Margaret St ITAL-MAIN BUIL	L DING			C F F F	Order Report Phone Fax:	No.: : #: :	10 02	03655 2 8245 0300			Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM	
Pro	oject ID:	63888											E	urofins Analytical Ser	vices Manager : A	ndrew Black	
		s	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)								
Syd	ney Laboratory	- NATA # 1261	Site # 18217		-	X	X	X	X								
<u> </u>			Ma	aterials			_			_							
142	L6-AD03	Jun 28, 2023	Du	st	S23-Jn006998	3	<u> </u>			_							
143	L6-LD03	Jun 28, 2023	Du	st	S23-Jn006998	4	_	X		4							
144	L5-L01	Jun 28, 2023	Pa	int	S23-Jn007019	1			X	_							
Test	t Counts					8	94	11	32								



Internal Quality Control Review and Glossary General

- 1. 2. 3.
- AC data may be available on request. All soil results are reported on a dry basis, unless otherwise stated. Samples were analysed on an 'as received' basis. Information identified on this report with the colour **blue** indicates data provided by customer that may have an impact on the results. This report replaces any interim results previously issued. 4. 5.

Holding Times Please refer to the most recent version of the 'Sample Preservation and Container Guide' for holding times (QS3001).

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported. Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units % w/w: F/fld F/mL g, kg g/kg L, mL L, mL L/min min	Percentage weight-for-weight basis, e.g. of asbestos in asbestos-containing finds in soil samples (% w/w) Airborne fibre filter loading as Fibres (N) per Fields counted (n) Airborne fibre reported concentration as Fibres per millilitre of air drawn over the sampler membrane (C) Mass, e.g. of whole sample (M) or asbestos-containing find within the sample (m) Concentration in grams per kilogram Volume, e.g. of air as measured in AFM (V = r x t) Airborne fibre sampling Flowrate as litres per minute of air drawn over the sampler membrane (r) Time (t), e.g. of air sample collection period
Calculations	
Airborne Fibre Concentration:	$C = \left(\frac{A}{a}\right) \times \left(\frac{N}{n}\right) \times \left(\frac{1}{r}\right) \times \left(\frac{1}{r}\right) = K \times \left(\frac{N}{n}\right) \times \left(\frac{1}{v}\right)$
Asbestos Content (as asbestos):	$\% w/w = \frac{(m \times P_A)}{M}$
Weighted Average (of asbestos):	$\mathscr{H}_{WA} = \sum \frac{(m \times P_A)_X}{x}$
Terms	
%asbestos	Estimated percentage of asbestos in a given matrix. May be derived from knowledge or experience of the material, informed by HSG264 Appendix 2, else assumed to be 15% in accordance with WA DOH Appendix 2 (P _A).
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded (non-friable) condition. For the purposes of the NEPM and WA DOH, ACM corresponds to material larger than 7 mm x 7 mm.
AF	Asbestos Fines. Asbestos contamination within a soil sample, as defined by WA DOH. Includes loose fibre bundles and small pieces of friable and non-friable material such as asbestos cement fragments mixed with soil. Considered under the NEPM as equivalent to "non-bonded / friable".
AFM	Airborne Fibre Monitoring, e.g. by the MFM.
Amosite	Amosite Asbestos Detected. Amosite may also refer to Fibrous Grunerite or Brown Asbestos. Identified in accordance with AS 4964-2004.
AS	Australian Standard.
Asbestos Content (as asbestos)	Total % w/w asbestos content in asbestos-containing finds in a soil sample (% w/w).
Chrysotile	Chrysotile Asbestos Detected. Chrysotile may also refer to Fibrous Serpentine or White Asbestos. Identified in accordance with AS 4964-2004.
COC	Chain of Custody.
Crocidolite	Crocidolite Asbestos Detected. Crocidolite may also refer to Fibrous Riebeckite or Blue Asbestos. Identified in accordance with AS 4964-2004.
Dry	Sample is dried by heating prior to analysis.
DS	Dispersion Staining. Technique required for Unequivocal Identification of asbestos fibres by PLM.
FA	Fibrous Asbestos. Asbestos containing material that is wholly or in part friable, including materials with higher asbestos content with a propensity to become friable with handling, and any material that was previously non-friable and in a severely degraded condition. For the purposes of the NEPM and WA DOH, FA generally corresponds to material larger than 7 mm x 7 mm, although FA may be more difficult to visibly distinguish and may be assessed as AF.
Fibre Count	Total of all fibres (whether asbestos or not) meeting the counting criteria set out in the NOHSC:3003
Fibre ID	Fibre Identification. Unequivocal identification of asbestos fibres according to AS 4964-2004. Includes Chrysotile, Amosite (Grunerite) or Crocidolite asbestos.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
HSG248	UK HSE HSG248, Asbestos: The Analysts Guide, 2nd Edition (2021).
HSG264	UK HSE HSG264, Asbestos: The Survey Guide (2012).
ISO (also ISO/IEC)	International Organization for Standardization / International Electrotechnical Commission.
K Factor	Microscope constant (K) as derived from the effective filter area of the given AFM membrane used for collecting the sample (A) and the projected eyepiece graticule area of the specific microscope used for the analysis (a).
LOR	Limit of Reporting.
MFM (also NOHSC:3003)	Membrane Filter Method. As described by the Australian Government National Occupational Health and Safety Commission, Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003(2005)].
NEPM (also ASC NEPM)	National Environment Protection (Assessment of Site Contamination) Measure, (2013, as amended).
Organic	Organic Fibres Detected. Organic may refer to Natural or Man-Made Polymeric Fibres. Identified in accordance with AS 4964-2004.
PCM	Phase Contrast Microscopy. As used for Fibre Counting according to the MFM.
PLM	Polarised Light Microscopy. As used for Fibre Identification and Trace Analysis according to AS 4964-2004.
Sampling	Unless otherwise stated Eurofins are not responsible for sampling equipment or the sampling process.
SMF	Synthetic Mineral Fibre Detected. SMF may also refer to Man Made Vitreous Fibres. Identified in accordance with AS 4964-2004.
SRA	Sample Receipt Advice.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres (particularly asbestos) in a given sample matrix.
UK HSE HSG	United Kingdom, Health and Safety Executive, Health and Safety Guidance, publication.
	Unidentified Mineral Fibre Detected. Fibrous minerals that are detected but have not been unequivocally identified by PLM with DS according the AS 4964-2004 May include (but not limited to) Actinolite, Anthophyllite or Tremolite asbestos.
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos- Contaminated Sites in Western Australia (updated 2021), including Appendix Four: Laboratory analysis
Weighted Average	Combined average % w/w asbestos content of all asbestos-containing finds in the given aliquot or total soil sample (%wA).



Comments

Sample Integrity	
Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Asbestos Counter/Identifier:

Chamath JHM Annakkage

Authorised by:

Laxman Dias

Senior Analyst-Asbestos

Senior Analyst-Asbestos

Glenn Jackson Managing Director

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please click here.

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.



JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000

Attention:

Stuart Lumsden

Report
Project name
Project ID
Received Date

1003655-S RPA HOSPITAL-MAIN BUILDING 63888 Jun 29, 2023

Iac-MRA	



NATA Accredited Accreditation Number 1261 Site Number 18217

Accredited for compliance with ISO/IEC 17025 – Testing NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.

Client Sample ID			L1-L01	L1-L02	L1-L03	L2-L01
Sample Matrix			Paint	Paint	Paint	Paint
Eurofins Sample No.			S23-Jn0069847	S23-Jn0069848	S23-Jn0069849	S23-Jn0069855
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	0.04	< 0.01	6.6	< 0.01
Lead (% w/w)	0.01	%	0.04	< 0.01	6.6	< 0.01

Client Sample ID			L3-LD01	L3-LD02	L4-LD01	L4-LD02
Sample Matrix			Dust	Dust	Dust	Dust
Eurofins Sample No.			S23-Jn0069867	S23-Jn0069868	S23-Jn0069897	S23-Jn0069898
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Heavy Metals						
Lead	5	mg/kg	130	< 5	510	100

Client Sample ID			L4-L01	L4-L02	L4-L03	L4-L04
Sample Matrix			Paint	Paint	Paint	Paint
Eurofins Sample No.			S23-Jn0069899	S23-Jn0069900	S23-Jn0069901	S23-Jn0069902
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	0.02	< 0.01	2.9	0.03

Client Sample ID			L4-L05	L4-L06	L4-L07	L4-L08
Sample Matrix			Paint	Paint	Paint	Paint
Eurofins Sample No.			S23-Jn0069903	S23-Jn0069904	S23-Jn0069905	S23-Jn0069906
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	< 0.01	0.09	0.06	0.32



Client Sample ID Sample Matrix Eurofins Sample No.			L4-L09 Paint S23-Jn0069907	L5-LD01 Dust S23-Jn0069921	L5-LD02 Dust S23-Jn0069922	L6-LD01 Dust S23-Jn0069936
Test/Reference	LOR	Unit	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Lead (% w/w) Heavy Metals	0.01	%	3.8	-	-	-
Lead	5	mg/kg	-	100	40	49

Client Sample ID			L6-LD02	L6-L01	L6-L02	L6-L03
Sample Matrix			Dust	Paint	Paint	Paint
Eurofins Sample No.			S23-Jn0069937	S23-Jn0069938	S23-Jn0069939	S23-Jn0069940
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	-	0.01	3.3	< 0.01
Heavy Metals						
Lead	5	mg/kg	56	-	-	-

Client Sample ID Sample Matrix Eurofins Sample No. Date Sampled			L6-L04 Paint S23-Jn0069941 Jun 28, 2023	L6-L05 Paint S23-Jn0069942 Jun 28, 2023	L6-L06 Paint S23-Jn0069943 Jun 28, 2023	L7-LD01 Dust S23-Jn0069953 Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	5.3	0.11	1.1	-
Heavy Metals						
Lead	5	mg/kg	-	-	-	190

Client Sample ID			L7-L01	L7-L02	L7-L03	L7-L04
Sample Matrix			Paint	Paint	Paint	Paint
Eurofins Sample No.			S23-Jn0069954	S23-Jn0069955	S23-Jn0069956	S23-Jn0069957
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	4.3	< 0.01	0.05	0.15

Client Sample ID Sample Matrix Eurofins Sample No. Date Sampled			L7-L05 Paint S23-Jn0069958 Jun 28, 2023	L7-L06 Paint S23-Jn0069959 Jun 28, 2023	L5-LD03 Dust S23-Jn0069975 Jun 28, 2023	L5-L02 Paint S23-Jn0069976 Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	< 0.01	0.03	-	0.08
Heavy Metals						
Lead	5	mg/kg	-	-	310	-



Client Sample ID			L5-L03	L5-L04	L5-L05	L5-L06
Sample Matrix			Paint	Paint	Paint	Paint
Eurofins Sample No.			S23-Jn0069977	S23-Jn0069978	S23-Jn0069979	S23-Jn0069980
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	3.5	5.4	7.5	3.0

Client Sample ID Sample Matrix Eurofins Sample No. Date Sampled			L5-L07 Paint S23-Jn0069981 Jun 28, 2023	L6-LD03 Dust S23-Jn0069984 Jun 28, 2023	L5-L01 Paint S23-Jn0070191 Jun 28, 2023
Test/Reference	LOR	Unit			
Lead (% w/w)	0.01	%	1.8	-	0.49
Heavy Metals					
Lead	5	mg/kg	-	26	-



Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Lead (% w/w)	Sydney	Jun 30, 2023	6 Months
- Method: LTM-MET-3040 Metals in Waters Soils & Sediments by ICP-MS			
Heavy Metals	Sydney	Jul 05, 2023	28 Days
- Method: LTM-MET-3040 Metals in Waters, Soils & Sediments by ICP-MS			

🛟 eurofins		fine	ABN: 50 005 08	ironment Testir 5 521	ig Australia Pty Lto	1					ABN: 91 05 0159 898	Eurofins Environn NZBN: 942904602495	nent Testing NZ Ltd 4
web: w email:	ww.eurofins.com.au	.com	Melbourne 6 Monterey Roa Dandenong Sou VIC 3175 Tel: +61 3 8564 NATA# 1261 Sit	Geelong d 19/8 Lew th Grovedal VIC 3216 5000 5000 Tel: +61 e# 1254 NATA# 1	Sydn. alan Street 179 M e Girrav b NSW 3 8564 5000 Tel: + 261 Site# 25403 NATA	ey lagowar Ro veen 2145 61 2 9900 # 1261 Sit	oad 8400 e# 1821	Canb Unit 1 Mitch ACT Tel: +	Brisbane 2 Dacre Street 1/21 Smallwood Place II Murarrie 911 QLD 4172 11 2 6113 8091 Tel: +61 7 3902 4600 # 1261 Site# 25466 NATA# 1261 Site# 20794	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Co Ad	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	stralia (NSW) Margaret St) P/L			O R P Fa	rder N eport hone: ax:	o.: ≭: 1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pro Pro	oject Name: oject ID:	RPA HOSP 63888	TAL-MAIN B	UILDING						E	urofins Analytical Ser	vices Manager : A	ndrew Black
		Sa	ample Detail			Asbestos Absence /Presence	Lead	Lead (% w/w)					
Sydı	ney Laboratory	- NATA # 1261	Site # 18217	,		Х	Х	Х					
Exte	rnal Laboratory	, 1			-								
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID								
1	L1-A01	Jun 28, 2023		Building Materials	S23-Jn006984	2 X							
2	L1-A02	Jun 28, 2023		Building Materials	S23-Jn006984	3 _X							
3	L1-A03	Jun 28, 2023		Building Materials	S23-Jn006984	4 x							
4	L1-A04	Jun 28, 2023		Building	S23-Jn006984	5 _X							
5	L1-A05	Jun 28, 2023		Building	S23-Jn006984	6 _X							
6	L1-L01	Jun 28. 2023		Paint	S23-Jn006984	7		x					
7	L1-L02	Jun 28, 2023		Paint	S23-Jn006984	8	1	X					
8	L1-L03	Jun 28, 2023		Paint	S23-Jn006984	9		х					
9	L2-A01	Jun 28, 2023		Building Materials	S23-Jn006985	0 x							

🛟 eurofins		fine	ABN: 50 005 085 521	ent Testing Austra	alia Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environn NZBN: 942904602495	nent Testing NZ Ltd 4
web: w email:	ww.eurofins.com.au EnviroSales@eurofins	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Stree Grovedale VIC 3216 Tel: +61 3 8564 500 NATA# 1261 Site# 3	Sydney t 179 Mage Girrawee NSW 214 00 Tel: +61 2 25403 NATA# 1	Canberra Brisbane owar Road Unit 1,2 Dacre Street 1/21 Small n Mitchell Murarrie 5 ACT 2911 QLD 417: 2 9900 8400 Tel: +61 2 6113 8091 Tel: +61 7 261 Site# 18217 NATA# 1261 Site# 25466				N Place 1 X 4600 N te# 20794 S	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Cc Ac	ompany Name: Idress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ıstralia (NSW) P/L Margaret St				Or Re Pr Fa	der N eport none: ix:	o.: #: 1003655 02 8245 0300			Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pr Pr	oject Name: oject ID:	RPA HOSF 63888	ITAL-MAIN BUILDI	NG							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos Absence /Presence	Lead	Lead (% w/w)						
Syd	ney Laboratory	- NATA # 1261	Site # 18217			х	х	х						
10	L2-A02	Jun 28, 2023	Build Mate	ing S23 rials	In0069851	x								
11	L2-A03	Jun 28, 2023	Build Mate	ing S23 rials	In0069852	х								
12	L2-A04	Jun 28, 2023	Build Mate	ing S23 rials	In0069853	x								
13	L2-A05	Jun 28, 2023	Build Mate	ing S23-J rials	In0069854	x								
14	L2-L01	Jun 28, 2023	Paint	S23-	In0069855			Х						
15	L3-A01	Jun 28, 2023	Build Mate	ing S23 rials	In0069856	x								
16	L3-A02	Jun 28, 2023	Build Mate	ing S23 rials	In0069857	x								
17	L3-A03	Jun 28, 2023	Build Mate	ing S23 rials	In0069858	х								
18	L3-A04	Jun 28, 2023	Build Mate	ing S23 rials	In0069859	х								
19	L3-A05	Jun 28, 2023	Build Mate	ing S23 rials	In0069860	х								

•	AURO	fine	Eurofins Environme ABN: 50 005 085 521	nt Testing Australi	a Pty Ltd						Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environn NZBN: 942904602495	nent Testing NZ Ltd
web: w email:	ww.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 25	Sydney 179 Mag Girrawee NSW 212 Tel: +61 2 403 NATA# 1	owar Ro n 15 2 9900 8 261 Site	oad 3400 e# 1821	Canb Unit 1 Mitche ACT 2 Tel: + 7 NATA	rra Brisbane Dacre Street 1/21 Smallwood Place Murarrie 11 QLD 4172 1 2 6113 8091 Tel: +61 7 3902 4600 1261 Site# 25466 NATA# 1261 Site# 207	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 94 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Co Ad	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	istralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	5.: : 1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pro Pro	oject Name: oject ID:	RPA HOSP 63888	ITAL-MAIN BUILDII	١G						E	urofins Analytical Serv	vices Manager : A	ndrew Black
		Si	ample Detail			Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217			Х	X	х					
20	L3-A06	Jun 28, 2023	Buildi Mater	ng S23-Jn ials	0069861	x							
21	L3-A07	Jun 28, 2023	Buildi Mater	ng S23-Jn ials	0069862	x							
22	L3-A08	Jun 28, 2023	Buildi Mater	ng S23-Jn ials	0069863	x							
23	L3-A09	Jun 28, 2023	Buildi Mater	ng S23-Jn ials	0069864	х							
24	L3-AD01	Jun 28, 2023	Dust	S23-Jn	0069865	Х							
25	L3-AD02	Jun 28, 2023	Dust	S23-Jn	0069866	Х							
26	L3-LD01	Jun 28, 2023	Dust	S23-Jn	0069867		х						
27	L3-LD02	Jun 28, 2023	Dust	S23-Jn	0069868		Х						
28	L4-A01	Jun 28, 2023	Buildi Mater	ng S23-Jn ials	0069869	х							
29	L4-A02	Jun 28, 2023	Buildi Mater	ng S23-Jn ials	0069870	х							
30	L4-A03	Jun 28, 2023	Buildi Mater	ng S23-Jn ials	0069871	х							

🛟 eurofins	Eurofins Environme ABN: 50 005 085 521	ent Testing Australia	Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	NZBN: 942904602495	ent Testing NZ Ltd		
web: v email:	ww.eurofins.com.au	s.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 2540	Sydney 179 Mage Girrawee NSW 214 Tel: +61 2 03 NATA# 1	owar Ro n 5 2 9900 8 261 Site	ad 3400 # 1821	Canb Unit 1 Mitch ACT 2 Tel: + 7 NATA	Brisbane 2 Dacre Street 1/21 Smallwo II Murarrie 9911 QLD 4172 61 2 6113 8091 Tel: +61 7 39 # 1261 Site# 25466 NATA# 1261	002 4600 I Site# 20794 S	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Cc Ac	mpany Name: dress:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				Oi Re Pl Fa	rder N eport none: ax:	o.: #: 1003655 02 8245 0300			Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pr Pr	oject Name: oject ID:	RPA HOSF 63888	PITAL-MAIN BUILDII	NG							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos Absence /Presence	Lead	Lead (% w/w)						
Syd	ney Laboratory	- NATA # 1261	Site # 18217			х	х	х						
31	L4-A04	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069872	х								
32	L4-A05	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069873	x								
33	L4-A06	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069874	x								
34	L4-A07	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069875	х								
35	L4-A08	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069876	х								
36	L4-A09	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069877	x								
37	L4-A10	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069878	x								
38	L4-A11	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069879	х								
39	L4-A12	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069880	х								
40	L4-A13	Jun 28, 2023	Buildi	ng S23-Jn0	069881	Х								

🛟 eurofins	ABN: 50 005 085 521	ent Testing Australia	a Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environn NZBN: 942904602495	nent Testing NZ Ltd		
web: w email:	ww.eurofins.com.au	s.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 25	Sydney 179 Mago Girrawee NSW 214 Tel: +61 2 403 NATA# 1	owar Ro n I5 2 9900 8 261 Site	ad 3400 # 1821	Canb Unit 1 Mitch ACT 2 Tel: + 7 NATA	erra ,2 Dacre Street ell 2911 61 2 6113 8091 ,# 1261 Site# 25466	Brisbane 1/21 Smallwood Place Murarrie QLD 4172 Tel: +61 7 3902 4600 6 NATA# 1261 Site# 2079-	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Cc Ac	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				Or Re Pr Fa	der N eport none: ix:	lo.: #: 1003 02 8	3655 3245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pr Pr	oject Name: oject ID:	RPA HOSF 63888	PITAL-MAIN BUILDI	NG							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos Absence /Presence	Lead	Lead (% w/w)						
Syd	ney Laboratory	- NATA # 1261	Site # 18217			Х	х	х						
40	L4-A13	Jun 28, 2023	Build Mate	ing S23-Jn rials	0069881									
41	L4-A14	Jun 28, 2023	Build Mate	ing S23-Jn rials	0069882	x								
42	L4-A15	Jun 28, 2023	Build Mate	ing S23-Jn rials	0069883	x								
43	L4-A16	Jun 28, 2023	Build Mate	ing S23-Jn rials	0069884	х			-					
44	L4-A17	Jun 28, 2023	Build Mate	ing S23-Jn rials	0069885	х								
45	L4-A18	Jun 28, 2023	Build Mate	ing S23-Jn rials	0069886	х								
46	L4-A19	Jun 28, 2023	Build Mate	ing S23-Jn rials	0069887	x								
47	L4-A20	Jun 28, 2023	Build Mate	ing S23-Jn rials	0069888	x								
48	L4-A21	Jun 28, 2023	Build Mate	ing S23-Jn rials	0069889	x								
49	L4-A22	Jun 28, 2023	Build	ing S23-Jn	0069890	Х								

🛟 eurofins		fine	Eurofins Environn ABN: 50 005 085 521	ient Testing /	Australia Pty Ltd						Eurofins ARL Pty Ltd ABN: 91 05 0159 898	NZBN: 942904602495	ent Testing NZ Ltd
web: w email:	ww.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 125	Geelong 19/8 Lewalar Grovedale VIC 3216 Tel: +61 3 85 4 NATA# 1261	Sydney n Street 179 Mag Girrawee NSW 214 564 5000 Tel: +61 I Site# 25403 NATA# 1	owar Ro n 15 2 9900 8 261 Site	oad 3400 e# 1821	Canb Unit 1 Mitche ACT 2 Tel: + 7 NATA	Brisbane 2 Dacre Street 1/21 Smallwood Place Murarrie Murarrie 911 QLD 4172 51 2 6113 8091 Tel: +61 7 3902 4600 # 1261 Site# 25466 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Co Ad	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ıstralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	o.: #: 1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pro Pro	oject Name: oject ID:	RPA HOSP 63888	ITAL-MAIN BUILD	NG						E	urofins Analytical Ser	vices Manager : Ai	ndrew Black
		Si	ample Detail			Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217			х	x	х					
			Mat	erials									
50	L4-A23	Jun 28, 2023	Buil Mat	ding erials	S23-Jn0069891	x							
51	L4-A24	Jun 28, 2023	Buil Mat	ding erials	S23-Jn0069892	х							
52	L4-A25	Jun 28, 2023	Buil Mat	ding erials	S23-Jn0069893	x							
53	L4-A26	Jun 28, 2023	Buil Mat	ding erials	S23-Jn0069894	х							
54	L4-AD01	Jun 28, 2023	Dus	t	S23-Jn0069895	х							
55	L4-AD02	Jun 28, 2023	Dus	t	S23-Jn0069896	Х							
56	L4-LD01	Jun 28, 2023	Dus	t	S23-Jn0069897		Х						
57	L4-LD02	Jun 28, 2023	Dus	t	S23-Jn0069898		Х						
58	L4-L01	Jun 28, 2023	Pair	nt	S23-Jn0069899			Х					
59	L4-L02	Jun 28, 2023	Pair	nt	S23-Jn0069900			Х					
60	L4-L03	Jun 28, 2023	Pair	nt	S23-Jn0069901			Х					
61	L4-L04	Jun 28, 2023	Pair	nt	S23-Jn0069902			Х					

🛟 eurofins		fine	ABN: 50 005 085 521	ent Testing Australia	Pty Ltd				Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environn NZBN: 942904602495	nent Testing NZ Ltd		
web: w email:	ww.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 2540	Sydney 179 Mago Girrawee NSW 214 Tel: +61 2 03 NATA# 1	owar Ro n I5 2 9900 8 261 Site	ad 3400 # 1821	Canb Unit 1 Mitch ACT 2 Tel: + 7 NATA	Brisbane 2 Dacre Street 1/21 Smallwood Place II Murarrie 911 QLD 4172 61 2 6113 8091 Tel: +61 7 3902 4600 # 1261 Site# 25466 NATA# 1261 Site# 2075	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 94 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Co Ad	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ıstralia (NSW) P/L Margaret St				Oi Re Pi Fa	der N eport none: ix:	o.: #: 1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pro Pro	oject Name: oject ID:	RPA HOSP 63888	ITAL-MAIN BUILDII	NG						E	urofins Analytical Ser	vices Manager : A	ndrew Black
		S	ample Detail			Asbestos Absence /Presence	Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217			Х	х	х					
62	L4-L05	Jun 28, 2023	Paint	S23-Jn0	069903			х					
63	L4-L06	Jun 28, 2023	Paint	S23-Jn0	069904			Х					
64	L4-L07	Jun 28, 2023	Paint	S23-Jn0	069905			Х					
65	L4-L08	Jun 28, 2023	Paint	S23-Jn0	069906			Х					
66	L4-L09	Jun 28, 2023	Paint	S23-Jn0	069907			Х					
67	L5-A01	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069908	х							
68	L5-A02	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069909	x							
69	L5-A03	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069910	x							
70	L5-A04	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069911	х							
71	L5-A05	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069912	x							
72	L5-A06	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069913	x							
73	L5-A07	Jun 28, 2023	Buildi	ng S23-Jn0	069914	Х							

🔅 eurofins	Eurofins Environme ABN: 50 005 085 521	ent Testing Australia	Pty Ltd			Eurofins ARL Pty Ltd ABN: 91 05 0159 898	d Eurofins Environment Testing NZ Ltd NZBN: 9429046024954							
web: w email:	ww.eurofins.com.au	s.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 2540	Sydney 179 Mago Girraweel NSW 214 Tel: +61 2 03 NATA# 12	owar Ro 5 2 9900 8 261 Site	ad 3400 # 1821	Canb Unit 1 Mitch ACT 2 Tel: + 7 NATA	Brisbane 2 Dacre Street 1/21 Smallwood II Murarrie 911 QLD 4172 Si 2 6113 8091 Tel: +61 7 3902 # 1261 Site# 25466 NATA# 1261 Sit	N d Place 1/ M 2 4600 N ite# 20794 S	Vewcastle //2 Frost Drive Mayfield West NSW 2304 Fel: +61 2 4968 8448 VATA# 1261 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Co Ad	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ıstralia (NSW) P/L Margaret St				Oi Re Pl Fa	rder N eport none: ax:	o.: #: 1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM	
Project Name: RPA HOSPITAL-MAIN BUILDING Project ID: 63888											E	urofins Analytical Ser	vices Manager : A	ndrew Black
Sample Detail						Asbestos Absence /Presence	Lead	Lead (% w/w)						
Syd	ney Laboratory	- NATA # 1261	Site # 18217			Х	Х	х						
			Mater	ials										
74	L5-A08	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069915	х								
75	L5-A09	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069916	х								
76	L5-A10	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069917	х								
77	L5-A11	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069918	х								
78	L5-AD01	Jun 28, 2023	Dust	S23-Jn0	069919	х								
79	L5-AD02	Jun 28, 2023	Dust	S23-Jn0	069920	х								
80	L5-LD01	Jun 28, 2023	Dust	S23-Jn0	069921		х							
81	L5-LD02	Jun 28, 2023	Dust	S23-Jn0	069922		х							
82	L6-A01	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069923	х								
83	L6-A02	Jun 28, 2023	Buildi Mater	ng S23-Jn0 ials	069924	х								
84	L6-A03	Jun 28, 2023	Buildi	ng S23-Jn0	069925	Х								

🍪 eurofins		ABN: 50 005 085 521	ent Testing Austral	ia Pty Ltd		Eurofins ARL Pty Ltd ABN: 91 05 0159 898	d Eurofins Environment Testing NZ Ltd NZBN: 9429046024954							
web: v email:	ww.eurofins.com.au	s.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 2	Sydney 179 Mag Girrawee NSW 212) Tel: +61 : 5403 NATA# 1	owar Ro n I5 2 9900 8 261 Site	ad 3400 2# 1821	Canb Unit 1 Mitch ACT 2 Tel: + 7 NATA	erra ,2 Dacre Street ell 2911 61 2 6113 8091 \# 1261 Site# 2546	Brisbane 1/21 Smallwood Place Murarrie QLD 4172 Tel: +61 7 3902 4600 i6 NATA# 1261 Site# 2079	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
Cc Ac	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				Oi Re Pl Fa	rder N eport none: ax:	lo.: #: 100 02 8)3655 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Project Name: RPA HOSPITAL-MAIN BUILDING Project ID: 63888											E	urofins Analytical Ser	vices Manager : A	ndrew Black
Sample Detail						Asbestos Absence /Presence	Lead	Lead (% w/w)						
Syd	ney Laboratory	- NATA # 1261	Site # 18217			х	х	х						
84	L6-A03	Jun 28, 2023	Build Mate	ing S23-Ji rials	n0069925									
85	L6-A04	Jun 28, 2023	Build Mate	ing S23-Ji rials	n0069926	x								
86	L6-A05	Jun 28, 2023	Build Mate	ing S23-Ji rials	n0069927	x								
87	L6-A06	Jun 28, 2023	Build Mate	ing S23-Ji rials	n0069928	x			-					
88	L6-A07	Jun 28, 2023	Build Mate	ing S23-Ji rials	n0069929	х								
89	L6-A08	Jun 28, 2023	Build Mate	ing S23-Ji rials	n0069930	x								
90	L6-A09	Jun 28, 2023	Build Mate	ing S23-Ji rials	n0069931	x								
91	L6-A10	Jun 28, 2023	Build Mate	ing S23-Ji rials	n0069932	x								
92	L6-A11	Jun 28, 2023	Build Mate	ing S23-Ji rials	n0069933	x								
93	L6-AD01	Jun 28, 2023	Dust	S23-JI	n0069934	Х]					

Eurofins Environment Testing Australia Pty ABN: 50 005 085 521 Melbourne Geelong S					Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954		
web: w email:	ww.eurofins.com.au EnviroSales@eurofins	s.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 25403	Sydney 179 Mago Girraweer NSW 214 Tel: +61 2 NATA# 12	Image Canberra Brisbane Newcastle Magowar Road Unit 1,2 Dacre Street 1/21 Smallwood Place 1/2 Frost Drive raween Mitchell Murarrie Mayfield West NSV W 2145 ACT 2911 QLD 4172 Tel: +61 2 4968 84 : +61 2 9900 8400 Tel: +61 2 6113 8091 Tel: +61 7 3902 4600 NATA# 1261 TA# 1261 Site# 18217 NATA# 1261 Site# 25466 NATA# 1261 Site# 20794 Site# 25079 & 2523						Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
Co Ac	ompany Name: Idress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ıstralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	lo.: #: 100365 02 8245	5 5 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM	
Pr Pr	Project Name: RPA HOSPITAL-MAIN BUILDING Project ID: 63888										E	urofins Analytical Serv	vices Manager : Aı	ndrew Black	
Sample Detail						Asbestos Absence /Presence	Lead	Lead (% w/w)							
Syd	ney Laboratory	- NATA # 1261	Site # 18217			х	х	х							
94	L6-AD02	Jun 28, 2023	Dust	S23-Jn00	69935	Х									
95	L6-LD01	Jun 28, 2023	Dust	S23-Jn00	69936		Х								
96	L6-LD02	Jun 28, 2023	Dust	S23-Jn00	69937		Х								
97	L6-L01	Jun 28, 2023	Paint	S23-Jn00	69938			Х							
98	L6-L02	Jun 28, 2023	Paint	S23-Jn00	69939			Х							
99	L6-L03	Jun 28, 2023	Paint	S23-Jn00	69940			Х							
100	L6-L04	Jun 28, 2023	Paint	S23-Jn00	69941			Х							
101	L6-L05	Jun 28, 2023	Paint	S23-Jn00	69942			Х							
102	L6-L06	Jun 28, 2023	Paint	S23-Jn00	69943			Х							
103	L7-A01	Jun 28, 2023	Buildi Mater	ng S23-Jn00 rials	69944	х									
104	L7-A02	Jun 28, 2023	Buildi Mater	ng S23-Jn00 ials	69945	х									
105	L7-A03	Jun 28, 2023	Buildi Mater	ng S23-Jn00 ials	69946	x									
106	L7-A04	Jun 28, 2023	Buildi Mater	ng S23-Jn00 ials	69947	х									

		fine	Eurofins Environme ABN: 50 005 085 521	ent Testing Australia	Pty Ltd	Eurofins ARL Pty Ltd ABN: 91 05 0159 898	J Eurofins Environment Testing NZ Ltd NZBN: 9429046024954						
web: w email:	ww.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 254	Sydney 179 Mago Girrawee NSW 214 Tel: +61 2 03 NATA# 13	owar Ro 5 2 9900 8 261 Site	ad 3400 # 1821	Canb Unit 1 Mitche ACT 2 Tel: + 7 NATA	Brisbane ,2 Dacre Street 1/21 Smallwood Place III Murarrie 911 QLD 4172 61 2 6113 8091 Tel: +61 7 3902 4600 # 1261 Site# 25466 NATA# 1261 Site# 20794	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Co Ad	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ıstralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	lo.: #: 1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pre Pre	oject Name: oject ID:	RPA HOSP 63888	ITAL-MAIN BUILDII	NG						E	urofins Analytical Serv	vices Manager : A	ndrew Black
	Sample Detail						Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217			х	х	Х					
107	L7-A05	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069948	х							
108	L7-A06	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069949	х							
109	L7-A07	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069950	х							
110	L7-A08	Jun 28, 2023	Buildi Mater	ng S23-Jn0 rials	069951	х							
111	L7-AD01	Jun 28, 2023	Dust	S23-Jn0	069952	Х							
112	L7-LD01	Jun 28, 2023	Dust	S23-Jn0	069953		Х						
113	L7-L01	Jun 28, 2023	Paint	S23-Jn0	069954			Х					
114	L7-L02	Jun 28, 2023	Paint	S23-Jn0	069955			Х					
115	L7-L03	Jun 28, 2023	Paint	S23-Jn0	069956			Х					
116	L7-L04	Jun 28, 2023	Paint	S23-Jn0	069957			Х					
117	L7-L05	Jun 28, 2023	Paint	S23-Jn0	069958			Х					
118	L7-L06	Jun 28, 2023	Paint	S23-Jn0	069959			Х					
119	L5-A12	Jun 28, 2023	Buildi	ng S23-Jn0	069960	Х							

🔅 eurofins		Eurofins Environme ABN: 50 005 085 521	ent Testing Australi	a Pty Ltd		Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954							
web: w email:	ww.eurofins.com.au	s.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 25	Sydney 179 Mag Girrawee NSW 214 Tel: +61 403 NATA# 1	owar Ro n 15 2 9900 8 261 Site	ad 3400 2# 1821	Canb Unit 1 Mitch ACT : Tel: + 7 NATA	erra ,2 Dacre Street ell 2911 61 2 6113 8091 # 1261 Site# 2546	Brisbane 1/21 Smallwood Place Murarrie QLD 4172 Tel: +61 7 3902 4600 6 NATA# 1261 Site# 2079	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
Co Ad	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	lo.: #: 100 02 8	3655 3245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	РМ
Project Name: RPA HOSPITAL-MAIN BUILDING Project ID: 63888											E	urofins Analytical Ser	vices Manager : A	ndrew Black
Sample Detail						Asbestos Absence /Presence	Lead	Lead (% w/w)						
Sydı	ey Laboratory	- NATA # 1261	Site # 18217			Х	х	х						
			Mater	rials										
120	L5-A13	Jun 28, 2023	Buildi Mater	ing S23-Jn rials	0069961	x								
121	L5-A14	Jun 28, 2023	Buildi Mater	ing S23-Jn rials	0069962	х								
122	L5-A15	Jun 28, 2023	Buildi Mater	ing S23-Jn rials	0069963	x								
123	L5-A16	Jun 28, 2023	Buildi Mater	ing S23-Jn rials	0069964	х								
124	L5-A17	Jun 28, 2023	Buildi Mater	ing S23-Jn rials	0069965	x								
125	L5-A18	Jun 28, 2023	Buildi Mater	ing S23-Jn rials	0069966	x								
126	L5-A19	Jun 28, 2023	Buildi Mater	ing S23-Jn rials	0069967	х]					
127	L5-A20	Jun 28, 2023	Buildi Mater	ing S23-Jn rials	0069968	х								
128	L5-A21	Jun 28, 2023	Buildi Mater	ing S23-Jn rials	0069969	х								

		fine	ABN: 50 005 085 521	ent Testing Australia	Pty Ltd	Eurofins ARL Pty Ltd ABN: 91 05 0159 898	J Eurofins Environment Testing NZ Ltd NZBN: 9429046024954						
web: w email:	ww.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 254	Sydney 179 Mago Girrawee NSW 214 Tel: +61 2 03 NATA# 13	owar Ro 5 2 9900 8 261 Site	ad 3400 # 1821	Canb Unit 1 Mitche ACT 2 Tel: + 7 NATA	Brisbane ,2 Dacre Street 1/21 Smallwood Place III Murarrie 911 QLD 4172 61 2 6113 8091 Tel: +61 7 3902 4600 # 1261 Site# 25466 NATA# 1261 Site# 20794	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Co Ad	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ıstralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	lo.: #: 1003655 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pre Pre	oject Name: oject ID:	RPA HOSP 63888	ITAL-MAIN BUILDI	NG						E	urofins Analytical Serv	vices Manager : A	ndrew Black
	Sample Detail						Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217			х	х	х					
129	L5-A22	Jun 28, 2023	Buildi Mate	ng S23-Jn0 rials	069970	х							
130	L5-A23	Jun 28, 2023	Buildi Mate	ng S23-Jn0 rials	069971	х							
131	L5-A24	Jun 28, 2023	Buildi Mate	ng S23-Jn0 rials	069972	х							
132	L5-A25	Jun 28, 2023	Buildi Mate	ng S23-Jn0 rials	069973	х							
133	L5-AD03	Jun 28, 2023	Dust	S23-Jn0	069974	Х							
134	L5-LD03	Jun 28, 2023	Dust	S23-Jn0	069975		Х						
135	L5-L02	Jun 28, 2023	Paint	S23-Jn0	069976			Х					
136	L5-L03	Jun 28, 2023	Paint	S23-Jn0	069977			Х					
137	L5-L04	Jun 28, 2023	Paint	S23-Jn0	069978			Х					
138	L5-L05	Jun 28, 2023	Paint	S23-Jn0	069979			Х					
139	L5-L06	Jun 28, 2023	Paint	S23-Jn0	069980			Х					
140	L5-L07	Jun 28, 2023	Paint	S23-Jn0	069981			Х					
141	L6-A12	Jun 28, 2023	Buildi	ng S23-Jn0	069982	Х							

	Eurofins Environment Testing Australia Pty ABN: 50 005 085 521										Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954		
web: www.eurofins.com.au email: EnviroSales@eurofins	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 m NATA# 1261 Site# 1254		Sydney 179 Mag Girrawee NSW 21 00 Tel: +61 25403 NATA# 1	Sydney 179 Magowar Road Girraween NSW 2145 Tel: +61 2 9900 840 8 NATA# 1261 Site# 1			erra ,2 Dacre Street ell 2911 61 2 6113 8091 # 1261 Site# 25-	Brisbane eet 1/21 Smallwood Place Murarrie QLD 4172 091 Tel: +61 7 3902 4600 * 25466 NATA# 1261 Site# 20794	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 04 Site# 25079 & 25289	Perth 46-48 Banksia Road 4 Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
Company Name: Address:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/L Margaret St				C R P F	Order N Report Phone: Fax:	lo.: #: 10 02	003655 2 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM	
Project Name: Project ID:	RPA HOSF 63888	PITAL-MAIN BUILDI	NG							E	urofins Analytical Ser	vices Manager : A	ndrew Black	
	S	ample Detail			Asbestos Absence /Presence	Lead	Lead (% w/w)							
Sydney Laboratory	NATA # 126	Site # 18217	i		Х	X	Х							
		Mate	rials											
142 L6-AD03	Jun 28, 2023	Dust	S23-	Jn0069983	X									
143 L6-LD03	Jun 28, 2023	Dust	S23-	Jn0069984		X								
144 L5-L01	Jun 28, 2023	Paint	t S23-	Jn0070191			X							
Test Counts					101	11	32							



Internal Quality Control Review and Glossary

General

- 1. Laboratory QC results for Method Blanks, Duplicates, Matrix Spikes, and Laboratory Control Samples follows guidelines delineated in the National Environment Protection (Assessment of Site Contamination) Measure 1999, as amended May 2013 and are included in this QC report where applicable. Additional QC data may be available on request.
- 2. All soil/sediment/solid results are reported on a dry basis, unless otherwise stated.
- 3. All biota/food results are reported on a wet weight basis on the edible portion, unless otherwise stated.
- 4. Actual LORs are matrix dependant. Quoted LORs may be raised where sample extracts are diluted due to interferences.
- 5. Results are uncorrected for matrix spikes or surrogate recoveries except for PFAS compounds.
- 6. SVOC analysis on waters are performed on homogenised, unfiltered samples, unless noted otherwise.
- 7. Samples were analysed on an 'as received' basis.
- 8. Information identified on this report with blue colour, indicates data provided by customer that may have an impact on the results.
- 9. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the SRA. If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

For VOCs containing vinyl chloride, styrene and 2-chloroethyl vinyl ether the holding time is 7 days however for all other VOCs such as BTEX or C6-10 TRH then the holding time is 14 days.

Units

mg/kg: milligrams per kilogram	mg/L: milligrams per litre	μg/L: micrograms per litre
ppm: parts per million	ppb: parts per billion	%: Percentage
org/100 mL: Organisms per 100 millilitres	NTU: Nephelometric Turbidity Units	MPN/100 mL: Most Probable Number of organisms per 100 millilitres
CFU: Colony forming unit		

Terms

APHA	American Public Health Association
coc	Chain of Custody
СР	Client Parent - QC was performed on samples pertaining to this report
CRM	Certified Reference Material (ISO17034) - reported as percent recovery.
Dry	Where a moisture has been determined on a solid sample the result is expressed on a dry basis.
Duplicate	A second piece of analysis from the same sample and reported in the same units as the result to show comparison.
LOR	Limit of Reporting.
LCS	Laboratory Control Sample - reported as percent recovery.
Method Blank	In the case of solid samples these are performed on laboratory certified clean sands and in the case of water samples these are performed on de-ionised water.
NCP	Non-Client Parent - QC performed on samples not pertaining to this report, QC is representative of the sequence or batch that client samples were analysed within.
RPD	Relative Percent Difference between two Duplicate pieces of analysis.
SPIKE	Addition of the analyte to the sample and reported as percentage recovery.
SRA	Sample Receipt Advice
Surr - Surrogate	The addition of a like compound to the analyte target and reported as percentage recovery.
твто	Tributyltin oxide (<i>bis</i> -tributyltin oxide) - individual tributyltin compounds cannot be identified separately in the environment however free tributyltin was measured and its values were converted stoichiometrically into tributyltin oxide for comparison with regulatory limits.
TCLP	Toxicity Characteristic Leaching Procedure
TEQ	Toxic Equivalency Quotient or Total Equivalence
QSM	US Department of Defense Quality Systems Manual Version 5.4
US EPA	United States Environmental Protection Agency
WA DWER	Sum of PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTSA, 8:2 FTSA

QC - Acceptance Criteria

The acceptance criteria should be used as a guide only and may be different when site specific Sampling Analysis and Quality Plan (SAQP) have been implemented

RPD Duplicates: Global RPD Duplicates Acceptance Criteria is 30% however the following acceptance guidelines are equally applicable:

Results <10 times the LOR: No Limit

Results between 10-20 times the LOR: RPD must lie between 0-50%

Results >20 times the LOR: RPD must lie between 0-30%

NOTE: pH duplicates are reported as a range not as RPD

Surrogate Recoveries: Recoveries must lie between 20-130% for Speciated Phenols & 50-150% for PFAS. SVOCs recoveries 20 - 150%

PFAS field samples that contain surrogate recoveries in excess of the QC limit designated in QSM 5.4 where no positive PFAS results have been reported have been reviewed and no data was affected.

QC Data General Comments

- 1. Where a result is reported as a less than (<), higher than the nominated LOR, this is due to either matrix interference, extract dilution required due to interferences or contaminant levels within the sample, high moisture content or insufficient sample provided.
- 2. Duplicate data shown within this report that states the word "BATCH" is a Batch Duplicate from outside of your sample batch, but within the laboratory sample batch at a 1:10 ratio. The Parent and Duplicate data shown is not data from your samples.
- 3. pH and Free Chlorine analysed in the laboratory Analysis on this test must begin within 30 minutes of sampling. Therefore, laboratory analysis is unlikely to be completed within holding time. Analysis will begin as soon as possible after sample receipt.
- 4. Recovery Data (Spikes & Surrogates) where chromatographic interference does not allow the determination of recovery the term "INT" appears against that analyte.
- 5. For Matrix Spikes and LCS results a dash "-" in the report means that the specific analyte was not added to the QC sample.
- 6. Duplicate RPDs are calculated from raw analytical data thus it is possible to have two sets of data.



Quality Control Results

Test			Units	Result 1			Acceptance Limits	Pass Limits	Qualifying Code
Method Blank									
Lead (% w/w)			%	< 0.01			0.01	Pass	
Method Blank				-					
Heavy Metals									
Lead			mg/kg	< 5			5	Pass	
LCS - % Recovery									
Heavy Metals									
Lead			%	91			80-120	Pass	
Test	Lab Sample ID	QA Source	Units	Result 1			Acceptance Limits	Pass Limits	Qualifying Code
Spike - % Recovery									
Heavy Metals				Result 1					
Lead	S23-JI0003067	NCP	%	104			75-125	Pass	
Test	Lab Sample ID	QA Source	Units	Result 1			Acceptance Limits	Pass Limits	Qualifying Code
Duplicate									
Heavy Metals				Result 1	Result 2	RPD			
Lead	S23-JI0003066	NCP	mg/kg	10	10	2.0	30%	Pass	



Comments

Sample Integrity	
Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Authorised by:

Andrew Black Fang Yee Tan Laxman Dias Mickael Ros Analytical Services Manager Senior Analyst-Metal Senior Analyst-Asbestos Senior Analyst-Metal

Glenn Jackson Managing Director

Final Report – this report replaces any previously issued Report

- Indicates Not Requested
- * Indicates NATA accreditation does not cover the performance of this service
- Measurement uncertainty of test data is available on request or please click here.

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.
CHAIN	OF C	USTODY	
-------	------	--------	--



PROJECT NO.: 63888	PROJECT NO.: 63888									LABORATORY BATCH NO.:												
PROJECT NAME: RPA HOSPITAL	. /					SAMPLERS: Stuart Lumsden/Jordan Gomez																
DATE NEEDED BY: STANDARD	TAT					Q	LEV	EL: NE	PM (2	013)						_						
PHONE: Sydney: 02 8245 030	0 Perth: 0	8 9488 010	0 Brisb	ane: 07 3112 2688															_			
SEND REPORT & INVOICE TO: (1) adminnsw@	jbsg.com.au	; (2) <u>slum</u>	nsden@jbsg.com.au; (3) jgomez@	ibsg.com	<u>au;</u>													_			
OMMENTS / SPECIAL HANDLING / STORAGE OR DISPOSAL:																						
Sample to be	sent	Separat	fely	from Sydney Ot	file	BESTOS													MALYNAK	VSIS W/W		
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	AS													80	NEP	NOTES:	
L4-A27	MATERIAL	29/06/23		1 x bag		X											_		_			
																	_					
						T																
					1	1																
						\uparrow									-							
						+																
						+						-			+							
	1				_	+			1				-									
	-					+			+						-							
					-	+			-		+	-	-		+	\vdash	-	\uparrow				
		-				┢		-			+-+		1		1	++	-		-			
						+	-		-	-	+ +		+		+		-					
						+-	-		1				-+		+	++	+					
						+	\vdash		-		+		-	-	+	++	-		-			
						-	\vdash		+						+							
						+-	\vdash		+					-	-	+	-		-			
APULICUS PE						+			RECEN	/FD BY			-			E E	OR RF	CEIVIN	Ġ L	ABU	SE ONLY:	
RELINQUISHED B NAME: Stuart Lumsden DATE:	29/6/2	J CONSI	GNMENT	NOTE NO.		NAME: have 2.5								OLER	SEAL -	Yes	No .	*****	inta	ct	Broken	
NAME: DATE:		CONSI	GNMENT	NOTE NO.		N O	AME: F:			(DATE:		CC	COOLER SEAL - Yes No Intact Broken								
OF:	TRANSPORT CO									uric Acid	Prsvd V	ial: S = :	Sulfuric	OLER	TEMP	de Zinc Pr	eg C svd; E =	EDTA	Prsvo	d; ST	= Sterile Bottle; O = Other	

Container & Preservative Codes: P = Plastic; J = 5 IMSO FormsO13 - Chain of Custody - Generic

JF-1003659



Eurofins Environment Testing Australia Pty Ltd

ABN: 50 005 085 521					
Melbourne	Geelong	Sydney	Canberra	Brisbane	Newcastle
6 Monterey Road	19/8 Lewalan Street	179 Magowar Road	Unit 1,2 Dacre Street	1/21 Smallwood Place	1/2 Frost Drive
Dandenong South	Grovedale	Girraween	Mitchell	Murarrie	Mayfield West NSW 2304
VIC 3175	VIC 3216	NSW 2145	ACT 2911	QLD 4172	Tel: +61 2 4968 8448
Tel: +61 3 8564 5000	Tel: +61 3 8564 5000	Tel: +61 2 9900 8400	Tel: +61 2 6113 8091	Tel: +61 7 3902 4600	NATA# 1261
NATA# 1261 Site# 1254	NATA# 1261 Site# 25403	NATA# 1261 Site# 18217	NATA# 1261 Site# 25466	NATA# 1261 Site# 20794	Site# 25079 & 25289

Perth

www.eurofins.com.au

EnviroSales@eurofins.com

Eurofins ARL Pty Ltd Eurofins Environment Testing NZ Ltd NZBN: 9429046024954

ABN: 91 05 0159 898	NZBN: 9429046024954									
Perth	Auckland	Christchurch								
46-48 Banksia Road	35 O'Rorke Road	43 Detroit Drive								
Welshpool	Penrose,	Rolleston,								
WA 6106	Auckland 1061	Christchurch 7675								
Tel: +61 8 6253 4444	Tel: +64 9 526 4551	Tel: +64 3 343 5201								
NATA# 2377 Site# 2370	IANZ# 1327	IANZ# 1290								

Sample Receipt Advice

Company name:	JBS & G Australia (NSW) P/L
Contact name:	Stuart Lumsden
Project name:	RPA HOSPITAL
Project ID:	63888
Turnaround time:	5 Day
Date/Time received	Jun 29, 2023 2:45 PM
Eurofins reference	1003659

Sample Information

- A detailed list of analytes logged into our LIMS, is included in the attached summary table. 1
- All samples have been received as described on the above COC.
- COC has been completed correctly. 1
- N/A Attempt to chill was evident.
- Appropriately preserved sample containers have been used. 1
- All samples were received in good condition.
- Samples have been provided with adequate time to commence analysis in accordance with the relevant holding times.
- Appropriate sample containers have been used. 1
- Sample containers for volatile analysis received with zero headspace. 1
- Split sample sent to requested external lab. X
- X Some samples have been subcontracted.
- N/A Custody Seals intact (if used).

Notes

Contact

If you have any questions with respect to these samples, please contact your Analytical Services Manager:

Andrew Black on phone : (+61) 2 9900 8490 or by email: AndrewBlack@eurofins.com Results will be delivered electronically via email to Stuart Lumsden - slumsden@jbsg.com.au.

Global Leader - Results you can trust



Certificate of Analysis

Environment Testing

JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000



NATA Accredited Accreditation Number 1261 Site Number 18217

Accredited for compliance with ISO/IEC 17025–Testing NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.

Attention:	Stuart Lumsden
Report	1003659-AID
Project Name	RPA HOSPITAL
Project ID	63888
Received Date	Jun 29, 2023
Date Reported	Jul 07, 2023
Methodology:	
Asbestos Fibre Identification	Conducted in accordance with the Australian Standard AS 4964 – 2004: Method for the Qualitative Identification of Asbestos in Bulk Samples and in-house Method LTM-ASB-8020 by polarised light microscopy (PLM) and dispersion staining (DS) techniques. NOTE: Positive Trace Analysis results indicate the sample contains detectable respirable fibres.
Unknown Mineral Fibres	Mineral fibres of unknown type, as determined by PLM with DS, may require another analytical technique, such as Electron Microscopy, to confirm unequivocal identity. NOTE: While Actinolite, Anthophyllite and Tremolite asbestos may be detected by PLM with DS, due to variability in the optical properties of these materials, AS4964 requires that these are reported as UMF unless confirmed by an independent technique.
Subsampling Soil Samples	The whole sample submitted is first dried and then passed through a 10mm sieve followed by a 2mm sieve. All fibrous matter greater than 10mm, greater than 2mm as well as the material passing through the 2mm sieve are retained and analysed for the presence of asbestos. If the sub 2mm fraction is greater than approximately 30 to 60g then a sub-sampling routine based on ISO 3082:2009(E) is employed. NOTE: Depending on the nature and size of the soil sample, the sub-2 mm residue material may need to be sub-sampled for trace analysis, in accordance with AS 4964-2004.
Bonded asbestos- containing material (ACM)	The material is first examined and any fibres isolated for identification by PLM and DS. Where required, interfering matrices may be removed by disintegration using a range of heat, chemical or physical treatments, possibly in combination. The resultant material is then further examined in accordance with AS 4964 - 2004. NOTE: Even after disintegration it may be difficult to detect the presence of asbestos in some asbestos-containing bulk materials using PLM and DS. This is due to the low grade or small length or diameter of the asbestos fibres present in the material, or to the fact that very fine fibres have been distributed intimately throughout the materials. Vinyl/asbestos floor tiles, some asbestos-containing sealants and mastics, asbestos-containing epoxy resins and some ore samples are examples of these types of material, which are difficult to analyse.
Limit of Reporting	The performance limitation of the AS 4964 (2004) method for non-homogeneous samples is around 0.1 g/kg (equivalent to 0.01% (w/w)). Where no asbestos is found by PLM and DS, including Trace Analysis, this is considered to be at the nominal reporting limit of 0.01% (w/w). The NEPM screening level of 0.001% (w/w) is intended as an on-site determination, not a laboratory Limit of Reporting (LOR), per se. Examination of a large sample size (e.g. 500 mL) may improve the likelihood of detecting asbestos, particularly AF, to aid assessment against the NEPM criteria. Gravimetric determinations to this level of accuracy are outside of AS 4964 and hence NATA Accreditation does not cover the performance of this service (non-NATA results shown with an asterisk). NOTE: NATA News March 2014, p.7, states in relation to AS 4964: "This is a qualitative method with a nominal reporting limit of 0.01 % " and that currently in Australia "there is no validated method available for the quantification of asbestos". This report is consistent with the analytical procedures and reporting recommendations in the NEPM and the WA DoH.



RPA HOSPITAL
63888
Jun 29, 2023
1003659-AID

Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
L4-A27	23-Jn0069990	Jun 29, 2023	Approximate Sample 2g / 90x55x1mm Sample consisted of: Brown woven material	No asbestos detected. Organic fibre detected. No trace asbestos detected.



Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description

Asbestos - LTM-ASB-8020

Testing SiteExtractedSydneyJun 30, 2023

Holding Time 3 Indefinite

				vironment Testin	g Australia Pty L	td				Eurofins ARL Pty Ltd	Eurofins Environn	nent Testing NZ Ltd
web: wv email: E	ww.eurofins.com.au	COM	Melbourne 6 Monterey Roa Dandenong Sou VIC 3175 Tel: +61 3 8564 NATA# 1261 Sit	Geelong d 19/8 Lewa kth Grovedale VIC 3216 5000 Tel: +61 3 te# 1254 NATA# 12	Sydi alan Street 179 e Girra NSV 8564 5000 Tel: 261 Site# 25403 NAT	ney Magowar Roa ween / 2145 +61 2 9900 84 A# 1261 Site#	Canberra d Unit 1,2 Dacre Stre Mitchell ACT 2911 00 Tel: +61 2 6113 800 18217 NATA# 1261 Site#	Brisbane t 1/21 Smallwood Place Murarrie QLD 4172 91 Tel: +61 7 3902 4600 25466 NATA# 1261 Site# 2075	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 94 Site# 25079 & 25289	Abit. 91 05 0159 896 Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	4 Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Cor Ado Pro Pro	mpany Name: dress: ject Name: ject ID:	JBS & G Au Level 1, 50 I Sydney NSW 2000 RPA HOSPI 63888	stralia (NSW Margaret St TAL) P/L			Order No.: Report #: Phone: Fax:	1003659 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
									E	urofins Analytical Ser	vices Manager : A	ndrew Black
		Sa	ample Detail			Asbestos Absence /Presence						
Sydn	ey Laboratory -	NATA # 1261	Site # 18217	7		X						
Exter	rnal Laboratory	Sample Date	Sampling	Matrix								
NU	Sample ID	Sample Date	Time	IVIAUIX								
1	L4-A27	Jun 29, 2023		Building Materials	S23-Jn006999	90 x						
Test	Counts					1						



Internal Quality Control Review and Glossary General

- 1. 2. 3.
- CC data may be available on request. All soil results are reported on a dry basis, unless otherwise stated. Samples were analysed on an 'as received' basis. Information identified on this report with the colour **blue** indicates data provided by customer that may have an impact on the results. This report replaces any interim results previously issued. 4. 5.

Holding Times Please refer to the most recent version of the 'Sample Preservation and Container Guide' for holding times (QS3001).

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported. Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units % w/w: F/fld F/mL g, kg g/kg L, mL L, mL L/min min	Percentage weight-for-weight basis, e.g. of asbestos in asbestos-containing finds in soil samples (% w/w) Airborne fibre filter loading as Fibres (N) per Fields counted (n) Airborne fibre reported concentration as Fibres per milliliter of air drawn over the sampler membrane (C) Mass, e.g. of whole sample (M) or asbestos-containing find within the sample (m) Concentration in grams per kilogram Volume, e.g. of air as measured in AFM (V = r x t) Airborne fibre sampling Flowrate as litres per minute of air drawn over the sampler membrane (r) Time (t), e.g. of air sample collection period
Calculations	
Airborne Fibre Concentration:	$C = \left(\frac{n}{a}\right) \times \left(\frac{1}{r}\right) \times \left(\frac{1}{r}\right) = K \times \left(\frac{n}{r}\right) \times \left(\frac{1}{v}\right)$
Asbestos Content (as asbestos):	$\% w/w = \frac{(m \times P_A)}{M}$
Weighted Average (of asbestos):	$\%_{WA} = \sum \frac{(m \times P_A)_X}{x}$
Terms %ashestos	Estimated percentage of ashestos in a given matrix. May be derived from knowledge or experience of the material informed by HSG264 Appendix 2 else
///////////////////////////////////////	assumed to be 15% in accordance with WA DOH Appendix 2 (P_A).
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded (non-friable) condition. For the purposes of the NEPM and WA DOH, ACM corresponds to material larger than 7 mm x 7 mm.
AF	Asbestos Fines. Asbestos contamination within a soil sample, as defined by WA DOH. Includes loose fibre bundles and small pieces of friable and non-friable material such as asbestos cement fragments mixed with soil. Considered under the NEPM as equivalent to "non-bonded / friable".
AFM	Airborne Fibre Monitoring, e.g. by the MFM.
Amosite	Amosite Asbestos Detected. Amosite may also refer to Fibrous Grunerite or Brown Asbestos. Identified in accordance with AS 4964-2004.
AS	Australian Standard.
Asbestos Content (as asbestos)	Total % w/w asbestos content in asbestos-containing finds in a soil sample (% w/w).
Chrysotile	Chrysotile Asbestos Detected. Chrysotile may also refer to Fibrous Serpentine or White Asbestos. Identified in accordance with AS 4964-2004.
COC	Chain of Custody.
Crocidolite	Crocidolite Asbestos Detected. Crocidolite may also reter to Fibrous Riebeckite or Blue Asbestos. Identified in accordance with AS 4964-2004.
Dry	Sample is dried by heating prior to analysis.
DS	Dispersion Staining. Technique required for Unequivocal Identification of asbestos fibres by PLM.
FA	Fibrous Asbestos. Asbestos containing material that is wholly or in part friable, including materials with higher asbestos content with a propensity to become friable with handling, and any material that was previously non-friable and in a severely degraded condition. For the purposes of the NEPM and WA DOH, FA generally corresponds to material larger than 7 mm x 7 mm, although FA may be more difficult to visibly distinguish and may be assessed as AF.
Fibre Count	Total of all fibres (whether asbestos or not) meeting the counting criteria set out in the NOHSC:3003
Fibre ID	Fibre Identification. Unequivocal identification of asbestos fibres according to AS 4964-2004. Includes Chrysotile, Amosite (Grunerite) or Crocidolite asbestos.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
HSG248	UK HSE HSG248, Asbestos: The Analysts Guide, 2nd Edition (2021).
HSG264	UK HSE HSG264, Asbestos: The Survey Guide (2012).
ISO (also ISO/IEC)	International Organization for Standardization / International Electrotechnical Commission.
K Factor	Microscope constant (K) as derived from the effective filter area of the given AFM membrane used for collecting the sample (A) and the projected eyepiece graticule area of the specific microscope used for the analysis (a).
LOR	Limit of Reporting.
MFM (also NOHSC:3003)	Membrane Filter Method. As described by the Australian Government National Occupational Health and Safety Commission, Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003(2005)].
NEPM (also ASC NEPM)	National Environment Protection (Assessment of Site Contamination) Measure, (2013, as amended).
Organic	Organic Fibres Detected. Organic may refer to Natural or Man-Made Polymeric Fibres. Identified in accordance with AS 4964-2004.
PCM	Phase Contrast Microscopy. As used for Fibre Counting according to the MFM.
PLM	Polarised Light Microscopy. As used for Fibre Identification and Trace Analysis according to AS 4964-2004.
Sampling	Unless otherwise stated Eurofins are not responsible for sampling equipment or the sampling process.
SMF	Synthetic Mineral Fibre Detected. SMF may also refer to Man Made Vitreous Fibres. Identified in accordance with AS 4964-2004.
SRA	Sample Receipt Advice.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres (particularly asbestos) in a given sample matrix.
UK HSE HSG	United Kingdom, Health and Safety Executive, Health and Safety Guidance, publication.
	Unidentified Mineral Fibre Detected. Fibrous minerals that are detected but have not been unequivocally identified by PLM with DS according the AS 4964-2004 May include (but not limited to) Actinolite, Anthophyllite or Tremolite asbestos.
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos- Contaminated Sites in Western Australia (updated 2021), including Appendix Four: Laboratory analysis
Weighted Average	Combined average % w/w asbestos content of all asbestos-containing finds in the given aliquot or total soil sample (%wA).



Comments

Sample Integrity	
Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Asbestos Counter/Identifier:

Bennel Jiri

Senior Analyst-Asbestos

Authorised by:

Sayeed Abu

Senior Analyst-Asbestos

Glenn Jackson Managing Director

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please click here.

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Page lof 3



CHAIN OF CUSTODY

PROJECT NO.: 63888								LABORATORY BATCH NO.:														
PROJECT NAME: RPA HOSP	ITAL - EXTERNA	L BUILDINGS				SAMPLERS: Stuart Lumsden/Jordan Gomez																
DATE NEEDED BY: STANDA	RD TAT					Q	CL	.EVE	L: NEP	PM (20	13)											
PHONE: Sydney: 02 8245	0300 Perth: (08 9488 010	0 Brisbai	ne: 07 3112 2688																		
SEND REPORT & INVOICE TO	D: (1) adminnsw(@jbsg.com.au	; (2) <u>slums</u> c	den@jbsg.com.au; (3) jgomez@	bsg.com	.au;																
COMMENTS / SPECIAL HANDLING /	STORAGE OR DISPOS	AL:					Γ	T											TYP	OF		
																11			ANA	LYSIS		
						8													z			
						5													CATIC	٤		
						١ <u>छ</u>		ΞĮ.		11									Inter	MM		
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	R	E	1					_						ē	NB	NOTES:	
394-A01	Material	28/6/23		1 x bag		X		_			_											
394-A02	Material	28/6/23		1 x bag	_	X		_			_				_				_			
394-A03	Material	28/6/23		1 x bag		X																
B94-A04	Material	28/6/23		1 x bag		х																
B94-A05	Material	28/6/23		1 x bag		X																
B94-A06	Material	28/6/23		1 x bag		Х																
B94-A07	Material	28/6/23		1 x bag		X																
B94-A08	Material	28/6/23		1 x bag		х																
B94-A09	Material	28/6/23		1 x bag		Х																
B94-A10	Material	28/6/23		1 x bag		Х																
B94-A11	Material	28/6/23		1 x bag		Х																
B94-A12	Material	28/6/23		1 x bag		х																
B94-AD01	Dust	28/6/23		1 x bag		х																
B94-LD01	Dust	28/6/23		1 x bag			Х															
B94-L01	Paint	28/6/23		1 x bag			Х	5														
B94-L02	Paint	28/6/23		1 x bag			Х	8														
B94-L03	Paint	28/6/23		1 x bag			Х															
B94-L04	Paint	28/6/23		1 x bag			Х															
B94-L05	Paint	28/6/23		1 x bag			Х															
RELINQUISHE	DBY: 1			METHOD OF SHIPMENT:				_	R	ECEIVE	D BY:						FOF	RECEN	/ING I	ABL	SE ONLY:	
NAME: Stuart Lumsden DATE	29/6/25	CONSI	SNMENT NO	TE NO.				IE: T	na	TT.	2:2	3		CO	OLER S	EAL - Y	es	NO	. Int	act	Broken	****
OF: JBS&G		TRANS	PORT CO.			0)F:		e	m	~			co	OLER T		deg	c				
NAME: DATE	1	CONSI	SNMENT NO	TE NO.		NAME: DATE:							CO	OLER S	EAL - Y	es	No	, In	tact	Broken		
OF TRANSPORT CO							ar i							co	OLER T	EMP	deg	с				
Container & Preservative Codes: F	= Plastic; J = Soll Jar;	B = Glass Bottle;	N = Nitric Acid	Prsvd.; C = Sodium Hydroxide Prsvd; VC	= Hydrochlo	Ic Aci	id Pr	rsvd	Vial; VS	= Sulfur	ic Acid	Prsvd Via	al; S = S	ulfuric /	Acid Prs	/d; Z = Z1	inc Prsvo	t; E = ED'	TA Prs	/d; ST	= Sterile Bottle; O =	Other

IMSO Forms013 - Chain of Custody - Generic

1003663

CHAIN OF CUSTODY 2 - F 3 SJBS&G



PROJECT NO.: 63888		LABORATORY BATCH NO.:																	
PROJECT NAME: RPA HOSPITA	L – EXTERNA	L BUILDINGS				SAMPLERS: Stuart Lumsden/Jordan Gomez													
DATE NEEDED BY: STANDARD	TAT					QC LEVEL: NEPM (2013)													
PHONE: Sydney: 02 8245 03																			
SEND REPORT & INVOICE TO: (1	L) adminnsw@	pjbsg.com.au	; (2) <u>slum</u> :	sden@jbsg.com.au; (3) _jgomez@	jbsg.com.	au;			41										
COMMENTS / SPECIAL HANDLING / STORAGE OR DISPOSAL:								4									TYPE O ASBEST ANALY	DF TOS SIS	
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	Ph	S	Ē										IDEN	NEPA	NOTES:
B94-L06	Paint	28/6/23		1 x bag			х											Т	
B95-A01	Material	28/6/23		1 x bag		X		1											
B95-A02	Material	28/6/23		1 x bag		X													
B95-A03	Material	28/6/23		1 x bag		Х													
B95-A04	Material	28/6/23		1 x bag		X													
B95-A05	Material	28/6/23		1 x bag		X												+	
B95-A06	Material	28/6/23		1 x bag		Х									1-1			1	
B95-A07	Material	28/6/23		1 x bag		X												1	
B95-A08	Material	28/6/23		1 x bag		X												-	
B95-A09	Material	28/6/23		1 x bag		X													
B95-A10	Material	28/6/23		1 x bag		X		T									1	+	
B95-AD01	Dust	28/6/23		1 x bag		X													
B95-LD01	Dust	28/6/23		1 x bag			х											+	
B95-L01	Paint	28/6/23		1 x bag			Х											1	
B95-L02	Paint	28/6/23		1 x bag			Х												
B95-L03	Paint	28/6/23		1 x bag			х												
B95-L04	Paint	28/6/23		1 x bag			Х												
B95-L05	Paint	28/6/23		1 x bag			Х												
B95-L06	Paint	28/6/23		1 x bag			Х												
RELINQUISHED BY NAME: Stuart Lumsden DATE: 7	9/6/25	CONSIG	METHOD OF SHIPMENT: CONSIGNMENT NOTE NO.					RECEIVED BY: NAME: DATE:				FOR RECEIVING LAB USE ONLY: COOLER SEAL Yes No Intact Broken							
OF: JBS&G TRANSPORT CO. NAME: DATE: CONSIGNMENT NOTE NO. OF: TRANSPORT CO Container & Preservative Codes: P = Plastic: J = Soli Jar: B = Glass Bottle: N = Nitric Acid Prsvd.: C = Sodium Hydroxide Prsvd: VC = Hydrochloriu								OF: COOLER TEMP No Intact Broken OF: COOLER TEMP COOLER TEMP Intact Broken Broken						sterile Bottle; O = Other					

IMSO FormsO13 - Chain of Custody - Generic

Page 3 of 3

CHAIN OF CUSTODY



OF:

I 100 3663

JBS&G



Eurofins Environment Testing Australia Pty Ltd

ABN: 50 005 085 521					
Melbourne	Geelong	Sydney	Canberra	Brisbane	Nev
6 Monterey Road	19/8 Lewalan Street	179 Magowar Road	Unit 1,2 Dacre Street	1/21 Smallwood Place	1/2
Dandenong South	Grovedale	Girraween	Mitchell	Murarrie	May
VIC 3175	VIC 3216	NSW 2145	ACT 2911	QLD 4172	Tel:
Tel: +61 3 8564 5000	Tel: +61 3 8564 5000	Tel: +61 2 9900 8400	Tel: +61 2 6113 8091	Tel: +61 7 3902 4600	NAT

www.eurofins.com.au

EnviroSales@eurofins.com

Eurofins ARL Pty Ltd Eurofins Environment Testing NZ Ltd ABN: 91 05 0159 898 NZBN: 9429046024954

lelbourne	Geelong	Sydney	Canberra	Brisbane	Newcastle	Perth	Auckland	Christchurch
Monterey Road	19/8 Lewalan Street	179 Magowar Road	Unit 1,2 Dacre Street	1/21 Smallwood Place	1/2 Frost Drive	46-48 Banksia Road	35 O'Rorke Road	43 Detroit Drive
andenong South	Grovedale	Girraween	Mitchell	Murarrie	Mayfield West NSW 2304	Welshpool	Penrose,	Rolleston,
/IC 3175	VIC 3216	NSW 2145	ACT 2911	QLD 4172	Tel: +61 2 4968 8448	WA 6106	Auckland 1061	Christchurch 7675
el: +61 3 8564 5000	Tel: +61 3 8564 5000	Tel: +61 2 9900 8400	Tel: +61 2 6113 8091	Tel: +61 7 3902 4600	NATA# 1261	Tel: +61 8 6253 4444	Tel: +64 9 526 4551	Tel: +64 3 343 5201
JATA# 1261 Site# 1254	NATA# 1261 Site# 25403	NATA# 1261 Site# 18217	NATA# 1261 Site# 25466	NATA# 1261 Site# 20794	Site# 25079 & 25289	NATA# 2377 Site# 2370	IAN7# 1327	IAN7# 1290

Sample Receipt Advice

Company name:	JBS & G Australia (NSW) P/L
Contact name:	Stuart Lumsden
Project name:	RPA HOSPITA-EXTERNAL BUILDING
Project ID:	63888
Turnaround time:	5 Day
Date/Time received	Jun 29, 2023 2:45 PM
Eurofins reference	1003663

Sample Information

- A detailed list of analytes logged into our LIMS, is included in the attached summary table. 1
- All samples have been received as described on the above COC. 1
- COC has been completed correctly. 1
- N/A Attempt to chill was evident.
- Appropriately preserved sample containers have been used. 1
- All samples were received in good condition.
- Samples have been provided with adequate time to commence analysis in accordance with the relevant ./ holding times.
- Appropriate sample containers have been used. 1
- Sample containers for volatile analysis received with zero headspace. 1
- X Split sample sent to requested external lab.
- X Some samples have been subcontracted.
- N/A Custody Seals intact (if used).

Notes

Contact

If you have any questions with respect to these samples, please contact your Analytical Services Manager:

Andrew Black on phone : (+61) 2 9900 8490 or by email: AndrewBlack@eurofins.com Results will be delivered electronically via email to Stuart Lumsden - slumsden@jbsg.com.au.

Global Leader - Results you can trust



Certificate of Analysis

Environment Testing

JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000



NATA Accredited Accreditation Number 1261 Site Number 18217

Accredited for compliance with ISO/IEC 17025–Testing NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.

Attention:	Stuart Lumsden
Report	1003663-AID
Project Name	RPA HOSPITA-EXTERNAL BUILDING
Project ID	63888
Received Date	Jun 29, 2023
Date Reported	Jul 06, 2023
Methodology:	
Asbestos Fibre Identification	Conducted in accordance with the Australian Standard AS 4964 – 2004: Method for the Qualitative Identification of Asbestos in Bulk Samples and in-house Method LTM-ASB-8020 by polarised light microscopy (PLM) and dispersion staining (DS) techniques. NOTE: Positive Trace Analysis results indicate the sample contains detectable respirable fibres.
Unknown Mineral Fibres	Mineral fibres of unknown type, as determined by PLM with DS, may require another analytical technique, such as Electron Microscopy, to confirm unequivocal identity. NOTE: While Actinolite, Anthophyllite and Tremolite asbestos may be detected by PLM with DS, due to variability in the optical properties of these materials, AS4964 requires that these are reported as UMF unless confirmed by an independent technique.
Subsampling Soil Samples	The whole sample submitted is first dried and then passed through a 10mm sieve followed by a 2mm sieve. All fibrous matter greater than 10mm, greater than 2mm as well as the material passing through the 2mm sieve are retained and analysed for the presence of asbestos. If the sub 2mm fraction is greater than approximately 30 to 60g then a sub-sampling routine based on ISO 3082:2009(E) is employed. NOTE: Depending on the nature and size of the soil sample, the sub-2 mm residue material may need to be sub-sampled for trace analysis, in accordance with AS 4964-2004.
Bonded asbestos- containing material (ACM)	The material is first examined and any fibres isolated for identification by PLM and DS. Where required, interfering matrices may be removed by disintegration using a range of heat, chemical or physical treatments, possibly in combination. The resultant material is then further examined in accordance with AS 4964 - 2004. NOTE: Even after disintegration it may be difficult to detect the presence of asbestos in some asbestos-containing bulk materials using PLM and DS. This is due to the low grade or small length or diameter of the asbestos fibres present in the material, or to the fact that very fine fibres have been distributed intimately throughout the materials. Vinyl/asbestos floor tiles, some asbestos-containing sealants and mastics, asbestos-containing epoxy resins and some ore samples are examples of these types of material, which are difficult to analyse.
Limit of Reporting	The performance limitation of the AS 4964 (2004) method for non-homogeneous samples is around 0.1 g/kg (equivalent to 0.01% (w/w)). Where no asbestos is found by PLM and DS, including Trace Analysis, this is considered to be at the nominal reporting limit of 0.01% (w/w). The NEPM screening level of 0.001% (w/w) is intended as an on-site determination, not a laboratory Limit of Reporting (LOR), per se. Examination of a large sample size (e.g. 500 mL) may improve the likelihood of detecting asbestos, particularly AF, to aid assessment against the NEPM criteria. Gravimetric determinations to this level of accuracy are outside of AS 4964 and hence NATA Accreditation does not cover the performance of this service (non-NATA results shown with an asterisk). NOTE: NATA News March 2014, p.7, states in relation to AS 4964: "This is a qualitative method with a nominal reporting limit of 0.01% " and that currently in Australia "there is no validated method available for the quantification of asbestos". This report is consistent with the analytical procedures and reporting recommendations in the NEPM and the WA DoH.



Project Name	RPA HOSPITA-EXTERNAL BUILDING
Project ID	63888
Date Sampled	Jun 28, 2023
Report	1003663-AID

Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
B94-A01	23-Jn0069998	Jun 28, 2023	Approximate Sample 6g / 35x10x5mm Sample consisted of: Yellow mastic material	No asbestos detected. No trace asbestos detected.
B94-A02	23-Jn0069999	Jun 28, 2023	Approximate Sample <1g / 10x7x2mm Sample consisted of: Grey mastic material	Chrysotile asbestos detected.
B94-A03	23-Jn0070000	Jun 28, 2023	Approximate Sample 10g / 35x20x3mm Sample consisted of: Yellow mastic material	No asbestos detected. No trace asbestos detected.
B94-A04	23-Jn0070001	Jun 28, 2023	Approximate Sample 8g / 30x25x10mm Sample consisted of: Grey hard cement fragments	No asbestos detected. No trace asbestos detected.
B94-A05	23-Jn0070002	Jun 28, 2023	Approximate Sample 3g / 30x20x5mm Sample consisted of: Grey layered fibre cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
B94-A06	23-Jn0070003	Jun 28, 2023	Approximate Sample 27g / 70x30x5mm Sample consisted of: Brown fibre plaster cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
B94-A07	23-Jn0070004	Jun 28, 2023	Approximate Sample 2g / 30x20x5mm Sample consisted of: Brown mastic material	No asbestos detected. No trace asbestos detected.
B94-A08	23-Jn0070005	Jun 28, 2023	Approximate Sample 3g / 30x15x10mm Sample consisted of: Brown mastic material	No asbestos detected. No trace asbestos detected.



Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
B94-A09	23-Jn0070006	Jun 28, 2023	Approximate Sample 3g / 40x20x5mm Sample consisted of: Brown fibre plaster cement material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
B94-A10	23-Jn0070007	Jun 28, 2023	Approximate Sample 2g / 70x20x2mm Sample consisted of: Light blue flexible vinyl sheet, amber glue and bituminous material attached	No asbestos detected. No trace asbestos detected.
B94-A11	23-Jn0070008	Jun 28, 2023	Approximate Sample 2g / 50x25x2mm Sample consisted of: Black flexible linoleum and amber glue	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.
B94-A12	23-Jn0070009	Jun 28, 2023	Approximate Sample <1g / 12x8x2mm Sample consisted of: Brown fibre plaster material and white coating	No asbestos detected. Organic fibre detected. No trace asbestos detected.
B94-AD01	23-Jn0070010	Jun 28, 2023	Approximate Sample 10g Sample consisted of: Brown dust particles, fragments of soft fibrous material, paint flakes, cement, plant residue and organic debris	No asbestos detected at the reporting limit of 0.01% w/w. Synthetic mineral fibre detected. Organic fibre detected. No trace asbestos detected.
B95-A01	23-Jn0070018	Jun 28, 2023	Approximate Sample 3g / 35x15x5mm Sample consisted of: Grey fibre cement material	Chrysotile asbestos detected.
B95-A02	23-Jn0070019	Jun 28, 2023	Approximate Sample 3g / 30x20x5mm Sample consisted of: Black woven fibrous matrix covered with bitumin	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.
B95-A03	23-Jn0070020	Jun 28, 2023	Approximate Sample 3g / 70x60x3mm Sample consisted of: Black fibro- bituminous material	Chrysotile asbestos detected.
B95-A04	23-Jn0070021	Jun 28, 2023	Approximate Sample <1g / 7x5x3mm Sample consisted of: Off-white mastic material	No asbestos detected. No trace asbestos detected.
B95-A05	23-Jn0070022	Jun 28, 2023	Approximate Sample 2g / 25x15x5mm Sample consisted of: Grey fibre cement material	Chrysotile, amosite and crocidolite asbestos detected.
B95-A06	23-Jn0070023	Jun 28, 2023	Approximate Sample 1g / 15x10x5mm Sample consisted of: Off-white sealant and adhesive material	No asbestos detected. No trace asbestos detected.
B95-A07	23-Jn0070024	Jun 28, 2023	Approximate Sample 4g / 30x15x10mm Sample consisted of: Grey mastic material with brown coating	No asbestos detected. No trace asbestos detected.
B95-A08	23-Jn0070025	Jun 28, 2023	Approximate Sample 2g / 60x30x2mm Sample consisted of: Off-white flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.



Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
B95-A09	23-Jn0070026	Jun 28, 2023	Approximate Sample 2g / 40x15x3mm Sample consisted of: Grey hard cement material with amber glue	No asbestos detected. No trace asbestos detected.
B95-A10	23-Jn0070027	Jun 28, 2023	Approximate Sample 1g / 20x15x3mm Sample consisted of: Black bituminous material	No asbestos detected. No trace asbestos detected.
B95-AD01	23-Jn0070028	Jun 28, 2023	Approximate Sample 16g Sample consisted of: Brown dust particles, fragments of soft fibrous material, compressed fibrous material, plaster, paint flakes, plant residue and organic debris	No asbestos detected at the reporting limit of 0.01% w/w. Synthetic mineral fibre detected. Organic fibre detected. No trace asbestos detected.
GH-A01	23-Jn0070037	Jun 28, 2023	Approximate Sample 4g / 25x10x4mm Sample consisted of: Yellow mastic material	No asbestos detected. No trace asbestos detected.
GH-A02	23-Jn0070038	Jun 28, 2023	Approximate Sample 2g / 20x15x3mm Sample consisted of: Grey fibre cement material	Chrysotile asbestos detected.
GH-A03	23-Jn0070039	Jun 28, 2023	Approximate Sample 11g / 70x20x5mm Sample consisted of: Blue semi brittle vinyl sheet , glue and cement attached	No asbestos detected. Synthetic mineral fibre detected. No trace asbestos detected.
GH-A04	23-Jn0070040	Jun 28, 2023	Approximate Sample 4g / 40x20x3mm Sample consisted of: Grey fibre cement material	Chrysotile asbestos detected.
B28-A01	23-Jn0070043	Jun 28, 2023	Approximate Sample 56g / 90x30x5mm Sample consisted of: Grey compressed fibre cement material	Chrysotile asbestos detected.
B28-A02	23-Jn0070044	Jun 28, 2023	Approximate Sample 25g / 50x30x7mm Sample consisted of: Grey fibre cement material	Chrysotile and amosite asbestos detected.
B28-A03	23-Jn0070045	Jun 28, 2023	Approximate Sample 22g / 110x35x2mm Sample consisted of: Grey brittle vinyl tile material	Chrysotile asbestos detected.
B28-A04	23-Jn0070046	Jun 28, 2023	Approximate Sample 1g / 30x5x5mm Sample consisted of: Pieces of rope	Chrysotile asbestos detected.



Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description

Asbestos - LTM-ASB-8020 Asbestos - LTM-ASB-8020

Testing Site	Extracted	Holding Time			
Sydney	Jul 06, 2023	Indefinite			
Sydney	Jul 06, 2023	Indefinite			

•		fine	Eurofins Env ABN: 50 005 08	r <mark>ironment Testin</mark> 5 521	g Australia Pty Ltd	Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environn	nent Testing NZ Lto 4					
web: www.eurofins.com.au email: EnviroSales@eurofins.com			Melbourne 6 Monterey Roa Dandenong Sou VIC 3175 Tel: +61 3 8564 NATA# 1261 Sit	gowar Ro en 45 2 9900 1261 Site	oad 8400 e# 1821	Cank Unit 7 Mitch ACT Tel: 4 Tel: 4	erra I,2 Dao ell 2911 -61 2 6 A# 126	Brisbane Newcastle tre Street 1/21 Smallwood Place 1/2 Frost Drive Murarrie Mayfield West NSW 2304 QLD 4172 Tel: +61 2 4968 8448 113 8091 Tel: +61 7 3902 4600 NATA# 1261 1 Site# 25466 NATA# 1261 Site# 20794 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290		
C ¢	company Name: Address:	JBS & G Au Level 1, 50 Sydney NSW 2000	stralia (NSW Margaret St) P/L			O R Pi Fa	rder I eport hone: ax:	No.: #:	1003663 02 8245 0300	Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
F	Project Name: Project ID:	RPA HOSP 63888	TA-EXTERN	IAL BUILDING						E	urofins Analytical Ser	vices Manager : A	ndrew Black
		Sá	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)				
Sy	dney Laboratory	- NATA # 1261	Site # 18217	7		Х	Х	Х	Х				
Ex	ternal Laboratory					-				_			
N	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID					_			
1	B94-A01	Jun 28, 2023		Building Materials	S23-Jn0069998		x			_			
2	B94-A02	Jun 28, 2023		Building Materials	S23-Jn0069999		x						
3	B94-A03	Jun 28, 2023		Building Materials	S23-Jn0070000		x						
4	B94-A04	Jun 28, 2023		Building Materials	S23-Jn0070001		x						
5	B94-A05	Jun 28, 2023		Building Materials	S23-Jn0070002		x			-			
6	B94-A06	Jun 28, 2023		Building Materials	S23-Jn0070003		x						
7	B94-A07	Jun 28, 2023		Building Materials	S23-Jn0070004		x						
8	B94-A08	Jun 28, 2023		Building Materials	S23-Jn0070005		x						

		fine	ABN: 50 005 085 52	iment Testing	Australia Pty Lto	ABN: 91 05 0159 898	NZBN: 942904602495	nent Testing NZ Ltd 4						
web	Melbourne Geelong S 6 Monterey Road 19/8 Lewalan Street 1 19/8 Lewalan Street 1 19/8 Lewalan Street 1 19/8 Lewalan Street 1 19/8 Lewalan Street 1 19/8 Lewalan Street 1 19/8 Lewalan Street 1 10/10 Logo 19/8 Lewalan Street 1 1 10/10 Logo 10/10 Logo 10/10 Logo 1 10/10 Logo 10/10 Logo 10/10 Logo 10/10 Logo 11/10 Log				Sydn an Street 179 M Girrax NSW 8564 5000 Tel: + 11 Site# 25403 NATA	ey Magowar I ween 2145 -61 2 990 A# 1261 S	Road 0 8400 ite# 182	Canb Unit 1 Mitch ACT 1 Tel: + 17 NATA	berra 1,2 Dac iell 2911 i-61 2 6 ⁻ A# 1261	Brisbane re Street 1/21 Smallwood Place Murarrie QLD 4172 113 8091 Tel: +61 7 3902 4600 1 Site# 25466 NATA# 1261 Site# 2079	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
	Company Name: Address:	JBS & G Au Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/ Margaret St	L			C R P F	rder N eport hone: ax:	No.: #:	1003663 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
l	Project Name: Project ID:	RPA HOSP 63888	PITA-EXTERNAL	BUILDING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
Sample Detail							Asbestos Absence /Presence	Lead	Lead (% w/w)					
Sy	dney Laboratory	- NATA # 1261	Site # 18217		1	X	X	X	X	_				
9	B94-A09	Jun 28, 2023	Bu Ma	ilding aterials	S23-Jn007000	6	X							
10	B94-A10	Jun 28, 2023	Bu	ilding	S23-Jn007000	07	x							
11	B94-A11	Jun 28, 2023	Bu	ilding	S23-Jn007000	8	x			-				
12	B94-A12	Jun 28, 2023	Bu	ilding aterials	S23-Jn007000	9	x							
13	B94-AD01	Jun 28, 2023	Du	ist	S23-Jn007001	0 X				_				
14	B94-LD01	Jun 28, 2023	Du	ist	S23-Jn007001	1		Х		-				
15	6 B94-L01	Jun 28, 2023	Pa	int	S23-Jn007001	2			Х					
16	6 B94-L02	Jun 28, 2023	Pa	int	S23-Jn007001	3			Х					
17	B94-L03	Jun 28, 2023	Pa	int	S23-Jn007001	4			X]				
18	B94-L04	Jun 28, 2023	Pa	int	S23-Jn007001	5			Х					
19	B94-L05	Jun 28, 2023	Pa	int	S23-Jn007001	6			Х					
20	B94-L06	Jun 28, 2023	Pa	int	S23-Jn007001	7			Х					
21	B95-A01	Jun 28, 2023	Bu	ilding	S23-Jn007001	8	х]				

eurofins.		fine	ABN: 50 005 085 52	iment Testin 1	g Australia Pty L	ABN: 91 05 0159 898	NZBN: 9429046024954								
web	Melbourne Geel 6 Monterey Road 19/8 Dandenong South Grov veb: www.eurofins.com.au VIC 3175 email: EnviroSales@eurofins.com NATA# 1261 Site# 1254			Geelong 19/8 Lewa Grovedale VIC 3216 Tel: +61 3 254 NATA# 12	Syc alan Street 179 e Girr NS1 3 8564 5000 Tel: 261 Site# 25403 NA	Sydney Canberra Brisbane Newcastle 179 Magowar Road Unit 1,2 Dacre Street 1/21 Smallwood Place 1/2 Frost Drive Girraween Mitchell Murarrie Mayfield West NSW 2304 NSW 2145 ACT 2911 QLD 4172 Tel: +61 2 4968 8448 Tel: +61 2 9900 8400 Tel: +61 2 6113 8091 Tel: +61 7 3902 4600 NATA# 1261 3 NATA# 1261 Site# 18217 NATA# 1261 Site# 25079 & 25289 Site# 25079 & 25289 Site# 25079 & 25289				Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290			
Company Name: J Address: L S N		JBS & G Au Level 1, 50 Sydney NSW 2000	JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000				Order No.: Report #: 1003663 Phone: 02 8245 0300 Fax:						Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
	Project Name: Project ID:	RPA HOSF 63888	PITA-EXTERNAL	BUILDING								E	urofins Analytical Ser	vices Manager : A	ndrew Black
Sample Detail					Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)							
Sy	dney Laboratory	- NATA # 1261	Site # 18217		-		х	Х	Х	Х	-				
22	B95-A02	Jun 28, 2023	Bu	aterials ilding	S23-Jn00700)19		×			-				
23	B95-A03	Jun 28, 2023	Bu	ilding	S23-Jn00700	020		x			-				
24	B95-A04	Jun 28, 2023	Bu	ilding aterials	S23-Jn00700)21		х			-				
25	6 B95-A05	Jun 28, 2023	Bu	ilding aterials	S23-Jn00700)22		х			-				
26	B95-A06	Jun 28, 2023	Bu Ma	ilding aterials	S23-Jn00700)23		х							
27	B95-A07	Jun 28, 2023	Bu Ma	ilding aterials	S23-Jn00700)24		х							
28	B95-A08	Jun 28, 2023	Bu Ma	ilding aterials	S23-Jn00700)25		х							
29	B95-A09	Jun 28, 2023	Bu Ma	ilding aterials	S23-Jn00700)26		х							
30	B95-A10	Jun 28, 2023	Bu Ma	ilding aterials	S23-Jn00700)27		х							

web: www.eurofins.com.au email: EnviroSales@eurofins.com		ABN: 50 005 085 521	ment Testing Austra	lia Pty Ltd	Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954								
		Melbourne Geelong Sydney 6 Monterey Road 19/8 Lewalan Street 179 Mago Dandenong South Grovedale Girraweer VIC 3175 VIC 3216 NSW 214 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254 NATA# 1261 Site# 25403 NATA# 12			owar Ro en 45 2 9900 1261 Site	Canberra Brisbane Newcastle owar Road Unit 1,2 Dacre Street 1/21 Smallwood Place 1/2 Frost Drive n Mitchell Murarrie Mayfield West NSV 5 ACT 2911 QLD 4172 Tei: +61 2 4968 84 29900 8400 Tei: +61 2 6113 8091 Tei: +61 7 3902 4600 NATA# 1261 261 Site# 18217 NATA# 1261 Site# 25079 & 2525 Site# 25079 & 2525 Site# 25079 & 2525			Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 44 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290		
Co Ad	mpany Name: dress:	JBS & G A Level 1, 50 Sydney NSW 2000	ustralia (NSW) P/I Margaret St	-			O Re Pl Fa	rder N eport none: ax:	lo.: #:	1003663 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM
Pr Pr	oject Name: oject ID:	RPA HOSF 63888	PITA-EXTERNAL	BUILDING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
	Sample Detail				Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)						
Syd	ney Laboratory	- NATA # 1261	I Site # 18217			Х	X	х	Х					
31	B95-AD01	Jun 28, 2023	Du	st S23-J	n0070028	Х								
32	B95-LD01	Jun 28, 2023	Du	st S23-J	n0070029			Х		_				
33	B95-L01	Jun 28, 2023	Pai	nt S23-J	n0070030				Х	_				
34	B95-L02	Jun 28, 2023	Pa	nt S23-J	n0070031				Х	_				
35	B95-L03	Jun 28, 2023	Pai	nt S23-J	n0070032				Х	_				
36	B95-L04	Jun 28, 2023	Pai	nt S23-J	n0070033				Х	-				
37	B95-L05	Jun 28, 2023	Pai	nt S23-J	n0070034				Х	-				
38	B95-L06	Jun 28, 2023	Pai	nt S23-J	n0070035				Х	-				
39	B95-L07	Jun 28, 2023	Pa	nt S23-J	n0070036				Х	-				
40	GH-A01	Jun 28, 2023	Bui Ma	lding S23-J terials	n0070037		x			4				
41	GH-A02	Jun 28, 2023	Bui Ma	lding S23-J terials	n0070038		x			-				
42	GH-A03	Jun 28, 2023	Bui Ma	lding S23-J terials	n0070039		x			4				
43	GH-A04	Jun 28, 2023	Bui Ma	lding S23-J terials	n0070040		х							

	Eurofins Environment Testing Australia Pty Ltd ABN: 50 005 085 521 ABN: 50 005 085 521 Melbourne 6 Monterey Road Dandenong South email: EnviroSales@eurofins.com Geelong 019/8 Lewalan Street 179 Mage Girrawee VIC 3175 Sydney 19/8 Lewalan Street VIC 3175 NATA# 1261 Site# 1254 NATA# 1261 Site# 25403 NATA# 1261								ABN: 91 05 0159 898	1ent Testing NZ Ltd				
web: w email: I				Canberra Brisban gowar Road Unit 1,2 Dacre Street 1/21 Sr en Mitchell Murarri 45 ACT 2911 QLD 4 2 9900 8400 Tel: +61 2 6113 8091 Tel: +61 1261 Site# 18217 NATA# 1261 Site# 25466			erra I,2 Dacr ell 2911 -61 2 61 A# 1261	Brisbane a Street 1/21 Smallwood Place Murarrie QLD 4172 13 8091 Tel: +61 7 3902 4600 Site# 25466 NATA# 1261 Site# 2075	Newcastle Place 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 4600 NATA# 1261 e# 20794 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290		
Company Name: JBS & G Australia (NSW) P/L Address: Level 1, 50 Margaret St Sydney NSW 2000			Order No.: Report #: 1003663 Phone: 02 8245 0300 Fax:						Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM			
Pro Pro	oject Name: oject ID:	RPA HOSP 63888	PITA-EXTERNAL E	BUILDING							E	urofins Analytical Ser	vices Manager : A	ndrew Black
		s	ample Detail			Asbestos - AS4964	Asbestos Absence /Presence	Lead	Lead (% w/w)					
Sydr	ney Laboratory	- NATA # 1261	Site # 18217			Х	X	X	X					
44	GH-L01	Jun 28, 2023	Pai	nt S23-Jn(070041				X					
45 46	GH-L02 B28-A01	Jun 28, 2023 Jun 28, 2023	Pau Bui Mat	nt S23-Jn(Iding S23-Jn(Serials	0070042 0070043		x		X					
47	B28-A02	Jun 28, 2023	Bui	lding S23-Jn0 terials	070044		х							
48	B28-A03	Jun 28, 2023	Bui Mat	lding S23-Jn(terials	070045		х							
49	B28-A04	Jun 28, 2023	Bui Mat	lding S23-Jn0 terials	070046		х							
50	B28-L01	Jun 29, 2023	Pai	nt S23-Jn(070047				Х					
Test	Counts					2	30	2	16					



Internal Quality Control Review and Glossary General

- 1. 2. 3.
- CC data may be available on request. All soil results are reported on a dry basis, unless otherwise stated. Samples were analysed on an 'as received' basis. Information identified on this report with the colour **blue** indicates data provided by customer that may have an impact on the results. This report replaces any interim results previously issued. 4. 5.

Holding Times Please refer to the most recent version of the 'Sample Preservation and Container Guide' for holding times (QS3001).

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported. Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units % w/w: F/fld F/mL g, kg g/kg L, mL L, mL L/min min	Percentage weight-for-weight basis, e.g. of asbestos in asbestos-containing finds in soil samples (% w/w) Airborne fibre filter loading as Fibres (N) per Fields counted (n) Airborne fibre reported concentration as Fibres per milliliter of air drawn over the sampler membrane (C) Mass, e.g. of whole sample (M) or asbestos-containing find within the sample (m) Concentration in grams per kilogram Volume, e.g. of air as measured in AFM (V = r x t) Airborne fibre sampling Flowrate as litres per minute of air drawn over the sampler membrane (r) Time (t), e.g. of air sample collection period
Calculations	
Airborne Fibre Concentration:	$C = \left(\frac{n}{a}\right) \times \left(\frac{1}{r}\right) \times \left(\frac{1}{r}\right) = K \times \left(\frac{n}{r}\right) \times \left(\frac{1}{v}\right)$
Asbestos Content (as asbestos):	$\% w/w = \frac{(m \times P_A)}{M}$
Weighted Average (of asbestos):	$\%_{WA} = \sum \frac{(m \times P_A)_X}{x}$
Terms %ashestos	Estimated percentage of ashestos in a given matrix. May be derived from knowledge or experience of the material informed by HSG264 Appendix 2 else
///////////////////////////////////////	assumed to be 15% in accordance with WA DOH Appendix 2 (P_A).
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded (non-friable) condition. For the purposes of the NEPM and WA DOH, ACM corresponds to material larger than 7 mm x 7 mm.
AF	Asbestos Fines. Asbestos contamination within a soil sample, as defined by WA DOH. Includes loose fibre bundles and small pieces of friable and non-friable material such as asbestos cement fragments mixed with soil. Considered under the NEPM as equivalent to "non-bonded / friable".
AFM	Airborne Fibre Monitoring, e.g. by the MFM.
Amosite	Amosite Asbestos Detected. Amosite may also refer to Fibrous Grunerite or Brown Asbestos. Identified in accordance with AS 4964-2004.
AS	Australian Standard.
Asbestos Content (as asbestos)	Total % w/w asbestos content in asbestos-containing finds in a soil sample (% w/w).
Chrysotile	Chrysotile Asbestos Detected. Chrysotile may also refer to Fibrous Serpentine or White Asbestos. Identified in accordance with AS 4964-2004.
COC	Chain of Custody.
Crocidolite	Crocidolite Asbestos Detected. Crocidolite may also reter to Fibrous Riebeckite or Blue Asbestos. Identified in accordance with AS 4964-2004.
Dry	Sample is dried by heating prior to analysis.
DS	Dispersion Staining. Technique required for Unequivocal Identification of asbestos fibres by PLM.
FA	Fibrous Asbestos. Asbestos containing material that is wholly or in part friable, including materials with higher asbestos content with a propensity to become friable with handling, and any material that was previously non-friable and in a severely degraded condition. For the purposes of the NEPM and WA DOH, FA generally corresponds to material larger than 7 mm x 7 mm, although FA may be more difficult to visibly distinguish and may be assessed as AF.
Fibre Count	Total of all fibres (whether asbestos or not) meeting the counting criteria set out in the NOHSC:3003
Fibre ID	Fibre Identification. Unequivocal identification of asbestos fibres according to AS 4964-2004. Includes Chrysotile, Amosite (Grunerite) or Crocidolite asbestos.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
HSG248	UK HSE HSG248, Asbestos: The Analysts Guide, 2nd Edition (2021).
HSG264	UK HSE HSG264, Asbestos: The Survey Guide (2012).
ISO (also ISO/IEC)	International Organization for Standardization / International Electrotechnical Commission.
K Factor	Microscope constant (K) as derived from the effective filter area of the given AFM membrane used for collecting the sample (A) and the projected eyepiece graticule area of the specific microscope used for the analysis (a).
LOR	Limit of Reporting.
MFM (also NOHSC:3003)	Membrane Filter Method. As described by the Australian Government National Occupational Health and Safety Commission, Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003(2005)].
NEPM (also ASC NEPM)	National Environment Protection (Assessment of Site Contamination) Measure, (2013, as amended).
Organic	Organic Fibres Detected. Organic may refer to Natural or Man-Made Polymeric Fibres. Identified in accordance with AS 4964-2004.
PCM	Phase Contrast Microscopy. As used for Fibre Counting according to the MFM.
PLM	Polarised Light Microscopy. As used for Fibre Identification and Trace Analysis according to AS 4964-2004.
Sampling	Unless otherwise stated Eurofins are not responsible for sampling equipment or the sampling process.
SMF	Synthetic Mineral Fibre Detected. SMF may also refer to Man Made Vitreous Fibres. Identified in accordance with AS 4964-2004.
SRA	Sample Receipt Advice.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres (particularly asbestos) in a given sample matrix.
UK HSE HSG	United Kingdom, Health and Safety Executive, Health and Safety Guidance, publication.
	Unidentified Mineral Fibre Detected. Fibrous minerals that are detected but have not been unequivocally identified by PLM with DS according the AS 4964-2004 May include (but not limited to) Actinolite, Anthophyllite or Tremolite asbestos.
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos- Contaminated Sites in Western Australia (updated 2021), including Appendix Four: Laboratory analysis
Weighted Average	Combined average % w/w asbestos content of all asbestos-containing finds in the given aliquot or total soil sample (%wA).



Comments

Sample Integrity	
Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Asbestos Counter/Identifier:

Chamath JHM Annakkage

Authorised by:

Sayeed Abu

Senior Analyst-Asbestos

Senior Analyst-Asbestos

Glenn Jackson Managing Director

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please click here.

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.



JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000



Stuart Lumsden

Report
Project name
Project ID
Received Date

1003663-S RPA HOSPITA-EXTERNAL BUILDING 63888 Jun 29, 2023

110001100 Dato 0011 20, 2020						
Client Sample ID			B94-LD01	B94-L01	B94-L02	B94-L03
Sample Matrix			Dust	Paint	Paint	Paint
Eurofins Sample No.			S23-Jn0070011	S23-Jn0070012	S23-Jn0070013	S23-Jn0070014
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Heavy Metals						
Lead	5	mg/kg	300	-	-	-
Lead (% w/w)	0.01	%	-	13	< 0.01	11

Client Sample ID Sample Matrix Eurofins Sample No.			B94-L04 Paint S23-Jn0070015	B94-L05 Paint S23-Jn0070016	B94-L06 Paint S23-Jn0070017	B95-LD01 Dust S23-Jn0070029
Test/Reference	LOR	Unit	Jun 20, 2023	Jun 20, 2023	Jun 28, 2023	Jun 26, 2023
Heavy Metals						
Lead	5	mg/kg	-	-	-	850
Lead (% w/w)	0.01	%	0.59	7.9	3.5	-

Client Sample ID			B95-L01	B95-L02	B95-L03	B95-L04
Sample Matrix			Paint	Paint	Paint	Paint
Eurofins Sample No.			S23-Jn0070030	S23-Jn0070031	S23-Jn0070032	S23-Jn0070033
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	34	24	13	0.01



NATA Accredited Accreditation Number 1261 Site Number 18217

Accredited for compliance with ISO/IEC 17025 – Testing NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.



Client Sample ID Sample Matrix			B95-L05 Paint	B95-L06 Paint	B95-L07 Paint	GH-L01 Paint
Eurofins Sample No.			S23-Jn0070034	S23-Jn0070035	S23-Jn0070036	S23-Jn0070041
Date Sampled			Jun 28, 2023	Jun 28, 2023	Jun 28, 2023	Jun 28, 2023
Test/Reference	LOR	Unit				
Lead (% w/w)	0.01	%	5.2	0.06	0.12	< 0.01

Client Sample ID			GH-L02	B28-L01
Sample Matrix			Paint	Paint
Eurofins Sample No.			S23-Jn0070042	S23-Jn0070047
Date Sampled			Jun 28, 2023	Jun 29, 2023
Test/Reference	LOR	Unit		
Lead (% w/w)	0.01	%	0.09	0.84



Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Heavy Metals	Sydney	Jun 30, 2023	28 Days
- Method: LTM-MET-3040 Metals in Waters, Soils & Sediments by ICP-MS			
Lead (% w/w)	Sydney	Jun 30, 2023	6 Months
- Method: LTM-MET-3040 Metals in Waters Soils & Sediments by ICP-MS			

	🔅 eurofins		Eurofins Env ABN: 50 005 08	ironment Testin 5 521	g Australia Pty Lt	td				Eurofins ARL Pty Lte ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954		
web: w email:	ww.eurofins.com.au	.com	Melbourne 6 Monterey Roa Dandenong Sou VIC 3175 Tel: +61 3 8564 NATA# 1261 Sit	Geelong d 19/8 Lewa th Grovedale VIC 3216 5000 Tel: +61 3 e# 1254	Sydi alan Street 179 alan Street 179 alan Street NSW 88564 5000 Tel: - 261 Site# 25403 NAT.	ney Magowar R aween / 2145 +61 2 9900 A# 1261 Sit	oad 8400 e# 1821	Canb Unit 1 Mitch ACT Tel: +	erra Brisbane Newcastle ,2 Dacre Street 1/21 Smallwood Place 1/2 Frost Drive ell Murarrie Mayfield West 2911 QLD 4172 Tel: +61 2 4961 61 2 6113 8091 Tel: +61 7 3902 4600 NATA# 1261 # 1261 Site# 25466 NATA# 1261 Site# 20794 Site# 25079 &	Perth 46-48 Banksia Road NSW 2304 Welshpool 8 8448 WA 6106 Tel: +61 8 6253 4444 25289 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
Co Ad	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	istralia (NSW Margaret St) P/L			O R P Fa	rder N eport hone: ax:	lo.: #: 1003663 02 8245 0300	Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM	
Pro Pro	oject Name: oject ID:	RPA HOSP 63888	ITA-EXTERN	IAL BUILDING						Eurofins Analytical Se	rvices Manager : A	ndrew Black	
	Sample Detail						Lead	Lead (% w/w)					
Syd	ney Laboratory	- NATA # 1261	Site # 18217	,		Х	Х	Х					
Exte	rnal Laboratory	,		1					-				
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID								
1	B94-A01	Jun 28, 2023		Building Materials	S23-Jn006999	98 x							
2	B94-A02	Jun 28, 2023		Building Materials	S23-Jn006999	99 x							
3	B94-A03	Jun 28, 2023		Building Materials	S23-Jn007000	x ⁰⁰							
4	B94-A04	Jun 28, 2023		Building Materials	S23-Jn007000	01 X							
5	B94-A05	Jun 28, 2023		Building Materials	S23-Jn007000	02 X							
6	B94-A06	Jun 28, 2023		Building Materials	S23-Jn007000	03 x							
7	B94-A07	Jun 28, 2023		Building Materials	S23-Jn007000	04 x							
8	B94-A08	Jun 28, 2023		Building Materials	S23-Jn007000	05 X							

•	🔅 eurofins	Eurofins Environr ABN: 50 005 085 521	nent Testing /	Australia Pty Ltd							Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954			
web: v email:	www.eurofins.com.au EnviroSales@eurofins	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 123	Geelong 19/8 Lewalar Grovedale VIC 3216 Tel: +61 3 85 54 NATA# 1261	Sydney n Street 179 Mag Girrawe NSW 21 NSW 21 564 5000 Tel: +61 1 Site# 25403 NATA#	owar Ro en 45 2 9900 8 1261 Site	ad 3400 2# 1821	Canb Unit 1 Mitch ACT : Tel: + 7 NATA	erra Brisbane ,2 Dacre Street 1/21 Small ell Murarrie 2911 QLD 4172 61 2 6113 8091 Tel: +61 7 # 1261 Site# 25466 NATA# 12	wood Place 3902 4600 61 Site# 20794	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
Cc Ac	ompany Name: Idress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ıstralia (NSW) P/L Margaret St				Oi Re Pi Fa	rder N eport none: ax:	lo.: #: 1003663 02 8245 0300)		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 PM Jul 6, 2023 5 Day Stuart Lumsden		
Pr Pr	oject Name: oject ID:	RPA HOSP 63888	ITA-EXTERNAL E	BUILDING							E	urofins Analytical Ser	vices Manager : A	ndrew Black	
		S	Sample Detail												
Syd	ney Laboratory	- NATA # 1261	Site # 18217			х	х	х							
9	B94-A09	Jun 28, 2023	Buil Mat	lding terials	S23-Jn0070006	х									
10	B94-A10	Jun 28, 2023	Buil Mat	lding terials	S23-Jn0070007	х									
11	B94-A11	Jun 28, 2023	Buil Mat	lding terials	S23-Jn0070008	х									
12	B94-A12	Jun 28, 2023	Buil Mat	lding terials	S23-Jn0070009	х									
13	B94-AD01	Jun 28, 2023	Dus	st	S23-Jn0070010	Х									
14	B94-LD01	Jun 28, 2023	Dus	st	S23-Jn0070011		Х								
15	B94-L01	Jun 28, 2023	Pair	nt	S23-Jn0070012			Х							
16	B94-L02	Jun 28, 2023	Pair	nt	S23-Jn0070013			Х							
17	B94-L03	Jun 28, 2023	Pair	nt	S23-Jn0070014			Х							
18	B94-L04	Jun 28, 2023	Pair	nt	S23-Jn0070015			Х							
19	B94-L05	Jun 28, 2023	Pair	nt	S23-Jn0070016			Х							
20	B94-L06	Jun 28, 2023	Pair	nt	S23-Jn0070017			Х							
21	B95-A01	Jun 28, 2023	Buil	lding	S23-Jn0070018	х									

	🎎 eurofins		ABN: 50 005 085 5	onment Testing 521	g Australia Pty Lt	d					Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954		
web: v email:	www.eurofins.com.au EnviroSales@eurofins	s.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 50 NATA# 1261 Site#	Geelong 19/8 Lewa Grovedale VIC 3216 000 Tel: +61 3 1254 NATA# 12	Sydn alan Street 179 M alan Street 179 M alan Street NSW 8564 5000 Tel: + 261 Site# 25403 NATA	ey /lagowar Ro ween 2145 61 2 9900 \# 1261 Sit	oad 8400 e# 1821	Canb Unit 1 Mitch ACT : Tel: +	erra Brisbane .2 Dacre Street 1/21 Smallwood Place Jl Murarrie 291 QLD 4172 61 2 6113 8091 Tel: +61 7 3902 4600 # 1261 Site# 25466 NATA# 1261 Site# 20794	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290	
Ca Aa	ompany Name: ddress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ustralia (NSW) I Margaret St	P/L			O R Pi Fa	rder N eport hone: ax:	lo.: #: 1003663 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM	
Pr Pr	Project Name: RPA HOSPITA-EXTERNAL BUILDING Project ID: 63888									E	urofins Analytical Ser	vices Manager : A	ndrew Black	
	Sample Detail					Asbestos Absence /Presence	Lead	Lead (% w/w)						
Syd	Iney Laboratory	- NATA # 1261	Site # 18217			Х	Х	Х						
			Ν	Materials										
22	B95-A02	Jun 28, 2023	E	Building Materials	S23-Jn007001	9 x								
23	B95-A03	Jun 28, 2023	E	Building Aaterials	S23-Jn007002	0 X								
24	B95-A04	Jun 28, 2023	E	Building Materials	S23-Jn007002	1 x								
25	B95-A05	Jun 28, 2023	E	Building Aaterials	S23-Jn007002	2 X								
26	B95-A06	Jun 28, 2023	E	Building Aaterials	S23-Jn007002	3 x								
27	B95-A07	Jun 28, 2023	E	Building Materials	S23-Jn007002	4 x								
28	B95-A08	Jun 28, 2023	E	Building Materials	S23-Jn007002	⁵ x								
29	B95-A09	Jun 28, 2023	E	Building Materials	S23-Jn007002	6 X								
30	B95-A10	Jun 28, 2023	E	Building Materials	S23-Jn007002	7 X								

•	🚯 eurofins		Eurofins Environme ABN: 50 005 085 521	ent Testing Australia F	Pty Ltd	Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954							
web: v email:	www.eurofins.com.au	.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	war Roa 5 9900 8 261 Site	ad 3400 9# 1821	Canb Unit 1 Mitche ACT 2 Tel: +1 7 NATA	Brisbane 2 Dacre Street 1/21 Smallwood Place II Murarrie 911 QLD 4172 51 2 6113 8091 Tel: +61 7 3902 4600 # 1261 Site# 25466 NATA# 1261 Site# 2075	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 94 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290			
Ca Ad	ompany Name: ddress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ıstralia (NSW) P/L Margaret St				Oi Re Pl Fa	rder N eport none: ax:	o.: ≇: 1003663 02 8245 0300		Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 PM Jul 6, 2023 5 Day Stuart Lumsden		
Pi Pi	oject Name: oject ID:	RPA HOSP 63888	ITA-EXTERNAL BU	IILDING						E	urofins Analytical Ser	vices Manager : Aı	ndrew Black	
		s	Sample Detail					Lead (% w/w)						
Syc	Iney Laboratory	- NATA # 1261	Site # 18217			х	х	х						
31	B95-AD01	Jun 28, 2023	Dust	S23-Jn00	70028	Х								
32	B95-LD01	Jun 28, 2023	Dust	S23-Jn00	70029		Х							
33	B95-L01	Jun 28, 2023	Paint	S23-Jn00	70030			Х						
34	B95-L02	Jun 28, 2023	Paint	S23-Jn00	70031			Х						
35	B95-L03	Jun 28, 2023	Paint	S23-Jn00	70032			Х						
36	B95-L04	Jun 28, 2023	Paint	S23-Jn00	70033			Х						
37	B95-L05	Jun 28, 2023	Paint	S23-Jn00	70034			х						
38	B95-L06	Jun 28, 2023	Paint	S23-Jn00	70035			х						
39	B95-L07	Jun 28, 2023	Paint	S23-Jn00	70036			х						
40	GH-A01	Jun 28, 2023	Buildi Mater	ng S23-Jn00 rials	70037	х								
41	GH-A02	Jun 28, 2023	Buildi Mater	ng S23-Jn00 rials	70038	х								
42	GH-A03	Jun 28, 2023	Buildi Mater	ng S23-Jn00 rials	70039	х								
43	GH-A04	Jun 28, 2023	Buildi Mater	ng S23-Jn00 rials	70040	Х								

•		fine	Eurofins Enviro ABN: 50 005 085 5	o <mark>nment Testi</mark> 21	ing Australia Pty	Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954										
web: wy email: E	ww.eurofins.com.au	s.com	Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 50 NATA# 1261 Site#	Canberra Brisbane Newcastle owar Road Unit 1,2 Dacre Street 1/21 Smallwood Place 1/2 Forso Drive an Mitchell Murarrie Mayfield West NS 45 ACT 2911 QLD 4172 Tel: +61 2 4968 8 2 9900 8400 Tel: +61 2 6113 8091 Tel: +61 7 3902 4600 NATA# 1261 1261 Site# 18217 NATA# 1261 Site# 25466 NATA# 1261 Site# 20794 Site# 25079 & 25.5							Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290				
Coi Ade	mpany Name: dress:	JBS & G Au Level 1, 50 Sydney NSW 2000	ustralia (NSW) F Margaret St	9/L				Oi Re Pi Fa	der N eport none: IX:	lo.: #: 10 02	03663 8245 0300			Received: Due: Priority: Contact Name:	Jun 29, 2023 2:45 Jul 6, 2023 5 Day Stuart Lumsden	PM	
Project Name: RPA HOSPITA-EXT Project ID: 63888			PITA-EXTERNA	TERNAL BUILDING											vices Manager : Andrew Black		
		s	ample Detail				Asbestos Absence /Presence	Lead	Lead (% w/w)								
Sydr	ey Laboratory	- NATA # 1261	Site # 18217				Х	Х	Х								
44	GH-L01	Jun 28, 2023	F	aint	S23-Jn0070	041			Х								
45 46	GH-L02 B28-A01	Jun 28, 2023 Jun 28, 2023	E	aint uilding laterials	S23-Jn0070 S23-Jn0070	042 043	х		X								
47	B28-A02	Jun 28, 2023	E	uilding laterials	S23-Jn0070	044	х										
48	B28-A03	Jun 28, 2023	E	uilding laterials	S23-Jn0070	045	х										
49	B28-A04	Jun 28, 2023	E N	uilding laterials	S23-Jn0070	046	х										
50	B28-L01	Jun 29, 2023	F	aint	S23-Jn0070	047			Х								
Test	Counts						32	2	16								



Internal Quality Control Review and Glossary

General

- 1. Laboratory QC results for Method Blanks, Duplicates, Matrix Spikes, and Laboratory Control Samples follows guidelines delineated in the National Environment Protection (Assessment of Site Contamination) Measure 1999, as amended May 2013 and are included in this QC report where applicable. Additional QC data may be available on request.
- 2. All soil/sediment/solid results are reported on a dry basis, unless otherwise stated.
- 3. All biota/food results are reported on a wet weight basis on the edible portion, unless otherwise stated.
- 4. Actual LORs are matrix dependant. Quoted LORs may be raised where sample extracts are diluted due to interferences.
- 5. Results are uncorrected for matrix spikes or surrogate recoveries except for PFAS compounds.
- 6. SVOC analysis on waters are performed on homogenised, unfiltered samples, unless noted otherwise.
- 7. Samples were analysed on an 'as received' basis.
- 8. Information identified on this report with blue colour, indicates data provided by customer that may have an impact on the results.
- 9. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the SRA. If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

For VOCs containing vinyl chloride, styrene and 2-chloroethyl vinyl ether the holding time is 7 days however for all other VOCs such as BTEX or C6-10 TRH then the holding time is 14 days.

Units

mg/kg: milligrams per kilogram	mg/L: milligrams per litre	μg/L: micrograms per litre
ppm: parts per million	ppb: parts per billion	%: Percentage
org/100 mL: Organisms per 100 millilitres	NTU: Nephelometric Turbidity Units	MPN/100 mL: Most Probable Number of organisms per 100 millilitres
CFU: Colony forming unit		

Terms

APHA	American Public Health Association
coc	Chain of Custody
СР	Client Parent - QC was performed on samples pertaining to this report
CRM	Certified Reference Material (ISO17034) - reported as percent recovery.
Dry	Where a moisture has been determined on a solid sample the result is expressed on a dry basis.
Duplicate	A second piece of analysis from the same sample and reported in the same units as the result to show comparison.
LOR	Limit of Reporting.
LCS	Laboratory Control Sample - reported as percent recovery.
Method Blank	In the case of solid samples these are performed on laboratory certified clean sands and in the case of water samples these are performed on de-ionised water.
NCP	Non-Client Parent - QC performed on samples not pertaining to this report, QC is representative of the sequence or batch that client samples were analysed within.
RPD	Relative Percent Difference between two Duplicate pieces of analysis.
SPIKE	Addition of the analyte to the sample and reported as percentage recovery.
SRA	Sample Receipt Advice
Surr - Surrogate	The addition of a like compound to the analyte target and reported as percentage recovery.
твто	Tributyltin oxide (<i>bis</i> -tributyltin oxide) - individual tributyltin compounds cannot be identified separately in the environment however free tributyltin was measured and its values were converted stoichiometrically into tributyltin oxide for comparison with regulatory limits.
TCLP	Toxicity Characteristic Leaching Procedure
TEQ	Toxic Equivalency Quotient or Total Equivalence
QSM	US Department of Defense Quality Systems Manual Version 5.4
US EPA	United States Environmental Protection Agency
WA DWER	Sum of PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTSA, 8:2 FTSA

QC - Acceptance Criteria

The acceptance criteria should be used as a guide only and may be different when site specific Sampling Analysis and Quality Plan (SAQP) have been implemented

RPD Duplicates: Global RPD Duplicates Acceptance Criteria is 30% however the following acceptance guidelines are equally applicable:

Results <10 times the LOR: No Limit

Results between 10-20 times the LOR: RPD must lie between 0-50%

Results >20 times the LOR: RPD must lie between 0-30%

NOTE: pH duplicates are reported as a range not as RPD

Surrogate Recoveries: Recoveries must lie between 20-130% for Speciated Phenols & 50-150% for PFAS. SVOCs recoveries 20 - 150%

PFAS field samples that contain surrogate recoveries in excess of the QC limit designated in QSM 5.4 where no positive PFAS results have been reported have been reviewed and no data was affected.

QC Data General Comments

- 1. Where a result is reported as a less than (<), higher than the nominated LOR, this is due to either matrix interference, extract dilution required due to interferences or contaminant levels within the sample, high moisture content or insufficient sample provided.
- 2. Duplicate data shown within this report that states the word "BATCH" is a Batch Duplicate from outside of your sample batch, but within the laboratory sample batch at a 1:10 ratio. The Parent and Duplicate data shown is not data from your samples.
- 3. pH and Free Chlorine analysed in the laboratory Analysis on this test must begin within 30 minutes of sampling. Therefore, laboratory analysis is unlikely to be completed within holding time. Analysis will begin as soon as possible after sample receipt.
- 4. Recovery Data (Spikes & Surrogates) where chromatographic interference does not allow the determination of recovery the term "INT" appears against that analyte.
- 5. For Matrix Spikes and LCS results a dash "-" in the report means that the specific analyte was not added to the QC sample.
- 6. Duplicate RPDs are calculated from raw analytical data thus it is possible to have two sets of data.



Quality Control Results

Test			Units	Result 1			Acceptance Limits	Pass Limits	Qualifying Code
Method Blank									
Heavy Metals									
Lead			mg/kg	< 50			50	Pass	
Method Blank				-			_		
Lead (% w/w)			%	< 0.01			0.01	Pass	
LCS - % Recovery									
Heavy Metals									
Lead			%	96		80-120		Pass	
Test	Lab Sample ID	QA Source	Units	Result 1			Acceptance Limits	Pass Limits	Qualifying Code
Spike - % Recovery									
Heavy Metals				Result 1					
Lead	S23-Jn0073483	NCP	%	106			75-125	Pass	
Test	Lab Sample ID	QA Source	Units	Result 1			Acceptance Limits	Pass Limits	Qualifying Code
Duplicate									
Heavy Metals				Result 1	Result 2	RPD			
Lead	S23-Jn0073482	NCP	mg/kg	28	16	56	30%	Fail	Q15



Comments

Sample Integrity	
Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

 Code
 Description

 Q15
 The RPD reported passes Eurofins Environment Testing's QC - Acceptance Criteria as defined in the Internal Quality Control Review and Glossary page of this report.

Authorised by:

Andrew Black Fang Yee Tan Mickael Ros Sayeed Abu Analytical Services Manager Senior Analyst-Metal Senior Analyst-Metal Senior Analyst-Asbestos

Glenn Jackson Managing Director

Final Report - this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please click here.

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

012848

CHAIN OF CUSTODY



PROJECT NO.: 63	888					LABORATORY BATCH NO.:									
PROJECT NAME:	PA					SAN	PLERS:	Toto	AN GOMEZ	p Pobe	et S	hanos	n.th.		
DATE NEEDED BY:	STANDARD					QCI	EVEL: N	NEPM (2013)			1-			
PHONE: Sydney: 02	2 8245 0300 Perth: (8 9488 01	.00 Brisba	ane: 07 3112 2688											
SEND REPORT & IN	IVOICE TO: (1) admini	nsw@jbsg.	com.au; (2)@i	bsg.com	au: (3				bibsg.com.	au				
COMMENTS / SPECIAL HAN	NDLING / STORAGE OR DISPOS/	AL:			0	F	TT	1 1					TYPE	OF	
						2							ASB	ESTOS LYSIS	
		Ž							NOL						
		8							IFICAT	WA					
SAMPLE ID	SAMPLE ID MATRIX DATE TIME TYPE & PRESERVATIVE pH												DENT	NOTE	S:
L6-17-13	L6-1713 MATTERIAL 10.07.23 Bay.												X		
6-1914		(<i>.</i>									X		
16-115															
16-1916													-c		
LL-L07	POIDA					X	+ +						1		
16-1-08					_	\Diamond									
17 806	Dona M (01				_									_	
17 810	in a sugerin L				-			_							
17000								_						_	
L1-1711		v		•				_					X		
					_		_								
					_										
													_		
RELINO	QUISHED BY:	A		METHOD OF SHIPMENT:				RECEIVE	D BY:			FOR	RECEIVING	AB LISE ONL	v.
NAME: JOLON	NAM	190	400	1117	COOLE	R SEAL -	Yes N	o Inta	ct Bro	oken					
OF: JBS&G GOMGZ TRANSPORT CO.)	2.3K		DITEMP		A	IAA-	
NAME:	DATE:	CONS	GNMENT NO	TE NO,		NAM	:		DATE:	COOLE	R SEAL -	Ves N	0 Int	ert Br	roken
						OF:				VLAL	SCAL TOTAL NO Intati Droken				
OF: Container & Preservative	Codes: D - Plactic: L - Soil Jan I	TRANS	SPORT CO	Provid - C - Codium Hudsouide Double VC	- Unidan ali I		110 1 1	10 0 11		COOLE	R TEMP	deg C			
A CONTRACTOR OF A CONTRACTOR	address i - ridacic, s - soli sar; i	- Glass bollie	; in – Infutic Acic	a Frisval, C = Socium Hydroxide Prsva; VC	 mydrochiol 	TC ACIO PI	sva vial; \	və = Sulfur	ic Acid Prsvd Vial; S	Sulturic Acid	I Prsvd; Z =	Zinc Prsvd:	E = EDTA Prsv	d: ST = Sterile	Bottle: O = Other

IMSO FormsO13 - Chain of Custody - Generic

1006675


Eurofins Environment Testing Australia Pty Ltd

ABN: 50 005 085 521										
Melbourne	Geelong	Sydney	Canberra	Brisbane	Newcastle					
6 Monterey Road	19/8 Lewalan Street	179 Magowar Road	Unit 1,2 Dacre Street	1/21 Smallwood Place	1/2 Frost Drive					
Dandenong South	Grovedale	Girraween	Mitchell	Murarrie	Mayfield West N					
VIC 3175	VIC 3216	NSW 2145	ACT 2911	QLD 4172	Tel: +61 2 4968 8					
Tel: +61 3 8564 5000	Tel: +61 3 8564 5000	Tel: +61 2 9900 8400	Tel: +61 2 6113 8091	Tel: +61 7 3902 4600	NATA# 1261					
NATA# 1261 Site# 1254	NATA# 1261 Site# 25403	NATA# 1261 Site# 18217	NATA# 1261 Site# 25466	NATA# 1261 Site# 20794	Site# 25079 & 25					

www.eurofins.com.au

EnviroSales@eurofins.com

Eurofins ARL Pty Ltd Eurofins Environment Testing NZ Ltd

	ADN. 91 03 0139 696	INZBIN. 9429040024934	•	
vcastle	Perth	Auckland	Christchurch	
Frost Drive	46-48 Banksia Road	35 O'Rorke Road	43 Detroit Drive	
field West NSW 2304	Welshpool	Penrose,	Rolleston,	
+61 2 4968 8448	WA 6106	Auckland 1061	Christchurch 7675	
A# 1261	Tel: +61 8 6253 4444	Tel: +64 9 526 4551	Tel: +64 3 343 5201	
# 25079 & 25289	NATA# 2377 Site# 2370	IANZ# 1327	IANZ# 1290	

Sample Receipt Advice

Company name:	JBS & G Australia (NSW) P/L
Contact name:	Check the COC for Project manager
Project name:	RPA
Project ID:	63888
Turnaround time:	5 Day
Date/Time received	Jul 11, 2023 2:36 PM
Eurofins reference	1006675

Sample Information

- 1 A detailed list of analytes logged into our LIMS, is included in the attached summary table.
- All samples have been received as described on the above COC. 1
- COC has been completed correctly. 1
- N/A Attempt to chill was evident.
- Appropriately preserved sample containers have been used. 1
- All samples were received in good condition.
- Samples have been provided with adequate time to commence analysis in accordance with the relevant holding times.
- Appropriate sample containers have been used. 1
- Sample containers for volatile analysis received with zero headspace. 1
- Split sample sent to requested external lab. X
- X Some samples have been subcontracted.
- N/A Custody Seals intact (if used).

Notes

Contact

If you have any questions with respect to these samples, please contact your Analytical Services Manager:

Andrew Black on phone : (+61) 2 9900 8490 or by email: AndrewBlack@eurofins.com

Results will be delivered electronically via email to Check the COC for Project manager - ursulalong@eurofins.com.

Global Leader - Results you can trust



Certificate of Analysis

Environment Testing

JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000



NATA Accredited Accreditation Number 1261 Site Number 18217

Accredited for compliance with ISO/IEC 17025–Testing NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.

Attention:	Rob Sharpsmith
Report	1006675-AID
Project Name	RPA
Project ID	63888
Received Date	Jul 11, 2023
Date Reported	Jul 18, 2023
Methodology:	
Asbestos Fibre Identification	Conducted in accordance with the Australian Standard AS 4964 – 2004: Method for the Qualitative Identification of Asbestos in Bulk Samples and in-house Method LTM-ASB-8020 by polarised light microscopy (PLM) and dispersion staining (DS) techniques. NOTE: Positive Trace Analysis results indicate the sample contains detectable respirable fibres.
Unknown Mineral Fibres	Mineral fibres of unknown type, as determined by PLM with DS, may require another analytical technique, such as Electron Microscopy, to confirm unequivocal identity. NOTE: While Actinolite, Anthophyllite and Tremolite asbestos may be detected by PLM with DS, due to variability in the optical properties of these materials, AS4964 requires that these are reported as UMF unless confirmed by an independent technique.
Subsampling Soil Samples	The whole sample submitted is first dried and then passed through a 10mm sieve followed by a 2mm sieve. All fibrous matter greater than 10mm, greater than 2mm as well as the material passing through the 2mm sieve are retained and analysed for the presence of asbestos. If the sub 2mm fraction is greater than approximately 30 to 60g then a sub-sampling routine based on ISO 3082:2009(E) is employed. NOTE: Depending on the nature and size of the soil sample, the sub-2 mm residue material may need to be sub-sampled for trace analysis, in accordance with AS 4964-2004.
Bonded asbestos- containing material (ACM)	The material is first examined and any fibres isolated for identification by PLM and DS. Where required, interfering matrices may be removed by disintegration using a range of heat, chemical or physical treatments, possibly in combination. The resultant material is then further examined in accordance with AS 4964 - 2004. NOTE: Even after disintegration it may be difficult to detect the presence of asbestos in some asbestos-containing bulk materials using PLM and DS. This is due to the low grade or small length or diameter of the asbestos fibres present in the material, or to the fact that very fine fibres have been distributed intimately throughout the materials. Vinyl/asbestos floor tiles, some asbestos-containing sealants and mastics, asbestos-containing epoxy resins and some ore samples are examples of these types of material, which are difficult to analyse.
Limit of Reporting	The performance limitation of the AS 4964 (2004) method for non-homogeneous samples is around 0.1 g/kg (equivalent to 0.01% (w/w)). Where no asbestos is found by PLM and DS, including Trace Analysis, this is considered to be at the nominal reporting limit of 0.01% (w/w). The NEPM screening level of 0.001% (w/w) is intended as an on-site determination, not a laboratory Limit of Reporting (LOR), per se. Examination of a large sample size (e.g. 500 mL) may improve the likelihood of detecting asbestos, particularly AF, to aid assessment against the NEPM criteria. Gravimetric determinations to this level of accuracy are outside of AS 4964 and hence NATA Accreditation does not cover the performance of this service (non-NATA results shown with an asterisk). NOTE: NATA News March 2014, p.7, states in relation to AS 4964: "This is a qualitative method with a nominal reporting limit of 0.01 % " and that currently in Australia "there is no validated method available for the quantification of asbestos". This report is consistent with the analytical procedures and reporting recommendations in the NEPM and the WA DoH.



Project Name	RPA
Project ID	63888
Date Sampled	Jul 10, 2023
Report	1006675-AID

Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
L6-A13	23-JI0019831	Jul 10, 2023	Approximate Sample 2g / 20x10x2mm Sample consisted of: Grey flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L6-A14	23-JI0019832	Jul 10, 2023	Approximate Sample <1g / 5x2x1mm Sample consisted of: White plaster cement material and fibre plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L6-A15	23-JI0019833	Jul 10, 2023	Approximate Sample 1g / 10x5x3mm Sample consisted of: Yellow mastic material	Chrysotile asbestos detected.
L6-A16	23-JI0019834	Jul 10, 2023	Approximate Sample 5g / 60x30x7mm Sample consisted of: Gold/ Brown vermiculite plaster material	No asbestos detected. Organic fibre detected. No trace asbestos detected.
L7-A09	23-JI0019837	Jul 10, 2023	Approximate Sample 2g / 30x15x2mm Sample consisted of: Blue flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L7-A10	23-JI0019838	Jul 10, 2023	Approximate Sample 2g / 30x12x2mm Sample consisted of: Amber flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.
L7-A11	23-JI0019839	Jul 10, 2023	Approximate Sample 1g / 20x10x2mm Sample consisted of: Pink flexible vinyl sheet and amber glue	No asbestos detected. No trace asbestos detected.



Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description

Asbestos - LTM-ASB-8020

Testing SiteExtractedSydneyJul 11, 2023

Holding Time Indefinite

			Eurofins Env ABN: 50 005 08	urofins Environment Testing Australia Pty Ltd BN: 50 005 085 521									Eurofins Environn NZBN: 942904602495	nent Testing NZ Ltd 4
web: web: web: web: web: web: web: web:	www.eurofins.com.au EnviroSales@eurofins	s.com	Melbourne 6 Monterey Roa Dandenong Sou VIC 3175 Tel: +61 3 8564 NATA# 1261 Sit	Geeld d 19/8 l th Grove VIC 3 5000 Tel: + e# 1254 NATA	bng Lewalan Street edale 1216 61 3 8564 5000 A# 1261 Site# 25403	Sydney 179 Mago Girraweer NSW 214 Tel: +61 2 NATA# 12	war Ro 5 9900 8 261 Site	ad 3400 # 1821	Canberra Unit 1,2 Dacre Street Mitchell ACT 2911 Tel: +61 2 6113 8091 17 NATA# 1261 Site# 254	Brisbane 1/21 Smallwood Place Murarrie QLD 4172 Tel: +61 7 3902 4600 466 NATA# 1261 Site# 2075	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 94 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Ca Aa	ompany Name: Idress:	JBS & G Au Level 1, 50 Sydney NSW 2000	istralia (NSW Margaret St) P/L				O Re Pl Fa	rder No.: eport #: 10 hone: 02 ax:	006675 2 8245 0300		Received: Due: Priority: Contact Name:	Jul 11, 2023 2:36 Jul 18, 2023 5 Day Rob Sharpsmith	PM
Pr Pr	oject Name: oject ID:	RPA 63888									E	urofins Analytical Ser	vices Manager : A	ndrew Black
		Si	ample Detail				Asbestos Absence /Presence	Lead (% w/w)						
Syd	ney Laboratory	- NATA # 1261	Site # 18217	,			Х	х						
Exte	ernal Laboratory	1	1						_					
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB	ID								
1	L6-A13	Jul 10, 2023		Building Materials	S23-JI001	9831	х							
2	L6-A14	Jul 10, 2023		Building Materials	S23-JI001	9832	х							
3	L6-A15	Jul 10, 2023		Building Materials	S23-JI001	9833	х							
4	L6-A16	Jul 10, 2023		Building Materials	S23-JI001	9834	Х							
5	L6-LO7	Jul 10, 2023		Paint	S23-JI001	9835		х						
6	L6-LO8	Jul 10, 2023		Paint	S23-JI001	9836		х	1					
7	L7-A09	Jul 10, 2023		Building Materials	S23-JI001	9837	х]					
8	L7-A10	Jul 10, 2023		Building Materials	S23-JI001	9838	х							
9	L7-A11	Jul 10, 2023		Building	S23-JI001	9839	Х]					

		Eurofins Environme	ent Testing Australia	Pty Ltd						Eurofins ARL Pty Ltd	Eurofins Environn	nent Testing NZ Ltd
web: www.eurofins.com.au email: EnviroSales@eurofins.com		ABN: 50 005 085 521 Melbourne Geelong Sydn 6 Monterey Road 19/8 Lewalan Street 179 N Dandenong South Grovedale Girrar VIC 3175 VIC 3216 NSW Tel: +61 3 8564 5000		Sydney 179 Magow Girraween NSW 2145 Tel: +61 2 9 03 NATA# 126	ydney Canberr. 79 Magowar Road Unit 1,2 ' irraween Mitchell ISW 2145 ACT 291 'ei: +61 2 9900 8400 Tel: +61 MATA# 1261 Site# 18217 NATA#		Canberra Unit 1,2 Dacre Street Mitchell ACT 2911 Tel: +61 2 6113 8091 7 NATA# 1261 Site# 2544	Brisbane 1/21 Smallwood Place Murarrie QLD 4172 Tel: +61 7 3902 4600 56 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	ABN: 91 05 0159 898 Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	NZBN: 942904602495 Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	4 Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Company Name: Address: Project Name: Project ID:	JBS & G A Level 1, 50 Sydney NSW 2000 RPA 63888	ustralia (NSW) P/L Margaret St				Or Re Pr Fa	rder No.: eport #: 100 none: 02 x:	06675 8245 0300		Received: Due: Priority: Contact Name:	Jul 11, 2023 2:36 Jul 18, 2023 5 Day Rob Sharpsmith	PM
	00000								E	urofins Analytical Ser	vices Manager : A	ndrew Black
	S	Sample Detail			Asbestos Absence /Presence	Lead (% w/w)						
Sydney Laboratory	- NATA # 126	1 Site # 18217			х	Х						
		Mate	rials									
Test Counts					7	2						



Internal Quality Control Review and Glossary General

- 1. 2. 3.
- CC data may be available on request. All soil results are reported on a dry basis, unless otherwise stated. Samples were analysed on an 'as received' basis. Information identified on this report with the colour **blue** indicates data provided by customer that may have an impact on the results. This report replaces any interim results previously issued. 4. 5.

Holding Times Please refer to the most recent version of the 'Sample Preservation and Container Guide' for holding times (QS3001).

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported. Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units % w/w: F/fld F/mL g, kg g/kg L, mL L, mL L/min min	Percentage weight-for-weight basis, e.g. of asbestos in asbestos-containing finds in soil samples (% w/w) Airborne fibre filter loading as Fibres (N) per Fields counted (n) Airborne fibre reported concentration as Fibres per milliliter of air drawn over the sampler membrane (C) Mass, e.g. of whole sample (M) or asbestos-containing find within the sample (m) Concentration in grams per kilogram Volume, e.g. of air as measured in AFM (V = r x t) Airborne fibre sampling Flowrate as litres per minute of air drawn over the sampler membrane (r) Time (t), e.g. of air sample collection period
Calculations	
Airborne Fibre Concentration:	$C = \left(\frac{n}{a}\right) \times \left(\frac{1}{r}\right) \times \left(\frac{1}{r}\right) = K \times \left(\frac{n}{r}\right) \times \left(\frac{1}{v}\right)$
Asbestos Content (as asbestos):	$\% w/w = \frac{(m \times P_A)}{M}$
Weighted Average (of asbestos):	$\%_{WA} = \sum \frac{(m \times P_A)_X}{x}$
Terms %ashestos	Estimated percentage of ashestos in a given matrix. May be derived from knowledge or experience of the material informed by HSG264 Appendix 2 else
///////////////////////////////////////	assumed to be 15% in accordance with WA DOH Appendix 2 (P_A).
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded (non-friable) condition. For the purposes of the NEPM and WA DOH, ACM corresponds to material larger than 7 mm x 7 mm.
AF	Asbestos Fines. Asbestos contamination within a soil sample, as defined by WA DOH. Includes loose fibre bundles and small pieces of friable and non-friable material such as asbestos cement fragments mixed with soil. Considered under the NEPM as equivalent to "non-bonded / friable".
AFM	Airborne Fibre Monitoring, e.g. by the MFM.
Amosite	Amosite Asbestos Detected. Amosite may also refer to Fibrous Grunerite or Brown Asbestos. Identified in accordance with AS 4964-2004.
AS	Australian Standard.
Asbestos Content (as asbestos)	Total % w/w asbestos content in asbestos-containing finds in a soil sample (% w/w).
Chrysotile	Chrysotile Asbestos Detected. Chrysotile may also refer to Fibrous Serpentine or White Asbestos. Identified in accordance with AS 4964-2004.
COC	Chain of Custody.
Crocidolite	Crocidolite Asbestos Detected. Crocidolite may also reter to Fibrous Riebeckite or Blue Asbestos. Identified in accordance with AS 4964-2004.
Dry	Sample is dried by heating prior to analysis.
DS	Dispersion Staining. Technique required for Unequivocal Identification of asbestos fibres by PLM.
FA	Fibrous Asbestos. Asbestos containing material that is wholly or in part friable, including materials with higher asbestos content with a propensity to become friable with handling, and any material that was previously non-friable and in a severely degraded condition. For the purposes of the NEPM and WA DOH, FA generally corresponds to material larger than 7 mm x 7 mm, although FA may be more difficult to visibly distinguish and may be assessed as AF.
Fibre Count	Total of all fibres (whether asbestos or not) meeting the counting criteria set out in the NOHSC:3003
Fibre ID	Fibre Identification. Unequivocal identification of asbestos fibres according to AS 4964-2004. Includes Chrysotile, Amosite (Grunerite) or Crocidolite asbestos.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
HSG248	UK HSE HSG248, Asbestos: The Analysts Guide, 2nd Edition (2021).
HSG264	UK HSE HSG264, Asbestos: The Survey Guide (2012).
ISO (also ISO/IEC)	International Organization for Standardization / International Electrotechnical Commission.
K Factor	Microscope constant (K) as derived from the effective filter area of the given AFM membrane used for collecting the sample (A) and the projected eyepiece graticule area of the specific microscope used for the analysis (a).
LOR	Limit of Reporting.
MFM (also NOHSC:3003)	Membrane Filter Method. As described by the Australian Government National Occupational Health and Safety Commission, Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003(2005)].
NEPM (also ASC NEPM)	National Environment Protection (Assessment of Site Contamination) Measure, (2013, as amended).
Organic	Organic Fibres Detected. Organic may refer to Natural or Man-Made Polymeric Fibres. Identified in accordance with AS 4964-2004.
PCM	Phase Contrast Microscopy. As used for Fibre Counting according to the MFM.
PLM	Polarised Light Microscopy. As used for Fibre Identification and Trace Analysis according to AS 4964-2004.
Sampling	Unless otherwise stated Eurofins are not responsible for sampling equipment or the sampling process.
SMF	Synthetic Mineral Fibre Detected. SMF may also refer to Man Made Vitreous Fibres. Identified in accordance with AS 4964-2004.
SRA	Sample Receipt Advice.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres (particularly asbestos) in a given sample matrix.
UK HSE HSG	United Kingdom, Health and Safety Executive, Health and Safety Guidance, publication.
	Unidentified Mineral Fibre Detected. Fibrous minerals that are detected but have not been unequivocally identified by PLM with DS according the AS 4964-2004 May include (but not limited to) Actinolite, Anthophyllite or Tremolite asbestos.
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos- Contaminated Sites in Western Australia (updated 2021), including Appendix Four: Laboratory analysis
Weighted Average	Combined average % w/w asbestos content of all asbestos-containing finds in the given aliquot or total soil sample (%wA).



Comments

23-JI0019832: Submitted sample size was too small. Results may be differ for bigger size of sample.

Sample Integrity	
Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Asbestos Counter/Identifier:

Chamath JHM Annakkage

Authorised by:

Sayeed Abu

Senior Analyst-Asbestos

Senior Analyst-Asbestos

Glenn Jackson Managing Director

Final Report - this report replaces any previously issued Report

- Indicates Not Requested

- * Indicates NATA accreditation does not cover the performance of this service
- Measurement uncertainty of test data is available on request or please click here.

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.



JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000

Attention:

Rob Sharpsmith

Report Project name Project ID Received Date **1006675-S** RPA 63888 Jul 11, 2023

D7 L6-LO8	
Paint	
II0019835 S23-JI001983	336
0, 2023 Jul 10, 2023	3
2.0 3.0	
	D7 L6-L08 Paint Paint II0019835 S23-JI00198 0, 2023 Jul 10, 2023 2.0 3.0



NATA Accredited Accreditation Number 1261 Site Number 18217

Accredited for compliance with ISO/IEC 17025 – Testing NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.



Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Lead (% w/w)	Sydney	Jul 17, 2023	6 Months

- Method: LTM-MET-3040 Metals in Waters Soils & Sediments by ICP-MS

web: www.eurofins.com.au email: EnviroSales@eurofins.com			Eurofins Env ABN: 50 005 08	r ironment Tes 5 521	ting Australia P	ty Ltd		Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environment Testing NZ Ltd NZBN: 9429046024954					
			Melbourne 6 Monterey Roa Dandenong Sou VIC 3175 Tel: +61 3 8564 NATA# 1261 Sit	Geelon d 19/8 Lo uth Groved VIC 32 5000 5000 Tel: +6 te# 1254 NATA#	Geelong Sydney 19/8 Lewalan Street 179 Magc 1 Grovedale Girrawear VIC 3216 NSW 214 1000 Tel: +61 3 8564 5000 Tel: +61 2 # 1254 NATA# 1261 Site# 25403 NATA# 1:			ad 3400 # 1821	Canberra Unit 1,2 Dacre Street Mitchell ACT 2911 Tel: +61 2 6113 8091 7 NATA# 1261 Site# 254	Brisbane 1/21 Smallwood Place Murarrie QLD 4172 Tel: +61 7 3902 4600 66 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 94 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Cc Ac	ompany Name: Idress:	JBS & G Au Level 1, 50 Sydney NSW 2000	stralia (NSW Margaret St) P/L				O Ri Pi Fa	rder No.: eport #: 10 hone: 02 ax:	06675 8245 0300		Received: Due: Priority: Contact Name:	Jul 11, 2023 2:36 Jul 18, 2023 5 Day Check the COC fo	PM r Project
Pr Pr	oject Name: oject ID:	RPA 63888									E	urofins Analytical Ser	vices Manager : A	ndrew Black
		Si	ample Detail				Asbestos Absence /Presence	Lead (% w/w)						
Syd	ney Laboratory	- NATA # 1261	Site # 18217	7			Х	Х]					
Exte	ernal Laboratory	<u>,</u>		1					-					
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB	ID								
1	L6-A13	Jul 10, 2023		Building Materials	S23-JI001	9831	х							
2	L6-A14	Jul 10, 2023		Building Materials	S23-JI001	9832	x							
3	L6-A15	Jul 10, 2023		Building Materials	S23-JI001	9833	x							
4	L6-A16	Jul 10, 2023		Building Materials	S23-JI001	9834	x							
5	L6-LO7	Jul 10, 2023		Paint	S23-JI001	9835		Х						
6	L6-LO8	Jul 10, 2023		Paint	S23-JI001	9836		х						
7	L7-A09	Jul 10, 2023		Building Materials	S23-JI001	9837	х							
8	L7-A10	Jul 10, 2023		Building Materials	S23-JI001	9838	х							
9	L7-A11	Jul 10, 2023		Building	S23-JI001	9839	х							

			Eurofins Environme	ent Testing Australia	Eurofins ARL Pty Ltd	Eurofins Environ	ment Testing NZ Ltd						
web: www.eurofins.com.au email: EnviroSales@eurofins		com	ABN: 50 005 085 521 Melbourne 6 Monterey Road Dandenong South VIC 3175 Tel: +61 3 8564 5000 NATA# 1261 Site# 1254	Geelong 19/8 Lewalan Street Grovedale VIC 3216 Tel: +61 3 8564 5000 NATA# 1261 Site# 254/	Sydney 179 Magowar Road Girraween NSW 2145 Tel: +61 2 9900 840 03 NATA# 1261 Site# 1		d 00	Canberra Unit 1,2 Dacre Street Mitchell ACT 2911 Tel: +61 2 6113 8091 7 NATA# 1261 Site# 2540	Brisbane 1/21 Smallwood Place Murarrie QLD 4172 Tel: +61 7 3902 4600 56 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 4 Site# 25079 & 25289	ABN: 91 05 0159 898 Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	NZBN: 94290460245 Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	154 Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290
Con Ado Pro	npany Name: Iress: ject Name: ject ID:	JBS & G A Level 1, 50 Sydney NSW 2000 RPA 63888	ustralia (NSW) P/L Margaret St				Or Re Ph Fa	der No.: port #: 100 one: 02 x:	06675 8245 0300		Received: Due: Priority: Contact Name:	Jul 11, 2023 2:36 Jul 18, 2023 5 Day Check the COC f	PM or Project
	•									E	urofins Analytical Ser	vices Manager : /	Andrew Black
		s	ample Detail			Asbestos Absence /Presence	Lead (% w/w)						
Sydn	ey Laboratory -	NATA # 1261	I Site # 18217			Х	Х						
			Mate	rials									
Test	Counts					7	2						



Internal Quality Control Review and Glossary

General

- 1. Laboratory QC results for Method Blanks, Duplicates, Matrix Spikes, and Laboratory Control Samples follows guidelines delineated in the National Environment Protection (Assessment of Site Contamination) Measure 1999, as amended May 2013 and are included in this QC report where applicable. Additional QC data may be available on request.
- 2. All soil/sediment/solid results are reported on a dry basis, unless otherwise stated.
- 3. All biota/food results are reported on a wet weight basis on the edible portion, unless otherwise stated.
- 4. Actual LORs are matrix dependant. Quoted LORs may be raised where sample extracts are diluted due to interferences.
- 5. Results are uncorrected for matrix spikes or surrogate recoveries except for PFAS compounds.
- 6. SVOC analysis on waters are performed on homogenised, unfiltered samples, unless noted otherwise.
- 7. Samples were analysed on an 'as received' basis.
- 8. Information identified on this report with blue colour, indicates data provided by customer that may have an impact on the results.
- 9. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the SRA. If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

For VOCs containing vinyl chloride, styrene and 2-chloroethyl vinyl ether the holding time is 7 days however for all other VOCs such as BTEX or C6-10 TRH then the holding time is 14 days.

Units

mg/kg: milligrams per kilogram	mg/L: milligrams per litre	μg/L: micrograms per litre
ppm: parts per million	ppb: parts per billion	%: Percentage
org/100 mL: Organisms per 100 millilitres	NTU: Nephelometric Turbidity Units	MPN/100 mL: Most Probable Number of organisms per 100 millilitres
CFU: Colony forming unit		

Terms

APHA	American Public Health Association
coc	Chain of Custody
СР	Client Parent - QC was performed on samples pertaining to this report
CRM	Certified Reference Material (ISO17034) - reported as percent recovery.
Dry	Where a moisture has been determined on a solid sample the result is expressed on a dry basis.
Duplicate	A second piece of analysis from the same sample and reported in the same units as the result to show comparison.
LOR	Limit of Reporting.
LCS	Laboratory Control Sample - reported as percent recovery.
Method Blank	In the case of solid samples these are performed on laboratory certified clean sands and in the case of water samples these are performed on de-ionised water.
NCP	Non-Client Parent - QC performed on samples not pertaining to this report, QC is representative of the sequence or batch that client samples were analysed within.
RPD	Relative Percent Difference between two Duplicate pieces of analysis.
SPIKE	Addition of the analyte to the sample and reported as percentage recovery.
SRA	Sample Receipt Advice
Surr - Surrogate	The addition of a like compound to the analyte target and reported as percentage recovery.
твто	Tributyltin oxide (<i>bis</i> -tributyltin oxide) - individual tributyltin compounds cannot be identified separately in the environment however free tributyltin was measured and its values were converted stoichiometrically into tributyltin oxide for comparison with regulatory limits.
TCLP	Toxicity Characteristic Leaching Procedure
TEQ	Toxic Equivalency Quotient or Total Equivalence
QSM	US Department of Defense Quality Systems Manual Version 5.4
US EPA	United States Environmental Protection Agency
WA DWER	Sum of PFBA, PFPeA, PFHxA, PFHpA, PFOA, PFBS, PFHxS, PFOS, 6:2 FTSA, 8:2 FTSA

QC - Acceptance Criteria

The acceptance criteria should be used as a guide only and may be different when site specific Sampling Analysis and Quality Plan (SAQP) have been implemented

RPD Duplicates: Global RPD Duplicates Acceptance Criteria is 30% however the following acceptance guidelines are equally applicable:

Results <10 times the LOR: No Limit

Results between 10-20 times the LOR: RPD must lie between 0-50%

Results >20 times the LOR: RPD must lie between 0-30%

NOTE: pH duplicates are reported as a range not as RPD

Surrogate Recoveries: Recoveries must lie between 20-130% for Speciated Phenols & 50-150% for PFAS. SVOCs recoveries 20 - 150%

PFAS field samples that contain surrogate recoveries in excess of the QC limit designated in QSM 5.4 where no positive PFAS results have been reported have been reviewed and no data was affected.

QC Data General Comments

- 1. Where a result is reported as a less than (<), higher than the nominated LOR, this is due to either matrix interference, extract dilution required due to interferences or contaminant levels within the sample, high moisture content or insufficient sample provided.
- 2. Duplicate data shown within this report that states the word "BATCH" is a Batch Duplicate from outside of your sample batch, but within the laboratory sample batch at a 1:10 ratio. The Parent and Duplicate data shown is not data from your samples.
- 3. pH and Free Chlorine analysed in the laboratory Analysis on this test must begin within 30 minutes of sampling. Therefore, laboratory analysis is unlikely to be completed within holding time. Analysis will begin as soon as possible after sample receipt.
- 4. Recovery Data (Spikes & Surrogates) where chromatographic interference does not allow the determination of recovery the term "INT" appears against that analyte.
- 5. For Matrix Spikes and LCS results a dash "-" in the report means that the specific analyte was not added to the QC sample.
- 6. Duplicate RPDs are calculated from raw analytical data thus it is possible to have two sets of data.



Quality Control Results

Test	Units	Result 1		Acceptance Limits	Pass Limits	Qualifying Code
Method Blank						
Lead (% w/w)	%	< 0.01		0.01	Pass	



Comments

Sample Integrity	
Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Authorised by:

Andrew Black Mickael Ros Sayeed Abu Analytical Services Manager Senior Analyst-Metal Senior Analyst-Asbestos

Glenn Jackson Managing Director

Final Report - this report replaces any previously issued Report

- Indicates Not Requested
- * Indicates NATA accreditation does not cover the performance of this service
- Measurement uncertainty of test data is available on request or please click here.

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

CHAIN OF CUSTODY



PROJECT NO.: 63888								LABORATORY BATCH NO :									
PROJECT NAME: KIA						SAMPLERS: TAROPH (marge 2 4 day 1 Change 1)											
DATE NEEDED BY: STAR	DATO					OCIEVEL NEPM (2013)											
PHONE: Sydney: 02 8245	PHONE: Sydney: 02 8245 0300 Perth: 08 9488 0100 Brisbane: 07 3112 2688																
SEND REPORT & INVOICE	TO: (1) admin	nsw@ibsg	.com.au: (2	2) SLUMSDEN	hsg.com		TGrom	3						_			
COMMENTS / SPECIAL HANDLING /	STORAGE OR DISPOS	SAL:	(1	,	bsg.com.	au, (5)				@JD	sg.com	.au		1-1-	Third of	1	
															ASBESTO	5	
																5	
															ICATIC	£	
SAMPLE ID	MATRIX	DATE	TIME	TYPE & PRESERVATIVE	рН										EPMA	NOTES	
EM-101	MARRIAL	10-07.23		Bag.								+++			V	NOTES:	
EM-02	F	1		10				-									
EM-03	N. No.	V		J.										+ +-	N.		
												+ +			X		
					_	_											
	-					_	_	\vdash	_								
					_												
					_												
									_								
															+		
												+-+-					
									-						+		
									-		+						
													+				
					-	-	_		-								
						_	_		_								
					-												
RELINOUS	RV.																
NAME: DATE:		CONSI	GNMENT NO	TE NO		010 M # /	RE	CEIVEL	BY:				FOR	RECEIVI	NG LAB U	JSE ONLY:	
JULUMP .	10.01	001101		12110.		DATE:	177	UV		2.30	COOL	ER SEAL -	Yes	No	Intact	Broken	
OF: JBS&G V V		TRANS	PORT CO.			OF:	IN				COOLE	RTEMP	W deg	A			
DATE:		CONSI	GNMENT NO	TE NO.		NAME:			DA	ATE:	COOL	R SEAL -	Yes	No	Intact .	Broken	
OF:		TRANS	PORT CO			OF:											
Container & Preservative Codes: P =	Plastic; J = Soil Jar; I	3 = Glass Bottle	; N = Nitric Acid	l Prsvd.; C = Sodium Hydroxide Prsvd; VC =	Hydrochlorid	Acid Prsv	d Vial; VS =	= Sulfuri	c Acid P	rsvd Vial: S = S	UDOLE	R IEMP	deg (A Droud- 5	T - Charile Dattley O - Cit	
-So romsols - Chain of Custody	- Generic													u, L – LUI	n riavu; S	- sterne bottle; U = Other	



Eurofins Environment Testing Australia Pty Ltd

ABN: 50 005 085 521					
Melbourne	Geelong	Sydney	Canberra	Brisbane	Newcastle
6 Monterey Road	19/8 Lewalan Street	179 Magowar Road	Unit 1,2 Dacre Street	1/21 Smallwood Place	1/2 Frost Drive
Dandenong South	Grovedale	Girraween	Mitchell	Murarrie	Mayfield West NSW 230
VIC 3175	VIC 3216	NSW 2145	ACT 2911	QLD 4172	Tel: +61 2 4968 8448
Tel: +61 3 8564 5000	Tel: +61 3 8564 5000	Tel: +61 2 9900 8400	Tel: +61 2 6113 8091	Tel: +61 7 3902 4600	NATA# 1261
NATA# 1261 Site# 1254	NATA# 1261 Site# 25403	NATA# 1261 Site# 18217	NATA# 1261 Site# 25466	NATA# 1261 Site# 20794	Site# 25079 & 25289

www.eurofins.com.au

Perth

Welshpool

NATA# 2377 Site# 2370

WA 6106

Eurofins ARL Pty Ltd Eurofins Environment Testing NZ Ltd ABN: 91 05 0159 898 NZBN: 9429046024954 Auckland 46-48 Banksia Road 35 O'Rorke Road Penrose, Auckland 1061 Tel: +61 8 6253 4444 Tel: +64 9 526 4551

IANZ# 1327

EnviroSales@eurofins.com

Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290

Sample Receipt Advice

Company name:	JBS & G Australia (NSW) P/L
Contact name:	Stuart Lumsden
Project name:	RPA
Project ID:	63888
Turnaround time:	5 Day
Date/Time received	Jul 11, 2023 2:36 PM
Eurofins reference	1006688

Sample Information

- A detailed list of analytes logged into our LIMS, is included in the attached summary table. 1
- All samples have been received as described on the above COC.
- COC has been completed correctly. 1
- N/A Attempt to chill was evident.
- Appropriately preserved sample containers have been used. 1
- All samples were received in good condition.
- Samples have been provided with adequate time to commence analysis in accordance with the relevant holding times.
- Appropriate sample containers have been used.
- Sample containers for volatile analysis received with zero headspace. 1
- Split sample sent to requested external lab. X
- X Some samples have been subcontracted.
- N/A Custody Seals intact (if used).

Notes

Contact

If you have any questions with respect to these samples, please contact your Analytical Services Manager:

Andrew Black on phone : (+61) 2 9900 8490 or by email: AndrewBlack@eurofins.com Results will be delivered electronically via email to Stuart Lumsden - slumsden@jbsg.com.au.

Global Leader - Results you can trust



Certificate of Analysis

Environment Testing

JBS & G Australia (NSW) P/L Level 1, 50 Margaret St Sydney NSW 2000



NATA Accredited Accreditation Number 1261 Site Number 18217

Accredited for compliance with ISO/IEC 17025–Testing NATA is a signatory to the ILAC Mutual Recognition Arrangement for the mutual recognition of the equivalence of testing, medical testing, calibration, inspection, proficiency testing scheme providers and reference materials producers reports and certificates.

Attention:	Stuart Lumsden
Report	1006688-AID
Project Name	RPA
Project ID	63888
Received Date	Jul 11, 2023
Date Reported	Jul 18, 2023
Methodology:	
Asbestos Fibre Identification	Conducted in accordance with the Australian Standard AS 4964 – 2004: Method for the Qualitative Identification of Asbestos in Bulk Samples and in-house Method LTM-ASB-8020 by polarised light microscopy (PLM) and dispersion staining (DS) techniques.
	NUTE: Positive Trace Analysis results indicate the sample contains detectable respirable tibres.
Unknown Mineral Fibres	Mineral fibres of unknown type, as determined by PLM with DS, may require another analytical technique, such as Electron Microscopy, to confirm unequivocal identity. NOTE: While Actinolite, Anthophyllite and Tremolite asbestos may be detected by PLM with DS, due to variability in the
	optical properties of these materials, AS4964 requires that these are reported as UMF unless confirmed by an independent technique.
Subsampling Soil Samples	The whole sample submitted is first dried and then passed through a 10mm sieve followed by a 2mm sieve. All fibrous matter greater than 10mm, greater than 2mm as well as the material passing through the 2mm sieve are retained and analysed for the presence of asbestos. If the sub 2mm fraction is greater than approximately 30 to 60g then a sub-sampling routine based on ISO 3082:2009(E) is employed. NOTE: Depending on the nature and size of the soil sample, the sub-2 mm residue material may need to be sub-sampled for trace analysis, in accordance with AS 4964-2004.
Bonded asbestos- containing material (ACM)	The material is first examined and any fibres isolated for identification by PLM and DS. Where required, interfering matrices may be removed by disintegration using a range of heat, chemical or physical treatments, possibly in combination. The resultant material is then further examined in accordance with AS 4964 - 2004. NOTE: Even after disintegration it may be difficult to detect the presence of asbestos in some asbestos-containing bulk materials using PLM and DS. This is due to the low grade or small length or diameter of the asbestos fibres present in the material, or to the fact that very fine fibres have been distributed intimately throughout the materials. Vinyl/asbestos floor tiles, some asbestos-containing sealants and mastics, asbestos-containing epoxy resins and some ore samples are examples of these types of material, which are difficult to analyse.
Limit of Reporting	The performance limitation of the AS 4964 (2004) method for non-homogeneous samples is around 0.1 g/kg (equivalent to 0.01% (w/w)). Where no asbestos is found by PLM and DS, including Trace Analysis, this is considered to be at the nominal reporting limit of 0.01% (w/w). The NEPM screening level of 0.001% (w/w) is intended as an on-site determination, not a laboratory Limit of Reporting (LOR), per se. Examination of a large sample size (e.g. 500 mL) may improve the likelihood of detecting asbestos, particularly AF, to aid assessment against the NEPM criteria. Gravimetric determinations to this level of accuracy are outside of AS 4964 and hence NATA Accreditation does not cover the performance of this service (non-NATA results shown with an asterisk). NOTE: NATA News March 2014, p.7, states in relation to AS 4964: "This is a qualitative method with a nominal reporting limit of 0.01 % " and that currently in Australia "there is no validated method available for the quantification of asbestos". This report is consistent with the analytical procedures and reporting recommendations in the NEPM and the WA DoH.



Project Name	RPA
Project ID	63888
Date Sampled	Jul 10, 2023
Report	1006688-AID

Client Sample ID	Eurofins Sample No.	Date Sampled	Sample Description	Result
EM-01	23-JI0019870	Jul 10, 2023	Approximate Sample 1g / 20x7x3mm Sample consisted of: Black sealant material	No asbestos detected. No trace asbestos detected.
EM-02	23-JI0019871	Jul 10, 2023	Approximate Sample 1g / 15x10x5mm Sample consisted of: Black flexible rubbery material sheet	No asbestos detected. No trace asbestos detected.
EM-03	23-JI0019872	Jul 10, 2023	Approximate Sample 7g / 50x15x10mm Sample consisted of: Off-white sealant material	No asbestos detected. No trace asbestos detected.



Sample History

Where samples are submitted/analysed over several days, the last date of extraction is reported.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description

Asbestos - LTM-ASB-8020

Testing SiteExtractedSydneyJul 11, 2023

Holding Time Indefinite

Eurofins Environment Testing Australia Pty Ltd ABN: 50 005 085 521									Eurofins ARL Pty Ltd ABN: 91 05 0159 898	Eurofins Environn NZBN: 942904602495	nent Testing NZ Ltd 4		
Web: www.eurofins.com.au Melbourne Geelong Sydney mail: EnviroSales@eurofins.com 179 Magov 179 Magov 179 Magov Melbourne 6 Monterey Road 19/8 Lewalan Street 179 Magov Opandenong South VIC 3216 NSW 2145 Tel: +613 8564 5000 Tel: +613 8564 5000 Tel: +613 8564 5000 NATA# 1261 Site# 1254 NATA# 1261 Site# 25403 NATA# 1261			owar Road n 5 2 9900 840 261 Site# 1	Canberra Unit 1,2 Dacre Street Mitchell ACT 2911 0 Tel: +61 2 6113 8091 18217 NATA# 1261 Site# 25	Brisbane 1/21 Smallwood Place Murarrie QLD 4172 Tel: +61 7 3902 4600 466 NATA# 1261 Site# 2079	Newcastle 1/2 Frost Drive Mayfield West NSW 2304 Tel: +61 2 4968 8448 NATA# 1261 94 Site# 25079 & 25289	Perth 46-48 Banksia Road Welshpool WA 6106 Tel: +61 8 6253 4444 NATA# 2377 Site# 2370	Auckland 35 O'Rorke Road Penrose, Auckland 1061 Tel: +64 9 526 4551 IANZ# 1327	Christchurch 43 Detroit Drive Rolleston, Christchurch 7675 Tel: +64 3 343 5201 IANZ# 1290				
Co Ad	ompany Name: Idress:	JBS & G Au Level 1, 50 I Sydney NSW 2000	stralia (NSW) Margaret St) P/L				Order No.: Report #: 10 Phone: 02 Fax:	006688 2 8245 0300		Received: Due: Priority: Contact Name:	Jul 11, 2023 2:36 F Jul 18, 2023 5 Day Stuart Lumsden	ΡM
Pro Pro	oject Name: oject ID:	RPA 63888								E	urofins Analytical Ser	vices Manager : A	ndrew Black
Sample Detail				Asbestos Absence /Presence									
Syd	ney Laboratory	- NATA # 1261	Site # 18217	,			X						
No	Sample ID	Sample Date	Sampling Time	Ма	atrix L	AB ID							
1	EM-01	Jul 10, 2023		Buildin Materia	g S23-Jl	0019870	x						
2	EM-02	Jul 10, 2023		Buildin Materia	g S23-Jl	0019871	x						
3	EM-03	Jul 10, 2023		Buildin Materia	g S23-Jl	0019872	x						
Test	t Counts						3						



Internal Quality Control Review and Glossary General

- 1. 2. 3.
- AC data may be available on request. All soil results are reported on a dry basis, unless otherwise stated. Samples were analysed on an 'as received' basis. Information identified on this report with the colour **blue** indicates data provided by customer that may have an impact on the results. This report replaces any interim results previously issued. 4. 5.

Holding Times Please refer to the most recent version of the 'Sample Preservation and Container Guide' for holding times (QS3001). If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported. Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units	
% w/w:	Percentage weight-for-weight basis, e.g. of asbestos in asbestos-containing finds in soil samples (% w/w)
F/fld	Airborne fibre filter loading as Fibres (N) per Fields counted (n)
a, ka	Andorne note reported concentration as horse per minimute of an drawn over the sampler memorane (C) Mass, e.g. of whole sample (M) or asbestos-containing flow within the sample (m)
g/kg	Concentration in grams per kilogram
L, mL L/min	Volume, e.g. of air as measured in AFM ($V = r \times t$) Airborne fibre sampling Flowrate as litres per minute of air drawn over the sampler membrane (r)
min	Time (t), e.g. of air sample collection period
Calculations	
Airborne Fibre Concentration:	$C = \left(\frac{a}{a}\right) \times \left(\frac{N}{n}\right) \times \left(\frac{1}{r}\right) \times \left(\frac{1}{r}\right) = K \times \left(\frac{N}{n}\right) \times \left(\frac{1}{v}\right)$
Asbestos Content (as asbestos):	$\% w/w = \frac{(m \times P_A)}{M}$
Weighted Average (of asbestos):	$\%_{WA} = \sum \frac{(m \times P_A)_X}{x}$
Terms	
%asbestos	Estimated percentage of asbestos in a given matrix. May be derived from knowledge or experience of the material, informed by HSG264 Appendix 2, else assumed to be 15% in accordance with WA DOH Appendix 2 (Pa)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded (non-friable) condition. For the purposes of the NEPM and WA DOH ACM corresponds to material larger than 7 mm x 7 mm
AF	Asbestos Fines. Asbestos contamination within a soil sample, as defined by WA DOH. Includes loose fibre bundles and small pieces of friable and non-friable
	material such as assests cement tragments mixed with soil. Considered under the NEPM as equivalent to "non-bonded / trable".
AFM	Arborne Fibre Monitoring, e.g. by the MFM.
Amosite	Amosite Asbestos Detected. Amosite may also refer to Fibrous Grunerite or Brown Asbestos. Identified in accordance with AS 4964-2004.
AS	Australian Standard.
Aspestos Content (as aspestos)	Total % www.asbestos.content in asbestos-containing inds in a soli sample (% www).
Chrysottle	Chrysolite Aspestos Delected. Chrysolite may also refer to Fibrous Selpentine of white Aspestos. Identified in accordance with AS 4904-2004.
	Cham di Custogy. Casialiti Askate Datatad - Casidalita muuslee referte Eitraus Disketilite er Dus Askates - Identified is casadeses with AC 4004 2004
Crocidolite	Crocoline Aspestos Detected. Crocolonie may also refer to Fibrous Riebeckite of blue Aspestos. Identified in accordance with AS 4904-2004.
Dry	Sample is oned by hearing prior to analysis.
DS EA	Dispersion Stammig. Technique required no onequivocan dennincation or aspessos notes by FLW.
FA	ribotos Asbestos. Asbestos contarinal material trata visiono in partinable, including materials with ingref asbestos contenti with a propertisity to become friable with handling, and any material that was previously non-friable and in a severely degraded condition. For the purposes of the NEPM and WA DOH, FA generally corresponds to material larger than 7 mm x 7 mm, although FA may be more difficult to visibly distinguish and may be assessed as AF.
Fibre Count	Total of all fibres (whether asbestos or not) meeting the counting criteria set out in the NOHSC:3003
Fibre ID	Fibre Identification. Unequivocal identification of asbestos fibres according to AS 4964-2004. Includes Chrysotile, Amosite (Grunerite) or Crocidolite asbestos.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
HSG248	UK HSE HSG248, Asbestos: The Analysts Guide, 2nd Edition (2021).
HSG264	UK HSE HSG264, Asbestos: The Survey Guide (2012).
ISO (also ISO/IEC)	International Organization for Standardization / International Electrotechnical Commission.
K Factor	Microscope constant (K) as derived from the effective filter area of the given AFM membrane used for collecting the sample (A) and the projected eyepiece graticule area of the specific microscope used for the analysis (a).
LOR	Limit of Reporting.
MFM (also NOHSC:3003)	Membrane Filter Method. As described by the Australian Government National Occupational Health and Safety Commission, Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003(2005)].
NEPM (also ASC NEPM)	National Environment Protection (Assessment of Site Contamination) Measure, (2013, as amended).
Organic	Organic Fibres Detected. Organic may refer to Natural or Man-Made Polymeric Fibres. Identified in accordance with AS 4964-2004.
PCM	Phase Contrast Microscopy. As used for Fibre Counting according to the MFM.
PLM	Polarised Light Microscopy. As used for Fibre Identification and Trace Analysis according to AS 4964-2004.
Sampling	Unless otherwise stated Eurofins are not responsible for sampling equipment or the sampling process.
SMF	Synthetic Mineral Fibre Detected. SMF may also refer to Man Made Vitreous Fibres. Identified in accordance with AS 4964-2004.
SRA	Sample Receipt Advice.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres (particularly asbestos) in a given sample matrix.
UK HSE HSG	United Kingdom, Health and Safety Executive, Health and Safety Guidance, publication.
UMF	Unidentified Mineral Fibre Detected. Fibrous minerals that are detected but have not been unequivocally identified by PLM with DS according the AS 4964-2004 May include (but not limited to) Actinolite, Anthophyllite or Tremolite asbestos.
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos- Contaminated Sites in Western Australia (updated 2021), including Appendix Four: Laboratory analysis
Weighted Average	Combined average % w/w asbestos content of all asbestos-containing finds in the given aliquot or total soil sample (%wA).



Comments

Sample Integrity	
Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Asbestos Counter/Identifier:

Chamath JHM Annakkage

Authorised by:

Sayeed Abu

Senior Analyst-Asbestos

Senior Analyst-Asbestos

Glenn Jackson Managing Director

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please click here.

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.



Appendix D Client Provided Floor Plans



Jacob	S	LEA
-------	---	-----

Royal Prince Alfred Hospital Redevelopment Stage 1



Royal Prince Alfred Hospital Redevelopment Stage 1



	J	a	C	0	b	S	LFZ
--	---	---	---	---	---	---	-----



Royal Prince Alfred Hospital Redevelopment Stage 1



	J	a	C	0	b	S	LFZ
--	---	---	---	---	---	---	-----



Royal Prince Alfred Hospital Redevelopment Stage 1



Já	aco	bs	

Scale 1:500 @ A1

Royal Prince Alfred Hospital Redevelopment Stage 1



	J	a	C	0	b	S	LFZ
--	---	---	---	---	---	---	-----



Royal Prince Alfred Hospital Redevelopment Stage 1



	J	a	C	0	b	S	LFZ
--	---	---	---	---	---	---	-----





J	a	C	0	b	S	LFZ



Royal Prince Alfred Hospital Redevelopment Stage 1



J	a	C	0	b	S	LFZ





J	a	C	0	b	S	LFZ





J	a	C	0	b	S	LFZ





J	a	C	0	b	S	LFZ




© JBS&G

This document is and shall remain the property of JBS&G. The document may only be used for the purposes for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited

Document Distribution

Rev No.	Copies	Recipient	Date
А	1 x Electronic	Zach Foster	16/08/2023
		Zach.Foster@cpbcon.com.au	

Document Status

Rev No.	Author	Reviewer	Approved for Issue		
		Name	Name	Signature	Date
А	Jordan Gomez Stuart Lumsden	Michael Samuel	Michael Samuel	Barl	16/08/2023

www.jbsg.com.au