

COWPASTURE ROAD BOSSLEY PARK NSW - EXISTING ADVERTISING SIGNS

Structural Assessment

Structural Consulting Engineering Services

Prepared for oOh! Media Operations Pty Ltd

Prepared by JMP Consulting Engineers

KEV.	DATE	STATUS					DESIGN	
DEV	DATE	STATUS	INIT	SIGN	INIT	SIGN	INIT	SIGN
A	27/02/2024	For Information	EVL		EVL		MB	
В	29/02/2024	Information Added as per DPHI Requirements	EVL		EVL		MB	

Structural Assessment Structural Consulting Engineering Services

Table of Contents

Introduction	
Description	
Design Methodology and Design Parameters	5
Summary of Results	6
Site Location	7
Existing Structure Geometry and Sizes	
Signage Weight and Wind Loading	9
Serviceability Assessment	
Strength Assessment	
Appendices	
Appendix 1 Original Structural Design Drawings	
Appendix 2 Structural Condition Report	

This document contains commercial information which has been prepared for the attention of the Client on this project. It is confidential and no information contained in this document shall be released in part or whole to any third party without the approval of John Mullen & Partners Pty Ltd.



Introduction

This report has been commissioned by oOh! Media for JMP to appraise the structural design and strength of the existing advertising signage structure attached to the roof of the pedestrian bridge over Cowpasture Road, Bossley Park, NSW.

The purpose of this appraisal is to evaluate the structure for compliance as part of the oOh! Media development application to the Department of Planning, Housing and infrastructure (DPHI) in NSW. DPHI requested oOh! Media to confirm that the specifications of the original structural design of the sign is compliant with current Design Standards and whether the "as built" structure conforms to the current relevant standards to be undertaken by a suitably registered structural engineer.

Our appraisal has been based upon information provided in the form of extracts from the original structural design drawings and a Structural Condition Report included within Appendix 1 and Appendix 2 respectively.

This report is not intended to be a dilapidation survey of the condition of the existing steel structure and that JMP have not witnessed the structure in person.

We have excluded from this appraisal an assessment of the existing bridge structure itself and maintenance access provisions, for conformance with the current BCA/NCC or other relevant Australian Standards.

This report is prepared by a Qualified Structural Engineer.

Structural Consulting Engineering Services



Description

The signage structure is commonly referred to as a double-sided front supersite having a nominal display size of 12,660mm long x 3,350mm high. The width of the display is approximately 1100mm wide.

The signage structure comprises a galvanised structural steel framed box structure with circular hollow section (CHS) legs. The legs penetrate the roof and are fully welded to the top of the bridge frame structures.

The structural steel framed box of the sign has upper and lower maintenance access catwalks which provide the sign installers access to the top and bottom of the sign for each face.



Design Methodology and Design Parameters

This report details the structural assessment of the existing steel framed box sign structure supporting the static screen for the Ultimate Limit State and Serviceability Limit State Loading Cases.

Wind loading used in the assessment is as per AS1170.2:2021 with the appropriate factors and wind speed for the region.

The weight of the advertising fixed banner skin, 12.66m x 3.35m applied on the structure is 15kgs each side. This load is equivalent to 0.35kg /m². Other accessories such as access catwalks are added as super imposed dead loads on the structure. Live loads on the walkways are also considered in accordance with AS1657.

The design evaluation of the signage framing members was undertaken using Space Gass and Toolkit software. Steel connections were evaluated using in house design procedures.

Steel Parameters

E = 200,000 MPa

Yield strength of plates = 300 MPa

Yield strength of hollow sections = 350 MPa

Yield strength of all other members = 250 MPa

Weld yield strength = 480 MPa

Design Codes and References

AS/NZS 1170.0:2002 Structural Design Actions – Part 0: General Principles.

AS/NZS 1170.1:2002 Structural Design Actions – Part 1: Permanent, Imposed and other actions.

AS/NZS 1170.2:2021 Structural Design Actions – Part 2: Wind Loads.

AS1657:2018 Fixed Platforms, Walkways, Stairways and Ladders – Design, Construction and Installation.

AS2312.1:2014 Guide to the Protection of Structural Steel against Atmospheric Corrosion by the Use of Protective Coatings.

AS4100:2020 Steel Structures

AASHTO LRFD Specifications for Structural Supports for Highway Signs, Luminaires and Traffic Signals.

Load Combinations

Load Combinations are based on the requirements of AS1170.0. Refer to Space Gass Input (Section D.2) for load combinations used in this assessment.

Structural Assessment Structural Consulting Engineering Services



Summary of Results

Based upon our analysis, we have found that all steel members are adequate for Ultimate Limit State Load Case.

All steel connections shown on the design drawings and depicted in the photos are adequate to resist the design forces.

All predicted displacements of the boxed frame are within the normal industry accepted Serviceability Limit State specified in AS1170.0.

Those recommendations nominated in the structural conditions report prepared by Arcadis should be implemented in the short term to prolong the longevity of the structure and be more serviceable.

The above-mentioned results and implementation of the recommendations ensure the structural viability of the signage structure and compliance with relevant Building Code of Australia (BCA) requirements and Australian Standards.

Structural Assessment Structural Consulting Engineering Services



Site Location



EXISTING ADVERTISING SIGNAGE, Project: COWPASTURE ROAD, BOSSLEY PARK. COMPUTATION SHEET Date: 26.02.2024 Project No: 4979 01 Designer: EL Level 7, 400 Collins Street Melbourne 3000 Date: 29.02.2024 Sheet Reviewer: MB Telephone (03) 9600 0366 Project Leader: EL of jmpmelb@jmp.com.au PHOTOGRAPHIC VIEW ADVERTISING DISPLAY SIZE: 12.66M X 3.35M COWPASTURE ROAD NORTHBOUND SOUTHBOUND -SOUTHBOUND -- - -1000 . _ _ 2660 COWPASTURE ROAD SITE PLAN

Rev: B 27/02/2024

Existing Structure Geometry and Sizes







EXISTING ADVERTISING SIGNAGE, Project: COWPASTURE ROAD, BOSSLEY PARK. COMPUTATION SHEET Date: 26.02.2024 Project No: 4979 01 Designer: EL Level 7, 400 Collins Street Melbourne 3000 MB Date: 29.02.2024 Sheet Telephone (03) 9600 0366 Project Leader: EL Reviewer: of jmpmelb@jmp.com.au 52 A 14 300 50x50x3.0 SH WELDED TO H2 MEMBERS M12 LOCK NUT -FOR LIGHT ARM INSTAL PROVIDE H4 TO EN FRAMES ONLY FOR FALL PROTECTION 6 SIGN PANEL BY SIGNAGE FABRICATOR MAX WEIGHT 15kg/m (A) n n Æ FIXED LADDER SAFETY CHAINS ACROSS OPEN END: FRAME FI (B) EXISTING BRIDGE STRUCTURE Z-BRACKET WELDED TO HORIZONTAL RAILS OF SIGN PANEL NOTE: DETAIL SCALE 1:20 2 S1 SECTION SCALE 1:50 LOCATION A D SUPPORT C URE DETERMIN FRAMES F1: EXIST. FRAME H3 125x75x6.0 UA — 8 FW SITE TO EXISTING FRAME AND NEW GRATH DED LAD ф - 6 PLATE 8 FW SITE FRAME CLEAT PLATE 8 CLEAT PLATE 1 M16 BOLT XIST. (B1) EXIST. FR 32 DETAIL SCALE 1:5 8 FW SITE A PROVIDE ADDITIONAL FLASHING AS REQUIRED TO NEW LATERAL RESTRAINT SHOE BRACKET - 50x20 150 LONG PL -8 FW EXISTING DEKTITE FLASH NOTE: SHOE BRACKET TO BE POSITIONED TO TOUCH EXISTING & CAP PLATE PRIOR TO SITE WELDING. 10 (FW ENSURE 15mm NOM, FROM TOP OF EXISTING CAP PLATE TO U/S OF SHOE BRACKET. SECTION BT DETAIL B 12mm PLATE FSBW CHS CONNECTION TO BRIDGE FRAMING

Rev: B 27/02/2024

Signage Weight and Wind Loading







COMPUTATION SHEET

EXISTING ADVERTISING SIGNAGE , Project: COWPASTURE ROAD, BOSSLEY PARK.

Designer: EL	Date: 26.02.2024	Project No: 4979 01		
				Level 7, 400 Collins Street
				Melbourne 3000
Project Leader: EL	Reviewer: MB	Date: 29.02.2024 Sheet	of	Telephone (03) 9600 0366 jmpmelb@jmp.com.au



Wind Actions

Wind Loads shall be calculated in accordance with AS1170.2:2021 Structural design actions - Wind Actions as specified below.

Parameters	ULS (1/500)	SLS (1/25)		
Importance Level	IL2			
Wind Region	A2 (Sydney)			
Regional Gust Wind Speed, Vr	45 m/s	37 m/s		
Terrain category	2			
Terrain/height multiplier, Mz.cat	As per Table 4.1 of AS/NZS 1170.2			
Directional multiplier, Ma	As per Table 3.2 of AS/NZS 1170.2			
Shielding multiplier, M₅	1.0			
Topographic multiplier, Mt	1.0			
Net pressure coefficient, CRO	As per Table B.2 of AS/NZS	1170.2		
Net porosity factor, Kg	1.0			
Aerodynamic shape factor, Cabe	CR. × KR			

Лони	MULLEN	& I	PARTNE	ERS
------	--------	-----	--------	-----



Assessment of Existing Signage Cowpasture Road, Bossley Park Oohh Media

Page: Project No.: 4979 01 Designed: EVL

Wind Analysis WA01

JMP

WIND V5.03

Design:	(Wind Analysis WA01) Sydney, Non-temporary structure
Importance:	All other structures not included in 1,3 or 4, Life = 50 years, Non-Cyclonic, APE = 500 years, APE.Serv = 25 years
Pressures:	Wu.max = 1.29kPa, Ws/Wu =0.68

Location - Fig 3.1(A), 3.1(B)

	Location = Sydney	y				
	Region =	А	Figure 3.1(A)			
	Sub region =	2	Figure 3.1(A)			
	Cyclonic =	N (Y)es, (N)o	Table 3.2(A)			
Importance	All other structures no	ot included in 1,3 or 4				
		Importance level =	2	1,2,3,4,(C)u	istom	
		Design working life =	50	Years		
	Annual prob. of	f exceedance (APE) = 1/	500	years	AS1170.0 - Table F2	
	Annual prob. of ex	ceed. Serv. (APE.s) = 1/	25	years	AS1170.0 - Appendix C	
Design wind sp	oeed (Vdes,q) - Cl 2.3					
	Ultimate regi	ional wind speed (VR) =	45	m/s	For a 1/500 APE - Table 3.1	
	Serv. regio	nal wind speed (VR.s) =	37	m/s	For a 1/25 APE.s - Table 3.1	
	Climate o	hange multiplier(Mc) =	1.00	Table 3.3		
	Minimum ult	imate speed (V/des A) -	20	m/c (122		
	winimum uit	imate speed (vdes,o) =	30	m/s - CI 2.3		
		Ratio VR.s / VR =	0.82			
		Ballanda (M				
		Ratio Ws / Wu =	0.68			

Design wind data for non-cyclonic areas with APE of 1:500 years

Dir (b)	Vdes,θ	Wu	Ws
	m/s	kPa	kPa
Ν	44.1	1.17	0.79
S	44.1	1.17	0.79
Е	44.1	1.17	0.79
w	46.4	1.29	0.87

Site wind data for non-cyclonic areas with APE of 1:500 years

Dir (b)	Md (*1)	VR*Mc*Md	Ave. Ht (z)	Cat	Mz,cat	Ms	Mt	Vsit,β	Wu.sit
		m/s	m					m/s	kPa
N	0.85	38.3	13.2	2	1.03	1.00	1.00	39.5	0.93
NE	0.75	33.8	13.2	2	1.03	1.00	1.00	34.8	0.73
E	0.85	38.3	13.2	2	1.03	1.00	1.00	39.5	0.93
SE	0.95	42.8	13.2	2	1.03	1.00	1.00	44.1	1.17
S	0.95	42.8	13.2	2	1.03	1.00	1.00	44.1	1.17
SW	0.95	42.8	13.2	2	1.03	1.00	1.00	44.1	1.17
w	1.00	45.0	13.2	2	1.03	1.00	1.00	46.4	1.29
NW	0.95	42.8	13.2	2	1.03	1.00	1.00	44.1	1.17

*1 - Refer to Table 3.2 and Cl 3.3, TC interpolated



Р

Assessment of Existing Signage

Cowpasture Road, Bossley Park Oohh Media

Page: Project No.: 4979 01 Designed: EVL

Hoarding H01

L

HOARDINGS	V5.01		JM	Ρ
Member:	(Hoarding H01) 12.7m wide x 3.4m high, 13.2m	to top (9.9m gap under)		
Normal:	Cp,n = 1.54			
Wind at θ =45:	Cp,n = 1.54			
Wind at θ =90:	Cp,n = ±1.2 - 0 to 2c, ±0.6 - 2c to 4c, then ±0.3			
Freestanding h	oardings and walls - Appendix B.2			
			b	
	Breadth (b) =	12660 mm	← →	
	Element height (c) =	3350 mm		
	Total height (h) =	13200 mm	c	
	Ratio (b/c) =	3.78		
	Ratio (c/h) =	0.25		
			+	
	Aerodynamic shape factor (Cshp) = Cp,	n*Kp Equ B.2		
	Cp,n = Net	t pressure coefficient - Cl B.2.1		
	Kp = Net	t porosity factor - Cl B.1.4		
Wind normal to	o hoarding or wall θ = 0° - Table B.2(A)			
	Ratio (b/c) =	3.78		
	Ratio (c/h) =	0.25		
	Cp,n = 1.3 + 0.5(0.3+log10(b/c))*(0.8-c/h) =	1.54		
	Vertical height of resultant (h-c/2) =	11525 mm above the surfac	e	
	Horizontal eccentricity of resultant (e = 0) =	0 mm (No eccentricity)		
Wind at θ = 45°	' to hoarding or wall - Table B.2(B) & B.2(C)			
	$P_{atio}(h/c) =$	2 70		
	Ratio(b/c) = Ratio(c/b) = Ratio(c/b) = Ratio(b/c) = Rat	0.25		
		0.25		
	$C_{\rm D}$ n = 1 3 + 0 5(0 3+log10(b/c))*(0 8-c/b) =	1 54		
	Vertical height of resultant $(h-c/2) =$	11525 mm above the surfac	e	
ł	Horizontal eccentricity of resultant ($e = 0.2*b$) =	2532 mm		
	From Table B.2(B)	2002		
Wind parallel to	o hoarding or wall θ = 90° - Table B.2(D)			
	Ratio (b/c) =	3.78		
	Ratio (c/h) =	0.25		
	(n n - +1	$\frac{1}{2}$ 0 to $\frac{1}{2}$ $\frac{1}{2}$ 0 f $\frac{1}{2}$ to $\frac{1}{2}$ to $\frac{1}{2}$	1 2	
	cp,n = <u>11</u> .	<mark>z - 0 t0 zt, 1</mark> 0.0 - zt t0 4t, then I		
Net porosity fa	ctor - B.1.4			
	Calidity factor (S) -	1 000 ratio of colid area to	total area of structure	
	Net porosity factor $k_D = \frac{1}{(1-\delta)^2} = \frac{1}{(1-\delta)^2}$	1 000		
	(100) = 100000000000000000000000000000000	1.000		



SPACE GARANGE 12 (64-bit) - JOHN MULLEN & PARTNERS PTY LTD Path: Z:_ Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model Designer: Date: Tuesday, February 27, 2024 10:35 AM, Page: 1

2 Dead Load + Signage Load

Load case 2







SPACE GASS 14.12 (64-bit) - JOHN MULLEN & PARTNERS PTY LTD Path: Z:_Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model Designer: Date: Tuesday, February 27, 2024 10:36 AM, Page: 1

SPACE

Load case 3





SPACE GENERAT PRACTOR A SECTION 12 (64-bit) - JOHN MULLEN & PARTNERS PTY LTD Path: Z:__Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model Designer: Date: Tuesday, February 27, 2024 10:36 AM, Page: 1

SPACE







Serviceability Assessment



Path: Z:__Frojects\4979-01 Cowpasture Road Bossley ...\X Computations\Model
Designer: _Date: Tuesday, February 27, 2024 12:03 PM, Page: 1 SPACE GASS 14.12 (64-bit) - JOHN MULLEN & PARTNERS PTY LTD





SPACE GASS 14.12 (64-bit) - JOHN MULLEN && PARTNERS PTY LTD
Path: Z:__Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model
Designer: Date: Tuesday, February 27, 2024 12:02 PM, Page: 1

13 (SW) DL+0.7LL

Load case 13

SPACE



Structural Assessment Structural Consulting Engineering Services



Strength Assessment



Path: Z:__Frojects\4979-01 Cowpasture Road Bossley ...\X Computations\Model
Designer: __Date: Tuesday, February 27, 2024 12:04 PM, Page: 1 SPACE GASS 14.12 (64-bit) - JOHN MULLEN & PARTNERS PTY LTD





SPACE Gass 14.12 (64-bit) - JOHN MULLEN && PARTNERS PTY LTD
Path: Z:__Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model
Designer: Date: Tuesday, February 27, 2024 12:04 PM, Page: 1

10 (SW) 1.2DL+1.5LL
 11 (SW) 0.9DL+ Wu
 12 (SW) 1.2DL+ Wu

Load cases 10-12

(1) Strength







SPACE Gamma Figure 12 (64-bit) - JOHN MULLEN && PARTNERS PTY LTD
Path: Z:___Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model
Designer: Date: Tuesday, February 27, 2024 12:05 PM, Page: 1

10 (SW) 1.2DL+1.5LL 11 (SW) 0.9DL+ Wu 12 (SW) 1.2DL+ Wu

Load cases 10-12

(1) Strength







Path: Z:__Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model Designer: Date: Tuesday, February 27, 2024 12:05 PM, Page: 1 SPACE GASS 14.12 (64-bit) - JOHN MULLEN & PARTNERS PTY LTD



5 H3=125*75*6 UA

7 SP1=88.9*5 CHS 6 H1=50*4 SHS

8 H4=50*4 SHS

1 STEEL Materials:



SPECIALIST macTUE SPACE CASS 14.12 (64-bit) - JOHN MULLEN & PARTNERS PTY LTD Path: Z:____Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model Designer: Date: Tuesday, February 27, 2024 12:07 PM, Page: 1

Load case 5 5 (SW) G









SPACE GERMANT PROTOCE SPACE 52314.12 (64-bit) - JOHN MULLEN & PARTNERS PTY LTD Path: Z:___Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model Designer: Date: Tuesday, February 27, 2024 12:08 PM, Page: 1

SPACE

Load case 3







SPACE GERMANT PROTOCE SPACE 525 14.12 (64-bit) - JOHN MULLEN & PARTNERS PTY LTD Path: Z:___Projects\4979-01 Cowpasture Road Bossley ...\X Computations\Model Designer: Date: Tuesday, February 27, 2024 12:09 PM, Page: 1

Load case 4











Appendices

Appendix 1 Original Structural Design Drawings





500 02 mm 01 0 1 1 1 1 1 1 Imminud 001

200 mm

02:6 9002/0











-!

0648 156BC2503

Structural Assessment Structural Consulting Engineering Services

Appendix 2 Structural Condition Report



ADVERTISING SIGNAGE STRUCTURE

Cowpasture Road, Bossley Park – Inbound & Outbound

Structural Condition Report

21 AUGUST 2023



CONTACT



CHRIS SLATER Senior Engineer

T 02 8907 3942 M 0410 630 972 E chris.slater@arcadis.com Arcadis

Level 16, 580 George Street Sydney NSW 2000

OOH! MEDIA ADVERTISING SIGNAGE STRUCTURE

Cowpasture Road, Bossley Park – Inbound & Outbound - Structural Condition Report

Author	Chris Slater	Ch: Stater .
Checker	Michael Cheng	
Approver	Michael Cheng	
Report No	30110779	
Date	21/08/2023	
Revision Text	1	

This report has been prepared for oOh! Media in accordance with the terms and conditions of appointment for TfNSW Large Format Inspection Reports, dated 13/10/2021. Arcadis Australia Pacific Pty Limited (ABN 76 104 485 289) cannot accept any responsibility for any use of or reliance on the contents of this report by any third party.

REVISIONS

Date	Description	Prepared by	Approved by
21/08/23	First issue	CS	MC
	21/08/23	21/08/23 First issue	21/08/23 First issue CS

CONTENTS

1 INTRODUCTION	1
1.1 General	1
1.2 Site Visit	1 2
2 DESCRIPTION	
3 STRUCTURAL CONDITION & OBSERVATIONS	
4 RECOMMENDATIONS	10

1 INTRODUCTION

1.1 General

Arcadis Australia Pacific Pty Ltd (Arcadis) was engaged by oOh! Media to conduct a structural condition report on the advertising signage structure attached to the roof of the pedestrian bridge over Cowpasture Road, Bossley Park.



Figure 1 Locality Plan

1.2 Site Visit

Chris Slater of Arcadis visited the site on Thursday 17th August 2023. The purpose of this visit was to undertake a detailed inspection of the advertising signage structure from all accessible areas. The inspection was achieved using a safety harness and working at height precautions in accordance with Work Health and Safety Regulations 2017.

The weather at the time of the inspection was fine and sunny.

During this visit, information and photographs were recorded regarding the condition of the fixing components, framing members, protective surfacing, and other relevant material with respect to the performance of the signage structure. All caption comments are indicative, with the true condition record being the photographic record.

2 DESCRIPTION

The signage structure is commonly referred to as a double sided front lit 'Supersite', having a nominal display size of 12.660m long x 3.350m high.

The signage structure comprises a galvanised steel framed box structure with circular hollow section (CHS) legs. The legs penetrate the pedestrian bridge roof and are fully welded to the top of the main frames of the superstructure.



Photo 1 – Signage structure legs welded to bridge superstructure (circled).

The galvanised steel framed box structure is equipped with an upper and lower catwalk, providing the signage installers access to the top and bottom of the respective sign faces.

Both catwalks exceed minimum width requirements and are equipped with compliant handrails and kick rails (where required). A permanent fixed ladder located at each end of the catwalk, provides access between the gantry levels. The ends of the upper catwalk are only fitted with safety chains, which does not necessarily provide adequate fall protection.

Advertising Signage Structure



Photo 2 – General end view of signage structure

Three horizontal rails (75 x 75 SHS) are connected to the front face of the signage box structure via bolted through bolts. These rails support the respective sign faces, which comprise steel framed sheet metal (Colorbond) segments, commonly referred to as `signage pans`.

The `signage pans` are separate entities, nominally 1200mm wide for the full height of the advertising sign, providing a flat backing for the vinyl advertising skin to be attached. These elements are fixed to the horizontal rails via angle brackets, and `Tek` screws.

The signage structure is also equipped with four overhead cantilever floodlights that illuminate the front of the advertising sign.

Access to the signage structure is gained via a padlocked access hatch in the roof of the pedestrian bridge. This access hatch permits entry to a galvanised steel-framed landing equipped with handrailing. An eyebolt has been fitted adjacent to the access hatch, providing a strong point for attaching a harness lanyard for ingress and egress purposes.



Photo 3 – Secured access hatch in roof of pedestrian bridge.



Photo 4 – Lanyard attachment eyebolt (circled)

During the inspection no other obvious defects that might warrant further investigation were noticed. However, that does not preclude the possibility that other less obvious defects may exist and were concealed.

For the intent of this report Arcadis has assumed that the existing signage structure has been designed in accordance with relevant Australian codes/standards and is structurally adequate for its purpose.

Advertising Signage Structure



3 STRUCTURAL CONDITION & OBSERVATIONS

Generally, the signage structure is in a satisfactory condition (refer photos 6 to 9).







Photo 7 – General view of lower catwalk



Photo 8 – General view of upper catwalk



Photo 9 – Typical horizontal rail connection

However, there are some issues that need to be addressed.

The issues observed were:

• Minor surface corrosion to logo box support framing (both sides).



Photo 10 – Minor surface logo box support framing (west).



Photo 11 – Minor surface logo box support framing (east).

• Minor surface corrosion to vertical ladder support framing.



Photo 12 – Minor surface corrosion to vertical ladder support framing.

• Corroding nut to vertical ladder support framing.



Photo 13 – Corroding nut to vertical ladder support framing.

Advertising Signage Structure

• Deteriorating hatch strut.



Photo 14 – Deteriorating hatch strut.

• Trip hazards to top catwalk.



Photo 15 – Trip hazards to top catwalk (circled).

4 RECOMMENDATIONS

We would recommend that the surface corrosion be wire brush cleaned and treated with a proprietary cold galvanising paint at the next scheduled maintenance programme, to avoid further corrosion developing and potentially more costly remediation. This may involve the complete replacement of nuts and bolts.

The deteriorating hatch struts be replaced.

Elimination of the trip hazards would necessitate total redesign and fabrication of the signage structure – a significantly costly exercise. In lieu of replacing the structure, measures such as 'tiger tape' on the trip hazard and warning signs should be instated.

Arcadis would recommend that the signage structure be re-inspected every three (3) years from the date of this report.

