

LAKEMBA ST DEVELOPMENT PTY LTD




Hazardous Materials Survey

64-70 King Georges Road & 280-300 Lakemba
Street, Wiley Park NSW

Document Control

Report Title: Hazardous Materials Survey

Report No: E25377.E10_Rev0

Copies		Recipient	
1	Soft Copy (PDF – Secured, issued by email)	Mustapha Saboune Lakemba St Development Pty Ltd 102/209 Castlereagh Street, SYDNEY NSW 2000	
2	Original (Saved to Digital Archives)	EI Australia Suite 6.01, 55 Miller Street, PYRMONT NSW 2009	
Author		Technical Reviewer	
			
Nathan Spanos Environmental Scientist Licensed Asbestos Assessor (LAA001320)		Nikolce Aleksieski Environmental Scientist Occupational Hygienist Licensed Asbestos Assessor (LAA001430)	
Revision	Details	Date	Amended By
0	Original	1 November 2021	-

© 2021 EI Australia (EI) ABN: 42 909 129 957

This report is protected by copyright law and may only be reproduced, in electronic or hard copy format, if it is copied and distributed in full and with prior written permission by EI.

Table of Contents

	Page Number
EXECUTIVE SUMMARY	1
1. INTRODUCTION	2
1.1 Background and Purpose	2
1.2 Scope of Works	2
2. SITE DESCRIPTION	3
2.1 Property Identification and Location	3
2.2 Building Descriptions	3
3. GENERAL METHODOLOGY	7
3.1 Asbestos	7
3.2 Lead in Paint	7
3.3 Synthetic Mineral Fibres (SMF)	8
3.4 Polychlorinated Biphenyls (PCBs)	8
4. RISK ASSESSMENT	9
4.1 Friability	9
4.2 Condition	9
4.3 Accessibility	10
4.4 Priority Ratings	10
4.4.1 Asbestos and SMF ratings	10
4.4.2 Lead-based Paint and Polychlorinated Biphenyls	10
5. SUMMARY OF RESULTS	12
6. RECOMMENDATIONS	15
6.1 Asbestos	15
6.1.1 Asbestos Removal Control Plan	15
6.1.2 Asbestos Fibre Air Monitoring	16
6.1.3 Management of Asbestos Waste	16
6.1.4 Asbestos Clearance Inspection	16
6.2 Lead Paint	17
6.3 Synthetic Mineral Fibres	18
6.4 Polychlorinated Biphenyl Capacitors	18
7. STATEMENT OF LIMITATIONS	20

Schedule of Tables

Table 2-1	Site Identification and Location	3
Table 2-2	Building Descriptions	3
Table 5-1	Summary Hazardous Materials	12

Appendices

APPENDIX A - HAZARDOUS MATERIALS REGISTER

APPENDIX B - LABORATORY COC AND ANALYTICAL RESULTS

Executive Summary

Lakemba St Development Pty Ltd engaged EI Australia (EI) to conduct a Hazardous Materials Survey for the property located at 64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW (herein referred to as 'the site'). The purpose of this Hazardous Materials Survey is to present the findings of a qualitative risk assessment of the hazardous building materials located on the site. The site inspection was undertaken on 11th of October 2021.

This report has been developed to assist Lakemba St Development Pty Ltd with the preparation for the redevelopment of the site. EI understand that proposed redevelopment of the site shall involve the demolition of existing structures.

Key Findings

The overall status of each hazardous material type is tabulated below.

Site Name	ACM (friable)	ACM (Non-friable)	SMF	LBP	PCBs
280 Lakemba Street	No	Yes	Yes	Yes	Yes
282-284 Lakemba Street	No	No	No	No	No
286 Lakemba Street	No	Yes	No	No	Yes
288 Lakemba Street	No	Yes	Yes	Yes	No
288a Lakemba Street	No	No	Yes	No	Yes
290 Lakemba Street	No	Yes	Yes	No	Yes
64 King Georges Road	No	Yes	Yes	No	Yes
66 King Georges Road	No	Yes	Yes	No	Yes
68 King Georges Road	No	No	No	No	No
70 King Georges Road	No	Yes	Yes	No	Yes

Note 1 Hazardous materials may be present within any inaccessible area stated in the register in **Appendix A**.

Note 2 Both asbestos and non-asbestos fibre cement sheeting (FCS) were identified in the site buildings. Adopting the precautionary principle and in the absence of a more comprehensive sampling and analytical program, EI recommends that where there is doubt over the type of FCS being handled, it should be assumed as asbestos-containing.

All identified hazardous building materials were ranked **Priority 3 or Priority 4** (i.e. stable and posing negligible health risk under present conditions). No immediate remedial action was deemed necessary. Refer to **Appendix A** for the formal Hazardous Materials Register.

1. Introduction

1.1 Background and Purpose

EI Australia (EI) was engaged by Lakemba St Development Pty Ltd to conduct a Hazardous Materials Survey (HMS) for the site located at 64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW.

EI understand that proposed redevelopment of the site shall involve demolition of existing structures. As such, a HMS is required as part of the Development Application (DA) submission to Council prior to demolition works.

This report documents the findings of the HMS performed by EI, which involved inspection of the building on site for the presence of hazardous materials, sampling of potential hazardous materials, and subsequent laboratory analysis for the relevant hazardous substances. In addition, this report provides recommendations for the safe management of hazardous materials during demolition works.

1.2 Scope of Works

The aim of the HMS was to:

- Ascertain whether the buildings on site contained hazardous material(s), including;
 - Asbestos-containing materials (ACM);
 - Synthetic mineral fibre (SMF) materials;
 - Lead-based paint systems (LBP); and
 - Polychlorinated biphenyls (PCB) containing materials;
- Undertake a qualitative risk assessment of the hazardous materials contained within the buildings;
- Develop control strategies for the ongoing management of hazardous materials contained within the buildings;
- Identify and provide recommendations where remedial works are needed; and
- Prepare a report with the findings of the inspection, including the hazardous materials register and recommendations for the ongoing management or remedial works.

2. Site Description

2.1 Property Identification and Location

The site identification details and associated information are presented in **Table 2-1**.

Table 2-1 Site Identification and Location

Attribute	Description
Street Address	64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW
Location Description	Approx. 14.8km southwest of Sydney CBD, the site is bound by Lakemba Street (north), Residential dwellings (east), King Georges Road (west) and residential and commercial units (south).
Site Coordinates	Northeast corner of site (GDA2020-MGA56) Easting: 321442.428, Northing: 6244910.867 (Source: http://maps.six.nsw.gov.au)
Site Area	Approximately 5,900 m ²

2.2 Building Descriptions

A brief description of each building/structure inspected is located in **Table 2-2**.

Table 2-2 Building Descriptions

Description

280 Lakemba Street, Wiley Park

The property consists of a single storey residential building with a rear garage. The residential building contained two bedroom areas, kitchen, living and dining areas with a rear extension consisting of a secondary bathroom and laundry space. The rear garage was noted to be an open space.

The primary materials of construction for the residential building were brick and fibre cement external walls, brick and plasterboard internal walls, plasterboard ceilings, terracotta roofing and timber and concrete flooring. The rear garage was constructed with fibre cement external walls, terracotta roofing and concrete flooring.



282-284 Lakemba Street, Wiley Park

The lot consisted of an open car parking area with some stockpiled and overgrown vegetation.

The primary material of construction for the car park was asphalt flooring.



Description

286 Lakemba Street, Wiley Park

The property consists of a single storey residential building. The residential building contained one bedroom area, kitchen, living and dining areas with a rear extension consisting of the bathroom and laundry space.

The primary materials of construction for the residential building were brick and fibre cement external walls, brick and plasterboard internal walls, plasterboard ceilings, terracotta roofing and timber and concrete flooring.



288 Lakemba Street, Wiley Park

The property consists of a single storey residential building. The residential building contained multiple bedroom areas, kitchen, living area, bathroom and laundry and a dining area.

The primary materials of construction for the residential building were brick external walls, brick and fibre cement internal walls, plasterboard and fibre cement ceilings, terracotta roofing and timber and concrete flooring.



288a Lakemba Street, Wiley Park

The property consists of a single covered garage space to commercial business. The building contained a bathroom area, kitchen and open office space.

The primary materials of construction for the building were brick external walls, brick internal walls, plasterboard ceilings, terracotta roofing and concrete flooring.



Description

290 Lakemba Street, Wiley Park

The property consists of a single storey residential building. The residential building contained multiple bedroom areas, kitchen, living area, bathrooms, and dining area with a rear extension comprising of a bathroom and laundry area.

The primary materials of construction for the building were brick and fibre cement external walls, brick and fibre cement internal walls, plasterboard ceilings, terracotta roofing and timber and concrete flooring.



64 King Georges Road, Wiley Park

The property consists of multiple single storey commercial businesses and a single double storey commercial business.

Commercial businesses observed included Hadda House, Blazin Grillz, Sign Cam, and Dadous Videos (inaccessible). The primary materials of construction were brick external walls, brick and plasterboard internal walls, plasterboard ceilings, concrete and timber flooring and metal roofing.



Description

66 King Georges Road, Wiley Park

The property consists of two single storey commercial businesses.

Commercial businesses noted included White Heaven Turkish Cuisine and JJ's Newsagency. The primary materials of construction were brick external walls, brick and plasterboard internal walls, plasterboard ceilings, concrete and timber flooring and metal roofing.



68 King Georges Road, Wiley Park

The lot consisted of an open car parking area with noted overgrown vegetation.

The primary material of construction for the car park was asphalt flooring.



70 King Georges Road, Wiley Park

The property consists of a single storey commercial business.

The building consisted of multiple office areas, open walk in reception area, bathroom and kitchenette area. The primary materials of construction were brick external walls, brick and plasterboard internal walls, plasterboard and SMF tiled ceilings, concrete flooring and metal roofing.



3. General Methodology

The survey was conducted to identify the presence and condition of hazardous building materials within the site. For the purpose of this survey, hazardous building materials included:

- Asbestos containing materials (ACMs);
- Synthetic Mineral Fibre (SMF) insulation materials;
- Lead based paints (LBPs) applied to building surfaces; and
- Fluorescent light capacitor fittings, containing polychlorinated biphenyls (PCBs).

The scope of the survey was limited to inspection of the accessible building construction materials, including finishes and operational services, with the collection of representative samples suspected of containing a hazardous substance (listed above), where it was permissible to do so.

Due to the destructive nature of the sampling process or access constraints, it is not possible to collect samples of all (suspected) materials. Where it was not possible to collect a sample, the inspector used their professional experience to make a judgement on the status of the material, or area, concerned. Where the inspector believed the material could contain asbestos, LBP, SMF and/or PCB, this was recorded in the survey report and the corresponding material should be treated as hazardous.

3.1 Asbestos

This component of the survey was carried out in accordance with the guidelines documented in the SafeWork NSW (2019) *How to Manage and Control Asbestos in the Workplace* and SafeWork NSW (2019) *How to Safely Remove Asbestos*. Below are definitions of the two forms of asbestos.

Non Friable asbestos material

Non-friable (bonded) asbestos is any material that contains asbestos in a bonded matrix. It may consist of Portland cement or various resin/binders and cannot be crushed by hand when dry.

Friable asbestos material

Friable asbestos is any material that contains asbestos and is in the form of a powder or can be crumbled, pulverized or reduced to powder by hand pressure when dry.

Samples of suspected ACMs were laboratory analysed for their asbestos content (presence / absence), in accordance with Australian Standard AS4964-2004 *Method for the Qualitative Identification of Asbestos in Bulk Samples*. The reporting limit of the method was 0.1 g/kg. Refer to **Appendix B** for the laboratory documentation.

3.2 Lead in Paint

Painted surfaces were sampled and laboratory analysed for their lead (Pb) content. The sampling program was representative of the various types of paints found within the site, concentrating on areas where LBPs may have been used (e.g. exterior gloss paints, window and door architraves, skirting boards, etc.).

Australian Standard AS 4361.2-2017 *Guide to Lead Paint Management, Part 2: Lead Paint in Residential, Public and Commercial Buildings* defines LBP as a paint film or component coat of a paint system in which the lead content (calculated as lead metal) is in excess of 0.1% by weight of the dry film, as determined by laboratory testing. The NSW *Work Health and Safety*

Regulation 2017 currently defines a lead process as works on paint containing more than 1.0% by dry weight of lead. Refer to **Appendix B** for the laboratory documentation.

3.3 Synthetic Mineral Fibres (SMF)

This component of the survey was carried out in accordance with the guidelines documented in the Safe Work Australia *Code of Practice for the Safe Use of Synthetic Mineral Fibres* [NOHSC: 2006 (1990)]. This code broadly identifies SMF materials found or suspected of being present during the survey based on a visual assessment.

3.4 Polychlorinated Biphenyls (PCBs)

Where safe access was gained, detailed information of capacitors in light fittings and other electrical equipment were noted for cross-referencing with the Australian and New Zealand Environmental and Conservation Council (ANZECC, 1997) *Identification of PCB Containing Capacitors Information Booklet*. This document defines PCB materials and wastes as follows:

<2 mg/kg	- PCB free.
2 mg/kg - <50 mg/kg	- Non-Scheduled PCB material or waste.
>50 mg/kg	- Scheduled PCB material or waste.
>100,000 mg/kg (10%)	- Concentrated PCB material

Due to the inherent hazard in accessing electrical components, or other reasons such as height restrictions, immovable equipment and furniture, some light fittings may not be safely accessed. In these instances, comment was made on the likelihood of PCB-containing materials, based upon age and appearance.

4. Risk Assessment

The building located at 64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW was the subject of a Hazardous Materials Survey. The Hazardous Materials Register, presented in **Appendix A**, assesses the risks associated with each identified hazardous material. In order to assess the health risks associated with asbestos, LBP, SMF and PCBs the following must be considered:

- Product type;
- Friability of the material;
- Condition;
- Accessibility requirements for building and/or maintenance; and
- Exposed surface area;
- Surface treatment (if any).

The purpose of the material risk assessment is to establish the relative risk posed by specific hazardous building materials identified in this assessment. The following risk factors are defined to assist in determining the relative health risk posed by each item.

4.1 Friability

The friability of a material describes the ease by which the material can be crumbled, which in turn, can increase the release of fibres into the air. Therefore, friability is only applicable to asbestos and SMF.

- **Friable asbestos** can be crumbled, pulverised, or reduced to powder by hand pressure, which makes it more dangerous than non-friable asbestos.
- **Non-friable asbestos** is typically comprised of asbestos fibres tightly bound in a non-asbestos matrix. If accidentally damaged or broken these ACMs may release fibres initially but will not continue to do so.
- **Bonded SMF** describes a synthetic fibrous material which has a specific designed shape and exists within a stable manufactured product.
- **Un-bonded SMF** is a loosely packed synthetic fibrous material which has no adhesive or cementitious binding properties.
- **Friable lead based paints** exhibit signs of severe deterioration and crumbled, pulverised, or reduced to powder by hand pressure.
- **Non-friable lead based paints** have remained adhered to the surface and are not easily removed.

4.2 Condition

The condition of the hazardous building materials identified during the assessment is reported as being **good**, **fair** or **poor**.

- **Good** refers to a material that is in sound condition with no or very minor damage or deterioration.
- **Fair** refers to a material that is generally in a sound condition, with some areas of damage or deterioration.

- **Poor** refers to a material that is extensively damaged or deteriorated.

4.3 Accessibility

- **Regular:** in an occupied space of the building and accessible to all personnel using/entering the building.
- **Occasional:** buildings or rooms that are used infrequently.
- **Maintenance Only:** accessible to maintenance personnel only.

4.4 Priority Ratings

The risk elements above are used to rate the overall health risk posed by the presence of the hazardous materials:

4.4.1 Asbestos and SMF ratings

Priority 1: Immediate Risk Level

Materials which, due to their present condition and location, present an immediate health risk. The material and area surrounding should be isolated from personnel with remedial actions recommended to be undertaken at the earliest practicable time.

Priority 2: Elevated Risk Level

Damaged or unstable materials which present an elevated health risk if disturbed to personnel within the vicinity, and have potential for contamination to be spread to other areas. The material should be stabilised immediately, with remedial actions considered for the material.

Priority 3: Low Risk Level

Stable material that have minor areas of damage requiring remedial action or is likely to be subject to damage or to degrade due environmental conditions. It is recommended that maintenance work be performed to stabilise and repair damaged areas. Controls should be implemented to protect these materials from further damage or degrading factors.

Priority 4: Negligible Risk Level

Stable material that presents a negligible health risk unless damaged. These materials should be maintained in good condition. They should be reassessed prior to any works that will impact the material.

Inaccessible:

The location was not accessed during the survey and a priority rating could not be applied. Once a location is accessed, the priority rating should be reassessed prior to any works that will be undertaken in this location.

4.4.2 Lead-based Paint and Polychlorinated Biphenyls

Priority 1: Immediate Risk Level

Materials which, due to their present condition and location, present an immediate health risk. The material and area surrounding should be isolated from personnel with remedial actions recommended to be undertaken at the earliest practicable time.

Priority 2: Potential Risk Level

Damaged or unstable materials which present an elevated health risk if disturbed to personnel within the vicinity, and have the potential for contamination to be spread to other areas. The material should be stabilised to immediately, with remedial actions considered for the material.

Priority 3: Negligible Risk Level

Stable material that presents a negligible health risk unless damaged. These materials should be maintained in good condition. They should be reassessed prior to any works that will impact the material.

Inaccessible:

The location was not accessed during the survey and a priority rating could not be applied. Once a location is accessed, the priority rating should be reassessed prior to any works at will be undertaken in this location.

5. Summary of Results

Based on the inspection of the structural materials making up the building designated for demolition, the identified hazardous materials are indicated in **Table 5-1**. Handling recommendations and material specific work plans for the relevant hazardous materials are outlined in **Section 6**. Photographs of the identified materials are presented in the register in **Appendix A**.

Table 5-1 Summary Hazardous Materials

Building	Location	Material Description
280 Lakemba Street	Internal, kitchen, ceiling	Asbestos cement sheeting (assumed)
	Internal, kitchen ceiling, manhole covers	Asbestos cement sheeting (assumed)
	Internal, rear extension, bathroom, ceiling	Asbestos cement sheeting
	Internal, rear extension, laundry, infill panels	Asbestos cement sheeting (assumed)
	Internal, rear extension, rear walls	Asbestos cement sheeting
	External, garage, walls/gables and debris on soil surface	Asbestos cement sheeting
	External, rear extension, infill panels	Asbestos cement sheeting (assumed)
	External, garage, edge capping	Asbestos cement sheeting
	External, rear extension, roofing panels	SMF fibre glass
	External, rear western wall	SMF Insulation
	External, main building, patio ceiling	Yellow lead based paint
	Internal, garage, ceiling	PCB containing single tubed fluorescent light fitting(assumed)
286 Lakemba Street	External, main building, gable	Asbestos cement sheeting
	External, main building, eaves	Asbestos cement sheeting
	External, main building, eave ends	Asbestos cement sheeting
	External, rear extension walls	Asbestos cement sheeting (assumed)
	External, eastern wall, electrical unit	Asbestos backing board (assumed)
	Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)
288 Lakemba Street	Internal, rear laundry room, northern wall	Asbestos cement sheeting
	Internal, kitchen, lower western wall	Asbestos cement sheeting
	External, eaves and patio ceiling	Asbestos cement sheeting
	External, western wall, electrical unit	Asbestos backing board (assumed)

Building	Location	Material Description
288a Lakemba Street	External, rear western wall	SMF insulation
	External, window sills	White lead based paint
	Internal, ceiling cavity	SMF Insulation
	External, upper wall	PCB containing single tube fluorescent light fittings (assumed)
290 Lakemba Street	External, eaves	Asbestos cement sheeting
	Internal, rear extension, walls	Asbestos cement sheeting
	Internal, bathroom, beneath sink, flooring	Asbestos vinyl floor tiles
	Internal, bathroom, shaving cabinet backing	Asbestos cement sheeting
	External, western wall, electrical unit lining	Asbestos backing board (assumed)
	External, western wall	SMF Insulation
	Internal, ceiling	PCB containing single & double tube fluorescent light fittings (assumed)
64 King Georges Road	Blazin Grillz – Internal entrance adjacent stairs to second floor, electrical unit	Asbestos backing board (assumed)
	Blazin Grillz – Internal, dining area, electrical unit	Asbestos backing board (assumed)
	Sign Com – Internal, ground floor, electrical unit	Asbestos backing board (assumed)
	External – awnings across building	Asbestos cement sheeting (assumed)
	Blazin Grillz– Internal, void above fridge room	SMF Insulation
	Blazin Grillz– Internal, ceiling cavity	SMF Insulation
	Blazin Grillz – Internal, second floor, wash room	SMF Insulation
	Blazin Grillz – Internal, second floor, ceiling cavity	SMF Insulation
	Hadda House – Internal, kitchen area	SMF Insulation
	Blazin Grillz – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)
	Sign Com – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)
	Hadda House – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)

Building	Location	Material Description
66 King Georges Road	White Heaven Turkish Cuisine – External, rear yard, loose panelling	Asbestos cement sheeting
	White Heaven Turkish Cuisine – Internal, rear bathroom, ceiling	Asbestos cement sheeting (assumed)
	White Heaven Turkish Cuisine – External awning	Asbestos cement sheeting (assumed)
	JJs Newsagency – External, rear patio ceiling	Asbestos cement sheeting (assumed)
	White Heaven Turkish Cuisine – Internal, rear laundry, ceiling	SMF Insulation
	White Heaven Turkish Cuisine – Internal, rear laundry	SMF Insulation
	White Heaven Turkish Cuisine – External, rear yard	SMF Insulation
	JJs Newsagency – Internal roof cavity	SMF Insulation
	White Heaven Turkish Cuisine – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)
	JJs Newsagency – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)
70 King Georges Road	Internal, south-western office area, flooring	Asbestos vinyl floor tiles
	External, eaves	Asbestos cement sheeting (assumed)
	Internal, ceiling cavity, membrane	SMF Insulation
	Internal, bathroom	SMF Insulation
	Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)

Note 1 Hazardous materials may be present within any inaccessible area stated in the register in **Appendix A**.

Note 2 Both asbestos and non-asbestos fibre cement sheeting (FCS) were identified in the site buildings. Adopting the precautionary principle and in the absence of a more comprehensive sampling and analytical program, EI recommends that where there is doubt over the type of FCS being handled, it should be assumed as asbestos-containing.

6. Recommendations

6.1 Asbestos

Asbestos materials should be removed prior to the commencement of any demolition works that may cause their disturbance. The removal of these materials is to be done in accordance with *NSW Work Health and Safety Act and Regulations 2017* and the following SafeWork NSW approved codes of practice:

- SafeWork NSW (2019) *How to Manage and Control Asbestos in the Workplace*; and
- SafeWork NSW (2019) *How to Safely Remove Asbestos*

The asbestos removal works require a minimum Class B licenced asbestos removal contractor. Should friable asbestos be identified during additional inspections and/or be created as a result of poor demolition practice the asbestos removal works would require a Class A asbestos removal licence. A notification must be made to SafeWork NSW five calendar days prior to undertaking any licenced asbestos removal work. This must be completed by the appointed asbestos removal contractor. At the completion of asbestos removal works a clearance certificate is required.

The following recommendations must be observed as minimum requirements during the removal of all ACM.

- The work area should be barricaded and appropriate signage installed.
- The ACM should be sealed or wetted with water.
- ACM should be removed with minimal breakage and where applicable, should be lowered to the ground not dropped.
- Where ACMs are too large to fit into an asbestos labelled waste bag, the ACM should be stacked or placed on a 200µm plastic ground sheet or lined skip bin and not allowed to lie about the site where they may be further broken or crushed by machinery or workers.
- Asbestos waste is to be securely packaged and labelled. Asbestos waste bags are to be double bagged while ACM in polythene sheeting should be double wrapped with adhesive tape applied to the entire length of every overlap to secure materials to minimise the risk of the polythene sheeting tearing or splitting.
- Any dust and/or ACM debris remaining around the removal area should be cleaned up using an approved "H" type HEPA vacuum cleaner.
- All asbestos containing waste is to be disposed at an approved disposal facility (contact local council or SafeWork NSW for nearest asbestos waste facility).

Where asbestos is to be removed, the licenced asbestos removal contractor should prepare an asbestos removal control plan prior to undertaking any removal works.

6.1.1 Asbestos Removal Control Plan

A site-specific Asbestos Removal Control Plan (ARCP) must be prepared by the Asbestos Removalist Contactor to document the management measures required to address the risks associated with potential exposure to asbestos. The ARCP must cover:

- Work area isolation (barrier protection, buffer zone);
- Removal methods (friable/non-friable);

- Contamination control methods (decontamination procedures); and
- Health and safety procedures (respiratory protection).

Asbestos removal works at the site, including the disturbance of any asbestos-impacted soils, must be managed strictly in accordance with the ARCP.

6.1.2 Asbestos Fibre Air Monitoring

There is no requirement to undertake asbestos fibre air monitoring during the removal of the non-friable asbestos materials on the boundary of the work areas. However as a matter of due diligence asbestos fibre air monitoring is recommended to be undertaken on the boundary of the work areas. Asbestos fibre air monitoring is required during friable asbestos removal works if identified. Asbestos fibre air monitoring is required to be undertaken by a company independent of the demolition and /or asbestos removal company. The asbestos fibre air monitoring should be undertaken by a company that is NATA (National Association of Testing Authorities) accredited.

6.1.3 Management of Asbestos Waste

The transportation and management of asbestos waste must be carried out in accordance with Part 7 of the *Protection of the Environment Operations (Waste) Regulation 2014*, which includes:

- Appropriate packaging, sealing, covering and/or wetting of the waste, as is required for the form of the asbestos contamination (i.e. bonded asbestos, friable asbestos or asbestos-contaminated soil);
- Reporting on transportation of asbestos waste by the transporter to the NSW EPA as required under Part 7, Section 79 of the *Waste Regulation 2014*; and

Disposal to an appropriately licensed (i.e. lawful) premises, with proper advice to the occupier of the premises, while incorporating measures for the prevention of dust generation, in accordance with Part 7, Section 80 of the *Waste Regulation 2014*.

Any ACM removed from the site should be tracked from the time of their removal from the structure until their disposal. Tracking of all ACM should be completed on the EPAs WasteLocate system. This system will require all details of the ACM to be transported, including but not limited to:

- Origin of material;
- Material type;
- Approximate volume; and
- Truck registration number.

Disposal locations will be determined by the remediation contractor. Disposal location, waste disposal documentation (i.e. weighbridge dockets, trip tickets and consignment disposal confirmation) and the above listed information should be provided to the remediation consultant for reporting purposes.

6.1.4 Asbestos Clearance Inspection

Under Clause 473 of the *NSW Work Health and Safety Regulation 2017*, a clearance inspection is required following the removal of any ACM by a competent person. A clearance inspection is to be carried out and a clearance certificate issued before the area can be re-occupied. The company undertaking the clearance inspection should be independent of the demolition and / or asbestos removal company.

6.2 Lead Paint

Site structures should be managed in accordance with the procedures detailed in the following references:

- Australian Standard AS 4361.2-2017 *Guide to Lead Paint Management, Part 2: Lead Paint in Residential, Public and Commercial Buildings*;
- NOHSC (1994a) *National Standard for the Control of Inorganic Lead at Work*; and
- NOHSC (1994b) *National Code of Practice for the Control and Safe Use of Inorganic Lead at Work*.

There are currently no legislative requirements for the general removal of stable lead-containing painted materials for structures remaining *in situ*.

The following recommendations must be observed as a minimum requirement when working with lead paint to reduce the potential for lead dust exposure.

- LBPs on structures otherwise from residential premises, educational or child care institutions are to be removed from all surfaces prior to demolition.
- Lead paint waste arising otherwise from residential premises, educational or child care institutions has been pre-classified as *Hazardous Waste* under the NSW EPA (2014) *Waste Classification Guidelines*.
- All building materials with lead paint are to be disposed as *Hazardous Waste*, unless the lead paint is removed prior to demolition.
- Wear an approved (Australian Standard AS1716) half face respirator or dust mask with a 'P2' (dust and fumes) protection rating if working directly with materials coated with lead paint during the demolition works.
- Wear work clothes that do not catch dust or flakes in pockets or cuffs. Consider using disposable overalls.
- Use an industrial vacuum cleaner fitted with High Efficiency Particulate Air (HEPA) filters for dust and debris clean up.
- When working on lead paint surfaces:
 - Use heavy-duty plastic sheeting to seal off work areas and collect debris;
 - Place a plastic drop sheet under the area to be worked upon (ensuring it extends a minimum of two metres from the base of the wall or structure and an extra metre for each storey being worked on (consider height and use more plastic if needed));
 - Fold the edge of the plastic nearest the wall and/or structure and secure it with tape, in order to prevent any dust falling between the edge of the plastic and the wall or structure; and
 - Fold and brace external edges of the plastic drop sheet.
- Wet any lead paint surface to be sanded or cut. Use water sparingly and do not spray water on power tools (e.g. drills). Wet the wall or structure to dampen down for dust control.
- Do not use open flame burners on lead paint.

- At the completion of the works, plastic sheeting used during lead paint removal is to be folded and sealed to ensure the materials are contained within the plastic sheeting.

The *NSW Work Health and Safety Regulation 2017* require that a person conducting a business or undertaking (PCBU) must notify SafeWork NSW of any lead risk work being undertaken. The PCBU must assess each lead process to determine whether lead risk work is being carried out. If a PCBU cannot determine whether lead risk work is being carried out, then the process is taken to include lead risk work until it can be determined that lead risk work is not being undertaken. A notification of lead risk work form must be submitted to SafeWork NSW at least seven days before lead work begins. These forms are available on the SafeWork NSW website and lodgement instructions are listed on the forms.

6.3 Synthetic Mineral Fibres

SMF materials should be removed during any demolition works that may cause their disturbance. SMF materials must be handled and removed in accordance with the *NSW Work Health and Safety Regulation 2017* and the *Safe Work Australia Synthetic Mineral Fibres National Standard* (NOHSC:1004) and *National Code of Practice* (NOHSC:2006).

The following guidance documents should be consulted for guidance regarding removal and disposal of SMF:

- *National Standard for the Safe Use of Synthetic Mineral Fibres* [NOHSC:1004 (1990)];
- *National Code of Practice for the Safe Use of Synthetic Mineral Fibres* [NOHSC:2006 (1990)]; and
- *Code of Practice for the Safe Use of Synthetic Mineral Fibres* (NOHSC, 1993).

These documents should be referred to for the disposal SMF materials. Under the EPA (2014) *Waste Classification Guidelines*, “synthetic fibre waste from materials such as fibreglass, polyesters and other plastics, being waste that is packaged securely to prevent dust emissions, but excluding asbestos waste which is a special waste”, is pre-classified as *General Solid Waste (Non Putrescible)*.

6.4 Polychlorinated Biphenyl Capacitors

All metal-cased capacitors, including fluorescent light fittings, should be assumed as containing PCBs. Any leaking PCB-containing capacitors identified should be removed and disposed prior to the commencement of any demolition works that may cause their disturbance.

The following recommendations must be observed when removing / handling PCB containing capacitors.

- Small quantities of PCBs are usually found in sealed containers known as capacitors. PCB-containing capacitors are unlikely to pose a health risk unless they become damaged and leak. Care must be taken when handling a damaged capacitor to ensure that spillage does not occur.
- The person handling any (damaged) capacitor should use disposable gloves. Wear gloves that are made of materials that are resistant to PCBs, such as Viton, polyethylene, polyvinyl alcohol (PVA), polytetrafluoroethylene (PTFE), butyl rubber, nitrile rubber or neoprene. Mid-arm length gauntlets may be required. Do not use gloves made of polyvinyl chloride (PVC) or natural rubber (latex).
- Wear disposable overalls made of Tyvek or materials with similar chemical resistant properties.

- When working with overhead equipment (e.g. fluorescent light fixtures), wear a full face shield and appropriate hair protection.
- Wash any non-disposable contaminated equipment with kerosene and collect the kerosene for disposal as a PCB-contaminated waste.
- PCB-containing equipment (capacitors, ballasts, etc.) is to be placed in a polyethylene bag, which then is to be placed in a sealable metal container. This container must be clearly marked with the details of the contents and must be maintained in good order (that is, no visible signs of damage or corrosion). If some of these materials are leaking, the container should be partially filled with an absorbent material, such as a commercial absorbent, kitty litter or a diatomaceous earth. The plastic wrapped leaking components can then be placed in the container.
- If PCB vapours are suspected (e.g. PCB leaks onto a hot surface in a confined space), wear a suitable respirator. Use a cartridge respirator suitable for chlorinated vapours. It is always prudent to ensure adequate ventilation. NOTE: PCBs do not vaporise readily at room temperature.
- Do not smoke while handling PCB capacitors.
- After handling PCBs, even if gloves were worn, wash hands well in warm, soapy water before eating, drinking, smoking, handling food or drink, or using toilet facilities.

PCB capacitors are to be disposed at a licenced waste facility. If PCB concentration is above the threshold concentration for PCBs scheduled waste (i.e. >50mg/kg), the waste must be also be transported by a suitably licenced contractor. For further details on this, contact the NSW EPA.

7. Statement of Limitations

This report has been prepared by EI Australia (EI) pursuant to EI Australia's Terms and Conditions.

The report is for the sole use by Lakemba St Development Pty Ltd. No responsibility is accepted for the use of any part of this report in any other context or for any other purpose or by other third parties. This report does not purport to provide legal advice. This report is prepared in response to specific instructions from Lakemba St Development Pty Ltd.

Unless otherwise stated in this report, the survey evaluates the presence of hazardous materials in/on the building(s) of the identified site, and excludes buried waste materials, contaminated dusts, and soils. The findings presented in this report are the result of a site walkover inspection, sampling, laboratory analysis, interviews with site personnel, and review of any documentation provided to EI. To the best of EI's knowledge, and in view of these limitations, the findings presented in this report represent a reasonable interpretation of the building materials on the site at the time of investigation.

This report relies upon data, surveys, measurements, and/or results taken at, or under, the particular times and conditions specified in this report. Any conclusions or recommendations only apply to the findings at that particular time.

EI is not a professional quantity surveyor (QS) organisation. Any areas, volumes, tonnages or any other quantities noted in this report are indicative estimates only. The services of a professional QS organisation should be engaged if quantities are to be relied upon.

The report should not be separated or reproduced in part, and EI should be retained to assist other professionals who may be affected by the issues addressed in this report to ensure the report is not misused in any way. In the interests of Work Health and Safety, and in the absence of a comprehensive testing program, EI recommends that where there is doubt over the composition of any suspect material, it should be assumed to contain asbestos until verified otherwise by appropriate analysis.

This report must be read in its entirety, and must not be copied, distributed or referred to in part. This report is not intended to be used for the purpose of tendering, preparation of costing or budgets, programming of works, refurbishment works or demolition works, unless expressly stated. The report must not be reproduced without the written approval of EI.

This report was conducted by trained personnel who have exercised reasonable care, skill and diligence. However, except for any non-excludable statutory provision, EI gives no warranty in relation to its services or the report, and is not liable for any loss, damage, injury or death suffered by any party (whether caused by negligence or otherwise) arising from or relating to the services or the use or otherwise of this report. All conclusions and recommendations made in this report are of the professional opinions of EI personnel involved with the project, and while normal checking of the accuracy of data has been conducted, any circumstances outside the scope of this report, or which are not made known to EI personnel, and which may impact on those opinions, are not the responsibility of EI.

Inaccessible areas

It is noted that given the constraints of practicable access encountered during the HMS, the following areas were not accessed or inspected:

- Wall cavities and set ceilings;

- Fire doors;
- Ceiling voids;
- Within those areas accessible only by dismantling equipment;
- Concealed within the building structure;
- Within voids or internal areas of plant, equipment, air-conditioning ducts, etc;
- Energised services, gas, electrical, and pressurised vessels;
- Areas deemed unsafe or hazardous at time of inspection;
- Within totally inaccessible areas such as voids and cavities created and intimately concealed within the building structure. These voids are only accessible during major demolition works; and
- Height restricted areas, including building roof areas.


Should demolition operations entail disturbance of materials in these locations, further investigation and sampling of specific areas should be conducted as part of an asbestos and lead management and abatement program, as per 'AS 2601-2001: The Demolition of Structures', prior to any works proceeding.

Appendix A - Hazardous Materials Register





Table A.1 Key and Explanatory Notes to Hazardous Building Material Register

Column Heading	Description
Location	A detailed description of the location of the hazardous building material relevant to this entry.
Material Type	<p>The specific hazardous building material type, e.g.</p> <p>Asbestos: asbestos cement sheet corrugated asbestos cement sheet, vinyl asbestos tiles, etc.</p> <p>SMF: foil backed SMF, compressed SMF ceiling tiles, SMF insulation to upper surface of ceiling, etc.</p> <p>Paint: Beige coloured lead-based paint system.</p> <p>PCB: Metal case capacitor 'Plessey 6.5 μF Type APF 265CR'.</p> <p><i>If inaccessible areas are noted, any of the above material types may be present.</i></p>
Friability	If the material can be crushed to a powder by hand pressure.
Sample	Sample Reference number allocated to the sample collected from this asbestos containing material
Results	Laboratory analytical results. Refer to Appendix B for laboratory analytical reports.
Quantity	The approximate quantity of hazardous building material relevant to this location. Depending on the nature of the material, the quantity is given as an area (m^2), length (m), number of pieces/units or not determined (ND).
Condition	<p>Good: good and stable condition.</p> <p>Fair: early signs of deterioration or localised areas of damage. For PCB capacitors this would include evidence of seals deteriorating.</p> <p>Poor: the material is in poor condition and remedial action is required, e.g. deteriorated friable asbestos materials, capacitors are leaking, etc.</p> <p>Unknown: the area was inaccessible</p>
Accessibility	<p>Regular: in the occupied space of the building and accessible to all personnel using/entering the building.</p> <p>Occasional: buildings or rooms that are used infrequently.</p> <p>Maintenance Only: accessible to maintenance personnel only.</p> <p>Inaccessible: the area was not able to be accessed during the inspection</p>
Risk Rating	<p>The allocated priority rating for this entry, refer Section 4.4.</p> <p>If the location was not accessible the risk rating is not able to be determined and shall be listed as inaccessible.</p>
Recommendations	Recommended actions for demolition works or damaged material.
Photograph	Photograph of location where sample was taken.




Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
280 Lakemba Street									
Inaccessible/Limited Access									
Internal, subfloor and ceiling spaces	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
Internal, bathroom, walls	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due to floor to ceiling tiled walls. When areas are accessible, confirm status of hazardous materials.	
Asbestos									
Internal, kitchen, ceiling	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection	-	4m ²	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Internal, kitchen ceiling, manhole covers	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection	-	2x units	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	No photograph taken during time of inspection
Internal, rear extension, bathroom, ceiling	Asbestos cement sheeting	Non-friable	Asb03	Amosite & Chrysotile Asbestos Detected	1m ²	Good Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

Internal, rear extension, laundry, infill panels	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection similar to Asb03	-	5m ²	Good Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Internal, rear extension, rear walls	Asbestos cement sheeting	Non-friable	Asb04	Amosite & Chrysotile Asbestos Detected	5m ²	Good Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External, garage, walls/gables and debris on soil surfaces	Asbestos cement sheeting	Non-friable	Asb05	Amosite & Chrysotile Asbestos Detected	40m ²	Fair-poor Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External, rear extension, infill panels	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection similar to Asb05	-	5m ²	Good-fair Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW


External, garage, edge capping	Asbestos cement sheeting	Non-friable	Asb06	Amosite & Chrysotile Asbestos Detected	1m ²	Good-fair Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Internal, rear extension, storage room adjacent kitchen, infill panel	Fibre cement sheeting	N/A	Asb01	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A	
Internal, rear extension, storage room adjacent kitchen, infill panel – mid portion	Fibre cement sheeting	N/A	Asb02	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A	
SMF									
External, rear extension, roofing panels	SMF fibre glass	Non-friable	Visual Inspection	-	Throughout rear extension roof	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
External, rear western wall	SMF Insulation	Non-friable	Visual Inspection	-	1x hot water unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

Paints




External, main building, patio ceiling	Yellow lead based paint	N/A	Pb02	25%w/w	ND	Fair Maintenance only	Priority 3: Low Risk under Present Conditions	Remove any grossly peeling paint and stabilise remaining paint membrane. Minimise abrasive works that will disturb paint during demolition.	
Internal and external, throughout	White paint	N/A	Pb01	0.034%w/w	N/A	N/A	N/A	N/A	

PCBs




Internal, garage, ceiling	PCB containing single tubed fluorescent light fitting(assumed)	N/A	Visual Inspection	-	1 unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
---------------------------	--	-----	-------------------	---	--------	-----------------------	-----------------------------------	----------------------------------	--


Hazardous Materials Register									
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW									
Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
282-284 Lakemba Street									
Asbestos									
No asbestos containing materials were identified	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
SMF									
No SMF containing materials were identified	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Paints									
No lead based paints were identified	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
PCBs									
No PCB containing materials were identified	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW


Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
286 Lakemba Street									
Inaccessible/Limited Access									
Internal, subfloor and ceiling spaces	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
Asbestos									
External, main building, gable	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection	-	5m ²	Good Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External, main building, eaves	Asbestos cement sheeting	Non-friable	Asb07	Chrysotile Asbestos Detected Organic Fibres Detected	5m ²	Good Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External, main building, eave ends	Asbestos cement sheeting	Non-friable	Asb08	Amosite & Chrysotile Asbestos Detected Organic Fibres Detected	<1m ²	Good Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW





External, rear extension walls	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection similar to Asb05	-	10m ²	Good Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External, eastern wall, electrical unit	Asbestos backing board (assumed)	Non-friable	Visual Inspection	-	1x unit	Good Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Internal, dining room ceiling, adjacent to kitchen	Fibre cement sheeting (Assumed)	N/A	Visual Inspection	-	20m ²	Good Regular	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Internal, front storage room, western wall	Fibre cement sheeting	N/A	Asb09	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A	
Internal, front bedroom, eastern wall wardrobe	Fibre cement sheeting	N/A	Visual Inspection similar to Asb09	-	5m ²	N/A	N/A	N/A	
Internal, rear extension, western bathroom walls	Fibre cement sheeting	N/A	Asb10	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A	

Hazardous Materials Register 64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW									
Internal, rear extension, laundry walls and ceiling	Fibre cement sheeting	N/A	Asb11	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A	
SMF									
Internal and external, throughout	No synthetic mineral fibres were identified	N/A	Visual inspection	N/A	N/A	N/A	N/A	N/A	
Paints									
Internal, front storage room	Light blue paint	N/A	Pb03	0.015% w/w	Throughout	N/A	N/A	N/A	
PCBs									
Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)	N/A	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4 - Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
288 Lakemba Street									
Inaccessible/Limited Access									
Internal, subfloor and ceiling spaces	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
Internal, bathroom, walls	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due to floor to ceiling tiled walls. When areas are accessible, confirm status of hazardous materials.	
Asbestos									
Internal, rear laundry room, northern wall	Asbestos cement sheeting	Non-friable	Asb12	Amosite & Chrysotile Asbestos Detected Organic Fibres Detected	8m ²	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Internal, kitchen, lower western wall	Asbestos cement sheeting	Non-friable	Asb13	Chrysotile Asbestos Detected	10m ²	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	



Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

External, eaves and patio ceiling	Asbestos cement sheeting	Non-friable	Asb14	Amosite & Chrysotile Asbestos Detected	30m ²	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External, western wall, electrical unit	Asbestos backing board (assumed)	Non-friable	Visual Inspection	-	1x unit	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
SMF									
External, rear western wall	SMF Insulation	Non-friable	Visual Inspection	-	1x hot water unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
Paints									
External, window sills	White lead based paint	N/A	Pb04	0.14% w/w	Throughout	Fair-poor Maintenance only	Priority 4: Negligible Risk Level	Remove any grossly peeling paint and stabilise remaining paint membrane. Minimise abrasive works that will disturb paint during demolition.	




Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

PCBs									
No PCB containing materials were identified	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	



Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
288a Lakemba Street									
Asbestos									
No asbestos containing materials were identified	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
SMF									
Internal, ceiling cavity	SMF Insulation	Non-friable	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
Paints									
No lead based paints were identified	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
PCBs									
External, upper wall,	PCB containing single & double tube fluorescent light fittings (assumed)	N/A	Visual inspection	-	approx. 7 units	Good	Good Maintenance Only	Priority 4 - Negligible Risk Level	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW


Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
290 Lakemba Street									
Inaccessible/Limited Access									
Internal, subfloor and ceiling spaces	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
Asbestos									
External, eaves	Asbestos cement sheeting	Non-friable	Asb17	Chrysotile Asbestos Detected Organic Fibres Detected	5m ²	Good-fair Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Internal, rear extension, walls	Asbestos cement sheeting	Non-friable	Asb18	Amosite & Chrysotile Asbestos Detected	30m ²	Good-fair Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Internal, bathroom, beneath sink, flooring	Asbestos vinyl floor tiles	Non-friable	Asb20	Chrysotile Asbestos Detected	0.5m ²	Good-fair Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

Internal, bathroom, shaving cabinet backing	Asbestos cement sheeting	Non-friable	Asb21	Chrysotile Asbestos Detected	0.1m ²	Good-fair Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External, western wall, electrical unit lining	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection	-	1m ²	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External, rear extension, infill panels	Fibre cement sheeting	N/A	Asb15	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A	
External, rear patio, ceiling	Fibre cement sheeting	N/A	Asb16	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A	
Internal, rear extension, bathroom ceiling	Fibre cement sheeting	N/A	Asb19	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A	
Internal, rear extension, flooring	Vinyl floor tiles	N/A	Asb22	No Asbestos Detected	N/A	N/A	N/A	N/A	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW


SMF



External, western wall	SMF Insulation	Non-friable	Visual Inspection	-	1x hot water unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
------------------------	----------------	-------------	-------------------	---	-------------------	-----------------------	-----------------------------------	----------------------------------	---




Paints





Internal, second level, walls and ceiling	White paint	N/A	Pb05	0.078% w/w	N/A	N/A	N/A	N/A	
---	-------------	-----	------	------------	-----	-----	-----	-----	--

PCBs

Internal, ceiling	PCB containing single & double tube fluorescent light fittings (assumed)	NA	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4 - Negligible Risk Level	Remove prior to demolition works	
-------------------	--	----	-------------------	---	------------	-----------------------	------------------------------------	----------------------------------	--

Hazardous Materials Register									
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW									
Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
64 King Georges Road									
Inaccessible/Limited Access									
Sign Com – Internal, ceiling and sub-floor space	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
Hadda House – Internal, ceiling and sub-floor space	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
Dadous Videos – Internal, ceiling and sub-floor space	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection. No keys made available to enter premises. When areas are accessible, confirm status of hazardous materials.	
Asbestos									
Blazin Grillz – Internal entrance adjacent stairs to second floor, electrical unit	Asbestos backing board (assumed)	Non-friable	Visual Inspection	-	1x unit	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Blazin Grillz – Internal, dining area, electrical unit	Asbestos backing board (assumed)	Non-friable	Visual Inspection	-	1x unit	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register									
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW									
Sign Com – Internal, ground floor, electrical unit	Asbestos backing board (assumed)	Non-friable	Visual Inspection	-	1x unit	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External – awnings across building	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection	-	40m ²	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
Hadda House – Internal, dining area, infill panels	Fibre cement sheeting	N/A	Asb28	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A	
SMF									
Blazin Grillz– Internal, void above fridge room	SMF Insulation	Non-friable	Visual Inspection	-	1x hot water unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register 64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW									
Blazin Grillz– Internal, ceiling cavity	SMF Insulation	Non-friable	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
Blazin Grillz – Internal, second floor, wash room	SMF Insulation	Non-friable	Visual Inspection	-	1x hot water unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
Blazin Grillz – Internal, second floor, ceiling cavity	SMF Insulation	Non-friable	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
Hadda House – Internal, kitchen area	SMF Insulation	Non-friable	Visual Inspection	-	1x hot water unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	


Paints





No lead based paints were identified





Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

PCBs


Blazin Grillz – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)	N/A	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4 - Negligible Risk Level	Remove prior to demolition works	
Sign Com – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)	N/A	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4 - Negligible Risk Level	Remove prior to demolition works	
Hadda House – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)	N/A	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4 - Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register 64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW									
Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
66 King Georges Road									
Inaccessible/Limited Access									
JJs Newsagency – Internal, subfloor and ceiling spaces	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
White Heaven Turkish Cuisine – Internal, subfloor and ceiling spaces	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
JJs Newsagency – Electrical Unit	Asbestos backing board (assumed)	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Unable to be identified at time of investigation When areas are accessible, confirm status of hazardous materials.	
White Heaven Turkish Cuisine – Electrical Unit	Asbestos backing board (assumed)	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Unable to be identified at time of investigation When areas are accessible, confirm status of hazardous materials.	
Asbestos									
White Heaven Turkish Cuisine – External, rear yard, loose panelling	Asbestos cement sheeting	Non-friable	Asb27	Chrysotile Asbestos Detected Organic Fibres Detected	<1m ²	Fair Maintenance only	Priority 4 - Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register									
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW									
White Heaven Turkish Cuisine – Internal, rear bathroom, ceiling	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection similar to Asb27	-	1m ²	Fair-poor Maintenance only	Priority 3 - Negligible Risk under present conditions	Remove prior to demolition works	
White Heaven Turkish Cuisine / JJ Newsagency – External awning	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection	-	40m ²	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
JJs Newsagency – External, rear patio ceiling	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection	-	5m ²	Good Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
SMF									
White Heaven Turkish Cuisine – Internal, rear laundry, ceiling	SMF Insulation	Non-friable	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	



Hazardous Materials Register 64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW									
White Heaven Turkish Cuisine – Internal, rear laundry	SMF Insulation	Non-friable	Visual Inspection	-	1x hot water unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
White Heaven Turkish Cuisine – External, rear yard	SMF Insulation	Non-friable	Visual Inspection	-	1x hot water unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
JJs Newsagency – Internal roof cavity	SMF Insulation	Non-friable	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
Paints									
No lead based paints were identified									
PCBs									
White Heaven Turkish Cuisine – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)	N/A	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4 - Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

JJs Newsagency – Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)	N/A	Visual Inspection	-	Throughout	Good Maintenance Only	Priority 4 - Negligible Risk Level	Remove prior to demolition works	
------------------------------------	---	-----	-------------------	---	------------	-----------------------	------------------------------------	----------------------------------	---

Hazardous Materials Register									
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW									
Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
68 King Georges Road									
Asbestos									
No asbestos containing materials were identified									
SMF									
No SMF containing materials were identified									
Paints									
No lead based paints were identified									
PCBs									
No PCB containing materials were identified									



Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

Location	Material Type	Friability	Sample	Analysis Result:	Quantity	Condition and Accessibility	Priority	Recommendations/ Comments	Photograph of material
70 King Georges Road									
Inaccessible/Limited Access									
Internal, subfloor and ceiling spaces	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
External, awning	Potential hazardous materials	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Inaccessible at time of inspection due confined space safety concerns. When areas are accessible, confirm status of hazardous materials.	
Electrical Unit	Asbestos backing board (assumed)	Unknown	Inaccessible	N/A	Not determined	Unknown Maintenance only	Unknown	Unable to be identified at time of investigation When areas are accessible, confirm status of hazardous materials.	
Asbestos									
Internal, south-western office area, flooring	Asbestos vinyl floor tiles	Non-friable	Asb26	Chrysotile Asbestos Detected	0.5m ²	Good-fair Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	
External, eaves	Asbestos cement sheeting (assumed)	Non-friable	Visual Inspection	-	10m ²	Good-fair Maintenance only	Priority 4 – Negligible Risk Level	Remove prior to demolition works	

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

Internal, office adjacent rear entrance, flooring	Vinyl floor tiles	Non-friable	Asb23	No Asbestos Detected	N/A	N/A	N/A	N/A
Internal, main reception area	Vinyl floor tiles	Non-friable	Asb24	No Asbestos Detected Organic Fibres Detected	N/A	N/A	N/A	N/A
Internal, main reception area adjacent safe	Vinyl floor tiles	Non-friable	Asb25	No Asbestos Detected	N/A	N/A	N/A	N/A

SMF

Internal, ceiling cavity, membrane	SMF Insulation	N/A	Visual inspection	-	Assumed throughout	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	
Internal, bathroom	SMF Insulation	N/A	Visual inspection	-	1x hot water unit	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works	

Paints

No lead based paints were identified

Hazardous Materials Register
64-70 King Georges Road & 280-300 Lakemba Street, Wiley Park NSW

PCBs

Internal, ceiling	PCB containing single tube fluorescent light fittings (assumed)	N/A	Visual inspection	-	Assumed throughout	Good Maintenance Only	Priority 4: Negligible Risk Level	Remove prior to demolition works
-------------------	---	-----	-------------------	---	--------------------	-----------------------	-----------------------------------	----------------------------------



Appendix B - Laboratory CoC and Analytical Results

Sheet <u>2</u> of <u>3</u>					Sample Matrix				Analysis																Comments			
Site: 64-70 King Georges Road and 280-300 Lakemba Street, Wiley Park			Project No. E25377		SOIL	WATER	0.45 µm field filtered	OTHER	HM ^A / TRH/BTEX/PAHs OC/PCP/CB/Asbestos	HM ^A / TRH/BTEX/PAHs	HM ^A / TRH/BTEX	BTEX	VOCs	Asbestos	Asbestos Quantification	Excavated Natural Material (ENM) Suite	Dewatering Suite	pH / pH peroxide	sPOCAS	Chromium Reducible Sulfur (CrS)	PFAS	pH / CEC (cation exchange)	pH / EC (electrical conductivity)	Sulphate / Chloride			TCLP HM ^B / PAH	HM ^A Arsenic Cadmium Chromium Copper Lead Mercury Nickel Zinc HM ^B Arsenic Cadmium Chromium Lead Mercury Nickel
Sample ID	Laboratory ID	Container Type	Sampling																									
			Date	Time																								
Asb13	13	zlb	11/10/2021	am/pm				X						X														
Asb14	14	zlb	11/10/2021	am/pm				X						X														
Asb15	15	zlb	11/10/2021	am/pm				X						X														
Asb16	16	zlb	11/10/2021	am/pm				X						X														
Asb17	17	zlb	11/10/2021	am/pm				X						X														
Asb18	18	zlb	11/10/2021	am/pm				X						X														
Asb19	19	zlb	11/10/2021	am/pm				X						X														
Asb20	20	zlb	11/10/2021	am/pm				X						X														
Asb21	21	zlb	11/10/2021	am/pm				X						X														
Asb22	22	zlb	11/10/2021	am/pm				X						X														
Asb23	23	zlb	11/10/2021	am/pm				X						X														
Asb24	24	zlb	11/10/2021	am/pm				X						X														

Container Type:
J = solvent washed, acid rinsed, Teflon sealed glass jar
S = solvent washed, acid rinsed glass bottle
P = natural HDPE plastic bottle
VC = glass vial, Teflon Septum
ZLB = Zip-Lock Bag

Investigator: I attest that these samples were collected in accordance with standard EI field sampling procedures.

Sampler's Name (EI)		Received by (SGS)	
Print	Nathan Spanos	Print	Pamela Yui
Signature		Signature	
Date	11/10/2021	Date	11/10/21 @ 3p

IMPORTANT:
Please e-mail laboratory results to: lab@eiaustralia.com.au

Report with EI Waste Classification Table ☐

Sampler's Comments:


Suite 6.01, 55 Miller Street,
PYRMONT NSW 2009
Ph: 9516 0722
lab@eiaustralia.com.au

COC June 2021 FORM v 5 - SGS

**LABORATORY
TURNAROUND**

- ☒ Standard
- ☐ 24 Hours
- ☐ 48 Hours
- ☐ 72 Hours
- ☐ Other _____

Dewatering Suite
pH & EC
TDS / TOC
Hardness
Total Cyanide
Metals (Al, As, Cd, Cr,
Cu, Pb, Hg, Ni, Zn)
TRH (F1, F2, F3, F4)
BTEX
PAH
Total Phenol

Sheet <u>3</u> of <u>3</u>					Sample Matrix				Analysis																Comments		
Site: 64-70 King Georges Road and 280-300 Lakemba Street, Wiley Park			Project No: E25377		SOIL	WATER	0.45 µm field filtered	OTHER	HM ^A /TRH/BTEX/PAHs OC/OP/PCB/Asbestos	HM ^A /TRH/BTEX/PAHs	HM ^A /TRH/BTEX	BTEX	VOCs	Asbestos	Asbestos Quantification	Excavated Natural Material (ENM) Suite	Dewatering Suite	pH / pH peroxide	sPOCAS	Chromium Reducible Sulfur (Cr/S)	PFAS	pH / CEC (cation exchange)	pH / EC (electrical conductivity)	Sulphate / Chloride	Lead	TCLP HM ^B / PAH	HM ^A Arsenic Cadmium Chromium Copper Lead Mercury Nickel Zinc HM ^B Arsenic Cadmium Chromium Lead Mercury Nickel
Sample ID	Laboratory ID	Container Type	Sampling																								
			Date	Time																							
Asb25	25	zlb	11/10/2021	am/pm				X						X												Dewatering Suite pH & EC TDS / TDU Hardness Total Cyanide Metals (As, Cd, Cr, Cu, Pb, Hg, Ni, Zn) TRH (F1, F2, F3, F4) BTEX PAH Total Phenol	
Asb26	26	zlb	11/10/2021	am/pm				X						X													
Asb27	27	zlb	11/10/2021	am/pm				X						X													
Asb28	28	zlb	11/10/2021	am/pm				X						X													
Pb01	29	zlb	11/10/2021	am/pm				X																X			
Pb02	30	zlb	11/10/2021	am/pm				X																X			
Pb03	31	zlb	11/10/2021	am/pm				X																X			
Pb04	32	zlb	11/10/2021	am/pm				X																X			
Pb05	33	zlb	11/10/2021	am/pm				X																X			
Container Type: J = solvent washed, acid rinsed, Teflon sealed glass jar S = solvent washed, acid rinsed glass bottle P = natural HDPE plastic bottle VC = glass vial, Teflon Septum ZLB = Zip-Lock Bag					Investigator: I attest that these samples were collected in accordance with standard EI field sampling procedures.											Report with EI Waste Classification Table <input type="checkbox"/>											
 <div style="text-align: right;"> Suite 6.01, 55 Miller Street, PYRMONT NSW 2009 Ph: 9516 0722 lab@eiaustralia.com.au </div> <div style="text-align: center; font-size: small;"> COC June 2021 FORM v5 - SGS </div>					Sampler's Name (EI) Print: Nathan Spanos					Received by (SGS): Print: <i>[Signature]</i>					Sampler's Comments:												
					Signature: <i>[Signature]</i>					Signature: <i>[Signature]</i>																	
					Date: 11/10/2021					Date: 11/10 @ 3p																	
					IMPORTANT: Please e-mail laboratory results to: lab@eiaustralia.com.au																						



SAMPLE RECEIPT ADVICE

SE224481

CLIENT DETAILS

Contact Nathan Spanos
Client EIAUSTRALIA
Address SUITE 6.01
55 MILLER STREET
PYRMONT NSW 2009

Telephone 61 2 95160722
Facsimile (Not specified)
Email Nathan.spanos@eiaustralia.com.au

Project **E25377 64-70 King Georges Rd and 280-300**
Order Number
Samples 33

LABORATORY DETAILS

Manager Huong Crawford
Laboratory SGS Alexandria Environmental
Address Unit 16, 33 Maddox St
Alexandria NSW 2015

Telephone +61 2 8594 0400
Facsimile +61 2 8594 0499
Email au.environmental.sydney@sgs.com

Samples Received Mon 11/10/2021
Report Due Mon 18/10/2021
SGS Reference **SE224481**

SUBMISSION DETAILS

This is to confirm that 33 samples were received on Monday 11/10/2021. Results are expected to be ready by COB Monday 18/10/2021. Please quote SGS reference SE224481 when making enquiries. Refer below for details relating to sample integrity upon receipt.

Samples clearly labelled	Yes	Complete documentation received	Yes
Sample container provided	Client	Sample cooling method	None
Samples received in correct containers	Yes	Sample counts by matrix	28 Material, 5 Paint
Date documentation received	11/10/2021	Type of documentation received	COC
Samples received in good order	Yes	Samples received without headspace	N/A
Sample temperature upon receipt	19°C	Sufficient sample for analysis	Yes
Turnaround time requested	Standard		

Unless otherwise instructed, water and bulk samples will be held for one month from date of report, and soil samples will be held for two months.

COMMENTS

This document is issued by the Company under its General Conditions of Service accessible at www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.



SAMPLE RECEIPT ADVICE

SE224481

CLIENT DETAILS

Client **EI AUSTRALIA**

Project **E25377 64-70 King Georges Rd and 280-300**

SUMMARY OF ANALYSIS

No.	Sample ID	Fibre ID in bulk materials
001	Asb01	1
002	Asb02	1
003	Asb03	1
004	Asb04	1
005	Asb05	1
006	Asb06	1
007	Asb07	1
008	Asb08	1
009	Asb09	1
010	Asb10	1
011	Asb11	1
012	Asb12	1
013	Asb13	1
014	Asb14	1
015	Asb15	1
016	Asb16	1
017	Asb17	1
018	Asb18	1
019	Asb19	1
020	Asb20	1
021	Asb21	1
022	Asb22	1
023	Asb23	1
024	Asb24	1

CONTINUED OVERLEAF

The above table represents SGS' interpretation of the client-supplied Chain Of Custody document.

The numbers shown in the table indicate the number of results requested in each package.

Please indicate as soon as possible should your request differ from these details .

Testing as per this table shall commence immediately unless the client intervenes with a correction .

CLIENT DETAILS

Client **EI AUSTRALIA**

Project **E25377 64-70 King Georges Rd and 280-300**

SUMMARY OF ANALYSIS

No.	Sample ID	Fibre ID in bulk materials	Metals in Paint by ICPOES
025	Asb25	1	-
026	Asb26	1	-
027	Asb27	1	-
028	Asb28	1	-
029	Pb01	-	1
030	Pb02	-	1
031	Pb03	-	1
032	Pb04	-	1
033	Pb05	-	1

The above table represents SGS' interpretation of the client-supplied Chain Of Custody document.
The numbers shown in the table indicate the number of results requested in each package.
Please indicate as soon as possible should your request differ from these details .
Testing as per this table shall commence immediately unless the client intervenes with a correction .

CLIENT DETAILS

Contact Nathan Spanos
Client EI AUSTRALIA
Address SUITE 6.01
 55 MILLER STREET
 PYRMONT NSW 2009

Telephone 61 2 95160722
Facsimile (Not specified)
Email Nathan.spanos@eiaustralia.com.au
Project **E25377 64-70 King Georges Rd and 280-300**
Order Number **E25377**
Samples 33

LABORATORY DETAILS

Manager Huong Crawford
Laboratory SGS Alexandria Environmental
Address Unit 16, 33 Maddox St
 Alexandria NSW 2015

Telephone +61 2 8594 0400
Facsimile +61 2 8594 0499
Email au.environmental.sydney@sgs.com
SGS Reference **SE224481 R0**
Date Received 11/10/2021
Date Reported 19/10/2021


COMMENTS

Accredited for compliance with ISO/IEC 17025 - Testing. NATA accredited laboratory 2562(4354).
 Sample # 1-2, 9-11,15-16, 19,22-25,28 : No trace asbestos fibres detected using trace analysis technique.
 Asbestos analysed by Approved Identifier Ravee Sivasubramaniam .

SIGNATORIES



Bennet LO
 Senior Chemist



Ravee SIVASUBRAMANIAM
 Hygiene Team Leader

Metals in Paint by ICPOES [AN065/AN320] Tested: 15/10/2021

			Pb01	Pb02	Pb03	Pb04	Pb05
			PAINT	PAINT	PAINT	PAINT	PAINT
			-	-	-	-	-
			11/10/2021	11/10/2021	11/10/2021	11/10/2021	11/10/2021
PARAMETER	UOM	LOR	SE224481.029	SE224481.030	SE224481.031	SE224481.032	SE224481.033
Lead, Pb	%w/w	0.001	0.034	25	0.015	0.14	0.078

Fibre ID in bulk materials [AN602] Tested: 18/10/2021

PARAMETER	UOM	LOR	Asb01	Asb02	Asb03	Asb04	Asb05
			MATERIAL	MATERIAL	MATERIAL	MATERIAL	MATERIAL
			-	-	-	-	-
			11/10/2021	11/10/2021	11/10/2021	11/10/2021	11/10/2021
			SE224481.001	SE224481.002	SE224481.003	SE224481.004	SE224481.005
Asbestos Detected	No unit	-	No	No	Yes	Yes	Yes

PARAMETER	UOM	LOR	Asb06	Asb07	Asb08	Asb09	Asb10
			MATERIAL	MATERIAL	MATERIAL	MATERIAL	MATERIAL
			-	-	-	-	-
			11/10/2021	11/10/2021	11/10/2021	11/10/2021	11/10/2021
			SE224481.006	SE224481.007	SE224481.008	SE224481.009	SE224481.010
Asbestos Detected	No unit	-	Yes	Yes	Yes	No	No

PARAMETER	UOM	LOR	Asb11	Asb12	Asb13	Asb14	Asb15
			MATERIAL	MATERIAL	MATERIAL	MATERIAL	MATERIAL
			-	-	-	-	-
			11/10/2021	11/10/2021	11/10/2021	11/10/2021	11/10/2021
			SE224481.011	SE224481.012	SE224481.013	SE224481.014	SE224481.015
Asbestos Detected	No unit	-	No	Yes	Yes	Yes	No

PARAMETER	UOM	LOR	Asb16	Asb17	Asb18	Asb19	Asb20
			MATERIAL	MATERIAL	MATERIAL	MATERIAL	MATERIAL
			-	-	-	-	-
			11/10/2021	11/10/2021	11/10/2021	11/10/2021	11/10/2021
			SE224481.016	SE224481.017	SE224481.018	SE224481.019	SE224481.020
Asbestos Detected	No unit	-	No	Yes	Yes	No	Yes

PARAMETER	UOM	LOR	Asb21	Asb22	Asb23	Asb24	Asb25
			MATERIAL	MATERIAL	MATERIAL	MATERIAL	MATERIAL
			-	-	-	-	-
			11/10/2021	11/10/2021	11/10/2021	11/10/2021	11/10/2021
			SE224481.021	SE224481.022	SE224481.023	SE224481.024	SE224481.025
Asbestos Detected	No unit	-	Yes	No	No	No	No

PARAMETER	UOM	LOR	Asb26	Asb27	Asb28
			MATERIAL	MATERIAL	MATERIAL
			-	-	-
			11/10/2021	11/10/2021	11/10/2021
			SE224481.026	SE224481.027	SE224481.028
Asbestos Detected	No unit	-	Yes	Yes	No

METHOD

METHODOLOGY SUMMARY

AN065/AN320

A portion of paint chips sample is digested with nitric acid to solubilise the metals into solution. Digest then analysed by ICP OES with result calculated back to the as received paint sample basis.

AN602

Qualitative identification of chrysotile, amosite and crocidolite in bulk samples by polarised light microscopy (PLM) in conjunction with dispersion staining (DS). AS4964 provides the basis for this document. Unequivocal identification of the asbestos minerals present is made by obtaining sufficient diagnostic 'clues', which provide a reasonable degree of certainty, dispersion staining is a mandatory 'clue' for positive identification. If sufficient 'clues' are absent, then positive identification of asbestos is not possible. This procedure requires removal of suspect fibres/bundles from the sample which cannot be returned.

AN602

Fibres/material that cannot be unequivocally identified as one of the three asbestos forms, will be reported as unknown mineral fibres (umf). The fibres detected may or may not be asbestos fibres.

AN602

AS4964.2004 Method for the Qualitative Identification of Asbestos in Bulk Samples, Section 8.4, Trace Analysis Criteria, Note 4 states: "Depending upon sample condition and fibre type, the detection limit of this technique has been found to lie generally in the range of 1 in 1,000 to 1 in 10,000 parts by weight, equivalent to 1 to 0.1 g/kg."

FOOTNOTES

*	NATA accreditation does not cover the performance of this service.	-	Not analysed.	UOM	Unit of Measure.
**	Indicative data, theoretical holding time exceeded.	NVL	Not validated.	LOR	Limit of Reporting.
		IS	Insufficient sample for analysis.	↑↓	Raised/lowered Limit of Reporting.
***	Indicates that both * and ** apply.	LNR	Sample listed, but not received.		

Unless it is reported that sampling has been performed by SGS, the samples have been analysed as received. Solid samples expressed on a dry weight basis.

Where "Total" analyte groups are reported (for example, Total PAHs, Total OC Pesticides) the total will be calculated as the sum of the individual analytes, with those analytes that are reported as <LOR being assumed to be zero. The summed (Total) limit of reporting is calculated by summing the individual analyte LORs and dividing by two. For example, where 16 individual analytes are being summed and each has an LOR of 0.1 mg/kg, the "Totals" LOR will be 1.6 / 2 (0.8 mg/kg). Where only 2 analytes are being summed, the "Total" LOR will be the sum of those two LORs.

Some totals may not appear to add up because the total is rounded after adding up the raw values.

If reported, measurement uncertainty follow the ± sign after the analytical result and is expressed as the expanded uncertainty calculated using a coverage factor of 2, providing a level of confidence of approximately 95%, unless stated otherwise in the comments section of this report.

Results reported for samples tested under test methods with codes starting with ARS-SOP, radionuclide or gross radioactivity concentrations are expressed in becquerel (Bq) per unit of mass or volume or per wipe as stated on the report. Becquerel is the SI unit for activity and equals one nuclear transformation per second.

Note that in terms of units of radioactivity:

- 1 Bq is equivalent to 27 pCi
- 37 MBq is equivalent to 1 mCi

For results reported for samples tested under test methods with codes starting with ARS-SOP, less than (<) values indicate the detection limit for each radionuclide or parameter for the measurement system used. The respective detection limits have been calculated in accordance with ISO 11929.

The QC and MU criteria are subject to internal review according to the SGS QAQC plan and may be provided on request or alternatively can be found here: www.sgs.com.au/en-gb/environment-health-and-safety.

This document is issued by the Company under its General Conditions of Service accessible at www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client only. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

This report must not be reproduced, except in full.

CLIENT DETAILS

Contact Nathan Spanos
 Client EI AUSTRALIA
 Address SUITE 6.01
 55 MILLER STREET
 PYRMONT NSW 2009

Telephone 61 2 95160722
 Facsimile (Not specified)
 Email Nathan.spanos@eiaustralia.com.au

Project **E25377 64-70 King Georges Rd and 280-300**
 Order Number **E25377**
 Samples 28

LABORATORY DETAILS

Manager Huong Crawford
 Laboratory SGS Alexandria Environmental
 Address Unit 16, 33 Maddox St
 Alexandria NSW 2015

Telephone +61 2 8594 0400
 Facsimile +61 2 8594 0499
 Email au.environmental.sydney@sgs.com

SGS Reference **SE224481 R0**
 Date Received 11 Oct 2021
 Date Reported 19 Oct 2021

COMMENTS

Accredited for compliance with ISO/IEC 17025 - Testing. NATA accredited laboratory 2562(4354).

Sample # 1-2, 9-11, 15-16, 19, 22-25, 28 : No trace asbestos fibres detected using trace analysis technique.

Asbestos analysed by Approved Identifier Ravee Sivasubramaniam.

SIGNATORIES



Bennet LO
 Senior Chemist



Ravee SIVASUBRAMANIAM
 Hygiene Team Leader

RESULTS

Fibre ID in bulk materials

Method AN602

Laboratory Reference	Client Reference	Matrix	Sample Description	Date Sampled	Fibre Identification	Est.%w/w*
SE224481.001	Asb01	Other	<1g Cement Sheet Fragments	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	
SE224481.002	Asb02	Other	25x20x4mm Cement Sheet Fragment	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	
SE224481.003	Asb03	Other	50x20x4mm Cement Sheet Fragment	11 Oct 2021	Amosite & Chrysotile Asbestos Detected	
SE224481.004	Asb04	Other	<1g Cement Sheet Fragments	11 Oct 2021	Amosite & Chrysotile Asbestos Detected	
SE224481.005	Asb05	Other	20x20x4mm Cement Sheet Fragment	11 Oct 2021	Amosite & Chrysotile Asbestos Detected	
SE224481.006	Asb06	Other	35x10x4mm cement Sheet Fragment	11 Oct 2021	Amosite & Chrysotile Asbestos Detected	
SE224481.007	Asb07	Other	30x10x3mm Cement Sheet Fragments	11 Oct 2021	Chrysotile Asbestos Detected Organic Fibres Detected	
SE224481.008	Asb08	Other	30x15x3mm Cement Sheet Fragments	11 Oct 2021	Amosite & Chrysotile Asbestos Detected Organic Fibres Detected	
SE224481.009	Asb09	Other	<1g Cement Sheet Fragments	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	
SE224481.010	Asb10	Other	10x5x3mm Cement Sheet Fragment	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	
SE224481.011	Asb11	Other	40x10x3mm Cement Sheet Fragments	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	
SE224481.012	Asb12	Other	30x10x4mm Cement Sheet Fragment	11 Oct 2021	Amosite & Chrysotile Asbestos Detected	
SE224481.013	Asb13	Other	10x10x3mm Cement Sheet Fragment	11 Oct 2021	Chrysotile Asbestos Detected	
SE224481.014	Asb14	Other	50x25x5mm Cement Sheet Fragment	11 Oct 2021	Amosite & Chrysotile Asbestos Detected	
SE224481.015	Asb15	Other	<1g Cement Sheet Fragments	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	
SE224481.016	Asb16	Other	<1g Cement Sheet Fragments	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	
SE224481.017	Asb17	Other	100x30x4mm Cement Sheet Fragment	11 Oct 2021	Chrysotile Asbestos Detected Organic Fibres Detected	
SE224481.018	Asb18	Other	40x10x4mm Cement Sheet Fragment	11 Oct 2021	Amosite & Chrysotile Asbestos Detected	
SE224481.019	Asb19	Other	<1g Cement Sheet Fragments	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	

RESULTS

Fibre ID in bulk materials

Method AN602

Laboratory Reference	Client Reference	Matrix	Sample Description	Date Sampled	Fibre Identification	Est.%w/w*
SE224481.020	Asb20	Other	60x40x2mm Vinyl tile fragment	11 Oct 2021	Chrysotile Asbestos Detected	
SE224481.021	Asb21	Other	<1g Cement Sheet Fragments	11 Oct 2021	Chrysotile Asbestos Detected	
SE224481.022	Asb22	Other	15x10x2mm Green vinyl Tile Fragment	11 Oct 2021	No Asbestos Detected	
SE224481.023	Asb23	Other	80x100x3mm Vinyl Tile Fragments	11 Oct 2021	No Asbestos Detected	
SE224481.024	Asb24	Other	110x90x3mm Vinyl Tile Fragments	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	
SE224481.025	Asb25	Other	60x30x3mm Vinyl Tile Fragments	11 Oct 2021	No Asbestos Detected	
SE224481.026	Asb26	Other	120x80x2mm Vinyl Tile Fragments	11 Oct 2021	Chrysotile Asbestos Detected	
SE224481.027	Asb27	Other	110x90x4mm Cement Sheet Fragment	11 Oct 2021	Chrysotile Asbestos Detected Organic Fibres Detected	
SE224481.028	Asb28	Other	20x5x3mm Cement Sheet Fragments	11 Oct 2021	No Asbestos Detected Organic Fibres Detected	

METHOD

METHODOLOGY SUMMARY

AN602	Qualitative identification of chrysotile, amosite and crocidolite in bulk samples by polarised light microscopy (PLM) in conjunction with dispersion staining (DS). AS4964 provides the basis for this document. Unequivocal identification of the asbestos minerals present is made by obtaining sufficient diagnostic 'clues', which provide a reasonable degree of certainty, dispersion staining is a mandatory 'clue' for positive identification. If sufficient 'clues' are absent, then positive identification of asbestos is not possible. This procedure requires removal of suspect fibres/bundles from the sample which cannot be returned.
AN602	Fibres/material that cannot be unequivocally identified as one of the three asbestos forms, will be reported as unknown mineral fibres (umf). The fibres detected may or may not be asbestos fibres.
AN602	AS4964.2004 Method for the Qualitative Identification of Asbestos in Bulk Samples, Section 8.4, Trace Analysis Criteria, Note 4 states: "Depending upon sample condition and fibre type, the detection limit of this technique has been found to lie generally in the range of 1 in 1,000 to 1 in 10,000 parts by weight, equivalent to 1 to 0.1 g/kg."

FOOTNOTES

Amosite	-	Brown Asbestos	NA	-	Not Analysed
Chrysotile	-	White Asbestos	LNR	-	Listed, Not Required
Crocidolite	-	Blue Asbestos	*	-	NATA accreditation does not cover the performance of this service.
Amphiboles	-	Amosite and/or Crocidolite	**	-	Indicative data, theoretical holding time exceeded.
			***	-	Indicates that both * and ** apply.

(In reference to soil samples only) This report does not comply with the analytical reporting recommendations in the Western Australian Department of Health Guidelines for the Assessment and Remediation and Management of Asbestos Contaminated sites in Western Australia - May 2009.

Unless it is reported that sampling has been performed by SGS, the samples have been analysed as received.

Where reported: 'Asbestos Detected': Asbestos detected by polarised light microscopy, including dispersion staining.

Where reported: 'No Asbestos Found': No Asbestos Found by polarised light microscopy, including dispersion staining.

Where reported: 'UMF Detected': Mineral fibres of unknown type detected by polarised light microscopy, including dispersion staining. Confirmation by another independent analytical technique may be necessary.

Even after disintegration it can be very difficult, or impossible, to detect the presence of asbestos in some asbestos-containing bulk materials using polarised light microscopy. This is due to the low grade or small length or diameter of asbestos fibres present in the material, or to the fact that very fine fibres have been distributed intimately throughout the materials.

The QC and MU criteria are subject to internal review according to the SGS QAQC plan and may be provided on request or alternatively can be found here: www.sgs.com.au/en-gb/environment-health-and-safety.

This document is issued by the Company under its General Conditions of Service accessible at www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client only. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

This test report shall not be reproduced, except in full.



STATEMENT OF QA/QC PERFORMANCE

SE224481 R0

CLIENT DETAILS

Contact Nathan Spanos
Client EI AUSTRALIA
Address SUITE 6.01
55 MILLER STREET
PYRMONT NSW 2009

Telephone 61 2 95160722
Facsimile (Not specified)
Email Nathan.spanos@eiaustralia.com.au

Project **E25377 64-70 King Georges Rd and 280-300**
Order Number **E25377**
Samples 33

LABORATORY DETAILS

Manager Huong Crawford
Laboratory SGS Alexandria Environmental
Address Unit 16, 33 Maddox St
Alexandria NSW 2015

Telephone +61 2 8594 0400
Facsimile +61 2 8594 0499
Email au.environmental.sydney@sgs.com

SGS Reference **SE224481 R0**
Date Received 11 Oct 2021
Date Reported 19 Oct 2021

COMMENTS

All the laboratory data for each environmental matrix was compared to SGS' stated Data Quality Objectives (DQO). Comments arising from the comparison were made and are reported below.

The data relating to sampling was taken from the Chain of Custody document.

This QA/QC Statement must be read in conjunction with the referenced Analytical Report.

The Statement and the Analytical Report must not be reproduced except in full.

All Data Quality Objectives were met (within the SGS Alexandria Environmental laboratory).

SAMPLE SUMMARY

Samples clearly labelled	Yes	Complete documentation received	Yes
Sample container provider	Client	Sample cooling method	None
Samples received in correct containers	Yes	Sample counts by matrix	28 Material, 5 Paint
Date documentation received	11/10/2021	Type of documentation received	COC
Samples received in good order	Yes	Samples received without headspace	N/A
Sample temperature upon receipt	19°C	Sufficient sample for analysis	Yes
Turnaround time requested	Standard		

SGS holding time criteria are drawn from current regulations and are highly dependent on sample container preservation as specified in the SGS "Field Sampling Guide for Containers and Holding Time" (ref: GU-(AU)-ENV.001). Soil samples guidelines are derived from NEPM "Schedule B(3) Guideline on Laboratory Analysis of Potentially Contaminated Soils". Water sample guidelines are derived from "AS/NZS 5667.1 : 1998 Water Quality - sampling part 1" and APHA "Standard Methods for the Examination of Water and Wastewater" 21st edition 2005.

Extraction and analysis holding time due dates listed are calculated from the date sampled, although holding times may be extended after laboratory extraction for some analytes. The due dates are the suggested dates that samples may be held before extraction or analysis and still be considered valid.

Extraction and analysis dates are shown in **Green** when within suggested criteria or **Red** with an appended dagger symbol (†) when outside suggested criteria. If the

Fibre ID in bulk materials

Method: ME-(AU)-[ENV]AN602

Sample Name	Sample No.	QC Ref	Sampled	Received	Extraction Due	Extracted	Analysis Due	Analysed
Asb01	SE224481.001	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb02	SE224481.002	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb03	SE224481.003	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb04	SE224481.004	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb05	SE224481.005	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb06	SE224481.006	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb07	SE224481.007	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb08	SE224481.008	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb09	SE224481.009	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb10	SE224481.010	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb11	SE224481.011	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb12	SE224481.012	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb13	SE224481.013	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb14	SE224481.014	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb15	SE224481.015	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb16	SE224481.016	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb17	SE224481.017	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb18	SE224481.018	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb19	SE224481.019	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	18 Oct 2021
Asb20	SE224481.020	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	19 Oct 2021
Asb21	SE224481.021	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	19 Oct 2021
Asb22	SE224481.022	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	19 Oct 2021
Asb23	SE224481.023	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	19 Oct 2021
Asb24	SE224481.024	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	19 Oct 2021
Asb25	SE224481.025	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	19 Oct 2021
Asb26	SE224481.026	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	19 Oct 2021
Asb27	SE224481.027	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	19 Oct 2021
Asb28	SE224481.028	LB234956	11 Oct 2021	11 Oct 2021	11 Oct 2022	18 Oct 2021	11 Oct 2022	19 Oct 2021

Metals in Paint by ICPOES

Method: ME-(AU)-[ENV]AN065/AN320

Sample Name	Sample No.	QC Ref	Sampled	Received	Extraction Due	Extracted	Analysis Due	Analysed
Pb01	SE224481.029	LB234829	11 Oct 2021	11 Oct 2021	09 Apr 2022	15 Oct 2021	09 Apr 2022	15 Oct 2021
Pb02	SE224481.030	LB234829	11 Oct 2021	11 Oct 2021	09 Apr 2022	15 Oct 2021	09 Apr 2022	15 Oct 2021
Pb03	SE224481.031	LB234829	11 Oct 2021	11 Oct 2021	09 Apr 2022	15 Oct 2021	09 Apr 2022	15 Oct 2021
Pb04	SE224481.032	LB234829	11 Oct 2021	11 Oct 2021	09 Apr 2022	15 Oct 2021	09 Apr 2022	15 Oct 2021
Pb05	SE224481.033	LB234829	11 Oct 2021	11 Oct 2021	09 Apr 2022	15 Oct 2021	09 Apr 2022	15 Oct 2021

Surrogate results are evaluated against upper and lower limit criteria established in the SGS QA/QC plan (Ref: MP-(AU)-[ENV]QU-022). At least two of three routine level soil sample surrogate spike recoveries for BTEX/VOC are to be within 70-130% where control charts have not been developed and within the established control limits for charted surrogates. Matrix effects may void this as an acceptance criterion. Water sample surrogate spike recoveries are to be within 40-130%. The presence of emulsions, surfactants and particulates may void this as an acceptance criterion.

Result is shown in **Green** when within suggested criteria or **Red** with an appended reason identifier when outside suggested criteria. Refer to the footnotes section at the end of this report for failure reasons.

No surrogates were required for this job.



METHOD BLANKS

SE224481 R0

Blank results are evaluated against the limit of reporting (LOR), for the chosen method and its associated instrumentation, typically 2.5 times the statistically determined method detection limit (MDL).

Result is shown in **Green** when within suggested criteria or **Red** with an appended dagger symbol (†) when outside suggested criteria.

Metals in Paint by ICPOES

Method: ME-(AU)-[ENV]AN065/AN320

Sample Number	Parameter	Units	LOR	Result
LB234829.001	Lead, Pb	%w/w	0.001	<0.001

Duplicates are calculated as Relative Percentage Difference (RPD) using the formula: $RPD = | \text{OriginalResult} - \text{ReplicateResult} | \times 100 / \text{Mean}$

The RPD is evaluated against the Maximum Allowable Difference (MAD) criteria and can be graphically represented by a curve calculated from the Statistical Detection Limit (SDL) and Limiting Repeatability (LR) using the formula: $MAD = 100 \times \text{SDL} / \text{Mean} + \text{LR}$

Where the Maximum Allowable Difference evaluates to a number larger than 200 it is displayed as 200.

RPD is shown in **Green** when within suggested criteria or **Red** with an appended reason identifier when outside suggested criteria. Refer to the footnotes section at the end of this report for failure reasons.

NOTE: The RPD reported is calculated from the unrounded data for the original and replicate result. Manual calculation of the RPD from the rounded data reported may

No duplicates were required for this job.



Laboratory Control Standard (LCS) results are evaluated against an expected result, typically the concentration of analyte spiked into the control during the sample preparation stage, producing a percentage recovery. The criteria applied to the percentage recovery is established in the SGS QA /QC plan (Ref: MP-(AU)-[ENV]QU-022). For more information refer to the footnotes in the concluding page of this report.

Recovery is shown in **Green** when within suggested criteria or **Red** with an appended dagger symbol (†) when outside suggested criteria.

Metals in Paint by ICPOES**Method: ME-(AU)-[ENV]AN065/AN320**

Sample Number	Parameter	Units	LOR	Result	Expected	Criteria %	Recovery %
LB234829.002	Lead, Pb	%w/w	0.001	0.010	0.01035	70 - 130	99

Matrix Spike (MS) results are evaluated as the percentage recovery of an expected result, typically the concentration of analyte spiked into a field sub-sample during the sample preparation stage. The original sample's result is subtracted from the sub-sample result before determining the percentage recovery. The criteria applied to the percentage recovery is established in the SGS QA/QC plan (ref: MP-(AU)-[ENV]QU-022). For more information refer to the footnotes in the concluding page of this report.

Recovery is shown in **Green** when within suggested criteria or **Red** with an appended reason identifier when outside suggested criteria. Refer to the footnotes section at the end of this report for failure reasons.

No matrix spikes were required for this job.

Matrix spike duplicates are calculated as Relative Percent Difference (RPD) using the formula: $RPD = | \text{OriginalResult} - \text{ReplicateResult} | \times 100 / \text{Mean}$

The original result is the analyte concentration of the matrix spike. The Duplicate result is the analyte concentration of the matrix spike duplicate.

The RPD is evaluated against the Maximum Allowable Difference (MAD) criteria and can be graphically represented by a curve calculated from the Statistical Detection Limit (SDL) and Limiting Repeatability (LR) using the formula: $MAD = 100 \times \text{SDL} / \text{Mean} + \text{LR}$

Where the Maximum Allowable Difference evaluates to a number larger than 200 it is displayed as 200.

RPD is shown in **Green** when within suggested criteria or **Red** with an appended reason identifier when outside suggested criteria. Refer to the footnotes section at the

No matrix spike duplicates were required for this job.

Samples analysed as received.

Solid samples expressed on a dry weight basis.

QC criteria are subject to internal review according to the SGS QA/QC plan and may be provided on request or alternatively can be found here : https://www.sgs.com.au/~media/Local/Australia/Documents/Technical Documents/MP-AU-ENV-QU-022_QA_QC_Plan.pdf

- * NATA accreditation does not cover the performance of this service .
- ** Indicative data, theoretical holding time exceeded.
- *** Indicates that both * and ** apply.
- Sample not analysed for this analyte.
- IS Insufficient sample for analysis.
- LNR Sample listed, but not received.
- LOR Limit of reporting.
- QFH QC result is above the upper tolerance.
- QFL QC result is below the lower tolerance.
- ① At least 2 of 3 surrogates are within acceptance criteria.
- ② RPD failed acceptance criteria due to sample heterogeneity.
- ③ Results less than 5 times LOR preclude acceptance criteria for RPD.
- ④ Recovery failed acceptance criteria due to matrix interference.
- ⑤ Recovery failed acceptance criteria due to the presence of significant concentration of analyte (i.e. the concentration of analyte exceeds the spike level).
- ⑥ LOR was raised due to sample matrix interference.
- ⑦ LOR was raised due to dilution of significantly high concentration of analyte in sample.
- ⑧ Reanalysis of sample in duplicate confirmed sample heterogeneity and inconsistency of results.
- ⑨ Recovery failed acceptance criteria due to sample heterogeneity.
- ⑩ LOR was raised due to high conductivity of the sample (required dilution).
- † Refer to relevant report comments for further information.

This document is issued by the Company under its General Conditions of Service accessible at www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client only. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law .

This test report shall not be reproduced, except in full.