

Supplementary Appendix P – Evidence of Works Required (DA23/907)



Figure 1. Evidence of brick paved veranda; Brick paving below concrete topping rear veranda (Source: JPA& D 2023)



Figure 2. Evidence of brick paved veranda; Brick paving below concrete topping to rear veranda (Source: JPA& D 2023)



Figure 3. Evidence of brick paved veranda; Brick to rear veranda (Source: JPA& D 2023)



Figure 4. Ground Floor storeroom of the main house; Brick below concrete topping to store of main house (Source: JPA&D 2023)



Figure 5. Ground Floor storeroom of the main house; Brick Floor below concrete store of main house (Source: JPA&D 2023)



Figure 6. Ground Floor storeroom of the main house; Brick floor surface in store of main house (Source: JPA&D 2023)



Figure 7. Ground Floor storeroom of the main house; Brick floor of storeroom in the main house (Source: JPA&D 2023)



Figure 8. Floor of the weatherboard cottage is brick paved below concrete topping (Source: JPA&D 2023)



Figure 9. Some bricks to be used for reconstruction of the weatherboard cottage chimney which are loose but insitu (Source: JPA&D 2023)



Figure 10. Other bricks stored on pallets in a shed on site (Source: JPA&D 2023)



Figure 11. Photograph of William Charles Hadley Childs Circa 1930'2 to 1940's, providing insight and base information for the reconstruction (Source: JPA&D 2023)
