


GEOTECHNICAL INVESTIGATION BATHURST HOSPITAL REDEVELOPMENT 361-365 HOWICK ST, WEST BATHURST NSW 2795 Prepared for HEALTH INFRASTRUCTURE Prepared by RCA AUSTRALIA RCA ref 16547-202/4 OCTOBER 2024



#### **RCA Australia**

ABN 53 063 515 711 92 Hill Street, Carrington NSW 2294

Telephone: 02 4902 9200 Email: <u>administrator@rca.com.au</u> Internet: www.rca.com.au

This document is and shall remain the property of RCA Australia. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission supplied at the time of proposal. Unauthorised use of this document in any form whatsoever is prohibited.

	DOCUMENT STATUS						
Rev No Comment		Author	Reviewer	Approved	Approved for Issue (Project Manager)		
No				Name	Signature	Date	
/0	Draft	R Cater	M Allman	M Allman		04.08.23	
/1	Draft	R Cater	M Allman	M Allman		18.08.23	
/2	Final	R Cater	M Allman	M Allman	MarAll	29.08.23	
/3	Revised Final	R Cater	M Allman	M Allman	Mask	06.05.24	
/4	Revised Final	R Cater	M Allman	M Allman	Mask	22.10.24	

DOCUMENT DISTRIBUTION						
Rev No			Issued to	Date		
/0	1	Electronic (email)	TSA management Andrew Neill – <u>andrew.neill@tsamgt.com</u> Bianca Batbaatar – <u>bianca.batbaatar@tsamgt.com</u>	04.08.23		
/0	1	Electronic report	RCA – job archive	04.08.23		
/1	1	Electronic (email)	TSA management Andrew Neill – <u>andrew.neill@tsamgt.com</u> Bianca Batbaatar – <u>bianca.batbaatar@tsamgt.com</u>	18.08.23		
/1	1	Electronic report	RCA – job archive	18.08.23		
/2	1	Electronic (email)	TSA management Andrew Neill – <u>andrew.neill@tsamgt.com</u> Bianca Batbaatar – <u>bianca.batbaatar@tsamgt.com</u>	29.08.23		



htal htal occupational Health and Safety CERTIFIED

DOCUMENT DISTRIBUTION					
Rev No			Date		
/2	1	Electronic report	RCA – job archive	29.08.23	
/3	1	Electronic (email)	TSA management Andrew Neill – <u>andrew.neill@tsamgt.com</u>	06.05.24	
/3	1	Electronic report	RCA – job archive	06.05.24	
/4	1	Electronic (email)	TSA Riley Andrew Neill – <u>andrew.neill@tsamgt.com</u>	22.10.24	
/4	1	Electronic report	RCA – job archive	22.10.24	



# Contents

1	INTRO	ODUCTION		
2	FIELD	AND L	ABORATORY INVESTIGATIONS	3
3	SITE	DESCRI	PTION	6
	3.1 3.2 3.3 3.4	SURFA SUBSU	NAL GEOLOGY AND SOIL LANDSCAPES CE CONDITIONS RFACE CONDITIONS IDWATER	7 7
4	DISCU	JSSION	AND COMMENTS	10
	4.1 4.2 4.3 4.4	Excav. Filling	CHNICAL CONDITIONS ATIONS G	10 11
	4.5		IGS	
		4.5.1 4.5.2 4.5.3	HIGH-LEVEL FOOTINGS PIERED FOOTINGS GEOTECHNICAL STRENGTH REDUCTION FACTOR	14
	4.6	SITE C	LASSIFICATION	15
	4.7	EARTH	QUAKE DESIGN	16
	4.8		ILITY DESIGN	
	4.9	Раvем 4.9.1 4.9.1 4.9.2 4.9.1	ENTS SUBGRADE CONDITIONS SUPPORT PARAMETERS PAVEMENT MATERIALS AND COMPACTION REQUIREMENTS SUBGRADE PREPARATION PAVEMENT DRAINAGE	17 17 18
	4.10		ΓΥ	
	4.11	Acid S	ULFATE SOILS	19
5	LIMIT	ATIONS		19

#### **APPENDIX A**

DRAWING 1 - SITE AND TEST LOCATION PLAN DRAWING 2 - GEOTECHNICAL SECTION A-A DRAWING 3 - GEOTECHNICAL SECTION B-B DRAWING 4 - GEOTECHNICAL SECTION C-C

#### **APPENDIX B**

ENGINEERING LOGS CORE PHOTOGRAPHS TEST PIT PHOTOGRAPHS EXPLANATORY NOTES

#### **APPENDIX C**

LABORATORY TEST RESULTS

#### APPENDIX D

**CONSULTANT DECLARATION** 



RCA ref 16547-202/4 Client ref HI23010 BHR

22 October 2024

Health Infrastructure 361 Howick St West Bathurst NSW 2795

Attention: Hariharan Balasubramaniam CC: Andrew Neill: andrew.neill@tsamgt.com



Geotechnical Engineering Engineering Geology Environmental Engineering Hydrogeology Construction Materials Testing Environmental Monitoring Noise & Vibration Occupational Hygiene

### GEOTECHNICAL INVESTIGATION BATHURST HOSPITAL REDEVELOPMENT 361-365 HOWICK ST, WEST BATHURST NSW 2795

#### **1** INTRODUCTION

This geotechnical investigation report has been prepared by RCA Australia (RCA) on behalf of Health Infrastructure for the redevelopment of the Bathurst Hospital at 361-365 Howick Street, Bathurst.

The site is located at 361-365 Howick Street, Bathurst, in the Bathurst Local Government Area. It is occupied by Bathurst Health Service, a Level C referral facility in the Western NSW Local Health District.

This report accompanies a State Significant Development Application that seeks approval for the construction and operation of a new-build expansion, refurbishment and repurposing works to the existing Bathurst Health Service main hospital building. Proposed works will include:

- A new-build, multi-storey health services building expansion toward Mitre St (including 1 plant level) to include overnight inpatient accommodation and non-admitted care services and a new hospital front-of house and entrance
- A new-build, two-storey expansion to the Emergency department and Operating Theatres (plus 1 plant level)

- A new-build, single-storey expansion to the existing Cancer Service building Daffodil Cottage
- Refurbishment and repurposing to areas of the existing hospital
- Site establishment, demolition of some existing structure, cut and fill and remediation works
- Vehicular circulation and car parking improvements
- Tree removal
- Landscape works
- Alteration and amplification of existing hospital plant and services infrastructure

For a detailed project description, refer to the Environmental Impact Statement prepared by Ethos Urban. A summary of the Planning Secretary's Environmental Assessment Requirements (SEARs) which relate to the geotechnical investigation is provided in **Table 1** together with a reference to the relevant Section of this report.

ltem	SEARs Requirement	Relevant Section of Report
13	Assess potential impacts on soil resources and related infrastructure and riparian lands on and near the site, including soil erosion,	Section 3.1, 4.2 and 4.3
13	salinity	Section 2, 3.1, 4.8 and 4.10
13	and acid sulfate soils.	Section 2 and 4.11
13	Provide a Surface and Groundwater Impact Assessment that assesses potential impacts on: • surface water resources (quality and quantity) including related infrastructure, hydrology, dependent ecosystems, drainage lines, downstream assets and watercourses. • groundwater resources in accordance with the <i>Groundwater Guidelines</i> .	Section 2 and 3.4

 Table 1
 Secretary's Environmental Assessment Requirements

Mitigation measures for the development relating to the geotechnical conditions at the site (as indicated by the findings of the geotechnical investigation studies described in this report) are provided in the discussion and comments in this report, listed as follows:

• Mitigation measures relating to the design and construction of excavations are provided in Section 4.2.

Health Infrastructure Geotechnical Investigation Bathurst Hospital Redevelopment RCA ref 16547-202/4, October 2024 Client ref HI23010



- Mitigation measures relating to the design and construction of filling are provided in Section 4.3.
- Mitigation measures relating to the design and construction of retaining structures are provided in Section 4.4.
- Mitigation measures relating to the design and construction of footings are provided in Section 4.5.
- Mitigation measures relating to the design and construction of pavements are provided in Section 4.9.

#### 2 FIELD AND LABORATORY INVESTIGATIONS

A concurrent preliminary site (contamination) assessment was undertaken by RCA along with the geotechnical investigation, the findings of which are reported separately.

Fieldwork was conducted from the 5<sup>th</sup> to the 9<sup>th</sup> of June 2023, and consisted of:

- Observations of site conditions.
- Drilling of eight bores (BH1 to BH8) to depths ranging from 8.0-19.8m. Bores were initially drilled using continuous flight augers and were then extended by NMLC diamond coring methods to termination depth. Core was recovered from all 8 bores. Point load strength testing was undertaken on representative core samples together with photography of the core.
- Drilling of one 300mm diameter bore (BH9) to 1.5m depth using an auger attachment fitted to an excavator to obtain information of existing pavement and subgrade conditions and to obtain a bulk sample of subgrade material for laboratory testing.
- Drilling of one bore using a hand auger (BH10) to 1.6m depth to obtain information on subsurface conditions where machinery access was not feasible.
- Dynamic cone penetrometer testing at the location of BH9 and BH10.
- Excavation of two test pits by excavator to depths of 1.25m (TP1) and 1.90m (TP2).
- In situ sampling and testing involving standard penetration testing and recovery of disturbed samples, bulk samples and samples for the concurrent preliminary site (contamination) assessment.

All fieldwork was carried out by and in the presence of RCA Australia (RCA) personnel. Test locations are shown on **Drawing 1** attached in **Appendix A**.

Test locations were set out and recorded with reference to existing site features and the locations should be considered approximate. Borehole surface levels for BH1 to BH8 have been estimated with reference to supplied survey information and should also be considered approximate.



Bore and test pit depths have been recorded relative to the existing ground surface at the time of investigation.

All bores and test pits were backfilled on completion.

Engineering logs of bores and test pits are presented in **Appendix B**, together with photographs and explanation sheets. Point load strength test results on rock core are shown on the logs.

Groundwater conditions have been noted on the bore and test pit logs at the time of fieldwork. Fluctuations in groundwater conditions/levels may be expected due to variations in rainfall and site conditions.

Laboratory testing of samples recovered during fieldwork consisted of:

- Three Atterberg limit and linear shrinkage tests to assess soil plasticity and shrinkage properties.
- Three standard compaction and four day soaked California bearing ratio (CBR) tests to assess subgrade strength.
- Three uniaxial compressive strength (UCS) tests to assess rock strength.
- Eight moisture content and density tests to assess rock properties.
- Eight chemistry tests to assess aggressivity to steel and concrete structures.

Laboratory test result sheets are attached in Appendix C.

A summary of laboratory test results are presented in Table 2 to Table 6.

Liquid Plastic Plasticity Linear Bore Depth (m) Soil Type Limit Limit Index Shrinkage (%) (%) (%) (%) CLAY with BH1 1.5 - 1.95 31 15 16 8 sand Gravelly BH2 1.3 - 1.5 26 15 11 5.5 CLAY Sandy BH3 CLAY, trace 16 12 1.5 - 1.95 28 6.5 gravel

**Table 2**Summary of Atterberg Limits and Linear Shrinkage Test Results



Test Pit/ Bore	Depth (m)	Soil Type	FMC (%)	MDD (t/m³)	SOMC (%)	CBR (%)	Swell (%)
TP1	0.6 - 0.8	Silty SAND with clay	7.8	1.768	13.9	6	1.0
TP2	0.85 - 1.1	Silty SAND with clay	12.2	1.883	11.5	10	0.5
BH9	0.7 - 1.1	Gravelly Clayey SAND	17.8	1.82	17.6	8	1.0

 Table 3
 Summary of Compaction and CBR Test Results

NOTES: FMC – field moisture content

MDD – maximum dry density (Standard compaction) SOMC – Standard optimum moisture content CBR – California bearing ratio, penetration 2.5 / 5.0mm

**Table 4**Summary of Rock UCS Test Results

Bore	Depth (m)	Rock Type	UCS (MPa)
BH1	18.15 - 18.30	Granite	0.69
BH2	5.48 - 5.70	Granite	0.20
BH5	17.43 - 17.70	Granite	0.37

NOTES: UCS – Uniaxial Compressive Strength

**Table 5**Summary of Rock Moisture Content and Density Test Results

Bore	Depth (m)	Rock Type	Moisture Content (%)	Dry Density (t/m³)
BH1	18.15 - 18.30	Granite	3.7	2.3
BH2	5.48 - 5.70	Granite	6.8	2.1
BH4	9.30 - 9.53	Granite	4.3	2.3
BH5	17.43 - 17.70	Granite	6.2	2.0
BH5	19.40 - 19.70	Granite	4.8	2.3
BH6	7.70 - 7.85	Granite	4.2	2.2
BH7	16.00 - 16.15	Granite	4.8	2.1
BH8	17.30 - 17.60	Granite	4.0	2.2



Bore	Depth (m)	Soil Type	EC (μS/cm)	рН <sub>(1:5)</sub>	Chloride (mg/kg)	Sulfate (mg/kg)
BH3	0.55 - 1.00	Gravelly Sandy CLAY	252	7.8	50	400
BH5	2.3 - 2.8	Extremely Weathered GRANITE	31	6.5	<10	40
BH6	1.5 -1.95	Silty SAND, trace of clay	77	7.3	<10	20
BH6	3.0 - 3.45	Silty SAND, trace of clay	119	7.3	<10	60
BH7	5.8 - 6.0	Highly Weathered GRANITE	37	6.9	<10	40
BH8	3.1 - 3.45	Silty SAND, trace of clay	123	7.6	<10	50
BH8	4.5 - 4.95	Silty SAND, trace of clay	97	6.6	50	50
BH8	5.8 - 6.0	Silty SAND, trace of clay	64	7.0	<10	40

 Table 6
 Summary of Soil Chemistry Test Results

Notes EC – Electrical Conductivity

Key findings of the laboratory testing are:

- The Atterberg limits test results indicate the samples tested are of low plasticity.
- The moisture content test results indicate the subgrade samples tested ranged from dry of, to approximately equal to standard optimum moisture content.
- The laboratory CBR of soils is in the range 6% to 10%.
- The rock strength of UCS samples is in the very low range, or below the very low range.

#### 3 SITE DESCRIPTION

#### 3.1 REGIONAL GEOLOGY AND SOIL LANDSCAPES

The NSW seamless geology map (published by the department of Regional NSW) indicates the site is underlain by the Bathurst Granite unit described as coarse-grained, porphyritic biotite granite.

The Soil Landscapes of the Bathurst 1:250,000 Sheet map and report (published by the department of Environment, Climate Change and Water NSW) indicates the site is within the Bathurst Soil Landscape comprising non-calcic brown soils with noted general soil properties including low soil salinity, moderate erosion hazard and moderate shrink-swell potential.



#### 3.2 SURFACE CONDITIONS

The site covers an area of approximately 4.1 hectares between Howick, Mitre, Durham and Commonwealth Streets, West Bathurst as shown on the locality plan on **Drawing 1** attached in **Appendix A**. **Drawing 1** also contains a recent aerial image of the site and shows the approximate investigation test locations.

The site is located on the lower slopes of a north-east facing hill with overall slopes of about 5-10°. The site levels have been significantly modified by cut and fill earthworks, primarily cut below the south-west of the main services building lower storey/car parking/loading dock areas and fill over the north-east of the site.

The site contains the existing hospital buildings, asphalt driveways and car parking, concrete loading dock and ambulance bay hardstands and landscaped areas as shown on the aerial image on **Drawing 1**.

An approximately 2m height cut in residual soils and extremely weathered granite was observed in a subfloor area to the west of the loading dock at the western end of the site. A fill batter was present beyond the car parking areas around the northeastern edge of the site. Silty/clayey sand soils and extremely weathered granite fragments were observed were exposed on the edge of the fill batter.

#### 3.3 SUBSURFACE CONDITIONS

The subsurface conditions encountered at the test locations are detailed on the engineering logs attached in **Appendix C**.

Geotechnical sections providing a visual summary of the subsurface conditions are provided on **Drawing 2**, **Drawing 3** and **Drawing 4** in **Appendix A**.

A summary of the depths to the various subsurface materials encountered at the test locations is provided in **Table 7**. A general description of the various subsurface materials encountered is provided in **Table 8**.



Health Infrastructure Geotechnical Investigation Bathurst Hospital Redevelopment RCA ref 16547-202/4, October 2024 Client ref HI23010

			D	epth (m)			
Test Pit/ Bore	Pavement Materials	Fill	Topsoil	Residual Soil	Extremely Weathered Granite	Highly Weathered Granite	Termination Depth (m)
BH1	N/A	0 - 0.6	not encountered	0.6 - 3.0	3.0 - 6.0	6.0 - 11.3	11.3
BH2	0 - 0.2	not encountered	not encountered	not encountered	0.2 - 4.8	4.8 - 9.9	9.9
BH3	0 - 0.6	0.6 - 1.5	not encountered	1.5 - 3.0	3.0 - 8.0	not encountered	8.0
BH4	0 - 0.2	0.2 - 0.5	not encountered	not encountered	0.5 - 3.9	3.9 - 9.9	9.9
BH5	0 - 0.3	0.3 - 1.6	not encountered	not encountered	1.6 - 5.3	5.3 - 19.8	19.8
BH6	0 - 0.1	0.1 - 7.5	not encountered	not encountered	not encountered	7.5 - 16.2	16.2
BH7	0 - 0.3	0.3 - 1.9	not encountered	1.9 - 2.6	2.6 - 5.4	5.4 - 10.0	10.0
BH8	N/A	0 - 6.1	not encountered	not encountered	6.1 - 7.3	7.3 - 19.3	19.3
BH9	0 - 0.7	not encountered	not encountered	0.7 - 1.5	not encountered	not encountered	1.5
BH10	not encountered	0 - 1.1	1.1 - 1.3	1.3 - 1.6	not encountered	not encountered	1.6
TP1	not encountered	not encountered	0 - 0.6	not encountered	0.6 - 1.3	not encountered	1.3
TP2	not encountered	0 - 0.7	0.7 - 0.9	0.9 - 1.4	1.4 - 1.9	not encountered	1.90

#### Table 7 Summary of Depths to Subsurface Materials at Test Locations

Health Infrastructure Geotechnical Investigation Bathurst Hospital Redevelopment RCA ref 16547-202/4, October 2024 Client ref HI23010



Page 8

AWS-TEM-010/1

	Description of oussurace materials				
Layer	Description	Typical Characteristics/Extent			
Pavement Materials	Concrete/asphaltic concrete over gravel base materials	Up to 0.7m thickness.			
	Typically sandy soil materials with a significant fines component.				
	Clayey fill materials encountered in BH3 and BH10.	Fill to depths of up to 7.5m			
Fill	Details in regard to placement and compaction of the existing fill at the site are unknown, however in the absence of earthworks documentation the existing fill at the site would be considered as uncontrolled fill.	encountered at the eastern end of the site.			
Topsoil	Silt materials	Only encountered in BH10, TP1 and TP2.			
Residual	Low to medium plasticity clay residual soils encountered in BH1, BH3 and BH7.	Lip to 2 4m thick			
Soil	Sandy residual soils with a significant fines component encountered in BH9, BH10 and TP2	Up to 2.4m thick.			
Extremely Weathered	Engineering properties of weakly	Some very high strength corestones encountered within extremely weathered profile.			
Granite	cemented very dense sandy soil.	Varies from not present to up to at least 5m thickness.			
		Core readily disintegrates under hand pressure.			
Highly Weathered	Coarse grained, crystalline structure. Very low strength.	Some very high strength corestones encountered within highly weathered profile.			
Granite		Deeply weathered granite profile with no further significant increase in strength with depth encountered in the boreholes.			

 Table 8
 Description of Subsurface Materials

#### 3.4 **G**ROUNDWATER

Groundwater was not encountered within the augered portion of the boreholes or within the test pits during or shortly after drilling/excavation. No longer term groundwater monitoring was carried out.

The addition of water to the boreholes during coring prevented meaningful groundwater observations within the cored portion of the boreholes.

Groundwater conditions are expected to vary with changes in climate and site conditions.

Transient/perched groundwater seepage could be expected to occur at the soil-rock interface following periods of rainfall. The possible presence of a deeper groundwater table within the extremely or highly weathered granite profile within the depths of excavation required for the development is expected to be unlikely.

Specific groundwater investigation to inform a groundwater assessment in accordance with the NSW Government January 2022 published *Guidelines for Groundwater Documentation for SSD/SSI Projects* document was not within the scope of the geotechnical investigation. Notwithstanding, and with reference to these guidelines following completion of the investigation and based on the information available, the project is expected to be located above the groundwater table and thus is unlikely to have a major impact on groundwater systems.

Where definitive information on groundwater levels at specific locations on the site is required, this should be further investigated by installing groundwater monitoring well(s) in boreholes and monitoring the water levels over a period of time.

#### 4 DISCUSSION AND COMMENTS

#### 4.1 GEOTECHNICAL CONDITIONS

Significant geotechnical features relevant to proposed development include the following:

- Deep fill to depths up to in the order of 8m was encountered over the eastern portion of the proposed development area.
- The natural subsurface materials at the site are associated with deeply weathered granite profile. Rock strength is typically very low with no further significant increase in rock strength with depth up to about 20m encountered in the boreholes.

#### 4.2 EXCAVATIONS

Draft schematic design drawings prepared by Taylor Thomson Whitting (Ref Project No. 231092, Revision A) show a proposed finished floor level of RL 665.765m for the proposed new building Level 00 in the eastern corner of the site which would require up to approximately 5m of excavation below existing site levels.

If/where excavations in proximity to existing structures are required, care and appropriate measures should be taken to ensure that the stability and support of the adjacent structures is maintained. This may require measures such as shoring and/or prior installation of excavation support (e.g., soldier pile wall or contiguous pile retaining wall) installed prior to excavation. Where existing footings and occur within a 2H:1V projection from the base of any proposed excavations, it is recommended that allowance should be made for the full support of the excavations.

It is suggested that full height retaining structures will be required as part of the final structure and may be used to temporarily support the excavation during the excavation and construction phase.



Excavations in the fill and residual soil materials are expected to be achievable by conventional earthmoving equipment such as backhoes and excavators. At the test pit locations TP1 and TP2, excavations are expected to be achievable to the depths shown on the test pit logs.

The extremely weathered and highly weathered granite materials are expected to be more resistant to excavation and may require heavy excavation equipment, e.g., bulldozers/large excavators and/or rock breakers to facilitate excavation.

Noise and vibration will be generated by excavation work on the site and allowance for this should be made during design and construction given the close proximity to hospital buildings.

It is recommended that long-term excavations should be battered at an appropriate batter slope for the material in which the excavation is undertaken and protected against erosion by vegetation and the provision of adequate drainage or be supported by properly designed and constructed retaining walls. Recommended batter slopes for temporary and long-term or permanent excavations are provided in **Table 9**.

	Recommended Maximum Batter Slopes for Excavations				
Strata	Temporary Excavations	Long-term or Permanent Excavations			
Existing silty and clayey sand fill	1.5H:1V	2H:1V			
Residual soils and extremely weathered granite with residual soil properties	1H:1V	2H:1V			
Highly weathered, very low strength granite	0.5H:1V	1H:1V			

 Table 9
 Recommended Batter Slopes for Excavations

It is noted that excavations in rock may be able to be battered steeper than that shown in **Table 9** subject to specific geotechnical assessment of the rock profile exposed in the excavations.

#### 4.3 FILLING

Any filling on the site should be placed and compacted in accordance with AS3798-2007, Guidelines on Earthworks for Commercial and Residential Development.

From a geotechnical perspective, material excavated from the site would generally be suitable for use as engineered fill provided deleterious material and particles with sizes greater than 75mm diameter are removed.



The placement and compaction of any proposed engineered fill to support structural loads should be undertaken in accordance with *AS* 3798-2007. Where it is proposed to found footings for the proposed new buildings in engineered fill, Level 1 supervision (as defined in *AS* 3798-2007) of earthworks should be undertaken.

All fill should be supported by properly designed and constructed retaining walls or else battered at 2H:1V or flatter and protected against erosion by vegetation or similar and the provision of adequate drainage provided with lining to minimise erosion.

If/where fill is to be placed on slopes of surface gradient greater than about 8H:1V (about  $7^{\circ}$ ) a benched (stepped) foundation should be cut into the slope to provide a level platform for the fill.

#### 4.4 RETAINING STRUCTURES

Design of retaining walls should:

- Consider surcharge loading from slopes, structures above and backfill behind the wall.
- Provide adequate subsurface and surface drainage.
- Utilise materials that are not susceptible to deterioration.
- Provide for full drainage or make provision to support full hydrostatic load.

Preliminary geotechnical design parameters for retaining wall design are presented in **Table 10**. Note that the parameters provided in **Table 10** do not include allowance for surcharge loads, slopes above the wall and hydrostatic pressure.

	Geotechnical Parameters					
Material	Bulk Unit Weight (kN/m³)	Cohesion c' (kPa)	Friction Angle ∳' (degrees)	At Rest <sup>(1)</sup> Coefficient of Lateral Earth Pressure	Active <sup>(2)</sup> Coefficient of Lateral Earth Pressure	
Fill	19	0	25	0.58	0.4	
Residual soils	19	5	25	0.58	0.4	
Extremely weathered granite	22	5	30	0.50	0.33	
Highly weathered, very low strength granite	24	10	35	0.43	0.27	

 Table 10
 Preliminary Geotechnical Parameters for Retaining Wall Design

(1) At Rest Lateral Earth Pressure for design of rigid and permanent walls.

(2) Active Lateral Earth Pressure for design of temporary flexible walls (eg cantilever walls).



It is recommended that geotechnical inspection of rock excavation is carried out to assess for the presence of adverse defects/structure that could affect short term stability and increase the pressures acting on retaining walls.

Foundations for retaining structures may be based on the parameters presented in **Table 11** and **Table 12**.

#### 4.5 FOOTINGS

All footings for structures should be founded below any existing fill, topsoil or deleterious soils and it is recommended that footings for the same structure should be founded on the same strata to minimise potential differential movements.

#### 4.5.1 HIGH-LEVEL FOOTINGS

High-level footing alternatives for the proposed new buildings could be expected to include slabs on ground with edge beams or pad footings for the support of concentrated loads. These high-level footing types could be founded on dense/very stiff or better residual soils or extremely weathered granite below any topsoil, or existing fill, or founded on engineered fill that is placed and compacted in accordance with *AS 3798-2007*.

It is recommended that footings for the same structure should be founded on the same strata to minimise potential differential movements.

Following bulk excavation for the proposed new building Level 00 towards the eastern corner of the site the exposed subgrade is expected to comprise a range of materials including:

- Existing uncontrolled fill materials including silty/clayey sand fill material with low standard penetration test N values of less than 10 recorded in the boreholes.
- Residual soils
- Extremely weathered granite

It is considered that the existing fill materials could either be excavated and replaced as engineered fill to facilitate construction of high-level slab on ground footings (with due regard for the potential for differential movements associated with, e.g., areas of extremely weathered granite subgrade and areas of engineered fill subgrade), or ground floor slabs over the existing fill materials left in place could be designed as suspended slabs.

Where the existing fill materials are left in place it is recommended that ground floor slabs over the existing fill materials are designed as suspended slabs. The existing fill materials, following proof roll to identify and weak or unsuitable areas and to compact the near surface materials, are expected to be suitable for support of temporary/construction loading including support of wet weight of concrete for suspended slab design



It is suggested that high-level footings may be proportioned based on the allowable bearing pressures shown on **Table 11**. Settlements of high-level footings under these design allowable bearing pressures are estimated to be less than 5-10mm.

Founding Strata	Allowable Bearing Pressure (kPa)
Engineered fill that is placed and compacted in accordance with <i>AS 3798-2007</i> under Level 1 inspection and testing	100
Residual soils	
- Dense or better relative density sand soils	150
- Very stiff or better consistency clay soils	
Extremely Weathered Granite	400
Highly Weathered Granite	700
- Very low strength	700

 Table 11
 Allowable Bearing Pressures for High Level Footings

Inspection of high-level footing excavations should be undertaken during construction to confirm founding conditions. The base of all footing excavations should be cleaned of fall-in prior to formation of the footing.

Piered footings are an alternative to high-level footings and are discussed in the following section.

#### 4.5.2 PIERED FOOTINGS

Suitable founding strata for piered footings are expected to comprise extremely weathered and highly weathered granite.

It is suggested that piered footings may be designed based on the parameters shown in **Table 12**.

Founding Strata	End Bearing Pressure (kPa)		Ultimate Shaft Adhesion <sup>(3)</sup> (kPa)		Young's Modulus <sup>(5)</sup>
	Ultimate <sup>(1)</sup>	Serviceability <sup>(2)</sup>	Compression	Uplift	Modulus
Dense/very stiff or better residual clay soils	-	-	40	20	30
Extremely Weathered Granite	3000	400	80	40	50
Highly Weathered, Very Low Strength Granite	5000	1000	150	75	100

Table 12Design Parameters for Bored Piers

(1) Ultimate values occur at large settlement (>5% of minimum footing dimensions).

(2) End bearing pressure to cause settlement of <1% of minimum footing dimension.

(3) Shaft adhesion should be ignored for the upper part of the subsurface profile for a depth corresponding to a minimum of three pier diameters.

(4) Parameters for piers assume L>4D (L= pier length, D = pier diameter).

(5) E' is stress dependent and should be selected from the appropriate stress range as required.

Any fall-in should be removed from the base of footing excavations or pier holes prior to the formation of the footings. Bored pier installation would require specific attention to removal of debris from socket bases and the base of all pier holes should be cleaned of fall-in prior to formation of the pier.

It is recommended that inspection of the footing excavations or pier holes be undertaken by an experienced engineer at the time of construction to confirm founding conditions.

#### 4.5.3 GEOTECHNICAL STRENGTH REDUCTION FACTOR

At this stage it is recommended that a geotechnical strength reduction factor ( $\phi_g$ ) of 0.5 be adopted. Depending on the proposed structural design system and proposed pile testing and construction verification level the geotechnical strength reduction factor will be able to be revised for detailed design.

#### 4.6 SITE CLASSIFICATION

The proposed development is beyond the scope of *AS2870-2011*. Discussion and comments in this section are provided for guidance.

In accordance with AS2870-2011 the site is classified as Class P due to the following:

- Abnormal moisture conditions associated with the existing structures at the site which are likely to have significantly modified the soil moisture conditions below.
- The presence of fill at the site.



The Atterberg limit and linear shrinkage laboratory test results summarised in **Table 2** indicate the clay soils samples tested are of low plasticity. Linear shrinkage values of 8% or less were recorded.

The boreholes indicated variable subsurface conditions including predominantly sand soils or low to medium plasticity clay soils over extremely weathered granite.

Based on the subsurface conditions encountered in the boreholes and interpretation of the laboratory test results, in the absence of abnormal moisture conditions characteristic surface movements at the site are calculated to be within the range associated with Class M - Moderately Reactive site classification as defined in *AS2870-2011*.

#### 4.7 EARTHQUAKE DESIGN

Based on the geotechnical investigation borehole information the site is classified as a Subsoil Class  $C_e$  – shallow soil site in accordance with AS 1170.4-2007.

It is noted that the highly weathered, very low strength granite does not meet the minimum compressive strength requirement to be considered as a rock site in accordance with AS *1170.4-2007*.

#### 4.8 DURABILITY DESIGN

Soil and rock samples were submitted for laboratory testing to assess potential for aggressive soil conditions that could impact on buried concrete and steel elements. Results of the analysis were compared to aggressivity levels in the Piling – Design and Installation Standard (AS2159-2009). The laboratory test reports for aggressivity are attached in **Appendix C** and results are summarized in **Table 6**.

Exposure classifications based on AS2159-2009 are presented in Table 13.

Bore	Depth (m)	Soil Type	Aggressivity to buried steel elements	Aggressivity to buried concrete elements
BH3	0.55 - 1.00	Gravelly Sandy CLAY	NOD-2007ESSIVE NOD-2007E	
BH5	2.3 - 2.8	Extremely Weathered GRANITE	Non-aggressive	Non-aggressive
BH6	1.5 -1.95	Silty SAND, trace of clay	Non-aggressive	Non-aggressive
BH6	3.0 - 3.45	Silty SAND, trace of clay	Non-aggressive	Non-aggressive
BH7	5.8 - 6.0	Highly Weathered GRANITE	Non-aggressive	Non-aggressive
BH8	3.1 - 3.45	Silty SAND, trace of clay	Non-aggressive	Non-aggressive
BH8	4.5 - 4.95	Silty SAND, trace of clay	Non-aggressive	Non-aggressive

Table 13	Summary of Soil and Rock Aggressivity Results

Health Infrastructure Geotechnical Investigation Bathurst Hospital Redevelopment RCA ref 16547-202/4, October 2024 Client ref HI23010



AWS-TEM-010/1

Bore	Depth (m)	Soil Type	Aggressivity to buried steel elements	Aggressivity to buried concrete elements
BH8	5.8 - 6.0	Silty SAND, trace of clay	Non-aggressive	Non-aggressive

The test results indicate non-aggressive conditions to buried steel and concrete in accordance with *AS2159-2009*.

#### 4.9 PAVEMENTS

#### 4.9.1 SUBGRADE CONDITIONS SUPPORT PARAMETERS

The natural subgrade conditions encountered in the test pits and BH9 comprised residual sandy soils or extremely weathered granite. The subgrade materials contain a significant proportion of silt and clay fines which are expected to influence the subgrade support properties.

Laboratory CBR values of 6%, 10% and 8% were recorded on samples of the subgrade materials from the test pits and BH9.

Due to the variability in the laboratory CBR results and expected variable composition and fines content in the natural subgrade materials it is suggested that design subgrade CBR value of 5% be adopted for pavement design purposes.

Estimates of subgrade Young's modulus for the residual soils are as follows:

- Short-term loading 35MPa
- Long-term loading 25 MPa

#### 4.9.1 PAVEMENT MATERIALS AND COMPACTION REQUIREMENTS

Pavement material specifications and compaction requirements for unbound pavement materials are shown on **Table 14**.

Table 14         Pavement Materials and Compaction Requirement
--

Pavement Layer	Material Specification	Compaction Requirements
<u>Basecourse</u> High quality crushed rock or base quality gravel	Material complying with RMS QA Specification 3051 (Ref [4]). CBR > 80% PI < 6%	Min 98% Modified (AS 1289 5.2.1)
<u>Subbase</u> Subbase quality gravel	Material complying with RMS QA Specification 3051 (Ref [4]). CBR > 30% PI < 12%	Min 95% Modified (AS 1289 5.2.1)
<u>Fill</u> Select subgrade or subgrade replacement	CBR > 15%	Min 100% Standard (AS 1289 5.1.1)

Health Infrastructure Geotechnical Investigation Bathurst Hospital Redevelopment RCA ref 16547-202/4, October 2024 Client ref HI23010



Subgrade		Min 100% Standard (AS 1289 5.1.1)
----------	--	--------------------------------------

CBR – California bearing ratio, PI – Plasticity index.

#### 4.9.2 SUBGRADE PREPARATION

Subgrade preparation for pavement construction could generally be expected to comprise the following:

- Excavation to subgrade formation level.
- Ripping of any weathered rock exposed at subgrade formation level to a minimum depth of 300mm below subgrade formation level.
- Proof rolling of the exposed subgrade with a heavy (minimum 10 tonne static) roller. Soft or weak areas detected during the proof rolling should be excavated and replaced with compacted select fill/subgrade replacement.

Compaction of the subgrade to achieve a minimum dry density ratio of 100% Standard (AS 1289 5.1.1).

#### 4.9.1 PAVEMENT DRAINAGE

The moisture regime associated with a pavement has a major influence on the performance of the pavement since the stiffness/strength of the pavement materials and subgrade is very dependent on the moisture content of the materials. Accordingly, to protect the pavement materials and subgrade from wetting up and softening, particular care would be required to provide a waterproof seal for the pavement materials and adequate surface and subsurface drainage of the pavement and adjacent area.

It is recommended that subsoil drains should be provided at the edge of pavements and interface with adjoining pavements.

Where subsoil drains will be subject to traffic it is suggested that no fines concrete be used for the drainage material.

#### 4.10 SALINITY

The Soil Landscapes of the Bathurst 1:250,000 Sheet map and report (published by the department of Environment, Climate Change and Water NSW) indicates the site is within the Bathurst Soil Landscape comprising non-calcic brown soils with noted general soil properties including low soil salinity.

The soil chemistry test results summarised in Sections 2 and 4.8 indicate non-aggressive conditions to buried steel and concrete in accordance with *AS2159-2009*. The limited soil electrical conductivity testing carried out for the geotechnical investigation indicates non-saline or slightly saline soil conditions

No evidence of salinity (e.g. staining, die back of trees, presence of indicator vegetation species etc.) was noted during the site fieldwork.



The findings of the geotechnical investigation indicate a Salinity Management Plan is not required.

#### 4.11 ACID SULFATE SOILS.

Published maps, the site location and elevation, together with the soil pH testing values recorded of between 6.5-7.8 (summarised in Section 2) indicate a very low probability of the presence of acid sulfate soils at the site.

The findings of the geotechnical investigation indicate an Acid Sulfate Soils Management Plan is not required.

#### 5 LIMITATIONS

This report has been prepared for Health Infrastructure in accordance with the agreement with RCA. The services performed by RCA have been conducted in a manner consistent with that generally exercised by members of its profession and consulting practice.

This report has been prepared for the sole use of Health Infrastructure for the specific purpose and the specific development described in the report. The report may not contain sufficient information for purposes or developments other than that described in the report or for parties other than Health Infrastructure. This report shall only be presented in full and may not be used to support objectives other than those stated in the report without permission.

The information in this report is considered accurate at the date of issue with regard to the current conditions of the site. The conclusions drawn in the report are based on interpolation between boreholes or test pits. Conditions can vary between test locations that cannot be explicitly defined or inferred by investigation.

Yours faithfully RCA AUSTRALIA

Robert Cater Senior Geotechnical Engineer

#### REFERENCES

Mr. All

Dr Mark Allman Principal Geotechnical Engineer

- [1] Standards Association of Australia. AS 2870-2011: Residential Slabs and Footings – Construction. Standards Association of Australia, 2011.
- [2] Standards Association of Australia. AS 3798-2007: Guidelines on Earthworks for Commercial and Residential Structures. Standards Association of Australia, 2007.

Health Infrastructure Geotechnical Investigation Bathurst Hospital Redevelopment RCA ref 16547-202/4, October 2024 Client ref HI23010



- [3] Standards Association of Australia. AS 2159-2009: Piling Design and Installation. Standards Association of Australia, 2009.
- [4] Roads and Maritime Services. "Granular Pavement Base and Subbase Materials", QA Specification 3051, Edition 7 / Revision 0, August 2018

AWS-TEM-010/1



- Drawing 1 Site and Test Location Plan
  - Drawing 2 Geotechnical Section A-A
  - Drawing 3 Geotechnical Section B-B
  - Drawing 4 Geotechnical Section C-C






- Approximate site boundary
- Geotechnical section
- Approximate test pit location
- Approximate borehole location
- Approximate hand auger location
- Approximate 300mm dia.pavement borehole location


Note: Aerial image taken from Nearmap, 25 February 2023 (used in accordance with commercial licence)





#### SITE AND TEST LOCATION PLAN BATHURST HOSPITAL BATHURST

frastructure		RCA Ref		16547-2	02/2		
RC	SCALE	1:1,500 (A3)	DRAWING	3 No	1	REV	1
MA	DATE	29/08/2023	OFFICE	NEW	CASTLE		



LEGEND

Geotechnical Units

ASPHALT

TOPSOIL


FILL

To Durham Street

IA	
ENTAL	

#### GEOTECHNICAL SECTION A-A BATHURST HOSPITAL BATHURST


tructu	ire		RCA Ref	16547-202/2		
	SCALE	As Shown (A3)	DRAWING No	2	REV O	
	DATE	4/08/2023	OFFICE NEWCASTLE			




Mitre Street

#### GEOTECHNICAL SECTION B-B BATHURST HOSPITAL BATHURST

tructu	ire		RCA Ref	16547-2	202/2
	SCALE	As Shown (A3)	DRAWING No	3	REV O
	DATE	4/08/2023	OFFICE N	EWCAS	TLE





#### **GEOTECHNICAL SECTION C-C** BATHURST HOSPITAL BATHURST

tructu	ıre		RCA Ref	16547-2	202/2
	SCALE	As Shown (A3)	DRAWING No	4	REV O
	DATE	4/08/2023	OFFICE <b>N</b>	EWCAS	TLE

# Appendix B

Engineering Logs Core Photographs Test Pit Photographs Explanatory Notes



# **GEOTECHNICAL BOREHOLE LOG**

BH1

SHEET 1 OF 4

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 09/06/2023 DATE COMPLETED: 09/06/2023 SURFACE RL: 674.80 m AHD COORDS:

		Borehole In	formatic	n				Field Material Infor	mation		
METHOD	WATER	FIELD TEST	SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME;plasticity/grain size, particle shape, colour, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	(5	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
		0.50m SPT 3, 6, 11 N=17 -PP>600kPa 0.95m	0.50m BH1a (0.6-0.7n D (0.5-0.94 <u>0.95m 1.00m</u> BH1b 1.20m				SM CL- CI	FILL, Silty SAND, fine to medium grained, brown, trace of gravel	M w <pl< td=""><td>Н</td><td>FILL Grass on surface - RESIDUAL</td></pl<>	Н	FILL Grass on surface - RESIDUAL
AD/T	(Not Encountered)	1.50m SPT 4, 9, 15 N=24 -PP>600kPa 1.95m	<u>1.50m</u> BH1c (1.8-2.0n D (1.5-1.9ຢ 2.00m	ľ	- - - - - - - - - - 2.0			becoming with extremely weathered granite lenses/zones at 2.2m			NOTE: Borehole surface RL estimated based on supplied sur plan (borehole not surveyed)
ws		3.00m 3.04m SPT 5/40mm N=R	3.00m D (3.04m	672.0 - - - - - - - - - - - - - - - - - -	- - - - - - - - - - - - - - - - - - -	+ + + -		Extremely Weathered Granite, properties of Silty Clayey SAND,, orange-brown CONTINUED AS CORED BOREHOLE	XW	VD	EXTREMELY WEATHERED MATERIAL
				671.0 671.0 - - - - - - - - - - - - - - - - - -	- 3.3 						-
I	_0G	GED: RC		-	+		CF	ECKED: MA	DA	TE: 04/0	)8/2023



# CORED BOREHOLE LOG

BH1 SHEET 2 OF 4

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 09/06/2023 DATE COMPLETED: 09/06/2023 SURFACE RL: 674.80 m AHD COORDS:

	Во	reho	ole	Info	rmati	on		Field Material Description
METHOD	WATER LOSS	CORE	RECOVERY	RQD	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, 
RCA_LIB_081_RCA_STANDARD.GLB_Log_RCA_CORED_BOREHOLE_LOG_16547-LOGS.GPJ_ <cdrawingfile>&gt; 04/08/2023 13:09 Produced by gINT Professional, Developed by Datgel NMI_C NMI_C</cdrawingfile>				6	674.5 - 674.0 - 673.5 - 673.0 - 6773.0 - 572.5 -			START CORING AT 3.15m
08.1_RCA_STANDARD.GLB_Log_RCA.CORED.BOREHOLE.LOG_16547-LOGS.GPJ_< <drawi< th=""><th></th><th></th><th>100</th><th></th><th>671.5 - 671.0 - 670.5 -</th><th></th><th></th><th>GRANITE, coarse grained, orange-brown and grey XW</th></drawi<>			100		671.5 - 671.0 - 670.5 -			GRANITE, coarse grained, orange-brown and grey XW
RCA_LIB_C	LO	GGE	ED:	RC	;			CHECKED: MA DATE: 04/08/2023



CLIENT: Health Infrastructure

LOCATION: Bathurst Hospital

PROJECT: Geotechnical and Contamination Investigation

PROJECT No: 16547

# CORED BOREHOLE LOG

BH1 SHEET 3 OF 4

DATE COMMENCED: 09/06/2023 DATE COMPLETED: 09/06/2023 SURFACE RL: 674.80 m AHD COORDS:

F				rmatic	-				Field	Materi		Descript			-	· · ·		
METHOD	WATER LOSS	RECOVERY		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	partic	DESCRIPTIO NAME; plasticity/grair cle shape, secondary of nstituents) (ROCK NA colour, minor constitu	N n size, colour, components, ME; grain size,	THERING	INF STF		) A I [ S	VER DEFI	ECT XING	AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling,		
		100	° (	- 569.5 - - -	- 5.00 - - - 5.5 -	· + + · + +		coarse grained, white, exture, indistinct fabric		XW								
v1 < <drawingfile>&gt; 04/08/2023 13:09 Produced by gINT Professional, Developed by Dalgel NMLC</drawingfile>	- SSO1 %0 -	100			- 6.0 6.0 					HW	•					Note: Granite core disintergrates readily into sandy soil under hand pressure     FE infilled defect, tight, up to 6mm thick		
RCA_LIB_081_RCA_STANDARD.GLB_L0g_RCA_CORED_BOREHOLE.LOG_16547-LOGS.GPJ		100	100		- 8.5 - - - - - - - - - - - - - - - - - - -	$\begin{array}{cccccccccccccccccccccccccccccccccccc$												
RCA_LIB_	LOG	GED	RC	;				CHECKED: MA	4						DATE: 04/08/2023			




# CORED BOREHOLE LOG

BH1

SHEET 4 OF 4

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 09/06/2023 DATE COMPLETED: 09/06/2023 SURFACE RL: 674.80 m AHD COORDS:

				ormati			Fie	ld Mater							000 0-D
METHOD	WATER LOSS	RECOVERY		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	THERING	IN ST	FER	RREI NGT MPa	D /	AVE DEI SPA	RAG FEC (CIN)	T AND ADDITIONAL OBSERVATIONS G (defect type, inclination, infilling,
NMLC	0% FOSS	100	100	664.5 -	- - - - - - - - - - - - - - - - - - -	+ + + + + + + + + + + + + + + +	GRANITE, coarse grained, white, grey and brown, crystallite texture, indistinct fabric	S HW						100	
	<b>V</b>		6	63.5-	- 	+ + + + + + + + + + + + + + + + + + + +	CORED BOREHOLE BH1 TERMINATED AT 11.30 m								
			6	563.0 -	+ + + - - 12.0										
			6	62.5 -	- - - - 12.5 -	5									
			6	562.0 -	- - - 13.0 -										
			6	61.5-	- - - 13.5 -	5									
			6	561.0 <i>-</i>	+ + - - 14.0 -										
			6	60.5 -	+ + - - 14.5 -	5									
			6	560.0 -	+										
L	OG	GED	RC	;			CHECKED: MA							D	ATE: 04/08/2023





BH2

SHEET 1 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 05/06/2023 DATE COMPLETED: 05/06/2023 SURFACE RL: 668.80 m AHD COORDS:

		Borehole					Field Material Infor	-			
						Z			¥		
METHOD	WATER	FIELD TEST	SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME;plasticity/grain size, particle shape, colour, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
DT			0.20m		- 0.49			CONCRETE, 180mm thick			LOADING DOCK/CAR PARKING SURFACE
			BH2	668.5 -	0.18 = 0.20	+++++++++++++++++++++++++++++++++++++++	GP SM	FILL, GRAVEL, medium, dark grey, sub-angular Extremely Weathered Granite, properties of Silty	XW	VD	FILL EXTREMELY WEATHERED MATERIAL
		0.50m	0.50m		-0.5			SAND, fine to coarse grained, trace of clay			
	untered).	0.54m SPT 5/40mm N=F	0.54m	_  .	+						
	(Not Encountered)		0.90m	668.0-	-						
			BH2a		- 1.0						NOTE: Borehole surface RL estimated based on supplied su plan (borehole not surveyed)
			1.20m			+ + +					
		1.48m	1.48m	667.5-							
		1.50m SPT 5/20mm N=F	1.50m		+-1.5- 			CONTINUED AS CORED BOREHOLE			
		<u>5/20111111111111111111111111111111111111</u>		667.0-	+						
					-2.0						
					+						
				666.5 -	+						
					-2.5						
				666.0-	-						
					- 3.0						
					_						
				 665.5							
					- 3.5						
					Ī						
				665.0 -							
					-4.0						
				664.5	ŧ						
					-4.5						
					+						
				664.0-	+						
			1		1					<u> </u>	
L	-06	GGED: RC					Cł	IECKED: MA	DA	TE: 04/0	08/2023



BH2

SHEET 2 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 05/06/2023 DATE COMPLETED: 05/06/2023 SURFACE RL: 668.80 m AHD COORDS:


				ormatio	-			Fie	eld Mate				-		
MEIHOU	WATER LOSS	RECOVERY		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	partic	DESCRIPTION NAME; plasticity/grain size, colour, cle shape, secondary components, nstituents) (ROCK NAME; grain size, colour, minor constituents)	WEATHERING	IN S <sup>-</sup> I	JFEF TREI S <sub>(50)</sub>	RRE[ NGTI MPa	VEF DEF SPAC	ECT CING	AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling,
				668.5 -	- 0.5										
	•			667.5 -		+ +		RING AT 1.50m coarse grained, orange-brown and grey	× ×						
		100	0	667.0-	- - - - 2.0	+ + + + + + + + + + + + + + + +									
				666.5-	- - - - 2.5		iron indurate 2.65m	ed/weakly cemented from 2.25m to							
		100	0	666.0-							8				
	- SSO7 %0	÷		665.5 -		+ + + + + + + + + + + +									
				665.0-	- - 4.0	+ + + + + + + + + + + + + + + +									
		100	0	664.5-	- - - 4.5	+ + + + + + + + + + + + + + + + + +									
		100	83	664.0 -	4.80 -	+ + + + + + + + + + + +	GRANITE, o and dark gro	coarse grained, orange-brown, pale gre ay, crystalline texture, indistinct fabric	y HW	•					Note: Granite core disintergrates readi into sandy soil under hand pressure
L	.OGC	GED	: RC	;				CHECKED: MA						DA	TE: 04/08/2023



BH2 SHEET 3 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 05/06/2023 DATE COMPLETED: 05/06/2023 SURFACE RL: 668.80 m AHD COORDS:

Borehole In	Information	Field	Mater	ial Descripti	on	
METHOD WATER LOSS RECOVERY	RQD RL (m AHD) DEPTH (m) GRAPHIC	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	WEATHERING	INFERRED STRENGTH Is <sub>(50)</sub> MPa	DEFECT	DEFECT DESCRIPTION AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling, planarity, roughness, thickness)
100	663.5 + + + + + + + + + + + + + + + + + + +	GRANITE, coarse grained, orange-brown, pale grey and dark grey, crystalline texture, indistinct fabric GRANITE, coarse grained, orange-brown, pale grey and dark grey, crystalline texture, indistinct fabric	E WEA		(mm) <u><u><u><u></u></u><u></u><u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u></u></u></u>	DZ 50 mm → DZ 50 mm JT 75° PR RF → DZ 180 mm
NMLC 0% LOSS	661.0 + + + + + + + + + + + + + + + + + + +	<pre>+ + + + + + + + + + + + + + + + + + +</pre>				— DZ 30 mm
	659.5 - + + + + + 659.0 - + + + + + + + + + + + + + + + + + +	* + + + + + + + + + + + + + + + + + CORED BOREHOLE BH2 TERMINATED AT 9.95 m				— JT 50° Fe PR S
LOGGED: F	660.0 - + + + + + + + + + + + + + + + + + +				DAT	— JT 50° Fe PR S — 50° Fe PR S





BH3

SHEET 1 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 08/06/2023 DATE COMPLETED: 08/06/2023 SURFACE RL: 674.10 m AHD COORDS:

		Borehole In	formatio	on				Field Material Infor	mation		
METHOD	WATER	FIELD TEST	SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME;plasticity/grain size, particle shape, colour, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
	A			674.0-	0.10	114		CONCRETE, 100mm thick			AMBULANCE BAY PAVEMENT
DT		0.55m	0.55m	-	- 0.5			CONCRETE, 440mm			
				673.5 -	0.55		CI- CH	FILL, Gravelly Sandy CLAY, medium plasticity, dark grey-brown, trace of brick fragments	w>PL		FILL .
		SPT	(0.55-0.7		t			grey-brown, trace of brick tragments			
		4, 14, 6 N=20	(0.55-1.0 BH3a	0m) <sup>-</sup>	Ť						
		1.00m	опза (0.9-1.1ı	m)	-1.0						
			1.10m	 •673.0			8				NOTE: Borehole surface RL estimated based on supplied sur
					ł						plan (borehole not surveyed)
	— (pe		1.30m		+						
	untere	1.50m	BH3b 1.50m	-	+						
	(Not Encountered)			- 672.5 -	- 1.50i ·		CI	Sandy CLAY, medium plasticity, orange-brown, fine to coarse grained sand, trace of fine gravel	1	VSt - H	RESIDUAL
	– (Noi	SPT	D		Ļ		į	coarse grained sand, trace of fine gravel			
AD/T		3, 3, 5 N=8 PP330 -	1.80m		ł						
		380kPa 1.95m	BH3c 1.95m 2.00m		ł						
					-2.0						-
				672.0-							
					I	///					
					Ļ	///					
					-2.5	///					-
				671.5-	+	///	1				
				-	t	///	1				
		2.90m			I						
	V	SPT 10/100mm	3.00m		-3.0-						
		N=R 3.00m		671.0 -	+			CONTINUED AS CORED BOREHOLE			
		0.0011			t						
					Ť						
					-3.5						
				 670.5	- 0.0						
					+						
					+						
				-	†						
				670.0 -	-4.0						
				.	ļ						
					+						
				-	ł						
				-	-4.5						-
				669.5 -	I						
					ļ						
					+						
						<u> </u>				<u> </u>	
ı	06	GED: RC					CF	IECKED: MA		TE: 04/0	18/2023
Ĺ		020.10								07/0	JU, LULU

RCA
A U S T R A L I A
GEOTECHNICAL • ENVIRONMENTAL

BH3

SHEET 2 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 08/06/2023 DATE COMPLETED: 08/06/2023 SURFACE RL: 674.10 m AHD COORDS:

	В	oreł	nole	Info	rmatic	n				Fi	eld Mat	eria	l De	scrip	otior	۱		
METHOD		· ^ _	RECOVERY		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	(SOIL partic minor co	DESCRIPTIC NAME; plasticity/gra cle shape, secondary nstituents) (ROCK N colour, minor const	DN ain size, colour, components, JAME; grain size,	RING		NFE STRE	RREI NGT MPa		VER DEFE	CT	AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling,
04/08/2023 13:10 Produced by gINT Professional, Developed by Datgel				6 6 6	574.0 - - - - - - - - - - - - - - - - - -	- 0.5 0.5 1.0 1.0 1.5 			RING AT 3.00m									
J < <drawingfile>&gt;</drawingfile>		•	100	0	671.0 -	<u>3</u> .00 - -	+ + + + + + + + + + + +		coarse grained, orang	ge-brown and gre	y XV	V						
RCA_LIB_081_RCA_STANDARD.GLB_L09_RCA_CORED_BOREHOLE_L0G_16547-L0G8.GP NMLC		- 0% LOSS	87	6		- 3.42 - - 3.5 - - 3.69 - - - 4.0 - - 4.0 - - - 4.5 - - - - - - - - -	+ + + + + + + + + + + + + + + + + + + +		S 0.27m (3.42-3.69) coarse grained, orang tructure	ge-brown and gre	y, XV	V	3					
RCA_LIB_(	LO	GG	BED:	RC	;				CHECKED: M	A							DAT	FE: 04/08/2023



BH3

SHEET 3 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 08/06/2023 DATE COMPLETED: 08/06/2023 SURFACE RL: 674.10 m AHD COORDS:

					ormatio	nospi		Field Material Description
METHOD	_	(0	RECOVERY		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)
			87	0	669.0 - - -	- - 	+ + + - + + +	GRANITE, coarse grained, orange-brown and grey, crystalline structure — JT 28° Fe PR S
					+ 668.5 - - - - 668.0 - -		$\cdot$ + + + + + + + + + + + + + + + + + + +	
			100	0	- - 667.5 - -	- 6.5  -	+ + + + + + + + + + + + + + + + + + +	
				(	- 	7.0   		
ראו מאוווקו וודר שי טעובטבט ואיוט רוטעטטע טין אוויו רוטופאאטוומו, בעימוטרעי טין במשמי		<b>V</b>		(		- 7.5 - - - - 8.00-	- + + + + + + + + + + + + + + + + +	
				(	666.0 - - - -			CORED BOREHOLE BH3 TERMINATED AT 8.00 m
				(	665.5 - - -			
וזטין בודיטטין ואיזיטין טואיטאואטיטר בעס ואטי סטאבו איר בייס ואיזי בעסטין א					665.0 - - - 664.5			
	L	OGC	GED	RC	-	-		CHECKED: MA         DATE: 04/08/2023

	GREY SCALE COTECHNICAL • ENVIRONMENTAL C M Y R C M Y R	PROJECT No: 16547 PROJECT: BATHURST HOSP LOCATION: BH3 DEPTH: 3.00-8.00 DATE: 08/06/2023	
Client:	Health Infrastructure		RCA Australia
Project:	Geotechnical Investigation	BH3 - Photograph 1 of 1	
Location:	Bathurst Hospital		RCA ref: 16547



BH4

SHEET 1 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital

DATE COMMENCED: 07/06/2023 DATE COMPLETED: 07/06/2023 SURFACE RL: 670.50 m AHD COORDS:

		Borehole Ir	oformatic	n				Field Material Infor	mation		
					Ê	0	NOI				
METHOD	WATER	FIELD TEST	SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME;plasticity/grain size, particle shape, colour, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
т	1			- I	0.13 -			CONCRETE, 130mm thick			CONCRETE FOOTPATH
			0.20m BH4 0.40m		0.13 - - 0.20 -		GM SM	FILL, Silty Sandy GRAVEL, fine to medium, dark grey, sub-angular FILL, Silty SAND, fine to coarse grained, brown	/ M		FILL
	untered)	0.50m 0.55m SPT	0.50		-0.50i -	+ +		GRANITE, pale grey, dark grey and orange	XW	EL	BEDROCK
	(Not Encountered)	10/50mm N=R	0.90m BH4a 1.10m	- - 669.5	- 1.0						NOTE: Borehole surface RL estimated based on supplied su plan (borehole not surveyed)
				-	ł	++++	-				TC Bit refusal at 1.3m
				669.0 -	- 1.5			CONTINUED AS CORED BOREHOLE			
				-	+						
				- 668.5	- 2.0						
				-	+						
				668.0-	- 2.5						
				-	-						
				- 667.5 -	3.0						
				-							
				- 667.0 -	-3.5						
				-	+						
				- 666.5 -	4.0						
				-	+						
				- 666.0	4.5						
				-	+						
				-							
L	.OG	GED: RC					CF	IECKED: MA			08/2023



BH4

SHEET 2 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 07/06/2023 DATE COMPLETED: 07/06/2023 SURFACE RL: 670.50 m AHD COORDS:

Γ	E	Bore	hole	Info	rmatio	on				Field N	Nater	ial D	escri	ptic	n		
	MEIHOU	WATER LOSS	CORE RECOVERY	RQD	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	partic	DESCRIPTION NAME; plasticity/grain si le shape, secondary cor nstituents) (ROCK NAM colour, minor constituer	nponents, E; grain size,	WEATHERING	STR Is <sub>(f</sub>	ERRE	TH a	DEF	ECT CING	AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling,
					- - - - - - - - - - - - - - - - - - -	-		START COF	RING AT 1.30m								
ſ			100	0	- 569.0	-	+ + + + +	GRANITE, c	oarse grained, brown		XW						
by gINT Professional, Developed by Datgel			100		-	- - - - - - - - - - - - - - -		GRANITE, c crystalline te	oarse grained, white, bro exture	own and grey,							
3:11 Produced			100	€	68.0 -	- 2.5	+ + + + + + + +										
RCA_LIB_081_RCA_STANDARD.GLB_Log_RCA_CORED_BOREHOLE_LOG_16647-LOGS.GPJ_< <drawingfile>&gt; 04/08/2023_13:11 Produced by gINT Professional, Developed by Datget</drawingfile>	NMLC		100	48		- -   - - - - - - - - - - - - -	$\begin{array}{c} + + + + + + + + + + + + + + + + + + +$	from 3.43m f	ength fresh granite core to 3.60m oarse grained, white, bro exture, indistinct fabric		HW			•			<ul> <li>JT 20° Clay VNR CU S</li> <li>Note: Point load test on granite corestone/fragment</li> <li>Note: Granite core disintergrates readily into sandy soil under hand pressure</li> </ul>
LIB_08.1_RCA_STANDARD.GLB_L0g_RCA_CORED_BORE			100		566.5 - - - 566.0 - - - - -	-	$\begin{array}{c} + & \cdot \\ + & + \\$					•					
RCA_L	LOGGED: RC								CHECKED: MA							DAT	TE: 04/08/2023



#### PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation

LOCATION: Bathurst Hospital


## CORED BOREHOLE LOG

BH4

SHEET 3 OF 3

DATE COMMENCED: 07/06/2023 DATE COMPLETED: 07/06/2023 SURFACE RL: 670.50 m AHD COORDS: DRILL MODEL: Hapijin D&B & D

				rmatio	-		Fie	ld Mate			ript		-		
METHOD	(0	RECOVERY		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	WEATHERING	IN S <sup>-</sup>	IFERF IREN s <sub>(50)</sub> M	RED GTH Pa	) A H I S	VEF DEF SPAC	ECT CING	AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling,
NMLC		100	9 00 9		- - - - - - - - - - - -	$\begin{array}{c} + & + & + & + \\ + & + & + & + & + \\ + & + &$	GRANITE, coarse grained, white, brown and grey, crystalline texture, indistinct fabric	HW					0 <del>-</del>	0 - 0	
NMLC			e	663.5 - - - - - - - - - - - - - - - - - -	- - -	$\begin{array}{cccccccccccccccccccccccccccccccccccc$									— DZ 50 mm
		96	94	- 662.0 - - -	- 8.5 - - - 8.87 -	+ + + + + + + + + + + + + + + + + + +	CORE LOSS 0.13m (8.87-9.00)								
				661.5 - - - 661.0 - - - -	- 9.00 - - - - - - 9.5 -	+ +	GRANITE, coarse grained, white, brown and grey, crystalline texture, indistinct fabric	HW							
				-	-		CORED BOREHOLE BH4 TERMINATED AT 9.85 I	n							
L	OG	GED	: RC	;			CHECKED: MA							DA	TE: 04/08/2023





#### **GEOTECHNICAL BOREHOLE LOG**

BH5

SHEET 1 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital

DATE COMMENCED: 07/06/2023 DATE COMPLETED: 07/06/2023 SURFACE RL: 669.70 m AHD COORDS:

	Borehole Information			Field Material Information								
METHOD	WATER		SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME;plasticity/grain size, particle shape, colour, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS	
	A							ASPHALTIC CONCRETE, 120mm thick	М		CAR PARK SURFACE	
				 669.5	0.12 -	$\bigotimes$		FILL, Silty Sandy GRAVEL			CAR PARK BASE MATERIAL	
			0.30m		0.27 -	XXX		FILL, Silty SAND, fine to coarse grained, brown and grey, trace of clay and gravel	-		FILL -	
			BH5 0. <b>50</b> m	-	†			grey, trace of clay and gravel			-	
					-0.5		k				-	
			D 0.5-0.95	 669.0	Ļ						-	
		4, 6, 9 N=15	BH5a (0.8-1.0r	m) <sup>-</sup>	+		k				-	
		0.95m	1.00m	-	†						-	
					+ 1.0		ł				NOTE: Borehole surface RL estimated based on supplied surv	
				 668.5 -	+						plan (borehole not surveyed)	
	(Not Encountered)		1.30m		ł						-	
AD/T	Encou	1.50m	BH5b 1. <b>50m</b>	-	†						-	
	- (Not	SPT		1 .	+ 1.5 + 1.60 -						-	
		9, 18/150mm N=R	D	 668.0	+	+ +	-	GRANITE, grey, dark grey and orange	XW	EL	BEDROCK	
		1.80m		-	ł	+ + + + + + + + + + + + + + + + + + + +					-	
			1.95m		+	+++++	1				-	
					-2.0	+++++	1				-	
				 667.5-	+	+ +					-	
					+	+ + +					-	
					+	+ +					-	
					-2.5	++++	1				-	
				 667.0-	Ļ	+ +					TC Bit refusal at 2.8m	
	Y	-			+	+ +		CONTINUED AS CORED BOREHOLE				
					-3.0						-	
					- 5.0						-	
				666.5 -	+							
				-	t							
					-3.5						_	
					+ 0.0							
				666.0 -	+							
				-	†							
					+4.0						_	
					+							
				665.5-	+							
				-	ŧ							
					+4.5							
					+							
				665.0 -	+							
					t						-	
					†						·	
L	-00	GED: RC					Cł	IECKED: MA	DA	TE: 04/0	08/2023	



BH5

SHEET 2 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 07/06/2023 DATE COMPLETED: 07/06/2023 SURFACE RL: 669.70 m AHD COORDS:

	Bore	ehole	Info	rmatic	n			F	ield N	lateria	al C	Desc	ript	ion			
METHOD	WATER LOSS	RECOVERY	RQD	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	partic	DESCRIPTION NAME; plasticity/grain size, colour, ele shape, secondary components, instituents) (ROCK NAME; grain size colour, minor constituents)	2,	Ξl	STI Is	ERF REN( 50) M	GTH IPa	I DI SF	EFE PAC	CT ING	DEFECT DESCRIPTION AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling, planarity, roughness, thickness)
2023 13:11 Produced by gIN 1 Professional, Developed by Datgel			6 6 6		- 1.0			RING AT 2.80m coarse grained, pale grey, brown and		XW							
	SS01 %0-	100 100	6 0		- 3.0 	+     + <td>dark grey, c</td> <td>hite, brown and grey at 4.3m</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	dark grey, c	hite, brown and grey at 4.3m									
KCA_LIB_00	LOG	GED	RC					CHECKED: MA								DAT	TE: 04/08/2023



## CORED BOREHOLE LOG

BH5

SHEET 3 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital

DATE COMMENCED: 07/06/2023 DATE COMPLETED: 07/06/2023 SURFACE RL: 669.70 m AHD COORDS:

Borehole Information	Field 1	Material Description
METHOD WATER LOSS RECOVERY ROD RL (m AHD) DEPTH (m)	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	O         INFERRED         AVERAGE         DEFECT DESCRIPTION           H         STRENGTH         DEFECT         AND ADDITIONAL OBSERVATIONS           K         Spacing         (mm)         (defect type, inclination, infilling, planarity, roughness, thickness)
Bind (Ar page)	<pre>+ + + + + + + + + + + + + + + + + + +</pre>	XW     Note: Granite core disintergrates readilinto sandy soil under hand pressure
BEHOLE LOG 16572.LOGS GPJ <-DawnigFile>> 040822023 13:11 Produced by Datage 	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	
ETANDARD GLB LOG CORED BC 660.5	+ + + + + + - + + + +	
LOGGED: RC	CHECKED: MA	DATE: 04/08/2023



## CORED BOREHOLE LOG

BH5

SHEET 4 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital

DATE COMMENCED: 07/06/2023 DATE COMPLETED: 07/06/2023 SURFACE RL: 669.70 m AHD COORDS:

DRILL MODEL: Hanjin D&B 8-D Field Material Description

				ormatio	Hospi		Fi	ield Mate		Descripti	-		
							DESCRIPTION						
METHOD	WATER LOSS	RECOVERY	RQD	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	(SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	WE/	ST 1 1 1 1 1 1 1	IFERRED IRENGTH s <sub>(50)</sub> MPa	DEFEC	ST NG	DEFECT DESCRIPTION AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling, planarity, roughness, thickness)
				-	+	+ +	GRANITE, coarse grained, white, brown and grey crystalline texture, indistinct fabric	, HW					
				659.5 - 1	-	+ + + +							
				-	ļ	+ + + + +							
				-	- 10.5	+ + + +							
				 659.0 –	+	+ + +							
				- 139.0	F	+ +							
		100	100	-	-	+ + + +							
				-	- 11.0 -	- + + + - +							
				 658.5 	-	+ + + + + +							
				-	ļ	- + + +							
				-	- 11.5	+ + + + +							
				- 658.0 –	Ì	+++++++++++++++++++++++++++++++++++++++							
				- 1	-	+ + +							
				-	40.0	+ + +							
		100	100	-	- 12.0	- + + + - +							
				 657.5 	ł	+ + + +							
				-	Ļ	- + + + - +							
NMLC	0% LOSS			-	- 12.5	+ + + + +							
2				 657.0	ļ	+++++++++++++++++++++++++++++++++++++++							
				-	F	+ +							
				-	- 13.0	+ + +							
				-	- 13.0	+ + +							
		100	100	656.5 -	ł	+ + +							
				-	Ļ	- + + + - +							
				-	- 13.5	+ + + +							
				- 656.0	Ļ	+ + + +							
				-	ł	+ + + + + +							
				-	- 14.0	- + + + - +							
				-	-	+ + + + + +							
			'	655.5 - 	ļ	+++++++++++++++++++++++++++++++++++++++							
				-	ļ.	+ + + + +			•				
		100	100	-	- 14.5	++++							
				- 655.0 –	ļ.	+++							
				-	+	+ + + +							
				-	†	• + + +							
ı	00	GED	PC				CHECKED: MA						E: 04/08/2023
	.00			,			GILGRED. WA						



BH5

SHEET 5 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 07/06/2023 DATE COMPLETED: 07/06/2023 SURFACE RL: 669.70 m AHD COORDS:

				rmatic	nosp			Fiel	d Materia		)escr	intic			U-0 Dx
	'n	RECOVERY	RQD	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	(SOIL NAME; plas particle shape, s minor constituents)	CRIPTION sticity/grain size, colour, econdary components, (ROCK NAME; grain size, nor constituents)	THERING	INF STF Is	ERRI RENG	ED TH Pa	AVE DEF SPA	RAGE FECT CING nm)	AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling,
		100	9 9 9		- 15.5 15.5 		GRANITE, coarse grain crystalline texture, indis	led, white, brown and grey, tinct fabric				HA HA	010 020		
NMLC	● 0% LOSS	100	9 9		- - - - - - - - - - - - - - - - - - -		fresh granite corestone								JT 45° PR RF
				_	-		CORED BOREHOLE B 19.78 m	H5 TERMINATED AT							
LO	GG	GED:	RC	;			CHEC	KED: MA						DA	TE: 04/08/2023







BH6

SHEET 1 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 08/06/2023 DATE COMPLETED: 08/06/2023 SURFACE RL: 669.90 m AHD COORDS:

			Borehole Ir	formatio	n				Field Material Infor	mation		
METHOD		WATER	FIELD TEST	SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME;plasticity/grain size, particle shape, colour, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
D	г	•		0.45		- 0.11	1.4		CONCRETE, 110mm thick			FOOTPATH PAVEMENT
			0.50m	0.15m BH6 0.30m 6 0.50m	- 	- 0.11 -		SM	FILL, Silty SAND, fine to coarse grained, brown, trace of clay	М		FILL -
			SPT 2, 3, 5 N=8 0.95m	D (0.5-0.95 BH6a/DU (0.8-1.0m	m) - IP1 1) - 669.0 -	-0.5						NOTE: Borehole surface RL estimated based on supplied surve plan (borehole not surveyed)
, Developed by Datgel			1.50m SPT 6, 6, 5 N=11 1.95m	1.50m D (1.5-1.95 BH6b/QA (1.8-2.0m	568.5            	- 1.5 2.0						- - - - - - - - - - - - - - - - - - -
wingFile>> 04/08/2023 13:07 Produced by gNT Professional, Developed by Datgel AD/T		(Not Encountered)	<u>3.00m</u>	2.80m	667.5 - - - - - - - - - - - - - - - - - -							- - - - - - Coarse, sub-rounded gravel fragment in SPT at 3.0m
-LOGS.GPJ < <drawingfile></drawingfile>			SPT 2, 3, 3 N=6 <u>3.45m</u>	D <u>3.45m</u> 6	- 	+ - 						- - - - -
08.1_RCA_STANDARD.GLB Log RCA NON CORED LOG 16547-LOGS.GPJ < <dre< td=""><td></td><td></td><td>4.50m</td><td>3.80m BH6d/Q<sub>i</sub> 4.00m 4.50m</td><td>666.0 </td><td>-4.0 </td><td></td><td></td><td></td><td></td><td></td><td></td></dre<>			4.50m	3.80m BH6d/Q <sub>i</sub> 4.00m 4.50m	666.0 	-4.0 						
8.1_RCA_STANDARD.GL			SPT 4, 4, 4 N=8 4.95m	D 4.95m	- - 	-						
RCA_LIB_0	LC	GG	BED: RC					Cł	IECKED: MA	DA	TE: 04/0	08/2023

RCA
A U S T R A L I A
GEOTECHNICAL • ENVIRONMENTAL

BH6

SHEET 2 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 08/06/2023 DATE COMPLETED: 08/06/2023 SURFACE RL: 669.90 m AHD COORDS:

		Borehole In	formatio	on				Field Material Info	mation		
METHOD	WATER		SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME;plasticity/grain size, particle shape, colour, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
				- - 664.5 - -	- - -   5.5 -		SM	FILL, Silty SAND, fine to coarse grained, brown, trace of clay	М		FILL
AD/T	(Not Encountered)	6.00m SPT 3, 2, 3 N=5	5.80m BH6e 6.00m	664.0	- 6.0						
	(Not En	<u>6.45m</u>	<u>6.45m</u>	-	- 6.5						 
- (				663.0 — - - - 662.5 —	- 7.0						
	L V	7.50m 7.53m	7.50m D 7.53m		7.50 _		SM	GRANITE, coarse grained, white, dark grey and brown, crystallite texture, indistinct fabric	A HW	<u>_ v</u>	BEDROCK
		SPT 8/30mm N=R		662.0				brown, crystallite texture, indistinct fabric			
				- 661.5 — - -	- 8.5 						
				661.0	9.0						
				660.5	- 9.5 						
				660.0	-						
	LOC	GGED: RC					Cł	IECKED: MA	DA	TE: 04/	08/2023

RCA
AUSTRALIA
GEOTECHNICAL • ENVIRONMENTAL

BH6

SHEET 3 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 08/06/2023 DATE COMPLETED: 08/06/2023 SURFACE RL: 669.90 m AHD COORDS:

	Bo	oreł	nole	Info	ormatio	on		Fi	eld Mate	ria	al Descript	tio	۱		
METHOD		WAIER LUSS	RECOVERY	RQD	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	WEATHERING	S	INFERRED STRENGTH Is <sub>(50)</sub> MPa	+	DEFE SPAC	ECT	DEFECT DESCRIPTION AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling, planarity, roughness, thickness)
				6											
				6	- 664.0	- 6.0									
Jalgei				6	- 	- 6.5									
ulessiulial, Leverupeu vy L				6	563.0 -	- 7.0									
		•		6	662.5	- - - - -	+ + - + - +	START CORING AT 7.53m GRANITE, coarse grained, white, dark grey and brown, crystallite texture, indistinct fabric	HW	'					<ul> <li>Note: Granite core disintergrates readily into sandy soil under hand pressure</li> </ul>
				6	- 662.0 - -	- 8.0									
			100	76	561.5 - -	- 8.5									DZ
		—————————————————————————————————————		6	561.0 	- 9.0	+ + + + + + + + + + + + + + + +								
ראמט האי איי א				6	560.5 - -	- 9.5	- + + + + + - + + + + + + + + + + + + +								
ILRUA OINI			100	100 0	560.0	-	- + + + + + + +								
	LO	GG	ED:	RC	;		+	CHECKED: MA		_				DAT	E: 04/08/2023



BH6

SHEET 4 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 08/06/2023 DATE COMPLETED: 08/06/2023 SURFACE RL: 669.90 m AHD COORDS:

Y       Y	DESCRIPTION AL OBSERVATIONS inclination, infilling, ghness, thickness)
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	
$\begin{array}{ c c c c c } \hline \\ \hline $	ing penetration
	ed in core loss zone
$\begin{array}{c} + 13.0 \\ + + \\ + \\ + \\ + \\ + \\ + \\ + \\ + \\ + $	
666.5       + + +         13.5       + + +         656.0       + + +         656.0       + + +         14.00       + + +         14.00       + + +         655.5       + + +         14.13       + + +         14.13       + + +         14.13       + + +         14.13       + + +         14.5       + + +         15       5         14.5       + + +         14.5       + + +         15       5         1655.5       + + +         1655.0       + + +         1655.0       + + +         1655.0       + + +         1655.0       + + +         17       fresh granite corestone from 14.80m to 14.93m         10       DATE: 04/08/2023	NR PR RF
LOGGED: RC CHECKED: MA DATE: 04/08/2023	



BH6

SHEET 5 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 08/06/2023 DATE COMPLETED: 08/06/2023 SURFACE RL: 669.90 m AHD COORDS:

				ormatio	on		Field							,		
METHOD	(0	RECOVERY		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	WEATHERING	IN S <sup>-</sup>	IFEF TRE Sرون	rre Ng <sup>-</sup> Mp	ED TH a	AV DE SP	EFE PAC	AGE ECT ING n)	AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling,
NMLC		94	91		- - - - - - - - - - - - - - - - - - -	+ + + + + + + + + + + + + + + +	GRANITE, coarse grained, white, dark grey and brown, crystallite texture, indistinct fabric	HW								
	_ ¥_		(	653.5 -	-16.20- - - - - - 16.5		CORED BOREHOLE BH6 TERMINATED AT 16.20 m			8						
			(	653.0 -	- - 17.0 -											
			6	652.5 -	- - 17.5 											
				 652.0 - 	- 18.0  											
				651.5 -   	- 18.5  											
				650.5 -	- 19.0 - - - - - 19.5											
			(	- - - 	-											
L	.OG(	GED	: RC	;			CHECKED: MA								DA	TE: 04/08/2023





BH7

SHEET 1 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 06/06/2023 DATE COMPLETED: 06/06/2023 SURFACE RL: 669.80 m AHD COORDS:

100	<i>"</i> (1)	Developed a la				1			· ·		
	<u> </u>	Borehole In	formatic	n I	1		z	Field Material Infor		<u> </u>	
METHOD	WATER	FIELD TEST	SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME;plasticity/grain size, particle shape, colour, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
	A				0.40		-	ASPHALTIC CONCRETE, 100mm thick			CAR PARK PAVEMENT
					+ 0.10 -		SM	FILL, Silty Sandy GRAVEL, fine to medium, grey-brown, sub-angular	М	1	CAR PARK BASE MATERIAL
			0.30m BH7a	 569.5 -	- 0.30 -		SM			-	FILL
			0.3-0.5n 0.50m	)	+			FILL, Silty SAND, fine to coarse grained, grey, trace of clay and fine gravel			
		0.50m	0.50m		-0.5		2				-
		SPT	D (0.5-0.95	m)	İ						
4		6, 6, 6 N=12	BH7b (0.8-1.0r	''' 669.0 -	+		2				
AD/T	(Not Encountered)	0.95m		ľ .	+						
	Enco		1.00m		+ 1.0		2				NOTE: Borehole surface RL
	10N	1.20m	1.20m		İ						estimated based on supplied sur plan (borehole not surveyed)
			(	] 568.5 -	+						
		SPT	D (1.2-1.65	I .	+						
		4, 6, 6 N=12	BH7c (1.6-1.8n		- 1.5		*				- TC Bit refusal at 1.8m
		1.65m	(1.0-1.01	ľ	İ						(on inferred very high strength granite boulder)
			1.80m	 568.0-	+						Wash bore/install casing
,	v				+			granite boulder in residual soil matrix at 1.8m			
					-2.0			CONTINUED AS CORED BOREHOLE			-
					İ						
			(	 667.5 -	1						
					÷						
					-2.5						-
					İ						
			(	 667.0 -	Į						
					+						
					- 3.0						-
					İ						
			(	 566.5-	Ļ						
					ł						
					- 3.5						-
					İ						
			(	 566.0-	+						
					+						
					-4.0						
				·	t						
				- 665.5	ļ						
					Ŧ						
				.	-4.5						-
				·	†						
				- 665.0	I						
					Ŧ						
LO	GG	GED: RC					CH	IECKED: MA	DA	TE: 04/0	08/2023
									1		

RCA
AUSTRALIA
GEOTECHNICAL • ENVIRONMENTAL

BH7

SHEET 2 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 06/06/2023 DATE COMPLETED: 06/06/2023 SURFACE RL: 669.80 m AHD COORDS:

	Bore	ehole	Info	ormatio	on		Field	Mater	ial Description		
METHOD	WATER LOSS	RECOVERY		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	WEATHERING	INFERRED STRENGTH Is <sub>(50)</sub> MPa چچچچچ الع کام کی کی کی کی کی کی کی کی کی کی کی کی کی	ECT	DEFECT DESCRIPTION AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling, planarity, roughness, thickness)
					- - 1.0 -						
					- - 1.5 - -						
				667.5 - - -	- <u>1.95</u> -2.0 - - - - - 2.5		START CORING AT 1.95m Sandy CLAY, medium plasticity, brown, with gravel/cobble sized fresh granite fragments, very stiff consistency	RS			
		100	0	- 	- 3.0		GRANITE coarse grained, pale grey, brown and dark grey	XW			— Water level at 3.1m on completion on NMLC coring
NMLC				 666.5 - - - - - -	- 3.5	+ + + + + + + + + + + + + + + + + + +					
					- 4.0 + + + + + 4.20 + +	+ + + + + + + +	becoming with gravel sized quartz, up to 50mm at 4.1m CORE LOSS 0.27m (4.20-4.47)				
		100 61		- - - - - - - - - - - -	4.47 	+ + + + + + + + + + + + + + + +	GRANITE, coarse grained, red-brown, crystalline texture	XW			
	LOG	GED	: RC	;			CHECKED: MA			DAT	E: 04/08/2023



BH7 SHEET 3 OF 3

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation

LOCATION: Bathurst Hospital

DATE COMMENCED: 06/06/2023 DATE COMPLETED: 06/06/2023 SURFACE RL: 669.80 m AHD COORDS:

	Bor	ehol	e Inf	orr	matic	n		Field Material Description
METHOD	WATER LOSS	CORE	RQD		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)       O RUE (SOUL (ROCK NAME; grain size, colour, minor constituents)       INFERRED (ROCK NAME; grain size, grain size, colour, minor constituents)       AVERAGE DEFECT (SOUL (SOUL) (SOUL (SOUL) (SO
				66	-  94.5	- - - 5.40 -	· + + · + + · + + · + + · + +	GRANITE, coarse grained, red-brown, crystalline XW
				66	- - 54.0	- 5.5 - -	+ + + + + + + + + + + + + + + +	GRANITE, coarse grained, pale grey, dark grey and orange-brown, crystalline texture, indistinct fabric
		100	73		- - - - - -	- 6.0  	· + · + + · + + · + + · + +	
oy Datgel					-	- - 6.5 -	+ + + + + + + + + + + + + +	dark brown zone from 6.6m to 6.7m
u4/U8/2/23 13:13 Froduced by gin I Froressonal, Developed by Uarge NMLC				66	i3.0 - - -	- - - 7.0 -	· + + + + + + + + + + + + + + + + + + +	dark brown zone from 6.6m to 6.7m
				66	;2.5 - -	- - - 7.5 -	+ + + + + + + + + + + + + +	
				66	- 2.0 - -	- - 8.0	· + + + · + + · + + · + + · + +	becoming white, dark grey and brown at 7.7m
		100	97		- 51.5 -	- - - 8.5	+ + + + + + + + + + + + + + + +	
סואומאורטמרד רמל אמא ממעבד המערומבר רמל ומאו-דמפטימר אי				66	- 51.0 -	- - - 9.0	- + + - + + - + + - + + - + + - + + - + +	
				66	- - 	- - - - 9.5	+ + + + + + + + + + + + + + + + + +	CS with fresh granite corestone fragments
				66	- - 60.0 -	-	+ + + + + + + + + + + + + + + +	
e'	.00	GEI	' D: R	С				CORED BOREHOLE BH7 TERMINATED AT 10.00 m CHECKED: MA DATE: 04/08/2023





#### **GEOTECHNICAL BOREHOLE LOG**

BH8

SHEET 1 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital

DATE COMMENCED: 06/06/2023 DATE COMPLETED: 06/06/2023 SURFACE RL: 668.60 m AHD COORDS:

		Borehole Ir	formatio	n				Field Mater	rial Informa	ation		
METHOD	WATER	TEST	SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	OBW (SOIL particle shape	DESCRIPTION NAME;plasticity/grain size, e, colour, secondary compone minor constituents) grain size, colour, minor consti	ents,		CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
	A		0.10m		0.10	17-21	WOOD CHIPS/M	ULCH		-	-	LANDSCAPED AREA
			BH8	668.5	0.10 -			, fine to coarse grained, trace	of clay	М		FILL
			0.30m		Į.		and gravel					
			0.40m		Ļ							
		0.50m	DU0-	-	-0.5							
			BH8a (0.4-0.6r	668.0	+							
		SPT 4, 6, 9 N=15	D (0.5-0.95	-	t							
			BH8b (0.9-1.1m	-	I							
		0.95m		– I	-1.0							NOTE: Daugh als surface Di
			1.10m	67.5 –	+							NOTE: Borehole surface RL estimated based on supplied su
				-	ł							plan (borehole not surveyed)
				-	t							
		1.50m	1.50m	-	-1.5							
			e	] 567.0	- 1.5							
		SPT	D-BH8c	-	-							
		7, 6, 7 N=13	(1.8-2.0m	1) -	ł							
		1.95m	2.00m	-	ł							
				-	-2.0							
				666.5	Ī							
				-	Ļ							
	Itered			-	ł							
A	(Not Encountered)			-	-2.5							
	(Not E		6	566.0 	t							
					Í							
				-	Ļ							
		3.00m	3.00m		- 3.0							
			D ( (3.0-3.45	65.5 -	ł							
		SPT 3, 5, 7 N=12	BH8d		t							
			(3.1-3.3m	1) - _	Ī							
		3.45m	3.45m	-	-3.5							
			6	1 565.0	ł							
				-	+							
				-	t							
				-	4.0							
				 664.5	4.0							
			`	-	ļ							
				-	ł							
		4.50m	4.50m	-	† .							
				-	-4.5							
		SPT	BH8e 6 (4.5-4.7m		I							
		2, 3, 5 N=8	D (4.5-4.95	m) -	ļ							
		4.95m	4.95m	-	ł							
					<u> </u>		<u> </u>				<u> </u>	
ı	00	GED: RC					CHECKED: MA			⁻⊿⊓	ΓE: 04/0	18/2023
L										DA		



#### **GEOTECHNICAL BOREHOLE LOG**

BH8

SHEET 2 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital

DATE COMMENCED: 06/06/2023 DATE COMPLETED: 06/06/2023 SURFACE RL: 668.60 m AHD COORDS:

		Borehole Ir						Field Material Infor	mation		
METHOD	WATER	FIELD	SAMPLE	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME;plasticity/grain size, particle shape, colour, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
AD/T	(Not Encountered)	6.00m	5.80m BH8f <b>6.00m</b>	663.5 - - - - - - - - - - - - - - - -				FILL, Silty SAND, fine to coarse grained, trace of clay and gravel	M		FILL
		- SPT 12/100mm N=R	<u>(6.01m</u> D		- 6.5		×	CONTINUED AS CORED BOREHOLE			-
				661.5 - - - - - - - - - - - - - - - - - - -	-7.0						
					- 8.0						
				659.5 - - - - - - - - - - - - - - - - - -	9.0 						
	_0G0	GED: RC		-			CH	IECKED: MA	DA	TE: 04/0	08/2023



BH8

SHEET 3 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 06/06/2023 DATE COMPLETED: 06/06/2023 SURFACE RL: 668.60 m AHD COORDS:

	Bore	ehole	e Inf	ormati	on		Field Material Description								
METHOD	WATER LOSS	CORE		RL (m AHD)	DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	WEATHERING	S	IFERRE IRENG s <sub>(50)</sub> MP	TH a	DE SP/		CT √G	DEFECT DESCRIPTION AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling, planarity, roughness, thickness)
eveloped by Datgel		100		663.0 - 662.5 -			START CORING AT 6.05m GRANITE, orange-brown becoming pale grey and dark grey at 6.55m	XW			H H	10	100 300	100 200	
< <drawingfile>&gt; 04/08/2023 13:13 Produced by gINT Professional, Developed by Datgel NMLC</drawingfile>				661.5 -     661.0 - 	-7.0 			HW	+						— Note: Granite core disintergrates readily into sandy soil under hand pressure
_				660.5 -	- 8.0	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$									
081_RCA_STANDARD.GLB_L09_RCA.CORED_BOREHOLE_L0G_16647-L0GS.GP		100		659.5 -		$\begin{array}{cccccccccccccccccccccccccccccccccccc$									
۳.	_0G	GED	 ): R(			<u>} + .</u>	CHECKED: MA							 DAT	E: 04/08/2023



## CORED BOREHOLE LOG

BH8

SHEET 4 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital

DATE COMMENCED: 06/06/2023 DATE COMPLETED: 06/06/2023 SURFACE RL: 668.60 m AHD COORDS:

	Bor	ehol	e Inf	orma	atio	n		Field	Mate	rial Description		
METHOD	WATER LOSS			í		DEPTH (m)	GRAPHIC LOG	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	WEATHERING	INFERRED AVE STRENGTH DE Is <sub>(50)</sub> MPa SP	EFECT ACING	DEFECT DESCRIPTION AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling, planarity, roughness, thickness)
		100	100	658. 658. 658.	+	- 10.5	+ + + + + + + + + + + + + + + + + + +	GRANITE, orange-brown	HW			— JT 60° PR S
				657.	.5	- 11.0	+ + + - + + + - + + + - + + + - + + + - + + + - + + +			-		
		10	100	657. 656.	+	- 11.5 - 12.0	+ + + + + + + + + + + + + + + + + + +	dark grey/brown altered zone from 12.1m to 12.65m			ſ	— JT 50° Fe PR VR
NMLC				656.	.0-+	- 12.5	+ + + + + + + + + + + + + + + + + + +					— JT 50° PR RF
		100	100	655. 655. 654.	.0	- 13.5	13.0 + + + + + + + + + 13.5 +					
-	_00	GEI	): R	654.	.0	- 14.5	- + + + + + + + + + + + + + + + + + + +	CHECKED: MA			DAT	-E: 04/08/2023




BH8

SHEET 5 OF 5

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE COMMENCED: 06/06/2023 DATE COMPLETED: 06/06/2023 SURFACE RL: 668.60 m AHD COORDS:

			rmatio						I Descriptio				
WATER LOSS	RECOVERY	RQD	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	r DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size colour, minor constituents)	THERING	l S	NFERRED	A\ D S	/ERAC DEFEC PACIN	IG	DEFECT DESCRIPTION AND ADDITIONAL OBSERVATIONS (defect type, inclination, infilling, planarity, roughness, thickness)
	100	100	553.5	- - - - - - - - - - 16.0 - -	+ + + + + + + + + + + + + + + + + + +	GRANITE, orange-brown	HW						
NMLC	100	60 06		- - - - - - - - - - - - - - - - - - -	+ + + + + + + + + + + + + + + + + + +	fresh granite corestone from 16.55m to 16.64m							
		6	550.0	18.5 - - - - - 19.0 - - - - - - - - - - - - - - - - - - -		CORED BOREHOLE BH8 TERMINATED AT 19.25 m							- DZ
LOG	GED	RC				CHECKED: MA		<u> </u>				⊥ ⊥ Ate	E: 04/08/2023







# GEOTECHNICAL BOREHOLE LOG BH9

SHEET 1 OF 1


PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE: 09/06/2023


SURFACE RL: ~674m AHD

COORDS:

EXCAVATION METHOD: 5t Excavator with 300mm Auger

Borehole Information						Field Material Information					
	WATER	DYNAMIC PENETROMETER	FIELD TEST	SAMPLE	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
	Encountered	6		0.30m BH9 0.50m	0.04 - - - - - - 0.5 - - - - 0.70 -			ASPHALTIC CONCRETE, 40mm thick FILL, Silty Sandy GRAVEL, fine to medium, grey, sub-angular	М	e	CAR PARK PAVEMENT CAR PARK BASE MATERIAL
	Not End	4 5 6 15 19		BH9a (0.8-1.0m B (0.7-1.1m 1.10m	i)	0.00		Clayey Gravelly SAND, fine to coarse grained, orange-brown Silty SAND, fine to coarse grained, brown, trace of clay and gravel		MD D - VD	RESIDUAL -
-				1.30m BH9b 1.50m	- - 		· · · · · · · · · · · · · · · · · · ·	BOREHOLE BH9 TERMINATED AT 1.50 m			-
sional, Developed by Datgel					-  2.0 -						
04/08/2023 13:08 Produced by gINT Professional,					- 2.5 -						
04/08/2023 13:00/08/2023 13:00					- 3.0 -						
ž					- 3.5 - -						
CA HAND AUGER LOG					- 4.0 - -						
08.1_RCA_STANDARD.GLB_Log_RCA HAND AUGER LOG_16547-LOGS.GPJ					- 4.5 - -						-  - - - -
RCA_LIB_08.1_RCA	L	OGGE	D: RC		_			CHECKED: MA	DA	 TE: 04/0	







# **GEOTECHNICAL BOREHOLE LOG**

**BH10** 

SHEET 1 OF 1

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital

DATE: 09/06/2023 SURFACE RL: ~673m AHD COORDS:

EXCAVATION METHOD: Hand Auger

┢	201		hole Infor		a	Field Material Information					
╞		Borehole Information									
	WATER	DYNAMIC PENETROMETER	FIELD TEST	SAMPLE	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
Ī		3		0.10m	0.10 -		ML	FILL/TOPSOIL, Clayey SILT, low plasticity, brown	М		FILL / TOPSOIL
		6 8 5 3		BH10 0.30m	- 0.10 - - - - 0.5		СІ	FILL, CLAY, medium plasticity, brown, with sand and gravel	w~PL		FILL
		2 3 2 2 11 6		0.80m BH10a 1.00m	1.0						estimated and extrapolated based on supplied survey plan (borehold not surveyed) - - - -
		6 10		1.10m BH10b 1.30m	- 1.10 -		ML	TOPSOIL, SILT, low plasticity, brown	М		TOPSOIL -
		11 11		BH10c 1.50m	- 1.30 -			Clayey SAND, fine to coarse grained, brown becoming pale brown at 1.4m		D	RESIDUAL -
		19			- 1.5 	1./					
y Datgel		19 23 25			-			BOREHOLE BH10 TERMINATED AT 1.60 m			-
Developed by		19 19			-2.0						-  -
Professional,		33			-						-
04/08/2023 13:08 Produced by gINT Professional. Developed by Datgel					- 2.5 -						-  - -
wingFile>> 04/08/2023 13:0					- 3.0						- - - - -
< <dra< td=""><td></td><td></td><td></td><td></td><td>-  3.5 -</td><td></td><td></td><td></td><td></td><td></td><td>-  - -</td></dra<>					- 3.5 -						-  - -
HAND AUGER LOG 16					- 4.0 -						- - - -
081_RCA_STANDARD.GLB Log RCA HAND AUGER LOG 16547-LOGS.GPJ					- 4.5 -						- - - - - -
8.1_RCA_ST.					-						-
RCA_LIB_0	L	OGGE	D: RC					CHECKED: MA	DA	TE: 04/0	)8/2023



# **GEOTECHNICAL TEST PIT LOG**

SHEET 1 OF 1

TP1

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE: 09/06/2023 SURFACE RL: ~669.3m AHD

COORDS:

EXCAVATION METHOD: 5t Excavator with 400mm Bucket

Test Pit Information						Field Material Information					
	WATER	DYNAMIC PENETROMETER	FIELD TEST	SAMPLE	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
	Not Encountered			TP1/DUF QA3 0.20m 0.60m TP1a B (0.6-0.8n 0.80m	- - - 0.5 - 0.60 -	······································	ML	TOPSOIL, SILT, low plasticity, orange-brown Extremely Weathered Granite, properties of Silty SAND, fine to coarse grained, orange-brown, with clay	M XW		TOPSOIL NOTE: Test pit surface RL estimated based on supplied survey plan (test pt not surveyed EXTREMELY WEATHERED MATERIAL
-				1.00m TP1b 1.20m	- - - - - - - - - - - - - - - - - - -	- + + - + + - + + - + + - + +	-	TEST PIT TP1 TERMINATED AT 1.25 m			- - - - - - - -
al, Developed by Datgel											- - - - -
04/08/2023 13:08 Produced by gINT Professional, Developed by Datgel											- - - - - -
< <drawingfile>&gt;</drawingfile>					- 3.0						- - - - - -
ND AUGER LOG 16547-LOGS.G					- - - 4.0						- - - - -
08.1_RCA_STANDARD.GLB_Log_RCA HAND AUGER LOG_16547-LOGS.GPJ					- 4.5 -						- - - - - - - - - - - - - - 
RCA_LIB_08.1_RCA_	L	OGGE	D: RC		-			CHECKED: MA	DA	ΓE: 04/0	- )8/2023





# **GEOTECHNICAL TEST PIT LOG**


TP2 SHEET 1 OF 1

PROJECT No: 16547 CLIENT: Health Infrastructure PROJECT: Geotechnical and Contamination Investigation LOCATION: Bathurst Hospital DATE: 09/06/2023 SURFACE RL: ~665.8m AHD

COORDS:

EXCAVATION METHOD: 5t Excavator with 400mm Bucket

Test Pit Information							Field Material Information				
	WATER	DYNAMIC PENETROMETER	FIELD TEST	SAMPLE	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	DESCRIPTION (SOIL NAME; plasticity/grain size, colour, particle shape, secondary components, minor constituents) (ROCK NAME; grain size, colour, minor constituents)	MOISTURE/ WEATHERING	CONSISTENCY/ RELATIVE DENSITY/ STRENGTH	STRUCTURE AND ADDITIONAL OBSERVATIONS
				0.10m 0.40m TP2a 0.50m	- 0.5			FILL, Silty SAND, fine to coarse grained, brown	M		FILL NOTE: Test pit surface RL estimated based on supplied survey plan (test pt not surveyed –
	Not Encountered			0.70m TP2b 0.80m 0.85m B 1.10m	0.65 - 0.85 - - 1.0		ML	TOPSOIL, SILT, low plasticity, brown Silty SAND, fine to coarse grained, brown, with clay and lenses of extremely weathered material	_	D - VD	TOPSOIL - - RESIDUAL - - -
y Datgel					- 1.40 - - 1.5 - -			Extremely Weathered Granite, properties of Silty SAND, fine to coarse grained, orange-brown, with clay	XW		EXTREMELY WEATHERED MATERIAL - - -
F Professional, Developed by Datgel								TEST PIT TP2 TERMINATED AT 1.90 m			
04/08/2023 13:08 Produced by gINT Professional,					- 2.5						
< <drawingfile>&gt;</drawingfile>					- 3.0						
ER LOG 16547-LOGS.GPJ					- 3.5 - - - - - 4.0						
08.1_RCA_STANDARD.GLB_Log_RCA HAND AUGER LOG_16547-LOGS.GPJ					- 4.5						- - - -
					-						-
RCA_LIB_	L	OGGE	D: RC					CHECKED: MA	DA	TE: 04/0	08/2023





### **Explanatory Notes – Soil Description**

In engineering terms, soil includes every type of uncemented or partially cemented material found in the ground. In practice, if the material can be remoulded by hand in its field condition or in water it is described as a soil. The dominant soil constituent is given in capital letters, with secondary textures in lower case. The dominant feature is assessed from AS 1726:2017 - Geotechnical Site Investigations and a soil symbol is used to define a soil layer.

#### METHOD

Method	Description
AD/T	Auger Drilling with tungsten carbide bit
AD/V	Auger Drilling with V Bit
AS	Auger Screwing
AT	Air Track
BH	Backhoe
CT	Cable Tool Rig
DB	Washbore Drag Bit
DT	Diatube
E	Excavator
EH	Excavator with Hammer
HA	Hand Auger
HQ	Diamond Core-63mm diameter
Ν	Natural Exposure
NMLC	Diamond Core-52mm diameter
NQ	Diamond Core-47mm diameter
Percussion	Percussion Drilling
PT	Push Tube
RR	Rock Roller
V	Vacuum Excavation
WS	Washbore
Х	Existing Excavation

#### WATER

 $\nabla$ Water level at date shown

Seepage

NOT ENCOUNTERED: The borehole/test pit was dry soon after excavation. Inflow may have been observed had the borehole/test pit been left open for a longer period.

NOT OBSERVED: The observation of groundwater, whether present or not, was not possible due to drilling water, surface seepage or cave in of the borehole/test pit.

#### SAMPLING

Sample	Description
В	Bulk Disturbed Sample
D	Disturbed Sample
SPT	Standard Penetration Test
U50	Undisturbed Sample - 50mm diameter
U75	Undisturbed Sample - 75mm diameter
ES	Soil Sample, Environmental
EW	Water Sample, Environmental
G	Gas Sample

#### SOIL CLASSIFICATION

The appropriate symbols are selected based on the result of visual examination, field tests and available laboratory test results, such as particle size analysis, liquid limit and plasticity index.

Group Symbol	Description
GW	Well graded gravel
GP	Poorly graded gravel
GM	Silty gravel
GC	Clayey gravel
SW	Well graded sand
SP	Poorly graded sand
SM	Silty sand
SC	Clayey sand
ML	Silt of low plasticity
CL	Clay of low plasticity
OL	Organic soil of low plasticity
CI	Clay of medium plasticity
MH	Silt of high plasticity
СН	Clay of high plasticity
OH	Organic soil of high plasticity
Pt	Peat, highly organic soil

#### **MOISTURE CONDITION**

d

For coarse grained soils, the following terms are used									
	Dry	- Non-cohesive and free-running							
	Moist	<ul> <li>Soil feels cool, darkened in colour</li> <li>Soil tends to stick together</li> </ul>							
	Wet	<ul> <li>Soil feels cool, darkened in colour</li> <li>Soil tends to stick together, free water forms when handling</li> </ul>							
	For fine g	grained soils, the following moisture content (w) terms are used:							
	w < PL	- Moist, dry of plastic limit							
	w ≈ PL	- Moist, near plastic limit.							
	w > PL	- Moist, wet of plastic limit.							

- w ≈ LL - Wet, near liquid limit.
- Wet, wet of liquid limit w > LL

#### PLASTICITY

Soil plasticity is a measure of the range of water content over which a soil exhibits plastic properties. The classification of the degree of plasticity in terms of the Liquid Limit (LL) is as follows.

Description of Plasticity	Range of Liquid Limit for Silt	Range of Liquid Limit for Clay
Non-plastic	Not applicable	Not applicable
Low plasticity	≤50	≤35
Medium plasticity	Not applicable	>35 and ≤50
High plasticity	>50	>50

#### **COHESIVE SOILS – CONSISTENCY**

The consistency of a cohesive soil is defined by descriptive terminology such as very soft, soft, firm, stiff, very stiff and hard. These terms are assessed by the shear strength of the soil as observed visually, by hand penetrometer, dynamic cone penetrometer or vane shear values and by resistance to deformation to hand moulding.

A hand penetrometer may be used in the field or the laboratory to provide an approximate assessment of the unconfined compressive strength (UCS) of cohesive soils. Undrained shear strength

 $c_u = 0.5 \times UCS$ . Undrained shear strength values are recorded in kPa as follows:

Telleffel		
Strength	Symbol	Indicative Undrained Shear Strength, c <sub>u</sub> (kPa)
Very Soft	VS	≤12
Soft	S	>12 and ≤25
Firm	F	>25 and ≤50
Stiff	St	>50 and ≤100
Very Stiff	VSt	>100 and ≤200
Hard	Н	>200
Friable	Fr	—

#### **COHESIONLESS SOILS – RELATIVE DENSITY**

Silt

Clay

Relative density terms such as very loose, loose, medium dense, dense and very dense are used to describe silty and sandy material, and these are usually based on resistance to drilling penetration, Standard Penetration Test (SPT) N values or Perth Sand Penetrometer

resistance.						
Term	Symbol	Density Ir	ndex			
Very Loose	VL	0 to 15				
Loose	L	15 to 35				
Medium Dens	e MD	35 to 65				
Dense	D	65 to 85				
Very Dense	VD	>85				
SOIL PARTICLE SIZE DESCRIPTIVE TERMS						
Fraction	Name	Subdivision	Size (mm)			
Oversize	Boulders		>200			
Oversize	Cobbles		63 to 200			
		Coarse	19 to 63			
	Gravel	Medium	6.7 to 19			
Coarse		Fine	2.36 to 6.7			
grained soil		Coarse	0.6 to 2.36			
	Sand	Medium	0.21 to 0.6			
		Fine	0.075 to 0.21			

0.002 to 0.075

< 0.002

Fine grained soil



### **Explanatory Notes - Rock Description**

#### METHOD

Refer to soil description sheet.

#### WATER

Refer to soil description sheet.

#### **ROCK QUALITY**

The defect spacing is shown where applicable and the Rock Quality Designation (RQD) and Total Core Recovery (TCR) for each core run is given where:

TCR =	Length of core recovered	× 100%
TOR =	Length of core run	X 100 /0

RQD =	Sum of axial length of sound core pieces >100mm long	× 100%
NQD =	Length of core run	X 100 /6

#### **ROCK MATERIAL WEATHERING**

Rock material weathering is described using the abbreviations and definitions used in AS1726:2017– Geotechnical Site Investigations.

Term		Abbre	viation	Definition
Residual	Soil	RS		Material is weathered to such an extent that it has soil properties. Mass structure and material texture and fabric of original rock are no longer visible, but the soil has not been significantly transported.
Extremely weathered		xw		Material is weathered to such an extent that it has soil properties. Mass structure and material texture and fabric of original rock are still visible.
Highly Weathered	Distinctly Weathered	HW	DW	The whole of the rock material is discoloured, usually by iron staining or bleaching to the extent that the colour of the original rock is not recognisable. Rock strength is significantly changed by weathering. Some primary minerals have weathered to clay minerals. Porosity may be increased by leaching or may be decreased due to deposition of weathering products in pores.
Moderately Weathered		MW		The whole of the rock material is discoloured, usually by iron staining or bleaching to the extent that the colour of the original rock is not recognisable, but shows little or no change of strength from fresh rock.
Slightly Weathere	d	SW		Rock is partially discoloured with staining or bleaching along joints but shows little or no change of strength from fresh rock.
Fresh		FR		Rock shows no sign of decomposition of individual minerals or colour changes.

Where it is not practicable to distinguish between 'Highly Weathered' and 'Moderately Weathered' rock the term 'Distinctly Weathered' may be used. 'Distinctly Weathered' is defined as follows: 'Rock strength usually changed by weathering. The rock may be highly discoloured, usually by iron staining. Porosity may be increased by leaching, or may be decreased due to deposition of weathering products in the pores'. There is some change in rock strength.

#### **ROCK MATERIAL STRENGTH**

Rock strength is described using AS1726:2017– Geotechnical Site Investigations and ISRM – Commission on Standardisation of Laboratory and Field Tests, 'Suggested method of determining the Uniaxial Compressive Strength of Rock materials and the Point Load Index' as follows:

Term	Abbreviation	Uniaxial Compressive Strength (MPa)	Point Load Index Is <sub>50</sub> (MPa)
Very Low	VL	0.6 to 2	0.03 to 0.1
Low	L	2 to 6	0.1 to 0.3
Medium	Μ	6 to 20	0.3 to 1
High	Н	20 to 60	1 to 3
Very High	VH	60 to 200	3 to 10
Extremely High	EH	>200	>10

-

Axial Point Load Index test.

#### DEFECT SPACING/BEDDING THICKNESS

Diametral Point Load Index test.

Depending on the project, may be either described as mean perpendicular spacing within a set of defects or bedding, or as the spacing between all defects within the rock mass.

Term	Defect Spacing	Bedding
Extremely closely spaced	<6 mm	Thinly laminated
	6 to 20 mm	Laminated
Very closely spaced	20 to 60 mm	Very thin
Closely spaced	0.06 to 0.2 m	Thin
Moderately widely spaced	0.2 to 0.6 m	Medium
Widely spaced	0.6 to 2.0 m	Thick
Very widely spaced	>2 m	Very thick

#### DEFECT DESCRIPTION

DELEGIBEOG		
Туре	Definition	
JT	Joint	
BP	Bedding Parting	
CO	Contact	
CS	Clay Seam	
CZ	Crush Zone	
DK	Dyke	
DZ	Decomposed Zone	
FC	Fracture	
FZ	Fracture Zone	
FL	Foliation	
FLT	Fault	
VN	Vein	
SM	Seam	
IS	Infilled Seam	
SZ	Shear Zone	

Planarity	Roughness
PR – Planar	VR – Very Rough
CU – Curved	RF – Rough
U – Undulating	S – Smooth
ST – Stepped	POL – Polished
IR – Irregular	SL – Slickensided

Symbol	Coating or Infill	
CA	Calcite	
Clay	Clay	
CN	Clean	
Fe	Iron oxide	
KT	Chlorite	
Qz	Quartz	
Х	Carbonaceous	
SN	Stain	
VNR	Veneer	

The inclinations of defects are measured from perpendicular to the core axis.

# Appendix C

Laboratory Test Results



CONSTRUCTION MATERIALS TESTING

92 Hill St Carrington Newcastle NSW 2294 Ph +61 2 4902 9200 Web www.rca.com.au ABN 53 063 515 711 NATA Accredited Laboratory: 9811 Corporate Site No: 9804 Construction Materials Testing

Project Name :	Health Infrastructure 1 Reserve Road, St Leonards, 16547 Geotechnical Investigation Bathurst Hospital , Bathurst	NSW, 2	2065					Rep Ord	ort N ort E er Ni : Met	oate umb	: er :		Р	age	e 1	of 3	18	8/07	7 - 00 7/20: 9.6.	23
Comple Number (													CAM		10	CATI				
p	23-1765						-	TP1					SAM	PLE	LU	CATI				
	9/06/2023								0.8r	~										
	17/07/2023							0.0-	0.01	1										
. ,																				
Sampling Method : //	AS SUPPLIED						-	Lot	Num	hor										
Material Type : Demortice : Deputte epoly to comple								rest	: Nur	nbe	r :									
Remarks : Results apply to sample																				
Moisture Method :	AS 1289.2.1.1	2,100				_	_		-		SR 1 Point Grap ce vs Penetrat			_	_		_			_
Maximum Dry Density (t/m <sup>3</sup> ) :	1.768	2,050		_					A	-		+		-			-			
Optimum Moisture Content (%) :	13.9	1,950 1,900 1,850												_					/	
Compactive Effort :	Standard	1,800	-	_			-			-		_	_	-			$\succ$	$\square$		
Nominated Percentage of MDD :	100	1,700										-				4				
Nominated Percentage of OMC :	100	1,550		_						-		+		$\swarrow$			_			
Achieved Percentage of MDD :	101	1,450 1,400 1,350										2	4							
Achieved Percentage of OMC :	100.0	1,300		_							4		_	-			+		_	_
Dry Density Before Soak (t/m³) :	1.779	1,200 1,150 0 1,150 0 1,050			_	4			$\times$											
Dry Density After Soak (t/m³) :	1.757	ō 1,000										_	_				_			
Moisture Content Before Soak (%) :	13.9	950 900 850					$\swarrow$					_								
Moisture Content After Soak (%) :	15.9	800				×.	-			-		+					_			
Density Ratio After Soak (%) :	99	700 650 600			Å							_		_			_			
Field Moisture Content (%) :	7.8	550		$\mathcal{K}$			-			-		-		-			-			
Top Moisture Content - After Penetration	15.9	450 400 350								_			-				_			
(%) : Total Moisture Content - After	15.9	300	A	_			-			-		-					-			
Penetration (%) :		200																		
Soak Condition :	Soaked	50					<u> </u>			-		+	_	+			+		_	
Soak Period (days) :	4		0.5 1	1.5 2	25	3		4	5		Penetratio	(mm) r	7.5				10			10
Swell (%) :	1.0																			
CBR Surcharge (kg) :	4.5																			
Oversize (%) :	0		Cl	BR 5.0	)mm	n (%	):	6												
Oversize Material Replaced (%) :	Excluded		C	BR Va	lue	(%	):	6												

9811



CONSTRUCTION MATERIALS TESTING

92 Hill St Carrington Newcastle NSW 2294 Ph +61 2 4902 9200 Web www.rca.com.au ABN 53 063 515 711 NATA Accredited Laboratory: 9811 Corporate Site No: 9804 Construction Materials Testing

Client : Address : Project Number : Project Name :	Health Infrastructure 1 Reserve Road, St Leonards, 16547 Controbuical Investigation	, NSW, 2065	5		Rep Ord	ort I ort I er N t Me	Date umb	e : ber :						18	8/07	7 - 0 7/20 39.6	023	
Location:	Geotechnical Investigation Bathurst Hospital , Bathurst				Test	t Me		1.		P	age	2 c	of 3		120	.9.0	.1.1	
Sample Number :	23-1766				Τ					SAMF	PLE			ON				
Date Sampled :	9/06/2023				TP2													
Date Tested :	17/07/2023				0.8	5-1.3	1m											
Sampled By :	RCA Geotech																	
Sampling Method :	AS SUPPLIED																	
Material Source :					Lot	Num	nber	:										
Material Type :					Test	t Nu	mbe	r:										
Remarks :Results apply to samp	oles as received																	
Moisture Method :	AS 1289.2.1.1				1		C	BR 1 Point Gra	ph									
Maximum Dry Density (t/m³) :	1.883	4,000					te	rce vs Penetra	101				$\pm$	T			+	
Optimum Moisture Content (%) :	11.5	3,800							_			4	_	+		$\Rightarrow$	¥	+
Compactive Effort :	Standard	3,600										+	—	$\pm$		Ħ	+	+
Nominated Percentage of MDD :	100	3,300 3,200								$\square$		+	$ \downarrow$	7			+	_
Nominated Percentage of OMC :	100	3,100							/			Ż	4	+	-	<u> </u>	+	+
Achieved Percentage of MDD :	100	2,500										$\pm$	_	+			$\pm$	$\pm$
Achieved Percentage of OMC :	99.0	2,600					-		7	4		+	_	+		$\mp$	+	+
		2,400					Ă.	$\square$				-	_	+			-	-
Dry Density Before Soak (t/m <sup>3</sup> ) :	1.891	2,100 0,100 2,100				Á	4					_	_	+		$\square$	_	_
Dry Density After Soak (t/m <sup>3</sup> ) :	1.878	5 1,500 L 1,800 1,700				4			-	-		+	—	+		+	+	+
Moisture Content Before Soak (%) :	11.4	1,600			A							+	_	-			_	+
Moisture Content After Soak (%) :	12.7	1,400							-	-		+	+	+		<b>—</b>	_	+
Density Ratio After Soak (%) :	100	1,100										_	_	_			_	_
Field Moisture Content (%) :	12.2	800							-			_	+	+		$\mp$	_	+
Top Moisture Content - After Penetration (%):	13.2	700 600 500										-	_	-			+	—
Total Moisture Content - After Penetration (%) :	13.0	400							_	_		_	+	+		<b>—</b>	+	+
Soak Condition :	Soaked	200										_	_	-			_	_
Soak Period (days) :	4	0.5	1 1.5 2 2	3	4	5		Penetratio	(mm) no	7.5				10				12.5
Swell (%) :	0.5																	
CBR Surcharge (kg) :	4.5																	
Oversize (%) :	0	C	BR 5.0mr	n (%) :	10													
Oversize Material Replaced (%) :	Excluded	C	BR Value	e (%) :	10													
Site Selection :				. ,														
Soil Description :	Silty SAND with clay																	
WORLD RECOGNISED ACCREDITATION	Accredited for compliance with	ISO/IEC 170					Tir		Æ iy Bi	PPRO DA aker Accr	- S	enic	or Se	oil T	-ech		in	

#### Document Code RF39-10



CONSTRUCTION MATERIALS TESTING

92 Hill St Carrington Newcastle NSW 2294 Ph +61 2 4902 9200 Web www.rca.com.au ABN 53 063 515 711 NATA Accredited Laboratory: 9811 Corporate Site No: 9804 Construction Materials Testing

Ition Test Method : AS 1289.6.1.1 Page 3 of 3  SAMPLE LOCATION BH9 0.7-1.1m Lot Number :
BH9 0.7-1.1m
BH9 0.7-1.1m
Lot Number :
Lot Number :
Test Number :
CSR 1 Pert Orga
e V
TO GRAV (INV
CBR 5.0mm (%) : <b>8</b>
CBR Value (%) : 8

9811



ENVIRONMENTAL • CONSTRUCTION MATERIALS TESTING 92 Hill St Carrington Newcastle NSW 2294 Ph +61 2 4902 9200 Web www.rca.com.au ABN 53 063 515 711 NATA Accredited Laboratory: 9811 Corporate Site No: 9804 **Construction Materials Testing** 

	Atte	rberg Limits F	Report		
Client : Address : Project Name : Project Number :	Health Infrastructure 1 Reserve Road, St Leonards, Geotechnical Investigation 16547	eserve Road, St Leonards, NSW, 2065 Report Date : Order Number :			
Location:	Bathurst Hospital , Bathurst			AS1289.3.1.2, 3.2.1, 3.3.1, 3.4.1	
Sample Number :	23-1768	23-1769	Page 1 23-1770	. of 1	
Test Number :	25 1700	25 1705	25 1770		
Date Sampled :	9/06/2023	8/06/2023	8/06/2023		
Date Tested :	30/06/2023	30/06/2023	30/06/2023		
Sampled By :	RCA Geotech	RCA Geotech	RCA Geotech		
Sampling Method :	AS SUPPLIED	AS SUPPLIED	AS SUPPLIED		
Material Source :					
Material Type :	CLAY with SAND	Gravelly CLAY	Sandy CLAY trace gravel		
Sample Location :	BH1	BH3	BH3		
	1.5-1.95m	1.3-1.5m	1.5-1.95m		
Lot Number :					
Moisture Method :	AS 1289.2.1.1	AS 1289.2.1.1	AS 1289.2.1.1		
Sample History :	Oven dried prep (50°C)	Oven dried prep (50°C)	Oven dried prep (50°C)		
Sample Preparation :	Dry	Dry	Dry		
Notes :	Slight cracking	Slight cracking	Slight cracking		
Mould Length (mm) :	125	125	125		
Liquid Limit (%) :	31	26	28		
Plastic Limit (%) :	15	15	16		
Plasticity Index (%) :	16	11	12		
Linear Shrinkage (%) :	8	5.5	6.5		
SPECIFICATION DETAILS	1		1 1		
Specification Number :					
Liquid Limit - Max :			1		
Plasticity Index - Max :					
Linear Shrinkage - Max :					
Remarks :	Results apply to samples as r	eceived	1		



Accredited for compliance with ISO/IEC 17025 - Testing.

APPROVED SIGNATORY

Timothy Baker - Senior Soil Technician NATA Accreditation Number : 9811

Document Code RF25-13



Sydney Laboratory Unit 5 / 43 Herbert St Artarmon NSW 2064 email: artarmon@ghd.com.au web: ghd.com.au/ghdgeotechnic: Tel: (02) 9462 4860 Fax: (02) 9462 4710

Uniaxial Compressive	e Strength	- Report			Report No: SYD2301721 Issue No: 1	
Client:	RCA Labor	atories		Accredited for compliance with ISO / IEC 17025 - Testing		
Project:	Job 16547			NATA	Laboratory Accreditation No. 679	
Location:	Bathurst					
Job No.:	12519163			Authorised signator	ry: D. Brooke Date of Issue: 6/07/2023 SHALL NOT BE REPRODUCED EXCEPT IN FULL.	
Sample Details						
Test Method:		AS4133.4.2.2 - I	ICS less than 5	50 Mpa		
Storage History:		Tested as receiv				
Sample ID:		SYD23-0317-01	SYD23-0317-02	SYD23-0317-04		
Client Sample ID:		-	-	-		
Borehole No.:		BH1	BH2	BH5		
Depth (m):		18.15 - 18.30	5.48 - 5.70	17.43 - 17.70		
Date Sampled:		9/06/2023	5/06/2023	7/07/2023		
Date Tested:						
		29/06/2023	29/06/2023	29/06/2023		
Sample Description:		Granite	Granite	Granite		
Test Results						
Sample Height (mm):		126.9	83.9	134.2		
Sample Diameter (mm):		52.5	52.6	52.6		
Sample Height/Diameter Ra	atio:	2.4	1.6	2.6		
Sample Dry Density (t/m3):		2.314	2.071	2.273		
Moisture Content (%):		3.7	6.8	4.3		
Time of Failure (min):		17.1	10.5	12.2		
Uniaxial compressive streng	nth (MPa) <sup>.</sup>	0.690	0.195	0.374		
Mode of Failure:	gar (in a).	Axial Multiple	Single Shear	Single Shear		
Specimen Comments:		Note 2	Note 1	Note 2		
Where rock strength is likely to exc	eed	Note 3	Note 2	Note 3		
50 Mpa, ends are ground flat to 0.0	2mm		Note 3			
Comments (if applica	•	1	<u> </u>	<u>                                     </u>		
Note 1	-	liameter ratio falls outs		limits of 2.5:1 to 3:1.		
Note 2		s not straight to within				
Note 3 Note 4		s not parallel or at right gth to diameter ratio fa	-	nethod limits of 2 0.1	to 2.5:1.	
	(1220) 110 101	-	performance of com			

Testing machine Wykeham Farrance - 50 kN



**Uniaxial Compressive Strength - Report** 

Sydney Laboratory Unit 5 / 43 Herbert St Artarmon NSW 2064 email: artarmon@ghd.com.au web: ghd.com.au/ghdgeotechnics Tel: (02) 9462 4860 Fax: (02) 9462 4710

# Report No: SYD2301721

Issue No: 1

Client:	RCA Laboratories	
Project:	Job 16547	Accredited for compliance with ISO / IEC 17025
Location:	Bathurst	Laboratory Accreditation No. 679
Job No.:	12519163	THIS DOCUMENT SHALL NOT BE REPRODUCED EXCEPT IN FULL.

# Photographs



BH1 18.15 - 18.30



BH2 5.48 - 5.70



BH5 17.43 - 17.70

#### Natural Moisture / Density Report **Report No:** SYD2301746 Client : **RCA** Laboratories Job No: 12519163 Project : Project 16547 Borehole No : See below Location : Bathurst NSW Depth : See below Sample No : See below Client ID : **TEST METHOD**: AS1289.2.1.1 See below Bulk Density Dry Density Depth FMC GHD Sample No BH ID (m) (%) (t/m<sup>3</sup>) (t/m<sup>3</sup>) Description SYD23-0317-02 BH4 9.3 - 9.53 2.159 2.033 granite 6.2 SYD23-0317-05 BH5 19.4 - 19.7 2.297 4.8 2.407 granite SYD23-0317-06 BH6 7.7 - 7.85 4.2 2.247 2.155 granite SYD23-0317-07 BH7 16.00 - 16.15 4.8 2.215 2.115 granite SYD23-0317-08 BH8 17.3 - 17.6 4.0 2.286 2.198 granite Comments : Bulk density performed on rock core by measurement & weight **GHD Pty Ltd** Tested By: AM 5/43 Herbert St Artarmon, NSW 2065 Date Tested: e 29/06/2023 Telephone: (02) 9462 4860 Fax: (02) 9462 4710 **GEOTECHNICAL TESTING SERVICES** Checked By: GV This document is issued in accordance with NATA's accreditation requirements. Approved P Accredited for compliance with ISO/IEC 17026 NATA Signatory Laboratory Accreditation Number: 679 D. Brooke Date : This laboratory certificate may not be reproduced except in full unless permission for the publication of an 6/07/2021

approved extract has been obtained from GHD Pty Ltd



#### **CERTIFICATE OF ANALYSIS** Page Work Order : ES2320297 : 1 of 4 Client : ROBERT CARR & ASSOCIATES P/L Laboratory : Environmental Division Sydney Contact : MR ROBERT CATER Contact : Customer Services ES Address Address : 277-289 Woodpark Road Smithfield NSW Australia 2164 : 92 HILL STREET **CARRINGTON NSW 2294** Telephone : +61 02 49029200 Telephone : +61-2-8784 8555 Project : GEOTECHNICAL INVESTIGATION Date Samples Received : 19-Jun-2023 16:08 Order number : 16547 Date Analysis Commenced : 20-Jun-2023 C-O-C number Issue Date : -----: 26-Jun-2023 13:47 Sampler : ROBERT CATER Site : -----

Accreditation No. 825 Accredited for compliance with ISO/IEC 17025 - Testing

This report supersedes any previous report(s) with this reference. Results apply to the sample(s) as submitted, unless the sampling was conducted by ALS. This document shall not be reproduced, except in full.

This Certificate of Analysis contains the following information:

: 8

: 8

: SYBQ/400/21

- General Comments
- Analytical Results

Additional information pertinent to this report will be found in the following separate attachments: Quality Control Report, QA/QC Compliance Assessment to assist with Quality Review and Sample Receipt Notification.

#### Signatories

Quote number

No. of samples received

No. of samples analysed

This document has been electronically signed by the authorized signatories below. Electronic signing is carried out in compliance with procedures specified in 21 CFR Part 11.

Signatories	Position	Accreditation Category		
Ankit Joshi	Senior Chemist - Inorganics	Sydney Inorganics, Smithfield, NSW		
Evie Sidarta	Inorganic Chemist	Sydney Inorganics, Smithfield, NSW		



#### **General Comments**

The analytical procedures used by ALS have been developed from established internationally recognised procedures such as those published by the USEPA, APHA, AS and NEPM. In house developed procedures are fully validated and are often at the client request.

Where moisture determination has been performed, results are reported on a dry weight basis.

Where a reported less than (<) result is higher than the LOR, this may be due to primary sample extract/digestate dilution and/or insufficient sample for analysis.

Where the LOR of a reported result differs from standard LOR, this may be due to high moisture content, insufficient sample (reduced weight employed) or matrix interference.

When sampling time information is not provided by the client, sampling dates are shown without a time component. In these instances, the time component has been assumed by the laboratory for processing purposes.

Where a result is required to meet compliance limits the associated uncertainty must be considered. Refer to the ALS Contract for details.

Key: CAS Number = CAS registry number from database maintained by Chemical Abstracts Services. The Chemical Abstracts Service is a division of the American Chemical Society.

LOR = Limit of reporting

^ = This result is computed from individual analyte detections at or above the level of reporting

ø = ALS is not NATA accredited for these tests.

~ = Indicates an estimated value.



# Analytical Results

					_			
Sub-Matrix: SOIL (Matrix: SOIL)			Sample ID	BH3, 0.55-1.00m	BH5, 2.3-2.8m	BH6, 1.5-1.95m	BH6, 3-3.45m	BH7, 5.8-6.0m
(								
		Sampli	ing date / time	08-Jun-2023 00:00	07-Jun-2023 00:00	08-Jun-2023 00:00	08-Jun-2023 00:00	06-Jun-2023 00:00
Compound	CAS Number	LOR	Unit	ES2320297-001	ES2320297-002	ES2320297-003	ES2320297-004	ES2320297-005
				Result	Result	Result	Result	Result
EA002: pH 1:5 (Soils)								
pH Value		0.1	pH Unit	7.8	6.5	7.3	7.3	6.9
EA010: Conductivity (1:5)								
Electrical Conductivity @ 25°C		1	µS/cm	252	31	77	119	37
EA055: Moisture Content (Dried @ 10	05-110°C)							
Moisture Content		1.0	%	15.9	12.7	22.3	9.6	6.7
ED040S : Soluble Sulfate by ICPAES								
Sulfate as SO4 2-	14808-79-8	10	mg/kg	400	40	20	60	40
ED045G: Chloride by Discrete Analys	ser							
Chloride	16887-00-6	10	mg/kg	50	<10	<10	<10	<10



# Analytical Results

Sub-Matrix: SOIL			Sample ID	BH8, 5.8-6.0m	BH8, 3.1-3.45m	BH8, 4.5-4.95m	 
(Matrix: SOIL)				-,			
· · · · · ·							
		Sampli	ng date / time	06-Jun-2023 00:00	06-Jun-2023 00:00	06-Jun-2023 00:00	 
Compound	CAS Number	LOR	Unit	ES2320297-006	ES2320297-007	ES2320297-008	 
				Result	Result	Result	 
EA002: pH 1:5 (Soils)							
pH Value		0.1	pH Unit	7.6	6.6	7.0	 
EA010: Conductivity (1:5)							
Electrical Conductivity @ 25°C		1	µS/cm	123	97	64	 
EA055: Moisture Content (Dried @ 10	05-110°C)						
Moisture Content		1.0	%	7.7	14.9	9.6	 
ED040S : Soluble Sulfate by ICPAES							
Sulfate as SO4 2-	14808-79-8	10	mg/kg	50	50	40	 
ED045G: Chloride by Discrete Analys	ser						
Chloride	16887-00-6	10	mg/kg	<10	50	<10	 
					1	1	

# Appendix D

**Consultant Declaration** 

# CONSULTANT DECLARATION

PROJECT DETAILS						
Project name	Bathurst Hospital Redevelopment					
Application number	SSD-64733959					
Address of subject land	361-365 Howick Street, Bathurst					
Lot / DP	Lot 100 in DP 1126063					
APPLICANT DETAILS						
Applicant name	Health Administration Corporation					
Applicant address	1 Reserve Road, St Leonards, NSW 2065					
REPORT DETAILS						
Name of report this	GEOTECHNICAL INVESTIGATION					
declaration relates	BATHURST HOSPITAL REDEVELOPMENT					
	361-365 HOWICK ST, WEST BATHURST NSW 2795					
Report reference no.	16547-202/4					
Report date	04/10/2024					
Company name (inc. ABN / ACN)	RCA Australia, ABN 53 063 515 711, ACN 063 515 711					
Author name	Robert Cater					
Author qualifications	BE (Civil), MEngSc					
Author address	92 Hill Street, Carrington, NSW 2294					
DECLARATION BY CO	NSULTANT					
Name	Dr Mark Allman					
Registration no.	N/A					
Organisation registered with	NSW Government SCM 1191					
Declaration	The undersigned declares that RCA Geotechnical Investigation Report reference no. 16547-202/4:					
	<ul> <li>has been prepared in accordance with the following policy, guidelines, or legislative requirements:</li> </ul>					
	<ul> <li>AS1726-2017 Geotechnical Site Investigations</li> </ul>					
	<ul> <li>contains all available information relevant to the environmental assessment of the development, activity or infrastructure to which the [consultant report] relates;</li> </ul>					
	<ul> <li>does not contain information that is false or misleading;</li> </ul>					
	<ul> <li>identifies and addresses the relevant Planning Secretary's environmental assessment requirements (SEARs) for the project;</li> </ul>					
	<ul> <li>identifies and addresses the relevant statutory requirements for the project, including any relevant matters for consideration in environmental planning instruments to which the [consultant report] relates; N/A</li> </ul>					
	<ul> <li>contains a consolidated summary of the proposed or necessary mitigation measures</li> </ul>					
Signature						