# Astrea

# Surveying Consulting Services

Part 1 – Desktop Analysis Review for Vincentia High SchoolPrepared for:(Commercial in Confidence)





Project Name	SINSW Due Diligence – Vincentia HS
Report Title	Survey Report
File Name	Land Survey DD – Vincentia – 8593 - Astrea – DDW005391/23

School Name	Vincentia High School	Consultancy Name	Astrea Pty Ltd
School ID Number	8593	Report Status	Final
School Address	142 The Wool Road, Vincentia.	Report Date:	15.12.2023
School Region	Southern NSW	Contract Number:	DDW005391/23

#### **Report Information**

Author	Scott Deveridge
Company Name	Astrea Pty Ltd
Contact Details	s.deveridge@astrea.com.au Mobile: 0425 285 270
Report Version	A
Report Date	30.10.2023
Project Reference	A4066-Vincentia

# **Document History**

Issue Date	Status	Comment/Description	Author	Reviewer	Approved
30.10.2023	Draft	Initial Issue	Scott Deveridge	Edyta Krynicka	Sup
15.12.2023	Final	Final Issue	Scott Deveridge	Edyta Krynicka	Sup

# Acronyms and Definitions

Acronym	Definition
AHD	Australian Height Datum
MGA	Map Grid of Australia
BYDA	Before You Dig Australia
AS5488	Australian Standard for Classification of Subsurface Utility Information
PM	Permanent Mark
SSM	State Survey Mark

# Table of Contents

1	EXE	CUTIVE SUMMARY	4
2	INTI	RODUCTION AND BACKGROUND	5
	2.1	Limitations	5
3	LAN	ID SURVEY DESTOP ANALYSIS REVIEW	6
	3.1	Site Information	6
	3.2	Survey Search Results	6
	3.3	Cadastral Map Search results	11
	3.4	Topographic Survey Information results	12
	3.5	BYDA Search and Underground Service Detection results	13
4	REC	OMMENDATION AND CONCLUSION	22

APPENDIX A – CADASTRAL SEARCH DOCUMENTS	23
APPENDIX B – BYDA SEARCH DOCUMENTS	
APPENDIX C – SHEETED DETAIL SITE SURVEY	79
APPENDIX D – UNDERGROUND SERVICE LOCATORS FIELD REPORT	85

# **1 EXECUTIVE SUMMARY**

Astrea was engaged to assist with the due diligence assessment of Milton Primary School. The scope of work included a desktop study, topographical survey and underground services survey.

We have collected, reviewed, and analysed all existing available site information. Land title information, survey control, and underground services have all been thoroughly searched from public records.

All information recovered has been summarised in this report and also provided within a dropbox folder. This folder also contains photographs taken on site. Appendix A of this report contains a summary of the cadastral land search.

A site detailed survey was undertaken in accordance with the scope of works contained in Part 2 of the Surveying Consulting Services brief version 1.5. The results of this survey have been summarised in this report and also in full in Appendix C and within a dropbox folder as Autocad dwg file and sheeted pdf.

The existing land, Lot 1 in DP 550361 and Lot 1 in DP 809057, is subject to Reservations and conditions contained in the crown grant and contain a notation on title that the land excludes minerals. The area of the existing site is 8.094 Ha.

As part of the topographical survey scope we search public utilities through a BYDA search. The results of that search have been summarised in Appendix B of this report.

Astrea has also undertaken subsurface utility investigations using non-invasive electromagnetic trace equipment at the proposed school site and surrounds. These services have been marked in field and subsequently surveyed to provide a utilities plan to aid in future planning and development.

The majority of utilities have been traced to QL-B specification – These traced utilities makeup the main services routes that show incoming water, electrical, gas and communication feeds to and from each building. The outgoing sewer and stormwater network has been investigated at pit interfaces and joined into the network where evidence exists.

# 2 INTRODUCTION AND BACKGROUND

## Vincentia High School:



As instructed, we have completed a desktop analysis review, detailed site survey, and underground service detection and survey in accordance with Contract ID DDWO05391/23. We understand the purpose of the survey is to assist with the due diligence around future replacement of demountables with permanent classrooms.

The scope of work is compliant with the Surveying Consulting Services, version 1.5, dated 21.03.2022, as provided with the request for tender. Part 1 – Desktop Analysis Review and Part 2 – Detailed Site Survey formed part of this work.

There were no other site documents provided to us.

We searched and ordered public records for land title and cadastral records, permanent survey control, and BYDA records for underground services.

The survey was undertaken during September 2023.

#### 2.1 Limitations

We have made every effort to collect, review and analyse all existing available site information and documentation. Within the detailed survey scope we have also made every effort to find visible services on the site and correlate with public utility records.

Some tracing/equipment limitations have been encountered within this investigation. These limitations include sewer lines that require specialised tracing equipment to determine lines/networks.

Astrea has tabled the significant information gaps within the report and recommends actions should the information be required for planning/design. These include - revisiting sections on completion of building works, CCTV pipe inspection and Non-Destructive Digging.

## 3 LAND SURVEY DESTOP ANALYSIS REVIEW

#### 3.1 Site Information

Vincentia High School is located at 142 The Wool Road, Vincentia. This is situated in the Local Government Area of Shoalhaven, Parish of Bherwerre, and County of St Vincent. The site is 8.094 ha in size and consists of land in certificate of titles 1/550361 and 1/809057.

#### 3.2 Survey Search Results

A cadastral records enquiry was undertaken and confirmed, for the address of 142 The Wool Road, Vincentia. The land is bound by The Wool Road in the north and national park to the east, south and west. Two unformed roads abut the site to the east and one unformed and unnamed road abuts the land to the south. The land holding is contained within certificate of titles 1/550361 and 1/809057 in the ownership of the Minister for Education and Training. The CRE report and subject plan are shown below. The following page illustrates the title diagrams DP 550361 and DP 809057. Full Cadastral search is contained in Appendix A.







FOLIO: 1/550361

\_\_\_\_

SEARCH DATE	TIME	EDITION NO	DATE
19/9/2023	2:17 PM	1	24/5/1994

# LAND

LOT 1 IN DEPOSITED PLAN 550361 AT VINCENTIA LOCAL GOVERNMENT AREA SHOALHAVEN PARISH OF BHERWERRE COUNTY OF ST VINCENT TITLE DIAGRAM DP550361

FIRST SCHEDULE

\_\_\_\_\_

MINISTER FOR EDUCATION

(AP U286648)

SECOND SCHEDULE (2 NOTIFICATIONS)

- 1 RESERVATIONS AND CONDITIONS IN THE CROWN GRANT(S)
- 2 LAND EXCLUDES MINERALS BY THE CROWN GRANT OF 137 ACRES 3 ROODS

NOTATIONS

UNREGISTERED DEALINGS: NIL

\*\*\* END OF SEARCH \*\*\*



FOLIO: 1/809057

\_\_\_\_

SEARCH DATE	TIME	EDITION NO	DATE
19/9/2023	2:17 PM	1	5/8/1991

#### LAND

----LOT 1 IN DEPOSITED PLAN 809057 AT VINCENTIA LOCAL GOVERNMENT AREA SHOALHAVEN PARISH OF BHERWERRE COUNTY OF ST VINCENT TITLE DIAGRAM DP809057

FIRST SCHEDULE \_\_\_\_\_

\_\_\_\_

MINISTER FOR SCHOOL EDUCATION AND YOUTH AFFAIRS (PA62688)

SECOND SCHEDULE (1 NOTIFICATION)

LAND EXCLUDES MINERALS -VIDE MEMORANDUM T447400 1

NOTATIONS \_\_\_\_\_

UNREGISTERED DEALINGS: NIL

\*\*\* END OF SEARCH \*\*\*

The existing land, Lot 1 in DP 550361 and Lot 1 in DP 809057, is subject to Reservations and conditions contained in the crown grant and contain a notation on title that the land excludes minerals. The area of the existing site is 8.094 Ha.

The area of the existing site is 4.042 Ha.

These easements are shown on the site detailed survey and highlighted on the cadastral map in this report.

Scims records were searched and the permanent survey control marks adopted for the survey are shown below. Australian Height Datum and MGA 2020 has been adopted as the coordinate system for the survey.





#### SCIMS SURVEY MARK REPORT AS AT: 22-SEP-2023

Your Reference: vincentia		Sear	ch Nu	umber:	1102354	L.		
MARK NAME STATUS	COORDINA	ATES AND HEIGHTS		CLASS	PU	LU	SOURCE	CSF CONVERGENCE AUSGEOID2020
PM 66500		Horizontal coor	dinates a	re adjusted	(or initia	lised) in GD	A2020	
	MGA2020	287056.963 6116022.339	56	В	0.03	0.04	301189	1.000153
	GDA2020	-35° 04' 33.97479" 150°	39' 52.	11638"				-1° 20' 33.53"
	GDA2020	Ellipsoidal Height	38.	U			300780	
	AHD71	Normal-Orthometric	19. <mark>36</mark> 7	В			210375	18.648
PM 66501	Horizontal coordinates are adjusted (or initialised) in GDA2020							
500 B 100 B	MGA2020	287148.053 6116179.025	56	В	0.03	0.04	301189	1.000153
	GDA2020	-35° 04' 28.96186" 150°	39' 55.	855 <mark>17</mark> "				-1° 20' 31.21"
	GDA2020	Ellipsoidal Height	36.	U			300780	
12	AHD71	Normal-Orthometric	17.600	В			210375	18.652

#### 3.3 Cadastral Map Search results

The site boundaries have been defined utilising reference marks found on the original plan of subdivision and more recent plans of survey surrounding the site. We are confident that title dimensions shown are available and the boundary location is suitable for this due diligence exercise. Our estimate on the overall accuracy of the resulting boundaries is +/- 50mm.

The land has frontage to and main vehicular access from The Wool Road.

The existing land, Lot 1 in DP 550361 and Lot 1 in DP 809057, is subject to Reservations and conditions contained in the crown grant and contain a notation on title that the land excludes minerals. The area of the existing site is 8.094 Ha.



#### 3.4 Topographic Survey Information results

Our approach was to collect as much data as thoroughly and quickly as possible to cause as little disruption to the school and also ensure a revisit would not be required. We utilised laser scanning for both the site and street frontage detail. Traditional surveying was done in tandom to pick up some tricky areas of terrain, service covers, painted underground services, and establish site control and the boundary survey.

#### **Survey Control:**

The survey control for this project was undertaken using a Leica TS16. A series of closed traverse loops were established throughout the school site as well as around the surrounding streets. State survey marks were located as part of this work. The survey has been placed on the MGA 2020 coordinate system and Australian Height Datum. The origin of marks adopted are shown on the previous page and the face of all plans. It is the responsibility of any user of this data to ensure any other data being integrated is on the same coordinate system.

#### **Point Cloud Data:**

As with the survey control the laser scanning of the site utilised a series of closed loops around the site buildings within the school grounds as well as a closed loop around the street frontages and perimeter of school. This ensured adequate coverage and overlap of data which is critical to an accurate registration of the overall point cloud. Furthermore, laser scan targets were placed across the site and at the street frontages. These were both acquired by the laser scanner and surveyed traditionally to gain accurate 3D coordinates for use in the final registration. Assessment of the final registration report confirmed to us that the final point cloud data sits within the stated accuracy below.

#### Survey Control: +/- 5mm. Extracted and Modelled Data: +/- 15-20mm

#### Registered Point Cloud Data: +/- 10-15mm Site Boundaries: +/- 50mm

The site and street frontages have been presented in 5sheets on our final survey drawing. The first sheet being the overall site at a scale of 1:1000 and the last 4 sheets at a scale of 1:300 dividing the site as shown on sheet 1 below. The full survey is contained in Appendix C.



## 3.5 BYDA Search and Underground Service Detection Results

As part of the topographical survey scope we search public utilities through a BYDA search.

Caller Details         Contact:       Astrea Locator       Caller Id:       3005839       Phone:       0.476.003.705         Company:       Astrea       Macquarie Park NSW 2113       Email:       dbyd@astrea.com.au         BANUSGT:       Banalit:       dbyd@astrea.com.au       Macquarie Park NSW 2113       Email:       dbyd@astrea.com.au         BANUSGT:       Banalit:       dbyd@astrea.com.au       Macquarie Park NSW 2113       Email:       dbyd@astrea.com.au         BANUSGT:       Banalit:       dbyd@astrea.com.au       Wincende Alford       Vincende Alford       Banalit:       dbyd@astrea.com.au         BANUSGT:       Banalit:       dbyd@astrea.com.au       Wincende Alford       Vincende Alford       Banalit:       dbyd@astrea.com.au         BANUSGT:       Banalit:       Astrea       Start Date:       End Date:       ibid@astrea.com.au         BANUSGT:       Banalit:       Astrea       Banalit:       Nanual Ecoavation       None Date:       ibid@astrea.com.au         BANUSGT:       Banalit:       Ostite:       Caster Activities:       Ecoavation:       Nanual Ecoavation:       None Date:       ibid@astrea.com.au       None Date:       ibid@astrea.com.au       None Date:       ibid@astrea.com.au       None Date:       ibid@astrea.com.au       None Date: </th <th colspan="6">Job No 34866513</th>	Job No 34866513					
Contact:       Attree       3005839       Phone:       0.476 003 705         Compary:       Attree       3005839       Phone:       0.476 003 705         Macquarie Park NSW 2113       Email:       dbyd@astrea.com.au         BRINSGT:       magnuarie Park NSW 2113       Email:       dbyd@astrea.com.au         BRINSGT:       magnuaries and the participating asset owners, who will send information to you directly.       The area for an area or area of an area of an area of an area of an area of a set.       Bord Park 2003       21/08/2024       21/08/20	Calle	r Details				
Company:       Astrea         Yeadmain Park NSW 2113       Email:       dbyd@astrea.com.au         Base Macquarie Park NSW 2113       User Reference:       Vincenta High School         Working on Behalf of:       Private       End Date:         Brow 2003       21/09/2023       21/09/2023         Address:       Caction of Workplace:       Caction in Road:         Both       Private       Manual Excavation, Machanical Excavation         Macquarie Park Now 2014       Park Park Park       Manual Excavation, Machanical Excavation         Macquarie Park Now 2014       Park Park Park Park Park Park Park Park	Contact:	Astrea Locator	Caller Id:	3005839	Phone:	0476 003 705
Address       32 Delnik       Macquane Park NSW 2113       maik       dydg@atrea.com.au         Image: Address and Enquiry Details       Banking and address and enquiry Details       Banking and address and enquiry Details         Rest: Address       Vincenda High School       Vincenda High School       Vincenda High School         Image: Address and Enquiry Details       User Reference:       Vincenda High School       Vincenda High School         Image: Address       Start Date:       End Date:       1009/2023       21/09/2023         Image: Address       Image: New York       End Date:       1009/2023       21/09/2023         Image: Address       Image: Address       Image: Address       Image: Address       Image: Address         Image: Address       Image: Address       Image: Address       Image: Address       Image: Address         Image: Address       Image: Address       Image: Address       Image: Address       Image: Address         Image: Address       Image: Address       Image: Address       Image: Address       Image: Address         Image: Address       Image: Address       Image: Address       Image: Address       Image: Address         Image: Address       Image: Address       Image: Address       Image: Address       Image: Address       Image: Address       Image: Address <td>Company</td> <td>: Astrea</td> <td></td> <td></td> <td></td> <td></td>	Company	: Astrea				
Macquarie park NSW 2113       Ensure       Digigational contract         Dig Site and Enquiry Details         ABNUSCT: Emanging the location of the proposed dig site and does not display any asset owners' pipe or cables. The area philighted has been used only to identify the participating asset owners, who will send information to you directly.         Image: Display the intervent of the proposed dig site and does not display any asset owners' pipe or cables. The area philighted has been used only to identify the participating asset owners, who will send information to you directly.         Image: Display the intervent of the proposed dig site and does not display any asset owners' pipe or cables. The area philighted has been used only to identify the participating asset owners, who will send information to you directly.         Image: Display the intervent of the proposed dig site and does not display any asset owners' pipe or cables. The area philiphic does not display any asset owners' pipe or cables. The area philiphic does not display any asset owners' pipe or cables. The area philiphic does not display any asset owners' pipe or cables. The area philiphic does not display any asset owners' pipe or cables. The area philiphic does not display any asset owners' pipe or cables. The area philiphic does not display any asset owners' philiphic does not cables. The area philiphic does not	Address:	32 Delhi Rd	Free it.	allowed Allowed and a second	200	
Dig Site and Enquiry Details         ABMING: The map below only displays the location of the proposed dig site and does not display any asset owner; pipe or cables. The area inhighted has been used only to identify the participating asset owners, who will send information to you directly.         Working on Behalf of:       Vincentia High School         Working on Behalf of:       Private         Enquiry Date:       Start Date:         Bi02/2023       21/09/2023         Address:       Had Date:         Bi02/2023       21/09/2023         Address:       Costed Activities         Excavation       Manual Excavation, Mechanical Excavation         Non-Destructive Digging       Location in Road:         Location of Workplace:       Location in Road:         0       Do North dig vithout plans, Safe excavation is your mess submit a new enquiry:         0       Do North dig vithout plans, Safe excavation is your responsibility. If you do not unders the plans or how to proceed safely, plaase contact the relevant asset owner.         The oldgement of an enquiry does not authorize the project to commence. You must obtain all necestary information from any and all likel impacted asset owners plor to excavation.         If plants are not received within 2 working days, contact the asset owners directly & quote their Sequence No.         ALWAYS perform an onsile inspection for the presence of asset. Should you require an onsile inspecton for the presence of asset owners and ide digi	CALCER CO.	Macquarie Park NSW 2113	Cintain	dbyd@astrea.com.	40	
ABAINING:The map below only displays the location of the proposed dig site and does not display any asset owners? pipe or tables. The area phighted has been used only to identify the participaning asset owners, who will send information to you directly.         Image: Comparison of the proposed dig site and does not display any asset owners? pipe or tables. The area phighted has been used only to identify the participaning asset owners, who will send information to you directly.         Image: Comparison of the proposed dig site and does not display any asset owners? pipe or tables. The area phighted has been used only to identify the participaning asset owners. Who will send information to you directly.         Image: Comparison of the display and behalf of:       Private         Enquity Date:       Start Date:       End Date:         100/2023       21/09/2023       21/09/2023         Address:       142 The Wool Road       Non-Destructive Digging         Location of Workplace:       Location in Road:       Exavation         Dia Purpose:       Compath, Nacue Strip, Road         Image: Compath/Provide Strip       Poly and Strip Strip       Poly and Strip         Dia NOT dig without plans. Safe excavation is your repponsibility. If you do not unders the plant are not we proceed afaely, plants contact the relevant asset owners directly. Poly and strip are not we proceed afaely, plants contact the asset owners directly. Poly and strip asset owners directly. Poly and strip asset owners directly. Poly and strip asset owners directly. B quote their Sequence No.         AlWXDS perform an onsite ingrese	Dig S	ite and Enquiry Detail	S			
User Reference:       Vincentia High School         Wriking on Behalf of:       Private         Equity Date:       Start Date:       10/02/023         12/09/2023       21/09/2023       21/09/2023         Address:       142 The Wool Road       Vincentia High School         13/09/2023       21/09/2023       21/09/2023         Address:       142 The Wool Road       Vincentia High School         142 The Wool Road       Vincentia NSW 2540       Diab Purpose:       Onsite Activities         Excavation       Manual Excavation, Mechanical Excavation       Non-Destructive Digging         Location of Workplace:       Location in Road:       Diab Purpose:       Corpath, Nacue Scrip, Road         -       Check that the location of the dig site is correct. If not you muss submit a new enquiry       Bohuld the scope of works change, or plan validity dates expire, you muss submit a new enquiry         -       De NOT dig without plans. Safe excavation is your responsibility. If you do not unders the plane on how to proceed alarly, plaase contact the relevant asset owners: If not you muss submit a new enquiry         -       Not supplied         Moto Supplied       Not supplied         -       Not supplied         -       Part Descent Supplied         -       Part Descent Supplicy of Care and safe ligging requirements.	ARNING:Th ghlighted ha	e map below only displays the is been used only to identify th	location of the proposed dig site and doe he participating asset owners, who will ser	es not display any asse nd information to you	et owners' pip directly.	e or c <mark>a</mark> bles. The area
Working on Behalf of:       Private         Enquiry Date:       Start Date:       End Date:         19/09/2023       21/09/2023       21/09/2023         Address:       142 The Wool Road         1/10 pripose:       Onsite Activities:         Excavation       Manual Excavation, Mechanical Excavation         Non-Destructive Digging       Location in Road:         Both       Footpath, Nature Strip, Road         Check that the location of the dig site is correct. If not you must submit a new enquiry         • Should the scope of works change, or plan validity dates expire, you must submit a new enquiry         • Should the scope of works change, or plan validity dates expire, you must submit a new enquiry         • Should the scope of works change, or plan validity dates expire, you must submit a new enquiry         • Do NOT dig without plans. Safe excavation is your responsibility. If you do not unders         • De Not dig without plans. Safe excavation is your responsibility. If you do not unders         • De lodgement of an enquiry does not autioning the project to commence. You must obtain all necessary information from any and all likel         Impacted asset owners plot to excavation.         If plan are not received within 2 working days, contact the asset owners directly & quote their Sequence No.         LVWXYS perform an onsite inspection for the presence of asset. Should your reguine an onsite location, contact the asset owners directly. Plenemeber, pla	-		User Reference:	Vincentia High S	chool	
Enquive Date:       Start Date:       End Date:         18/08/2023       21/08/2023       21/08/2023       21/09/2023         Address:       142 The Wool Road       Vincentia NW 2540         Job Purpose:       Manual Excavation, Mechanical Excavation         Non-Destructive Ubigging       Location of Workplace:       Location in Road:         Both       Footpath, Nature Strip, Road         - Check that the location of the dig site is correct. If not you must submit a new enquiry       • Should the scope of work: change, or plan validity dates expire, you must submit a new enquiry.         • Do NOT dig without plans. Safe excavation is your responsibility. If you do not unders the should you require an onsite inscent the relevant asset owner.         Notest/Description of Works:       Not supplied         Your Responsibilities and Duty of Care       Not supplied         The lodgement of an enquiry does not authorize the project to commence. You must obtain all necessary information from any and all likel impacted asset owners prior to excavation.         Irplana are noteviewing within the ward location of asset.       Not supplied         You damage an underground asset your practice, with www.byda.com.au       The set on			Working on Behalf of:	Private		
19/09/2023       21/09/2023       21/09/2023         Address:       142 The Wool Road         142 The Wool Road       Non-Destructive Digging         100 Purpose:       Onsite Activities         Excavation       Manuas Subsci Road         100 Purpose:       Contain in Road         Excavation       Manuas Subsci Road         100 Purpose:       Contain in Road         Excavation of Workplace:       Location in Road         100 Purpose:       Contain in Road         Both       Forospath, Naure Strip, Road         100 Purpose:       Contain in Road         100 Point dig without plans. Safe excavation is your responsibility. If you do not unders the soft how to plans on how to proceed safely, please contact the relevant asset owners.         Notes/Description of Works:       Not supplied         Your Responsibilities and Duty of Care         The longement of an enquiry does not authorize the project to commence. You must obtain all necessary information from any and all likel         Impacted asset owners prior to excavation.       Provide to excavation.         If you do not deail the exact location of assets.       Should you require an onsite location, contact the asset owners directly. P         Promote to escavation.       Status deases.       Portio to escavation.         Portiols to escavation asset to subsci no		- Andrew - A	Enquiry Date:	Start Date:	E	nd Date:
Address:       142 The Wool Road Vincentia NSW 2540         Job Purpose:       Onsite Activities:         Excavation       Manual Excavation, Mechanical Excavation Non-Destructive Digging         Location of Workplace:       Location in Road:         Both       Footpath, Nature Strip, Road         • Check that the location of the dig site is correct. If not you must submit a new enquiry       • Onotid the scope of works change, or plan validity dates expire, you must submit a new enquiry         • On Of dig without plans. Safe excavation is your responsibility. If you do not unders the plans or how to proceed safely, please contact the relevant asset owners.         Notes/Description of Works:         Notes/Description of Works:         Notes/Description of the presence of assets. Should you require an onsite location, contact the asset owners directly. Please enemetry plans on notate inspection for the presence of assets.         Pothe to establish the exact location of all underground assets using a hand showl, before using heavy machinery.         Post dames an underground asset you MUST advise the asset owner directly & quote their Sequence No.         Asset Owner Details         assets owners listed below have been requirements regarding Duty of Care and asfed digging requirements.         Post dames an underground asset you MUST advise the asset owner directly & quote their Sequence No.         ALWAYS perform an onsite inspection of all underground assets.         Pothole to establish the exact location of all und			18/08/2023	21/08/2023	2	1/09/2023
In a the Wool hoad Vincentia NW 2540         Job Purpose:       Onsite Activities:         Excavation       Manual Excavation, Mechanical Excavation Non Destruice Digging:         Outcation of Workplace:       Location in Road:         Both       Footpath, Nature Strip, Road         Incential excavation of the dig site is correct. If notyou must submit a new enquiry       Should the scope of works change, or plan validity dates expire, you must submit a new enquiry.         Do NDT dig without plans. Safe excavation is your responsibility. If you do not unders the anso or how to proceed safely, please contact the relevant asset owners.         Nets/Description of Works:       Not supplied         The lodgement of an enquiry does not authorise the project to commence. You must obtain all necessary information from any and all likel impacted asset owners pior to excavation.         If plan are not received within 2 working days, contact the asset owners directly & quote their Sequence No.         LIVWYS perform an onsite inspection for the presence of assets. Should you require an onsite location, contact the asset owners directly. Premember, plan do not detail the exact location of all underground assets using a hand shovel, before using heavy machiney.         Pothole to stepping to prive to contact the asset owners motile location, contact the asset owners directly. Premember, plans on on stea lenge to private policy and the terms and disclaimers set out at www.byda.com.au         Browner Disted Both mergenees to to asset.       Potope Care using heavy underenes.         Unwys performa n			Address:			
Job Purpose:       Onsite Activities         Excavation       Manual Excavation, Machanical Excavation, Nochanical Excavation, Submit a net enquiry. <ul> <li>Check that the location of the dig life is correct. If not you must submit a net enquiry.</li> <li>Do NOT dig without plans. Safe excavation is your responsibility. If you do not unders the plans or how to proceed safely, please contact the relevant asset owners.</li> </ul> <ul> <li>De NOT dig without plans. Safe excavation is your responsibility. If you do not unders the plans or how to proceed safely, please contact the relevant asset owners.</li> <li>Not supplied</li> </ul> <ul> <li>De NOT dig without plans. Safe excavation is your responsibility. If you do not unders the plans or how to proceed safely, please contact the asset owners.</li> </ul> <ul> <li>De NOT dig without plans. Safe excavation is your responsibility. If you do not unders the plans on one device asset.</li> </ul> <ul> <li>De Not dis safe digging requirements.</li> </ul>			142 The Wool Road Vincentia NSW 2540			
Excavation       Manual Excavation, Mechanical Excavation Non-Destructive Digging         Excavation       Manual Excavation, Mechanical Excavation Non-Destructive Digging         Excavation       Non-Destructive Digging         Excavation       Footpath, Nature Strip, Road			lob Purpose:	Onsite	Activities	
Location of Workplace:         Location in Road:           Both         Footpath, Nature Strip, Road           Image: Construction of the digite is correct. If not you must submit a new enquiry.         Should the scope of works change, or plan validity dates expire, you must submit a new enquiry.           Image: Do NOT dig without plans. Safe excavation is your responsibility. If you do not unders the plans or how to proceed safely, please contact the relevant asset owners.           Weak-Obscription of Works:           Not supplied           The lodgement of an enquiry does not authorise the project to commence. You must obtain all necessary information from any and all likel impacted asset owners prior to excavation.           If plans are not received within 1 2 working days, contact the asset owners directly & quote their Sequence No.           ALWXYS perform an onsite inspection for the presence of assets.           Pothole to establish the exact location of all underground assets using a hand shovel, before using heavy machinery.           Ensure you adhere to any State legislative requirements regarding Duty of Care and safe digging requirements.           If you damage an underground asset you MUST advites the asset owners and all scaliners set out at www.byda.com.au           Asset Owner Detail B           Asset owners listed below have been requested to contact you with information about their asset locations within 2 working days.           Asset owners listed below have been requested to contact you with information about their asset locations within 2 working days.		ne wood \$6	Excavation	Manua Non-D	al Excavation, estructive Dig	Mechanical Excavation ging
Both         Footpath, Nature Strip, Road           • Check that the location of the dig site is correct. If not you must submit a new enquiry           • Should the scope of works change, or plan validity dates expire, you must submit a ne enquiry.           • O NOT dig without plans. Safe excavation is your responsibility. If you do not unders the plans or how to proceed safely, please contact the relevant asset owners.           Notes/Description of Works:           Not diggement of an enquiry does not authorize the project to commence. You must obtain all necessary information from any and all likel impacted asset owners prior to excavation.           I' plans are not received within 2 working days, contact the asset owners directly & quote their Sequence No.           ALWXYS perform an onsite inspection for the presence of assets. Should you require an onsite location, contact the asset owners directly. Plans are not received within 2 working days, contact the assets using a hand shovel, before using heavy machinery.           Ensure you adhere to any State legislater requirements regarding Duty of Care and safe digging requirements.           By using this service, yob UNUST advise the asset owner immediately.           By using this service, yob UNUST advise the asset owner immediately.           By using this service, yobidy and the terms and disclaimers taset locations within 2 working days.           Attributed the allowed to information issued by post. It is <u>your responsibility</u> to disclaimers and arou           By using this service, yobidy and the terms and disclaimers taset locations within 2 working days.		he /	Location of Workplace:	Locati	on in Road:	
<ul> <li>Check that the location of the dig site is correct. If not you must submit a new enquiry         <ul> <li>Should the scope of works change, or plan validity dates expire, you must submit a new enquiry.</li> <li>Do NOT dig without plans. Safe excavation is your responsibility. If you do not unders the plans or how to proceed afely, please contact the relevant asset owners.</li> </ul> </li> <li>Notes/Description of Works:         <ul> <li>Not supplied</li> </ul> </li> <li>Pologe not a enquiry does not authoring the project to commence. You must obtain all necessary information from any and all likel impacted asset owners prior to excavation.</li> <li>If plans are not received within 2 working days, contact the asset owners directly &amp; quote their Sequence No.</li> <li>ALWAYS perform an onsite inspection of all underground assets using a hand shovel, before using heavy machinery.</li> <li>Prove damage an underground asset you WUST advice the asset owner and safe digging requirements.</li> <li>If you damage an underground asset you WUST advice the asset owner and safe digging requirements.</li> <li>If you damage an underground asset, you with information about, before using heavy machinery.</li> <li>Ensure you adhere to any State legislative requirements regarding DUty of Care and safe digging requirements.</li> <li>If you damage an underground asset you WUST advice the asset owner and safe digging requirements.</li> <li>If you damage an underground asset you with information about their asset locations within 2 working days.</li> <li>ditional time should be allowed for information issued by post. It is your responsibility to identify at asset owners information issued by out their offices to collect plans.</li> <li>asset owners instel below have been requersed owners are registered with the Before You Dig service, so it is your responsibility to identify at asset owners insting ther directly.<td></td><td></td><td>Both</td><td>Footpa</td><td>ath, Nature Sti</td><td>rip, Road</td></li></ul>			Both	Footpa	ath, Nature Sti	rip, Road
Your Responsibilities and Duty of Care         The lodgement of an enquipy does not authorise the project to commence. You must obtain all necessary information from any and all likel impacted asset owners prior to excavation.         If plans are not received within 2 working days, contact the asset owners directly & quote their Sequence No.         ALWAYS perform an onsite inspection for the presence of assets. Should you require an onsite location, contact the asset owners directly. P remember, plans do not detail the exact location of assets.         Pothole to establish the exact location of all underground assets using a hand shovel, before using heavy machinery.         Ensure you adhere to any State legislative requirements regarding Duty of Care and safe digging requirements.         If you damage an underground asset you MUST advise the asset owner immediately.         By using this service, you agree to Privacy Policy and the terms and disclaimers set out at www.byda.com.au         For more information on safe excavation practices, visit www.byda.com.au         Asset Owner Details         exasets owners listed below have been requested to contact you with information about their asset locations within 2 working days.         ditional time should be allowed for information issued by post. It is your responsibility to identify the presence of any underground assets in and arour ar proposed dig site. Please be aware, that not all asset owners are registered with the Before You Dig service, so it is your responsibility to identify are taxy asset owners not listed here directly.         Asset owners not listed here directly.       Asset owners not		Ň.	Notes/Description of Works: Not supplied			
The lodgement of an enquiry does not authorise       the project to commence. You must obtain all necessary information from any and all likel impacted asset owners prior to excavation.         If plans are not received within 2 working days, contact the asset owners directly & quote their Sequence No.         ALWAYS perform an onsite inspection for the presence of assets. Should you require an onsite location, contact the asset owners directly. P remember, plans do not detail the exact location of all underground assets using a hand shovel, before using heavy machinery.         Ensure you adhere to any State legislative requirements regarding Duty of Care and safe digging requirements.         If you damage an underground asset you MUST advise the asset owner immediately.         By using this service, you agree to Privacy Policy and the terms and disclaimers set out at www.byda.com.au         For more information on safe excavation practices, visit www.byda.com.au         Asset Owner Details         e assets owners not listed below have been requested to contact you with information about their asset locations within 2 working days.         ditional time should be allowed for information issued by post. It is your responsibility to identify the presence of any underground assets in and arour aur proposed dig site. Please be aware, that not all asset owners are registered with the Before You Dig service, so it is <u>your responsibility</u> to identify and tast ay asset owners highlighted by asterisks ** require that you visit their offices to collect plans.         kester owners highlighted with a hash # require that you call them to discuss your enquiry or to obtain plans.         eq, No.	Vaure	Responsibilities and I	Duty of Care			
Asset Owner Details         e assets owners listed below have been requested to contact you with information about their asset locations within 2 working days.         ditional time should be allowed for information issued by post. It is your responsibility to identify the presence of any underground assets in and arous ur proposed dig site. Please be aware, that not all asset owners are registered with the Before You Dig service, so it is your responsibility to identify an ntact any asset owners not listed here directly.         Asset owners highlighted by asterisks ** require that you visit their offices to collect plans.         ksset owners highlighted with a hash # require that you call them to discuss your enquiry or to obtain plans.         eq. No.       Authority Name       Phone       Status         28546382       Endeavour Energy       (02) 9853 4161       NOTIFIED         28546381       NBN Co NswAct       1800 687 626       NOTIFIED         28546383       Telstra NSW South       1800 653 935       NOTIFIED	Tour	ment of an enquiry <u>does not a</u>	<u>uthorise</u> the project to commence. You m on.	ust obtain all necessar	ry information	from any and all like
e assets owners listed below have been requested to contact you with information about their asset locations within 2 working days. ditional time should be allowed for information issued by post. It is <u>your responsibility</u> to identify the presence of any underground assets in and arous ur proposed dig site. Please be aware, that not all asset owners are registered with the Before You Dig service, so it is <u>your responsibility</u> to identify and ntact any asset owners not listed here directly. Asset owners highlighted by asterisks ** require that you visit their offices to collect plans. Isset owners highlighted with a hash # require that you call them to discuss your enquiry or to obtain plans. Eq. No. Authority Name Phone Status 28546382 Endeavour Energy (02) 9853 4161 NOTIFIED 28546381 NBN Co NswAct 1800 687 626 NOTIFIED 28546380 Shoalhaven Water (02) 4429 3214 NOTIFIED 28546383 Telstra NSW South 1800 653 935 NOTIFIED	The lodge impacted If plans ar ALWAYS p remember Pothole to Ensure yo If you dan By using t	asset owners prior to excavation e not received within 2 workin erform an onsite inspection for plans do not detail the exact setablish the exact location on u adhere to any State legislation hage an underground asset yo his service, you agree to Privat information on safe excaval	g days, contact the asset owners directly & ir the presence of assets. Should you requilocation of assets. if all underground assets using a hand sho re requirements regarding Duty of Care an u MUST advise the asset owner immediate y Policy and the terms and disclaimers set ion practices, visit www.byda.com.au	& quote their Sequenc ire an onsite location, ovel, before using heav id safe digging require ely. t out at <b>www.byda.co</b>	contact the a vy machinery. ments. <b>m.au</b>	sset owners directly. P
Asset owners highlighted with a hash # require that you visit their offices to collect plans. seet owners highlighted with a hash # require that you call them to discuss your enquiry or to obtain plans. eq. No. Authority Name Phone Status 28546382 Endeavour Energy (02) 9853 4161 NOTIFIED 28546381 NBN Co NswAct 1800 687 626 NOTIFIED 28546380 Shoalhaven Water (02) 4429 3214 NOTIFIED 28546383 Telstra NSW South 1800 653 935 NOTIFIED	The lodge impacted If plans ar ALWAYS p remember Pothole to Ensure yo If you dan By using t For more	asset owners prior to excavation e not received within 2 workin erform an onsite inspection for plans do not detail the exact o establish the exact location o u adhere to any State legislatin age an underground asset yo his service, you agree to Privace information on safe excavant t Owner Details	g days, contact the asset owners directly & r the presence of assets. Should you requilocation of assets. f all underground assets using a hand sho re requirements regarding Duty of Care an u MUST advise the asset owner immediate y Policy and the terms and disclaimers set ion practices, visit www.byda.com.au	& quote their Sequenc ire an onsite location, svel, before using hear id safe digging require ely. t out at www.byda.com	vy machinery. ments.	sset owners directly. P
Authority Name         Phone         Status           28546382         Endeavour Energy         (02) 9853 4161         NOTIFIED           28546381         NBN Co NswAct         1800 687 626         NOTIFIED           28546380         Shoalhaven Water         (02) 4429 3214         NOTIFIED           28546383         Telstra NSW South         1800 653 935         NOTIFIED	The lodge impacted If plans ar ALWAYS p remember Pothole to Ensure yoo If you dan By using t For more Asse: me assets own ditional time ur proposed ntact any asset	asset owners prior to excavation e not received within 2 workin erform an onsite inspection for plans do not detail the exact o establish the exact location o u adhere to any State legislatin age an underground asset you his service, you agree to Privac information on safe excavat t Owner Details hers listed below have been requisioned be allowed for information dig site. Please be aware, that no iet owners not listed here direct	g days, contact the asset owners directly & r the presence of assets. Should you requi- location of assets. f all underground assets using a hand sho re requirements regarding Duty of Care an u MUST advise the asset owner immediate y Policy and the terms and disclaimers set <b>ion practices, visit www.byda.com.au</b> lested to contact you with information about on issued by post. It is <u>your responsibility</u> to at all asset owners are registered with the Be ly.	& quote their Sequenc ire an onsite location, ovel, before using hear id safe digging require ely. t out at www.byda.com their asset locations wi b identify the presence of efore You Dig service, so	contact the a contact the a vy machinery. m.au ithin 2 working of any undergro it is <u>your res</u>	sset owners directly. Pl days. pund assets in and arour ponsibility to identify ar
28546382         Endeavour Energy         (02) 9853 4161         NOTIFIED           28546381         NBN Co NswAct         1800 687 626         NOTIFIED           28546380         Shoalhaven Water         (02) 4429 3214         NOTIFIED           28546383         Telstra NSW South         1800 653 935         NOTIFIED	The lodge impacted if plans ar ALWAYS p remember Pothole to Ensure yo if you dan By using t For more Asset ditional time ur proposed ntact any ass Asset owners	asset owners prior to excavation e not received within 2 workin erform an onsite inspection for plans do not detail the exact o establish the exact location o u adhere to any State legislatin hage an underground asset yo his service, you agree to Privace information on safe excavat t Owner Details towner Details thould be allowed for information dig site. Please be aware, that no should be allowed for information should be allowed for information should be allowed for information thet owners not listed here direct s highlighted by asterisks ** required highlighted with a hash # required	g days, contact the asset owners directly & r the presence of assets. Should you requi- location of assets. f all underground assets using a hand sho re requirements regarding Duty of Care an u MUST advise the asset owner immediate y Policy and the terms and disclaimers set tion practices, visit www.byda.com.au ested to contact you with information about on issued by post. It is <u>your responsibility</u> to at all asset owners are registered with the Be ly. uire that you visit their offices to collect plan e that you call them to discuss your enquiry of	& quote their Sequenc ire an onsite location, ovel, before using hear id safe digging require ely. t out at www.byda.co their asset locations wi o identify the presence of efore You Dig service, so 15. or to obtain plans.	contact the a vy machinery. ments. m.au ithin 2 working of any undergro it is <u>your res</u>	days. sset owners directly. Pl days. aund assets in and arour ponsibility to identify ar
28546381         NBN Co NswAct         1800 687 626         NOTIFIED           28546380         Shoalhaven Water         (02) 4429 3214         NOTIFIED           28546383         Telstra NSW South         1800 653 935         NOTIFIED	The lodge impacted if plans an ALWAYS p remember Pothole to Ensure yo if you dan By using t For more Asset e assets owner ditional time ur proposed intact any ass Asset owners eq. No.	asset owners prior to excavation e not received within 2 workin erform an onsite inspection for plans do not detail the exact pestablish the exact location of u adhere to any State legislatin hage an underground asset yo his service, you agree to Privac information on safe excavant t Owner Details even listed below have been requised should be allowed for informati- dig site. Please be aware, that most et owners not listed here direct is highlighted by asterisks ** requir Authority Name	g days, contact the asset owners directly & r the presence of assets. Should you requilocation of assets. f all underground assets using a hand sho re requirements regarding Duty of Care an u MUST advise the asset owner immediate y Policy and the terms and disclaimers set tion practices, visit www.byda.com.au lested to contact you with information about on issued by post. It is <u>your responsibility</u> to ot all asset owners are registered with the Be ly. uire that you visit their offices to collect plan e that you call them to discuss your enquiry of the set of the	& quote their Sequenc ire an onsite location, ovel, before using hear id safe digging require ely. t out at <b>www.byda.co</b> their asset locations wi b identify the presence of efore You Dig service, so 15. or to obtain plans. <b>Phone</b>	contact the a contact the a vy machinery. ments. m.au ithin 2 working of any undergro of any undergro t it is <u>your res</u>	sset owners directly. Pl days. und assets in and arour <u>ponsibility</u> to identify ar <b>tatus</b>
28546380         Shoalhaven Water         (02) 4429 3214         NOTIFIED           28546383         Telstra NSW South         1800 653 935         NOTIFIED	The lodge impacted If plans an ALWAYS p remember Pothole to Ensure you If you dan By using t For more Asset assets own ditional time ur proposed intact any ass Asset owners eq. No. 28546382	asset owners prior to excavation e not received within 2 workin erform an onsite inspection for plans do not detail the exact pestablish the exact location of u adhere to any State legislath hage an underground asset yo his service, you agree to Privac information on safe excavant t Owner Details ers listed below have been requi- should be allowed for informati- dig site. Please be aware, that meet owners not listed here direct s highlighted by asterisks ** requir Authority Name Endeavour Energy	g days, contact the asset owners directly & r the presence of assets. Should you requi- location of assets. f all underground assets using a hand sho re requirements regarding Duty of Care an u MUST advise the asset owner immediate y Policy and the terms and disclaimers set <b>ion practices, visit www.byda.com.au</b> lested to contact you with information about on issued by post. It is <b>your responsibility</b> to at all asset owners are registered with the Be ly. uire that you visit their offices to collect plan e that you call them to discuss your enquiry of the set of the set of	& quote their Sequenc ire an onsite location, ovel, before using hear id safe digging require ely. t out at www.byda.com their asset locations wi b identify the presence of efore You Dig service, so 15. or to obtain plans. Phone (02) 9853 4161	contact the a contact the a vy machinery. m.au ithin 2 working of any undergro b it is <u>your res</u>	days. Jund assets in and arour ponsibility to identify ar tatus OTIFIED
28546383 Telstra NSW South 1800 653 935 NOTIFIED	The lodge impacted If plans ar ALWAYS p remember Pothole to Ensure yoo If you dan By using t For more Asset e assets own ditional time ur proposed ntact any ass Asset owners eq. No. 28546382 28546381	asset owners prior to excavation e not received within 2 workin erform an onsite inspection for plans do not detail the exact pestablish the exact location of u adhere to any State legislatin age an underground asset you his service, you agree to Privac information on safe excavant t Owner Details ers listed below have been requi- should be allowed for informati- dig site. Please be aware, that no ret owners not listed here direct s highlighted by asterisks ** required highlighted with a hash # required Authority Name Endeavour Energy NBN Co NswAct	g days, contact the asset owners directly & r the presence of assets. Should you requilocation of assets. f all underground assets using a hand sho re requirements regarding Duty of Care an u MUST advise the asset owner immediate ty Policy and the terms and disclaimers set <b>ion practices, visit www.byda.com.au</b> lested to contact you with information about on issued by post. It is <u>your responsibility</u> to at all asset owners are registered with the Be (y. uire that you visit their offices to collect plan e that you call them to discuss your enquiry of the set of the set of th	& quote their Sequenc ire an onsite location, ovel, before using hear id safe digging require ely. t out at www.byda.com their asset locations wi b identify the presence of efore You Dig service, so 15. or to obtain plans. Phone (02) 9853 4161 1800 687 626	contact the ar contact the ar yr machinery. m.au ithin 2 working of any undergro of any undergro b it is <u>your res</u> N N	days. sound assets in and arour ponsibility to identify ar tatus OTIFIED OTIFIED
	The lodge impacted If plans ar ALWAYS p remember Pothole to Ensure yoo If you dan By using t For more Asset e assets owners eq. No. 28546382 28546380	asset owners prior to excavation e not received within 2 workin erform an onsite inspection for plans do not detail the exact o establish the exact location o u adhere to any State legislatin age an underground asset yo his service, you agree to Privace <b>information on safe excavat</b> t <b>Owner Details</b> ters listed below have been requi- should be allowed for informati- dig site. Please be aware, that m ist owners not listed here direct s highlighted by asterisks ** req- highlighted with a hash # requiries <b>Authority Name</b> Endeavour Energy NBN Co NswAct Shoalhaven Water	g days, contact the asset owners directly & r the presence of assets. Should you requilocation of assets. f all underground assets using a hand shore requirements regarding Duty of Care an u MUST advise the asset owner immediate y Policy and the terms and disclaimers set tion practices, visit www.byda.com.au lested to contact you with information about on issued by post. It is <u>your responsibility</u> to at all asset owners are registered with the Be ly. uire that you visit their offices to collect plan e that you call them to discuss your enquiry of the set of the s	& quote their Sequenc ire an onsite location, ovel, before using hear id safe digging require ely. t out at www.byda.com their asset locations wi b identify the presence of efore You Dig service, so 15. or to obtain plans. Phone (02) 9853 4161 1800 687 626 (02) 4429 3214	contact the ar contact the ar vy machinery. ments. m.au ithin 2 working of any undergro it is <u>your res</u> it is <u>your res</u> N N N	days. bund assets in and arour ponsibility to identify ar tatus OTIFIED OTIFIED OTIFIED

Table 1 – AS5488-2019 s	ummary of Quality Levels
Quality Level D	- (least accurate level and if used on its own has a high risk of damage) QL-D information is generally obtained from existing records provided by utilities as a result of a Before You Dig enquiry being lodged. In many cases the asset depicted on the plan is in a schematic format only and intended only to indicate its presence.
Quality Level C	<ul> <li>- (low accuracy and a high risk of damage) Is described as a surface feature correlation or an interpretation of the approximate location and attributes of a subsurface utility asset using a combination of existing records and site survey of visible evidence – for example you can see the pit lids shown on the plan but the actual position of underground connection between pits is still assumed.</li> </ul>
Quality Level B	<ul> <li>- (significant risk reduction) Provides relative subsurface feature locations in three dimensions. The minimum requirement for QL- B is relative spatial position, this can be achieved via an electromagnetic frequency locating device. An electronic location provided by a DBYD Certified Locator to QL-B standard would have a maximum horizontal tolerance of plus or minus 300mm and a maximum vertical tolerance of plus or minus 500mm.</li> </ul>
Quality Level A	- (meets location accuracy standards for minimum risk when excavating) Is the highest Quality Level accuracy and consists of positive identification of the attribute and location of a subsurface utility at a point to an absolute spatial position in three dimensions. It is the only quality level that defines a subsurface utility as 'Validated'.

## Equipment and Methodology.

Astrea DBYD accredited technicians were deployed to the school to investigate subsurface utilities pursuant with AS5488 – 2019 specification.

Field technicians have located subsurface utilities using various techniques. These can be classified into their appropriate levels (see below) depending on the method used to identify each service. (AS5488-2019: Summary of quality levels is depicted below in (table 1).

BYD (Before You Dig) and existing site records were first reviewed to gain an understating of the infrastructure that may be present within the school. The information on record was however minimal and thus in field investigations were used as the primary method for data collection. It is important to note the class assigned to each of subsurface utility asset as this helps to define the accuracies and confidence levels attributed to various parts of the utilities network.

Primary equipment used in the investigations consisted of the Radio Detection Electromagnetic transmitter/receiver TX10 and 8200 devices in conjunction with Mala Easy Locator Pro – Ground Penetrating Units.

## Method of Investigation:

Water - Revision of Sydney Water BYD plans – information of street frontages only, no information of internal network is on record.

Water services were investigated first by visual surface features and connection to physical points via electronic tracing.

The water can be separated into two systems- Domestic potable and fire services. Where conductive pipes are used in the system then these assets will be located to QL-B specification using EM methods.

Electrical – Revision of Ausgrid electrical plans. – information on street frontages to substation only.

Electrical lines area generally conductive and traced via means of EM induction. Physical features such as light poles have been connected to and traced via EM. Where electrical pits are present onsite then cables have been traced via EM induction clamping.

**Communication** – Revision of Telstra, NBN and Optus plans – Limited internal information. Communication network is generally investigated via accessing of service pits via EM induction clam method. Where services are nonconductive then conduits have been traced via inserting conductive traces rods into the conduits with subsequent EM trace.

Sewer - Sydney Water BYD plans – information on street frontages only, internal information is limited. Existing as built plans available that show the main network existing within the school grounds.

The sewer network is investigated at the pit interface where the depth, size direction and material of pipes are measured to quality level A specification. These measurements are review against the BYD and as-built information whereby connection between manholes points can be established.

Stormwater – No stormwater BYD were available. No as built available.

Stormwater pits were investigated at the pit interface where depth, size direction and pipe material were recorded to quality level A. Pits were joined in the network via sonic testing. Where this was not possible then a conductive trace rod and sonde was inserted and subsequently traced via EM.

Unknown Pipes – A variety of random scans are carried out of the duration of the works. This is achieved by using both EM and GRR to scan areas to identify anomalies that present in linear arrangements. Once anomalies are identified via these methods technicians attempt to traditional trace and identify source points. When these features cannot be identified then they are marked as unknow pipe on the plan.

Asset:	Description
	Water Meter Fire Hydrant Booster – Located at the Main Vehicle entry gate
	Sewer Rising Main/ Pump out – Located on the Northern Boundary off the Wool Rd
	LPG Storage Tank – Located adjacent to the staff carpark

# Key Utility Infrastructure Features:

Main Communications Pit entry point - Located on western CNR or The Wool Rd and School Entry
Irrigation Tank – Located on the Northern Boundary off the Wool Rd
Endeavour Energy Electrical substation/Transformer – Located adjacent to the staff carpark off the main building C



Pipe blockages/Pit Obstructions -

Where possible, Astrea endeavours to show a completed stormwater/sewer network.

There are some instances onsite where a pipe network could not be determined due to features blocked pipes, pits full of debris, buried pits or junction chambers or non-present junction chambers. See (image 2) below.



Image 2 – SW Pit 45, unable to visually inspect and measure pipes. Pit has substantial debris. Pit has been joined into the network to quality level C specification.

In these instances, technicians have made best effort to assume the line of these services and the network in which they discharge into. The quality level of pipes should be noted in these scenarios.

Astrea can make recommendations on alternative methods such as CCTV or jetting of blockages that may assist in confirming these networks. (UTO) unable to open – Where possible technicians open pits using best industry practice however in some instances there were pits that cannot be opened without specialised mechanical lifting or casing unnecessary damage to existing areas. (Image 3) below is an example pit that could not be opened during routine investigations.



Image 3 – SW32, Stormwater pit cover has no lifting points and cannot be manually lifted by a twoperson team.

Confined Space – Confined spaces have been investigated from the surface only via means of visual inspection, GPR tracing or clamping of services and tracing of conductive services. Confined space establishment is recommended where additional information of pits/chambers is required.



Image 4 – UP04 Large retention chamber cannot be safely investigated without confined space setup. Locked Pits – Some pits have been locked by service authorities – These may require service representatives to provide access/or attend site.



Image 5 – Sewer Rising Main pit locked – Shoalhaven water to provide access if internal information is required.

#### Asset Register – Trace Limitations

Pit Asset	Limitation	Comment	Recommendation
UP04	Safety – Confined Space Full of Debris	Large retention pit – unknow functionality – The pit is full of debris and needs a confined space setup to investigate further	Confined space setup and pit clean out, Potential robotic CCTV inspection
SEW02	Incomplete trace downstream outlet	A trace rod has been inserted into the downstream outlet; this has become stuck along the alignment – due depth of the pit	Robotic CCTV camera/trace
SW04	Incomplete trace to next downstream Pit/outfall	A trace rod has been inserted into the downstream outlet. This has become stuck along the alignment	Robotic CCTV camera/Trace
SW32	UTO - Unable to open pit	The pit Lid does not have any lifting points and is too heavy to manure otherwise	Install lifting points or mechanical lift

			11
SW45	FOD – Pit Full of Debris	The pit is Full of debris and conduits are unable to be visually inspected – pipe details have been assumed to QLC specification	Clean Pit and resurvey if required
SW40	FOD – Pit is full of Debris	The pit is full of debris and pipes are unable to be visually inspected, pipes have been joined into the network to quality level D	Clean pit/pipe
SW66	Pipe Blockage	A trace rod has been inserted into the pipe but has become stuck due to a blockage	Pipe cleaning/CCTV
Sewer Rising Main	Non-conductive services	Poly sewer service is a nonconductive and non- traceable via conventional EM There is no trace via GPR	NDD over suspected alignment if required.
Main Water Feed	Conductive Service	The pipe is made out of PVC material and is nonconductive, GPR has been utilised to trace it where possible however the trace became poor under reenforced concrete	NDD to confirm GPR alignment
Water Feed to Agricultural area	Non-conductive services	A poly water line is said to exist between main meterage point and agricultural yard – No GPR pickup online	NDD Known/Potential alignment
Sports Field Irrigation	Non-conductive services	Poly Water service is a nonconductive material and cannot be traced via conventional EM, GPR has been unsuccessful in tracing the network	NDD potential GPR targets in areas where information is required
Sewer Inspection Openings Various	Partial trace on pipe networks	Flexible trace rods have been inserted into inspection openings – in some instances these have become stuck in plumbing features e.g., "U" bends and corners etc.	CCTV Camera alignments where required
Sewer Connections – Demountable	Sewer discharge has been assumed class D	No inspection pits present	Require Licenced plumber to open sewer connections to insert rod and trace.

# 4 RECOMMENDATION AND CONCLUSION

In relation to the site detail and level survey .....

In relation to underground services we have made every attempt to find all information on public record.

Where possible Astrea has aimed to achieve Quality level B data. It is recommended that NDD be carried out over areas of concern so that the highest level of data (Quality level A) be achieved. Where services routes cannot be determined due to lack of traceable signal then it is recommended that Non-Destructive Digging be utilised to help define routes.

Where localised plumbing features are required to be traced it is recommended that push Camera CCTV be utilised to help identify alignments. Camera footage can help identify obstructions sometimes attributed to plumbing features (boundary traps U bends etc.) which could not otherwise be determined with traditional EM tracing.

Appendix A of this report contains all Cadastral search documents purchased and utilised as part of this report.

Appendix B contains all relevant documents ordered via the BYDA search.

Appendix C contains the sheeted detailed site survey.

Appendix D contains the underground service locators field report.

Appendix A. Cadastral Search Documents.



Report Generated 2:16:14 PM, 19 September, 2023 Copyright © Crown in right of New South Wales, 2017

This information is provided as a searching aid only.Whilst every endeavour is made to ensure that current map, plan and titling information is accurately reflected, the Registrar General cannot guarantee the information provided. For ALL ACTIVITY PRIOR TO SEPTEMBER 2002 you must refer to the RGs Charting and Reference Maps

Page 1 of 6

$\wedge$		Cadastral Records Enquiry Report : Lot 1 DP 809057			
	SW) REGISTRY	Locality : VINCENTIA		Parish : BHERWERRE	
$\searrow$	SERVICES	LGA : SHOALHAVEN		County : ST VINCENT	
		Status	Surv/Comp	Purnose	
DP287	'85	Olalas	ourwoomp	i uipose	
Lot(s):	1758				
	🖳 DP1247959	REGISTERED	COMPILATION	DEPARTMENTAL	-
DP270	528				
Lot(s):	1, 2, 3	HISTORICAL	SUR//EV	SUBDIVISION	
	DF 072032 DF1024478	HISTORICAL	SURVEY	SUBDIVISION	
	DP1069250	HISTORICAL	COMPILATION	SUBDIVISION	
DP866	983				
Lot(s):	1				
	MSW GAZ.	06-09-2	2019	Folio : 3549	
		NATIONAL PARK		1074	
DP877	ANT OF JERV	IS BAT FARR NATIONAL FAR	TRO AND WILD LIFE ACT I	1974	
Lot(s):	792				
- (-)	DP874040	HISTORICAL	SURVEY	RESUMPTION O	R ACQUISITION
DP101	5690				
Lot(s):	1, 2, 3, 4				
1 = 1(=);	UP724963	HISTORICAL	COMPILATION	DEPARIMENTAL	-
Lot(s):	4	HISTORICAL	SUR/EY		٦
	DP136334	HISTORICAL			5
DP102	24478	THOTOTOTA		DEFARTMENTA	-
Lot(s):	53, 54				
	🦳 DP872852	HISTORICAL	SURVEY	SUBDIVISION	
DP112	3782				
Lot(s):	128, 129				22
		HISTORICAL	SURVET	ROADS ACT, 198	13
	CLOSED ROAD LOTS 1-12 DP1	24-04-2 118806	2008	Folio : 2913	
Lot(s):	128, 129, 172, 173,	174			
1 = 1 (= ) .	UP1022286	HISTORICAL	SURVEY	SUBDIVISION	
LOI(S).	DP874040	HISTORICAL	SURVEY	RESUMPTION O	R ACQUISITION
DP114	1763	The renderate	OURVET		
Lot(s):	224				
	🖳 DP1193728	REGISTERED	SURVEY	EASEMENT	
Lot(s):	209, 210, 211, 215,	216, 217, 218, 222, 223, 224,	225, 226, 227, 228		
	UP874040	HISTORICAL	SURVEY	RESUMPTION O	R ACQUISITION
	UP1022286	HISTORICAL	SURVEY	SUBDIVISION	
	UP1118806	HISTORICAL	SURVEY	ROADS ACT, 199	03
	UP1123782	HISTORICAL	SURVEY	SUBDIVISION	
	DP1138189	HISTORICAL	SURVEY	SUBDIVISION	
Lot(o).	200 219	HISTORICAL	SURVET	SUBDIVISION	
Lot(S):	NSW GAZ.	24-04-2	2008	Folio : 2913	
	LOTS 1-12 DP1	118806			
DP116	9907				
Lot(s):	901 901 901 901	HISTORICAL	SUR/EV		
	DP1022286	HISTORICAL	SURVEY	SUBDIVISION	
	DP1118806	HISTORICAL	SURVEY	ROADS ACT 190	3
	DP1123782	HISTORICAL	SURVEY	SUBDIVISION	
	DP1138189	HISTORICAL	SURVEY	SUBDIVISION	
	DP1141762	HISTORICAL	SURVEY	SUBDIVISION	
	DP1141763	HISTORICAL	SURVEY	SUBDIVISION	
	DP1193728	REGISTERED	SURVEY	EASEMENT	

NS	LAND REGISTRY SERVICES	Cadastral Records Enquiry Report : Lot 1 DP 809057Locality : VINCENTIAParish : BHERWERRE		Ref : NOUSER	
	SERVICES	LGA : SHOALHAVEN		County : ST VINCENT	
		Status	Surv/Comp	Purpose	
DP1182	358				
Lot(s): 2			μιναν/Διί Δρι β	SUBDIVISION	
Lot(s)· 1	BI 1200347	TRE-ALLOCATED	UNAVAILADL	306610131010	
	DP874040	HISTORICAL	SURVEY	RESUMPTION	OR ACQUISITION
Į.	🚽 DP1123782	HISTORICAL	SURVEY	SUBDIVISION	
Į.	DP1215651	REGISTERED	COMPILATION	EASEMENT	
Į.	🚽 DP1215695	REGISTERED	SURVEY	EASEMENT	
	🚽 DP1269182	REGISTERED	SURVEY	RESUMPTION	OR ACQUISITION
Lot(s): 1	, 2				
	DP1022286	HISTORICAL	SURVEY	SUBDIVISION	1000
		HISTORICAL	SURVEY	RUADS ACT, 1	1993
2	CLOSED ROAD	24-0 <sup>.</sup> 118806	4-2008	F0110 : 2913	
DP1195	858				
Lot(s): 6	004				
		HISTORICAL	SURVEY	RESUMPTION	OR ACQUISITION
8			SURVET		1002
			SURVET		1995
	DP1138189	HISTORICAL	SURVEY	SUBDIVISION	
	DP1141762	HISTORICAL	SURVEY	SUBDIVISION	
	DP1141763	HISTORICAL	SURVEY	SUBDIVISION	
	DP1154415	HISTORICAL	SURVEY	SUBDIVISION	
, i	DP1154465	HISTORICAL	SURVEY	SUBDIVISION	
, i	 DP1170950	HISTORICAL	SURVEY	SUBDIVISION	
	DP1171256	HISTORICAL	SURVEY	SUBDIVISION	
Į.	DP1183960	HISTORICAL	SURVEY	SUBDIVISION	
	NSW GAZ. CLOSED ROAD LOTS 1-12 DP1	24-0 <sup>.</sup> 118806	4-2008	Folio : 2913	
DP1231 Lot(s): 1	236				
	🚽 DP874040	HISTORICAL	SURVEY	RESUMPTION	OR ACQUISITION
	👤 DP1286547	PRE-ALLOCATED	UNAVAILABLE	SUBDIVISION	
	NSW GAZ. CLOSED ROAD LOT 1 DP12312	16-0. 36	2-2018	Folio : 624	
DP1231 Lot(s): 1	370 422, 1423, 1424, 1 DP874040	425 HISTORICAI	SURVEY	RESUMPTION	
	DP1022286	HISTORICAL	SURVEY	SUBDIVISION	
	DP1118806	HISTORICAL	SURVEY	ROADS ACT.	1993
	DP1123782	HISTORICAL	SURVEY	SUBDIVISION	
Į.	DP1138189	HISTORICAL	SURVEY	SUBDIVISION	
	DP1141762	HISTORICAL	SURVEY	SUBDIVISION	
Į.	🚽 DP1141763	HISTORICAL	SURVEY	SUBDIVISION	
Į.	💐 DP1154415	HISTORICAL	SURVEY	SUBDIVISION	
Į.	🚽 DP1154465	HISTORICAL	SURVEY	SUBDIVISION	
Į.	DP1170950	HISTORICAL	SURVEY	SUBDIVISION	
Į.	DP1171256	HISTORICAL	SURVEY	SUBDIVISION	
Į.	DP1183960	HISTORICAL	SURVEY	SUBDIVISION	
	P1195858	HISTORICAL	COMPILATION	SUBDIVISION	
	NSW GAZ. CLOSED ROAD LOTS 1-12 DP1 <sup>1</sup>	24-0 118806	4-2008	Folio : 2913	

		<u>Cada</u>	astral Rec	ords Enqu	iiry Report : Lot 1 DP 8	<u>09057</u>	Ref : NOUSER
NSW	NSW REGISTRY Locality : VINCENTIA Parish : BHERWERRE		BHERWERRE				
	SERVICES	LGA :	SHOALHAVE	N	County	: ST VINCENT	
			0		0 10	5	
DD105711	10		Status		Surv/Comp	Purpose	
Lot(s): 160	D5, 1606, 1607, DP874040	1608, 160	09, 1610, 161 <i>1</i> HISTORICAL	, 1612, 1613,	1614, 1615, 1616, 1617, 1618 SURVEY	8, 1619, 1620, 1621, RESUMPTION O	1622, 1623, 1624, 162 R ACQUISITION
	DP1022286		HISTORICAL		SURVEY	SUBDIVISION	
	DP1118806		HISTORICAL		SURVEY	ROADS ACT 199	93
	DP1123782		HISTORICAL		SURVEY	SUBDIVISION	
	DP1138189		HISTORICAL		SURVEY	SUBDIVISION	
	DP11/1762		HISTORICAL		SURVEY	SUBDIVISION	
	DP1141763		HISTORICAL		SURVEY	SUBDIVISION	
	DP1154415		HISTORICAL		SURVEY	SUBDIVISION	
	DP1154465		HISTORICAL		SURVEY	SUBDIVISION	
	DP1170950		HISTORICAL		SURVEY	SUBDIVISION	
	DP1171256		HISTORICAL		SURVET	SUBDIVISION	
	DP1192060					SUBDIVISION	
	DF1105900					SUBDIVISION	
	DF1193030					SUBDIVISION	
Lot(c): 160	DF 1231370	1609 160	11310RICAL	1612 1612	1614 1615 1616 1617 1619		
LUI(S). 100	NSW GAZ	1000, 100	09, 1010, 101	24-04-2008		, Folio · 2913	
19	CLOSED ROA LOTS 1-12 DP	D 1118806		21012000	·	0110 1 2010	
DP128902	24						
Lot(s): 31,	32						
	DP28785		HISTORICAL		SURVEY	UNRESEARCHE	2
	DP1247959		HISTORICAL		COMPILATION	DEPARTMENTAL	-
	DP1280272		HISTORICAL		COMPILATION	CONSOLIDATION	N
DP129456	52						
Lot(s): 1, 2							
Pood	DF 002097		TISTORICAL		SORVET	RESUME HON O	K ACQUISITION
Polygon Ic 16779896	d(s): 161087560 2, 167798975,	), 1610879 16903915	563, 16432783 1, 169039434	39, 164328030	), 164328032, 164328036, 164	328061, 164328062	, 167788895,
<b>**</b>	NSW GAZ. CLOSED ROA LOTS 1-12 DP	D 1118806		24-04-2008	F	Folio : 2913	
SP103477	7						
	DP874040		HISTORICAL		SURVEY	RESUMPTION O	R ACQUISITION
	DP1022286		HISTORICAL		SURVEY	SUBDIVISION	
	DP1118806		HISTORICAL		SURVEY	ROADS ACT, 199	93
	DP1123782		HISTORICAL		SURVEY	SUBDIVISION	
	DP1138189		HISTORICAL		SURVEY	SUBDIVISION	
	DP1141762		HISTORICAL		SURVEY	SUBDIVISION	
	DP1141763		HISTORICAL		SURVEY	SUBDIVISION	
	DP1154415		HISTORICAL		SURVEY	SUBDIVISION	
	DP1154465		HISTORICAL		SURVEY	SUBDIVISION	
	DP1170950		HISTORICAL		SURVEY	SUBDIVISION	
	DP1171256		HISTORICAL		SURVEY	SUBDIVISION	
	DP1183960		HISTORICAL		SURVEY	SUBDIVISION	
	DP1195858		HISTORICAL		COMPILATION	SUBDIVISION	
	DP1231370		HISTORICAL		SURVEY	SUBDIVISION	
<b>**</b>	NSW GAZ. CLOSED ROA LOTS 1-12 DP	D 1118806		24-04-2008	F	Folio : 2913	
Road Polygon Ic	d(s): 105535040	), 107092:	364, 10709236	6			
	NSW GAZ RESERVED A PART OF JER	S NATION	NAL PARK NATIONAL PA	13-09-2019 NRK	F	Folio : 3763	

Cadastral Records Enquiry Report : Lot 1 DP 809057

LAND REGISTRY SERVICES

Locality : VINCENTIA LGA : SHOALHAVEN

County : ST VINCENT

Surv/Comp

Purpose

Parish : BHERWERRE

Status Polygon Id(s): 107201042, 107201044, 107201048, 107201050, 107201056, 107201059, 107201061, 107201062, 107202714 NSW GAZ. 22-08-2008 Folio : 7967

DEDICATED PUBLIC ROAD LOTS 62, 64, 68, 69 AND 70 DP874040



Locality : VINCENTIA

Parish : BHERWERRE

Plan
DP28785
DP46903
DP216858
DP270528
DP550361
DP575155
DP575156
DP575158
DP575159
DP575160
DP575161
DP702404
DP793394
DP809057
DP866983
DP875010
DP877477
DP1015690
DP1024478
DP1123782
DP1141763
DP1141763
DP1169907
DP1182358
DP1195858
DP1195858
DP1231236
DP1231370
DP1231370
DP1257110
DP1289024
DP1294562
SP103477

SERVICES	LGA : SHOALHAVEN	County : ST VINCENT
	Surv/Comp	Purpose
0 8 2 3 3 7 7 8 8 8 8 8 6 0 0 0	SURVEY SURVEY	Purpose UNRESEARCHED ROADS ACT, 1993 SUBDIVISION COMMUNITY PLAN SUBDIVISION SUBDIVISION SUBDIVISION SUBDIVISION SUBDIVISION SUBDIVISION SUBDIVISION SUBDIVISION SUBDIVISION RESUMPTION OR ACQUISITION RESUMPTION OR ACQUISITION CONSOLIDATION RESUMPTION OR ACQUISITION SUBDIVISION
	COMPILATION	STRATA PLAN



Information Provided Through Aussearch Ph. 02 9054 6867 Fax.

NEW SOUTH WALES LAND REGISTRY SERVICES - TITLE SEARCH \_\_\_\_\_

FOLIO: 1/550361

\_ \_ \_ \_ \_ \_

SEARCH DATE	TIME	EDITION NO	DATE
19/9/2023	2:17 PM	1	24/5/1994

#### LAND \_\_\_\_

LOT 1 IN DEPOSITED PLAN 550361 AT VINCENTIA LOCAL GOVERNMENT AREA SHOALHAVEN PARISH OF BHERWERRE COUNTY OF ST VINCENT TITLE DIAGRAM DP550361

FIRST SCHEDULE

\_\_\_\_\_

MINISTER FOR EDUCATION

(AP U286648)

SECOND SCHEDULE (2 NOTIFICATIONS)

\_\_\_\_\_

1 RESERVATIONS AND CONDITIONS IN THE CROWN GRANT(S)

2 LAND EXCLUDES MINERALS BY THE CROWN GRANT OF 137 ACRES 3 ROODS

#### NOTATIONS

#### \_\_\_\_\_

UNREGISTERED DEALINGS: NIL

\*\*\* END OF SEARCH \*\*\*

#### vincentia

#### PRINTED ON 19/9/2023

\* Any entries preceded by an asterisk do not appear on the current edition of the Certificate of Title. Warning: the information appearing under notations has not been formally recorded in the Register. InfoTrack an approved NSW Information Broker hereby certifies that the information contained in this document has been provided electronically by the Registrar General in accordance with Section 96B(2) of the Real Property Act 1900.



Information Provided Through Aussearch Ph. 02 9054 6867 Fax.

(PA62688)

NEW SOUTH WALES LAND REGISTRY SERVICES - TITLE SEARCH \_\_\_\_\_

FOLIO: 1/809057

\_\_\_\_

SEARCH DATE	TIME	EDITION NO	DATE
19/9/2023	2:17 PM	1	5/8/1991

#### LAND \_\_\_\_

LOT 1 IN DEPOSITED PLAN 809057 AT VINCENTIA LOCAL GOVERNMENT AREA SHOALHAVEN PARISH OF BHERWERRE COUNTY OF ST VINCENT TITLE DIAGRAM DP809057

FIRST SCHEDULE \_\_\_\_\_

MINISTER FOR SCHOOL EDUCATION AND YOUTH AFFAIRS

SECOND SCHEDULE (1 NOTIFICATION)

SERVICES

\_\_\_\_\_ 1 LAND EXCLUDES MINERALS -VIDE MEMORANDUM T447400

NOTATIONS

\_\_\_\_\_

UNREGISTERED DEALINGS: NIL

\*\*\* END OF SEARCH \*\*\*

#### vincentia

#### PRINTED ON 19/9/2023

\* Any entries preceded by an asterisk do not appear on the current edition of the Certificate of Title. Warning: the information appearing under notations has not been formally recorded in the Register. InfoTrack an approved NSW Information Broker hereby certifies that the information contained in this document has been provided electronically by the Registrar General in accordance with Section 96B(2) of the Real Property Act 1900.



Req:R404836 /Doc:DP 0862697 P /Rev:03-Oct-1996 /NSW LRS /Pgs:ALL /Prt:23-Oct-2023 15:12 /Seq:1 of 2 © Office of the Registrar-General /Src:InfoTrack /Ref:A4066





Reg:R231994 /Doc:DP 0550361 P /Rev:02-Sep-1992 /NSW LRS /Pgs:ALL /Prt:19-Sep-2023 15:15 /Seq:1 of 1 © Office of the Registrar-General /Src:InfoTrack /Ref:SINSW

![](_page_33_Figure_1.jpeg)

TABLE ADDED IN

This negative is a photograph made as a permanent record of a document in the custody of the Registrar General this day. 28th May, 1991

![](_page_34_Figure_1.jpeg)

S.B. 51232

L

Req:R231993 /Doc:DP 0809057 P /Rev:10-Nov-1992 /NSW LRS /Pgs:ALL /Prt:19-Sep-2023 15:15 /Seq:1 of 1 © Office of the Registrar-General /Src:InfoTrack /Ref:SINSW

Req:R231999 /Doc:DP 1024478 P /Rev:03-Apr-2001 /NSW LRS /Pgs:ALL /Prt:19-Sep-2023 15:16 /Seq:1 of 2
0 Office of the Registrar-General /Src:InfoTrack /Ref:SINSW

![](_page_35_Figure_1.jpeg)
Req:R231999 /Doc:DP 1024478 P /Rev:03-Apr-2001 /NSW LRS /Pgs:ALL /Prt:19-Sep-2023 15:16 /Seq:2 of 2 © Office of the Registrar-General /Src:InfoTrack /Ref:SINSW





Req:R231997 /Doc:DP 1182358 P /Rev:26-Mar-2013 /NSW LRS /Pgs:ALL /Prt:19-Sep-2023 15:16 /Seq:2 of 4

© Offi i c

PLAN FORM 6 WARNING: Creasing or fo	ePla
DEPOSITED PLAN A	DMINISTRATION SHEET Sheet 1 of 3 sheet(s
SIGNATURES, SEALS AND STATEMENTS of intention to dedicate public roads, public reserves and drainage reserves or create easements, restrictions on the use of land and positive covenants IT IS INTENDED TO DEDICATE THE LANDS MARKED ROAD WIDENING (R1) AND (R2) TO THE PUBLIC AS PUBLIC ROAD SUBJECT TO EASEMENT FOR SEWER MAIN (VIDE DP1141763) IN REGARD (R1) AND SUBJECT TO EASEMENT FOR TRANSMISSION LINE 18.29 WIDE (VIDE D 36543) IN REGARD (R2).	Office Use Onl DP1182358 Office Use Onl Registered: 26.3.2013 Title System: TORRENS DUBDIN (ICION)
	Purpose: SUBDIVISION PLAN OF SUBDIVISION OF LOT 177 DP1123782, LOT 801 DP1022286, LOT 2 AND 3 DP1118806 AND LOTS 72 AND 73 DP 874040
	SHOALHAVEN
	LGA: <del>SWALHAVEN</del> CITY
	Locality: VINCENTIA
	Parish: BHERWERRE
	County: ST VINCENT
	Survey Certificate
	I, DAMIAN JOSEPH MAGUIRE
	of LOCKLEY LAND TITLE SOLUTIONS PO BOX 400 GLADESVILLE 1675
If space is insufficient use PLAN FORM 6A annexure sheet Crown Lands NSW/Western Lands Office Approval Iin approving this plan certify (Authorised Officer) that all necessary approvals in regard to the allocation of the land	a surveyor registered under the Surveying and Spatial Information Ac 2002, certify that the survey represented in this plan is accurate, has been made in accordance with the Surveying and Spatial Information Regulation, 2006 and was completed on: 14/9/10 The survey relates to LOT 1
shown herein have been given	
Signature:	Signature
Subdivision Certificate	Datum Line: "X" "Y"
Assessment Act 1979 have been satisfied in relation to:	Iype: Urban/Kural
the proposed SUBDIVISION set out herein	
(insert 'subdivision' or 'new road') *Authorised Person/*General Managor/*Accredited Certifier Consent Authority: DEPT OF PLANNING Date of Endorsement: 0 FEBRUARY, 2012 Accreditation no: 25/005/11	DP1123782 DP1141763 DP1022286 15040-1603 DP1118806 DP874040 DP810820
	If space is insufficient use PLAN FORM 6A annexure sheet
* Strike through inapplicable parts.	Surveyor's Reference:33294-33569 DP

Req:R231997 /Doc:DP 1182358 P /Rev:26-Mar-2013 /NSW LRS /Pgs:ALL /Prt:19-Sep-2023 15:16 /Seq:3 of 4 © Office

: .

PLAN OF SUBDIVISION OF LOT 177 DP1123782, LOT 801 DP1022286, LOT 2 AND DP1118806 AND LOTS 72 AND 73 DP 874040	<sup>3</sup> DP1182358
	Office C Registered: 26.3.2013
Subdivision Certificate No.: 12437	Date of Endorsement: 8 FEBRUARY, 2
EXECUTED by STOCKLAND DEVELOPMENT PTY LIMITED ACN 000 064 835 in-accordance with Section 127 of the Corporations Act 	) ) ) )
Executed on behalf of Stock. Lond Develop ACN 00000488S by its attorney Matthew A under Power of Attorney Book 4537 No. G who states that he/she has received no notice of revocation of the Power of Attorney in the presence of:	neit Ply United lears \$1 Stratuc of Attorney Matthew Mears Name of Attorney C. Katase Signance of Withess

Req:R231997 /Doc:DP 1182358 P /Rev:26-Mar-2013 /NSW LRS /Pgs:ALL /Prt:19-Sep-2023 15:16 /Seq:4 of 4 uistrar-Ceneral /Sra:InfoTrack /Bef

		-				- ·		
	1							
1	orrice	OT	the Registr	ar-General	/SEC.In	TOLLACK	/Rel:SINSW	

ePlan WARNING: Creasing or folding will lead to rejection PLAN FORM 6A DEPOSITED PLAN ADMINISTRATION SHEET Sheet 3 of 3 sheet(s) Office Use Only **PLAN OF SUBDIVISION OF LOT 177** DP1123782, LOT 801 DP1022286, LOT 2 AND 3 DP1182358 DP1118806 AND LOTS 72 AND 73 DP 874040 Office Use Only 26.3.2013 **Registered**: 8 FEBRUARY, 2012 12437 Subdivision Certificate No.: Date of Endorsement: EXECUTED by VINCENTIA NOMINEES PTY LTD ACN 137 903 327 in accordance with Section 127 of the Corporations Act ¥ Signature of Director Signature of director/secretary Peter John Horton THOMAS WILLIAM POCKETT, х ÷ .....Director NAME (please print) NAME (please print) Surveyor's Reference: 33294-33569 DP

Req:R231998 /Doc:DP 1294562 P /Rev:16-Aug-2023 /NSW LRS /Prt:19-Sep-2023 15:16 /Seq:1 of 6 © Office of the Registrar-General /Src:InfoTrack /Ref:SINSW



PLAN FORM 2 (A2)

L

of Req:R231998 /Doc:DP 1294562 P /Rev:16-Aug-2023 /NSW LRS /Prt:19-Sep-2023 15:16 /Seq:2 of 6 © Office of the Registrar-General /Src:InfoTrack /Ref:SINSW



## Req:R231998 /Doc:DP 1294562 P /Rev:16-Aug-2023 /NSW LRS /Prt:19-Sep-2023 15:16 /Seq:3 of 6 © Office of the Registrar-General /Src:InfoTrack /Ref:SINSW



I

Req:R231998 /Doc:DP 1294562 P /Rev:16-Aug-2023 /NSW LRS /Prt:19-Sep-2  $\hat{A} \odot$  Office of the Registrar-General /Src:InfoTrack /Ref:SINSW

PLAN FORM 6 (2019) DEPOSITED PLAN AD	MINISTRATION SHEET Sheet 1 of 3 sheet(s)
Office Use Only Registered: 16/08/2023	Office Use Only
Title System: TORRENS	
PLAN OF SUBDIVISION OF LOT 51 IN DP 862697	LGA: SHOALHAVEN Locality: VINCENTIA Parish: BHERWERRE County: ST VINCENT
<ul> <li>Survey Certificate</li> <li>I, TERRY EDWARD BARTLETT</li> <li>of Stantec Australia Pty Ltd.</li> <li>a surveyor registered under the Surveying and Spatial Information Act 2002, certify that:</li> <li>*(a) The land shown in the plan was surveyed in accordance with the Surveying and Spatial Information Regulation 2017, is accurate and the survey was completed on 18<sup>th</sup> November 2022, or</li> <li>*(b) The part of the land shown in the plan ("being Lots 1 &amp; 2) was surveyed in accordance with the Surveying and Spatial Information Regulation 2017, the part surveyed is accurate and the survey was completed on 26th November 2022. The part not surveyed being part of Lot 2 was compiled in accordance with that Regulation.</li> <li>*(c) The land shown in this plan was compiled in accordance with the Surveying and Spatial Information Regulation 2017.</li> <li>Datum Line: "A" (SSM 76129) - "B" (SSM 19548)</li> <li>Type: *Urban/*Rural</li> <li>The terrain is *Level-Undulating / *Steep-Mountainous.</li> </ul> Signature: Dated: 18/11/2022 Surveyor Identification No: 438 Surveyor registered under the Surveying and Spatial Information Act 2002 *Strike out inappropriate words. **Specify the land actually surveyed or specify any land shown in the plan that is pain was	Crown Lands NSW/Western Lands Office Approval  (Authorised Officer) in approving this plan certify that all necessary approvals in regard to the allocation of the land shown herein have been given.  Signature: Date:
Plans used in the preparation of survey/compilation.         DP       647048       DP       1118806         DP       862697       DP       1182358         DP       810820       DP       1183960         DP       874040       DP       1195858         DP       877477       DP       1231236         DP       1022286       R       15040-1603         UNREGISTERED PLAN BY MICHAEL POIDEVIN (SURVEYOR'S REF - 62-2016)       Surveyor's Reference: 30/100879       DP-01	Statements of intention to dedicate public roads create public reserves and drainage reserves, acquire/resume land.

PLAN FO	RM 6A (2019)		MINI		
			INITIAL		Sneet 2 of 3 sheet(s)
Registerer	<b>.</b> (16/08/	2023 Office Use Only			Office Use Only
PLAN OF OF LOT 5	SUBDIVISION 1 IN DP 862697	7		DP129	94562
Subdivision C Date of Endo	Certificate number: rsement:22 DEC	SC22/1149 EMBER 2022	This s • / • S • / • / 1	sheet is for the provision of the for A schedule of lots and addresses Statements of intention to create accordance with section 88B <i>Cor</i> Signatures and seals- see 195D Any information which cannot fit i 1 of the administration sheets.	ollowing information as required: s - See 60(c) SSI Regulation 2017 and release affecting interests in <i>nveyancing Act</i> 1919 <i>Conveyancing Act</i> 1919 in the appropriate panel of sheet
Lat	Church Normhan	0(( ))		<b>2</b> ( <b>7</b>	······································
LOT				Street Type	
2	N/A	The Wool		Road	Vincentia

If space is insufficient use additional annexure sheet

Surveyor's Reference: 304100879 DP-01

Req:R231998 /Doc:DP 1294562 P /Rev:16-Aug-2023 /NSW LRS /Prt:19-Sep-2 © Office of the Registrar-General /Src:InfoTrack /Ref:SINSW

h Na na mana any amin'ny tanàna mandritra dia kaominina dia kaominina dia kaominina mandritry dia kaominina dia	
PLAN FORM 6A (2019) DEPOSITED PLAN AI	OMINISTRATION SHEET         Sheet 3 of 3 sheet(s)
Registered: 16/08/2023 Office Use Only	
PLAN OF SUBDIVISION OF LOT 51 IN DP 862697	DP1294562
Subdivision Certificate number: SC22/1149 Date of Endorsement:22.DECEMBER.2022	<ul> <li>This sheet is for the provision of the following information as required:</li> <li>A schedule of lots and addresses - See 60(c) <i>SSI Regulation 2017</i></li> <li>Statements of intention to create and release affecting interests in accordance with section 88B <i>Conveyancing Act 1919</i></li> <li>Signatures and seals- see 195D <i>Conveyancing Act 1919</i></li> <li>Any information which cannot fit in the appropriate panel of sheet 1 of the administration sheets.</li> </ul>
EXECUTED on behalf of SHOALHAVEN CITY COUN	NCIL by its authorised delegate pursuant
to s.377 of Local Government Act 1993 No 30	$\frac{57EM+N}{Name of Delegate} 0.00000000000000000000000000000000000$
I certify that I am an eligible witness and that the dele	gate signed in my presence
Signature of Witness	
CARCOLYN Name of Witness	
<u>BRIDGE RD. NOWRA</u> 2541 Address of Witness	
If space is insufficient us	e additional annexure sheet
Surveyor's Reference: 304100879 DP-01	



## SCIMS SURVEY MARK REPORT AS AT: 22-SEP-2023

Your Reference: vincentia					ch Nu	ımber:	1102354	
MARK NAME STATUS	COORDINA	TES AND HEIGHTS	CLASS	PU	LU	SOURCE	CSF CONVERGENCE AUSGEOID2020	
PM 66500		Horizontal coord	dinates ar	e adjusted	(or initial	ised) in GD/	42020	
	MGA2020	287056.963 6116022.339	56	В	0.03	0.04	301189	1.000153
	GDA2020	-35° 04' 33.97479" 150°	39' 52.1	11638"				-1° 20' 33.53"
	GDA2020	Ellipsoidal Height	38.	U			300780	
	AHD71	Normal-Orthometric	19.367	В			210375	18.648
PM 66501		Horizontal coord	dinates ar	e adjusted	(or initial	ised) in GD/	42020	
	MGA2020	287148.053 6116179.025	56	В	0.03	0.04	301189	1.000153
	GDA2020	-35° 04' 28.96186" 150°	39' 55.8	35517"				-1° 20' 31.21"
	GDA2020	Ellipsoidal Height	36.	U			300780	
	AHD71	Normal-Orthometric	17.600	В			210375	18.652



IMS M	Mark Status* F Found Intact N Not Found							
SS	РМ	TS	CR	ММ	СР	GB		<ul><li>D Destroyed</li><li>S Subsidence Area</li></ul>
۲			▼	+	0	*	Established GDA2020 + Accurate AHD71	U Uncertain
۲			V	+	0	*	Established GDA2020 Only	N Restlicted Acce
۲				+	0	*	Accurate AHD71 Only	
•			V	+	0	*	Accurate AHD71 + Approx. GDA2020	
			V	+	0	*	Approx. GDA2020 Only	
۲			V	+	0	*	Unknown	* Where available, the Mark Status is appended to the
stablished GDA coordinates are assigned accuracy class 3A, 2A, A, B, C or D ccurate AHD heights are assigned accuracy class L2A, LA, LB, LC, LD, 2A, A or B								Mark Number in the map



Note: SCIMS publishes coordinates, heights, Uncertainty and Class for NSW State control survey marks to an appropriate precision based on survey observations currently on public record. Positional Uncertainty and Local Uncertainty are only displayed where computed through a least-squares network adjustment. Refer to Surveyors-General's Directions: http://spatialservices.finance.nsw.gov.au/surveying/publications/surveyor\_generals\_directions

Disclaimer: This report has been generated by various sources and is provided for information purposes only. Spatial Services, a division of the NSW Department of Customer Service, does not warrant or represent that the information is free from errors or omission, or that it is exhaustive. Spatial Services accepts no liability for loss, damage, or costs that may incur relating to any use or reliance upon the information in this report. Spatial Services gives no warranty in relation to the information, especially material supplied by third parties.



SURVEY MARK							
Mark	Name		Ali	as			
PM 66500							
Status	Date 0	Comments					
Location	Monument		D	ate Placed	Placed By	,	
GROUND LEVEL	UNKNOWN				,		
MGA2020/GDA2020		<i>.</i>		/ · · · · · · · · · · · · · · · · · · ·	0.0.0000		
	Horizonta	coordinates a	are adjusted	(or initialised) i	n GDA2020		
MGA2020 Easting	MGA2020 Northing	Zone	GDA2020	Latitude		GDA2020 Lor	ngitude
287056.963	6116022.339	56	-35° 04' 33	.97479"		150° 39' 52.116	38"
Class	Positional Uncertaint	у	Local Unc	ertainty		GDA2020 Upo	dated
В	0.03		0.04			9-MAY-2023	
Source	Туре	Method	<u>.</u> т	Date issued	Issued	Ву	
301189 Decision Defense	ADJUSTMENT	DYNADJUS	51	1-MAY-2023	JOEL H	AASDYK	
Previous Reference		Location					
n/a		n/a					n/a
Comments							
GDA2020 STATE ADJU	ISTMENT MAY 2023						
MGA2020 Combined	Scale Factor		MG	A2020 Conv	ergence		
1.000153			-1°	20' 33.53"			
AusGeoid2020(NI)							
18.648							
GDA2020 Ellipsoidal	Height						
Height	licight						
38							
Class	Positional Uncertainty		Local Un	rertainty	Ellipsoidal	Height Lindate	d
	r ositional oncertainty		Local One	Jontainty	15-NOV-20	21	
Source	Tupo	Mathad		Data issued	locued		
Source							
300780	COMPUTATION	MANUAL		15-NOV-202*	I JONAT	HON SMITH	
Previous Reference		Location					File Number
n/a		n/a					n/a
Comments							
GDA2020 ELLIPSOIDA	L HEIGHTS DERIVED U	SING AUSGE	OID2020 FF	ROM AHD71 - (	GNSS AND (	OTHER SOURC	ES
AHD71							
Height							
19.367							
Class	Positional Uncertainty		Local Und	certainty	AHD Upda	ated	
В					20-DEC-19	95	
Source	Туре	Method		Date issued	Issued	Ву	
210375	HEIGHTING	LEVADJ		20-DEC-1995	5 n/a		
Previous Reference		Location					File Number
95380		n/a					n/a
Comments							
VINCENTIA TAFE PWD	)						







SURVEY MARK							
Mark	Name		Ali	as			
PM 66501							
Status	Date (	Comments					
Location	Monument		D	ate Placed	Placed By	,	
GROUND LEVEL	UNKNOWN						
MGA2020/GDA2020	Horizonta	Loordinator	are adjusted	(or initialized) i	n CDA2020		
MCA2020 Fasting		Zono			II GDA2020		aituda
MGA2020 Easting	MGA2020 Northing	Zone	GDA2020			GDA2020 LOF	
287148.053	6116179.025	56	-35° 04' 28.	.96186"		150° 39° 55.855	
		.y		enanty		GDA2020 Opt	Jaleu
D		Mothod	0.04	Data issued	locuod	9-MA 1-2023	
301180			э <b>т</b>				
Brovious Poference	ADJUSTMENT	Location		1-IVIA 1-2023	JOEL H	AASDIK	File Number
Comments		n/a					Π/α
Comments							
GDA2020 STATE ADJU	ISTMENT MAY 2023						
MGA2020 Combined	Scale Factor		MG	A2020 Conv	ergence		
1.000153			-1°	20' 31.21"			
AusGeoid2020(N)							
18.652							
GDA2020 Ellipsoidal	Height						
Height							
36.							
Class	Positional Uncertainty	,	Local Und	certaintv	Ellipsoidal	Height Update	d
U	,			, <b>,</b>	15-NOV-20	21	-
Source	Type	Method		Date issued	Issued	By	
300780	COMPLITATION	MANUAI		15-NOV-2021		HON SMITH	
Previous Reference				10 110 1 202			File Number
li/a		n/a					11/a
							E 9
GDA2020 ELLIPSOIDA					GINSS AND		L9 
AHD71							
Height							
17.600							
Class	Positional Uncertainty	,	Local Und	certainty	AHD Upda	ated	
В					20-DEC-19	95	
Source	Туре	Method		Date issued	Issued	Ву	
210375	HEIGHTING	LEVADJ		20-DEC-1995	5 n/a		
Previous Reference		Location					File Number
95380		n/a					n/a
Comments							
VINCENTIA TAFE PWD	)						









## SCIMS SURVEY MARK REPORT AS AT: 22-SEP-2023

Your Reference: v2					ch Nu	imber:	1102358	
MARK NAME STATUS	COORDINA	TES AND HEIGHTS		CLASS	PU	LU	SOURCE	CSF CONVERGENCE AUSGEOID2020
SS 76129		Horizontal coord	dinates ar	e adjusted	(or initial	ised) in GD	A2020	
	MGA2020	286443.819 6115751.694	56	В	0.02	0.04	301189	1.000156
	GDA2020	-35° 04' 42.28639" 150°	39' 27.6	67383"				-1° 20' 47.87"
	GDA2020	Ellipsoidal Height	38.46	D	0.03	0.04	301189	
	AHD71	Normal-Orthometric	19.833	В			236763	18.658



SCIMS M	Mark Status* F Found Intact N Not Found							
SS	РМ	тѕ	CR	ММ	СР	GB		D Destroyed
<ul> <li>•</li> <li>•</li> <li>•</li> <li>•</li> <li>•</li> <li>•</li> </ul>			V V V	••••		* * *	Established GDA2020 + Accurate AHD71 Established GDA2020 Only Accurate AHD71 Only Accurate AHD71 + Approx. GDA2020 Approx. GDA2020 Only	U Uncertain R Restricted Access
<ul> <li>Establishe</li> <li>Accurate</li> </ul>	ed GDA co AHD heigh	oordinates	are assign	ned accura	acy class : s L2A, LA	A, 2A, A, , LB, LC,	Unknown B, C or D LD, 2A, A or B	* Where available, the Mark Status is appended to the Mark Number in the map

Note: SCIMS publishes coordinates, heights, Uncertainty and Class for NSW State control survey marks to an appropriate precision based on survey observations currently on public record. Positional Uncertainty and Local Uncertainty are only displayed where computed through a least-squares network adjustment. Refer to Surveyors-General's Directions: http://spatialservices.finance.nsw.gov.au/surveying/publications/surveyor\_generals\_directions

Disclaimer: This report has been generated by various sources and is provided for information purposes only. Spatial Services, a division of the NSW Department of Customer Service, does not warrant or represent that the information is free from errors or omission, or that it is exhaustive. Spatial Services accepts no liability for loss, damage, or costs that may incur relating to any use or reliance upon the information in this report. Spatial Services gives no warranty in relation to the information, especially material supplied by third parties.



SURVEY MARK							
Mark	Name Alias						
SS 76129							
Status	Date (	Comments					
Location	Monument		D	ate Placed	Placed By		
GROUND LEVEL	UNKNOWN						
MGA2020/GDA2020	Horizonta	L coordinatos a	vro adjusted	(or initialized) i	n CDA2020		
MCA2020 Fasting					II GDA2020		aitudo
MGA2020 Easting	MGA2020 Northing	Zone	GDA2020			GDA2020 LON	
200443.019 Class	Desitional Uncortaint	00		20039		150° 39' 27.67383"	
B		у		enanny		GDA2020 Opu	aleu
Source		Method	0.04	Date issued	lssued	By	
301189	ADJUSTMENT	DYNADJUS	т	1-MAY-2023	JOEL H	AASDYK	
Previous Reference		Location	· •	1 10011 2020	0011		File Number
n/a		n/a					n/a
Comments							
GDA2020 STATE AD II	ISTMENT MAY 2023						
MGA2020 Combined	Scale Factor		MG	A2020 Conv	ergence		
1.000156			-1°	-1° 20' 47.87"			
AusGeoid2020(N)							
18.658							
GDA2020 Ellipsoidal	Height						
Height							
38.46							
Class	Positional Uncertainty		Local Und	certainty	Ellipsoidal	Height Update	d
D	0.03		0.04		9-MAY-202	3	
Source	Туре	Method		Date issued	Issued	Ву	
301189	ADJUSTMENT	DYNADJUS	T	1-MAY-2023	JOEL H	AASDYK	
Previous Reference		Location					File Number
n/a		n/a					n/a
Comments							
GDA2020 STATE ADJU	ISTMENT MAY 2023						
AHD71							
Height							
19.833							
Class	Positional Uncertainty		Local Und	certainty	AHD Upda	ited	
В					19-JUN-201	19	
Source	Туре	Method		Date issued	Issued	Ву	
236763	ADJUSTMENT	GEOLAB		27-JAN-2016	DENNIS	S SLUYS	
Previous Reference		Location					File Number
n/a		SHOALHAVE	N - (LGA)				n/a
Comments							
RE-ADJUSTEMENT OF	B2 GNSS NETWORK I	N SHOALHAV	'EN AREA S	TAGE 2			



Č				
© LAND NSW Di Other than or fair deal be reprodu price with	INFORMATION CENTR EPARTMENT OF LANDS for the purpose of rese ing no part of this data ced by any means with	E LOC. arch may hout		SSM 76129 BRASS PLAQUE Description IN _ ROUNDABOUT
Parish Munic	BHERK ipality or Sh	IERRECou	NTY St. VINCENT Town/Suburb	Locality VINCENTIA HUSKISSON 9027-4-N
	1	Reserve	KOAD ROAD	Reserve
_	JERVIS	BAM	2920 0:3 0:3 0:3 0 1:3.9 ELP 2.0 LOAD	JERVIS BAY ROAD
14	TO PRINC	ES HU	ROAD Keek	Reserve
SURVEY PR MARK HEIGHT DETE	ACTICE REG	ULATION 1990 SOURCE DATE	Measurements are in metres	I certify that the Mark or Marks have been placed and numbered as detailed hereon.
(specif	y) DOPTED MAR	TRIG. HEIGHTING KS	Replaces PM Organiza Ref	Mark placed 23/8 /19 94 REPLACEMENT SKETCM ation placing Marks



Appendix B. BYDA Search Documents.



# Job No 34866513

Caller Details					
Contact:	Astrea Locator	Caller Id:	3005839	Phone:	0476 003 705
Company:	Astrea				
Address:	32 Delhi Rd Macquarie Park NSW 2113	Email:	dbyd@astrea.com.a	au	
Dig Site and Enquiry Details					

<u>WARNING</u>: The map below only displays the location of the proposed dig site and does not display any asset owners' pipe or cables. The area highlighted has been used only to identify the participating asset owners, who will send information to you directly.



pating asset owners, who will ser	id information to you dire	nformation to you directly.			
User Reference:	Vincentia High Scho	Vincentia High School			
Working on Behalf of:	Private				
Enquiry Date:	Start Date:	End Date:			
18/08/2023	21/08/2023	21/09/2023			
Address:					
142 The Wool Road Vincentia NSW 2540					
Job Purpose:	Onsite Act	tivities:			
Excavation	Manual Ex Non-Destri	cavation, Mechanical Excavation, uctive Digging			
Location of Workplace:	Location i	n Road:			
Both	Footpath,	Nature Strip, Road			
<ul> <li>Check that the location of th</li> <li>Should the scope of works cl enquiry.</li> <li>Do NOT dig without plans. So the plans or how to proceed</li> </ul>	e dig site is correct. If not y nange, or plan validity dat afe excavation is your resp safely, please contact the	you must submit a new enquiry. es expire, you must submit a new ponsibility. If you do not understanc relevant asset owners			

Notes/Description of Works:

Not supplied

### Your Responsibilities and Duty of Care

- The lodgement of an enquiry does not authorise the project to commence. You must obtain all necessary information from any and all likely impacted asset owners prior to excavation.
- If plans are not received within 2 working days, contact the asset owners directly & quote their Sequence No.
- ALWAYS perform an onsite inspection for the presence of assets. Should you require an onsite location, contact the asset owners directly. Please remember, plans do not detail the exact location of assets.
- Pothole to establish the exact location of all underground assets using a hand shovel, before using heavy machinery.
- Ensure you adhere to any State legislative requirements regarding Duty of Care and safe digging requirements.
- If you damage an underground asset you MUST advise the asset owner immediately.
- By using this service, you agree to Privacy Policy and the terms and disclaimers set out at www.byda.com.au
- For more information on safe excavation practices, visit www.byda.com.au

### **Asset Owner Details**

The assets owners listed below have been requested to contact you with information about their asset locations within 2 working days.

Additional time should be allowed for information issued by post. It is <u>your responsibility</u> to identify the presence of any underground assets in and around your proposed dig site. Please be aware, that not all asset owners are registered with the Before You Dig service, so it is <u>your responsibility</u> to identify and contact any asset owners not listed here directly.

\*\* Asset owners highlighted by asterisks \*\* require that you visit their offices to collect plans.

# Asset owners highlighted with a hash # require that you call them to discuss your enquiry or to obtain plans.

Seq. No.	Authority Name	Phone	Status
228546382	Endeavour Energy	(02) 9853 4161	NOTIFIED
228546381	NBN Co NswAct	1800 687 626	NOTIFIED
228546380	Shoalhaven Water	(02) 4429 3214	NOTIFIED
228546383	Telstra NSW South	1800 653 935	NOTIFIED

END OF UTILITIES LIST

### Lodge Your Free Enquiry Online - 24 Hours a Day, Seven Days a Week



Issue Date: 18/08/2023, BYDA Sequence No: 228546382

UREMENTS	DRAWING SHOULD BE READ IN ACCORDANCE			
D UNDER TI DEPOT AS F	NS GENERAL TERMS & CONDITIONS DOCUMENT. HIS PROJECT SHOULD BE RETURNED REQUIRED			
RUPTION AD BE CON	TO ANY CUSTOMER'S SUPPLY MUST BE AVOIDED. ISIDERED;			
MANAGE AN	IY NECESSARY INTERRUPTION TO SUPPLY, , OBTAINING INTEGRAL ENERGY APPROVAL			
TS:				
ASSEMBLY CURRENT BTAIN THE I OUNTED AC	WITH A NEW LV 1250A LY THE LV FUSE ASSEMBLY NEW 1250A LV CIRCUIT CCESS.			
ENTIRE EAS	SEMENT AREA			
ere: Xeived With Ted For Mic Ied The Des Igner	HIN SIX (6)MONTHS OF THIS CERTIFICATION XRE THAN SIX (6) MONTHS SIGN MUST BE RESUBMITTED FOR			
DEMNIT NERGY'S R ON THE IN NET SITE. T LIMITED THONS ENT STAND RUCTION	Y ELEVANT STANDARDS ITEGRAL ENERGY TO; IARD			
UCTION DCTION				
INSTRUCTION	ON PRIES WITH C(b) -1 PRIES D DISTRIBUTION			
REFIES INTE	OTHER RELEVANT			
PLIANCE OF THE DESIGN WITH THE ABOVE				
2009				
ORIKS	CUSTOMER CUSTOMER FUNDED Includes but not limited to;	ifications.dgn		
pection &	- Providing sile access CO-ORDINATION SUPPLY REQUIRED DATE	el 3/Vincentio HS - Level 3 Mad		
· S	N/A MATERIAL RETURNS TO NEAREST INTEGRAL ENERGY	asktopvieve		
3	1 x 400A LV Ase strip, assembly & support frame	gs \ Alzaalmm \ D		
		nd Saltin		
SCHOO	L SITE	tivDocumente o		
DET- ntia	Gene Ransom 02 93728568	38136 AM C		
E	ł	07/2009 - Bi		
IGH S( 80 UB 50	HOOL       INTEGRAL         994       A1         310691       B         SHEET MOLI OF LSHEETS	AzooimM BNODES 14/0		
	·			
	WAE-0910724	r.		





### WARNING

All electrical apparatus shall be regarded as live until proved de-energised. Contact with live electrical apparatus will cause severe injury or death.

Underground assets may be congested at the approach to bridges and other structures. Typical asset depths and alignment may vary substantially, rising and falling sharply and at much shallower depths than elsewhere as they are

channelled into shared allocated spaces on bridges and other structures.

Additional precautions and underground asset location methods will be required in proximity to bridges and other structures.

In accordance with the *Electricity Supply Act* 1995, you are obliged to report any damage to Endeavour Energy Assets immediately by calling **131 003**.

The customer must obtain a new set of plans from Endeavour Energy if work has not been started or completed within twenty **(20)** working days of the original plan issue date.

The customer must contact Endeavour Energy if any of the plans provided have blank pages, as some underground asset information may be incomplete.

Endeavour Energy underground earth grids may exist and their location **may not** be shown on plans. Persons excavating are expected to exercise all due care, especially in the vicinity of padmount substations, pole mounted substations, pole mounted switches, transmission poles and towers.

Endeavour Energy plans **do not** show any underground customer service mains or information relating to service mains within private property.

Asbestos or asbestos-containing material may be present on or near Endeavour Energy's underground assets.

Organo-Chloride Pesticides (OCP) may be present in some sub-transmission trenches.

All plans must be made available at the worksite where excavation is to be undertaken in either printed or electronic format. If the plans are in an electronic format, they must be in a format visible on a screen size 10 inches or greater. Plans must be reviewed and understood by the crew on site prior to commencing excavation.

Non-destructive water excavation must be operated at or below 2000PSI. Any operation exceeding 2000PSI must be classed and treated as a destructive excavation practice

### **INFORMATION PROVIDED BY ENDEAVOUR ENERGY**

Any plans provided pursuant to this service are intended to show the approximate location of underground assets relative to road boundaries, property fences and other structures at the time of installation.

Depth of underground assets may vary significantly from information provided on plans as a result of changes to road, footpath or surface levels subsequent to installation.

Such plans have been prepared solely for use by Endeavour Energy staff for design, construction and maintenance purposes.

All enquiry details and results are kept in a register.

### DISCLAIMER

Whilst Endeavour Energy has taken all reasonable steps to ensure that the information contained in the plans is as accurate as possible it will accept no liability for inaccuracies in the information shown on such plans.



Cadastre: © Land and Property Information 2015, 2016

















### WARNING

All electrical apparatus shall be regarded as live until proved de-energised. Contact with live electrical apparatus will cause severe injury or death.

Underground assets may be congested at the approach to bridges and other structures. Typical asset depths and alignment may vary substantially, rising and falling sharply and at much shallower depths than elsewhere as they are

channelled into shared allocated spaces on bridges and other structures.

Additional precautions and underground asset location methods will be required in proximity to bridges and other structures.

In accordance with the *Electricity Supply Act* 1995, you are obliged to report any damage to Endeavour Energy Assets immediately by calling **131 003**.

The customer must obtain a new set of plans from Endeavour Energy if work has not been started or completed within twenty **(20)** working days of the original plan issue date.

The customer must contact Endeavour Energy if any of the plans provided have blank pages, as some underground asset information may be incomplete.

Endeavour Energy underground earth grids may exist and their location **may not** be shown on plans. Persons excavating are expected to exercise all due care, especially in the vicinity of padmount substations, pole mounted substations, pole mounted switches, transmission poles and towers.

Endeavour Energy plans **do not** show any underground customer service mains or information relating to service mains within private property.

Asbestos or asbestos-containing material may be present on or near Endeavour Energy's underground assets.

Organo-Chloride Pesticides (OCP) may be present in some sub-transmission trenches.

All plans must be made available at the worksite where excavation is to be undertaken in either printed or electronic format. If the plans are in an electronic format, they must be in a format visible on a screen size 10 inches or greater. Plans must be reviewed and understood by the crew on site prior to commencing excavation.

Non-destructive water excavation must be operated at or below 2000PSI. Any operation exceeding 2000PSI must be classed and treated as a destructive excavation practice

### **INFORMATION PROVIDED BY ENDEAVOUR ENERGY**

Any plans provided pursuant to this service are intended to show the approximate location of underground assets relative to road boundaries, property fences and other structures at the time of installation.

Depth of underground assets may vary significantly from information provided on plans as a result of changes to road, footpath or surface levels subsequent to installation.

Such plans have been prepared solely for use by Endeavour Energy staff for design, construction and maintenance purposes.

All enquiry details and results are kept in a register.

### DISCLAIMER

Whilst Endeavour Energy has taken all reasonable steps to ensure that the information contained in the plans is as accurate as possible it will accept no liability for inaccuracies in the information shown on such plans.



Cadastre: © Land and Property Information 2015, 2016

То:	Astrea Locator
Phone:	Not Supplied
Fax:	Not Supplied
Email:	Astrea.Locator.3005839@mail.au.pac.pcges.com.au

Dial before you dig Job #:	34866513	
Sequence #	228546381	
Issue Date:	18/08/2023	
Location:	142 The Wool Road, Vincentia, NSW, 2540	

# **Indicative Plans**



34	Parcel and the location		
3	Pit with size "5"		
25	Power Pit with size "2E". Valid PIT Size: e.g. 2E, 5E, 6E, 8E, 9E, E, null.		
	Manhole		
$\otimes$	Pillar		
2 PO-T-25.0m P40-20.0m 9	Cable count of trench is 2. One "Other size" PVC conduit (PO) owned by Telstra (-T-), between pits of sizes, "5" and "9" are 25.0m apart. One 40mm PVC conduit (P40) owned by NBN, between pits of sizes, "5" and "9" are 20.0m apart.		
-0 10.0m	2 Direct buried cables between pits of sizes ,"5" and "9" are 10.0m apart.		
-0	Trench containing any INSERVICE/CONSTRUCTED (Copper/RF/Fibre) cables.		
-0	Trench containing only DESIGNED/PLANNED (Copper/RF/Fibre/Power) cables.		
-0	Trench containing any INSERVICE/CONSTRUCTED (Power) cables.		
BROADWAY ST	Road and the street name "Broadway ST"		
Scale	0 20 40 60 Meters 1:2000 1 cm equals 20 m		













# **Emergency Contacts**

You must immediately report any damage to the **nbn**<sup>™</sup> network that you are/become aware of. Notification may be by telephone - 1800 626 329.










T	Report Damage: https://service.telstra.com.au/customer/general/forms/report-damage-to-telstra-equipment Ph - 13 22 03	Sequence Number: 228546383
	Email - Telstra.Plans@team.telstra.com Planned Services - ph 1800 653 935 (AEST bus hrs only) General Enquiries	CAUTION: Fibre optic and/ or major network present
	TELSTRA LIMITED A.C.N. 086 174 781	approximate and the services should you require
	Generated On 18/08/2023 14:40:59	any assistance.

The above plan must be viewed in conjunction with the Mains Cable Plan on the following page

#### WARNING

Telstra plans and location information conform to Quality Level "D" of the Australian Standard AS 5488-Classification of Subsurface Utility Information.

As such, Telstra supplied location information is indicative only. Spatial accuracy is not applicable to Quality Level D.

Refer to AS 5488 for further details. The exact position of Telstra assets can only be validated by physically exposing it.

Telstra does not warrant or hold out that its plans are accurate and accepts no responsibility for any inaccuracy.

Further on site investigation is required to validate the exact location of Telstra plant prior to commencing construction work.

A Certified Locating Organisation is an essential part of the process to validate the exact location of Telstra assets and to ensure the asset is protected during construction works.

See the Steps- Telstra Duty of Care that was provided in the email response.



-	Report Damage: https://service.telstra.com.au/customer/general/forms/report-damage-to-telstra-equipment Ph - 13 22 03	Sequence Number: 228546383	
	Email - Telstra.Plans@team.telstra.com Planned Services - ph 1800 653 935 (AEST bus hrs only) General Enquiries	CAUTION: Fibre optic and/ or major network present	
	TELSTRA LIMITED A.C.N. 086 174 781	in plot area. Flease read the Duty of Care and	
	Generated On 18/08/2023 14:41:00	any assistance.	

#### WARNING

Telstra plans and location information conform to Quality Level "D" of the Australian Standard AS 5488-Classification of Subsurface Utility Information.

As such, Telstra supplied location information is indicative only. Spatial accuracy is not applicable to Quality Level D.

Refer to AS 5488 for further details. The exact position of Telstra assets can only be validated by physically exposing it.

Telstra does not warrant or hold out that its plans are accurate and accepts no responsibility for any inaccuracy.

Further on site investigation is required to validate the exact location of Telstra plant prior to commencing construction work.

A Certified Locating Organisation is an essential part of the process to validate the exact location of Telstra assets and to ensure the asset is protected during construction works.

See the Steps- Telstra Duty of Care that was provided in the email response.

## APPENDIX C – SHEETED DETAIL SITE SURVEY

# A1

l	7.11				
	UTILITY ASSETS LEGEND				
	ELECTRICITY		-EU ——	—— EU –	
	COMMS TELEPHONE LINE		-т —	т –	
	COMMS OPTICAL FIBRE		- OU	OU	
	COMMS HOUSE CONNECTION	۱	– TH ——	—— ТН —	
	WATER MAIN				
	RECYCLED WATER MAIN		- WR		
	WATER HOUSE CONNECTION		– WH	—— WH—	
	LOW PRESSURE GAS				
	GAS HOUSE CONNECTION		– GH ——	—— GH—	
	SEWER MAIN		– s —	—— s —	
	STORMWATER PIPE	_	sw —	- sw ——	- sw —
	OVERHEAD ELECTRICITY	_	OHP	- OHP	OHP

UTILITY MAPPING NOTES:

- Subsurface utility investigation was undertaken by Atrea Pty Ltd, the plan is to be read inconjuction with the subsurface utility investigation report. Positions are based on Astrea Class A & B point surface indicator(s) located during field survey. Confirmation of the exact position should be made to the relevant authorities prior to any excavation work. Other services may still exist. 3. This plan shows a representation of the dwg model. this model should be
- viewed in a cadd environment to interpret this information. 4. This utility plan is valid for 28 days starting from the date of the issue, as underground utility works are often updated.
- 5. Electricity cables are not necessarily enclosed in conduits and are not
- necessarily covered with markers, tape or other indicators of their presence. 6. All services have been electronically traced in the field and are shown here for diagrammatic purposes only. Depths shown are approximate only and should be verified prior to works.
- 7. This plan includes information describing the location of subterranean features, which were purported to exist at the time of the survey. This information was compiled from a combination of field techniques and available data from cooperating utility authorities. Whilst all care has been taken in the preparation of this plan of survey, we cannot guarantee that the plan is without flaw of any kind.

SUBSURFACE UTILITY INFORMATION (SUI) AS5488 LOCATION CLASS

CLASS A: Information is the highest possible level of accuracy and is obtained by exposing the underground utility using a on-destructive excavation (pot holing) technique. The vertical information for this locating method is to the top or shallowest part of the located service. The 3D location is recorded by survey as an X, Y, Z coordinate.

D. P. 866983

SHEET 03

CLASS B: Information is collected by designating the horizontal and vertical location of underground utilities by using electromagnetic pipe and cable locators, sondes or flexi-trace, ground penetrating radar and acoustic pulse equipment. This is the most common form of utility locating and although an X, Y and Z axis can be established it is not always entirely accurate due to differing electromagnetic fields, soil conditions and multiple banks of cables affecting the locating signal.

CLASS C: Information is collected by correlating the survey of visible utility surface features such as marker plates or water hydrants and acquired Dial-Before-You-Dig plans to "draw" a string which shows the approximate position of services. This method does not usually show multiple banks of cables and does not always show three dimensional information. Electronically traced locate marks with poor scratchy signals are represented as QL-C.

CLASS D: Information is the most basic level of utility locations using only information based on existing Dial-Before-You-Dig plans and by measuring boundary offsets etc. This method of utility locations should always be treated as an indication of the presence of a amount of reliance on it. Project risks related to underground utilities can then be managed.



10 20 30 40 50 60 70 80 90 100

PM66501

ORIENTATION PM66501 - PM 76129

AHD ORIGIN PM66501 RL 17.600

ORIGIN

**GDA** 

2020



IAL BEFORE DIG www.**1100**.com.au

E 287148.053 N 6116179.025 PURPOSE: ENGINEERING DESIGN SHEET 01 0F 05

	MGA TN APPROX.
SURVEY SOLUTIONS MAPPING , TRINITI II, TRINITI BUSINESS PARK ROAD, NORTH RYDE 2113 ERIDGE 0425 285 270	JOB REFERENCE : A4066 DWG No. A4066–UTIL&TOPO SURVEYOR: BD, JD, EK DATE OF SURVEY: OCT 2023 UTILITY LOCATOR: LB C ASTREA 2023 - UNAUTHORISED USE IS PROHIBITED
strea	REV AMENDMENTS DATE

TITLE NOTATIONS 1/550361: 1. RESERVATIONS AND CONDITIONS IN THE CROWN GRANT 2. LAND EXCLUDES MINERALS BY THE CROWN GRANT OF 137 ACRES 3 ROODS TITLE NOTATIONS 1/809057: 1. LAND EXCLUDES MINERALS VIDE MEMORANDUM T447400

# UTILITY ASSETS LEGEND

ELECTRICITY	EU EU	J ———
COMMS TELEPHONE LINE	TT	
COMMS OPTICAL FIBRE	OUOU	J
COMMS HOUSE CONNECTION	I TH TH	I ———
WATER MAIN		
RECYCLED WATER MAIN		R
WATER HOUSE CONNECTION	—— WH——— WI	
LOW PRESSURE GAS		
GAS HOUSE CONNECTION	GH GH	I
SEWER MAIN	— s — s	
STORMWATER PIPE	— sw — sw —	— SW —
OVERHEAD ELECTRICITY	— онр— онр—	OHP

## UTILITY MAPPING NOTES:

- Subsurface utility investigation was undertaken by Atrea Pty Ltd, the plan is to be read inconjuction with the subsurface utility investigation report. Positions are based on Astrea Class A & B point surface indicator(s) located during field survey. Confirmation of the exact position should be made to the relevant authorities prior to any excavation work. Other services may still exist. 3. This plan shows a representation of the dwg model. this model should be
- viewed in a cadd environment to interpret this information. 4. This utility plan is valid for 28 days starting from the date of the issue, as underground utility works are often updated.
- 5. Electricity cables are not necessarily enclosed in conduits and are not necessarily covered with markers, tape or other indicators of their presence. 6. All services have been electronically traced in the field and are shown here for
- diagrammatic purposes only. Depths shown are approximate only and should be verified prior to works.

 This plan includes information describing the location of subterranean features, which were purported to exist at the time of the survey. This information was compiled from a combination of field techniques and available data from cooperating utility authorities. Whilst all care has been taken in the preparation of this plan of survey, we cannot guarantee that the plan is without flaw of any kind.

SUBSURFACE UTILITY INFORMATION (SUI) AS5488 LOCATION CLASS amount of reliance on it. Project risks related to underground utilities can then be managed.

CLASS A: Information is the highest possible level of accuracy and is obtained by exposing the underground utility using a on-destructive excavation (pot holing) technique. The vertical information for this locating method is to the top or shallowest part of the located service. The 3D location is recorded by survey as an X, Y, Z coordinate.

THE WOOL ROAD

CLASS B: Information is collected by designating the horizontal and vertical location of underground utilities by using electromagnetic pipe and cable locators, sondes or flexi-trace, ground penetrating radar and acoustic pulse equipment. This is the most common form of utility locating and although an X, Y and Z axis can be established it is not always entirely accurate due to differing electromagnetic fields, soil conditions and multiple banks of cables affecting the locating signal.

CLASS C: Information is collected by correlating the survey of visible utility surface features such as marker plates or water hydrants and acquired Dial-Before-You-Dig plans to "draw" a string which shows the approximate position of services. This method does not usually show multiple banks of cables and does not always show three dimensional information. Electronically traced locate marks with poor scratchy signals are represented as QL-C.

CLASS D: Information is the most basic level of utility locations using only information based on existing Dial-Before-You-Dig plans and by measuring boundary offsets etc. This method of utility locations should always be treated as an indication of the presence of a service only and should not be used for design. GPR scans are also represented as QL-D



	and the state	- STERNE		
2				*
		122210		
		Carlo and	•••	
		19-19-19-19	1981 1993 1993	• 2045
		Contraction of the	+21.17	
		9611	+19.07 +2964 +1957 +1959 +1959 +1959 +10.02	•2254
The share the second				P. 550
				• 20.53
			• 25.07 • 10.72	+ 20.58
			• 1932 • • 1939 • • 1934 • • 1934	
			•19.60 UN	
	1/	-2014		
A CARLES		n 110 110 100	2	
		- 20 T		
		-un -un - un - 19 - 19 - 19 - 19 - 19 - 19 - 19 - 1	· · · · · · · · · · · · · · · · · · ·	+ 22.16
	• mp	•10.0 · 10.0		/
	•337 n	•157		
		funder Inn		
			• 22.54	•22.53
• 103	100.	0 • • • • •		
· 1024				
· 105 · 107	• 1929 • 1929 • 1929			• 2244 @etg
-mg -mg	0 0 .20	• 22	hear.	
+10.73 +10.74 +1	•			
• 00 • 033 • 030 • 030		Contraction of the		
Ma - 207 - 103 - 103 - 103		•224		
· 1937 • 2037		221		• 22.84
· · · · · · · · · · · · · · · · · · ·			•223	
• 50 22	• 22.31	- 2240	• • 22.88	
				+2254
	• 2233			$\langle \rangle$
от	Constant of	•225	+2278	
· · · · · · · · · · · · · · · · · · ·	• 22.48		22.55	
		200°		
GENERAL SURVEY LEGEND: INAGE PIT RAINAGE JUNCTION MANHOLE	GENERAL SURVEY NOTES : * THIS TITLEBLOCK IS AN INTEGRAL PART OF * COORDINATE SYSTEM MGA 2020 * LEVEL DATI IM IS AND	THIS DWG AND SHOULD NOT BE REMOVED	CLIENT : SCHOOLS INFRASTRUCTURE	
IVDRANT IVDRANT TOP VALVE ULLY PIT SAS MARKER	* IT IS THE RESPONSIBILITY OF ANY USER OF BEING INTEGRATED IS ON THE SAME COOR * REFER TO THE FACE OF THE PLAN FOR TITL	THIS DATA TO ENSURE ANY OTHER DATA DINATE SYSTEM .E NOTATIONS		SUITE 6.0 39 DELHI
AS LEST POINT DWER POLE DW - DRIVEWAY ELSTRA PIT LP - LIP OF GUTTER OF KERB EOT - END OF TRACE M RAMP UTL - UNABLE TO LOCATE	* CONTOURS ARE INDICATIVE OF LAND FORM	VEY. M. SPOT LEVELS TAKE PRECEDENCE.	UTILITY MAPPING IN ACCORDANCE WITH AS4588.1-2019	www.astrea
	0 10	20 .30		
YOU DIG		- E N ATION -	PURPOSE: ENGINEERING DESIGN	- /
www.1100.com.au	2020 AHD OF	RIGIN -	SHEET 02 0F 05	



# TITLE NOTATIONS 1/550361: 1. RESERVATIONS AND CONDITIONS IN THE CROWN GRANT 2. LAND EXCLUDES MINERALS BY THE CROWN GRANT OF 137 ACRES 3 ROODS TITLE NOTATIONS 1/809057:

1. LAND EXCLUDES MINERALS VIDE MEMORANDUM T447400

UTILITY MAPPING NOTES:

UTILITY ASSETS LEGEND		
ELECTRICITY	—— EU ——	—— EU ———
COMMS TELEPHONE LINE	т	т
COMMS OPTICAL FIBRE	OU	OU
COMMS HOUSE CONNECTION	—— ТН ——	—— TH ———
WATER MAIN		
RECYCLED WATER MAIN	WR	WR
WATER HOUSE CONNECTION		
LOW PRESSURE GAS		
GAS HOUSE CONNECTION	—— GH——	GH
SEWER MAIN	— s —	s
STORMWATER PIPE	— sw —	- sw — sw —
OVERHEAD ELECTRICITY	— онр	OHP OHP

Subsurface utility investigation was undertaken by Atrea Pty Ltd, the plan is to be read inconjuction with the subsurface utility investigation report. Positions are based on Astrea Class A & B point surface indicator(s) located during field survey. Confirmation of the exact position should be made to the relevant authorities prior to any excavation work. Other services may still exist. 3. This plan shows a representation of the dwg model. this model should be

- viewed in a cadd environment to interpret this information. 4. This utility plan is valid for 28 days starting from the date of the issue, as underground utility works are often updated.
- 5. Electricity cables are not necessarily enclosed in conduits and are not
- necessarily covered with markers, tape or other indicators of their presence. 6. All services have been electronically traced in the field and are shown here for diagrammatic purposes only. Depths shown are approximate only and should be verified prior to works.
- . This plan includes information describing the location of subterranean features, which were purported to exist at the time of the survey. This information was compiled from a combination of field techniques and available data from cooperating utility authorities. Whilst all care has been taken in the preparation of this plan of survey, we cannot guarantee that the plan is without flaw of any kind.

SUBSURFACE UTILITY INFORMATION (SUI) AS5488 LOCATION CLASS

CLASS A: Information is the highest possible level of accuracy and is obtained by exposing the underground utility using a on-destructive excavation (pot holing) technique. The vertical information for this locating method is to the top or shallowest part of the located service. The 3D location is recorded by survey as an X, Y, Z coordinate.

CLASS B: Information is collected by designating the horizontal and vertical location of underground utilities by using electromagnetic pipe and cable locators, sondes or flexi-trace, ground penetrating radar and acoustic pulse equipment. This is the most common form of utility locating and although an X, Y and Z axis can be established it is not always entirely accurate due to differing electromagnetic fields, soil conditions and multiple banks of cables affecting the locating signal.

CLASS C: Information is collected by correlating the survey of visible utility surface features such as marker plates or water hydrants and acquired Dial-Before-You-Dig plans to "draw" a string which shows the approximate position of services. This method does not usually show multiple banks of cables and does not always show three dimensional information. Electronically traced locate marks with poor scratchy signals are represented as QL-C.

CLASS D: Information is the most basic level of utility locations using only information based on existing Dial-Before-You-Dig plans and by measuring boundary offsets etc. This method of utility locations should always be treated as an indication of the presence of a service only and should not be used for design. GPR scans are also represented as QL-D amount of reliance on it. Project risks related to underground utilities can then be managed.







UTILITY ASSETS LEGEND ELECTRICITY COMMS TELEPHONE LINE COMMS OPTICAL FIBRE





UTILITY ASSETS LEGEND		
ELECTRICITY	—— EU ——	—— EU ———
COMMS TELEPHONE LINE	—т —	T
COMMS OPTICAL FIBRE	OU	OU
COMMS HOUSE CONNECTION	V —— тн ——	TH
WATER MAIN		
RECYCLED WATER MAIN		
WATER HOUSE CONNECTION		WH
LOW PRESSURE GAS		
GAS HOUSE CONNECTION	—— GH——	GH
SEWER MAIN	s	s
STORMWATER PIPE	— sw —	- sw — sw —
OVERHEAD ELECTRICITY	OHP	OHP OHP

Subsurface utility investigation was undertaken by Atrea Pty Ltd, the plan is to be read inconjuction with the subsurface utility investigation report. Positions are based on Astrea Class A & B point surface indicator(s) located during field survey. Confirmation of the exact position should be made to the relevant authorities prior to any excavation work. Other services may still exist.

- 3. This plan shows a representation of the dwg model. this model should be viewed in a cadd environment to interpret this information. 4. This utility plan is valid for 28 days starting from the date of the issue, as
- underground utility works are often updated.

UTILITY MAPPING NOTES:

- 5. Electricity cables are not necessarily enclosed in conduits and are not necessarily covered with markers, tape or other indicators of their presence. 6. All services have been electronically traced in the field and are shown here for diagrammatic purposes only. Depths shown are approximate only and should
- be verified prior to works. '. This plan includes information describing the location of subterranean features,
- which were purported to exist at the time of the survey. This information was compiled from a combination of field techniques and available data from cooperating utility authorities. Whilst all care has been taken in the preparation of this plan of survey, we cannot guarantee that the plan is without flaw of any kind. SUBSURFACE UTILITY INFORMATION (SUI) AS5488 LOCATION CLASS

amount of reliance on it. Project risks related to underground utilities can then be managed.

CLASS A: Information is the highest possible level of accuracy and is obtained by exposing the underground utility using a on-destructive excavation (pot holing) technique. The vertical information for this locating method is to the top or shallowest part of the located service. The 3D location is recorded by survey as an X, Y, Z coordinate.

CLASS B: Information is collected by designating the horizontal and vertical location of underground utilities by using electromagnetic pipe and cable locators, sondes or flexi-trace, ground penetrating radar and acoustic pulse equipment. This is the most common form of utility locating and although an X, Y and Z axis can be established it is not always entirely accurate due to differing electromagnetic fields, soil conditions and multiple banks of cables affecting the locating signal.

CLASS C: Information is collected by correlating the survey of visible utility surface features such as marker plates or water hydrants and acquired Dial-Before-You-Dig plans to "draw" a string which shows the approximate position of services. This method does not usually show multiple banks of cables and does not always show three dimensional information. Electronically traced locate marks with poor scratchy signals are represented as QL-C.

CLASS D: Information is the most basic level of utility locations using only information based on existing Dial-Before-You-Dig plans and by measuring boundary offsets etc. This method of utility locations should always be treated as an indication of the presence of a service only and should not be used for design. GPR scans are also represented as QL-D



# (UNFORME ROAD UNNAMED

GENERAL SURVEY NOTES : * THIS TITLEBLOCK IS AN INTEGRAL PART OF THIS DWG AND SHOULD NOT BE REMOVED	CLIENT : SCHOOLS INFRASTRUCTURE	DIGI
* COORDINATE SYSTEM MGA 2020 * LEVEL DATUM IS AHD	PLAN IN RELATION TO :	UTILI
* IT IS THE RESPONSIBILITY OF ANY USER OF THIS DATA TO ENSURE ANY OTHER DATA BEING INTEGRATED IS ON THE SAME COORDINATE SYSTEM	VINCENTIA HIGH SCHOOL	SUITE (
* REFER TO THE FACE OF THE PLAN FOR TITLE NOTATIONS * BOUNDARIES HAVE BEEN DEFINED BY SURVEY. * CONTOURS ARE INDICATIVE OF LAND FORM. SPOT LEVELS TAKE PRECEDENCE.	SHOWING : TOPOGRAPHICAL SURVEY AND	SCOTT www.astr
	AS4588 1-2019	



www.**1100**.com.au

GENERAL SURVEY LEGEND:

	SC	CALE 1:300			
0 1	0		20		3
		ORIGIN	- E	N	
GDA		ORIENTATION	-		
2020		AHD ORIGIN	-		

CTION QUALITY LEVEL PIPE MATERIAL & SIZ

TN/Á A100

VINCENTIA HIGH SCHOOL SHOWING : TOPOGRAPHICAL SURV UTILITY MAPPING IN ACCORDANCE AS4588.1-2019

SHEET 05 0F 05

PURPOSE: ENGINEERING DESIGN

REV

AMENDMENTS

APPENDIX D – Underground Service Locator Field Report.



# Consult Manage Deliver

# SUBSURFACE UTILITY INVESTIGATION REPORT FOR

Schools Infrastructure

Vincentia High School



COMPILED BY: LB MB TH

INVESTIGATION 9-Oct-2023 DATE:





Consult Manage Deliver

CLIENT:	Schools Infrastructure	DATE:	9-Oct-2023
SITE CONTACT:	Glenn Francis	MOBILE:	0428 261 881
EMAIL:	Glenn.francis@det.nsw.edu.au		
WORK LOCATION:	Vincentia High School		

INVESTIGATION BY:	LB MB TH	DBYD REF. NO: 34866513
SITE SPECIFIC PLANS:	NA	DBYD ENQUIRY DATE: 18-Aug-2023
SWMS NO:	COMPLETED: YES NO	
CLIENT SITE REVIEW:	COMPLETED: YES NO	ASTREA SITE SUPERVISOR: LB MB TH

LOCATING QUALITY LEVELS PURSUANT TO AS5488-2019			
Quality Level A	Visualisation / Confirmation of a Service, position and depth, by non- destructive digging (NDD) methods or points of entry to pits or manholes. Recommended Quality Level prior to construction or		
QL-A	excavation.		
Quality Level B	Locating of Services using Radio Detection methods. Acceptable range of accuracy for Quality Level B is 300mm for position and 500mm in Depth.		
QL-B			
Quality Level C	Services Marked out using only surface features in the field. Such surface features include, Hydrants, Gas Markers, Pits etc. No indication of service location or depth can be attained from Quality Level C.		
QL-C			
Quality Level D	Services marked up using DBYD plans only. Offsets on plans can be used to obtain such indication of services in field but no indication of service confirmation can be given.		

Consult Manage Deliver

SERVICE:	QUALITY LEVEL:	COMMENT:	TRACE METHOD:
TELECOMMUNICATIONS	QL-A 🖌 QL-B 🖌 QL	-C 🖌 QL-D	GPR EM
OPTICAL FIBRE	QL-A 🗌 QL-B 🖌 QL	-C QL-D	GPR 🔄 EM 🖌
ELECTRICITY	QL-A 🗌 QL-B 🖌 QL	-C 🔽 QL-D	GPR 🖌 EM 🖌
WATER	QL-A 🗌 QL-B 🖌 QL	-C 🗌 QL-D 🖌	GPR 🖌 EM 🖌
GAS	QL-A 🗌 QL-B 🖌 QL	-c 🗌 QL-D 🖌	GPR 🖌 EM 🖌
SEWER	QL-A 🖌 QL-B 🖌 QL	-C 🖌 QL-D 🖌	GPR 🖌 EM 🖌
STORMWATER	QL-A 🖌 QL-B 🗌 QL	-C 🖌 QL-D 🖌	GPR 🖌 EM 🖌
UNKNOWN	QL-A QL-B QL	-C QL-D	GPR EM

# Site Notes

Some some services could not be traced as these were non conductive services-e.g. sewer rising main. These will be represented as class on the drawing.

Large retention pit in the sewer pump out yard was full of debris, could not determine the function of pit.

Sewer gravity pit could not be traced into the rising main pump. Pipe may be obstructed.

Some pits were full or debris and could not be traced- asset register in main report.

Consult

Manage Deliver

# Scope of Works



### **Colour Legend**



### Code Legend

EU - Electricity Underground	LG - Low Pressure Gas Main	WM - Water Main
TN - Telstra Network underground	HG - High Pressure Gas Main	RWM - Recycled Water
OU - Optic Fibre Underground	SM - Sewer Main	UP - Unknown Service
CN - Other Comms Network	RSM - Rising Sewer Main	SW - Drainage Network

### Class D (not identified)

#### . . . . . . . . . . . .

UTL = UNABLE TO LIFT FOD = FULL OF DEBRIS FOW = FULL OF WATER



Consult







Consult

Manage Deliver

























Consult

Manage Deliver







#### DISCLAIMERS

This plan includes information describing the location of subterranean features, which were purported to exist at the time of the survey. This information was compiled from a combination of field techniques and available data from cooperating utility authorities. Whilst all care has been taken in the preparation of this plan of survey, Astrea cannot guarantee that the plan is without flaw of any kind. Therefore, Astrea expressly disclaims all liability for errors or omissions of any kind whatsoever or from any loss, damage or other consequences, which may arise from any person relying on anything, stated on this plan. In particular, it is recommended that users satisfy themselves as to the location of subterranean features such as utilities, which may or may not be shown on this plan by deploying vacuum excavation techniques.

REPORTED BY:	LB MB TH
DATE:	9-Oct-2023
SIGNATURE:	R







