

Service protection report

Joseph plumbing

supplier no: 873


Property Address: 8 Hillview Avenue, Bankstown, NSW 2200

Client: (Nemco Design)

PNum: 13802447

Hillview Ave

*The Storm water pipe crosses the right side fence of 168 Hillcrest avenue at a distance to the back fence = 7 m
Depth to invert = 0.875 m*



*The Storm water pipe crosses the back fence of 168 Hillcrest avenue at a distance to the right side fence = 13.65 m
Depth to invert = 0.975 m*

Pipe size: 750 mm

Pipe type: R.C.

Strata: Clay, Soil

Asset Location method: Electronic Pipe Locator/ Potholing/ Surveying/ Accessing structures

Asset indicators: Paint on fence

I, Housien Nasrallah of Joseph plumbing, being accredited to carry out a Service Protection Report, certify that the information shown on the Report is accurate and has been prepared in accordance with the relevant instructions.

Prepared by: Joseph plumbing
Housien.nasrallah@gmail.com

signature: *Y. NASRALLAH*
Mobile: 0410055075

Date: 25/09/2023

Abn: 35134685108