

HERITAGE ASSESSMENT, WILLOW RUN, 105-119 BONG BONG ROAD, MITTAGONG

ATTACHMENT 1. CURRENT PHOTOGRAPHS. All photographs: Paul Wallace.

Note: (numbers refer to location of photos on map included at p.12 of Heritage Assessment)



Figure 1. Homestead building, Willow Run, front (north eastern) view (no. 7)



Figure 2. Homestead building, Willow Run, rear (south western) view – sole driveway access (Osage Orange trees at left of photo) (no. 9)



Figure 3. Homestead building, Willow Run, north western side (no. 4)



Figure 4. Toilet building near homestead (eastern side), Willow Run (no. 17)



Figure 5. Shed building, showing recessed rafters in roof, near homestead (south eastern side), Willow Run (no. 13)



Figure 6. View to shed and eastern side of homestead, Willow Run (no. 23)



Figure 7. Well at south western side of homestead, Willow Run (no. 32)



Figure 8. Well (filled in) at south eastern side of homestead, Willow Run (no. 14)



Figure 9. Orchard, located north-east of homestead, Willow Run (no. 19)



Figure 10. Drainage channel, located north-west of orchard, Willow Run (no. 16)



Figure 11. Site of former dairy buildings, located south-east of homestead, Willow Run (no. 25)



Figure 12. Site of former brickpit, located north-west of homestead, Willow Run (no. 34)



Figure 13. Water tank used as service reservoir, located on Council land, within area proposed for exclusion from existing property, Willow Run (no. 36)



Figure 14. Concrete floor, site of former slaughterhouse, Willow Run (no. 46)



Figure 15. Pockets of significant vegetation within area proposed for exclusion from existing property, Willow Run (residence is on separate lot) (no. 52)



Figure 16. Dam at far north-west of existing lot, within area proposed for exclusion from existing property, Willow Run (residence is on separate lot) (no. 54)



Figure 17. Significant tree: probably Apple Box (*Eucalyptus bridgesiana*) to south-west of existing property, Willow Run (no. 41)



Figure 18. Significant tree: Paperbark (*Melaleuca Quinquenervia*) to south-west of existing property, Willow Run (no. 42)



Figure 19. Entry gate and driveway, Willow Run (no. 48)