

Locked Bag 5020 Parramatta NSW 2124
Level 6, 10 Valentine Avenue
Parramatta NSW 2150
Tel: (02) 9873 8500 Fax: (02) 9873 8599
TTY (02) 9211 4723 ABN 30 841 387 271
www.heritage.nsw.gov.au
heritagemailbox@environment.nsw.gov.au

DOC19/1052799

Mr Nick Johnston Project Director, Heritage Core Parramatta North Infrastructure NSW Level 12, MLC Centre, 19 Martin Place SYDNEY NSW 2000

Email: njohnston@ugdc.nsw.gov.au

cc: SWilliams@tkda.com.au

Dear Nick

# APPROVAL UNDER SECTION 60 OF THE HERITAGE ACT 1977 CUMBERLAND DISTRICT HOSPITAL GROUP, STATE HERITAGE REGISTER No 00820

Address: 5 Fleet Street, Parramatta

**Application no:** S60/2019/227, received 12 December 2020

Proposal: Western Sydney Start-up Hub - Conservation and Adaptation Works to

Buildings C104, C104A, C107, C190 (part) and C111

As delegate of the Heritage Council of NSW (the Heritage Council), I have considered the above Section 60 application. Pursuant to section 63 of the *Heritage Act 1977*, approval is granted subject to the following conditions.

### 1. APPROVED DEVELOPMENT

Development must be in accordance with:

a) Architectural drawings prepared by TKD Architects as listed below.

Dwg No	Dwg Title	Date	Rev
Project Name: F	Parramatta North Growth Centre Heritage Repairs – Tranche 2		
AR.S60.0000	LOCATION PLAN AND COVER SHEET	29.11.19	Α
AR.S60.0001	EXISTING SITE PLAN AND STAGING DIAGRAM	29.11.19	Α
AR.S60.1001	ACTIVATION PRECINCT - PROPOSED GROUND FLOOR PLAN	29.11.19	А
AR.S60.1002	ACTIVATION PRECINCT - PROPOSED FIRST FLOOR PLAN	29.11.19	Α
AR.S60.2001	BUILDINGS C104+C104a DEMOLITION GROUND FLOOR PLAN	29.11.19	А
AR.S60.2002	BUILDINGS C104+C104a PROPOSED GROUND FLOOR PLAN	29.11.19	А
AR.S60.2003	BUILDINGS C104+C104a DEMOLITION FIRST FLOOR PLAN	29.11.19	А
AR.S60.2004	BUILDINGS C104+C104a PROPOSED FIRST FLOOR PLAN	29.11.19	А
AR.S60.2005	BUILDINGS C104+C104a DEMOLITION ROOF PLAN	29.11.19	А
AR.S60.2006	BUILDINGS C104+C104a PROPOSED ROOF PLAN	29.11.19	А

AR.S60.2007	BUILDINGS C104+C104a DEMOLITION/PROPOSED SOUTH	29.11.19	А
AR.S60.2008	BUILDINGS C104+C104a DEMOLITION/PROPOSED NORTH ELEVATION	29.11.19	А
AR.S60.2009	BUILDINGS C104+C104a DEMOLITION/PROPOSED EAST ELEVATION	29.11.19	А
AR.S60.4001	BUILDING C107 DEMOLITION GROUND FLOOR PLAN	17.02.20	Α
AR.S60.4001	BUILDING C107 PROPOSED GROUND FLOOR PLAN	17.02.20	В
AR.S60.4002	BUILDING C107 DEMOLITION/PROPOSED FIRST FLOOR PLAN	29.11.19	А
AR.S60.4003	BUILDINGS C107+C104 DEMOLITION/PROPOSED WEST ELEVATION	29.11.19	А
AR.S60.6001	BUILDING C111 DEMOLITION/PROPOSED GROUND & FIRST FLOOR PLANS 1:100 AR.S60.6002	29.11.19	A
AR.S60.6002	BUILDING C111 DEMOLITION/PROPOSED ROOF PLAN	29.11.19	Α
AR.S60.6003	BUILDING C111 DEMOLITION/PROPOSED NORTH & WEST ELEVATIONS	29.11.19	А
AR.S60.6004	BUILDING C111 DEMOLITION/PROPOSED SOUTH & EAST ELEVATION	29.11.19	А

- b) Cumberland Hospital (East Campus) Site Buildings C104, C104A, C107, and C111, Proposed Conservation and Adaptive Re-use, Statement of Heritage Impact, Tanner Kibble Denton Architects, December 2019:
- c) Cumberland Hospital (East Campus) site—Buildings C104, C104A, C107, C109 (part) and C111 Proposed Conservation and Adaptive Re-use—HIS Addenda, Statement of Heritage Impact, Tanner Kibble Denton Architects, 25 February 2020

**EXCEPT AS AMENDED** by the following conditions of this approval.

### 2. INTERPRETATION PLAN

Further interpretive design development is required as an integral part of the proposed design and development. This is to clearly communicate and innovatively interpret the contribution of the affected buildings to the story and evolution of the site's layered history, including the use and function. The interpretive design must be developed in accordance with the CMP's policies and the PNHS Interpretation Strategy, including all phases of the sites development. This must be prepared by an interpretive specialist in consultation with the architect to integrate interpretation into the construction and finishes. This must be submitted to the satisfaction of Heritage NSW prior to the finalisation of detailed design for the new works.

Reason: Because the proposal involves demolition, interpretation is required to communicate the layers of history of these site's elements. This will enhance the community's understanding of the history and heritage significance of the overall site and to ensure that the use and function of the buildings, and their historical relationship to the broader precinct and phases of history are clearly communicated. It will also mitigate against the removal of the mid-20<sup>th</sup> century additions. Innovative interpretation of the building's histories should be an integral part of the final detailed design for the new works.

### 3. SALVAGE REPORT

The proponent must prepare a Salvage Report which identifies any material for salvage (including within ceiling and underfloor spaces), how recovery of material will be

undertaken for these items, and where this material will be stored. This should be prepared prior to demolition works proceeding and submitted to Heritage NSW for general acceptance.

Reason: To ensure significant material is identified, and appropriately handled.

### 4. 1940s WC ADDITIONS (BUILDING C107)

Demolition of the first floor 1940s WC addition located adjacent to the Building C105 is not approved as part of these works. However, the modern airlock can be removed as well as the internal fixtures and fittings.

Reason: This addition provides evidence of the evolution of care and the need for improved access to WC facilities during the Parramatta Mental Hospital phase (1916-1962), and the physical changes that occurred in the mid-20th century. In addition, it has not been demonstrated that the location of this structure detracts from the spatial qualities of the adjacent yard.

### 5. NEW OPENINGS IN SANDSTONE WALLS

Methodology for cutting into sandstone walls must be provided to Heritage NSW for general acceptance prior to this component of the works proceeding. The methodology must be determined in consultation with the nominated heritage consultant. Details must also be provided of treatment to cut edges and include details of thresholds, lintels and framing.

Reason: To ensure the penetrations are appropriately finished, and that as little significant fabric is impacted by the works as possible.

### 6. REMOVAL OF CONCRETE RENDER FROM SANDSTONE WALLS

Methodology for removal of concrete render from original sandstone walls must be provided to Heritage NSW for general acceptance prior to this component of the works proceeding. This must be prepared by a qualified specialist with practical experience in conservation and restoration of similar structures, materials and methods. Further, a trial of the methodology must be undertaken in a non-visually prominent area to ensure it achieves the desired outcome without damage to the sandstone. This is to be confirmed on site in consultation with the nominated heritage consultant. Confirmation of the trial including images, must be provided to Heritage NSW for general acceptance prior to its adoption across the affected buildings.

Reason: To ensure significant fabric is not adversely impacted by the proposed works, and to provide opportunity to adjust the methodology on site if required.

### 7. CONSERVATION WORKS

A methodology for all repair/conservation works including schedule of works is to be submitted to Heritage NSW for general acceptance prior to this component of the works proceeding.

Reason: To ensure significant fabric is not adversely impacted by the proposed works.

### 8. STEEL-FRAMED GLAZED BOX ENTRY WITH STEEL CANOPY

Further detailed design of the proposed steel framed glazed entry box and steel canopy including renders, and fixing details, must be provided to Heritage NSW for general acceptance prior to this component of the works proceeding.

Reason: To ensure the installation of these elements do not have an adverse physical or visual impact on significant fabric.

### 9. NEW INTERNAL LIFT AND MEZZANINE

Further detailed design of the proposed internal lift and mezzanine level including renders, and fixing details into original fabric, must be provided to Heritage NSW for general acceptance prior to this component of the works proceeding.

Reason: To ensure the installation of these elements do not have an adverse physical and visual impact on significant fabric.

### 10. NEW SERVICES

Further detailed design of the proposed new building services including electrical power and lighting, communications and security, fire detection and suppression and mechanical services must be provided to Heritage NSW for general acceptance prior to these components of the works proceeding. In particular, details of mechanical ducts, location and number of external a/c condensers, fresh air intakes and exhaust vents are required.

Reason: To ensure the installation of these elements do not have an adverse physical and visual impact on significant fabric and spaces.

### 11. NEW TOILET/SHOWER FACILITIES

Further detailed design of the proposed new toilet and shower facilities including wall treatments to existing sandstone walls, and service provision to the spaces must be provided to Heritage NSW for general acceptance prior to these components of the works proceeding. In particular, further detail must be provided of the proposed WC facility on level 1 (Building C107) including floor treatment to original timber floor; and, proposed shower cubicles (Building C109) including wall treatment to sandstone walls above sill height.

Reason: To ensure the installation of the toilet/shower facilities do not have an adverse physical impact on significant fabric or spaces.

### 12. NEW SCREENED SERVICES ENCLOSURE

Further detailed design of the proposed new screened services enclosure adjacent to Building C104a, including scale, materiality and any fixing details must be provided to Heritage NSW for general acceptance prior to this component of the works proceeding.

Reason: To ensure the construction of the screened enclosure is of a scale, bulk, form and materiality that appropriately responds to and enhances the character of the Parramatta Lunatic Asylum buildings; and to ensure it does not obstruct significant views and vistas or adversely impact on the footprint of the early garden setting.

### 13. CAFÉ FITOUT

The café fitout proposed within the former Boiler Room of Building C104a is not approved.

Reason: A separate application with appropriate documentation will be required to undertake these works once a potential tenant is secured to ensure that the adaptive reuse meets the operator's requirements and minimises impacts.

### 14. NEW RAMP

Further detailed design of the proposed ramp adjacent to Building C111, including handrail details and proposed impact to the adjacent palm tree must be provided to Heritage NSW for general acceptance prior to this component of the works proceeding.

Reason: To ensure the construction of the ramp is of a materiality that appropriately responds to and enhances the character of the area.

### 15. HERITAGE CONSULTANT

A suitably qualified and experienced heritage consultant must be nominated for this project. The nominated heritage consultant must provide input into the detailed design, provide heritage information to be imparted to all tradespeople during site inductions, and oversee the works to minimise impacts to heritage values. The nominated heritage consultant must be involved in the selection of appropriate tradespersons, and must be satisfied that all work has been carried out in accordance with the conditions of this consent.

Reason: To ensure that appropriate heritage advice is provided to support best practice conservation and ensure works are undertaken in accordance with this approval.

### 16. APPROPRIATELY SKILLED TRADESPEOPLE

Only tradespeople with appropriate skills, qualifications and practical experience in conservation and restoration of similar heritage structures, materials and construction methods should be employed/contracted/sub-contracted to carry out the works. The tradespeople must undergo heritage induction by the heritage consultant.

Reason: To ensure that original and/or significant fabric and values are not damaged, diminished or put at risk during demolition and construction of the approved works.

### 17. SITE PROTECTION

Significant built elements are to be protected during site preparation and the works from potential damage, in particular during removal of the mid-20<sup>th</sup> century additions. Protection systems must ensure significant fabric is not damaged or removed.

Reason: To ensure that significant fabric is not damaged during the works.

### 18. PHOTOGRAPHIC ARCHIVAL RECORDING

A photographic archival recording of the affected buildings must be prepared prior to the commencement of works. This recording can be in digital form and must be in accordance with the NSW Heritage Division (Heritage NSW) publication Photographic Recording of Heritage Items using Digital Capture (2006). A digital copy of the archival record must be provided to Heritage NSW.

Reason: To capture the condition and appearance of the place prior to modification of the site which impacts significant fabric

### 19. COMPLIANCE

If requested, the applicant and any nominated heritage consultant may be required to participate in audits of Heritage Council of NSW approvals to confirm compliance with conditions of consent.

Reason: To ensure that the proposed works are completed as approved.

### 20. DURATION OF APPROVAL

This approval will lapse five years from the date of the consent unless the building works associated with the approval have physically commenced.

Reason: To ensure the timely completion of works.

NOTE: The proposed demolition works of the mid-20<sup>th</sup> century additions have been assessed on a case-by-case basis and in consideration of cumulative impacts, to determine whether these additions are central to the heritage values of the buildings, that their demolition will not adversely impact the significance of the buildings, and that their removal will enhance the heritage significance of other more significant buildings and structures. Acceptance of these works should not be used as a basis to demolish other similar additions across the site.

It should be noted that an approval under the *Heritage Act 1977* is additional to that which may be required from other Local Government and State Government Authorities in order to undertake works.

Should you have any queries regarding the Western Sydney Start-Up Hub conservation and adaptation works (S60/2019/227), please contact David Nix, Senior Heritage Officer, at Heritage NSW, Department of Premier and Cabinet on (02) 9895 6523 or at <a href="mailto:david.nix@environment.nsw.gov.au">david.nix@environment.nsw.gov.au</a>.

Yours sincerely

**SARAH JANE BRAZIL** 

Senior Team Leader, Major Projects Heritage NSW, Community Engagement Department of Premier and Cabinet

As Delegate of the Heritage Council of NSW

4 May 2020

# PARRAMATTA NORTH **GROWTH CENTRE**

# HERITAGE REPAIRS TRANCHE 2 CUMBERLAND HOSPITAL PRECINCT

# DRAWING SCHEDULE

AR.S60.0000	LOCATION PLAN AND COVER SHEET	NTS
AR.S60.0001	EXISTING SITE PLAN AND STAGING DIAGRAM	1:250
AR.S60.1001	ACTIVATION PRECINCT - PROPOSED GROUND FLOOR PLAN	1:300
AR.S60.1002	ACTIVATION PRECINCT - PROPOSED FIRST FLOOR PLAN	1:300
AR.S60.2001 AR.S60.2002 AR.S60.2003 AR.S60.2004 AR.S60.2005 AR.S60.2006 AR.S60.2007 AR.S60.2008 AR.S60.2009	BUILDINGS C104+C104a DEMOLITION GROUND FLOOR PLAN BUILDINGS C104+C104a PROPOSED GROUND FLOOR PLAN BUILDINGS C104+C104a DEMOLITION FIRST FLOOR PLAN BUILDINGS C104+C104a PROPOSED FIRST FLOOR PLAN BUILDINGS C104+C104a DEMOLITION ROOF PLAN BUILDINGS C104+C104a PROPOSED ROOF PLAN BUILDINGS C104+C104a DEMOLITION/PROPOSED SOUTH ELEVATION BUILDINGS C104+C104a DEMOLITION/PROPOSED NORTH ELEVATION BUILDINGS C104+C104a DEMOLITION/PROPOSED EAST ELEVATION & SECTION	1:100 1:100 1:100 1:100 1:100 1:100 1:100
AR.S60.4001	BUILDING C107 DEMOLITION/PROPOSED GROUND FLOOR PLAN	1:100
AR.S60.4002	BUILDING C107 DEMOLITION/PROPOSED FIRST FLOOR PLAN	1:100
AR.S60.4003	BUILDINGS C107+C104 DEMOLITION/PROPOSED WEST ELEVATION	1:100
AR.S60.6001 AR.S60.6002 AR.S60.6003 AR.S60.6004	BUILDING C111 DEMOLITION/PROPOSED GROUND & FIRST FLOOR PLANS BUILDING C111 DEMOLITION/PROPOSED ROOF PLAN BUILDING C111 DEMOLITION/PROPOSED NORTH & WEST ELEVATIONS BUILDING C111 DEMOLITION/PROPOSED SOUTH & EAST ELEVATIONS	1:100 1:100 1:100 1:100

# FLOOR AREA SCHEDULE

C104	G.01	147 sqm
	G.02	35 sqm
	G.03	42 sqm
	G.04	7 sqm
	G.05	8 sqm
	G.06	6 sqm
	TOTAL	205 sqm
	1.01	113 sqm
	1.02	1.5 sqm
	1.03	17.5 sqm
	TOTAL	172 sqm
C104a	G.01	73 sqm
	G.02	57 sqm
	G.03	73 sqm
	G.04	21 sqm
	G.05	6 sqm
	TOTAL	230 sqm
C107	G.01	133 sqm
	G.02	144 sqm
	G.03a	15 sqm
	G.03b	13 sqm

C107	G.04	12.5 sqm
	G.05	136 sqm
	G.06	7 sqm
	G.07	7 sqm
	G.08	15 sqm
	G.09	15 sqm
	G.10	7 sqm
	G.11	7 sqm
	G.12	15 sqm
	G.13	15 sqm
	G.14	15 sqm
	G.15	15 sqm
	G.16	7 sqm
	TOTAL	578.5 sqm
	1.01	132 sqm
	1.02a	100 sqm
	1.02b	41 sqm
	1.03	21 sqm
	1.04	5 sqm
	1.05	10.5 sqm
	1.06	136 sqm
	1.07	7 sqm

	1.09	15 sqm
	1.10	15 sqm
	1.11	7 sqm
	1.12	7 sqm
	1.13	15 sqm
	1.14	15 sqm
	1.15	15 sqm
	1.16	15 sqm
	1.17	7 sqm
	TOTAL	570.5 sqm
	TOTAL	570.5 sqm
C111	G.01	<b>570.5 sqm</b> 40 sqm
C111		
C111	G.01	40 sqm
C111	G.01 G.02	40 sqm 91 sqm
C111	G.01 G.02 G.03	40 sqm 91 sqm 41 sqm
C111	G.01 G.02 G.03 G.04	40 sqm 91 sqm 41 sqm 30 sqm
C111	G.01 G.02 G.03 G.04 G.05	40 sqm 91 sqm 41 sqm 30 sqm 17 sqm

1.08

7 sqm

**HERITAGE ACT 1977 APPLICATION UNDER SECTION 60** 

**Application No:** \$60/2019/227

Approved by: the Heritage Council of NSW **Delegated Authority** 

On: 04/05/2020

These plans should be read in conjunction with the decision notice

SHO

(for) Delegate Heritage Council



Infrastructure NSW

T +61 2 9216 5700 PO BOX R220 Royal Exchange NSW 2010

Aver

PROJECT MANAGER

T +61 2 9380 8816 Level 1, 171 William St Darlinghurst, NSW, 2010

Abbreviations (E) EXISTING (N) PROPOSED

Rev Date Description P1 14.10.19 P2 22.10.19 P3 29.10.19 P4 25.11.19 A 29.11.19 Final Draft S60 Application

Checked Auth. Proj. Dir CMJ CMJ CMJ CMJ

NSW Nominated Architects:
Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015

PARRAMATTA NORTH GROWTH CENTRE **HERITAGE REPAIRS - TRANCHE 2** 

HISTORIC CORE NORTH - FEMALE FACTORY/ ASYLUM PRECINCT SITE PLAN AND COVER SHEET



Tanner Kibble Denton Architects Pty Ltd


T +61 2 9281 4399 F +61 2 9281 4337


www.tkda.com.au


PO Box 660 Darlinghurst NSW 1300 Australia Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.









ROOFWORK

CLIENT

T +61 2 9216 5700

Royal Exchange NSW 2010

PO BOX R220

Infrastructure NSW

- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting, ridge and hip cappings with new TME
- A5 Replace deteriorated lead flashings, ridge and hip cappings with new TME

**INS** 

- A6 Remove redundant and intrusive services penetrations
- linings, fretwork and mouldings
- A8 Repair roof lantern structure, louvres, cladding and windows
- A9 Repair roof dormer structure, cladding and windows
- A10 Repair galvanised steel vents
- A11 Prime and repaint all new and previously painted timber elements TME or original
- new TME gutters, rainwater heads and downpipes and connect to stormwater drains
- A12 Replace deteriorated rainwater goods with
- A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK
  - - redundant services and patch repair

Key

- B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and
- B3 Rub back areas of minor surface damage
- B4 Repair unsound stone with mortar patch
- B5 Replace damaged stone with stone indent
- B6 Replace missing, loose and non-matching pointing with new TME
- B7 Remove infill/door and reconstruct stonework
- B8 Remove infill and reconstruct opening in
- original detail
- B11 Repair sandstone flagging to verandah
- B12 Check over all brickwork and repair as necessary
- B13 Repair render finishes

**Abbreviations** 

(E) EXISTING

(N) PROPOSED

- stonework to original detail B9 Remove doorway and reconstruct window to to original detail
- B10 Repair all cast iron wall vents replacing deteriorated stones with new TME
- B14 Demolish concrete floor slabs and re-instate verandah floor
- WINDOWS AND DOORS
- C1 Reconstruct original door and window joinery
- C2 Repair damaged door and window joinery to original detail C3 Make all windows and doors operable
- C5 Replace damaged glazing and putty
- C4 Prime and repaint all new and previously painted timber elements TME or original
  - C6 Repair and repaint cast iron window grilles C7 Lock doors shut
- WALLS

  - D2 Apply new plaster finish TME
    - CEILINGS
- E3 Install new ripple iron ceiling TME

Rev Date

P1 29.10.19

P2 25.11.19

A 29.11.19

- INTERNAL CONSERVATION WORKS LEGEND:

SW SW

- D1 Repair plaster finish
- D3 Remove wall tiles and repair wall finish D3 Remove plasterboard wall linings and associated fixings

Description

Final Draft

Preliminary Draft

S60 Application

- E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling
- E4 Install new timber board ceiling TME E5 Remove FC ceiling
- E6 Remove PB ceiling
- **FLOORS** F1 Repair timber flooring and floor structure F2 Repair concrete floor
- F3 Remove concrete topping from concrete slab and repair slab F4 Repair timber skirtings and replace
- deteriorated timber skirtings with new TME
- F5 New timber skirtings TME
- Checked Auth. Proj. Dir Proj. Arch Drawn CMJ CMJ SW JF Job No. 1:100 160481 A1

NSW Nominated Architects:
Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015

PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2

F6 Remove carpet

DOORS

architraves

architraves TME

F7 Repair flagstone floor

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

HISTÖRIC CORE NORTH - FEMALE FACTORY/ ASYLUM PRECINCT **BUILDING C104 + C104a - DEMOLITION GROUND** PLAN

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

H9 Reconstruct verandah to original detail

ADAPTATION WORKS

original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall

www.tkda.com.au

+61 2 9281 4399

F +61 2 9281 4337

including new/repaired sandstone edging

H10 Reconstruct 1880s doorway and door

H12 Remove block-out panel from window

H19 Construct new verandah extension

H13 New glazed door

H16 New doorway

H17 Lock doors shut

H18 Re-swing door

Tanner Kibble Denton Architects Pty Ltd

PO Box 660 Darlinghurst NSW 1300 Australia

H15 New glazed partition

H20 Install new timber stair

Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

H14 New lightweight partition

H11 New glazed entry door with awning over

PROJECT MANAGER


T +61 2 9380 8816

Level 1, 171 William St

Darlinghurst, NSW, 2010

Aver

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.



- ROOFWORK
- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting,
- ridge and hip cappings with new TME A5 Replace deteriorated lead flashings, ridge and
- A6 Remove redundant and intrusive services penetrations

**INS** 

- hip cappings with new TME
- linings,fretwork and mouldings

A9 Repair roof dormer - structure, cladding and

- A8 Repair roof lantern structure, louvres, cladding and windows
- A10 Repair galvanised steel vents

windows

- A11 Prime and repaint all new and previously painted timber elements TME or original
- A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and downpipes and connect to stormwater drains
- A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK

Key

- B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and redundant services and patch repair
- B3 Rub back areas of minor surface damage
- B4 Repair unsound stone with mortar patch
- B5 Replace damaged stone with stone indent B6 Replace missing, loose and non-matching pointing with new TME
- B7 Remove infill/door and reconstruct stonework
- B8 Remove infill and reconstruct opening in
- stonework to original detail B9 Remove doorway and reconstruct window to original detail
- B10 Repair all cast iron wall vents B11 Repair sandstone flagging to verandah

verandah floor

- replacing deteriorated stones with new TME
- B12 Check over all brickwork and repair as necessary
  - B13 Repair render finishes
  - B14 Demolish concrete floor slabs and re-instate
- C1 Reconstruct original door and window joinery to original detail

WINDOWS AND DOORS

- C2 Repair damaged door and window joinery to original detail
- C3 Make all windows and doors operable C4 Prime and repaint all new and previously painted timber elements TME or original
- C7 Lock doors shut
- C5 Replace damaged glazing and putty C6 Repair and repaint cast iron window grilles

### INTERNAL CONSERVATION WORKS LEGEND: WALLS

- D1 Repair plaster finish
- D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish
- D3 Remove plasterboard wall linings and associated fixings
- **CEILINGS**
- E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling E3 Install new ripple iron ceiling TME
- E4 Install new timber board ceiling TME E5 Remove FC ceiling

E6 Remove PB ceiling

- **FLOORS** F1 Repair timber flooring and floor structure
- F2 Repair concrete floor F3 Remove concrete topping from concrete slab and repair slab
- F4 Repair timber skirtings and replace deteriorated timber skirtings with new TME F5 New timber skirtings TME
- Checked Auth. Proj. Dir Proj. Arch Drawn JF

1:100 160481 A1 NSW Nominated Architects:

Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015

HISTORIC CORE NORTH - FEMALE FACTORY/ ASYLUM PRECINCT BUILDING C104 + C104a - PROPOSED GROUND FLOOR PLAN

SHO

NOTE:

(for) Delegate Heritage Council

NEW FIT-OUT INDICATIVE ONLY

H10 Reconstruct 1880s doorway and door

H11 New glazed entry door with awning over

H12 Remove block-out panel from window

H19 Construct new verandah extension

H13 New glazed door

H16 New doorway

H18 Re-swing door

Tanner Kibble Denton Architects Pty Ltd

+61 2 9281 4399

F +61 2 9281 4337

www.tkda.com.au

PO Box 660 Darlinghurst NSW 1300 Australia

H17 Lock doors shut

H15 New glazed partition

H20 Install new timber stair

Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

H14 New lightweight partition

including new/repaired sandstone edging

T +61 2 9216 5700 PO BOX R220 Royal Exchange NSW 2010

Infrastructure NSW

CLIENT

Darlinghurst, NSW, 2010

PROJECT MANAGER

T +61 2 9380 8816

Level 1, 171 William St

Aver

**Abbreviations EXISTING** (N) PROPOSED

Rev Date Description P1 29.10.19 Preliminary Draft P2 18.11.19 For Client Review P3 25.11.19 Final Draft A 29.11.19 S60 Application

SW CMJ SW CMJ CMJ SW SW SW Job No.

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.

F6 Remove carpet

DOORS

architraves

architraves TME

F7 Repair flagstone floor

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

AR.S60.2002

PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

H9 Reconstruct verandah to original detail

ADAPTATION WORKS


original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall



ROOFWORK

CLIENT

T +61 2 9216 5700

Royal Exchange NSW 2010

PO BOX R220

Infrastructure NSW

- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting,
- A5 Replace deteriorated lead flashings, ridge and
- hip cappings with new TME
- linings, fretwork and mouldings
- A8 Repair roof lantern structure, louvres,
- cladding and windows A9 Repair roof dormer - structure, cladding and windows
- A10 Repair galvanised steel vents
- ridge and hip cappings with new TME A11 Prime and repaint all new and previously painted timber elements TME or original
- A6 Remove redundant and intrusive services
- penetrations
  - A12 Replace deteriorated rainwater goods with

T +61 2 9380 8816

Level 1, 171 William St

PROJECT MANAGER

- new TME gutters, rainwater heads and downpipes and connect to stormwater drains
- A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK
  - B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and
  - redundant services and patch repair B3 Rub back areas of minor surface damage
  - B4 Repair unsound stone with mortar patch
  - B5 Replace damaged stone with stone indent
  - B6 Replace missing, loose and non-matching pointing with new TME
  - B7 Remove infill/door and reconstruct stonework
- B8 Remove infill and reconstruct opening in
- original detail B10 Repair all cast iron wall vents
- replacing deteriorated stones with new TME B12 Check over all brickwork and repair as necessary
- B13 Repair render finishes
  - B14 Demolish concrete floor slabs and re-instate verandah floor

**Abbreviations** 

(E) EXISTING

(N) PROPOSED

- stonework to original detail B9 Remove doorway and reconstruct window to
- to original detail
- original detail B11 Repair sandstone flagging to verandah
  - painted timber elements TME or original
    - C5 Replace damaged glazing and putty C7 Lock doors shut
- WINDOWS AND DOORS
- C1 Reconstruct original door and window joinery
- C2 Repair damaged door and window joinery to
- C3 Make all windows and doors operable C4 Prime and repaint all new and previously
  - C6 Repair and repaint cast iron window grilles E3 Install new ripple iron ceiling TME

Rev Date

P1 29.10.19

P2 25.11.19

A 29.11.19

- INTERNAL CONSERVATION WORKS LEGEND:
- WALLS D1 Repair plaster finish
- D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish
- D3 Remove plasterboard wall linings and associated fixings
- CEILINGS
- E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling

Description

Final Draft

Preliminary Draft

S60 Application

- E4 Install new timber board ceiling TME E5 Remove FC ceiling
- E6 Remove PB ceiling
- **FLOORS** F1 Repair timber flooring and floor structure
- F2 Repair concrete floor F3 Remove concrete topping from concrete slab and repair slab F4 Repair timber skirtings and replace
- deteriorated timber skirtings with new TME
- F5 New timber skirtings TME

### Checked Auth. Proj. Dir Proj. Arch Drawn SW CMJ SW CMJ JF Job No. 1:100 160481 A1

HERITAGE REPAIRS - TRANCHE 2 NSW Nominated Architects: Robert Denton Alex Kibble Registration No. 5782
Registration No. 6015

F6 Remove carpet

DOORS

architraves

architraves TME

F7 Repair flagstone floor

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

HISTÖRIC CORE NORTH - FEMALE FACTORY/ ASYLUM PRECINCT BUILDING C104 + C104a - DEMOLITION FIRST FLOOR PLAN

PARRAMATTA NORTH GROWTH CENTRE

including new/repaired sandstone edging H10 Reconstruct 1880s doorway and door H11 New glazed entry door with awning over H12 Remove block-out panel from window

the decision notice

SHO

(for) Delegate Heritage Council

These plans should be read in conjunction with

H2 Remove internal fit-out H3 New steel-framed stair and mezzanine H13 New glazed door H14 New lightweight partition

H4 New lift for equitable access H5 New workstations and loose furniture H15 New glazed partition

H6 New electrical, communications, fire H16 New doorway detection and mechanical services H17 Lock doors shut

H7 New sanitary facilities H8 Create new opening in wall

H18 Re-swing door H19 Construct new verandah extension H9 Reconstruct verandah to original detail H20 Install new timber stair

+61 2 9281 4399

Tanner Kibble Denton Architects Pty Ltd

PO Box 660 Darlinghurst NSW 1300 Australia

Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

F +61 2 9281 4337 www.tkda.com.au



Aver

Darlinghurst, NSW, 2010

Key

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.


AR.S60.2003

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

ADAPTATION WORKS

original fabric



ROOFWORK

CLIENT

T +61 2 9216 5700

Infrastructure NSW

- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details
- A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting, ridge and hip cappings with new TME
- hip cappings with new TME
- A6 Remove redundant and intrusive services penetrations
- A5 Replace deteriorated lead flashings, ridge and
- A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK linings, fretwork and mouldings
- cladding and windows
- A10 Repair galvanised steel vents
- A11 Prime and repaint all new and previously
- A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and downpipes and connect to stormwater drains

windows

- A8 Repair roof lantern structure, louvres,
- painted timber elements TME or original

Key

- B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and
- A9 Repair roof dormer structure, cladding and B3 Rub back areas of minor surface damage
  - B4 Repair unsound stone with mortar patch
  - B5 Replace damaged stone with stone indent
  - B6 Replace missing, loose and non-matching pointing with new TME
  - B7 Remove infill/door and reconstruct stonework
- B8 Remove infill and reconstruct opening in
- stonework to original detail B9 Remove doorway and reconstruct window to
- original detail redundant services and patch repair B10 Repair all cast iron wall vents
  - B11 Repair sandstone flagging to verandah replacing deteriorated stones with new TME
    - B12 Check over all brickwork and repair as necessary
      - B13 Repair render finishes
      - B14 Demolish concrete floor slabs and re-instate verandah floor

**Abbreviations** 

(E) EXISTING (N) PROPOSED

- C7 Lock doors shut
- WINDOWS AND DOORS
- C1 Reconstruct original door and window joinery to original detail
- C2 Repair damaged door and window joinery to original detail C3 Make all windows and doors operable
- C4 Prime and repaint all new and previously painted timber elements TME or original
  - C6 Repair and repaint cast iron window grilles
  - C5 Replace damaged glazing and putty

## INTERNAL CONSERVATION WORKS LEGEND:

Rev Date

P1 29.10.19

A 29.11.19

- WALLS D1 Repair plaster finish
- D2 Apply new plaster finish TME
- D3 Remove wall tiles and repair wall finish D3 Remove plasterboard wall linings and

associated fixings

- **CEILINGS**
- E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling

Description

Preliminary Draft

S60 Application

Final Draft

E3 Install new ripple iron ceiling TME

- E4 Install new timber board ceiling TME
- E5 Remove FC ceiling E6 Remove PB ceiling
- **FLOORS** F1 Repair timber flooring and floor structure
- F2 Repair concrete floor F3 Remove concrete topping from concrete slab
- and repair slab F4 Repair timber skirtings and replace
- deteriorated timber skirtings with new TME
- F5 New timber skirtings TME
- Checked Auth. Proj. Dir Proj. Arch Drawn CMJ CMJ CMJ SW JF

CMJ Job No. 1:100 160481 A1

NSW Nominated Architects:
Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

### PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

H9 Reconstruct verandah to original detail

ADAPTATION WORKS

original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall

HISTÖRIC CORE NORTH - FEMALE FACTORY/ ASYLUM PRECINCT BUILDING C104 + C104a - PROPOSED FIRST FLOOR PLAN

Approved by: the Heritage Council of NSW **Delegated Authority** 

These plans should be read in conjunction with

including new/repaired sandstone edging

H10 Reconstruct 1880s doorway and door

H12 Remove block-out panel from window

H19 Construct new verandah extension

H13 New glazed door

H16 New doorway

H17 Lock doors shut

H18 Re-swing door

Tanner Kibble Denton Architects Pty Ltd

+61 2 9281 4399

F +61 2 9281 4337

www.tkda.com.au

PO Box 660 Darlinghurst NSW 1300 Australia

H15 New glazed partition

H20 Install new timber stair

Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

H14 New lightweight partition

H11 New glazed entry door with awning over

On: 04/05/2020

the decision notice

SHE

(for) Delegate Heritage Council

PO BOX R220 Level 1, 171 William St Royal Exchange NSW 2010 Darlinghurst, NSW, 2010 INS



PROJECT MANAGER

T +61 2 9380 8816

Aver

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.


F6 Remove carpet

DOORS

architraves

architraves TME

F7 Repair flagstone floor



# NOTE:

BUILDING C104 ROOF REPAIR WORKS HAS S57(2) APPROVAL

including new/repaired sandstone edging

H10 Reconstruct 1880s doorway and door

H12 Remove block-out panel from window

H19 Construct new verandah extension

H13 New glazed door

H16 New doorway

H17 Lock doors shut

H18 Re-swing door

Tanner Kibble Denton Architects Pty Ltd

+61 2 9281 4399

F +61 2 9281 4337

www.tkda.com.au

PO Box 660 Darlinghurst NSW 1300 Australia

H15 New glazed partition

H20 Install new timber stair

Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

H14 New lightweight partition

H11 New glazed entry door with awning over

# **EXTERNAL CONSERVATION WORKS LEGEND:**

ROOFWORK

CLIENT

T +61 2 9216 5700

Royal Exchange NSW 2010

PO BOX R220

Infrastructure NSW

- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting,
- ridge and hip cappings with new TME A5 Replace deteriorated lead flashings, ridge and
- penetrations

**INS** 

- hip cappings with new TME A6 Remove redundant and intrusive services
- A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK linings, fretwork and mouldings
- A8 Repair roof lantern structure, louvres,
- cladding and windows A9 Repair roof dormer - structure, cladding and
- A10 Repair galvanised steel vents
- A11 Prime and repaint all new and previously
- downpipes and connect to stormwater drains
- windows
- painted timber elements TME or original
- A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and

Key

- B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and
- redundant services and patch repair B3 Rub back areas of minor surface damage
- B4 Repair unsound stone with mortar patch
- B5 Replace damaged stone with stone indent B6 Replace missing, loose and non-matching pointing with new TME
- B7 Remove infill/door and reconstruct stonework
- stonework to original detail B9 Remove doorway and reconstruct window to
- original detail B10 Repair all cast iron wall vents

B8 Remove infill and reconstruct opening in

- B11 Repair sandstone flagging to verandah replacing deteriorated stones with new TME
- B12 Check over all brickwork and repair as necessary

verandah floor

- B13 Repair render finishes B14 Demolish concrete floor slabs and re-instate

**Abbreviations** 

(E) EXISTING

(N) PROPOSED

- WINDOWS AND DOORS
- to original detail
- original detail
- C4 Prime and repaint all new and previously painted timber elements TME or original
- C6 Repair and repaint cast iron window grilles
- C1 Reconstruct original door and window joinery
- C3 Make all windows and doors operable

- C2 Repair damaged door and window joinery to
- C5 Replace damaged glazing and putty
- C7 Lock doors shut

Rev Date

P1 29.10.19

P2 25.11.19

A 29.11.19

- INTERNAL CONSERVATION WORKS LEGEND:
  - WALLS D1 Repair plaster finish
  - D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish
  - D3 Remove plasterboard wall linings and associated fixings
  - CEILINGS

Description

Final Draft

Preliminary Draft

S60 Application

- E1 Repair ripple iron ceiling
- E2 Repair timber boarded ceiling E3 Install new ripple iron ceiling TME
- E4 Install new timber board ceiling TME E5 Remove FC ceiling
- E6 Remove PB ceiling **FLOORS**
- F1 Repair timber flooring and floor structure F2 Repair concrete floor
- F3 Remove concrete topping from concrete slab and repair slab F4 Repair timber skirtings and replace
- deteriorated timber skirtings with new TME F5 New timber skirtings TME

SW CMJ SW CMJ

Checked Auth. Proj. Dir Proj. Arch Drawn JF Job No. 1:100 160481 A1 NSW Nominated Architects:
Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015

F6 Remove carpet

DOORS

architraves

architraves TME

F7 Repair flagstone floor

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

H9 Reconstruct verandah to original detail

ADAPTATION WORKS

original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall

HISTÖRIC CORE NORTH - FEMALE FACTORY/ ASYLUM PRECINCT BUILDING C104 + C104a - DEMOLITION ROOF PLAN




Aver

T +61 2 9380 8816

Level 1, 171 William St

PROJECT MANAGER

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.



- ROOFWORK
- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting,
- ridge and hip cappings with new TME A5 Replace deteriorated lead flashings, ridge and
- hip cappings with new TME A6 Remove redundant and intrusive services penetrations
- linings, fretwork and mouldings
- A8 Repair roof lantern structure, louvres,
- cladding and windows A9 Repair roof dormer - structure, cladding and windows
- A10 Repair galvanised steel vents
- A11 Prime and repaint all new and previously painted timber elements TME or original
- A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and

downpipes and connect to stormwater drains

- B3 Rub back areas of minor surface damage

Key

- B7 Remove infill/door and reconstruct stonework
- A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK
  - B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and
  - redundant services and patch repair
  - B4 Repair unsound stone with mortar patch
  - B5 Replace damaged stone with stone indent
  - B6 Replace missing, loose and non-matching pointing with new TME
- B8 Remove infill and reconstruct opening in stonework to original detail
- B9 Remove doorway and reconstruct window to original detail B10 Repair all cast iron wall vents
- B11 Repair sandstone flagging to verandah
- necessary

verandah floor

- B13 Repair render finishes B14 Demolish concrete floor slabs and re-instate
- replacing deteriorated stones with new TME B12 Check over all brickwork and repair as

**Abbreviations** 

(E) EXISTING (N) PROPOSED

- - C7 Lock doors shut

- WINDOWS AND DOORS
- C2 Repair damaged door and window joinery to
- original detail

- C4 Prime and repaint all new and previously

- C6 Repair and repaint cast iron window grilles

- painted timber elements TME or original

- C1 Reconstruct original door and window joinery to original detail
- C3 Make all windows and doors operable
- C5 Replace damaged glazing and putty
  - E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling E3 Install new ripple iron ceiling TME

Rev Date

P1 29.10.19

P2 25.11.19

A 29.11.19

WALLS

associated fixings

Description

Preliminary Draft

S60 Application

Final Draft

CEILINGS

- INTERNAL CONSERVATION WORKS LEGEND:
- E4 Install new timber board ceiling TME D1 Repair plaster finish E5 Remove FC ceiling E6 Remove PB ceiling
- D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish
- D3 Remove plasterboard wall linings and **FLOORS** F1 Repair timber flooring and floor structure F2 Repair concrete floor
  - F3 Remove concrete topping from concrete slab and repair slab

SW SW

- F4 Repair timber skirtings and replace deteriorated timber skirtings with new TME F5 New timber skirtings TME
- Checked Auth. Proj. Dir Proj. Arch Drawn CMJ CMJ CMJ SW JF

CMJ Job No. 160481 A1 1:100

NSW Nominated Architects:
Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015

### original fabric F8 Construct raised timber floor and ramps (1:25) above reinstated verandah floor H2 Remove internal fit-out H3 New steel-framed stair and mezzanine H4 New lift for equitable access

- DOORS
- G1 Repair timber joinery door, frame and architraves

F6 Remove carpet

F7 Repair flagstone floor

- H5 New workstations and loose furniture H6 New electrical, communications, fire G2 New timber joinery door, frame and architraves TME
  - detection and mechanical services
    - H7 New sanitary facilities H8 Create new opening in wall

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

ADAPTATION WORKS

H9 Reconstruct verandah to original detail

PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2

HISTÖRIC CORE NORTH - FEMALE FACTORY/ ASYLUM PRECINCT BUILDING C104 + C104a - PROPOSED ROOF PLAN

WORKS HAS S57(2) APPROVAL

including new/repaired sandstone edging

H10 Reconstruct 1880s doorway and door

H12 Remove block-out panel from window

H19 Construct new verandah extension

H13 New glazed door

H16 New doorway

H17 Lock doors shut

H18 Re-swing door

Tanner Kibble Denton Architects Pty Ltd

+61 2 9281 4399

F +61 2 9281 4337

www.tkda.com.au

PO Box 660 Darlinghurst NSW 1300 Australia

H15 New glazed partition

H20 Install new timber stair

Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

H14 New lightweight partition

H11 New glazed entry door with awning over



Infrastructure NSW

CLIENT

T +61 2 9216 5700

PO BOX R220

T +61 2 9380 8816


Level 1, 171 William St

Darlinghurst, NSW, 2010

PROJECT MANAGER

Aver

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.






**INS** 

PROPOSED NORTH ELEVATIONS

AR.S60.2008

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.





3 PROPOSED EAST ELEVATION

# **EXTERNAL CONSERVATION WORKS LEGEND:**

ROOFWORK

CLIENT

T +61 2 9216 5700

Royal Exchange NSW 2010

PO BOX R220

Infrastructure NSW

- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting, ridge and hip cappings with new TME

**INS** 

- penetrations
- A5 Replace deteriorated lead flashings, ridge and hip cappings with new TME
- A6 Remove redundant and intrusive services
- A9 Repair roof dormer structure, cladding and windows A10 Repair galvanised steel vents

linings, fretwork and mouldings

cladding and windows

A8 Repair roof lantern - structure, louvres,

- A11 Prime and repaint all new and previously painted timber elements TME or original
- downpipes and connect to stormwater drains

A7 Repair timber fascias, barge boards, eaves

- new TME gutters, rainwater heads and
- A12 Replace deteriorated rainwater goods with
- B3 Rub back areas of minor surface damage B4 Repair unsound stone with mortar patch

redundant services and patch repair

B2 Remove corroded embedments and

STONEWORK AND BRICKWORK

- B5 Replace damaged stone with stone indent
- B6 Replace missing, loose and non-matching pointing with new TME

- B7 Remove infill/door and reconstruct stonework
- stonework to original detail B1 Repair cracked stonework to engineer's detail B9 Remove doorway and reconstruct window to
  - original detail B10 Repair all cast iron wall vents

B8 Remove infill and reconstruct opening in

- B11 Repair sandstone flagging to verandah replacing deteriorated stones with new TME
- B12 Check over all brickwork and repair as necessary
- B13 Repair render finishes
- B14 Demolish concrete floor slabs and re-instate verandah floor

Abbreviations

**EXISTING** 

(N) PROPOSED

WINDOWS AND DOORS

to original detail

original detail

- C7 Lock doors shut

C3 Make all windows and doors operable

C4 Prime and repaint all new and previously

painted timber elements TME or original

C1 Reconstruct original door and window joinery

E1 Repair ripple iron ceiling C5 Replace damaged glazing and putty C6 Repair and repaint cast iron window grilles

Rev Date

P1 29.10.19

P2 25.11.19

A 29.11.19

- E3 Install new ripple iron ceiling TME
- D2 Apply new plaster finish TME C2 Repair damaged door and window joinery to

WALLS

D3 Remove wall tiles and repair wall finish D3 Remove plasterboard wall linings and associated fixings

D1 Repair plaster finish

INTERNAL CONSERVATION WORKS LEGEND:

CEILINGS

Description

Final Draft

Preliminary Draft

S60 Application

- E2 Repair timber boarded ceiling
- E4 Install new timber board ceiling TME
- E5 Remove FC ceiling E6 Remove PB ceiling
- **FLOORS**
- F1 Repair timber flooring and floor structure F2 Repair concrete floor
- F3 Remove concrete topping from concrete slab and repair slab
- F4 Repair timber skirtings and replace deteriorated timber skirtings with new TME
- F5 New timber skirtings TME Checked Auth. Proj. Dir Proj. Arch Drawn

CMJ CMJ CMJ SW MDB,JF Job No. CMJ 1:100 160481 A1

NSW Nominated Architects:
Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015

PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2 Drawing Title HISTÖRIC CORE NORTH - FEMALE FACTORY ASYLUM PRECINCT

F8 Construct raised timber floor and ramps


G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

PROPOSED EAST ELEVATION AND SECTION

\_E5 DEMOLITION SECTION
1:100



F6 Remove carpet

DOORS

architraves

architraves TME

F7 Repair flagstone floor

HERITAGE ACT 1977 **APPLICATION UNDER SECTION 60 Application No:** S60/2019/227 Approved by: the Heritage Council of NSW **Delegated Authority** On: 04/05/2020 These plans should be read in conjunction with the decision notice SHO (for) Delegate Heritage Council

# NOTE:

BUILDING C104 ROOF REPAIR WORKS HAS S57(2) APPROVAL

including new/repaired sandstone edging

- H10 Reconstruct 1880s doorway and door H11 New glazed entry door with awning over
- H12 Remove block-out panel from window
- H13 New glazed door
- H14 New lightweight partition

- H15 New glazed partition
- H16 New doorway

Tanner Kibble Denton Architects Pty Ltd

+61 2 9281 4399

F +61 2 9281 4337

PO Box 660 Darlinghurst NSW 1300 Australia

Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

- H17 Lock doors shut
- H18 Re-swing door
- H19 Construct new verandah extension H20 Install new timber stair

www.tkda.com.au



Darlinghurst, NSW, 2010


PROJECT MANAGER

T +61 2 9380 8816

Level 1, 171 William St

Aver

Key



AR.S60.2009

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

H9 Reconstruct verandah to original detail

ADAPTATION WORKS


original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall



- ROOFWORK
- A1 Provide safe access for inspection of roof framing
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with new TME
- A4 Replace deteriorated steel roof sheeting, ridge and hip cappings with new TME
- A5 Replace deteriorated lead flashings, ridge and

Infrastructure NSW

T +61 2 9216 5700

Royal Exchange NSW 2010

PO BOX R220

- hip cappings with new TME A6 Remove redundant and intrusive services
- penetrations
- A7 Repair timber fascias, barge boards, eaves linings,fretwork and mouldings A8 Repair roof lantern - structure, louvres,
- cladding and windows A9 Repair roof dormer - structure, cladding and windows
- A10 Repair galvanised steel vents A11 Prime and repaint all new and previously painted timber elements TME or original
- A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and downpipes and connect to stormwater drains
- STONEWORK AND BRICKWORK

General Notes

- B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and redundant services and patch repair
- B3 Rub back areas of minor surface damage B4 Repair unsound stone with mortar patch
- B5 Replace damaged stone with stone indent B6 Replace missing, loose and non-matching pointing with new TME
- B7 Remove infill/door and reconstruct stonework TME
- B8 Remove infill and reconstruct opening in
- stonework to original detail B9 Remove doorway and reconstruct window to original detail
- B11 Repair sandstone flagging to verandah replacing deteriorated stones with new TME

  C4 Prime and repaint all new and previously B12 Check over all brickwork and repair as
- necessarv B13 Repair render finishes

B10 Repair all cast iron wall vents

C7 Lock doors shut

# WINDOWS AND DOORS

C1 Reconstruct original door and window joinery to original detail C2 Repair damaged door and window joinery to

painted timber elements TME or original

- original detail C3 Make all windows and doors operable
- C5 Replace damaged glazing and putty
- B14 Demolish concrete floor slabs and re-instate C6 Repair and repaint cast iron window grilles

## INTERNAL CONSERVATION WORKS LEGEND:

- WALLS
- D1 Repair plaster finish
- D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish D3 Remove plasterboard wall linings and associated fixings
- CEILINGS
- E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling
- E3 Install new ripple iron ceiling TME
- E4 Install new timber board ceiling TME E5 Remove FC ceiling
- E6 Remove PB ceiling **FLOORS**
- F1 Repair timber flooring and floor structure
- F2 Repair concrete floor F3 Remove concrete topping from concrete slab
- and repair slab F4 Repair timber skirtings and replace
- deteriorated timber skirtings with new TME F5 New timber skirtings TME

## **ADAPTATION WORKS LEGEND:**

- F6 Remove carpet ADAPTATION WORKS H1 Demolish intrusive additions and repair
- F7 Repair flagstone floor F8 Construct raised timber floor and ramps original fabric

Project

- H2 Remove internal fit-out (1:25) above reinstated verandah floor
  - H3 New steel-framed stair and mezzanine
- H4 New lift for equitable access G1 Repair timber joinery door, frame and
  - H5 New workstations and loose furniture H6 New electrical, communications, fire
  - detection and mechanical services H7 New sanitary facilities
  - H8 Create new opening in wall H9 Reconstruct verandah to original detail
- including new/repaired sandstone edging H10 Reconstruct 1880s doorway and door

These plans should be read in conjunction with

- H11 New glazed entry door with awning over H12 Remove block-out panel from window
- H13 New glazed door
- H14 New lightweight partition H15 New glazed partition

On: 04/05/2020

SHO

(for) Delegate Heritage Council

the decision notice

- H16 New doorway
- H17 Lock doors shut H18 Re-swing door H19 Construct new verandah extension

H20 Install new timber stair Tanner Kibble Denton Architects Pty Ltd PO Box 660 Darlinghurst NSW 1300 Australia Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

T +61 2 9281 4399

F +61 2 9281 4337

www.tkda.com.au

Level 1, 171 William St

Aver

Darlinghurst, NSW, 2010

T +61 2 9380 8816

PROJECT MANAGER

(E) EXISTING (N) PROPOSED

Abbreviations

Rev Date A 17.02.20 S60 Revision

Description

Checked Auth. Proj. Dir CMJ SW MDB,JF,FF 160481 A1 1:100

NSW Nominated Architects: Robert Denton Registration No. 5782 Alex Kibble Registration No. 6015

ASYLUM PRECINCT **BUILDING C107 + C109 - DEMOLITION GROUND** FLOOR PLAN Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.

G2 New timber joinery door, frame and

DOORS

architraves


architraves TME

AR.S60.4000

PARRAMATTA NORTH GROWTH CENTRE

**HERITAGE REPAIRS - TRANCHE 2** 

HISTORIC CORE NORTH - FEMALE FACTORY/



- ROOFWORK
- A1 Provide safe access for inspection of roof framing
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with
- new TME A4 Replace deteriorated steel roof sheeting,
- ridge and hip cappings with new TME A5 Replace deteriorated lead flashings, ridge and

- hip cappings with new TME A6 Remove redundant and intrusive services
- penetrations

Infrastructure NSW

T +61 2 9216 5700

PO BOX R220

- linings, fretwork and mouldings
- cladding and windows
- A10 Repair galvanised steel vents
- painted timber elements TME or original

PROJECT MANAGER

Aver

- A7 Repair timber fascias, barge boards, eaves
- A8 Repair roof lantern structure, louvres,

General Notes

- A9 Repair roof dormer structure, cladding and windows
- A11 Prime and repaint all new and previously
- A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and downpipes and connect to stormwater drains
- STONEWORK AND BRICKWORK
  - B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and redundant services and patch repair
- B3 Rub back areas of minor surface damage B4 Repair unsound stone with mortar patch
- B5 Replace damaged stone with stone indent B6 Replace missing, loose and non-matching
- pointing with new TME
- B7 Remove infill/door and reconstruct stonework TME
- B8 Remove infill and reconstruct opening in
- stonework to original detail B9 Remove doorway and reconstruct window to original detail
- B10 Repair all cast iron wall vents B11 Repair sandstone flagging to verandah
- necessary B13 Repair render finishes
  - verandah floor
- replacing deteriorated stones with new TME C4 Prime and repaint all new and previously B12 Check over all brickwork and repair as
  - B14 Demolish concrete floor slabs and re-instate C6 Repair and repaint cast iron window grilles C7 Lock doors shut
- WINDOWS AND DOORS
- C1 Reconstruct original door and window joinery to original detail
- C2 Repair damaged door and window joinery to original detail C3 Make all windows and doors operable
- painted timber elements TME or original C5 Replace damaged glazing and putty

## INTERNAL CONSERVATION WORKS LEGEND:

- WALLS
- D1 Repair plaster finish
- D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish D3 Remove plasterboard wall linings and associated fixings
- CEILINGS
- E1 Repair ripple iron ceiling
- E2 Repair timber boarded ceiling E3 Install new ripple iron ceiling TME
- E6 Remove PB ceiling **FLOORS**

E5 Remove FC ceiling

F1 Repair timber flooring and floor structure F2 Repair concrete floor

E4 Install new timber board ceiling TME

- F3 Remove concrete topping from concrete slab and repair slab
- F4 Repair timber skirtings and replace deteriorated timber skirtings with new TME F5 New timber skirtings TME

Checked Auth.

SW

SW

CMJ CMJ

CMJ

## ADAPTATION WORKS LEGEND:

- ADAPTATION WORKS
- F7 Repair flagstone floor H1 Demolish intrusive additions and repair F8 Construct raised timber floor and ramps original fabric
- H2 Remove internal fit-out (1:25) above reinstated verandah floor

  - H3 New steel-framed stair and mezzanine H4 New lift for equitable access
  - H5 New workstations and loose furniture H6 New electrical, communications, fire
  - detection and mechanical services
  - H7 New sanitary facilities
  - H18 Re-swing door H8 Create new opening in wall H19 Construct new verandah extension H9 Reconstruct verandah to original detail H20 Install new timber stair

T +61 2 9281 4399 F +61 2 9281 4337 www.tkda.com.au

These plans should be read in conjunction with

including new/repaired sandstone edging

H10 Reconstruct 1880s doorway and door

H11 New glazed entry door with awning over

H12 Remove block-out panel from window

the decision notice

SHO

H13 New glazed door

H16 New doorway

Tanner Kibble Denton Architects Pty Ltd

PO Box 660 Darlinghurst NSW 1300 Australia

Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia

H17 Lock doors shut

H14 New lightweight partition

H15 New glazed partition

(for) Delegate Heritage Council

T +61 2 9380 8816 Level 1, 171 William St Royal Exchange NSW 2010 Darlinghurst, NSW, 2010



Abbreviations (E) EXISTING (N) PROPOSED Rev Date Description P1 18.11.19 Preliminary Draft P2 25.11.19 Final Draft 29.11.19 S60 Application 17.02.20 S60 Revision

Proj. Dir Proj. Arch Drawn MDB,JF,FF CMJ SW 160481 A1 1:100

NSW Nominated Architects: Robert Denton Registration No. 5782 Alex Kibble Registration No. 6015

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.

PARRAMATTA NORTH GROWTH CENTRE **HERITAGE REPAIRS - TRANCHE 2** Drawing Title HISTORIC CORE NORTH - FEMALE FACTORY/

**DOORS** 

architraves

architraves TME


F6 Remove carpet


G1 Repair timber joinery door, frame and


Project

G2 New timber joinery door, frame and

**ASYLUM PRECINCT BUILDING C107 + C109 - PROPOSED GROUND** FLOOR PLAN







- ROOFWORK
- A1 Provide safe access for inspection of roof
- A3 Replace deteriorated Welsh roof slates with
- A5 Replace deteriorated lead flashings, ridge and hip cappings with new TME
- A6 Remove redundant and intrusive services penetrations
- linings, fretwork and mouldings A8 Repair roof lantern - structure, louvres,
- cladding and windows A2 Repair roof framing to engineer's details A9 Repair roof dormer - structure, cladding and windows

Aver

- A10 Repair galvanised steel vents A4 Replace deteriorated steel roof sheeting, ridge and hip cappings with new TME A11 Prime and repaint all new and previously
  - painted timber elements TME or original

PROJECT MANAGER

T +61 2 9380 8816

A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and

downpipes and connect to stormwater drains

- A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK B1 Repair cracked stonework to engineer's detail
  - B2 Remove corroded embedments and redundant services and patch repair
  - B3 Rub back areas of minor surface damage B4 Repair unsound stone with mortar patch
    - B5 Replace damaged stone with stone indent
      - B6 Replace missing, loose and non-matching pointing with new TME

Application No: S60/2019/227

- B7 Remove infill/door and reconstruct stonework

HERITAGE ACT 1977 APPLICATION UNDER SECTION 60

- B8 Remove infill and reconstruct opening in
- stonework to original detail B9 Remove doorway and reconstruct window to
- original detail B10 Repair all cast iron wall vents
- B11 Repair sandstone flagging to verandah replacing deteriorated stones with new TME B12 Check over all brickwork and repair as
- necessary
- B13 Repair render finishes

verandah floor

- B14 Demolish concrete floor slabs and re-instate
- WINDOWS AND DOORS

C7 Lock doors shut

- C1 Reconstruct original door and window joinery
- C2 Repair damaged door and window joinery to
- original detail
- C4 Prime and repaint all new and previously painted timber elements TME or original
- C6 Repair and repaint cast iron window grilles
- to original detail
- C3 Make all windows and doors operable
- C5 Replace damaged glazing and putty
- D3 Remove wall tiles and repair wall finish D3 Remove plasterboard wall linings and associated fixings

D1 Repair plaster finish

WALLS

**CEILINGS** 

D2 Apply new plaster finish TME

INTERNAL CONSERVATION WORKS LEGEND:

E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling

Description

E3 Install new ripple iron ceiling TME

- E4 Install new timber board ceiling TME E5 Remove FC ceiling
- E6 Remove PB ceiling

F2 Repair concrete floor

- **FLOORS** F1 Repair timber flooring and floor structure
- F3 Remove concrete topping from concrete slab and repair slab
- F4 Repair timber skirtings and replace deteriorated timber skirtings with new TME
- F5 New timber skirtings TME
- Checked Auth. Proj. Dir Proj. Arch Drawn
  - CMJ MDB,JF Job No. 1:100 160481 A1

NSW Nominated Architects: Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015 ASYLUM PRECINCT

PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2 HISTORIC CORE NORTH - FEMALE FACTORY/

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

H9 Reconstruct verandah to original detail

ADAPTATION WORKS

original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall

**BUILDING C107 + C104 PROPOSED/ DEMOLITION** 

T +61 2 9216 5700 PO BOX R220 Royal Exchange NSW 2010

Infrastructure NSW

CLIENT

INS

Level 1, 171 William St Darlinghurst, NSW, 2010

Approved by: the Heritage Council of NSW **Delegated Authority** On: 04/05/2020 These plans should be read in conjunction with he decision notice

SHO

for) Delegate eritage Council

**EXISTING** (N) PROPOSED

Abbreviations

P1 19.11.19 Preliminary Draft P2 25.11.19 Final Draft A 29.11.19 S60 Application

Rev Date

CMJ CMJ CMJ

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.

F6 Remove carpet

DOORS

architraves

architraves TME

F7 Repair flagstone floor

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

**WEST ELEVATIONS** AR.S60.4003 PO Box 660 Darlinghurst NSW 1300 Australia Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia +61 2 9281 4399 F +61 2 9281 4337 www.tkda.com.au

H13 New glazed door

H16 New doorway

H17 Lock doors shut

H18 Re-swing door

Tanner Kibble Denton Architects Pty Ltd

H15 New glazed partition

H20 Install new timber stair

H14 New lightweight partition


including new/repaired sandstone edging


H10 Reconstruct 1880s doorway and door

H12 Remove block-out panel from window

H19 Construct new verandah extension

H11 New glazed entry door with awning over





- ROOFWORK A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details
- A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting, ridge and hip cappings with new TME
- A6 Remove redundant and intrusive services penetrations

**INS** 

CLIENT

Infrastructure NSW

- hip cappings with new TME
- A5 Replace deteriorated lead flashings, ridge and
- A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK linings, fretwork and mouldings A8 Repair roof lantern - structure, louvres,
- cladding and windows A9 Repair roof dormer - structure, cladding and windows
- A10 Repair galvanised steel vents A11 Prime and repaint all new and previously
- painted timber elements TME or original

Key

A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and downpipes and connect to stormwater drains

PROJECT MANAGER

Aver

- B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and
- redundant services and patch repair B3 Rub back areas of minor surface damage B4 Repair unsound stone with mortar patch
- B5 Replace damaged stone with stone indent B6 Replace missing, loose and non-matching pointing with new TME
- B7 Remove infill/door and reconstruct stonework
- B8 Remove infill and reconstruct opening in
- stonework to original detail B9 Remove doorway and reconstruct window to original detail
- B10 Repair all cast iron wall vents B11 Repair sandstone flagging to verandah replacing deteriorated stones with new TME
- B12 Check over all brickwork and repair as necessary B13 Repair render finishes

**Abbreviations** 

**EXISTING** 

(N) PROPOSED

verandah floor

- B14 Demolish concrete floor slabs and re-instate
- WINDOWS AND DOORS
- C1 Reconstruct original door and window joinery
- original detail C3 Make all windows and doors operable
- C5 Replace damaged glazing and putty
- to original detail C2 Repair damaged door and window joinery to
- C4 Prime and repaint all new and previously painted timber elements TME or original
  - C6 Repair and repaint cast iron window grilles C7 Lock doors shut

## INTERNAL CONSERVATION WORKS LEGEND:

- WALLS D1 Repair plaster finish
- D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish D3 Remove plasterboard wall linings and
- associated fixings **CEILINGS**

Rev Date

P1 22.10.19

P2 25.11.19

A 29.11.19

E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling

Description

Final Draft

Preliminary Draft

S60 Application

E3 Install new ripple iron ceiling TME

- E4 Install new timber board ceiling TME E5 Remove FC ceiling
- E6 Remove PB ceiling **FLOORS** F1 Repair timber flooring and floor structure
- F2 Repair concrete floor F3 Remove concrete topping from concrete slab and repair slab
- F4 Repair timber skirtings and replace deteriorated timber skirtings with new TME F5 New timber skirtings TME

SW

Checked Auth. Proj. Dir Proj. Arch Drawn CMJ CMJ CMJ MDB,JF 160481 A1 1:100

### NSW Nominated Architects: Robert Denton Registration No. 5782 Alex Kibble Registration No. 6015 Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.

F6 Remove carpet

DOORS

architraves

architraves TME

F7 Repair flagstone floor

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

H9 Reconstruct verandah to original detail

ADAPTATION WORKS

original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall

HISTORIC CORE NORTH - FEMALE FACTORY/ ASYLUM PRECINCT **BUILDING C111 - DEMOLITION/PROPOSED GROUND & FIRST FLOOR PLAN** 

including new/repaired sandstone edging H10 Reconstruct 1880s doorway and door H11 New glazed entry door with awning over H12 Remove block-out panel from window

HERITAGE ACT 1977

**APPLICATION UNDER SECTION 60** 

Delegated Authority

Approved by: the Heritage Council of NSW

These plans should be read in conjunction with

**Application No:** S60/2019/227

On: 04/05/2020

(for) Delegate Heritage Council

the decision notice

H13 New glazed door

- H14 New lightweight partition

- H15 New glazed partition

Tanner Kibble Denton Architects Pty Ltd

+61 2 9281 4399

PO Box 660 Darlinghurst NSW 1300 Australia

Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia


- H16 New doorway H17 Lock doors shut H18 Re-swing door
- H19 Construct new verandah extension H20 Install new timber stair

F +61 2 9281 4337 www.tkda.com.au



T +61 2 9216 5700 T +61 2 9380 8816 PO BOX R220 Level 1, 171 William St Royal Exchange NSW 2010 Darlinghurst, NSW, 2010





- ROOFWORK
- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details
- A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting, ridge and hip cappings with new TME

CLIENT

T +61 2 9216 5700

PO BOX R220

- hip cappings with new TME

- A5 Replace deteriorated lead flashings, ridge and
- A6 Remove redundant and intrusive services penetrations
- A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK linings,fretwork and mouldings
- A8 Repair roof lantern structure, louvres, cladding and windows
- A9 Repair roof dormer structure, cladding and windows A10 Repair galvanised steel vents
- A11 Prime and repaint all new and previously
- painted timber elements TME or original
- A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and downpipes and connect to stormwater drains

Key

- B1 Repair cracked stonework to engineer's detail B2 Remove corroded embedments and
- redundant services and patch repair B3 Rub back areas of minor surface damage
- B4 Repair unsound stone with mortar patch
- B5 Replace damaged stone with stone indent
- B6 Replace missing, loose and non-matching pointing with new TME
- B7 Remove infill/door and reconstruct stonework

- B8 Remove infill and reconstruct opening in stonework to original detail
- B9 Remove doorway and reconstruct window to original detail
- B10 Repair all cast iron wall vents B11 Repair sandstone flagging to verandah
- replacing deteriorated stones with new TME B12 Check over all brickwork and repair as necessary
- B13 Repair render finishes
- B14 Demolish concrete floor slabs and re-instate C6 Repair and repaint cast iron window grilles verandah floor

Abbreviations

(E) EXISTING

(N) PROPOSED

# WINDOWS AND DOORS

- C1 Reconstruct original door and window joinery to original detail
- C2 Repair damaged door and window joinery to original detail C3 Make all windows and doors operable

C4 Prime and repaint all new and previously

- painted timber elements TME or original
- C5 Replace damaged glazing and putty C7 Lock doors shut

## INTERNAL CONSERVATION WORKS LEGEND:

Rev Date

P1 22.10.19

P2 25.11.19

A 29.11.19

- WALLS
- D1 Repair plaster finish
- D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish
- associated fixings
- **CEILINGS** E1 Repair ripple iron ceiling

Description

Final Draft

Preliminary Draft

S60 Application

E2 Repair timber boarded ceiling

E3 Install new ripple iron ceiling TME

- D3 Remove plasterboard wall linings and **FLOORS** 
  - F1 Repair timber flooring and floor structure

Checked Auth. Proj. Dir

F2 Repair concrete floor

E5 Remove FC ceiling

E6 Remove PB ceiling

F3 Remove concrete topping from concrete slab and repair slab F4 Repair timber skirtings and replace

E4 Install new timber board ceiling TME

- F5 New timber skirtings TME

# deteriorated timber skirtings with new TME

SW CMJ SW CMJ SW CMJ Job No.

Proj. Arch Drawn

NSW Nominated Architects:
Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015

SW MDB, JF 1:100 160481 A1

F6 Remove carpet

**DOORS** 

architraves

architraves TME

F7 Repair flagstone floor

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

Project

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

ASYLUM PRECINCT **BUILDING C111 - EXISTING/PROPOSED ROOF** PLAN Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies 
Drawing No.

HISTORIC CORE NORTH - FEMALE FACTORY/

HERITAGE REPAIRS - TRANCHE 2

PARRAMATTA NORTH GROWTH CENTRE

AR.S60.6002

ADAPTATION WORKS LEGEND:

H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

H9 Reconstruct verandah to original detail

ADAPTATION WORKS

original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall

HERITAGE ACT 1977 **APPLICATION UNDER SECTION 60** 

**Application No:** S60/2019/227 Approved by: the Heritage Council of NSW

**Delegated Authority** 

These plans should be read in conjunction with the decision notice



Heritage Council

including new/repaired sandstone edging

H10 Reconstruct 1880s doorway and door

H11 New glazed entry door with awning over H12 Remove block-out panel from window

H13 New glazed door H14 New lightweight partition

H15 New glazed partition

H16 New doorway H17 Lock doors shut

H18 Re-swing door H19 Construct new verandah extension H20 Install new timber stair

Tanner Kibble Denton Architects Pty Ltd PO Box 660 Darlinghurst NSW 1300 Australia Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia +61 2 9281 4399 F +61 2 9281 4337 www.tkda.com.au





Royal Exchange NSW 2010

Infrastructure NSW






T +61 2 9380 8816


Level 1, 171 William St


Darlinghurst, NSW, 2010


Aver

PROJECT MANAGER









H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall

# **EXTERNAL CONSERVATION WORKS LEGEND:**

ROOFWORK

Infrastructure NSW

CLIENT

T +61 2 9216 5700

- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting,
- ridge and hip cappings with new TME

- A6 Remove redundant and intrusive services
- A9 Repair roof dormer structure, cladding and windows A10 Repair galvanised steel vents
- painted timber elements TME or original A5 Replace deteriorated lead flashings, ridge and
- hip cappings with new TME
- penetrations

Aver

A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and downpipes and connect to stormwater drains

linings,fretwork and mouldings

cladding and windows

A8 Repair roof lantern - structure, louvres,

A11 Prime and repaint all new and previously

A7 Repair timber fascias, barge boards, eaves STONEWORK AND BRICKWORK B1 Repair cracked stonework to engineer's detail

Key

- B2 Remove corroded embedments and redundant services and patch repair
- B3 Rub back areas of minor surface damage B4 Repair unsound stone with mortar patch
- B5 Replace damaged stone with stone indent
- B6 Replace missing, loose and non-matching pointing with new TME
- B7 Remove infill/door and reconstruct stonework
- B8 Remove infill and reconstruct opening in
- stonework to original detail B9 Remove doorway and reconstruct window to
- original detail B10 Repair all cast iron wall vents B11 Repair sandstone flagging to verandah
- replacing deteriorated stones with new TME B12 Check over all brickwork and repair as
- necessary
- B13 Repair render finishes

verandah floor

B14 Demolish concrete floor slabs and re-instate

Abbreviations

**EXISTING** 

(N) PROPOSED

- WINDOWS AND DOORS
- C1 Reconstruct original door and window joinery
- original detail
- C6 Repair and repaint cast iron window grilles C7 Lock doors shut
- to original detail C2 Repair damaged door and window joinery to
- C4 Prime and repaint all new and previously painted timber elements TME or original
- WALLS
- D1 Repair plaster finish D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish
- C3 Make all windows and doors operable
- C5 Replace damaged glazing and putty
- E3 Install new ripple iron ceiling TME

associated fixings

**CEILINGS** 

Rev Date

- INTERNAL CONSERVATION WORKS LEGEND:
  - E4 Install new timber board ceiling TME E5 Remove FC ceiling
- E6 Remove PB ceiling D3 Remove plasterboard wall linings and

Checked Auth. Proj. Dir

- **FLOORS** F1 Repair timber flooring and floor structure
- F2 Repair concrete floor F3 Remove concrete topping from concrete slab and repair slab
- F4 Repair timber skirtings and replace deteriorated timber skirtings with new TME F5 New timber skirtings TME
- CMJ CMJ SW MDB, JF Job No. 160481 A1 1:100 NSW Nominated Architects:

Proj. Arch Drawn

F7 Repair flagstone floor

DOORS

architraves

architraves TME

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2 HISTORIC CORE NORTH - FEMALE FACTORY/

ASYLUM PRECINCT **BUILDING C111 - DEMOLITION NORTH & WEST ELEVATIONS** Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.

H19 Construct new verandah extension H9 Reconstruct verandah to original detail H20 Install new timber stair Tanner Kibble Denton Architects Pty Ltd PO Box 660 Darlinghurst NSW 1300 Australia Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia +61 2 9281 4399 F +61 2 9281 4337 www.tkda.com.au

H13 New glazed door

H16 New doorway

H17 Lock doors shut

H18 Re-swing door

H15 New glazed partition

H14 New lightweight partition



H10 Reconstruct 1880s doorway and door

H12 Remove block-out panel from window

H11 New glazed entry door with awning over






PROJECT MANAGER


T +61 2 9380 8816

E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling Description

P1 22.10.19 Preliminary Draft A 29.11.19 S60 Application


Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015








2 DEMOLITION EAST ELEVATION





# **EXTERNAL CONSERVATION WORKS LEGEND:**

ROOFWORK

Infrastructure NSW

CLIENT

T +61 2 9216 5700

Royal Exchange NSW 2010

PO BOX R220

- A1 Provide safe access for inspection of roof
- A2 Repair roof framing to engineer's details A3 Replace deteriorated Welsh roof slates with
- A4 Replace deteriorated steel roof sheeting,
- ridge and hip cappings with new TME A5 Replace deteriorated lead flashings, ridge and
- hip cappings with new TME

INS

- A6 Remove redundant and intrusive services penetrations
- linings, fretwork and mouldings
- A8 Repair roof lantern structure, louvres, cladding and windows A9 Repair roof dormer - structure, cladding and windows
- A10 Repair galvanised steel vents

PROJECT MANAGER

T +61 2 9380 8816

Level 1, 171 William St

Darlinghurst, NSW, 2010

Aver

- A11 Prime and repaint all new and previously painted timber elements TME or original
- A12 Replace deteriorated rainwater goods with new TME - gutters, rainwater heads and downpipes and connect to stormwater drains
- A7 Repair timber fascias, barge boards, eaves
  - redundant services and patch repair B3 Rub back areas of minor surface damage B4 Repair unsound stone with mortar patch

STONEWORK AND BRICKWORK

B5 Replace damaged stone with stone indent B6 Replace missing, loose and non-matching pointing with new TME

B2 Remove corroded embedments and

- B7 Remove infill/door and reconstruct stonework

B1 Repair cracked stonework to engineer's detail

- **APPLICATION UNDER SECTION 60** Application No: S60/2019/227
- On: 04/05/2020
- HERITAGE ACT 1977
- Approved by: the Heritage Council of NSW **Delegated Authority**
- These plans should be read in conjunction with the decision notice
- SHIPS (for) Delegate Heritage Council

- B8 Remove infill and reconstruct opening in
- stonework to original detail B9 Remove doorway and reconstruct window to original detail
- B10 Repair all cast iron wall vents B11 Repair sandstone flagging to verandah replacing deteriorated stones with new TME
- B12 Check over all brickwork and repair as necessary B13 Repair render finishes B14 Demolish concrete floor slabs and re-instate

Abbreviations

**EXISTING** 

(N) PROPOSED

verandah floor

- original detail
- C6 Repair and repaint cast iron window grilles
- WINDOWS AND DOORS
- C2 Repair damaged door and window joinery to
- C4 Prime and repaint all new and previously painted timber elements TME or original
- C7 Lock doors shut
- C1 Reconstruct original door and window joinery to original detail
- C3 Make all windows and doors operable
- C5 Replace damaged glazing and putty
  - E3 Install new ripple iron ceiling TME

Description

Final Draft

Preliminary Draft

S60 Application

Rev Date

P1 22.10.19

P2 25.11.19

A 29.11.19

WALLS

- INTERNAL CONSERVATION WORKS LEGEND:
- E4 Install new timber board ceiling TME D1 Repair plaster finish E5 Remove FC ceiling

sw

- D2 Apply new plaster finish TME D3 Remove wall tiles and repair wall finish D3 Remove plasterboard wall linings and
- associated fixings **CEILINGS**
- E1 Repair ripple iron ceiling E2 Repair timber boarded ceiling
- E6 Remove PB ceiling **FLOORS** F1 Repair timber flooring and floor structure
- F2 Repair concrete floor F3 Remove concrete topping from concrete slab and repair slab
  - F4 Repair timber skirtings and replace
  - deteriorated timber skirtings with new TME F5 New timber skirtings TME
  - Checked Auth. Proj. Dir Proj. Arch Drawn CMJ CMJ MDB, JF Job No.

1:100 160481 A1 NSW Nominated Architects: Robert Denton Registration No. 5782
Alex Kibble Registration No. 6015

Do not scale drawings. Verify all dimensions on site. Notify architect of all discrepancies Drawing No.

F6 Remove carpet

DOORS

architraves

architraves TME

F7 Repair flagstone floor

F8 Construct raised timber floor and ramps

G1 Repair timber joinery door, frame and

G2 New timber joinery door, frame and

(1:25) above reinstated verandah floor

PARRAMATTA NORTH GROWTH CENTRE HERITAGE REPAIRS - TRANCHE 2

ADAPTATION WORKS

original fabric

H2 Remove internal fit-out

H7 New sanitary facilities

H4 New lift for equitable access

H8 Create new opening in wall

H1 Demolish intrusive additions and repair

H3 New steel-framed stair and mezzanine

H5 New workstations and loose furniture

H6 New electrical, communications, fire

detection and mechanical services

H9 Reconstruct verandah to original detail

HISTORIC CORE NORTH - FEMALE FACTORY/ ASYLUM PRECINCT **BUILDING C111 - DEMOLITION SOUTH & EAST ELEVATIONS** 

AR.S60.6004

including new/repaired sandstone edging

H10 Reconstruct 1880s doorway and door

H12 Remove block-out panel from window

H19 Construct new verandah extension

H13 New glazed door

H16 New doorway

H17 Lock doors shut

H18 Re-swing door

H15 New glazed partition

H20 Install new timber stair

H14 New lightweight partition

H11 New glazed entry door with awning over

Tanner Kibble Denton Architects Pty Ltd PO Box 660 Darlinghurst NSW 1300 Australia Level 1, 19 Foster Street, Surry Hills NSW 2010 Australia +61 2 9281 4399 F +61 2 9281 4337 www.tkda.com.au

