



Figure 1-1 View from the south west corner of the site looking north



Figure 1-2 South west corner of site looking south west



Figure 1-3 View from the south west corner of the site looking north



Figure 1-4 Treated pine fencing posts on site



Figure 1-5 Rock stockpile



Figure 1-6 Dense vegetation and weeds



Figure 1-7 Stock watering facility



Figure 1-8 Small earth dam southern portion of the site



Figure 1-9 Earth dams southern portion of site





Figure 1-10 Stock loading facility on site



Figure 1-11 Stock watering facility



Figure 1-12 Exposed natural rock outcrop near centre of site



Figure 1-13 Fence posts on site



Figure 1-14 Piles of local rock on site



Figure 1-15 Drainage channel northern portion of site



Figure 1-16 Building materials near centre of site