

FIGURE C3
EXISTING CONDITIONS (SENIORS LIVING SITE)

1% AEP
2hr Duration
Hazard



Map Produced by
Cardno NSW / ACT Water and Environment
Date: November 2017
Coordinate System: MGA Zone 56
Project: 59915160



FIGURE C4
EXISTING CONDITIONS (SENIORS LIVING SITE)






FIGURE C5
EXISTING CONDITIONS (SENIORS LIVING SITE)

**1% AEP + Climate Change
2hr Duration
Depth and Water Levels**

Map Produced by
Cardno NSW / ACT Water and Environment
Date: November 2017
Coordinate System: MGA Zone 56
Project: 59915160





FIGURE C6
EXISTING CONDITIONS (SENIORS LIVING SITE)

**1% AEP+ Climate Change
2hr Duration
Velocity**



Map Produced by
Cardno NSW / ACT Water and Environment
Date: November 2017
Coordinate System: MGA Zone 56
Project: 59915160






FIGURE C8
EXISTING CONDITIONS (SENIORS LIVING SITE)

PMF
15 min Duration
Depth and Water Levels



Map Produced by
Cardno NSW / ACT Water and Environment
Date: November 2017
Coordinate System: MGA Zone 56
Project: 59915160

