

Additional Information MOD 24/1002 Lower Supertrail (Lot 876 DP 1243112) Thredbo

Item 1: Justification for additional trenching

An unmapped Telstra cable and recently installed HV cable was identified within close proximity of the disturbance area. Trench alignment adjustments were required in various locations to avoid the unknown services. A closer power supply was found to support the new fan below existing pit 610.

Item 2: Justification for construction corridor expansion

The justification for the construction corridor expansion was provided in the Mod report and Site Plan (Rev B), no further justification is warranted. There will be no impact to adjacent vegetation from edge effects. The disturbance will be kept to the minimum for the proposed works. A review of the construction corridor has been undertaken, noting a reduction in various locations in Rev C.

Additional Item: Plan discrepancies

As part of this review, it was identified the fan originally proposed adjacent to existing pit 607 had been shown on top of pit 607 in Site Plan (Rev B). It has now been adjusted as per the original Site Plan.