


Asbestos Register

(Hazardous Materials and Risk Assessment)

School:	Leppington Public School (2926)
Region:	South Western Sydney AMU
State Electorate:	Leppington
Local Government Area:	Camden

Last Reviewed By:	OHMS Hygiene 06-JUL-2021
Last Revised By:	WSP 16-MAR-2024

Historical Fibro In Grounds Investigations/Events	No
No previous investigations have been recorded against the school. However, asbestos containing materials maybe present in grounds from time to time and caution must be exercised prior to any grounds disturbance.	



Preface to Asbestos Register

Limitations

Asbestos Registers established (first surveyed 2007/08) and maintained for the Department of Education (DoE) are limited in extent, in that:

1. All inspections and surveys of materials and finishes in DoE facilities are non-disturbance, with
 2. Samples undertaken by hygienist to determine whether a sample is an Asbestos Containing Material (ACM),
 3. The hygienist may apply a single sample to like materials within a space and adjoining spaces, but not normally between buildings,
 4. Successive inspections have reduced any inconclusive records such as "assumed asbestos" in difficult to access areas, by undertaking additional sampling with lifting devices.
 5. In compliance with WHS Act 2011 and WHS Regulations 2017, additional inspections have been undertaken in ceiling spaces and sub-floor areas where access is possible.
 - Where the ground floor is slab on ground, no inspection is made beneath the slab.
 - Where fibro fragments (ACM taken for sampling) are located in ceiling spaces or sub floor voids air monitoring is normally undertaken at time of sampling, and clearance undertaken as soon as practicable.
 6. No attempt has been made to identify any ACM that is hidden from view or encapsulated within
 - Any wall cavity
 - Sub floor area, particularly formwork for slabs in/on ground,
 - Services (that may use ACM) such as: pipe lagging, asbestos cement pipes, flues.
 7. All known ACM in Grounds (Fibro in Grounds) is made available in associated site specific asbestos management plans in DoE electronic files.
- Notwithstanding information provided, ACM may be present in grounds from time to time and caution must be exercised prior to any grounds disturbance.

Use of the Asbestos Register

Prior to any disturbance works being undertaken in a building to which this asbestos register applies it will be necessary to confirm the extent of any ACM by a disturbance investigation:

- If the building was built prior to 2003
- If any ACM has been identified in the Asbestos Register for the building.

Update of Asbestos Registers

Asbestos Register Data is updated regularly by the DoE Hygienist Panel via the Online Asbestos Register Tool (Managed by Business Systems, School Infrastructure NSW). Internal users can view the latest edition of the Asbestos Register in the AMS.

Please note: The Department's external website may not contain the latest revision of the Asbestos Register.

Notes 1: Vermiculite

- During 2018/19, all vermiculite occurrences in DoE schools identified in 2007/08, were "composite tested" in accordance with a safe work NSW agreed procedure. This required multiple testing of all vermiculite occurrences.
- During the period 2007/08 to 2018/19, some vermiculite has been over sheeted and a warning is indicated for schools where this has happened.

Note 2: DoE website link for information is here:

<https://www.schoolinfrastructure.nsw.gov.au/about-us/workingwithus/schools-asbestos-register.html>
<https://education.nsw.gov.au/about-us/strategies-and-reports/our-reports-and-reviews/schools-asbestos-register>

Note 3: Material Condition Assessment

The material condition assessment descriptors from Section 3 of the Asbestos Management Plan (AMP) is extracted below. Please read the AMP in its entirety for further information.

3.3.2.1 Material condition assessment

The OART records the material condition of identified ACM in the following format:

Rating	Description
Good condition (1)	For non-friable asbestos that is sealed and has no visible damage. This primarily related to asbestos cement (AC) sheet and vinyl tiles
Minimal damage (2)	For non-friable asbestos that has a very small amount of damage, eg hairline cracks.
Some damage / unsealed (3)	For non-friable asbestos with significant breakage or several small areas where material has been damaged, revealing loose asbestos fibres. Non-friable asbestos that is unsealed.
Poor condition (4)	For non-friable asbestos that has extensive damage. Visible asbestos debris
Friable asbestos (5)	Any occurrence of friable asbestos

Product	Material Description	Extent	Location	Material Condition	Risk Status	Remediation Priority	Result
B00A - Administration - 1967 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	15.00m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos)
Gable Verge Lining	Flat AC Sheeting	20.00m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos)
Underfloor Voids	AC Fragments/Debris	1.00	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)	Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Interior							
B00A - R0001 - Movement - 13.19 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos)
B00A - R0002 - Principal - 23.36 m2							
No Asbestos							
B00A - R0003 - Sick Bay - 7.34 m2							
No Asbestos							
B00A - R0004 - Interview - 15.46 m2							
No Asbestos							
B00A - R0005 - Movement - 4.47 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos)
B00A - R0006 - Entry Vestibule - 20.25 m2							
No Asbestos							
B00A - R0007 - General Storeroom - .49 m2							
No Asbestos							
B00A - R0008 - Handwashing Facilities - .27 m2							
Wall Linings Internal	Flat AC Sheeting	1.00m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0009 - Clerical Office - 21.07 m2							
No Asbestos							
B00A - R0010 - Movement - 15.68 m2							
No Asbestos							
B00A - R0011 - General Storeroom - 3.51 m2							
No Asbestos							
B00A - R0012 - Cleaning Distributed Store - 3.55 m2							
Wall Linings Internal	Flat AC Sheeting	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0013 - Staff Toilet - 3.47 m2							
Wall Linings Internal	Flat AC Sheeting	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00A - R0014 - Craft Store - 7.21 m2							
No Asbestos							
B00A - R0015 - Staff Toilet - 3.64 m2							
Wall Linings Internal	Flat AC Sheeting	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00B - General Learning - 1968 - Brick/Veneer							
Exterior							

Eaves Linings	Flat AC Sheeting	10.00m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
Gable Verge Lining	Flat AC Sheeting	20.00m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00B - R0001 - Communal Space - 91.12 m2							
No Asbestos							
B00B - R0002 - Staff Room Annexe - 10.4 m2							
No Asbestos							
B00B - R0003 - Home Base Store - 13.12 m2							
No Asbestos							
B00B - R0004 - Movement - 26.36 m2							
Ceiling Structures/Linings	Flat AC Sheeting	27.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - Pupil Facilities - 1966 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	18.00m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
Interior							
B00C - R0001 - Toilets - Girls - 28.71 m2							
Partition Walls (Cubides)	Compressed AC Sheet	16.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00C - R0002 - Drinking Facilities - 17.17 m2							
No Asbestos							
B00C - R0003 - Kiln Room - 6.16 m2							
No Asbestos							
B00C - R0004 - P.E. Store - 6.16 m2							
No Asbestos							
B00C - R0005 - Drinking Facilities - 17.07 m2							
No Asbestos							
B00C - R0006 - Toilets - Boys - 28.7 m2							
Partition Walls (Cubides)	Compressed AC Sheet	10.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - General Learning - 1966 - Brick/Veneer							
Exterior							
Eaves Linings	Flat AC Sheeting	30.00m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos)
Gable Verge Lining	Flat AC Sheeting	20.00m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos)
Interior							
B00D - R0001 - Movement - 1.19 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos)
B00D - R0002 - Movement - 3.15 m2							
No Asbestos							
B00D - R0003 - Uniform Shop - 3.87 m2							
Floor Coverings Res/Textile	Vinyl Tiles	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00D - R0004 - Home Base Store - 4.76 m2							
No Asbestos							
B00D - R0005 - Home Base - 56.76 m2							
No Asbestos							
B00D - R0006 - Home Base - 56.46 m2							

No Asbestos							
B00D - R0007 - Home Base Store - 4.71 m2							
No Asbestos							
B00D - R0008 - Personal Effects Storage - 3.85 m2							
No Asbestos							
B00D - R0009 - Movement - 3.19 m2							
No Asbestos							
B00D - R0010 - Movement - 1.36 m2							
Ceiling Structures/Linings	Flat AC Sheeting	2.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos)
B00D - R0011 - Home Base - 57.6 m2							
No Asbestos							
B00D - R0012 - Home Base Store - 5.21 m2							
No Asbestos							
B00D - R0015 - General Storeroom - .55 m2							
No Asbestos							
B00D - R0016 - Movement - 1.48 m2							
No Asbestos							
B00D - R0017 - General Storeroom - .55 m2							
No Asbestos							
B00D - R0018 - Home Base Store - 5.42 m2							
No Asbestos							
B00D - R0019 - Home Base - 57.86 m2							
No Asbestos							
B00D - R0020 - Movement - 132.09 m2							
No Asbestos							
B00D - R0021 - Practical Activities/Movement - 2hb - 13.76 m2							
No Asbestos							
B00E - Library/Tiered Learning - 1981 - Brick/Block							
Exterior							
No Asbestos							
Interior							
B00E - R0001 - Plant - 1.77 m2							
No Asbestos							
B00E - R0002 - Special Programs Store - 5.07 m2							
No Asbestos							
B00E - R0003 - Special Programs Room - 39.98 m2							
No Asbestos							
B00E - R0004 - Movement - 3.78 m2							
No Asbestos							
B00E - R0005 - Staff Toilet - 6.43 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	2.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0006 - Staff Toilet - 6.86 m2							
Partition Walls (Cubicles)	Compressed AC Sheet	2.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0007 - Movement - 2.54 m2							
No Asbestos							
B00E - R0008 - Distribution Board - 1.72 m2							
Note: No inspection of live electrical installation							
Wall Linings Internal	Flat AC Sheeting	1.00m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00E - R0009 - Movement - 10.53 m2							
No Asbestos							

B00E - R0010 - Library Office/Workroom - 24.31 m2							
No Asbestos							
B00E - R0011 - Communications Room - 13.1 m2							
No Asbestos							
B00E - R0012 - Reading Area - 155.27 m2							
No Asbestos							
B00E - R0013 - Movement - 3.28 m2							
No Asbestos							
B00E - R0014 - Movement - 122.15 m2							
No Asbestos							
B00F - Pupil Facilities - 1968 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	23.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
Interior							
B00F - R0001 - Movement - 13.65 m2							
Ceiling Structures/Linings	Flat AC Sheeting	14.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0002 - Canteen - 18.02 m2							
Ceiling Structures/Linings	Flat AC Sheeting	19.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0003 - Canteen Office/Store - 3.28 m2							
Ceiling Structures/Linings	Flat AC Sheeting	4.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0004 - Canteen Office/Store - 2.85 m2							
Ceiling Structures/Linings	Flat AC Sheeting	3.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
B00F - R0005 - Cleaning Distributed Store - 4.58 m2							
No Asbestos							
B00G - Pupil Facilities - 1968 - Brick/Block							
Exterior							
Eaves Linings	Flat AC Sheeting	12.00m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00G - R0001 - Drinking Facilities - 8.68 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0002 - Toilets - Boys - 8.68 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0003 - Cleaning Distributed Store - 4.2 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0004 - Garden Store - 4.2 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0005 - Toilets - Girls - 8.68 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00G - R0006 - Drinking Facilities - 8.68 m2							
Ceiling Structures/Linings	Flat AC Sheeting	9.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - Staff Facilities - 1923 - Timber							
Exterior							

Ceiling Voids	Assumed Asbestos						
Interior							
B00H - R0002 - General Storeroom - 5.85 m2							
No Asbestos							
B00H - R0003 - Movement - 14.4 m2							
Ceiling Structures/Linings	Flat AC Sheeting	15.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00H - R0004 - General Storeroom - 10.73 m2							
No Asbestos							
B00H - R0005 - Home Base - 41.69 m2							
Assumed Asbestos - New Room Created							
B00H - R0006 - Practical Activities - 1hb - 13.93 m2							
Assumed Asbestos - New Room Created							
B00I - General Learning - 1913 - Timber							
Exterior							
No Asbestos							
Interior							
B00I - R0001 - Home Base - 47.21 m2							
No Asbestos							
B00I - R0002 - Movement - 12.14 m2							
No Asbestos							
B00J - General Learning - 1959 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	30.00m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
Interior							
B00J - R0001 - External Movement - 5.97 m2							
Ceiling Structures/Linings	Flat AC Sheeting	5.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
B00J - R0002 - Movement - 3.19 m2							
No Asbestos							
B00J - R0003 - Personal Effects Storage - 10.62 m2							
No Asbestos							
B00J - R0004 - Home Base - 57.04 m2							
No Asbestos							
B00J - R0005 - Home Base - 67.16 m2							
No Asbestos							
B00J - R0006 - Practical Activities - 1hb - 5.98 m2							
No Asbestos							
B00J - R0007 - Personal Effects Storage - 5.91 m2							
No Asbestos							
B00J - R0008 - Home Base Store - 4.72 m2							
No Asbestos							
B00J - R0009 - Movement - 8.14 m2							
No Asbestos							
B00J - R0010 - Toilets - Boys/Girls - 4.4 m2							
Wall Linings Internal	Flat AC Sheeting	5.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	5.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
B00J - R0011 - Movement - 7.65 m2							
Ceiling Structures/Linings	Flat AC Sheeting	8.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)

B00J - R9001 - General Assistant/Bulk Store - 37.23 m2							
No Asbestos							
B00K - General Learning - 1915 - Timber							
Exterior							
No Asbestos							
Interior							
B00K - R0001 - Practical Activities - 44.02 m2							
Ceiling Structures/Linings	Flat AC Sheeting	45.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
Wall Linings Internal	Flat AC Sheeting	30.00m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
B00K - R0002 - Withdrawal Space - 1hb - 5.8 m2							
Ceiling Structures/Linings	Flat AC Sheeting	6.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
Wall Linings Internal	Flat AC Sheeting	6.00m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
B00K - R0003 - External Movement - 10.49 m2							
Ceiling Structures/Linings	Flat AC Sheeting	11.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
B00L - General Learning - 1955 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	15.00m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos) , Amosite (brown asbestos)
Interior							
B00L - R0001 - Home Base - 54.04 m2							
No Asbestos							
B00L - R0002 - External Movement - 17.16 m2							
Ceiling Structures/Linings	Flat AC Sheeting	18.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
B00L - R0003 - Communal/Performance Store - 6.02 m2							
Ceiling Structures/Linings	Flat AC Sheeting	7.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
B00L - R0004 - Staff Room Annexe - 9.4 m2							
No Asbestos							
B00L - R0005 - Special Programs Room - 13.44 m2							
No Asbestos							
B00L - R0006 - Movement - 3.13 m2							
No Asbestos							
B00M - General Learning - 1955 - Timber							
Exterior							
Eaves Linings	Flat AC Sheeting	35.00m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
Interior							
B00M - R0001 - Home Base - 54.11 m2							
No Asbestos							
B00M - R0004 - No Access - 42.1 m2							
Ceiling Structures/Linings	Flat AC Sheeting	43.00m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos), Amosite (Brown asbestos), Crocidolite (blueasbestos)
B00M - R0005 - Sports Store - 8.58 m2							
No Asbestos							
B00M - R0006 - Home Base Store - 5.16 m2							
No Asbestos							
B00M - R0007 - Practical Activities - 1hb - 7.9 m2							
No Asbestos							

B00M - R0008 - Practical Activities - 1hb - 4.92 m2							
No Asbestos							
B00M - R0009 - Home Base Store - 4.52 m2							
No Asbestos							
B00M - R0010 - Home Base - 56.96 m2							
No Asbestos							
B00N - Administration - 1955 - Timber Shed							
Exterior							
Wall Cladding	Flat AC Sheeting	13.00m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)	Chrysotile (white asbestos)
Interior							
B00N - R0001 - Other-Vacant - 20.29 m2							
No Asbestos							
B00P - Administration - 1991 - Steel							
Exterior							
No Asbestos							
Interior							
B00P - R0001 - Movement - 8.79 m2							
No Asbestos							
B00P - R0002 - Staff Toilet - 1.51 m2							
No Asbestos							
B00P - R0003 - Community Clinic - 9.99 m2							
No Asbestos							
B00Q - Pupil Facilities - 1955 - Brick/Block							
Exterior							
No Asbestos							
Interior							
B00Q - R0001 - Drinking Facilities - 9.38 m2							
No Asbestos							
B00R - Pupil Facilities - 2019 - Brick/Block							
Exterior							
No Asbestos							
Interior							
B00R - R0001 - Disabled Toilet - 12.43 m2							
No Asbestos							
B00R - R0002 - External Movement - 11.19 m2							
No Asbestos							

Demountables					
D10054 - Placement Date : 08-JAN-2019					
Exterior					
Floor	Adhesive	Floor Throughout			Assumed Asbestos
Underfloor Voids	AC Fragments/Debris				Assumed Asbestos
Underfloor Voids	Flat AC Sheeting				Assumed Asbestos
Window Putty	Mastic	Windows Throughout			Assumed Asbestos
Interior					
No Asbestos Found					
D10620 - Placement Date : 08-DEC-2020					
Exterior					
Floor	Adhesive	Floor Throughout			Assumed Asbestos
Underfloor Voids	AC Fragments/Debris				Assumed Asbestos
Underfloor Voids	Flat AC Sheeting				Assumed Asbestos
Window Putty	Mastic	Windows Throughout			Assumed Asbestos
Interior					
No Asbestos Found					
D11025 - Placement Date : 31-DEC-2019					
Exterior					
Window Putty	Mastic	Windows Throughout			Assumed Asbestos
Ramp	Compressed AC Sheet				Assumed Asbestos
Awnings	Flat AC Sheeting				Assumed Asbestos
Underfloor Voids	AC Fragments/Debris				Assumed Asbestos
Entry Steps	Compressed AC Sheet				Assumed Asbestos
Wall Cladding	Flat AC Sheeting				Assumed Asbestos
Underfloor Voids	Flat AC Sheeting				Assumed Asbestos
Landing	Compressed AC Sheet				Assumed Asbestos
Interior					
R1- Entry					
Assumed Asbestos - Room Not Accessed					
R2- Home Base					
Assumed Asbestos - Room Not Accessed					
R3- Practical Activity Area					
Assumed Asbestos - Room Not Accessed					
R4- Home Base Store					
Assumed Asbestos - Room Not Accessed					
R5- Withdrawal Space					
Assumed Asbestos - Room Not Accessed					
D13012 - Placement Date : 08-DEC-2020					
Exterior					
Floor	Adhesive	Floor Throughout			Assumed Asbestos
Underfloor Voids	AC Fragments/Debris				Assumed Asbestos
Underfloor Voids	Flat AC Sheeting				Assumed Asbestos
Window Putty	Mastic	Windows Throughout			Assumed Asbestos
Interior					
No Asbestos Found					
D13574 - Placement Date : 23-MAY-2019					
Exterior					
Floor	Adhesive	Floor Throughout			Assumed Asbestos

Underfloor Voids	AC Fragments/Debris				Assumed Asbestos
Underfloor Voids	Flat AC Sheeting				Assumed Asbestos
Window Putty	Mastic	Windows Throughout			Assumed Asbestos
Interior					
No Asbestos Found					
D14111 - Placement Date : 23-MAY-2019					
Exterior					
Floor	Adhesive	Floor Throughout			Assumed Asbestos
Underfloor Voids	AC Fragments/Debris				Assumed Asbestos
Underfloor Voids	Flat AC Sheeting				Assumed Asbestos
Window Putty	Mastic	Windows Throughout			Assumed Asbestos
Interior					
No Asbestos Found					
D14766 - Placement Date : 06-JAN-2021					
Exterior					
Floor	Adhesive	Floor Throughout			Assumed Asbestos
Underfloor Voids	AC Fragments/Debris				Assumed Asbestos
Underfloor Voids	Flat AC Sheeting				Assumed Asbestos
Window Putty	Mastic	Windows Throughout			Assumed Asbestos
Interior					
No Asbestos Found					
D14914 - Placement Date : 18-NOV-2020					
Exterior					
Floor	Adhesive	Floor Throughout			Assumed Asbestos
Underfloor Voids	AC Fragments/Debris				Assumed Asbestos
Underfloor Voids	Flat AC Sheeting				Assumed Asbestos
Window Putty	Mastic	Windows Throughout			Assumed Asbestos
Interior					
No Asbestos Found					
D15095 - Placement Date : 21-NOV-2023					
No Asbestos Found					
D15390 - Placement Date : 08-JAN-2019					
Exterior					
Floor	Adhesive	Floor Throughout			Assumed Asbestos
Underfloor Voids	AC Fragments/Debris				Assumed Asbestos
Underfloor Voids	Flat AC Sheeting				Assumed Asbestos
Window Putty	Mastic	Windows Throughout			Assumed Asbestos
Interior					
No Asbestos Found					
D16239 - Placement Date : 21-NOV-2023					
No Asbestos Found					