



Figure 24 – Original 'Sirius' building signage at western façade.

### External numbered signage

Allow to remove existing street number signage if found to be redundant and / or in poor condition.

New numbering / wayfinding signage is to be developed together with the heritage consultant, project architect, and other relevant stakeholders, and is to have regard for the character of the building.

### Internal signage

Allow to remove all existing internal signage (with the exception of the 'Phillip Rooms' signage, to be addressed below).

New signage is to be developed together with the heritage consultant, project architect, and other relevant stakeholders, and is to have regard for the character of the building.

### Phillip Room signage

Check the condition of the existing wall-mounted 'Phillip Rooms' signage at the northern wall of the core (located outside of the Phillip Room itself). If found to be in good condition, allow for careful removal and reinstatement in an appropriate, visible location (noting that the M & S letters will need to be reproduced).

If found to be in poor condition, or if removal is not feasible, allow to reproduce like-for-like (with regard to dimensions, typeface, and colour finish) and install in a publicly visible location.



Figure 25 – Original 'Phillip Rooms' signage mounted to northern side of core.



