

**Photo Analysis from Wat Phrayortkeo Dhammayanaram temple and
Share-Way and T-Way to the west of the Site**



Figure 1: View toward the Site from the parkland to the rear of the Wat Phrayortkeo Dhammayanaram temple (i.e. the Site cannot be seen due to the tall trees within the parklands).



Figure 2: View toward the Site from the parkland to the rear of the Wat Phrayortkeo Dhammayanaram temple (i.e. the Site cannot be seen due to the tall trees within the parklands).



Figure 3: View of the Wat Phrayortkeo Dhammayanaram temple from the parkland to the rear in the context of existing unsightly retail buildings adjacent.



Figure 4: View of the Wat Phrayortkeo Dhammayanaram temple from Smithfield Road in the context of existing unsightly retail buildings adjacent.



Figure 5: View of the northern part of the Site from the share-way (adjacent to the T-Way) to the west – the Site is barely visible due to the remnant bushland in the creek corridor which is under regeneration.



Figure 6: View of the southern part of the Site from the share-way (adjacent to the T-Way) to the west – the Site is not visible due to the remnant bushland in the creek corridor which is under regeneration.



Figure 7: View of the Site from the share-way (adjacent to the T-Way) to the west – the Site is barely visible due to the remnant bushland in the creek corridor which is under regeneration.



Figure 8: View of the southern part of the Site from the intersection of Elizabeth Drive and the T-Way to the south-west – the Site is barely visible due to the remnant bushland in the creek corridor which is under regeneration.