Attachment 5: Compliance Table

DA-2016/1353 Alterations and additions to Wollongong Private Hospital

CHAPTER D13 – WOLLONGONG CITY C	ENTRE			
2 Building form				
Objectives/controls	Comment	Complies		
2.2 Building to street alignment and street setbacks Minimum 4m setback	4m provided	Yes		
William 4m Selback	411 provided	163		
2.5 Side and rear building setbacks and building separation				
'Commercial' means all non-residential uses		Yes		
Up to 24m: 3m side setback and 9m rear setback Over 24m: 6m side setback and 12m rear setback	Building proper observes 6m for majority of western elevation, with exception of projecting blade wall (4.56m) and corner return of the building (5.54m). These occur approximately half way along the elevation. The medical suites on Level 6 sit behind the existing fire stair.			
	Rear setback not relevant as site adjoins existing hospital allotment.			
2.8 Landscape design Integrate landscaping into design of development.	Landscape design prepared by Arcadia Landscape Architects. Fails to provide public domain treatment at	No		
Add value and quality of life for residents.	existing hospital (e.g. pram ramps).			
Improve stormwater quality and control run-off.	Fails to resolve transition between existing hospital driveway and proposed driveway. Further details/revised plans needed.			
Refer Chapter E6 Landscaping and Public Domain Technical Manual.				
2.9 Planting on structures		Yes		
Provide sufficient soil depth and area to allow for plant growth.	No objection. Trees and shrubs shown on landscape plan.			
2.11 Development on classified roads	Crown Street is classified road. No new access from Crown Street.	Yes		
3 Pedestrian amenity				
Objectives/controls	Comment	Complies		

Retail tenancy proposed for Urunga Parade yes ground level. 3.4 Safety and security No specific details about security access systems provided. Ground level terrace/cafe likely to be closed at night. Use of this entrance likely to be to by hyperbaric staff or visitors and staff with on-street parking. Lighting to be appropriate for residential setting. 3.5 Awnings Provided on Urunga Parade lower ground and ground level within property. Poor execution of existing hospital driveway. This has not been rectified in proposal. Full details of footpath levels not provided. 3.8 Building exteriors Proposed materials are similar to existing hospital driveway. This has not been rectified in proposal. Full details of footpath levels not provided. No additional signage proposed. No additional signage proposed. No additional signage proposed. No additional parking spaces provided. Access, parking and servicing Objectives/controls Comment Complies 4.2 Pedestrian access and mobility No additional parking spaces provided. No internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuving areas A.4 On-site parking No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. No details of electricity requirements. Utility Yes			
systems provided. Ground level terrace/café likely to be closed at night. Use of this entrance likely to be by hyperbaric staff or visitors and staff with on-street parking. 3.5 Awnings Provided on Urunga Parade lower ground and ground level within property. Poor execution of existing hospital driveway. This has not been rectified in proposal. Full details of footpath levels not provided. Proposed materials are similar to existing hospital. Appropriate for setting. Proposed materials are similar to existing hospital. Appropriate for setting. No additional signage proposed. N/a No additional signage proposed. N/a Access, parking and servicing Objectives/controls Comment Complies 4.2 Pedestrian access and mobility No additional parking spaces provided. Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuvring areas Poor execution of existing hospital. The extension does not sit above or project beyond the existing hospital. View impacts not expected. No additional parking spaces provided. Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuvring areas One additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. No additional spaces provided. Retail and medical suites would attract additional car spaces.	3.3 Active street frontages		Yes
and ground level within property. 3.6 Vehicular footpath crossings Poor execution of existing hospital driveway. No This has not been rectified in proposal. Full details of footpath levels not provided. Proposed materials are similar to existing hospital. Appropriate for setting. No additional signage proposed. No additional signage proposed. No additional signage proposed. The extension sits within the L-shape of the existing hospital. The extension does not sit above or project beyond the existing hospital. View impacts not expected. Access, parking and servicing Objectives/controls Comment Complies A.2 Pedestrian access and mobility No additional parking spaces provided. Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuvring areas No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. No additional spaces provided. Retail and medical suites would attract additional car spaces. No details of electricity requirements. Utility	3.4 Safety and security	systems provided. Ground level terrace/café likely to be closed at night. Use of this entrance likely to be by hyperbaric staff or visitors and staff with on-street parking. Lighting to be appropriate for residential	No
This has not been rectified in proposal. Full details of footpath levels not provided. 3.8 Building exteriors Proposed materials are similar to existing hospital. Appropriate for setting. No additional signage proposed. No additional signage proposed. The extension sits within the L-shape of the existing hospital. The extension does not sit above or project beyond the existing hospital. View impacts not expected. Access, parking and servicing Objectives/controls Comment Complies A.2 Pedestrian access and mobility No additional parking spaces provided. Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuvring areas No additional driveway to support one emergency hyperbaric space. 4.4 On-site parking No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. The building is serviced by the major No details of electricity requirements. Utility Yes	3.5 Awnings		Yes
hospital. Appropriate for setting. 3.9 Advertising and signage No additional signage proposed. N/a The extension sits within the L-shape of the existing hospital. The extension does not sit above or project beyond the existing hospital. View impacts not expected. Access, parking and servicing Objectives/controls Comment Complies A.2 Pedestrian access and mobility No additional parking spaces provided. Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. A.3 Vehicular driveways and manoeuvring areas One additional driveway to support one emergency hyperbaric space. A.4 On-site parking No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. The building is serviced by the major No details of electricity requirements. Utility Yes	3.6 Vehicular footpath crossings	This has not been rectified in proposal. Full	No
3.10 Views and view corridors The extension sits within the L-shape of the existing hospital. The extension does not sit above or project beyond the existing hospital. View impacts not expected. 4 Access, parking and servicing Objectives/controls Comment Complies A.2 Pedestrian access and mobility No additional parking spaces provided. Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuvring areas One additional driveway to support one emergency hyperbaric space. No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. No details of electricity requirements. Utility Yes	3.8 Building exteriors		Yes
existing hospital. The extension does not sit above or project beyond the existing hospital. View impacts not expected. 4 Access, parking and servicing Objectives/controls Comment Complies 4.2 Pedestrian access and mobility No additional parking spaces provided. Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuvring areas One additional driveway to support one emergency hyperbaric space. No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. 4.5 Site facilities and services The building is serviced by the major No details of electricity requirements. Utility Yes	3.9 Advertising and signage	No additional signage proposed.	N/a
A.2 Pedestrian access and mobility No additional parking spaces provided. Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuvring areas One additional driveway to support one emergency hyperbaric space. No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. 4.5 Site facilities and services The building is serviced by the major No details of electricity requirements. Utility Yes	3.10 Views and view corridors	existing hospital. The extension does not sit above or project beyond the existing hospital.	Yes
A.2 Pedestrian access and mobility No additional parking spaces provided. Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuvring areas One additional driveway to support one emergency hyperbaric space. No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. 4.5 Site facilities and services The building is serviced by the major No details of electricity requirements. Utility Yes	4 Access, parking and servicing		
Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga Parade. 4.3 Vehicular driveways and manoeuvring areas One additional driveway to support one emergency hyperbaric space. No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. 4.5 Site facilities and services The building is serviced by the major No details of electricity requirements. Utility Yes		Comment	Complies
areas 4.4 On-site parking No additional spaces provided. Details of practitioner numbers not provided. Retail and medical suites would attract additional car spaces. 4.5 Site facilities and services The building is serviced by the major No details of electricity requirements. Utility Yes	4.2 Pedestrian access and mobility	Internal access to current hospital lifts from existing car park would remain. Poor footpath and public domain outcome on Urunga	No
practitioner numbers not provided. Retail and medical suites would attract additional car spaces. 4.5 Site facilities and services The building is serviced by the major No details of electricity requirements. Utility Yes	- -		Yes
The building is serviced by the major No details of electricity requirements. Utility Yes	4.4 On-site parking	practitioner numbers not provided. Retail and medical suites would attract additional car	No
The building is serviced by the major No details of electricity requirements. Utility Yes	4.5 Site facilities and services		
	The building is serviced by the major	No details of electricity requirements. Utility	Yes

to result in any need to augment these connection at developer's expense. services.

5 Environmental management		
Objectives/controls	Comment	Complies
5.2 Energy efficiency and conservation	No specific measures documented.	N/a
5.3 Water conservation	Sydney Water approvals required for hospitals at Construction Certificate stage.	N/a
5.4 Reflectivity	The proposed materials are not highly reflective.	Yes
5.6 Waste and recycling	No additional waste facilities provided. SEE suggests all servicing requirements would be met in existing hospital. It is unclear how the extension staff (e.g. retail) would access the existing waste room which is located at the rear of the loading dock. The relationship with existing stratum lots has not been clarified.	No
8 Works in the public domain	Urunga Parade streetscape requires public domain works. These not satisfactory	No