











CleanPeak E N E R G Y

NO UNAUTHORISED ACCESS BEYOND THIS POINT

ALL PERSONNEL MUST REPORT TO SITE OFFICE. ALL PERSONNEL MUST BE SITE INDUCTED BEFORE STARTING WORK ON THIS PROJECT SITE.

| METYHELKE | TOOL SECTION | PERSONAL F Equipment / C Must be worn | LOTHING (PPE) |
|-------------------------------------|--------------------------------|---|----------------------------|
| IN CASE OF EMERGENCY DIAL 000 | DANGER CONSTRUCTION SITE | ALL VISITORS MUST REPORT TO THE SITE OFFICE | AUTHORISED PERSONS ONLY |
| Project Name: | URADQUINT | V Salar | |
| Site Address: | 1268 May Ban | 2 DOLAR FARM | |
| Site Contact: | Heiner Guenze | ROAD URANGLOW | TY.NSW 2652 |
| Project Emergency Contact: | 0474 748 925 | /CPE Project Mommyu 0421818071/045340 | 0.1.42 |
| | Project Admin : | 0400 460 190 | 0 648 |





Akcome Optoelectronics (CN)

| aqoNew/Energy/Corp.(CN) | Vivint Solar (US) |
|--------------------------------|---|
| | CIMIC Group (AU) |
| | Consolidated Edison (US) |
| | Consolidated Electrical Distributors (US) |
| | Copenhagen Infrastructure Partners K/S (DK) |
| | DecmilGroup(AU) |
| | Elecnor SÅ(ES) |
| | Enel SpÅ(IT) |
| | Engie SÅ (FR) |
| JinkoSolar Holding Co Ltd (CN) | Fuji Electric Co (JP) |
| | Green Light Contractors Pty (AU) |
| | Henan Senyuan Electric Co (CN) |
| | Hengtong Optic:electric Co (CN) |
| | Linnotech Corp (JP) |
| | Jiawei Renewable Energy Co (CN) |
| | Kenya Electricity Generating Co PLC (KE) |
| | MAONENG Group (AU) |
| | Metka-Egn (GB) |
| _ | MVV/Energie/ÅG(DE) |
| | NextEra Energy (US) |
| | Sungrow, Power Supply, Co.(CN) |
| | Swinerton Builders (US) |
| | |

Sustainable Power Group (US)



Toxic smoke warning for community

Chris McLennan

CFA crews have brought a fire at a Raywood solar farm under control.

Ten Country Fire Authority units responded to a fire at the solar farm about 28km north of Bendigo at 5.50pm on Thursday.

The solar farm was located in McQualters Road, Raywood.

While near Cohuna, one of Victoria's biggest solar farms has been out of action for almost a year. Built at a cost of around \$67 million in 2019, the Cohuna solar farm is still undergoing a refit after a fire in late 2023.

Meanwhile on Thursday, 10 CFA units from Bridgewater, Campbells Forest, Eaglehawk, Golden Square, Raywood and Wuodvale attended the Raywood solar farm fire.

Police and Powercor were

also on the scene. A transformer caught fire on the "moderately sized commercial solar farm" and crews used foam to extinguish it, the CFA said in a statement.

A warning was issued to the Raywood community because of the black toxic smoke drifting over the township.

"Access was difficult for crews because of the density of the smoke," the CFA said.

The scene was under control about 8.30pm.

Energy Safe Victoria is investigating the cause of the fire.

There was a small fire at a solar farm at Walla Walla, just north of Albury, back in early January as well.

Local farmers blamed the owner of the solar farm for failing to adequately maintain the grass around the farm. II Tooborac fire - page 10



A transformer at a central Victorian solar farm caught fire late on Thursday. Picture CFA















Advisory Note AN-004 Extinguishment of Li-Ion Battery Fires

This advisory note provides important information regarding the evaluation and verification of evidence of conformity for the extinguishment of Li-Ion batteries under the CSIRO Verification Services' ActivFire® Scheme.

With increasing usage of Li-Ion batteries in our daily lives, there has been an increase in documented fires, both in Australia and globally, caused by failure of Li-Ion batteries. Some of these fires have caused serious damage to properties in Australia, while fatalities have occurred overseas, throwing a spotlight onto the safety of Li-Ion batteries.

While a number of Li-lon battery fire extinguishment solutions have been proposed globally, no Australian Standard has been published to provide performance requirements for the extinguishment of fires related to Li-Ion batteries.

In Australia, the Australia Competition and Consumer Commission (ACCC) sets out a list of mandatory standards to make particular safety or information features on products compulsory for legal supply of the product into the Australian market. This includes portable aerosol fire extinguishers and portable non-aerosol fire extinguishers. More information can be found here: https://www.productsafety.gov.au/product-safetylaws/safety-standards-bans/mandatory-standards.

Accordingly, CSIRO Verification Services' ActivFire® Scheme advises its stakeholders that it has not and will not certify, and thus provide a Certificate of Conformity, that any fire extinguisher can effectively extinguish a Li-Ion battery fire.

CSIRO Verification Services' ActivFire* Scheme supports the development of an Australian Standard and/or acceptance of an internationally recognised Standard that includes performance requirements for the extinguishments of Li-Ion battery fires and will continue to work with key stakeholders in the development of such a Standard.

Please contact your local fire brigade in the case of a Li-Ion battery fire.

Issuing Authorities

Kai Loh, Executive Office, ActivFire scheme - CSIRO Verification Services

Tracey Gramlick, Deputy Director - Growth and Strategy, Infrastructure Technologies

Issue date

30-Nov-2023

As Australia's national science agency and innovation catalyst, CSIRO is solving the greatest challenges through innovative science and technology.

CSIRO. Unlocking a better future for everyone.

Contact us 1300 363 400 +61 3 9545 2176

csiroenquiries@csiro.au csiro.au

For further information CSIRO Conformity Services Branch conformityServices@csiro.au

ration 3 - house state: 30-Mory 2023 AN-004 W @ CSIRO Australia, 2023

Fuge 1 of 1



COMMONWEALTH PFAS BAN

Solar Panels + the Electrical Wiring sourced from China are both coated in PFOS (Perfluorooctane Sulfonate or Perfluorooctane Sulfonic Acid) listed as a Toxic Contaminant in the updated Australian Drinking Water Guidelines.

Lithium-ion Batteries are also a Toxic PFAS Contaminant.

Due to these 'Forever Chemicals' being linked to cancer, birth defects, liver disease, thyroid disease, plummeting sperm counts and a range of other serious health problems the <u>Commonwealth Government has</u> <u>effectively banned the import, use and</u> <u>manufacture of some of the more</u> <u>prominent types of PFAS (PFOS, PFOA</u> <u>and PFHxS) from 1 July 2025.</u> (21 Feb 2024)













CleanPeak E N E R G Y

NO UNAUTHORISED ACCESS BEYOND THIS POINT

ALL PERSONNEL MUST REPORT TO SITE OFFICE. ALL PERSONNEL MUST BE SITE INDUCTED BEFORE STARTING WORK ON THIS PROJECT SITE.

| METYHELKE | TOOL SECTION | PERSONAL F Equipment / C Must be worn | LOTHING (PPE) |
|-------------------------------------|--------------------------------|---|----------------------------|
| IN CASE OF EMERGENCY DIAL 000 | DANGER CONSTRUCTION SITE | ALL VISITORS MUST REPORT TO THE SITE OFFICE | AUTHORISED PERSONS ONLY |
| Project Name: | URADQUINT | V Salas | |
| Site Address: | 1268 May Ban | 2 DOLAR FARM | |
| Site Contact: | Heiner Guenze | ROAD URANGLOW | TY.NSW 2652 |
| Project Emergency Contact: | 0474 748 925 | /CPE Project Mommyu 0421818071/045340 | 0.1.42 |
| | Project Admin : | 0400 460 190 | 0 648 |





Akcome Optoelectronics (CN)

| aqoNew/Energy/Corp.(CN) | Vivint Solar (US) |
|--------------------------------|---|
| | CIMIC Group (AU) |
| | Consolidated Edison (US) |
| | Consolidated Electrical Distributors (US) |
| | Copenhagen Infrastructure Partners K/S (DK) |
| | DecmilGroup(AU) |
| | Elecnor SÅ(ES) |
| | Enel SpÅ(IT) |
| | Engie SÅ (FR) |
| JinkoSolar Holding Co Ltd (CN) | Fuji Electric Co (JP) |
| | Green Light Contractors Pty (AU) |
| | Henan Senyuan Electric Co (CN) |
| | Hengtong Optic:electric Co (CN) |
| | Linnotech Corp (JP) |
| | Jiawei Renewable Energy Co (CN) |
| | Kenya Electricity Generating Co PLC (KE) |
| | MAONENG Group (AU) |
| | Metka-Egn (GB) |
| _ | MVV/Energie/ÅG(DE) |
| | NextEra Energy (US) |
| | Sungrow, Power Supply, Co.(CN) |
| | Swinerton Builders (US) |
| | |

Sustainable Power Group (US)













