Document Control

Job No: 222078

Principal Author:	Issue.	Revision	Date
Michael Moutrie	-	Draft	18-10-2022
		Original for DA issued	30-10-2022
	А	Revised for NCC 2022	12-10-2023

report

Statement of Compliance Access for People with a Disability

Uniting Edinglassie ILUs 1-3 Emerald St Emu Plains

Accessible Building Solutions 124 Upper Washington Drive

Bonnet Bay NSW 2226



accessible buildina solutions

Report

Report Type:	Statement of Compliance - BCA Access Provisions
Development:	1-3 Emerald St, 6 & 8 Troy St Emu Plains

Introduction:

This report has been prepared to accompany a Development Application and has been based on the following drawings prepared by Group GSA:

A 2000	Basement Plan
A 2001-2004	Overall Floor Plans
A 2010-2012	Building A Plans
A 2020-2022	Building B Plans
A 2030-2032	Building C Plans
A 2040-2042	Building D Plans
A 2050-2052	Building E Plans

LA01-LA09 Landscape plans by Taylor Brammer

Limitations and Copyright information:

This report is not to be used for any other purpose than its original intention. The assessment is based on the provided drawings and compliance relies upon the implementation of all the recommendations listed in this report and the works constructed in accordance with AS1428.1-2009 and other latest, relevant standards and regulations applicable at the time of construction.

Assessment is based on the classification/use of the building. If the Class of the building changes to any other building Class, this access report will have to be updated accordingly.

This report and the drawings in this report are a copyright of Accessible Building Solutions and can only be used for the purposes of this particular project and can only be modified by Accessible Building Solutions. This document may also contain Standards Australia Ltd copyrighted material which may not be reproduced.

This report does not assess compliance matters related to WHS, Structural design, Services design, Parts of DDA other than those related to APS or Parts of BCA or Parts of Australian Standards other than those directly referenced in this report.

ABS gives no warranty or guarantee that this report is correct or complete and will not be liable for any loss arising from the use of this report. We are not to be held responsible if LHA comes to a different conclusion about compliance with the Livable Housing Guidelines. At this point of time only LHA is able to confirm whether a project has met all the requirements needed to be awarded a particular Quality Mark.

A report issued for DA (development application) is not suitable for use for CC (construction certificate application).

Job No 222078

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 2 of 19

P (Michael) 0450 334 995

- P (admin) 0415 255 163 E michael@absaccess.com.au

Assessment:

Assessment Criteria DA

This assessment has been undertaken to the extent necessary to issue development consent under the Environmental Planning and Assessment Act. Generally, assessment has been in regard to the capability of the proposal to achieve compliance where there is insufficient information to fully assess if compliance has been achieved. The project documentation should incorporate the requirements as listed in this report to ensure compliance.

Note: At design/drawing stage there is not enough information provided to ensure full compliance as a lot of access requirements depend on fittings and finishes. In this report "complies" means that, based on the drawings reviewed, the design is capable of compliance provided that dimensions, fittings and finishes are completed to the relevant standard.

Compliance is required with the following:

- The Access provisions of the BCA 2022
- The Access To Premises Standard
- AS1428 suite of Standards
- AS2890.6 for car parking
- AS1735.12 for lifts
- AS4299 Adaptable Housing
- SEPP Housing 2021 Chapter 3 Part 5
- Council's DCP relating to Access for People with a Disability

Assessment

The building work comprises of new independent living units in an existing seniors living village.

Under the BCA the building is classified as follows,

- Class 2 (building containing more than 2 SOUs i.e. sole-occupancy units)
- Class 7a (car park)
- Class 9b (assembly building)

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226 ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

P (Michael) 0450 334 995

Background

Uniting is responsible for the Uniting Church's ministry for older people, particularly those who are disadvantaged, vulnerable and isolated.

Uniting operates more than 200 aged care services, with more than 14,000 clients in residential and community care programs and employs over 3,500 full time equivalent staff across NSW/ACT. Uniting is the single largest provider of aged care services in NSW and the ACT.

The Edinglassie Village site has been identified by Uniting as in need of redevelopment.

A 73-bed nursing home and a 53 bed hostel have made way for the recently constructed 100 bed residential aged care facility and carparking, whilst existing 45 independent living units (ILUs) remain.

A local heritage listed sandstone chapel is located mid-way along the Emerald Street boundary. Nos 6 and 8 Troy Street are single storey residences located on the Western side of the site, to be incorporated into the redevelopment.

The site is relatively flat but does fall gently towards the south and west and is listed as flood affected on Council's maps, effected mainly by flood waters from the north and east.

There are several substantial and highly valued trees scattered across the site, primarily along the highway frontage.

Project Proposal

The existing 45 ILUs are in the south eastern and north western portions of the site and were constructed in the 1970's as villa style developments. Their design and features are out of step with contemporary demand and requiring increasing levels of maintenance to keep them to a serviceable condition. For these reasons, the proposal is to demolish and replace them with a more contemporary design and greater product mix that make greater use of the valuable site and provides Uniting an opportunity to accommodate and assist more residents in the Emu Plains area.

The proposed redevelopment will provide 147 ILU's with a unique identity and character that not only underpins all aspects of design and reflects the Uniting values, but also reflects upon Emu Plains as an established suburb in the west of Sydney.

Job No 222078

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 4 of 19

P (Michael) 0450 334 995

P (admin) 0415 255 163 E michael@absaccess.com.au

The following tables assess compliance with the relevant parts of the BCA and Standards **BCA Assessment**

	BCA Part D4 Access for People with a Disability BCA D4D2 Requirements for Access for people with a disability SOU refers to Sole Occupancy Unit
Requirement	 Class 2 From a required accessible pedestrian entrance to at least 1 floor with SOUs and to the entry of doors of each SOU on that level. To and within 1 of each type of room or space in common use. Where floor or part of a floor is accessed by an AS1428.1 ramp or lift, all SOUs on that level to the entry door and to and within all common use areas on that level.
Compliance	Complies.
Comments	Access has been provided from the main pedestrian entry to the entry doors of all SOUs on all levels by means of a lift. Access has been provided to communal open space on Ground Level. Details to be verified at CC stage of works.
Requirement	Class 7a To and within any level containing accessible carparking spaces.
Compliance Comments	Complies.
Comments	Access has been provided to the accessible car parking spaces by means of a lift. Details to be verified at CC stage of works.
Requirement	Class 9b- Assembly building not being a schools and early childhood centres To wheelchair seating spaces (numbers assessed further on in the report) To all areas except tiers that do not contain wheelchair seating spaces.
Compliance	Complies.
Comments	Details to be verified at CC stage of works.
Requirement	 In areas required to be accessible, the following is to be provided: Width of accessways shall be min 1M clear, and to be increased for door circulation, turning areas and passing areas as required by AS 1428.1 Doors shall provide a clear opening of 850mm with a step free threshold and the required circulation spaces, hardware and luminance contrast as required by AS 1428.1 The separation of doors in airlocks shall comply with AS 1428.1 Door mats, floor grates and the abutment of different finishes shall comply with BCA and AS 1428.1 In accessible sole occupancy units, the light switches shall be 30x30mm min size at a height to match the door handles. GPOs shall be located between 600 and 1100mm above the floor and 500mm from an internal corner.
Compliance	Complies.
Comments	All of the above listed requirements are achievable and to be assessed for compliance at verified at CC stage of works.

Job No 222078

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 5 of 19

	BCA Part D4D3 Access to buildings
Requirement	 Accessway is required from; Main pedestrian entry at the site boundary for new buildings
	Main pedestrian entry door for existing buildings
	 Any other accessible building connected by a pedestrian link Accessible car parking spaces
Compliance	Complies.
Comments	Access has been provided from the main pedestrian entry at the site boundary by means of a pathway / ramp.
	Access has been provided from accessible car parking spaces by means of a lift. Details to be verified at CC stage of works.
Requirement	Accessway is required through:
	 Main entry and Not less than 50% of all pedestrian entrances and in building with floor area over
Compliance	500m ² , non-accessible entry and accessible entry to be not more than 50M apart. Complies.
Comments	The development has only 1 main entry per building which has been designed to be
	accessible.
	Details to be verified at CC stage of works.
Requirement	 Where Accessible pedestrian entry has multiple doorways At least 1 to be accessible if 3 provided
	At least 50% to be accessible, if more than 3 provided
Compliance	Where doorway has multiple leaves, at least 1 leaf is to have clear opening of 850mm (excluding automatic doors).
Comments	Complies. Where multiple leaf doorways have been used, at least 1 operable leaf is required to
	provide a clear opening of 850mm with the door circulations spaces as per AS1428.1. Where single hinged doors have been used, the door leaf is required to provide a clear opening of 850mm with the door circulations spaces as per AS1428.1.
	This is achievable and the door selections are to be verified at CC stage of works.
Requirement	BCA Part D4D4 Parts of buildings required to be accessible Every Ramp (excluding fire-isolated ramp) to be compliant with AS1428.1 and slip resistance of ramp and landings compliant with BCA Table D3D15
Compliance	N/A
Comments	No ramps have been identified in the development.
Requirement Compliance	Every Walkway to be compliant with AS1428.1 Complies.
Comments	Detailed features of the walkways will be assessed with the requirements of AS1428.1 at the CC stage of works.
	Note: all walkways shall have a barrier or continue for a further 600mm in a different material on each side of the walkway.

Page 6 of 19

Requirement	Step / Kerb ramp if provided is to be compliant with AS1428.1 and Slip resistance of
	ramp and landings compliant with BCA Table D3D15
Compliance Comments	N/A No step / kerb ramps have been identified in the development.
Requirement	Every Stairway (excluding fire-isolated stairway) is to be compliant with AS1428.1 and
-	slip resistance of treads, landings and nosing strips compliant with BCA Table D3D15
Compliance Comments	N/A No stairways have been identified in the development.
Requirement	
Requirement	Every Fire-isolated Stairway is to be compliant with the relevant sections of AS1428.1 & slip resistance of treads, landings and nosing strips compliant with BCA Table D3D15
Compliance	Complies.
Comments	Where fire-isolated stairways have been provided, the features of the stairway will be assessed with the relevant requirements of AS1428.1 at the CC stage of works.
Requirement	Passing spaces requirement It is a requirement to provide passing spaces in accessways complying with AS1428.1 at maximum 20 M intervals, where a direct line of sight is not available. Space required is width of 1800mmx2800mm (in the direction of travel). Chamfer of 400x400mm is permitted at corners.
Compliance	N/A
Comments	There are no accessways over 20 M lengths in the development where a direct line of sight is not available.
Requirement	Turning spaces requirement It is a requirement to provide turning spaces in accessways complying with AS1428.1 within 2M of the end of accessways where it is not possible to continue travelling and at every 20M intervals. Space required is width of 1540mm x 2070mm (in the direction of travel).
Compliance	Complies.
Comments	Adequate turning spaces have been provided. Details to be verified at CC stage of works.
Requirement	Carpet specifications Carpet if used in areas required to be accessible are to be provided with pile height or thickness not more than 11mm and carpet backing not more than 4mm bringing the total height to a maximum of 15mm.
Compliance	Complies.
Comments	Only applies to carpets provided in the common use areas.
	Carpet selections generally take place at CC stage of works. Selection of carpets as specified above will lead to compliance and these selection details are to be verified at CC stage of works.

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 7 of 19

Requirement	 BCA Part D4D5 Exemptions Access is not required to be provided in the following areas : where access would be inappropriate because of the use of the area
	where area would pose a health and safety risk
Compliance	 any path which exclusively provides access to an exempted area For information only.
Comments	Areas such as lift machine rooms, fire services room, and mechanical rooms in the development are exempted from providing access under this clause due to WHS concerns.
	BCA Part D4D6 Accessible Carparking
Requirement	Parking Service Accessible carparking space need not be provided when a parking service is provided and direct access to any of the carparking spaces is not available to the public.
Compliance	N/A
Comments Requirement	Accessible car parking spaces shall have pavement marking in accordance with
Compliance	AS 2890.6. Complies.
Comments	Note: the pavement marking shall have the appropriate slip resistance for the location.
Requirement	Class 2 There are no carparking requirements for a Class 2 under the BCA. If adaptable housing has been mandated by the Council, carparking spaces will be required under the requirements of AS4299- Adaptable housing
Compliance Comments	N/A The parking for the residential units is assessed later in this report.
	BCA Part D4D7 Signage
Requirement	Braille and Tactile signage is required to identify Accessible & Ambulant Sanitary facilities, Fire Exits, areas with Hearing Augmentation and the location of Accessible entrances and toilets
Compliance	Complies.
Comments	
	BCA Part D4D8 Hearing Augmentation
Requirement	Hearing Augmentation is only required where an inbuilt amplification system (other than emergency) is installed in a Class 9b building, or in an auditorium, conference / meeting room or an reception area where a screen is used.
Compliance	Complies.
Comments	If inbuilt amplification system is proposed in the development, then hearing augmentation is to be provided.

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 8 of 19

	BCA Part D4D9 Tactile indicators (TGSIs)
Requirement	 TGSIs are required when approaching; Stairways other than fire-isolated stairways and stairways within a SOU of a Class 2 building or a non-accessible SOU of a Class 3 building Escalators / passenger conveyor / moving walk Ramp (other than fire-isolated ramps / kerb or step or swimming pool ramps) Under an overhead obstruction of <2M if no barrier is provided When accessway meets a vehicular way adjacent to a pedestrian entry (if no kerb / kerb ramp provided at the location) Compliance is required with AS1428.4.1 including Luminance contrast and slip resistance requirements for all TGSIs. TGSIs are not required in areas not required to be accessible
Compliance	Complies.
Comments	In the proposal, TGSIs are required in the following locations, except where excluded under the following section:
	 At top and bottom landings of stairways and 1:14 ramps, <u>600-800mm</u> depth or min 12 discrete cones are required at 300+/-10mm from edge of hazard At mid landings of stairway and 1:14 ramp, <u>300-400mm</u> depth or min 6 discrete cones are required <u>only where handrails are not continuous</u> or landing is more than 3M
	• Where accessway meets a vehicular way, 600-800mm depth or min 12 discrete
	 cones are required at 300+/-10mm from edge of hazard. Under the stairway to warn of overhead obstruction, 600-800mm depth or min 12 discrete cones are required at 300+/-10mm from edge of hazard Details to be verified at CC stage of works.
Requirement	 BCA Part D4D12 Limitations on Ramps A series of connecting ramps cannot have a vertical height of 3.6M
Requirement Compliance	
	 A series of connecting ramps cannot have a vertical height of 3.6M A landing for a step ramp cannot overlap a landing for another ramp
Compliance	 A series of connecting ramps cannot have a vertical height of 3.6M A landing for a step ramp cannot overlap a landing for another ramp N/A No ramps have been provided in the development.
Compliance Comments Requirement	 A series of connecting ramps cannot have a vertical height of 3.6M A landing for a step ramp cannot overlap a landing for another ramp N/A No ramps have been provided in the development. BCA Part D4D13 Glazing on Accessways Glazing requirements- Where there is no chair rail, handrail or transom, all frameless or fully glazed doors, sidelights and any glazing capable of being mistaken for a doorway or opening are required to have a glazing strip as per requirements of AS1428.1
Compliance Comments	 A series of connecting ramps cannot have a vertical height of 3.6M A landing for a step ramp cannot overlap a landing for another ramp N/A No ramps have been provided in the development. BCA Part D4D13 Glazing on Accessways Glazing requirements- Where there is no chair rail, handrail or transom, all frameless or fully glazed doors, sidelights and any glazing capable of being mistaken for a doorway or opening are required to have a glazing strip as per requirements of
Compliance Comments Requirement	 A series of connecting ramps cannot have a vertical height of 3.6M A landing for a step ramp cannot overlap a landing for another ramp N/A No ramps have been provided in the development. BCA Part D4D13 Glazing on Accessways Glazing requirements- Where there is no chair rail, handrail or transom, all frameless or fully glazed doors, sidelights and any glazing capable of being mistaken for a doorway or opening are required to have a glazing strip as per requirements of AS1428.1

Page 9 of 19

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

	BCA Part F Accessible Sanitary Facilities BCA F4D5 Accessible sanitary facilities
Requirement	
Compliance	Complies.
Comments	Common use unisex accessible toilet facilities have been provided in the development. Details to be verified at CC stage of works.
Requirement Compliance	Accessible unisex toilets are to be designed in accordance with AS1428.1 Complies.
Comments	The width and length requirements depend on selected fixtures.
	Minimum size of an accessible toilet is required to be 1.9M x 2.7M after tiling works. To be verified at CC stage of works.
Requirement	Ambulant use male / female toilets are to be provided if an additional toilet to the Accessible unisex toilet is provided.
Compliance	Complies
Comments	Separate Male & Female Ambulant facilities have been provided
Requirement Compliance	Ambulant use toilets are to be designed in accordance with AS1428.1. Complies with the width and length requirements
Comments	Minimum size of an accessible toilet is required to be 900mm to 920mm width x 1.62M (dependent on WC pan and location of door to the cubicle) To be verified at CC stage of works.
	BCA F4D6 Accessible unisex sanitary compartments
Requirement	Class 2 At least 1 when sanitary compartments are provided in common areas.
Compliance	N/A
Comments	No common use sanitary facilities have been proposed in the development.
Requirement	Class 5, 6, 7, 8 or 9 (excluding ward area of 9a health-care) 1 on every storey containing sanitary compartments. Where more than 1 bank of sanitary compartments on a level, at 50% of banks
Compliance	Complies.
Comments	To be verified at CC stage of works.

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 10 of 19

- P (Michael) 0450 334 995 P (admin) 0415 255 163 E michael@absaccess.com.au

	BCA F4D7 Requirements for Accessible unisex showers as per AS1428.1-2009
Requirement	•
	At least 1 when showers are provided in common areas.
Compliance	N/A
Comments	No common use shower facilities have been proposed in the development.
Requirement	Class 5, 6, 7, 8 or 9 (excluding ward area of 9a health-care) When BCA requires provision of 1 or more showers, then 1 for every 10 showers.
Compliance	N/A
Comments	No common use shower facilities have been proposed in the development.

Requirement	Class 9b
Nequilement	An accessible adult change facility is required where
	 The building is a sports venue or the like with a design occupancy of not less than
	35,000 spectators
	 The building contains a swimming pool with a perimeter of not less than 70m and that is required by Table D3.1 to be accessible
	• The building is a museum, gallery, theatre or the like with a design occupancy of not less than 1,500 patrons
	 The building is in a passenger use area of an airport terminal within an airport that accepts flights that are public transport services as defined in the Disability Standards for Accessible Public Transport 2002
Compliance	N/A
Comments	No accessible adult change facilities are required in the development.

BCA F4D12 Accessible Adult Change Facilities

Job No 222078

Page 11 of 19

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

	BCA Part E3 Lift Installations BCA E3D7 Lift Types & Limitations
Requirement	 The following limitations apply to the use of lifts: Stairway platform lifts must not serve a space accommodating more than 100 persons; used in high traffic areas such as theatres, auditoriums, traffic interchange, shopping centre; used where another type of lift can be installed; connect more than 2 storeys; when folded not encroach on the required width of the stair A low-rise platform lift must not travel more than 1m A low-rise constant pressure lift must not travel more than 2m if unenclosed or 4m if enclosed or be used in high traffic areas such as theatres, auditoriums, traffic interchange, shopping centre A small sized, low speed automatic lift must not travel more than 12m If the lift car is fully enclosed the lift must not rely on a constant pressure device for its operation
Compliance	Complies.
Comments	Details to be verified at CC stage of works. BCA E3D8 Lift Installations
Requirement	
	In an accessible building, every passenger lift must comply with Clause E3D8
Compliance	Capable of compliance
Comments	 Lift floor dimensions (excluding stairway platform lift) are listed below. Lifts traveling 12M or under, floor size, 1100mm wide x 1400mm deep Lifts travelling more than 12M, floor size 1400mm wide x 1600mm deep Details to be verified at CC stage of works.
Requirement	If the effective height of the building is over 12M, at least one of the lifts is required to be a stretcher lift, which is to accommodate a raised stretcher with clear space of not less than 600 x 2000mm long x 1400mm high above FFL.
Compliance	Complies.
Comments	Details to be verified at CC stage of works.

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 12 of 19

<u>SEPP Housing 2021 Chapter 3 Part 5</u> Compliance assessment with Schedule 4 of SEPP Housing 2021

Application	Requirement	Development is Seniors housing that consists of hostels or self- contained dwellings	
	Compliance Comment	Complies. The development consists of self- contained dwellings.	
Siting	Requirement	 To a site with gradient of < 1:10: ALL dwellings linked by an AS1428.1 compliant accessible path to an adjoining public road. Wheelchair Access To a site with gradient of > 1:10: The % of dwellings that must have wheelchair access (accessible) must equal the proportion of the site that has a gradient of less than 1:10, or 50%, whichever is the greater, and Accessible dwellings are to be linked by an AS1428.1 	
		compliant accessible path to an adjoining public road or an internal road or a driveway that is accessible to all residents. Common areas	
	Compliance	Access must be provided as per AS1428.1 to and within all common areas / facilities within the development. Complies.	
	Comment	Access has been provided to all dwellings by pathway from adjoining street. Access has been provided to the common areas. Details to be verified at CC stage of works.	
Security	Requirement	 Pathway lighting to be : Glare free for pedestrians and dwellings and Must provide at least 20 lux at ground level. 	
	Compliance Comment	Complies. Details to be verified at CC stage of works.	
Letterboxes	Requirement	 Letterboxes must be: Situated on a hard standing area and have wheelchair circulation and linked via an accessible path as per AS1428.1, Lockable and Located together in a central location adjacent to the street entry or, in the case of self-contained dwellings, must be located together in one or more central locations adjacent to the street the street entry. 	
	Compliance Comment	Complies. If the letterboxes are operable / lockable from the front (facing the street), then the hard standing area to be provided in front of the letterbox. Details to be verified at CC stage of works.	

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

Page 13 of 19

- P (Michael) 0450 334 995 P (admin) 0415 255 163 E michael@absaccess.com.au

Private car accommodation	Requirement Compliance Comment	 Car parking spaces (not being car parking for employees) must be: AS2890.6 compliant. 10% of car parking spaces or min 1 (if < than 10 spaces) must be able to be increased to 3.8M width. Provide power-operated door to garage, or power point and an area for motor or control rods to enable a power-operated door to be installed at a later date. Complies. The parking provided under the SEPP is on the basis that Uniting is a social housing provider and thus the required parking is 0.5 spaces per bedroom. Additional parking will be provided as standard spaces. Details to be verified at CC stage of works.
Accessible entry	Requirement	 Every entry to the dwelling must comply with Clause 4.3.1 and 4.3.2 of AS4299 i.e. : Slope at entry to be <1:40, 1550mm diameter landing with low threshold and smooth transition for wheelchair, 850mm clear door opening with circulation spaces and Door hardware as per AS1428.1.
	Compliance Comment	
Interior: general	Requirement Compliance Comment	Internal doorways must have: - 850mm a minimum clear opening space, - Internal corridors must have a minimum 1M width and - Door circulation spaces to AS 1428.1. Complies. Details to be verified at CC stage of works.
Main Bedroom	<i>Compliance</i> <i>Comment</i>	 At least 1 Bedroom within each dwelling must have, Wardrobe and bed sized as follows: In the case of a dwelling in a hostel—a single-size bed, and In the case of a self-contained dwelling—a queen-size bed. Bedroom must contain a clear area for the bed of at least: 1,200mm wide at the foot of the bed, and 1,000mm wide beside the bed between it and the wall, wardrobe or any other obstruction. Bedroom must have, 2 double general power outlets on the wall where the head of the bed is likely to be Bedroom must have at least one general power outlet on the wall opposite the wall where the head of the bed of the bed is likely to be. Bedroom must have a telephone outlet next to the bed on the side closest to the door and a general power outlet beside the telephone outlet. Bedroom must have wiring to allow a potential illumination level of at least 300 lux. Complies. Details to be verified at CC stage of works.

Jo	bb	No	22	207	'8

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 14 of 19

Bathroom	Compliance	At least one bathroom must be on ground / main floor and circulation space for sanitary facilities must be provided in accordance with AS 1428.1 Bathroom must have shower as per AS1428.1 including shower circulation spaces. Shower to be: - Without a hob - Waterproofed to AS 3740 - Floor falls to waste - Walls reinforced to accommodate grabrails / folding seat in the future - Taps to be lever or capstan with single outlet - Taps to be lever or capstan with single outlet - Taps to be easily reached from shower entry The following can be accommodated either immediately or in the future , - A grab rail - Portable shower head - Folding seat Bathroom must have wall cabinet that is sufficiently illuminated Bathroom must have a double general power outlet beside the mirror Complies.
	Comment	
Toilet	Requirement	 A visitable toilet must be provided as per of AS 4299 on ground floor including: Space of 900mm x 1250mm required in front of the WC pan Slip resistant floor and
	Compliance	 Capability of accommodating grabrails as per AS1428.1
	Compliance Comment	
Surface finishes	Requirement Compliance Comment	Balconies and external paved areas must have slip-resistant surfaces. Complies. Details to be verified at CC stage of works.
Door hardware	Requirement Compliance Comment	Door handles and hardware for all doors must be provided in accordance with AS 4299 - Single hand operation, lever style, - Operation located between 900-100mm above FFL and All external doors to be keyed alike Complies. Details to be verified at CC stage of works.
Ancillary items	Requirement	 Switches and power points must be provided in accordance with AS 4299 Switches located between 900-1000mm and in line with door handles, Rocker action / toggle / push pad switches with 35mm width are preferred and GPOs to be at least 600mm above FFL (1000mm preferred) and not less than 500mm horizontally from internal corners.
	Compliance Comment	

Addition requirements for any seniors housing consisting of self-contained dwellings are listed below

Job No 222078

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 15 of 19

		P	
Living room and Dining room	Requirement Compliance Comment	 Living room must have Circulation space in accordance with clause 4.7.1 of AS 4299 i.e. 2250mm diameter Telephone adjacent to a general power outlet. Living and dining room must have wiring to allow a potential illumination level of at least 300 lux. Complies. Details to be verified at CC stage of works. 	
Kitchen	Requirement	 1550mm must be provided between benches as per Clause 4.5.2 of AS4299 Circulation spaces must be provided at the door (if provided) as per AS1428.1 Following fittings must be provided as per Clause 4.5 of AS 4299: 800mm wide work surface which is adjustable or a replaceable as a unit at variable heights within range of 750mm to 850mm above FFL, Tap set with capstan or lever handles with the taps or operating handles to be located 300mm from front of the sink, Cooktops with front or side controls with raised crossbars, isolating switch and a work surface of 800mm length at the same height and Wall oven located next to adjustable height work bench minimum 800mm width and where oven is hinged, the clear work surface is to be on the opposite side of the hinge. "D" pull cupboard handles must be provided such that they are located towards the top of below-bench cupboards and towards the bottom of overhead cupboards GPO outlets must be provided as follows: At least one double general power outlet within 300 millimeters of the front of a work surface, and At least one GPO provided for a refrigerator in such a position as to be easily accessible after the refrigerator is 	
	Compliance Comment	Complies. Details to be verified at CC stage of works.	
Access	Requirement Compliance Comment	Access to kitchen, main bedroom, bathroom / toilet In a multi-storey self-contained dwelling, the kitchen, main bedroom, bathroom and toilet must be located on the entry level N/A	
Lifts in multi- storey buildings	Requirement	In a multi-storey building containing separate self-contained dwellings on different storeys, lift access must be provided to dwellings above the ground level of the building by way of a lift complying with clause E3.6 of the BCA	
	Compliance Comment	N/A	

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 16 of 19

Laundry	Requirement Compliance Comment	
Storage	Requirement Compliance Comment	of AS4299 i.e. 600mm minimum width and adjustable shelving Complies.
Garbage	Requirement Compliance Comment	A garbage storage area must be provided in an accessible location. Complies. Details to be verified at CC stage of works.

Statement of Compliance

On the basis of the above assessment, I am satisfied that the proposal can achieve compliance with the access provisions of the BCA and the Access to Premises Standard.

Munth

Michael Moutrie ACAA Accredited Access Consultant No 581

Job No 222078

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 17 of 19



Statement of experience

	Michael Moutrie Director, Accessible Building Solutions
<image/>	Qualifications: ACAA Accredited Access Consultant No 581 Certificate IV in Access Consulting Registered Assessor of Livable Housing Australia (License no 20265) Registered Changing Places assessor (No 021) Completed SDA Assessor training OH&S Induction Training Certificate Michael is a member of Camden Council's Access Committee Michael started working in Access in 2015 and became a director of Accessible Building Solutions in 2018. Combining his background in fitness and travel, Michael has an interest in the application of accessibility to recreational activities and has been involved with the access award winning Wet'n' Wild Sydney, Jamberoo Action Park and numerous Leisure Centres. Michael is experienced in the following areas: Building audits Access Reports for DA & CC Livable Housing Assessment Changing Places assessment Expert witness in the Land & Environment Court of NSW Michael maintains a high level of continuing professional education and has published articles in the ACAA Insight magazine.
ACCREDITED MEMBER Howard Moutrie: 177	Howard Moutrie Consultant Qualifications: • • B. Arch (Hons) Registered Architect ARB Reg. No 4550 • ACAA Accredited Access Consultant Reg. No. 177 • Registered Assessor of Livable Housing Australia (License no 10054) • Registered Changing Places assessor (No 007)
Assessor Livable Howard Moutrie	Howard has been or is a member of the following: Standards Australia ME/64 Committee (Access Standards) Sutherland Council Design Review Panel & Access Committee City of Sydney Access Panel 2010 Building Professionals Board Access Advisory Panel ACAA Management Committee
S 2020	 Howard Moutrie is an experienced access consultant with over 15 years experience. Howard has contributed for over 10 years on the Standards Australia Committee ME/64, providing input into the AS 1428 suite of Standards and the Adaptable Housing Standard has acted as an expert witness in the Land & Environment Court. Howard has presented at numerous seminars and training sessions including ACAA National Conference, ACAA State Network Seminars, RAIA Network Seminars, Building Designers Association Seminars.

Job No 222078

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 18 of 19

Accessible Building Solutions 124 Upper Washington Drive, Bonnet Bay NSW 2226

ABN 58 006 628 812 The Trustee For The Howard & Anne Moutrie Family Trust

Page 19 of 19