

Principal Author: Michael Moutrie
Reviewed: Howard Moutrie

Issue.	Revision	Date
-	Original for DA issued	05-12-2019



report

Statement of Compliance Access for People with a Disability

Stratford House Lifestyle Village

Rockford Rd Tahmoor

Accessible Building Solutions

124 Upper Washington Drive
Bonnet Bay NSW 2226

P 0415 255 163

E howard@absaccess.com.au

Accredited Access Consultant
Howard Moutrie ACAA No 177

Report

Report Type: Statement of Compliance - BCA Access Provisions
Development: Stratford House Lifestyle Village

Introduction:

This report has been prepared to accompany a Development Application and has been based on the following drawings prepared by McCabe Architects:

TP 003	Masterplan
TP 104	Communal Building Ground Floor Plan
TP 105	Communal Building First Floor Plan
TP 200	Type A Plan
TP 201	Type B Plan
TP 202	Type C Plan
TP 203	Type D Plan
TP 204	Type E Plan
TP 205	Type F Plan

Limitations and Copyright information:

This report is not to be used for any other purpose than its original intention. The assessment is based on the provided drawings and compliance relies upon the implementation of all the recommendations listed in this report and the works constructed in accordance with AS1428.1-2009 and other latest, relevant standards and regulations applicable at the time of construction.

Assessment is based on the classification/use of the building. If the Class of the building changes to any other building Class, this access report will have to be updated accordingly.

All dimensions mentioned in the report are CLEAR dimensions and are not to be reduced by projecting skirting, kerbs, handrails, lights, fire safety equipment, door handles less than 900mm above FFL (finished floor level) or any other fixtures/fit out elements. Only some numerical requirements from relevant AS (Australian Standards) have been noted in the report, however for further details and for construction purposes refer to the relevant AS, a copy of which can be purchased from SAI Global.

This report and the drawings in this report are a copyright of Accessible Building Solutions and can only be used for the purposes of this particular project and can only be modified by Accessible Building Solutions. This document may also contain Standards Australia Ltd copyrighted material which may not be reproduced.

This report does not assess compliance matters related to WHS, Structural design, Services design, Parts of DDA other than those related to APS or Parts of BCA or Parts of Australian Standards other than those directly referenced in this report.

ABS gives no warranty or guarantee that this report is correct or complete and will not be liable for any loss arising from the use of this report. We are not to be held responsible if LHA comes to a different conclusion about compliance with the Livable Housing Guidelines. At this point of time only LHA is able to confirm whether a project has met all the requirements needed to be awarded a particular Quality Mark.

We have no ability to check for slip resistance of surfaces. All wet areas, parking areas, pavement markings shall have the appropriate slip resistance for the location. We also have no ability to check for wall reinforcements once the walls have already been constructed. The builder is to take full responsibility that these requirements are met as a part of construction being as per requirements of AS1428.1/ AS4299 / AS2890.6/ AS3661/ AS4586

A report issued for DA (development application) is not suitable for use for CC (construction certificate application).

Assessment:

Assessment Criteria DA

This assessment has been undertaken to the extent necessary to issue development consent under the Environmental Planning and Assessment Act. Generally, assessment has been in regard to the capability of the proposal to achieve compliance where there is insufficient information to fully assess if compliance has been achieved. The project documentation should incorporate the requirements as listed in this report to ensure compliance.

Note: At design/drawing stage there is not enough information provided to ensure full compliance as a lot of access requirements depend on fittings and finishes. Where this report lists "capable of compliance" it means that there is nothing to stop full compliance as long as fittings and finishes are completed to the relevant standard

Compliance is required with the following:

- The Access Provisions of the BCA 2019
- The Access To Premises Standard
- AS1428 suite of Standards
- AS2890.6 for car parking
- AS1735.12 for lifts
- SEPP Housing for Seniors or People with a Disability
- Council's DCP relating to Access for People with a Disability

Assessment

The building work comprises of seniors living townhouses with community buildings and offstreet carparking

Under the BCA the building is classified as follows,

- Class 1a (detached house or attached dwellings such as townhouse or villas)
- Class 7a (car park)
- Class 9b (assembly building)
- Class 10b (pool)

Where the building is existing, the new work and the affected part must comply with the BCA. The affected part will be assessed in detail at the CC stage.

Note: There are no access requirements in the BCA for Class 1a buildings

The following tables assess compliance with the relevant parts of the BCA and Standards
BCA Assessment

BCA Part D3 Access for People with a Disability
BCA D3.1 Requirements for Access for people with a disability
 SOU refers to Sole Occupancy Unit

Requirement	Class 7a
Compliance	To and within any level containing accessible carparking spaces.
Comments	N/A No accessible parking is required or provided
Requirement	Class 9b- Assembly building not being a schools and early childhood centres
Compliance	To wheelchair seating spaces (numbers assessed further on in the report) <ul style="list-style-type: none"> To all areas except tiers that do not contain wheelchair seating spaces. Complies.
Comments	Details to be verified at CC stage of works.
Requirement	Class 10b
Compliance	Swimming pool associated with Class 1b, 2, 3, 5, 6, 7, 8 or 9 (except for a pool for the exclusive use of a SOU) with perimeter more than 40M.
Comments	N/A Pool is existing
Requirement	In areas required to be accessible, the following is to be provided: <ul style="list-style-type: none"> Width of accessways shall be min 1M clear, and to be increased for door circulation, turning areas and passing areas as required by AS 1428.1 Doors shall provide a clear opening of 850mm with a step free threshold and the required circulation spaces, hardware and luminance contrast as required by AS 1428.1 The separation of doors in airlocks shall comply with AS 1428.1 Door mats, floor grates and the abutment of different finishes shall comply with BCA and AS 1428.1 In accessible sole occupancy units, the light switches shall be 30x30mm min size at a height to match the door handles. GPOs shall be located between 600 and 1100mm above the floor and 500mm from an internal corner.
Compliance	Capable of compliance.
Comments	All of the above listed requirements are achievable and to be assessed for compliance at verified at CC stage of works.
Requirement	BCA Part D3.2 Access to buildings
Compliance	Accessway is required from; <ul style="list-style-type: none"> Main pedestrian entry at the site boundary for new buildings Main pedestrian entry door for existing buildings Any other accessible building connected by a pedestrian link Accessible car parking spaces Complies.
Comments	Access has been provided from the main pedestrian entry at the site boundary by means of a pathway / ramp. Details to be verified at CC stage of works.

Requirement	Accessway is required through: <ul style="list-style-type: none"> • Main entry and • Not less than 50% of all pedestrian entrances and in building with floor area over 500m², non-accessible entry and accessible entry to be not more than 50M apart.
Compliance	Capable of compliance.
Comments	The development has only 1 main entry which has been designed to be accessible. Details to be verified at CC stage of works.
Requirement	Where Accessible pedestrian entry has multiple doorways <ul style="list-style-type: none"> • At least 1 to be accessible if 3 provided • At least 50% to be accessible, if more than 3 provided Where doorway has multiple leaves, at least 1 leaf is to have clear opening of 850mm (excluding automatic doors).
Compliance	Capable of compliance.
Comments	Where multiple leaf doorways have been used, at least 1 operable leaf is required to provide a clear opening of 850mm with the door circulations spaces as per AS1428.1. Where single hinged doors have been used, the door leaf is required to provide a clear opening of 850mm with the door circulations spaces as per AS1428.1. This is achievable and the door selections are to be verified at CC stage of works.
Requirement	BCA Part D3.3 Parts of buildings required to be accessible Every Ramp (excluding fire-isolated ramp) to be compliant with AS1428.1 and slip resistance of ramp and landings compliant with BCA Table D2.14
Compliance	N/A
Comments	No ramps have been identified in the development.
Requirement	Every Walkway to be compliant with AS1428.1
Compliance	Capable of compliance.
Comments	Detailed features of the walkways will be assessed with the requirements of AS1428.1 at the CC stage of works. Note: all walkways shall have a barrier or continue for a further 600mm in a different material on each side of the walkway.
Requirement	Step / Kerb ramp if provided is to be compliant with AS1428.1 and Slip resistance of ramp and landings compliant with BCA Table D2.14
Compliance	Capable of compliance.
Comments	Detailed features of the ramp will be assessed with the requirements of AS1428.1 at the CC stage of works.
Requirement	Every Stairway (excluding fire-isolated stairway) is to be compliant with AS1428.1 and slip resistance of treads, landings and nosing strips compliant with BCA Table D2.14
Compliance	Capable of compliance.
Comments	Where non-fire-isolated stairways have been provided, the features of the stairway will be assessed with the requirements of AS1428.1 at the CC stage of works.
Requirement	Every Fire-isolated Stairway is to be compliant with the relevant sections of AS1428.1 & slip resistance of treads, landings and nosing strips compliant with BCA Table D2.14
Compliance	N/A
Comments	No fire-isolated stairways have been identified in the development

Requirement	Passing spaces requirement It is a requirement to provide passing spaces in accessways complying with AS1428.1 at maximum 20 M intervals, where a direct line of sight is not available. Space required is width of 1800mmx2800mm (in the direction of travel). Chamfer of 400x400mm is permitted at corners.
Compliance	N/A
Comments	There are no accessways over 20 M lengths in the development where a direct line of sight is not available.
Requirement	Turning spaces requirement It is a requirement to provide turning spaces in accessways complying with AS1428.1 within 2M of the end of accessways where it is not possible to continue travelling and at every 20M intervals. Space required is width of 1540mm x 2070mm (in the direction of travel).
Compliance	Complies.
Comments	Adequate turning spaces have been provided. Details to be verified at CC stage of works.
Requirement	Carpet specifications Carpet if used in areas required to be accessible are to be provided with pile height or thickness not more than 11mm and carpet backing not more than 4mm bringing the total height to a maximum of 15mm.
Compliance	Capable of compliance
Comments	Only applies to carpets provided in the resident use areas. Carpet selections generally take place at CC stage of works. Selection of carpets as specified above will lead to compliance and these selection details are to be verified at CC stage of works.
Requirement	BCA Part D3.4 Exemption Access is not required to be provided in the following areas : <ul style="list-style-type: none"> • where access would be inappropriate because of the use of the area • where area would pose a health and safety risk • any path which exclusively provides access to an exempted area
Compliance	For information only.
Comments	Areas such as lift machine rooms, fire services room, and mechanical rooms in the development are exempted from providing access under this clause due to WHS concerns.
Requirement	BCA Part D3.5 Accessible Carparking Parking Service Accessible carparking space need not be provided when a parking service is provided and direct access to any of the carparking spaces is not available to the public.
Compliance	N/A
Comments	
Requirement	Accessible car parking spaces shall have pavement marking in accordance with AS 2890.6.
Compliance	N/A
Comments	

Requirement	In situations where not more than 5 carparking spaces have been provided The car parking space need not be designated, so as to restrict the use of the carparking space only for people with a disability.
Compliance	N/A
Comments	
Requirement	BCA Part D3.6 Signage Braille and Tactile signage is required to identify Accessible & Ambulant Sanitary facilities, Fire Exits, areas with Hearing Augmentation and the location of Accessible entrances and toilets
Compliance	Capable of compliance.
Comments	
Requirement	BCA Part D3.7 Hearing Augmentation Hearing Augmentation is only required where an inbuilt amplification system (other than emergency) is installed in a Class 9b building, or in an auditorium, conference / meeting room or an reception area where a screen is used.
Compliance	Capable of compliance.
Comments	If inbuilt amplification system is proposed in the development, then hearing augmentation is to be provided.
Requirement	Where Hearing Augmentation is provided in form of an induction loop, it must be provided to not less than 80% of the floor area.
Compliance	
Comments	
Requirement	BCA Part D3.8 Tactile indicators (TGSIs) TGSIs are required when approaching; <ul style="list-style-type: none"> - Stairways other than fire-isolated stairways and stairways within a SOU of a Class 2 building or a non-accessible SOU of a Class 3 building - Escalators / passenger conveyor / moving walk - Ramp (other than fire-isolated ramps / kerb or step or swimming pool ramps) - Under an overhead obstruction of <2M if no barrier is provided - When accessway meets a vehicular way adjacent to a pedestrian entry (if no kerb / kerb ramp provided at the location) Compliance is required with AS1428.4.1 including Luminance contrast and slip resistance requirements for all TGSIs.
Compliance	Capable of compliance.
Comments	In the proposal, TGSIs are required in the following locations: <ul style="list-style-type: none"> • At <u>top and bottom landings</u> of stairways and 1:14 ramps, <u>600-800mm</u> depth or min 12 discrete cones are required at 300+/-10mm from edge of hazard • At <u>mid landings</u> of stairway and 1:14 ramp, <u>300-400mm</u> depth or min 6 discrete cones are required <u>only where handrails are not continuous</u> or landing is more than 3M • Where accessway meets a vehicular way, 600-800mm depth or min 12 discrete cones are required at 300+/-10mm from edge of hazard. • Under the stairway to warn of overhead obstruction, 600-800mm depth or min 12 discrete cones are required at 300+/-10mm from edge of hazard Details to be verified at CC stage of works.

Glazing strip selections are to be verified at CC stage of works.

BCA Part F Accessible Sanitary Facilities
BCA F2.4 Accessible sanitary facilities

<i>Requirement</i>	Accessible unisex toilet is to be provided in accessible part of building such that; <ul style="list-style-type: none"> • It can be entered without crossing an area reserved for 1 sex only • Where male and female sanitary facilities are provided at different locations, Accessible unisex toilet is only required at one of the locations • Even distribution of LH and RH facilities If no lift is required to be provided to a level, then accessible facility is not required on that level.
<i>Compliance</i>	Complies.
<i>Comments</i>	Common use unisex accessible toilet facilities have been provided in the development. Details to be verified at CC stage of works.
<i>Requirement</i>	Accessible unisex toilet are to be designed in accordance with AS1428.1
<i>Compliance</i>	Capable of compliance
<i>Comments</i>	<p>The width and length requirements depend on selected fixtures.</p> <p>Minimum size of an accessible toilet is required to be 1.9M x 2.7M after tiling works. To be verified at CC stage of works.</p>
<i>Requirement</i>	Ambulant use male / female toilets are to be provided if an additional toilet to the Accessible unisex toilet is provided.
<i>Compliance</i>	Complies
<i>Comments</i>	<p>The following Ambulant facilities have been provided</p> <p>2 Male Ambulant use toilets + 2 Female Ambulant use toilets</p>
<i>Requirement</i>	Ambulant use toilets are to be designed in accordance with AS1428.1.
<i>Compliance</i>	Complies with the width and length requirements
<i>Comments</i>	<p>Minimum size of an accessible toilet is required to be 900mm to 920mm width x 1.62M (dependent on WC pan and location of door to the cubicle)</p> <p>To be verified at CC stage of works.</p>
<i>Requirement</i>	BCA F2.4(a) Accessible unisex sanitary compartments Class 5, 6, 7, 8 or 9 (excluding ward area of 9a health-care) 1 on every storey containing sanitary compartments. Where more than 1 bank of sanitary compartments on a level, at 50% of banks
<i>Compliance</i>	Complies.
<i>Comments</i>	To be verified at CC stage of works.
<i>Requirement</i>	BCA F2.4(b) Requirements for Accessible unisex showers as per AS1428.1-2009 Class 5, 6, 7, 8 or 9 (excluding ward area of 9a health-care) When BCA requires provision of 1 or more showers, then 1 for every 10 showers.
<i>Compliance</i>	Complies.
<i>Comments</i>	To be verified at CC stage of works.

BCA Part E Lift Installations

<i>Requirement</i>	In an accessible building, every passenger lift must comply with Tables E3.6(a) and E3.6(b).
<i>Compliance</i>	Capable of compliance
<i>Comments</i>	<p>Lift floor dimensions (excluding stairway platform lift) are listed below.</p> <ul style="list-style-type: none"> • Lifts traveling 12M or under, floor size, 1100mm wide x 1400mm deep • Lifts travelling more than 12M, floor size 1400mm wide x 1600mm deep <p>Details to be verified at CC stage of works.</p>
<i>Requirement</i>	If the effective height of the building is over 12M, at least one of the lifts is required to be a stretcher lift, which is to accommodate a raised stretcher with clear space of not less than 600 x 2000mm long x 1400mm high above FFL.
<i>Compliance</i>	Capable of compliance
<i>Comments</i>	Details to be verified at CC stage of works.

Application of Access to Premises Standards (APS) to existing buildings
Affected part upgrades

<i>Requirement</i>	<ul style="list-style-type: none"> • In general, APS covers new building work to existing buildings, such as an extension or upgrade • APS only apply to that part of the building that is the subject of the building approval application and the 'affected part' • Application of the APS to new work in an existing building does not trigger the need to upgrade the whole building or parts of the building outside the new work that is subject to the building approval application • The definition of 'affected part' of a building is limited to the area between (and including) the principal pedestrian entrance and the new work, but does not extend from the entrance to the allotment boundary or any required carparking spaces. It also does not extend to any toilet facilities or other rooms adjacent to the pathway between the principal pedestrian entrance and the area of the new work • When the 'affected part' is triggered it does not require access upgrades to any step or stairway adjacent to a continuous accessible path of travel • Where an access barrier, such as a step, is located at the threshold of a principal pedestrian entrance the 'affected part' upgrade would require the removal of the step
<i>Compliance</i>	Capable of compliance
<i>Comments</i>	Existing doors to poolhouse may need to be widened. Details to be verified at CC stage of works.

SEPP Housing for Seniors and People with Disability 2004

Compliance assessment with Schedule 3 of SEPP Housing for Seniors or People with a Disability

<i>Application</i>	<i>Requirement</i>	Development is Seniors housing that consists of hostels or self-contained dwellings
	<i>Compliance Comment</i>	Complies. The development consists of self- contained dwellings.
<i>Siting</i>	<i>Requirement</i>	Wheelchair Access To a site with gradient of < 1:10: <ul style="list-style-type: none">- ALL dwellings linked by an AS1428.1 compliant accessible path to an adjoining public road.
	<i>Requirement</i>	Wheelchair Access To a site with gradient of > 1:10: <ul style="list-style-type: none">- The % of dwellings that must have wheelchair access (accessible) must equal the proportion of the site that has a gradient of less than 1:10, or 50%, whichever is the greater, and- Accessible dwellings are to be linked by an AS1428.1 compliant accessible path to an adjoining public road or an internal road or a driveway that is accessible to all residents.
	<i>Compliance Comment</i>	Common areas Access must be provided as per AS1428.1 to and within all common areas / facilities within the development. Complies. Access has been provided to all dwellings by pathway from adjoining street. Access has been provided to the common areas. Details to be verified at CC stage of works.
	<i>Compliance Comment</i>	
<i>Security</i>	<i>Requirement</i>	Pathway lighting to be : <ul style="list-style-type: none">- Glare free for pedestrians and dwellings and- Must provide at least 20 lux at ground level.
	<i>Compliance Comment</i>	Capable of compliance Details to be verified at CC stage of works.
<i>Letterboxes</i>	<i>Requirement</i>	Letterboxes must be: <ul style="list-style-type: none">- Situated on a hard standing area and have wheelchair circulation and linked via an accessible path as per AS1428.1,- Lockable and- Located together in a central location adjacent to the street entry or, in the case of self-contained dwellings, must be located together in one or more central locations adjacent to the street entry.
	<i>Compliance Comment</i>	Capable of compliance If the letterboxes are operable / lockable from the front (facing the street), then the hard standing area is to be provided in front of the letterbox. Details to be verified at CC stage of works.

Private car accommodation	Requirement	<p>Car parking spaces (not being car parking for employees) must be:</p> <ul style="list-style-type: none"> - AS2890.1 compliant i.e. 3.2M x 5.4M (3.8M width if in an enclosed garage) and - Provided with 2.5M internal height clearance and 2.2M height clearance at garage door. <p>5% of car parking spaces or min 1 (if < than 20 spaces) must be able to be increased to 3.8M width.</p> <p>Provide power-operated door to garage, or power point and an area for motor or control rods to enable a power-operated door to be installed at a later date.</p> <p>Capable of compliance</p> <p>Details to be verified at CC stage of works.</p>
Accessible entry	Requirement	<p>Every entry to the dwelling must comply with</p> <p>Clause 4.3.1 and 4.3.2 of AS4299 i.e. :</p> <ul style="list-style-type: none"> - Slope at entry to be <1:40, - 1550mm diameter landing with low threshold and smooth transition for wheelchair, - 850mm clear door opening with circulation spaces and - Door hardware as per AS1428.1. <p>Capable of compliance</p> <p>Details to be verified at CC stage of works.</p>
Interior: general	Requirement	<p>Internal doorways must have:</p> <ul style="list-style-type: none"> - 850mm a minimum clear opening space, - Internal corridors must have a minimum 1M width and - Door circulation spaces to AS 1428.1.
	Compliance Comment	<p>Capable of compliance</p> <p>Details to be verified at CC stage of works.</p>
Main Bedroom		<p>At least 1 Bedroom within each dwelling must have,</p> <p>Wardrobe and bed sized as follows:</p> <ul style="list-style-type: none"> - In the case of a dwelling in a hostel—a single-size bed, and - In the case of a self-contained dwelling—a queen-size bed. <p>Bedroom must contain a clear area for the bed of at least:</p> <ul style="list-style-type: none"> - 1,200mm wide at the foot of the bed, and - 1,000mm wide beside the bed between it and the wall, wardrobe or any other obstruction. <p>Bedroom must have 2 double general power outlets on the wall where the head of the bed is likely to be</p> <p>Bedroom must have at least one general power outlet on the wall opposite the wall where the head of the bed is likely to be.</p> <p>Bedroom must have a telephone outlet next to the bed on the side closest to the door and a general power outlet beside the telephone outlet.</p> <p>Bedroom must have wiring to allow a potential illumination level of at least 300 lux.</p> <p>Capable of compliance</p> <p>Details to be verified at CC stage of works.</p>
	Compliance Comment	

<i>Bathroom</i>	<i>Requirement</i>	<p>At least one bathroom must be on ground / main floor and circulation space for sanitary facilities must be provided in accordance with AS 1428.1</p> <p>Bathroom must have shower as per AS1428.1 including shower circulation spaces. Shower to be:</p> <ul style="list-style-type: none"> - Without a hob - Waterproofed to AS 3740 - Floor falls to waste - Walls reinforced to accommodate grabrails / folding seat in the future - Taps to be lever or capstan with single outlet - Taps to be easily reached from shower entry <p>The following can be accommodated either immediately or in the future,</p> <ul style="list-style-type: none"> - A grab rail - Portable shower head - Folding seat <p>Bathroom must have wall cabinet that is sufficiently illuminated</p> <p>Bathroom must have a double general power outlet beside the mirror</p>
	<i>Compliance Comment</i>	<p>Capable of compliance</p> <p>Details to be verified at CC stage of works.</p>
<i>Toilet</i>	<i>Requirement</i>	<p>A visitable toilet must be provided as per of AS 4299 on ground floor including:</p> <ul style="list-style-type: none"> - Space of 900mm x 1250mm required in front of the WC pan - Slip resistant floor and - Capability of accommodating grabrails as per AS1428.1
	<i>Compliance Comment</i>	<p>Capable of compliance</p> <p>Details to be verified at CC stage of works.</p>
<i>Surface finishes</i>	<i>Requirement</i>	Balconies and external paved areas must have slip-resistant surfaces.
	<i>Compliance Comment</i>	<p>Capable of compliance</p> <p>Details to be verified at CC stage of works.</p>
<i>Door hardware</i>	<i>Requirement</i>	<p>Door handles and hardware for all doors must be provided in accordance with AS 4299</p> <ul style="list-style-type: none"> - Single hand operation, lever style, - Operation located between 900-1000mm above FFL and <p>All external doors to be keyed alike</p>
	<i>Compliance Comment</i>	<p>Capable of compliance</p> <p>Details to be verified at CC stage of works.</p>
<i>Ancillary items</i>	<i>Requirement</i>	<p>Switches and power points must be provided in accordance with AS 4299</p> <ul style="list-style-type: none"> - Switches located between 900-1000mm and in line with door handles, - Rocker action / toggle / push pad switches with 35mm width are preferred and - GPOs to be at least 600mm above FFL (1000mm preferred) and not less than 500mm horizontally from internal corners.
	<i>Compliance Comment</i>	<p>Capable of compliance</p> <p>Details to be verified at CC stage of works.</p>

Addition requirements for any seniors housing consisting of self-contained dwellings are listed below

Living room and Dining room	Requirement	Living room must have <ul style="list-style-type: none"> - Circulation space in accordance with clause 4.7.1 of AS 4299 i.e. 2250mm diameter - Telephone adjacent to a general power outlet. Living and dining room must have wiring to allow a potential illumination level of at least 300 lux.
	Compliance Comment	Capable of compliance Details to be verified at CC stage of works.
Kitchen	Requirement	1550mm must be provided between benches as per Clause 4.5.2 of AS4299 Circulation spaces must be provided at the door (if provided) as per AS1428.1 Following fittings must be provided as per Clause 4.5 of AS 4299: <ul style="list-style-type: none"> - 800mm wide work surface which is adjustable or a replaceable as a unit at variable heights within range of 750mm to 850mm above FFL, - Tap set with capstan or lever handles with the taps or operating handles to be located 300mm from front of the sink, - Cooktops with front or side controls with raised crossbars, isolating switch and a work surface of 800mm length at the same height and - Wall oven located next to adjustable height work bench minimum 800mm width and where oven is hinged, the clear work surface is to be on the opposite side of the hinge. "D" pull cupboard handles must be provided such that they are located towards the top of below-bench cupboards and towards the bottom of overhead cupboards GPO outlets must be provided as follows: <ul style="list-style-type: none"> - At least one double general power outlet within 300 millimeters of the front of a work surface, and - At least one GPO provided for a refrigerator in such a position as to be easily accessible after the refrigerator is installed.
	Compliance Comment	Capable of compliance Details to be verified at CC stage of works.
Access	Requirement	Access to kitchen, main bedroom, bathroom / toilet In a multi-storey self-contained dwelling, the kitchen, main bedroom, bathroom and toilet must be located on the entry level
	Compliance Comment	N/A
Lifts in multi-storey buildings	Requirement	In a multi-storey building containing separate self-contained dwellings on different storeys, lift access must be provided to dwellings above the ground level of the building by way of a lift complying with clause E3.6 of the BCA
	Compliance Comment	N/A

Laundry	Requirement	Laundry must have: <ul style="list-style-type: none"> - Circulation space at door as per AS1428.1, - Provision for the installation of an automatic washing machine and a clothes dryer, - A clear space in front of appliances of at least 1,300mm, - A slip-resistant floor surface and An accessible path to clothes line (if provided).
	Compliance Comment	Capable of compliance Details to be verified at CC stage of works.
Storage	Requirement	A linen storage must be provided in accordance as per Clause 4.11.5 of AS4299 i.e. 600mm minimum width and adjustable shelving
	Compliance Comment	Capable of compliance Details to be verified at CC stage of works.
Garbage	Requirement	A garbage storage area must be provided in an accessible location.
	Compliance Comment	Capable of compliance Details to be verified at CC stage of works.

Statement of Compliance

On the basis of the above assessment, I am satisfied that the proposal can achieve compliance with the access provisions of the BCA and the Access to Premises Standard & SEPP Seniors Living



Howard Moutrie

ACAA Accredited Access Consultant No 177

Date of report: 03-12-2019

Statement of experience

Howard Moutrie



Qualifications:

B. Arch (Hons) Registered Architect ARB Reg. No 4550 ACAA Accredited Access Consultant Reg. No. 177 OHS Induction Training, OHS – Monitoring a Safe Workplace
Registered Assessor of Livable Housing Australia (License no 10054)
Registered Changing Places assessor (No 007)



Howard has been or is a member of the following:
Standards Australia ME/64 Committee (Access Standards)
Sutherland Council Design Review Panel
Sutherland Council Access Committee
City of Sydney Access Panel 2010
Building Professionals Board Access Advisory Panel
ACAA NSW Network of Access Consultants Management Committee



Howard Moutrie is an architect with over 30 years of experience. Howard is an experienced practicing access consultant and has previously spent 10 years on the Standards Australia Disabled Access Committee ME/64, providing input into the AS 1428 suite of Standards and the Adaptable Housing Standard. Howard has provided comment to numerous Councils on their Access Policy and acted as an expert witness in the Land & Environment Court.

Howard maintains a high level of continuing education programs and has presented at numerous seminars and training sessions including ACAA National Conference, ACAA State Network Seminars, RAIA Network Seminars, Building Designers Association Seminars.



Michael Moutrie is an access consultant. Combined with his training as a travel agent he has reviewed the accessibility of popular tourist areas around the world. Michael has:

- a Certificate IV in Access Consulting,
- completed the Livable Housing Assessor course
- completed the OHS Construction Induction Training Certificate.
- is an associate member of ACAA (No 581).