Phase I Environmental Site Assessment

Barbary Coast Investments Pty Limited



Robin Hood Hotel 203 Bronte Road Waverley NSW

July 2016



Risk Tech

Phase I Environmental Site Assessment Report

Report For:	Barbary Coast Pty Limited
Location:	203 Bronte Road Waverley NSW
Report Prepared By:	Ruth Heywood, RiskTech Pty Ltd
Date of Inspection:	8 August 2016
Inspection By:	Ruth Heywood, RiskTech Pty Ltd

Disclaimer & Statement of Confidentiality

This document has been prepared solely for the benefit of the Client for the purpose set out herein and should not be used for any other purpose than as an expression of the opinion of *RiskTech Pty Limited ABN 18 095 583 556 ("RT")* and the other related matters dealt with herein.

No responsibility is accepted to any other party for any loss or damage resulting from the use by the Client of this document for any reason whatsoever including but not limited to negligence on the part of RT or even a breach by RT in its contractual obligation to the Client in preparing the document. This document is confidential to the Client and RT does not intend that any other person accept or rely upon it.

The Document is based on RT's analytical processes and the information provided to RT by the Client and/or nominated third parties at the time of provision of information both on location and/or in written format. Such information supplied has not been independently verified by RT. Whilst this document is accurate to the best of RT's knowledge, information and belief, RT cannot guarantee the completeness or accuracy of any descriptions or conclusions based on the supplied information.

The information or recommendations contained in this document are advisory only and RT has no responsibility for the management or operation of any financial and/or risk minimisation and/or related procedures which may be implemented.

File NamePrepared ByReviewed byIssue
No.Issue Date203 Bronte Road, Waverley NSW ENV
HZM Aug16Ruth HeywoodBernard Day122/08/2016

Document Revision Record



Table of Contents

1	Ex	ecutive Summary	3
	1.1	General	3
	1.2	Key Findings	3
	1.3	Key Recommendations	4
2	Int	RODUCTION	5
	2.1	Scope	5
	2.2	Limitations	5
3	ΕN	vironmental Issues	6
	3.1	Property Location and Adjacent Land Uses	6
	3.1.1	Location and Description	6
	3.1.2	Surrounding Landuse	7
	3.2	SITE HISTORY	8
	3.2.1	Previous Environmental Reports	8
	3.2.2	Historical Title Information	9
	3.2.3	Historical Aerial Photographs	11
	3.2.4	NSW WorkCover	12
	3.2.5	Heritage Search	12
	3.2.6	Planning Searches	12
	3.2.7	UXO SITE SEARCH	13
	3.2.8	NSW EPA Search	14
	3.2.9	Contamination from Past Uses	15
	3.3	Environmental Issues	16
	3.3.1	Emissions to Atmosphere	16
	3.3.2	WASTE WATER MANAGEMENT	16
	3.3.3	Solid Waste Management	18
	3.3.4	Bulk Fuel Storage	19
	3.3.5	CHEMICAL STORAGE	19
	3.3.6	Hazardous Materials	20
	3.3.7	COOLING TOWERS	23
	3.3.8	POTENTIAL FOR CONTAMINATION	24
List of A	ppen	dices	
AF	PPENDI	x 1 — Historical Aerial Photos	26
Ar	PPENDI	x 2 - Historical Titles	30
Ar	PPENDI	x 3 – Section 149	31
Af	PPENDI	x 4 – Dangerous Goods Search	32

1 Executive Summary

1.1 General

RiskTech Pty Limited was commissioned to form part of a team to undertake a Phase I Environmental Site Assessment of the Robin Hood Hotel and surrounding sites on the corner of Bronte Road and Carrington Road, Waverley Sydney. This report documents the findings of the assessment of the site conducted on 8 August 2016.

This assessment covers the Robin Hood Hotel (RHH) site, 94 Carrington Road (a set of apartments), the Legion Club located at 213 Bronte Rd and the retail shops located at 227, 225 and 223 Bronte Road underneath the apartments at 94 Carrington Road,

1.2 Key Findings

The key findings are as follows:

- The site represents a <u>low</u> environmental risk.
- Areas of environmental concern include a disused incinerator and a disused grease underground trap that has been filled in.
- Cleaning chemicals on site are not stored within secondary containment and are within close proximity to a drain.
- Current site activities are considered unlikely to give rise to significant soil or groundwater contamination and no visual evidence of contamination due to these activities was observed during the site inspection.
- No bulk underground fuel storage tanks were identified on site.
- No cooling towers were present on site.
- The main air conditioning chiller sets use R22 an ozone depleting substance and R410a refrigerant a non-ozone depleting substance.
- Asbestos containing materials have been identified on the site in old electrical backing boards, bituminous membranes and fibre cement sheeting. A fibre cement sheeting fragment was also identified within the exposed fill material at 94 Carrington Road.
- The site is not listed on the NSW EPA's List of NSW contaminated sites notified to EPA; or the Contaminated Land: Record of Notices.

1.3 Key Recommendations

The key recommendations are as follows:

- Install secondary containment for the cleaning and washing chemicals to contain potential leaks and prevent unintentional spillage to stormwater drains.
- Engage a suitably qualified person to remove visible fragments of bonded asbestos from the fill material and undertake an asbestos clearance.
- Asbestos materials are present on site, ensure that any renovations/removal of items containing asbestos are undertaken by a licenced asbestos contractor under controlled conditions.
- Consider lifecycle assessments and upgrade A/C systems to run on non-ozone depleting refrigerants.
- Ensure that a Trade waste agreement in place for the grease trap and the sump pit.
- Consider undertaking a Phase 2 investigation (e.g. intrusive soil sampling) prior to future site redevelopments to identify historical contamination (e.g. from fill material) and to verify the site suitability for the intended use.

2 Introduction

RiskTech Pty Limited was engaged by Barbary Coast Pty Limited to complete a Phase I Environmental Site Assessment of the Robin Hood Hotel and surrounding sites located at the corner of Bronte Road and Carrington Road, Waverley Sydney. This consisted of a site inspection on 8 August 2016 as well as a documentation review.

2.1 Scope

The objective of the Phase I Environmental Assessment was to conduct a site inspection and collate historical information in order to establish weather activities have occurred on site that may have resulted in contamination of the land.

The assessment incorporated a review of available historical information and current site operations. The assessment methodology involved:

- Site inspection to verify reported information and visual examination of the facilities.
- Review of commentary with relevant personnel;
- Review of available statutory, maintenance, operational and environmental documentation;
- Undertaking relevant historical searches; and
- Preparation of a report outlining the findings of the assessment and recommendations.

2.2 Limitations

- The assessment is limited to those physical aspects that could be observed during inspections of accessible areas.
- Detailed testing/intrusive investigations were not included in this assessment.
- The assessment does not cover defects in inaccessible places or latent defects.
- We have generally used and relied upon information supplied as being regarded as authoritative and reliable. Review of reports and certification documentation is limited to those that were supplied as part of the Phase I Environmental Site Assessment and historical searches.

3 Environmental Issues

3.1 Property Location and Adjacent Land Uses

3.1.1 Location and Description

The subject site is a mixed use site that comprises 7 lots of land. The site contains the Robin Hood Hotel, a block of 6 apartments, 3 shop front and the Legion Club. The Robin Hood Hotel was originally constructed in 1938. Both the apartment block and the shop fronts share common land on which the buildings are two stories high and the Robin Hood Hotel is spread over three levels. The Legion Club was not accessible at the time of the inspection.

The Robin Hood Hotel (RHH), originally built in 1938, comprises three levels on a sloping block. The lowest level is the bottle shop and plant rooms on the southern portion of the site. The middle level is the main bars, pokies and restaurant levels. The top level of the RHH has a function room that is still in use in the southern portion of the level and the northern portion was previously hotel rooms that are now part way through renovations.

There are 6 apartments at 94 Carrington Road of which one is tenanted and the other 5 are vacant and disused. There are 3 one bedroom apartments on the ground level and 3 two bedroom apartments on the first level.

There are three retail shops located on Bronte Road to the south of the RHH. The shops are small, single room and a store room, and are located underneath the first level apartments at 94 Carrington Road.

The Legion Club is located at 213 Bronte Road. Although the Legion Club is part of this assessment no access was granted to the site for a site inspection as part of this assessment.

Site Identification			
Item	Details		
Site Owner	Barbary Coast Pty Limited		
Address	203, 213, 223, 225 & 227 Bronte Road, Waverley NSW 94 Carrington Road, Waverley NSW		
Title Details	Lot 1 DP 655918 (RHH) Lot 1 DP 59526 (RHH) Lots A DP 105665 (RHH) Lots B & C DP 105665 (Legion Club) Lots A & B DP332733 (94 Carrington Road)		
Local Government Authority	Waverley Council Parish of Alexandria County of Cumberland		
Land Area	~2, 176m² area		



Site Identification

Current Site User

Commercial/residential



& 94 Carrington Road Waverley NSW

3.1.2 Surrounding Landuse

The site is situated in approximately 5.5 km south east of Sydney's CBD. The following provides a summary of surrounding land uses:

Direction	Landuse
North	Retail/commercial buildings
South	A Retail/commercial buildings
East	Retail/commercial buildings and Bronte Road
West	Retail/commercial buildings and Carrington Road

The nearest water body to the site is Bronte beach, approximately 1.5 km to the east of the site and Sydney Harbour approximately 3.3 km to the north of the site.

Barbary Coast Investments Pty Limited



203 Bronte Road, Waverley NSW



Site Location: 203 Bronte Road Waverley NSW

Courtesy SixMaps, 2016

3.2 Site History

3.2.1 Previous Environmental Reports

The following report was available for review as part of this assessment:

Hazardous Materials Survey Report and Register, 94 Carrington Road, 223 – 227 Bronte Road and Robin Hood Hotel Bottle Shop Waverley NSW; Environmental Monitoring Services December 2015.

The findings of this report indicated that asbestos containing materials, standard Synthetic Mineral Fibre items and lead paint were present on site, however, no PCBs were identified. The items identified are summarised below:

94 Carrington Road

- Asbestos containing bituminous sealant membrane to roof flashing and some sections of adjacent concrete.
- Asbestos containing bituminous waterproofing membrane to 2nd Floor balcony.
- Asbestos containing bituminous sealant membrane to terracotta tiles on 1st Floor balcony.
- Asbestos containing fibre cement sheeting to rear of cupboards in bathrooms.
- External window frame paint was found to contain lead.
- SMF insulation batts on the roof of the garage.



<u> 223 – 227 Bronte Road</u>

- Asbestos containing electrical backing board in west cupboard on external north wall (presumed asbestos).
- Asbestos containing vinyl floor tiles underneath hot water heater in 225 Bronte Road (Hairdresser's).

Robin Hood Hotel Bottle Shop

- Asbestos containing bituminous waterproofing membrane to roof of driveway.
- The Robin Hood Hotel 203 Bronte Road Waverley NSW, Heritage Impact Statement; John Oultram Heritage & Design August 2011.

This report outlines a detailed history of the site and the surrounding area. It highlights the significance of the heritage of the site in relation to the history of the area. For a detailed history of the site and surrounding area the full heritage report can be viewed on the Robin Hood Hotel website.

3.2.2 Historical Title Information

Historical title searches are typically undertaken to indicate possible sources of contamination based upon the likely operations carried out on the site by the owner/tenant of the property.

A limited historical title search was undertaken for this property. A summary of historical title information has been provided in the table below.

Historical Title Summary – 203 Bronte Road, Waverley NSW				
Title Reference	Registered Proprietors	Date	Status	
Lot 1 DP 655918	Raymond Laurence Whitten, Daniel Maurice Whitten, Andrew John Whitten	16.09.2009	Current	
Lot 1 DP 59526	Raymond Laurence Whitten, Daniel Maurice Whitten, Andrew John Whitten	16.09.2009	Current	
Lot A DP 105665	Raymond Laurence Whitten, Daniel Maurice Whitten, Andrew John Whitten	16.09.2009	Current	
V. 14152 F. 44	Tooth & Co Limited	24.06.1980	Historical	
	Edward James Joseph Wales of Waverley, Licenced Publican	05.11.1956	Historical	
V. 4168 F. 58	John Bruce Burgess of Sydney, an Optometrist	13.07.1928	Historical	
V. 4168 F. 59	Stanley Gordon Burgess of Sydney, a Quantity Surveyor	13.07.1928	Historical	
	Tooth & Co. Limited	11.09.1936	Historical	
V. 4168 F. 60	Alan Leigh Burgess of Gerringong, a Farmer	13.07.1928	Historical	
	Tooth & Co. Limited	11.09.1936	Historical	
V. 2686 F. 105	Walter Scott Harkness of Woollahra	24.07.1918	Historical	



.

203 Bronte Road, Waverley NSW

Historical Title Summary – 203 Bronte Road, Waverley NSW				
	Phillip William Rygate, Surveyor, and Arthur Muddle	26.07.1918	Historical	
V. 1154 F. 69	David Stuart of Paddington, a Builder	12.02.1895	Historical	
Lot C DP 150665	Australian Legion of Ex-servicemen and Women	-	Current	
V. 8137 F. 249	Australian Legion of Ex-servicemen and Women	10.04.1961	Historical	
	Bank of New South Wales	15.03.1962	Historical	
	Commercial and General Insurance Limited	04.04.1962	Historical	
V. 5614 F. 125	Helen Notaras, a retired Restaurant Proprietor	25.10.1946	Historical	
V. 5614 F. 126	John Cassimatis of Sydney, a Milkbar Proprietor	25.10.1946	Historical	
	Australian Legion of Ex-servicemen and Women	30.08.1960	Historical	
V. 3274 F. 129	Bondi Land and Buildings Limited	21.01.1922	Historical	
	Edward James Egan of Bondi Estate Agent & John Bourke of Woollahra Contractor	30.01.1922	Historical	
Application 804010	Lewis Gordon from Crown Grant	15.06.1848	Historical	
Lots A & B DP 332733	Barbary Coast Investments Pty Limited	20.04.2016	Current	
V. 4832 F. 179	Angelo Mellitas of Sydney, a Confectioner	05.04.1937	Historical	
	Charles West, Alexander Charles, Allistair Alexander & James Lord Milson	03.05.1937	Historical	
	Coleman Products Pty Ltd	09.06.1975	Historical	
V. 4759 F. 123	Angelo Mellitas of Sydney, a Confectioner	05.05.1936	Historical	
V. 4759 F. 127	Angelo Mellitas of Sydney, a Confectioner	05.05.1936	Historical	
	Claire Lloyd, Wife of Robert Lloyd, a Solicitor	15.05.1936	Historical	

A detailed history of the site was undertaken for the Robin Hood Hotel in the Robin Hood Hotel Heritage Impact Statement prepared by John Oultram Heritage & Design in August 2011. For a detailed site history refer to this report.

In general the Robin Hood Hotel, 94 Carrington Road the retail shops and the Legion Club buildings have been present on site since the 1930s. From the time that the land was transferred from crown grant to a private owner in 1848 there have been a number of private and commercial owners. Tooth & Co. Pty Limited purchased the land on which the RHH stands today. Although the owners have changed the building has remained on the site.

Refer to **Appendix 2** for the copies of the title search information.

3.2.3 Historical Aerial Photographs

Historical aerial photographs may indicate possible sources of historical contamination based upon the activities carried out on the site/adjacent sites. Historical aerial photographs for the site were viewed from 1930 - 2016. A summary of findings from seven of these is provided in the table below:

Historical Aerial Photography					
Photo Year	Observation				
1930	Site	The majority of the site has small buildings on it with what appears to be an unsealed area in the northern portion of the site. The buildings appear to either be residential or commercial/retail.			
	Surrounds	The area surrounding the site appears to be high density houses/shops of which the majority appear to be single level.			
1943	Site	The original Robin Hood Hotel is now visible on the northern portion of the site. The central and southern portions of the site appear to have 6 buildings on them and a driveway in the south western corner of the site.			
	Surrounds	The surrounding area appears similar to the 1930 photograph, a mixture of retail and residential.			
1965	Site	The building in the central western portion of the site has changed from two buildings to one large building. The remainder of the site appears unchanged from the 1943 photograph.			
	Surrounds	There are no discernible differences to the area surrounding the site from the 1943 aerial photograph.			
1978	Site	There are no discernible differences to the site from the 1965 aerial photograph.			
1770	Surrounds	There are no discernible differences to the area surrounding the site from the 1965 aerial photograph.			
1001	Site	There are no discernible differences to the site from the 1978 aerial photograph.			
1991	Surrounds	The surrounding area appears similar to the 1978 aerial photograph.			
2001	Site	There are no discernible differences to the site from the 1991 aerial photograph.			
2001	Surrounds	The surrounding area appears similar to the 1991 aerial photograph.			
2016	Site	There are no discernible differences to the site from the 2001 aerial photograph.			
2010	Surrounds	The surrounding area appears similar to the 2001 aerial photograph.			

Historical aerial photograph of the site and surrounding area show that the buildings that are on the site have predominantly been present from between 1930 and 1943. Very little change is visible to the buildings on the site from 1943 to the present day. The area surrounding the site appears to have been a mixture of residential and retail/commercial since the 1930's. Few changes can be seen in the areas surrounding the site to the present day.

Copies of the aerial photographs can be found in **Appendix 1**.



3.2.4 NSW WorkCover

A WorkCover Storage of Hazardous Chemicals Search was undertaken for the part of the site located at 203 Bronte Road Waverley. The information from the search indicated that there is no known record of any licences issued for the storage of dangerous goods at the site e.g. fuel in underground storage tanks (refer to **Appendix 4** for the WorkCover Search Results).

3.2.5 Heritage Search


A search was undertaken on the NSW EPA website to assess the heritage status of the site. The site is not listed as a heritage. A Further search was undertaken on the NSW Heritage website and it lists the site as being of regional heritage value as a place demonstrating late 19th and early 20th century commercial buildings along a main street. The website then goes on to state that "on the available evidence, Charring Cross commercial centre does not meet any National Heritage Criteria".

The site was confirmed in the Section 149 as being in a heritage conservation area, however it is listed as containing a heritage item.

3.2.6 Planning Searches

3.2.6.1 Acid Sulfate Soils

Acid sulfate soils are naturally occurring soils or sediments that are formed under waterlogged conditions containing iron sulphide minerals, and when disturbed release sulphuric acid.



A search of the Australian Soil Resource information System (ASRIS) National Acid Sulfate Soils Risk Map was carried out for the site. The search revealed that the site is in an area with low probability of acid sulfate soils.

It is noted that the Acid Sulfate Soils Maps do not describe the actual severity of acid sulfate soils in a particular area, but provide an initial indication that acid sulfate soils could be present on the site. The drainage from acid sulfate soil lands can create conditions which are toxic to aquatic and terrestrial life and grazing animals. The best management option for the problem of acid sulfate soils is not to disturb the soil. However, land development and agricultural activities in coastal areas will often interfere with acid sulfate soils. The presence of potential acid sulfate soil is an important consideration when developing a site with any structures that contain steel or concrete. The local government may require the submission of an Acid Sulfate Soil Management Plan prior to development consent.

3.2.6.2 Geology

A review of the Sydney 1 : 250,000 Geological Series Sheets S1 56-5 third edition (1966) indicates that the site is underlain by quaternary aged alluvium, sand, gravel silt and clay. This is then overlain by Triassic aged Hawkesbury sandstone and quartz with inclusions of some shale.

3.2.6.3 Section 149 Certificate

Section 149 Planning Certificates are issued in accordance with the Environmental Planning & Assessment Act 1979. They contain information on how a property may be used and the restrictions on development.

Information to be disclosed on a Section 149 (2) Planning Certificate is specified under the Environmental Planning and Assessment Regulation 2000 (Schedule 4) and shows the zoning of the property, its relevant state, regional and local planning controls and other property issues such as land contamination and road widening. A section 149(2) and 149(5) certificate provides the same information but also includes other factors such as advice from other authorities.

The Section 149(2&5) certificate for the site was reviewed (dated 18/5/16). A summary of relevant information is as follows:

- The land is zoned B4 Mixed Use
- The land <u>is</u> affected by State Environmental Planning Policies and Regional Environmental Plans.
- The lands does not comprise critical habitat
- The land is located within a heritage conservation area identified within the Waverley Local Environmental Plan 2012.
- The land is not subject to flood related development controls.
- The land is not in a bush fire prone area.
- The land <u>is not</u> affected by road widening or road realignment.
- The land <u>is not</u> in a coastal protection zone.
- Council has not been notified that the property contains loose fill asbestos ceiling insulation.
- The land is not noted as being significantly contaminated land.
- The land is not subject to a management order.
- The land <u>is</u> not identified as being affected by acid sulfate soils.

Refer to **Appendix 3** for the \$149 Certificate.


3.2.7 UXO Site Search

As a result of military training and live firing undertaken by Australian and Allied forces there are many areas throughout Australia not controlled by the Commonwealth, which may be subject to residual unexploded ordnance (UXO) contamination. In accordance with Commonwealth policy, the Department of Defence has



undertaken to identify and record sites where there is potential for such contamination.

The site is not located in an area that poses a risk to UXO.



3.2.8 NSW EPA Search

In NSW the management of contaminated land is shared by the Environment Protection Authority (EPA), the Department of Planning and Infrastructure and planning consent authorities (usually local councils). Under the Contaminated Land Management Act 1997 (CLM Act), the EPA regulates contaminated sites where the contamination is significant enough to warrant regulation. Contaminated sites that are not regulated by the EPA are managed by local councils through land-use planning processes.

The EPA has 2 online lists and a public register:

- List of NSW contaminated sites notified to EPA;
- List of Contaminated Land: Record of Notices; &
- Protection of the Environment Operations Act 1997.

Subsequent to amendments to Section 60 of the CLM Act 'Duty to Report Contaminated Sites', the Environment Protection Authority (EPA) has received many notices from owners or occupiers of sites where they believe the sites are contaminated (i.e. 'List of NSW contaminated Sites notified to the EPA').

The sites appearing on this 'List of NSW contaminated sites notified to the EPA' indicate that the notifiers consider that the sites are contaminated and warrant reporting to EPA. However, the contamination may or may not be significant enough to warrant regulation by the EPA. A site will be on the 'Contaminated Land: Record of Notices' only if the EPA has issued a regulatory notice in relation to the site under the CLM Act.



3.2.8.1 Searches

An online search through the EPA contaminated land public records was completed for the current site being investigated. It is noted that an absence of a site from the list does not necessarily imply the site is not contaminated.

- The site is <u>not</u> listed on the 'List of NSW contaminated sites notified to EPA'.
- The site is <u>not</u> listed on the 'Contaminated Land: Record of Notices list'. There are no sites noted nearby to the site.

A search of the public register maintained by NSW EPA under the Protection of the Environment Operations Act 1997 (POEO Act) was undertaken and the search identified that, for the site, there were:

- No prevention, clean-up or prohibition notices; and
- <u>No</u> transfer, suspension, surrender or revocation of an environment protection licence.

3.2.9 Contamination from Past Uses

No industrial activities or storage of fuel has been identified on the site or adjacent sites through the historical site searches. Based upon the historical searches, review of the supplied report and site assessment the likelihood of sub-surface contamination from previous land uses is considered low.

3.3 Environmental Issues

3.3.1 Emissions to Atmosphere

Emissions to atmosphere from the site include:

- Building exhaust from toilet facilities throughout the building;
- Kitchen exhaust from the cafe within the building; and
- Air conditioning exhaust throughout the building.

None of the emissions listed above would require an Environment Protection Licence.

Recommendations

Nil

3.3.2 Waste Water Management

The following wastewater is generated on site from:

- Kitchen;
- Bathrooms/toilets;
- Grease trap; and
- Stormwater.

3.3.2.1 Grease Trap

There is one above ground grease trap present on site that is now used instead of the decommissioned and now backfilled underground grease trap. RiskTech was advised that the grease trap is regularly serviced and maintained and reviewed documentation that confirmed this. RiskTech was advised that there is a current Trade Waste Agreement in place for the grease trap, however the current Trade Waste agreement was not available for review at the time of the assessment.

Although the Legion Club was not inspected during this assessment it is highly likely that there is at least a second grease trap present on that site to service the Legion Clubs kitchen facilities.



Photo 1: Grease trap in the lower level back
of house area of the Robin Hood HotelPhoto 2: Disused grease trap adjacent to
current grease trap

Recommendations

Ensure a current Trade Waste Agreement is in place for the site.

 Undertake a site inspection on the Legion Club to confirm the presence/absence of a grease trap.

3.3.2.2 Stormwater

Stormwater is collected on site by gutters and drains on the exterior of the buildings. This is then fed directly to stormwater drainage systems associated with Bronte Road and Carrington Road.

Drainage is also located throughout the lower level of the RHH throughout the back of house storage areas. Cleaning chemicals, that are not currently stored in secondary containment, are being stored in close proximity to some of these drains. This has the potential to cause stormwater contamination in the event of accidental spillage or leaks in the storage containers.



Photo 5: Drainage within the lower level back of house area of the Robin Hood Hotel

Photo 6: Stormwater drain in the loading dock/rubbish area of the Robin Hood Hotel

Recommendations

Refer to recommendation in section 3.3.5 Chemical Storage

3.3.2.3 Sump Pits

No sump pits were observed on the site at the time of the inspection.

3.3.3 Solid Waste Management

Waste management currently poses a low environmental risk at the site.

Solid waste streams generated at the subject site include:

- Standard organic wastes, co-mingled, glass, plastic and paper generated by general commercial activities.
- A disused incinerator was present on site with chutes on the upper and middle level of the RHH and the incinerator present on the lower level of the RHH.

RiskTech was advised that a current waste removal contract was in place for the site and service agreements with both Veolia and URM waste management services were available for review.



Photo 7: Waste disposal area

Photo 8: Waste disposal area



Photo 9: Chute for disused incinerator on the upper hotel level of the Robin Hood Hotel gra

Photo 10: Disused incinerator adjacent to the grease trap on the lower level of the Robin Hood Hotel

The disused incinerator is located in a boarded off area adjacent to the grease trap on the lower level of the RHH. Although the incinerator is no longer in use, it is likely to have historically been used to burn all types or rubbish that was generated on the site. This would have the potential to have produced burnt material that may have been disposed of on the site.

General housekeeping of waste storage areas throughout the site were kept in a neat and tidy state with the exception of pallets stored in the waste area.

Risk Tech

Recommendations

- If demolition and/or major refurbishment are to be undertaken on the site, consider a phase 2 investigation to identify any historical contamination and verify the site suitability for the intended land use.
- Ensure good housekeeping is maintained throughout all storage areas of the site.

3.3.4 Bulk Fuel Storage

No underground storage tanks are present on site. The WorkCover Storage of Hazardous Chemicals Search did not identify any historically stored chemicals such as fuel in underground storage tanks.

3.3.5 Chemical Storage

Cleaning chemicals, washing chemicals and gas cylinders are stored on site.

Cleaning and washing chemicals are stored in the back of house/maintenance area on the lower level of the RHH. Cleaning and washing chemicals were not stored in secondary containment and visual evidence of leaks/spills were present on the floor. Cleaning chemicals are stored in close proximity to a drain in the floor.

A number of paint tins are stored in the upper hotel room area of the RHH. These paints are being temporarily stored for use during renovations of the hotel area of the RHH. The paints are not stored in secondary containment, however, are not near any stormwater drains.

Several sets of gas cylinders are stored on site on the lower level of the RHH. The gas cylinders are secured and segregated correctly.

No bulk quantities of chemicals are stored on site that would require a license.



Photo 11: Paints stored on Level 1 in a hotel room

Photo 12: Cleaning chemicals stored without secondary containment in close proximity to a drain in the floor

Risk Tech

Barbary Coast Investments Pty Limited

203 Bronte Road, Waverley NSW





Photo 13: White marks on the floor show areas where cleaning chemicals have leaked

Photo 14: Washing chemicals stored without secondary containment in close proximity to a drain in the floor



Photo 15: Correctly secured and stored gas cylinders

Recommendations

Ensure chemicals throughout the site are stored with secondary containers to contain any potential leaks and prevent accidental discharge to stormwater drains.

3.3.6 Hazardous Materials

A walkthrough asbestos/hazardous materials assessment has been undertaken as part of this due diligence. In summary:

3.3.6.1 Asbestos

A hazardous materials survey was undertaken for the site in December 2015. This survey identified asbestos containing materials at the RHH, the apartments and the retail shops. The asbestos items identified were all non-friable and comprised electrical backing boards, fibre cement sheeting and bituminous water proofing membrane.

Further to this a fragment of suspected asbestos containing fibre cement sheeting was identified on the surface of the exposed fill at 94 Carrington Road. Only a single fragment was observed during the site inspection.

During the site inspection the manager of the RHH, Daniel Whitten, mentioned that there is asbestos items identified within the roof cavity of the RHH. Daniel stated that



Barbary Coast Investments Pty Limited 203 Bronte Road, Waverley NSW

there had been previous assessments of this area however this assessment was not available for review at the time of the inspection.






Photo 18: Asbestos containing fibre cement sheeting at 94 Carrington Road

Photo 19: Asbestos containing bituminous membrane on the roof of the RHH

3.3.6.2 Synthetic Mineral Fibres

Standard insulation materials are present on site, including air conditioning ductwork insulation in the ceiling spaces and plant internal insulation (e.g. hot water heaters). There was also discarded SMF insulation batts on the roof of the garage at 94 Carrington Road.



Photo 20: SMF insulation within hot water heater at the Robin Hood Hotel

Photo 21: Discarded SMF insulation batts on the garage roof at 94 Carrington Road



3.3.6.3 Polychlorinated BiPhenyls (PCBs)

PCBs were commonly used in fluorescent light fittings and other electrical installations up until the 1970s. Although the original buildings were constructed prior to this time several refurbishments have been undertaken since then. No PCBs were identified in the 2015 Hazardous Materials Survey and not were identified or suspected during the site inspection. PCBs are therefore not suspected to be present on site.

3.3.6.4 Lead Paint

Lead based paint was identified as being present on site in the 2015 Hazardous Materials Survey. It was confirmed as being present on the exterior window frames of 94 Carrington Road and within 225 Bronte Road (rear area ceiling). Many interior ceiling and wall paint samples were negative when tested for lead. Many areas of the site were inaccessible for lead paint testing.



Photo 22: Lead based paint on the exterior window frames of the apartments at 94 Carrington Road

Recommendations

When demolition or refurbishment works are to involve the disturbance of confirmed lead-containing paint, dust suppression techniques should be utilised. Any works, which may disturb potential lead-based paint systems, should be conducted in accordance with the requirements of Australian Standard AS 4361.2 1998 Guide to lead paint management, Part 2: Residential and commercial buildings.

3.3.6.5 Ozone Depleting Substances (ODS)

Various air conditioning units and chillers are present on site. They appear to be R410a refrigerant, a non-ozone depleting substance, and R22 refrigerant, an ozone depleting substance.


Under the Montreal Protocol (Copenhagen Revision 1992), hydrochlorofluorocarbon (HCFC) refrigerants (such as R22) are to be phased out by 2030. The Commonwealth Government has introduced controls on the import and manufacture of HCFC refrigerants for both new and used equipment for the economic life of that equipment.

All fluorocarbons (CFCs, HCFC and HFCs) require contractors to have a refrigerant handling licence.

Barbary Coast Investments Pty Limited

Risk Tech

203 Bronte Road, Waverley NSW



All fluorocarbons (CFCs, HCFC and HFCs) require contractors to have a refrigerant handling licence.

Recommendations:

There is consequently no environmental liability associated with the continued, effective use of air-conditioning units using HCFC refrigerants. However, should any air-conditioning plant currently utilising R22 refrigerant require upgrade or replacement in the future, consideration should be given to selecting plant that utilises a refrigerant gas with a lower ozone depleting potential.

3.3.7 Cooling Towers

There are no cooling towers present on the site.

3.3.8 Potential for Contamination

3.3.8.1 Visible Contamination

No visible signs of staining or unusual residues were observed on the driveway area of the RHH Bottle Shop, the driveway/garage area of 94 Carrington Road, ancillary structures or surrounding areas.

No odours were apparent during the site inspection.

3.3.8.2 On Site Sources of Contamination

Based on the historical aerial photographs, the structures on the site have remained predominantly the same since 1943, with the exception of one building changing in the central western portion of the site in the 1965 photograph. During this time it is possible that the ash that was produced by the incinerator may have been disposed of in the exposed ground surface areas of the site.

A disused grease trap was identified on the lower level of the RHH. RiskTech was advised that the disused grease trap had been filled in previously.

The driveway area of 94 Carrington Road appears, from the historical aerial photographs, to have remained unsealed since 1930, the earliest available photograph. Given that this area comprises a driveway and a garage there is potential for historical use/storage of minor quantities of fuel and other household garage chemicals, however, no visible evidence of this was observed during the site inspection.

Fill was identified within the driveway area of 94 Carrington Road. A fragment of suspected asbestos fibre cement sheeting was identified on the surface of this fill.

Further to this minor amounts of lead paint were identified on the exterior of the windows at 94 Carrington Road. Given the age of the other buildings on the wider site it is likely that lead containing paint would be present underneath the new layer of paint on the other buildings.

The Legion Club was not accessible for inspection at the time of this report.

3.3.8.3 Off Site Sources of Contamination

The historic surrounding landuse of mixed residential and retail/commercial uses did not indicate any potential sources of contamination that would affect the site.

3.3.8.4 Summary

Based on information obtained for this site, review of available historical information and assessment of potential environmental issues at the site, the potential for contamination can be summarised:

- Historical site activities are considered to be unlikely to have given rise to soil or groundwater contamination.
- Current site activities are considered to have a low potential of giving rise to significant soil or groundwater contamination.
- Adjacent sites are not considered to have potential to have given rise to soil or groundwater contamination.
- Asbestos materials are present on site, ensure that any renovations/removal of items containing asbestos are undertaken by a licenced asbestos contractor or competent person under controlled conditions.



Barbary Coast Investments Pty Limited


- 203 Bronte Road, Waverley NSW
- The site is considered suitable for the current commercial land use and represents a <u>low</u> environmental risk, however it is recommended that a phase 2 investigation be undertaken prior to any future site redevelopments to identify any historical contamination, such as use of fill on the site, ash from the incinerator or lead leaching from paint, and verify the site suitability for the intended land use.

Risk Tech

Barbary Coast Investments Pty Limited

203 Bronte Road, Waverley NSW


Appendix 1 – Historical Aerial Photos



Aerial Photo: 1943

Courtesy Sixmaps

Barbary Coast Investments Pty Limited 203 Bronte Road, Waverley NSW



Aerial Photo: 1978

Courtesy NSW LPI

Barbary Coast Investments Pty Limited 203 Bronte Road, Waverley NSW





Aerial Photo: 2001

Courtesy Google Earth

Risk Tech

Barbary Coast Investments Pty Limited 203 Bronte Road, Waverley NSW



Aerial Photo: 2016

Courtesy Google Earth



203 Bronte Road, Waverley NSW

Appendix 2 – Historical Titles

Title Search



LAND AND PROPERTY INFORMATION NEW SOUTH WALES - TITLE SEARCH

FOLIO: 1/59526

SEARCH DATE	TIME	EDITION NO	DATE
27/11/2015	6:16 PM	4	16/9/2009

LAND ____

LOT 1 IN DEPOSITED PLAN 59526 LOCAL GOVERNMENT AREA WAVERLEY PARISH OF ALEXANDRIA COUNTY OF CUMBERLAND TITLE DIAGRAM DP59526

FIRST SCHEDULE ------

RAYMOND LAURENCE WHITTEN

IN 1/2 SHARE DANIEL MAURICE WHITTEN IN 1/4 SHARE ANDREW JOHN WHITTEN IN 1/4 SHARE AS TENANTS IN COMMON

(TA AE981622)

SECOND SCHEDULE (4 NOTIFICATIONS)

1 RESERVATIONS AND CONDITIONS IN THE CROWN GRANT(S)

2

AE981623 MORTGAGE TO WESTPAC BANKING CORPORATION AE981624 MORTGAGE TO BARBARY COAST INVESTMENTS PTY LTD 3

AE981625 CHARGE TO MAXWELL SERNACK 4

NOTATIONS _____

UNREGISTERED DEALINGS: NIL

*** END OF SEARCH ***

140078

PRINTED ON 27/11/2015

* Any entries preceded by an asterisk do not appear on the current edition of the Certificate of Title. Warning: the information appearing under notations has not been formally recorded in the Register.

Title Search



LAND AND PROPERTY INFORMATION NEW SOUTH WALES - TITLE SEARCH

FOLIO: 1/655918

SEARCH DATE	TIME	EDITION NO	DATE
27/11/2015	6:16 PM	2	16/9/2009

LAND ----

LOT 1 IN DEPOSITED PLAN 655918 LOCAL GOVERNMENT AREA WAVERLEY PARISH OF ALEXANDRIA COUNTY OF CUMBERLAND TITLE DIAGRAM DP655918

FIRST SCHEDULE

RAYMOND LAURENCE WHITTEN IN 1/2 SHARE DANIEL MAURICE WHITTEN IN 1/4 SHARE ANDREW JOHN WHITTEN IN 1/4 SHARE AS TENANTS IN COMMON

(TA AE981622)

SECOND SCHEDULE (4 NOTIFICATIONS)

RESERVATIONS AND CONDITIONS IN THE CROWN GRANT(S) 1

2

AE981623 MORTGAGE TO WESTPAC BANKING CORPORATION AE981624 MORTGAGE TO BARBARY COAST INVESTMENTS PTY LTD 3

AE981625 CHARGE TO MAXWELL SERNACK 4

NOTATIONS _____

UNREGISTERED DEALINGS: NIL

*** END OF SEARCH ***

140078

PRINTED ON 27/11/2015

* Any entries preceded by an asterisk do not appear on the current edition of the Certificate of Title. Warning: the information appearing under notations has not been formally recorded in the Register.

Title Search



LAND AND PROPERTY INFORMATION NEW SOUTH WALES - TITLE SEARCH

FOLIO: A/105665

SEARCH DATE	TIME	EDITION NO	DATE
27/11/2015	6:17 PM	4	16/9/2009

LAND ____

LOT A IN DEPOSITED PLAN 105665 LOCAL GOVERNMENT AREA WAVERLEY PARISH OF ALEXANDRIA COUNTY OF CUMBERLAND TITLE DIAGRAM DP105665

FIRST SCHEDULE _____

RAYMOND LAURENCE WHITTEN IN 1/2 SHARE DANIEL MAURICE WHITTEN IN 1/4 SHARE ANDREW JOHN WHITTEN IN 1/4 SHARE AS TENANTS IN COMMON

(TA AE981622)

SECOND SCHEDULE (4 NOTIFICATIONS)

RESERVATIONS AND CONDITIONS IN THE CROWN GRANT(S) 1

- 2
- AE981623 MORTGAGE TO WESTPAC BANKING CORPORATION AE981624 MORTGAGE TO BARBARY COAST INVESTMENTS PTY LTD AE981625 CHARGE TO MAXWELL SERNACK 3

4

NOTATIONS _____

UNREGISTERED DEALINGS: NIL

*** END OF SEARCH ***

140078

PRINTED ON 27/11/2015

* Any entries preceded by an asterisk do not appear on the current edition of the Certificate of Title. Warning: the information appearing under notations has not been formally recorded in the Register.



New South Wales Land & Property > Street Address Listing

NSW: Street Address Enquiry - 94 Carrington Waverley

The following list matches your search criteria. To order a search, tick on the check box and click 'Order'.

Address	Title Ref	Document	ts			Fee
94 CARRINGTON RD, WAVERLEY 2024	A/332733	☑ _{Title}	Historical		Prior Title	\$17.75
94 CARRINGTON RD, WAVERLEY 2024	B/332733	I Title	Historical	CT Enquiry	Prior Title	\$17.75
				(Total:	\$35,50

This information is provided as a searching aid only. The Registrar General does not guarantee the information provided.

1

Title Search



LAND AND PROPERTY INFORMATION NEW SOUTH WALES - TITLE SEARCH

FOLIO: AUTO CONSOL 20002-28

SEARCH DATE	TIME	EDITION NO	DATE
27/6/2016	12:03 PM	1	20/4/2016

LAND

LAND DESCRIBED IN SCHEDULE OF PARCELS AT WAVERLY LOCAL GOVERNMENT AREA WAVERLEY PARISH OF ALEXANDRIA COUNTY OF CUMBERLAND TITLE DIAGRAM DP332733

FIRST SCHEDULE

BARBARY COAST INVESTMENTS PTY LIMITED

SECOND SCHEDULE (4 NOTIFICATIONS)

1 LAND EXCLUDES MINERALS AND IS SUBJECT TO RESERVATIONS AND CONDITIONS IN FAVOUR OF THE CROWN - SEE CROWN GRANT(S)

2 A694135 RIGHT OF WAY 0.915 METRE(S) WIDE APPURTENANT TO THE PART(S) OF LOT A IN DP332733 AFFECTING THE PART SHOWN SO BURDENED IN DP978682

3 C405215 RIGHT OF WAY VARIABLE WIDTH APPURTENANT TO THE PART(S) OF LOT A IN DP332733 AFFECTING THE PART SHOWN SO BURDENED IN DP186706

4 AK315124 MORTGAGE TO WESTPAC BANKING CORPORATION

NOTATIONS

UNREGISTERED DEALINGS: NIL

SCHEDULE OF PARCELS

LOT A IN DP332733 LOT B IN DP332733.

*** END OF SEARCH ***

InfoTrack An Approved LPI NSW Information Broker

Title Search



LAND AND PROPERTY INFORMATION NEW SOUTH WALES - TITLE SEARCH

FOLIO: AUTO CONSOL 20002-28

SEARCH DATE	TIME	EDITION NO	DATE
27/6/2016	12:03 PM	1	20/4/2016

LAND

LAND DESCRIBED IN SCHEDULE OF PARCELS AT WAVERLY LOCAL GOVERNMENT AREA WAVERLEY PARISH OF ALEXANDRIA COUNTY OF CUMBERLAND TITLE DIAGRAM DP332733

FIRST SCHEDULE

BARBARY COAST INVESTMENTS PTY LIMITED

SECOND SCHEDULE (4 NOTIFICATIONS)

1 LAND EXCLUDES MINERALS AND IS SUBJECT TO RESERVATIONS AND CONDITIONS IN FAVOUR OF THE CROWN - SEE CROWN GRANT(S)

2 A694135 RIGHT OF WAY 0.915 METRE(S) WIDE APPURTENANT TO THE PART(S) OF LOT A IN DP332733 AFFECTING THE PART SHOWN SO BURDENED IN DP978682

3 C405215 RIGHT OF WAY VARIABLE WIDTH APPURTENANT TO THE PART(S) OF LOT A IN DP332733 AFFECTING THE PART SHOWN SO BURDENED IN DP186706

4 AK315124 MORTGAGE TO WESTPAC BANKING CORPORATION

NOTATIONS

UNREGISTERED DEALINGS: NIL

SCHEDULE OF PARCELS

LOT A IN DP332733 LOT B IN DP332733.

*** END OF SEARCH ***

InfoTrack An Approved LPI NSW Information Broker

Title Search



LAND AND PROPERTY INFORMATION NEW SOUTH WALES - TITLE SEARCH

FOLIO: B/105665

SEARCH DATE	TIME	EDITION NO	DATE
6/6/2016	4:42 PM	3	27/10/1997

LAND

LOT B IN DEPOSITED PLAN 105665 LOCAL GOVERNMENT AREA WAVERLEY PARISH OF ALEXANDRIA COUNTY OF CUMBERLAND TITLE DIAGRAM DP105665

FIRST SCHEDULE

EASTERN SUBURBS LEGION CLUB LIMITED

(T 3527265)

SECOND SCHEDULE (6 NOTIFICATIONS)

1	RESERVATI	ONS AND CONDITIONS IN THE CROWN GRANT(S)
2	C405215	RIGHT OF WAY AFFECTING THE LAND OF VARIABLE WIDTH SHOWN IN THE DP186706
3	2486601	LEASE TO OPTUS MOBILE PTY LIMITED OF PREMISES SHOWN HATCHED IN PLAN WITH 2486601. EXPIRES 21-7-2001
4	2486602	LEASE TO OPTUS MOBILE PTY LIMITED OF PREMISES SHOWN HATCHED IN PLAN WITH 2486602. COMMENCING 22-7-2001.
5	2486603	EXPIRES 21-7-2006 LEASE TO OPTUS MOBILE PTY LIMITED OF PREMISES SHOWN HATCHED IN PLAN WITH 2486603. COMMENCING 22-7-2006. EXPIRES 21-7-2011
6	2486604	LEASE TO OPTUS MOBILE PTY LIMITED OF PREMISES SHOWN HATCHED IN PLAN WITH 2486604. COMMENCING 22-7-2011. EXPIRES 21-7-2016
NOT	ATIONS	

NOTATIONS

NOTE: THE CERTIFICATE OF TITLE FOR THIS FOLIO OF THE REGISTER DOES NOT INCLUDE SECURITY FEATURES INCLUDED ON COMPUTERISED CERTIFICATES OF TITLE ISSUED FROM 4TH JANUARY, 2004. IT IS RECOMMENDED THAT STRINGENT PROCESSES ARE ADOPTED IN VERIFYING THE IDENTITY OF THE PERSON(S) CLAIMING A RIGHT TO DEAL WITH THE LAND COMPRISED IN THIS FOLIO. UNREGISTERED DEALINGS: NIL

*** END OF SEARCH ***

140078

PRINTED ON 6/6/2016

* Any entries preceded by an asterisk do not appear on the current edition of the Certificate of Title. Warning: the information appearing under notations has not been formally recorded in the Register.

InfoTrack An Approved LPI NSW Information Broker

Title Search



LAND AND PROPERTY INFORMATION NEW SOUTH WALES - TITLE SEARCH

FOLIO: C/105665

SEARCH DATE	TIME	EDITION NO	DATE
6/6/2016	4:42 PM	2	27/10/1997

LAND

LOT C IN DEPOSITED PLAN 105665 LOCAL GOVERNMENT AREA WAVERLEY PARISH OF ALEXANDRIA COUNTY OF CUMBERLAND TITLE DIAGRAM DP105665

FIRST SCHEDULE

EASTERN SUBURBS LEGION CLUB LIMITED

(T 3527265)

SECOND SCHEDULE (1 NOTIFICATION)

1 RESERVATIONS AND CONDITIONS IN THE CROWN GRANT(S)

NOTATIONS

NOTE: THE CERTIFICATE OF TITLE FOR THIS FOLIO OF THE REGISTER DOES NOT INCLUDE SECURITY FEATURES INCLUDED ON COMPUTERISED CERTIFICATES OF TITLE ISSUED FROM 4TH JANUARY, 2004. IT IS RECOMMENDED THAT STRINGENT PROCESSES ARE ADOPTED IN VERIFYING THE IDENTITY OF THE PERSON(S) CLAIMING A RIGHT TO DEAL WITH THE LAND COMPRISED IN THIS FOLIO. UNREGISTERED DEALINGS: NIL

*** END OF SEARCH ***

140078

PRINTED ON 6/6/2016


* Any entries preceded by an asterisk do not appear on the current edition of the Certificate of Title. Warning: the information appearing under notations has not been formally recorded in the Register.

84 /Req:C162684 /Doc:CT 05000-150 CT /Rev:07-Aug-2012 /Sts:OK.OK /Prt:08-Jul-2016 14:05 /Seq:1 of 2 Ref:lpi:syd-drel /Src:W 7Message: Supplied by LPT NSW

201. new South Wales. 72913-1 5,38 Appn. No. 32435 [CERTIFICATE OF TITLE.] Reference to last certificate ORDER NO. C704551 Vol. 4786 Fol. 10 CANCELLED REOISTER BOOK." 5000 Fol. 150 Vol TCOTH & CO. LIMITED, by virtue of Certificate of Title Volume 4786 Folio 10, now surrendered is now the proprietor of an Estate in Fee Simple, _ subject nevertheless to the reservations and conditions, if any, contained in the Grant hereinafter referred to, and also subject to such piece of land situated encumbrances, liens, and interests as are notified hereon, in That Parish of Alexandria _____, and County of Cumberland in the Municipality of Waverley containingEleven perches or thereabouts as shown in the plan hereon and therein edged red being part of 4 acres 3 roods 8 perches originally granted to Lewis Gordon by Crown Grant dated the 15th day of June 1848. In witness whereof I have hereunto signed my name and affixed my Seal, this Fifteenth day of December 1938. Mit edgard Signed in the presence of Registrar General. Lease dated the 23rd day of September 1935 Regis-tered Book 1732 No. 154 from Tooth & Co. Limited to Charles Boyce Beeton of Waverley Hotelkeeper of the land above described on which is erected prem-ises known as "Robin Hood" Hotel for the term of 5 years from the 9th day of September 1935. Registrar General. The within mentioned LEASE Her Seale 1732 Ze has expired by effluxion of time. Dated 1774 December 1940 Vide co7160 pod REGISTRAR GERERAL SE]]0. C9.71.662 18 TA LARCE . Carletter to a adel ll per rom the sald leath miled V Produced 17th December 1840 and antered 17th Recember 1940 eromb fr 10 o'clock in the line noon. rington Gar The within mentioned LEASE No. ______ Dop. Reg. Gen 16. 1. 1933 has expired by effluxion of time, Hard . 6haberch 1940 Vide 0467114 167110 Scale 208. to one inch C 704 551 REGISTRAR CENERAL. NOTIFICATION REFERRED TO Easement (if any) in respect of the barge board of a building which overhangs part of the south eastern boundary to the extent of 3 inches. Unele Sten -10 Registrar General.

84 'Req:C162684 /Doc:CT 05000-150 CT /Rev:07-Aug-2012 /Sts:OK.OK /Prt:08-Jul-2016 14:05 /Seq:2 of 2 Ref:lpi:syd-drel /Src:W 7Message: Supplied by LPT NSW

trom the said Soll 9 to Limited to Edward James Joseph Wales of Sydny Licensed Publican No. H 33 Hb 95 . Leave dread the fullenting st from the sold Lasth & Co Limited to Educard James Produced -19 and entered 6th allasah 1346 Joseph plates of Waverly decensed find at 3mb At 3 o'clock in the after Entered and Moundiet 19 59. REGISTRAR GENERAL milation The wifin mentioned LEASE No. 7467115 REGISTRAR GENERAL hes expired by effluxion of time. Dhed 8th October 1948 Vide D903131 9 H 334695 has expired by effluxion of time LEASE NO ... =Entered _26th November 1962 1334494 MEGISTRAR OENERAL. Noj 9 03732. Jean. dated b" hyterduriges from the sold sooth to Limited to Edward Johns Otherson as the rest mass wave a distingtion of a distribution of all those mess wave a distingtion of a distribution of all most motion the distribution of a distribution of all waver by Produced gth October 1948 and the rest 8th October 1948 Walso REGISTRAN GENERAL V 114444 ++ 10 o' idook as the gove No. 1199517 Leave Decod 112 October 6162 Hoon. to Edward James Joseph Hales of Joursky Entered 26th November 1:62. REGISTRAR GENERAL. The within mentioned LEASE No. Dan 2732 Jaloo has expired by effluxion of time. REGISTRAR GENERAL Dated 23+ doctober 1951 Vide F-559514 18ASE W8. J199517 ... has expired by effluxion of time Entered 17th alecember 1965 REGISTRAR GENERAL watao No. 1559515 Leave dated in the September 195 from the said Tooth & bo. Limited its Edward fames forephi walls of Sydney Licensed. REGISTRAR GENERAL N statusei 26th October 1951 and entered 26th October 1951 NOORT 3076 LEASE 20-mto 413 o'clock in the atter noon. -dated 2/28 October 1965 Edward James Jeseph Dales of Warenley to. Public Lunsed REGISTRAR CENERAL Entered 17th accember 1965 andation VEEASE No ._ F559515 has expired by effusion of time. 6602.277 __ Entered __ sett. november 1956 REGISTRAR GENERAL KI LEASE No K 193076 has expired by effluxion of time =Entered 26 H Senual 19 71 REGISTRAR GENERAL Jakas Q No. 6663078 Lease dored and Pataber 1956. from the said both & Co. Limited to Edward James Jacph REGISTRAR GENERAL Wales of Warresly, Licensed Publica _____dated 13 the batober 1970 No.M129765 dans 10 toduard James Joseph Male of Marchey, Lieused Cublichen. the Moreen 956 Entered 26 th Manuary 1971 REGISTRAR GENERAL. REGISTRAR GENERAL 22 LEASE No. GGORA78 -has expired by effluxion of time. NO. PLARAGE LEASE, aced 3rd Fanuary 1971 See 11 334 byu Entered and Manuember to Educard James Joseph Walls of Waverland 1959 Licenced Publican of primises being the Robin Watson 22nd Murch 1270 Emered ... As the land in chie REGISTRAR GENERAL this Jeld is cancello Vol. 305 Fol. RECEDAR GENERAL.




SECOND SCHEDULE

RG 2/64

G-RY 1. Reservations and conditions, if any, contained in the Crown grant above referred to. 2. R756406 Lease to Lorraine Paule Hadin prevarely, Licensed Publican of premises known as "Robin Hood" Hotel, Waverley, Expires 27-10-1980. Contract Structure Contracts 3. R756406 Lease affected by R756407 Mortgage to Tooth & Co. Limited. CANCELLED X8X1404 6-10.1428


NOTE: ENTRIES RULED THROUGH AND AUTHENTICATED BY THE SEAL OF THE REGISTRAR GENERAL ARE CANCELLED

	K-10-1534
Keittat General Keittat General Keittat General	KEGISTERED Semanter of Resistanter of Kesistanter of Kesistanter of
KEGISTERED Signature of Registrar General	KEGISTERED Signature of A Kegistrar General C
Kedistrat General C Kolistrat General C	KEGISTERED Signatuc of Registrar General C C
REGISTERED Signature of Registrar General C 6-10-152d 1	REGISTERED Signature of Registrar General C 6-10-193d 1 1
REGISTERED Signature of Registrar General C 6-10-193d 1 6-10-193d 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	REGISTERED Signature of Registrar General C K-10-1924 K
85.101-38	85.101-39




85 /Req:C162685 /Doc:CT 03274-129 CT /Rev:03-Aug-2012 /Sts:OK.OK /Prt:08-Jul-2016 14:05 /Seq:1 of 2 Ref:lpi:syd-drel /Src:W /Message: Supplied by LPI NSW

Appn. No. 2.3485 new South Wales. [CERTIFICATE OF TITLE] REGISTER BOOK. 3274 For 129 VOL. CANCELLED D Bondi Land and Buildings Limited, applicant in primary application N 23485 is now the proprietor of an estate in fee simple subject nevertheless to the reservations and conditions if any contained in the grant hereinafter referred to and also subject to such encumbrances liens and interests as are notified hereon in Hrat piece of land situated in the ethenicipality of Wewerley parish of Alexandria and burnhy of burnherland as shown in the plan hereon and therein edged red and also shown in the plan lodged with said application of 23485 being part of "hour acres three roods eight perches delineated in the public map of the said parish in the Obepartment of Rando originally granted to Lewis Gordon by Crown grant dated the fifteenth day of June one thousand right hundred and forty eight -21 day of In witness whereof, I have hereinto signed my name and affixed my Scal, this 1922 helening henon Signed in the presence of Registrar General St. Leichhardt (Alg.d 12' 42' 12') toAPfd Kerb AP.F. 16 Sin 000 134 A. 81/4 in 145 (Nº 17) (Nº 19) (Nº 21.) A.P.F.J George & ON Carrington R.J. BURGESS 332 · 21 24 £ 3



85 /Req:C162685 /Doc:CT 03274-129 CT /Rev:03-Aug-2012 /Sts:OK.OK /Prt:08-Jul-2016 14:05 /Seq:2 of 2 Ref:lpi:syd-drel /Src:W /Message: Supplied by LPI NSW

10. A 739278 BMORIGIDE dated 30 August from the said Bondi Land and Buildings 1921 Limited To Edward James Egan of Bondi Caldle A Agent and John Bruske of January 1922 pler necn. Elaur FEDISTRA , GENERAL GAVENTAS ac 10 January 1902 gar General. Profilement 112104 19 22 anuan in the after al neon Antheraul No. A 188926 TRANSFER dated 10th Februar 19 22 from the said Bondi Land and Buyld is with consenticf martgagee) Sardiner of hart _of the land within described. Produced and entered 1922, Jel march 1922 o'clock in the n00n. Both Bleauth Cancelled & Certificate of Title issued Vol. 296 Fol. 139 Acres TRAR GENERAL No. A SPLIPIO DIRANGEER and 3rd April from the said Boude Land and Buildings 1972 p to furt couscul of Mortgagees William to Samlel Jrey. el pari of the land within described. 201 Produced and entered 84 192 ure. o'cleck in the after 1 3 Noch. at_ Cancelled & Certifice:e of Tille Issued elea Vol. 3327 Fol. 205 REGISTRAR GENERAL No. A Q17790 TRANSFER dated & M. Jehnen 1023 from the said with Teali of the land within described Produced and entered Get April 19 23 o'clock in the fore noon 11 at pleaser. Cancelled & Certificate of Title issued Vol. 343 & Fol. 79 W.to REGISTRAR GENERAL DISCHARGE of within Mortgage 957321 No. A 144 g "In 1923 392 78 dated A 1923 and entered Produced. 0 .1923 3 1/2 o'clock in the CENSP Eleastly 873 Arres REGISTRAR GENERAL A772704 The within Caveat No._ is hereby withdrawn. Nide: A'957322 1923 Dated. cleanily. TP. REGISTRAR GENERAL dated 15 June 1923 957323 TRANSFER No. A_ Buildings from the said Bondi hand Wineston ited ahar residue Sof the fand willin assoribed Producea ona envered Asty 1 1923 3. tan npan.) O CLOCK THE Cancelled & Conficate of Title issued Vol. 44 Fol. 238 HTH SEGISTRAR GENERAL . .



the Municipality of Waverley Parish of Alexandria and County of Cumberland being part of 1.942 hectares granted to Lewis Gordon on 15-6-1848.

FIRST SCHEDULE


SECOND SCHEDULE

1. Reservations and conditions, if any, contained in the Crown Grant above referred to. 2. Lease No. P642466 of premises being the "Robin Hood" Hotel to Edward James Joseph Wales of Waverley, Licensed Publican. Registered 22-3-1976. Surrenderd R756405

NOTE: ENTRIES RULED THROUGH AND AUTHENTICATED BY THE SEAL OF THE REGISTRAR GENERAL ARE CANCELLED.

(Page 2 of 2 pages)	Supplied by LPI NSW	Vol. 13057 Fol. 180
Lence 1756406 X82 Mort 18-5 1991 descale	NATURE INSTRUMENT NATURE NUMBER DATE LECASC ALDER DATE LECASC PUBLICALO LECASC PUBLICALO LECASC PUBLICALO LECASC PUBLICALO LECASC RTS. 64.06	Lorraine Paula Havin by Transfer
affected by RTSHAR Hold and for the stand of the RTSHAR Contrained to the stand of	SECOND SCHEDU PARTICULARS PARTICULARS CREATED OF RHATER TRANSPERCY LANSE Donatey of University to Teach of Donatey of University to Teach of Alected by RHATERS Transperce of Lance to Alected by RHATERS Mougage of Lance to Alected by RHATERS Mougage of Lance to Alected by RETHERS Alected by RETHERS ALE to Alected by RETHERS Alected by RETHERS ALE to Alected by RETHERS ALE to Alected by RETHERS ALE to Alected by RETHERS ALE to Alected by RETHERS ALE to Alected by RETHERS ALE to Alected by RETHERS ALE	FIRST SCHEDULE (continued) REGISTERED PROPRIETOR Z132733. Registered 9-8-1990 GENERATIO FOLIO SEE AUTO FOLIO
	ENTERED ENTERED 	NATURE
	Registrar General	INSTRUMENT NUMBER
ARE CANCELLED	ancolled Distancelled Cancelled	DATE
	CANCELLATION R 51412 9 R 51412 9 R 514128 R 756405	ENTERED
		Registrar General
	213273224 -47 2466920 4 2466920 4 2466920 4 ML R ML R	R 756404L X881404L X881404L X881404L

90 /Req:C178290 /Doc:CT 13057-180 CT /Rev:16-Dec-2010 /Sts:OK.OK /Prt:08-Jul-2016 13:41 /Seq:2 of 2 Ref:1 1:syd-drel /Src:W /Message: Supplied by LPI NSW



			FIRST SCHEDULE (continued)		-		, 17 V.C.N. Bligh	V.C.N. Blight, Government Printer
			REGISTERED PROPRIETOR	NATURE	INSTRUMENT NUMBER	DATE	ENTERED	Signature of Rezistrar-General
			SECOND SCHEDULE (continued)					
NATURE	INSTRUMENT NUMBEA	DATE	PARTICULARS	ENTERED	Signature of Registrar-Generel	0	CANCELLATION	
Mertguy Mertgrads	R275124P		to comen sealth Trading Bank et Australia to Commensionitis Savings Bank of Australia	1261-6-01	and the second se			
				0.25				

83 /Req:Cl62683 /Doc:CT 10494-204 CT /Rev:21-Dec-2010 /Sts:OK.OK /Prt:08-Jul-2016 13:43 /Seq:2 of 2 Ref:Lpi:syd-arei /Src:w /Message: Supplied by LPI NSW



203 Bronte Road, Waverley NSW

Appendix 3 – Section 149

PLANNING CERTIFICATE UNDER SECTION 149 ENVIRONMENTAL PLANNING AND ASSESSMENT ACT 1979

WAVERLEY

Ruth Heywood RiskTech, Level 5, 3 Rider Boulevard

Cert. No.35297 Date: 21 July 2016 Receipt No. 1701416 Your reference: KF ROBIN HOOD HOTE:17009

Property location	ROBIN HOOD HOTEL, 203-209 Bronte Road, WAVERLEY NSW 2024
Parcel description:	Lot 1 DP 655918, Lot A DP 105665, Lot 1 DP 59526
Owner:	Mr R L Whitten and Mr D M Whitten and Mr A J Whitten
	C/- Robin Hood Hotel 203 Bronte Rd WAVERLEY NSW 2024

[The next page is page 2]

In accordance with the requirements of section 149 of the Environmental Planning and Assessment Act 1979 (as amended), the following prescribed matters relate to the land at the date of this certificate.

ITEM 1

Names of relevant planning instruments and DCPs

(1) The name of each environmental planning instrument that applies to the carrying out of development on the land.

The following environmental planning instruments apply to the carrying out of development on the land:

Waverley LEP 2012 (Amendment No. 9) - Gazetted: 30 January 2015

- SEPP No. 4 Development Without Consent and Miscellaneous Complying Development
- SEPP No. 6 Number of Storeys in a Building
- SEPP No. 14 Coastal Wetlands
- SEPP No. 19 Bushland in Urban Areas
- SEPP No. 22 Shops and Commercial Premises
- SEPP No. 32 Urban Consolidation (Redevelopment of Urban Land)
- SEPP No. 33 Hazardous and Offensive Development
- SEPP No. 50 Canal Estates
- SEPP No. 55 Remediation of Land
- SEPP No. 64 Advertising and Signage
- SEPP No. 65 Design Quality of Residential Flat Development
- SEPP No. 70 Affordable Housing (Revised Schemes)
- SEPP No. 71 Coastal Protection
- SEPP (Affordable Rental Housing) 2009
- SEPP (Building Sustainability Index: BASIX) 2004
- SEPP (Exempt and Complying Development Codes) 2008
- SEPP (Housing for Seniors or People with a Disability) 2004
- SEPP (Infrastructure) 2007
- SEPP (Major Development) 2005
- SEPP (Temporary Structures) 2007
- SREP (Sydney Harbour Catchment)

Any enquiries regarding these SEPPs should be directed to the Department of Planning and Environment on: *(02)* 9228 6333 or http://www.planning.nsw.gov.au

(2) The name of each proposed environmental planning instrument that will apply to the carrying out of development on the land and that is or has been the subject of community consultation or on public exhibition under the Act (unless the Secretary has notified the council that the making of the proposed instrument has been deferred indefinitely or has not been approved).

The following proposed environmental planning instruments apply to the carrying out of development on the land:

 Planning Proposal No 1/2016 to amend Waverley Local Environmental Plan 2012 in relation to design excellence considerations, heritage corrections and other minor amendments. Proposed Competition SEPP

Note: Any enquiries regarding these SEPPs should be directed to the Department of Planning and Environment on: *(02)* 9228 6333 or http://www.planning.nsw.gov.au

(3) The name of each development control plan that applies to the carrying out of development on the land.

The following development control plan (DCP) applies to the land:

- Waverley DCP 2012 Amendment No. 4
- (4) In this clause, proposed environmental planning instrument includes a planning proposal for a LEP or a draft environmental planning instrument.

ITEM 2

Zoning and land use under relevant LEPs

For each environmental planning instrument or proposed instrument referred to in clause 1 (other than a SEPP or proposed SEPP) that includes the land in any zone (however described):

- (a) the identity of the zone, whether by reference to a name (such as "Residential Zone" or "Heritage Area") or by reference to a number (such as "Zone No 2(a)"),
- (b) the purposes for which the instrument provides that development may be carried out within the zone without the need for development consent,
- (c) the purposes for which the instrument provides that development may not be carried out within the zone except with development consent,
- (d) the purposes for which the instrument provides that development is prohibited within the zone,

Waverley LEP 2012 (Amendment No. 9) - Gazetted: 30 January 2015

Zone B4 Mixed Use

- 1 Objectives of zone
 - To provide a mixture of compatible land uses.
 - To integrate suitable business, office, residential, retail and other development in accessible locations so as to maximise public transport patronage and encourage walking and cycling.
 - To encourage commercial uses within existing heritage buildings and within other existing buildings surrounding the land zoned B3 Commercial Core.
- 2 Permitted without consent

Home occupations

3 Permitted with consent

Boarding houses; Building identification signs; Business identification signs; Child care centres; Commercial premises; Community facilities; Educational establishments; Entertainment facilities; Function centres;

Hostels; Hotel or motel accommodation; Information and education facilities; Light industries; Medical centres; Passenger transport facilities; Recreation facilities (indoor); Registered clubs; Respite day care centres; Restricted premises; Roads; Self-storage units; Seniors housing; Shop top housing; Any other development not specified in item 2 or 4.

4 Prohibited

Agriculture; Air transport facilities; Airstrips; Amusement centres; Boat building and repair facilities; Boat launching ramps; Boat sheds; Camping grounds; Caravan parks; Cemeteries; Charter and tourism boating facilities; Crematoria; Depots; Eco-tourist facilities; Electricity generating works; Exhibition homes; Exhibition villages; Extractive industries; Farm buildings; Forestry; Freight transport facilities; Heavy industrial storage establishments; Helipads; Highway service centres; Home occupations (sex services); Industrial retail outlets; Industrial training facilities; Industries; Jetties; Marinas; Mooring pens; Moorings; Open cut mining; Recreation facilities (major); Research stations; Residential accommodation; Resource recovery facilities; Rural industries; Sex services premises; Signage; Storage premises; Transport depots; Truck depots; Warehouse or distribution centres; Waste disposal facilities; Water recreation structures; Water supply systems; Wharf or boating facilities.

(e) whether any development standards applying to the land fix minimum land dimensions for the erection of a dwelling-house on the land and, if so, the minimum land dimensions so fixed,

The land is **not** subject to any development standards that fix minimum land dimensions for the erection of a dwelling house.

(f) whether the land includes or comprises critical habitat,

The land does **not** comprise critical habitat.

(g) whether the land is in a conservation area (however described),

The land **is** within a Heritage Conservation Area.

- The land is located within a Heritage Conservation Area General identified in Waverley Local Environmental Plan 2012.
- (h) whether an item of environmental heritage (however described) is situated on the land.

The land **contains** an Item of Environmental Heritage.

• The land contains a Heritage Item - General identified in Waverley Local Environmental Plan 2012.

ITEM 2A

Zoning and land use under <u>State Environmental Planning Policy (Sydney</u> <u>Region Growth Centres) 2006</u>

To the extent that the land is within any zone (however described) under:

- (a) Part 3 of the State Environmental Planning Policy (Sydney Region Growth Centres) 2006 (the 2006 SEPP), or
- (b) A Precinct Plan (within the meaning of the 2006 SEPP), or
- (c) A proposed Precinct Plan that is or has been the subject of community consultation or on public exhibition under the Act,

the particulars referred to in clause 2(a)-(h) in relation to that land (with a reference to "the instrument" in any of those paragraphs being read as a reference to Part 3 of the 2006 SEPP, or the Precinct Plan or proposed Precinct Plan, as the case requires).

The land is **not** subject to the <u>State Environmental Planning Policy (Sydney</u> <u>Region Growth Centres) 2006.</u>

ITEM 3

Complying development

- (1) The extent to which the land is land on which complying development may be carried out under each of the codes for complying development because of the provisions of clauses 1.17A (1) (c) to (e), (2), (3) and (4), 1.18 (1) (c3) and 1.19 of State Environmental Planning Policy (Exempt and Complying Development Codes) 2008.
- (2) The extent to which complying development may not be carried out on that land because of the provisions of clauses 1.17A (1) (c) to (e), (2), (3) and (4), 1.18 (1) (c3) and 1.19 of that Policy and the reasons why it may not be carried out under those clauses.
- (3) If the council does not have sufficient information to ascertain the extent to which complying development may or may not be carried out on the land, a statement that a restriction applies to the land, but it may not apply to all of the land, and that council does not have sufficient information to ascertain the extent to which complying development may or may not be carried out on the land.

General Housing Code

Complying development under the General Housing Code **may not** be carried out on the land. The land is affected by specific land exemption:

- land contains a Heritage Item.
- land is located within a Heritage Conservation Area development is excluded from SEPP (Exempt and Complying Development) 2008, unless the development is for a detached outbuilding or swimming pool.

Rural Housing Code

There are no lands within the Waverley Council area that are affected by this Code.

Housing Alterations Code

Complying development under the Housing Alterations Code **may not** be carried out on the land. The land is affected by specific land exemption:

land contains a Heritage Item.

General Development Code

Complying development under the General Development Code **may not** be carried out on the land. The land is affected by specific land exemption:

land contains a Heritage Item.

Commercial and Industrial Alterations Code

Complying development under the Commercial and Industrial Alteration Code **may not** be carried out on the land. The land is affected by specific land exemptions:

land contains a Heritage Item.

Commercial and Industrial (New Buildings and Additions) Code

Complying development under the Commercial and Industrial (New Building and Additions) Code **may not** be carried out on the land. The land is affected by specific land exemptions:

- land contains a Heritage Item.
- land is located within a Heritage Conservation Area.

Subdivisions Code

Complying development under the Subdivisions Code **may not** be carried out on the land. The land is affected by specific land exemptions:

land contains a Heritage Item.

Demolition Code

Complying development under the Demolition Code **may not** be carried out on the land. The land is affected by specific land exemption:

land contains a Heritage Item.

Fire Safety Code

Complying development under the Fire Safety Code **may not** be carried out on the land. The land is affected by specific land exemptions:

land contains a Heritage Item.

Disclaimer: If a restriction applies to the land, the restriction may not apply to all of the land. Council does not have sufficient information to ascertain the extent to which complying development may or may not be carried out on the land.

Complying development may be able to be carried out on the land provided it meets the requirements and standards of *State Environmental Planning Policy (Exempt and Complying Development Codes) 2008.*

ITEM 4

Coastal protection

Whether or not the land is affected by the operation of section 38 or 39 of the <u>Coastal Protection Act 1979</u>, but only to the extent that the council has been so notified by the Department of Finance, Services and Innovation.

The land is **not** affected by Sections 38 or 39 of the <u>Coastal Protection Act</u> <u>1979.</u>

ITEM 4A

Certain information relating to beaches and coasts

(1) In relation to a coastal council - whether an order has been made under Part 4D of the <u>Coastal Protection Act 1979</u> in relation to temporary coastal protection works (within the meaning of that Act) on the land (or on public land adjacent to that land), except where the council is satisfied that such an order has been fully complied with.

No.

(2) In relation to a coastal council:

(a) Whether the council has been notified under section 55x of the <u>Coastal</u> <u>Protection Act 1979</u> that temporary coastal protection works (within the meaning of that Act) have been placed on the land (or on public land adjacent to that land), and

No.

(b) If works have been so placed-whether the council is satisfied that the works have been removed and the land restored in accordance with that Act.

Not applicable.

(3) (Repealed)

ITEM 4B

Annual charges under <u>Local Government Act 1993</u> for coastal protection services that relate to existing coastal protection works

In relation to a coastal council - whether the owner (or any previous owner) of the land has consented in writing to the land being subject to annual charges under section 496B of the *Local Government Act 1993* for coastal protection services that relate to existing coastal protection works (within the meaning of section 553B of that Act).

No.

Note "Existing coastal protection works" are works to reduce the impact of coastal hazards on land (such as seawalls, revetments, groynes and beach nourishment) that existed before the commencement of section 553B of the <u>Local Government</u> <u>Act 1993.</u>

ITEM 5

Mine subsidence

Whether or not the land is proclaimed to be a mine subsidence district within the meaning of section 15 of the *Mine Subsidence Compensation Act 1961*.

The land is **not** proclaimed to be a mine subsidence district within the meaning of section 15 of the *Mine Subsidence Compensation Act 1961*.

ITEM 6

Road widening and road realignment

Whether or not the land is affected by any road widening or road realignment under:

- (a) Division 2 of Part 3 of the Roads Act 1993, or
- (b) any environmental planning instrument, or
- (c) any resolution of the council.

The land is **not** affected by any road widening or road realignment under Division 2 of Part 3 of the Roads Act 1993, or any environmental planning instrument or any resolution of the Council.

ITEM 7

Council and other public authority policies on hazard risk restrictions

Whether or not the land is affected by a policy:

- (a) adopted by the council, or
- (b) adopted by any other public authority and notified to the council for the express purpose of its adoption by that authority being referred to in planning certificates issued by the council,

that restricts the development of the land because of the likelihood of land slip, bushfire, tidal inundation, subsidence, acid sulphate soils or any other risk (other than flooding).

- (a) The land is **not** affected by a policy adopted by Council that restricts the development of land because of the likelihood of land slip, bushfire, tidal inundation, subsidence, acid sulphate soils or any other risk (other than flooding).
- (b) The land is **not** affected by a policy adopted by another public authority and notified to the Council for the express purpose of its adoption by that authority being referred to in planning certificates issued by the Council, that restricts the development of land because of the likelihood of land slip, bushfire, tidal inundation, subsidence, acid sulphate soils or any other risk (other than flooding).

ITEM 7A

Flood related development controls information

(1) Whether or not development on that land or part of the land for the purposes of dwelling houses, dual occupancies, multi dwelling housing or residential flat buildings (not including development for the purposes of group homes or seniors housing) is subject to flood related development controls.

The land is **not** subject to flood related development controls for the purposes of dwelling houses, dual occupancies, multi dwelling housing or residential flat buildings (not including development for the purposes of group homes or seniors housing).

(2) Whether or not development on that land or part of the land for any other purpose is subject to flood related development controls.

The land is **not** subject to flood related development controls.

(3) Words and expressions in this clause have the same meanings as in the instrument set out in the Schedule to the Standard Instrument (Local Environmental Plans) Order 2006.

ITEM 8

Land reserved for acquisition

Whether or not any environmental planning instrument or proposed environmental planning instrument referred to in clause 1 makes provision in relation to the acquisition of the land by a public authority, as referred to in section 27 of the Act.

The land is **not** affected by any environmental planning instrument or proposed environmental planning instrument referred to in clause 1 that provides for the acquisition of the land by a public authority, as referred to in section 27 of the Act.

ITEM 9

Contributions plans

The name of each contributions plan applying to the land.

Waverley Council Development Contribution Plan 2006 (Amendment No.7).

ITEM 9A

Biodiversity certified land

If the land is biodiversity certified land (within the meaning of Part 7AA of the <u>Threatened Species Conservation Act 1995</u>), a statement to that effect.

The land is **not** biodiversity certified land under Part 7AA of the <u>Threatened</u> <u>Species Conservation Act 1995.</u>

ITEM 10

Biobanking agreements

If the land is land to which a biobanking agreement under Part 7A of the <u>*Threatened Species Conservation Act 1995*</u> relates, a statement to that effect (but only if the council has been notified of the existence of the agreement by the Chief Office of Environment and Heritage).

Council has **not** been notified of any biobanking agreement under Part 7A of the <u>Threatened Species Conservations Act 1995</u> relating to the land.

ITEM 11

Bush fire prone land

If any of the land is bush fire prone land (as defined in the Act), a statement that all or, as the case may be, some of the land is bush fire prone land.

If none of the land is bush fire prone land, a statement to that effect.

The land is **not** bush fire prone land (as defined in the Act).

ITEM 12

Property vegetation plans

If the land is land to which a property vegetation plan under the Native Vegetation Act 2003 applies, a statement to that effect (but only if the council has been notified of the existence of the plan by the person or body that approved the plan under that Act).

Council has **not** been notified of any property vegetation plans under the *Native Vegetation Act 2003* applying to the land.

ITEM 13

Orders under Trees (Disputes Between Neighbours) Act 2006

Whether an order has been made under the Trees (Disputes Between Neighbours) Act 2006 to carry out work in relation to a tree on the land (but only if the council has been notified of the order).

No.

ITEM 14

Directions under Part 3A

If there is a direction by the Minister in force under section 75P (2) (c1) of the Act that a provision of an environmental planning instrument prohibiting or restricting the carrying out of a project or a stage of a project on the land under Part 4 of the Act does not have effect, a statement to that effect identifying the provision that does not have effect.

There is **no** direction under Part 3A.

ITEM 15

Site compatibility certificates and conditions for seniors housing

If the land is land to which <u>State Environmental Planning Policy (Housing for</u> <u>Seniors or People with a Disability) 2004</u> applies:

- (a) a statement of whether there is a current site compatibility certificate (seniors housing), of which the council is aware, in respect of proposed development on the land and, if there is a certificate, the statement is to include:
 - (i) the period for which the certificate is current, and
 - (ii) that a copy may be obtained from the head office of the Department, and

Council has **not** been notified of any site compatibility certificate and conditions for seniors housing.

(b) a statement setting out any terms of a kind referred to in clause 18 (2) of that Policy that have been imposed as a condition of consent to a development application granted after 11 October 2007 in respect of the land.

Council has **not** been notified of any site compatibility certificate and conditions for seniors housing.

ITEM 16

Site compatibility certificates for infrastructure

A statement of whether there is a valid site compatibility certificate (infrastructure), of which the council is aware, in respect of proposed development on the land and, if there is a certificate, the statement is to include:

- (a) the period for which the certificate is valid, and
- (b) that a copy may be obtained from the head office of the Department.

Council has **not** been notified of any site compatibility certificate for infrastructure.

ITEM 17

Site compatibility certificates and conditions for affordable rental housing.

- (1) A statement of whether there is a current site compatibility certificate (affordable rental housing), of which the council is aware, in respect of proposed development on the land and, if there is a certificate, the statement is to include:
 - (a) the period for which the certificate is current, and
 - (b) that a copy may be obtained from the head office of the Department.

Council has **not** been notified of any site compatibility certificate and condition for affordable rental housing.

(2) A statement setting out any terms of a kind referred to in clause 17(1) or 38 (1) of <u>State Environmental Planning Policy (Affordable Rental Housing) 2009</u> that

have been imposed as a condition of consent to a development application in respect of the land.

Council has **not** been notified of any site compatibility certificate and condition for affordable rental housing.

ITEM 18

Paper subdivision information

(1) The name of any development plan adopted by a relevant authority that applies to the land or that is proposed to be subject to a consent ballot.

Council is **not** aware of any development plan adopted by a relevant authority that applies to the land or that is proposed to be subject to a consent ballot.

(2) The date of any subdivision order that applies to the land.

There is **no** subdivision order applying to the land.

(3) Words and expressions used in this clause have the same meaning as they have in Part 16C of this Regulation.

ITEM 19

Site verification certificates

A statement of whether there is a current site verification certificate, of which the council is aware, in respect of the land and, if there is a certificate, the statement is to include:

(a) the matter certified by the certificate, and

Note. A site verification certificate sets out the Secretary's opinion as to whether the land concerned is or is not biophysical strategic agricultural land or critical industry cluster land—see Division 3 of Part 4AA of State Environmental Planning Policy (Mining, Petroleum Production and Extractive Industries) 2007.

- (b) the date on which the certificate ceases to be current (if any), and
- (c) that a copy may be obtained from the head office of the Department.

Council has not been notified of any site verification certificates.

ITEM 20

Loose-fill asbestos insulation

If the land includes any residential premises (within the meaning of Division 1A of Part 8 of the <u>Home Building Act 1989</u>) that are listed on the register that is required to be maintained under that Division, a statement to that effect

Council has **not** been notified of a residential dwelling erected on this land containing loose-fill asbestos ceiling insulation. Contact NSW Fair Trading for more information.

Note: The following matters are prescribed by section 59(2) of the <u>Contaminated</u> <u>Land Management Act 1997</u> as additional matters to be specified in a planning certificate:

(a) that the land to which the certificate relates is significantly contaminated land within the meaning of that Act-if the land (or part of the land) is significantly contaminated land at the date when the certificate is issued,

No.

(b) that the land to which the certificate relates is subject to a management order within the meaning of that Act-if it is subject to such an order at the date when the certificate is issued,

No.

(c) that the land to which the certificate relates is the subject of an approved voluntary management proposal within the meaning of that Act-if it is the subject of such an approved proposal at the date when the certificate is issued,

No.

(d) that the land to which the certificate relates is subject to an ongoing maintenance order within the meaning of that Act-if it is subject to such an order at the date when the certificate is issued,

No.

(e) that the land to which the certificate relates is the subject of a site audit statement within the meaning of that Act-if a copy of such a statement has been provided at any time to the local authority issuing the certificate.

No.

Information provided under S.149 (2) is in accordance with the matters prescribed under Schedule 4 of the *Environmental Planning and Assessment Regulation 2000* and is provided only to the extent that the Council has been notified by the Department of Public Works or Department of Planning and Environment.

For the purpose of s.149 (5) of the *Environmental Planning and Assessment Act, 1979,* the following additional information is provided with relation to development applications which have been determined.

When information pursuant to Section 149 (5) is requested, the Council is under no obligation to furnish any of the information supplied herein pursuant to that Section.

DA-434/2008/B	Approved	26-Jul-2011	Modification of internal layout of Hotel and increase in number of persons on the lower outdoor deck from 15 to 21 (Condition 6).
DA-6/2012	Approved -	31-Mar-2014	Alterations and

	Land & Environment Court		conversion of first floor of Hotel to a restaurant and public area (including smokers area) for an additional 150 patrons.
DA-473/2015	Approved	15-Apr-2016	To install food and beverage caravan in bottle shop at Robin Hood Hotel
DA-6/2012/A	Approved	06-Apr-2016	Modifications to internal layout and conditions of consent (Robin Hood Hotel)

Additional Information Section 149 (5)

• The land has a frontage to an Arterial Road.

Council draws your attention to Section 149 (6) which states that a Council shall not incur any liability in respect of any advice provided in good faith pursuant to sub-section (5).

The absence of any reference to any matters affecting the land shall not imply that the land is not affected by any matter not referred to in this Certificate.

Please contact the Council's Duty Planner for further information about any instruments or affectations referred to in the Certificate.

PETER BROWN GENERAL MANAGER



Appendix 4 – Dangerous Goods Search



Our Ref: D16/628649 Your ref: Ruth Heywood

15 July 2016

Attention: Ruth Heywood Risk Tech Level 5 3 Rider Blvd Rhodes NSW 2138

Dear Ms Heywood,

RE SITE: 203 Bronte Rd Waverley NSW

I refer to your site search request received by SafeWork NSW on 11 July 2016 requesting information on Storage of Hazardous Chemicals for the above site.

A search of the records held by SafeWork NSW has not located any records pertaining to the above mentioned premises.

For further information or if you have any questions, please call our Customer Service Centre on 13 10 50 or email <u>licensing@safework.nsw.gov.au</u>

Yours sincerely,

Brent Jones Customer Service Officer **Customer Service Centre - Operations** SafeWork NSW