

Re: Dilapidation Report for Property

Job: 200462

Date: 06-01-2024

Prepared for: Orosi
Project: 3-4 Llanfoyst St, Randwick



Prepared by:
Per:

Smart Structures Australia
Ref: 200462 – Pre Dilap

Table of Contents

INTRODUCTION	3
EXECUTIVE SUMMARY	4
INSPECTED AREAS	5
APPENDIX (A)	6
“Council Assets ”	6
APPENDIX (B)	9
“5 Llanfoys Street, Randwick, NSW ”	9
APPENDIX (C)	11
“3 Albert Street, Randwick ”	11
APPENDIX (D)	13
“5 Albert Street, Randwick ”	13
APPENDIX (E)	16
“12 Milford Street, Randwick”	16
DISCLAIMER	20

INTRODUCTION

Important Information Regarding the Scope and Limitations of the Inspection and this Report

- I. This report is **not** an all-encompassing report dealing with the building from every aspect. This report is **not** a Certificate of Compliance with the requirements of any Act, Regulation, Ordinance or by-law. It is **not** a structural report. Should you require any advice of a structural nature you should contact a structural engineer.
- II. **THIS IS A VISUAL INSPECTION ONLY** limited to those areas and the sections of the property fully accessible to the inspector on the date of inspection. An inspection **does not** include breaking apart, dismantling, removing or moving objects including but not limited to, foliage, mouldings, roof insulation/insulation, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances or personal possessions. The inspector **cannot** see inside walls, between floors, inside skilled iron roofing, behind stored goods in cupboards, or other areas that are concealed or obstructed. The inspector **did not** dig, gouge, force or perform any other invasive procedures. Visible timbers cannot be destructively probed or hit without the written permission of the property owner.
- III. This report **does not** and **cannot** make comment upon defects that may have been concealed during the assessment or detection of defects (including - rising damp and leaks) which may be subject to the prevailing weather conditions; the presence or absence of timber pests, gas-fittings, common property areas, environmental concerns; the proximity of the property to flight paths, railways, or busy traffic; noise levels; health and safety issues; heritage concerns; security concerns; fire protections; site drainage (apart from surface water drainage); swimming pools and spas (non-structural); detection and identification of illegal building work; detection and identification of illegal plumbing work; durability of exposed finishes; neighbourhood problems; and document analysis; electrical installations; any matters that are solely regulated by statute; any area(s) or item(s) that **could not** be inspected by the consultant. Accordingly, this report is **not a guarantee** that defects and/ or damage **do not** exist in any inaccessible or partly inaccessible areas or sections of the property. (NB: such matters may upon request be covered under the terms of a special purpose property report.)
- IV. In the event of any controversy or claim arising out of, or relating to this report, it will be settled by arbitration, in accordance with the rules of the Institute of Arbitrators Australia. Any judgments from such arbitration shall be binding upon both parties.

EXECUTIVE SUMMARY

The building on **3-4 Llanfoyst St, Randwick** will be demolished as part of a residential development. The site inspection was conducted on 04-12-2023.

Smart Structure Australia (SSA) has been engaged by **Orosi** to conduct a Dilapidation Report of **3-4 Llanfoyst St, Randwick** will be demolished as part of a residential development. The site inspection was conducted to satisfy condition(s) of the DA Consent.

Inspections areas are limited to:.

- **5 Llanfoyst St, Randwick**, Exterior and interior walls, exterior and interior flooring, and fence adjacent to the proposed construction site.
- **3 Albert St, Randwick**, Exterior and interior walls, exterior and interior flooring, and fence adjacent to the proposed construction site.
- **5 Albert St, Randwick**, Exterior and interior walls, exterior and interior flooring, and fence adjacent to the proposed construction site.
- **12 Milford St, Randwick**, Exterior and interior walls, exterior and interior flooring, and fence adjacent to the proposed construction site.
- Areas highlighted on the image on the following page.
- Facades adjacent to the work site.
- Trees, shrubs and grasses.
- All existing street furniture, lighting poles, traffic poles, signs, and the like.
- All existing footpaths and kerbstones.
- All existing pit covers.

Only a visual inspection was carried out, which was used to create this report, no core drilling, testing or structural sampling has been carried out. The report will also comment on any obvious signs of damage to finishes in these areas but will exclude the following:

- Areas surrounding **3-4 Llanfoyst St, Randwick** not listed above.
- Fit-outs which are not parts of the finishes such as light, kitchen and theatre fixtures and the like.
- Building interior existing services such as electrical, air conditioning, lift, water, telecom, fire and the like.
- Doors and windows.
- The interior room surfaces.

INSPECTED AREAS

The Area*(s) inspected were:

The internal, external spaces of the property as accessible and visible.

The Area*(s) NOT Accessible for any Inspection and the Reason(s) why were:

No inspection was made of concealed frame timbers or any areas concealed by wall linings/sidings, soil, landscaping, rubbish, floor coverings, furniture, pictures, appliances, stored items, insulation, hollow blocks/pots or any other obstructions to visual inspection.

Further than **20m** from the said site unless otherwise stated.

The Area*(s) in which Visual Inspection was Obstructed and the reason(s) why were:

Floor coverings and furnishings

Vegetation growth

Stored boxes etc...

* No comment is made on these concealed areas.

APPENDIX (A)

“Council Assets ”

This section considers the existing condition of footpaths, kerbs and gutter, road surface and all existing street furniture, lighting poles, traffic poles, signs prior to the commencement of any works proposed at: **3-4 Llanfoyst St, Randwick.**



Summary:

The above highlighted section of **Llanfoyst St** associated with the subject site was inspected and photographic evidence was compiled to depict the existing condition of the council assets along this particular stretch of the road prior to the commencement of any work at the subject site.

The road surface of **Llanfoyst St** at the time of the inspection was in a poor condition with evidence of cracking, and sinking adjacent to the proposed site as noted in the table below, with photos attached in Appendix A.

At the same time, the kerb, gutter and footpath that accompany the roadway were also inspected. At the time of this inspection, Kerb and gutter were found to be in reasonable condition. There was not a proper footpath pavement at the time of the inspection as shown on the photos.

The condition of the telegraph poles, street signs, and service pits was also inspected and determined to be in good condition.

Summary of photos attached in Appendix A:

Appendix A Council Assets	
Figure Number	Description
1~103	General condition of Llanfoyst St council assets
1 ~ 65	General condition of kerb and gutter
18-29-31-44-53-62-	Crack propagation through kerb and gutter
67~102	
69-70-73-74-75-76-77-78-79-80-81-82-83-88-91-92-95-96-	Crack propagation and damages evidence through road surface
103	General condition of street telegraph pole
28-37-68	General condition of service pit

"This table provides an overview of the cracks observed in the photos from the Appendix.

It is important to note that not all cracks are mentioned in this table. For a more comprehensive view and additional evidence, please refer to the photos in the Appendix.

APPENDIX (B)

“5 Llanfoys Street, Randwick, NSW ”

This section considers the existing condition of internal floors, walls, ceiling of all the units, garage of the building, as accessible and visible prior to the commencement of any proposed works on the 3-4 Llanfoys Street, Randwick, NSW.



Summary:

The above highlighted property at **5 Llanfoys Street, Randwick, NSW**, which is associated with the subject site was inspected and photographic evidence compiled in order to depict the existing condition of the building prior to the commencement of any work at the subject site.

This section considers the existing condition of the walls, ceiling, flooring, of the internals of all units at **5 Llanfoys Street, Randwick, NSW**. The building on **5 Llanfoys Street, Randwick, NSW** has 3 levels, and 7 units. Every unit has a living room, kitchen, bathroom, master bedroom, bedroom, and a balcony. The property also has one level garage and storages

At the time of inspection, the internal walls, ceiling, flooring of all the units were found to be in good condition with no evidence of cracks as noted in the table below, with photos attached in Appendix B-2.

At the time of inspection, external of the building and common areas were found to be in good condition with no evidence of cracks propagating through the garage floor as noted in the table below, with photos attached in Appendix B-1.

Summary of photos attached in Appendix B-1 & B-2

Appendix B-1 external and common areas of 5 Llanfoyst St	
Figure Number	Description
1~91	General condition of common areas
Appendix B-1 Internal of units of 5 Llanfoyst St	
Figure Number	Description
1~233	General condition of internal of units
1~45	General condition of internal walls, ceiling and floor of unit 3
46~102	General condition of internal walls, ceiling and floor of unit 4
103~129	General condition of internal walls, ceiling and floor of unit 6
130~164	General condition of internal walls, ceiling and floor of unit 2
165~200	General condition of internal walls, ceiling and floor of unit 7
201~233	General condition of internal walls, ceiling and floor of unit 1
	No Access to Unit 5

"This table provides an overview of the cracks observed in the photos from the Appendix.

It is important to note that not all cracks are mentioned in this table. For a more comprehensive view and additional evidence, please refer to the photos in the Appendix.

APPENDIX (C)

“3 Albert Street, Randwick ”

This section considers the existing condition of external of the building . SSA tried to get access by sending registered mail to all units without any respond.



Summary:

SSA tried to get access by sending 2 registered mail to all 10 units without any respond. The registered mail evidence are as below:




The image displays ten 'Registered Post - Lodgement Receipt' forms, numbered 1 through 10, arranged in two columns of five. Each form is a standard Australian Registered Post receipt, used for tracking and proof of delivery. The forms are for registered mail items sent to Unit 1/3 Albert St, Randwick, NSW 2031. The sender is 'Cam' and the date is 5/12/23. Each form includes a warning: 'WARNING: This envelope is not suitable for sending jewellery or precious stones. Small rigid items such as keys or coins should be securely packed to avoid loss or damage.'

APPENDIX (D)

“5 Albert Street, Randwick ”

This section considers the existing condition of internal floors, walls, ceiling of all the units, garage of the building, as accessible and visible prior to the commencement of any proposed works 3-4 Llanfoys Street, Randwick, NSW.



Summary:

The above highlighted property at **5 Albert Street, Randwick**, which is associated with the subject site was inspected and photographic evidence compiled in order to depict the existing condition of the building prior to the commencement of any work at the subject site.

This section considers the existing condition of the walls, ceiling, flooring, of the internals of all units at **5 Albert Street, Randwick**. The building has 3 levels, and 4 units. Every unit has a living room, kitchen, bathroom, master bedroom, bedroom, and a balcony. The property also has 4 garages.

At the time of inspection, the internal walls, ceiling, and flooring of all the units were found to be in good condition with few minor cracks as noted in the table below, with photos attached in Appendix D-2.

The property has 4 garage spaces. At the time of inspection, these were found to be in reasonable condition with evidence of cracks propagating through the garage floor as noted in the table below, with photos attached in Appendix B.

Summary of photos attached in Appendix D-1 “& D-2

Appendix D-1 external and common areas of 5 Albert Street	
Figure Number	Description
1~312	General condition of common areas
21-24-26-151-240-241-246-247-253-254-263-268-274-275-278-294-295-296-270-	Damages evidence through external wall
28-29-30-31-32-33-41-42-43-44-57-58-59-127-128-239-	Crack propagation or damages evidence through footpath or carpark slab
38-39-47-48-49-64-65-66-67-68-103-104-113-114-115-116-217-	Crack propagation or damages evidence through carpark internal wall
Appendix D-2 Internal units of 5 Albert Street	
Figure Number	Description
1~270	General condition of internal walls, ceiling and floor surface of all units
1~46	General condition of unit 2
47~136	General condition of unit 4
65-111	Slight separation between cornice and ceiling
92-93-94-95-100-106-	Crack propagation through internal wall
121-122-123-124	Damages evidence through internal wall or ceiling paint
137~215	General condition of unit 3
150	Damages evidence through internal wall or ceiling paint
220-270	General condition of unit 1
270	Crack propagation through floor surface at the entry

"This table provides an overview of the cracks observed in the photos from the Appendix.

It is important to note that not all cracks are mentioned in this table. For a more comprehensive view and additional evidence, please refer to the photos in the Appendix.

APPENDIX (E)

“12 Milford Street, Randwick”

This section considers the existing condition of internal floors, walls, ceiling of all the units, garage of the building, as accessible and visible prior to the commencement of any proposed works **3-4 Llanfoys Street, Randwick, NSW.**



Summary:

The above highlighted property at **12 Milford Street, Randwick** which is associated with the subject site was inspected and photographic evidence compiled in order to depict the existing condition of the building prior to the commencement of any work at the subject site.

This section considers the existing condition of the walls, ceiling, flooring, of the internals of all units at **12 Milford Street, Randwick**. The building has 7 levels, and 30 units. Every unit has a living room, kitchen, bathroom, master bedroom, bedroom, and a balcony.

At the time of inspection, the internal walls, ceiling, flooring of all the units were found to be in good condition with few minor cracks as noted in the table below, with photos attached in Appendix E-2.

At the time of inspection, common areas were found to be in reasonable condition with cracks propagating through the garage floor as noted in the table below, with photos attached in Appendix E-1.

Summary of photos attached in Appendix E-1 “& E-2

Appendix E-1 external and common areas of 12 Milford Street	
Figure Number	Description
1~417	General condition of common areas
3-4-140-141-142-143- 150-151-161-162-205- 211-212-213-214-215- 216-217-221-222-227- 228-229-230-233-234- 235-236-239-240-241- 250-251-252-253-288- 289-290-291-301-302- 303-308-309-310-311- 312-313-317-318-327- 343-344-345-346-347- 348-349-351-	Crack propagation through driveway or carpark floor surface
40-41-42-74-75-76-77- 78-88-189-190-	Crack propagation through internal walls , ceiling or floors
44-45-46-112-113-114- 115-116-121-122-123- 124-125-172-225-244- 245-246-247-	Paint damages evidence
293-294-297-298-299- 300	Crack propagation through external wall

"This table provides an overview of the cracks observed in the photos from the Appendix.

It is important to note that not all cracks are mentioned in this table. For a more comprehensive view and additional evidence, please refer to the photos in the Appendix.

Appendix B-1 internal of units of 12 Milford Street	
Figure Number	Description
1~59	General condition of units 1D
43-	Paint damages evidence
60~106 & 218~225	General condition of units 1A
107~147	General condition of units 1C
133-134-135-	Crack propagation through internal wall
146-147	Separation between cornice and ceiling
148~217	General condition of units 1B
226~281	General condition of units 2A
259	Paint damages evidence
282~330	General condition of units 2B
326	Crack propagation through internal wall
331~380	General condition of units 3D
357-360	Paint damages evidence
3881~445	General condition of units 3A
446~499	General condition of units 3C
500~554	General condition of units 4B
555~578	General condition of units 4C
579~620	General condition of units 4A
621~650	General condition of units 5C
651~687	General condition of units 5D
688~750	General condition of units 5C
722-723-724-725-726-727-728-729-730	Crack propagation through internal wall
751~788	General condition of units 6C
789~839	General condition of units 6B
840~903	General condition of units 6A
904~946	General condition of units 6D
947~994	General condition of units 3B
995~1034	General condition of units 7A
1027-1028	Paint damages evidence
1035~1065	General condition of units 7C
1054-1055-1056	crack propagation through internal ceiling
1054	Paint damages evidence
1066~1107	General condition of units 7D
1106	Crack propagation through internal wall
1108~1162	General condition of units 7B
1156-1157-	Crack propagation through internal wall
1163~1192	General condition of units 6C
1189-1190	Crack propagation through internal wall
1193~1224	General condition of units 4D
1225~1267	General condition of units 5A
1268~1295	General condition of units 2C
	No access to unit 2D & 5B

DISCLAIMER

DISCLAIMER OF LIABILITY: - No liability shall be accepted on account of failure of the within Report to notify any problems in any area(s) or section(s) of the subject property physically Inaccessible for inspection or to which access for Inspection is denied by or to the Consultant (including but not limited to any area(s) or section(s) so specified by the within Report).

DISCLAIMER OF LIABILITY TO THIRD PARTIES: - This Report is made solely for the use and benefit of Client named on the front of this Report and no liability or responsibility whatsoever is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report whether in whole or in part does so at their own risk.

Please do not hesitate to contact us, should you have any further queries regarding this report.



Shahab Rad

Managing Director | Principal Engineer
B.E. (Civil) | M.E(STR) | M.I.E (AUST) | CPEng | NER 3262751 | RPEQ

Appendix A

General Condition of Llanfoyst St Council Assets



Figure 1 –



Figure 2 –



Figure 3 –




Figure 4 –




Figure 5 –



Figure 6 –



Figure 7 –



Figure 8 –



Figure 9 –




Figure 10 –




Figure 11 –



Figure 12 –



Figure 13 –



Figure 14 –




Figure 15 –



Figure 16 –



Figure 17 –



Figure 18 –



Figure 19 –



Figure 20 –



Figure 21 –




Figure 22 –




Figure 23 –



Figure 24 –



Figure 25 –



Figure 26 –



Figure 27 –



Figure 28 –



Figure 29 –



Figure 30 –



Figure 31 –



Figure 32 –



Figure 33 –



Figure 34 –



Figure 35 –



Figure 36 –



Figure 37 –



Figure 38 –



Figure 39 –



Figure 40 –



Figure 41 –



Figure 42 –



Figure 43 –



Figure 44 –



Figure 45 –




Figure 46 –



Figure 47 –



Figure 48 –



Figure 49 –



Figure 50 –



Figure 51 –



Figure 52 –



Figure 53 –




Figure 54 –



Figure 55 –



Figure 56 –



Figure 57 –



Figure 58 –



Figure 59 –



Figure 60 –



Figure 61 –



Figure 62 –



Figure 63 –



Figure 64 –



Figure 65 –



Figure 66 –



Figure 67 –



Figure 68 –



Figure 69 –



Figure 70 –



Figure 71 –




Figure 72 –



Figure 73 –



Figure 74 –



Figure 75 –



Figure 76 –



Figure 77 –



Figure 78 –




Figure 79 –



Figure 80 –



Figure 81 –



Figure 82 –



Figure 83 –



Figure 84 –



Figure 85 –



Figure 86 –



Figure 87 –



Figure 88 –



Figure 89 –



Figure 90 –



Figure 91 –



Figure 92 –



Figure 93 –



Figure 94 –




Figure 95 –



Figure 96 –



Figure 97 –



Figure 98 –



Figure 99 –



Figure 100 –



Figure 101 –



Figure 102 –



Figure 103 –

Appendix B-1

External and Common Areas

5 Llanfoyst St, Randwick



Figure 1 –



Figure 2 –



Figure 3 –



Figure 4 –



Figure 5 –



Figure 6 –




Figure 7 –



Figure 8 –



Figure 9 –



Figure 10 –



Figure 11 –



Figure 12 –



Figure 13 –



Figure 14 –



Figure 15 –



Figure 16 –




Figure 17 –



Figure 18 –



Figure 19 –



Figure 20 –




Figure 21 –



Figure 22 –



Figure 23 –




Figure 24 –



Figure 25 –




Figure 26 –




Figure 27 –



Figure 28 –




Figure 29 –




Figure 30 –



Figure 31 –



Figure 32 –



Figure 33 –




Figure 34 –




Figure 35 –



Figure 36 –



Figure 37 –



Figure 38 –



Figure 39 –




Figure 40 –



Figure 41 –



Figure 42 –



Figure 43 –




Figure 44 –




Figure 45 –




Figure 46 –




Figure 47 –



Figure 48 –



Figure 49 –



Figure 50 –




Figure 51 –



Figure 52 –



Figure 53 –



Figure 54 –




Figure 55 –



Figure 56 –



Figure 57 –




Figure 58 –



Figure 59 –




Figure 60 –



Figure 61 –



Figure 62 –



Figure 63 –



Figure 64 –



Figure 65 –




Figure 66 –



Figure 67 –



Figure 68 –




Figure 69 –



Figure 70 –




Figure 71 –



Figure 72 –



Figure 73 –




Figure 74 –



Figure 75 –



Figure 76 –



Figure 77 –



Figure 78 –



Figure 79 –



Figure 80 –



Figure 81 –



Figure 82 –




Figure 83 –



Figure 84 –



Figure 85 –



Figure 86 –




Figure 87 –



Figure 88 –



Figure 89 –



Figure 90 –



Figure 91 –

Appendix B-2
Internal of Units
5 Llanfoyst St, Randwick



Figure 1 –



Figure 2 –




Figure 3 –



Figure 4 –



Figure 5 –



Figure 6 –



Figure 7 –



Figure 8 –



Figure 9 –




Figure 10 –




Figure 11 –



Figure 12 –



Figure 13 –



Figure 14 –



Figure 15 –



Figure 16 –



Figure 17 –



Figure 18 –



Figure 19 –



Figure 20 –




Figure 21 –



Figure 22 –



Figure 23 –



Figure 24 –



Figure 25 –



Figure 26 –




Figure 27 –




Figure 28 –



Figure 29 –




Figure 30 –




Figure 31 –




Figure 32 –



Figure 33 –




Figure 34 –



Figure 35 –




Figure 36 –



Figure 37 –



Figure 38 –



Figure 39 –



Figure 40 –



Figure 41 –




Figure 42 –



Figure 43 –




Figure 44 –




Figure 45 –




Figure 46 –



Figure 47 –



Figure 48 –



Figure 49 –



Figure 50 –




Figure 51 –




Figure 52 –




Figure 53 –



Figure 54 –



Figure 55 –



Figure 56 –



Figure 57 –




Figure 58 –




Figure 59 –



Figure 60 –



Figure 61 –



Figure 62 –




Figure 63 –




Figure 64 –



Figure 65 –



Figure 66 –




Figure 67 –




Figure 68 –




Figure 69 –




Figure 70 –




Figure 71 –




Figure 72 –




Figure 73 –




Figure 74 –




Figure 75 –



Figure 76 –




Figure 77 –



Figure 78 –



Figure 79 –



Figure 80 –




Figure 81 –



Figure 82 –



Figure 83 –



Figure 84 –



Figure 85 –



Figure 86 –



Figure 87 –



Figure 88 –



Figure 89 –



Figure 90 –



Figure 91 –



Figure 92 –



Figure 93 –



Figure 94 –



Figure 95 –




Figure 96 –



Figure 97 –



Figure 98 –



Figure 99 –



Figure 100 –



Figure 101 –



Figure 102 –




Figure 103 –



Figure 104 –




Figure 105 –



Figure 106 –




Figure 107 –



Figure 108 –



Figure 109 –



Figure 110 –



Figure 111 –




Figure 112 –



Figure 113 –




Figure 114 –



Figure 115 –



Figure 116 –



Figure 117 –



Figure 118 –




Figure 119 –




Figure 120 –



Figure 121 –



Figure 122 –



Figure 123 –



Figure 124 –



Figure 125 –



Figure 126 –



Figure 127 –



Figure 128 –




Figure 129 –




Figure 130 –




Figure 131 –




Figure 132 –



Figure 133 –



Figure 134 –



Figure 135 –




Figure 136 –




Figure 137 –



Figure 138 –



Figure 139 –




Figure 140 –




Figure 141 –



Figure 142 –



Figure 143 –




Figure 144 –



Figure 145 –



Figure 146 –




Figure 147 –



Figure 148 –



Figure 149 –



Figure 150 –



Figure 151 –



Figure 152 –



Figure 153 –



Figure 154 –



Figure 155 –



Figure 156 –



Figure 157 –




Figure 158 –




Figure 159 –




Figure 160 –



Figure 161 –



Figure 162 –




Figure 163 –



Figure 164 –



Figure 165 –



Figure 166 –




Figure 167 –




Figure 168 –



Figure 169 –



Figure 170 –




Figure 171 –




Figure 172 –



Figure 173 –




Figure 174 –



Figure 175 –



Figure 176 –




Figure 177 –



Figure 178 –




Figure 179 –




Figure 180 –



Figure 181 –




Figure 182 –




Figure 183 –



Figure 184 –




Figure 185 –




Figure 186 –



Figure 187 –



Figure 188 –




Figure 189 –




Figure 190 –




Figure 191 –



Figure 192 –



Figure 193 –



Figure 194 –



Figure 195 –



Figure 196 –



Figure 197 –



Figure 198 –



Figure 199 –




Figure 200 –



Figure 201 –



Figure 202 –



Figure 203 –



Figure 204 –



Figure 205 –



Figure 206 –



Figure 207 –




Figure 208 –




Figure 209 –




Figure 210 –



Figure 211 –




Figure 212 –



Figure 213 –




Figure 214 –




Figure 215 –




Figure 216 –



Figure 217 –



Figure 218 –



Figure 219 –



Figure 220 –



Figure 221 –




Figure 222 –



Figure 223 –



Figure 224 –




Figure 225 –



Figure 226 –



Figure 227 –




Figure 228 –



Figure 229 –



Figure 230 –



Figure 231 –



Figure 232 –




Figure 233 –

Appendix C

External and Common Areas

3 Albert St, Randwick



Figure 1 –



Figure 2 –



Figure 3 –



Figure 4 –



Figure 5 –



Figure 6 –



Figure 7 –



Figure 8 –



Figure 9 –



Figure 10 –



Figure 11 –




Figure 12 –



Figure 13 –



Figure 14 –




Figure 15 –



Figure 16 –



Figure 17 –




Figure 18 –



Figure 19 –



Figure 20 –



Figure 21 –



Figure 22 –



Figure 23 –



Figure 24 –



Figure 25 –



Figure 26 –



Figure 27 –



Figure 28 –



Figure 29 –



Figure 30 –



Figure 31 –



Figure 32 –



Figure 33 –



Figure 34 –



Figure 35 –



Figure 36 –



Figure 37 –



Figure 38 –



Figure 39 –



Figure 40 –



Figure 41 –



Figure 42 –



Figure 43 –



Figure 44 –



Figure 45 –



Figure 46 –



Figure 47 –



Figure 48 –



Figure 49 –



Figure 50 –



Figure 51 –



Figure 52 –



Figure 53 –



Figure 54 –



Figure 55 –



Figure 56 –



Figure 57 –



Figure 58 –



Figure 59 –



Figure 60 –



Figure 61 –



Figure 62 –



Figure 63 –



Figure 64 –



Figure 65 –



Figure 66 –



Figure 67 –



Figure 68 –



Figure 69 –



Figure 70 –



Figure 71 –



Figure 72 –



Figure 73 –



Figure 74 –



Figure 75 –



Figure 76 –



Figure 77 –




Figure 78 –



Figure 79 –



Figure 80 –



Figure 81 –



Figure 82 –



Figure 83 –



Figure 84 –



Figure 85 –



Figure 86 –



Figure 87 –



Figure 88 –



Figure 89 –



Figure 90 –



Figure 91 –



Figure 92 –



Figure 93 –



Figure 94 –



Figure 95 –



Figure 96 –



Figure 97 –



Figure 98 –



Figure 99 –



Figure 100 –



Figure 101 –



Figure 102 –



Figure 103 –



Figure 104 –



Figure 105 –



Figure 106 –



Figure 107 –



Figure 108 –



Figure 109 –

Appendix D-1

5 Albert Street, Randwick

External



Figure 1 –



Figure 2 –



Figure 3 –



Figure 4 –



Figure 5 –



Figure 6 –



Figure 7 –



Figure 8 –



Figure 9 –



Figure 10 –



Figure 11 –



Figure 12 –



Figure 13 –



Figure 14 –



Figure 15 –



Figure 16 –



Figure 17 –



Figure 18 –



Figure 19 –



Figure 20 –



Figure 21 –



Figure 22 –



Figure 23 –



Figure 24 –



Figure 25 –



Figure 26 –



Figure 27 –



Figure 28 –



Figure 29 –



Figure 30 –



Figure 31 –



Figure 32 –



Figure 33 –



Figure 34 –



Figure 35 –



Figure 36 –



Figure 37 –



Figure 38 –



Figure 39 –



Figure 40 –



Figure 41 –



Figure 42 –



Figure 43 –



Figure 44 –



Figure 45 –



Figure 46 –



Figure 47 –



Figure 48 –



Figure 49 –



Figure 50 –



Figure 51 –



Figure 52 –



Figure 53 –



Figure 54 –



Figure 55 –



Figure 56 –



Figure 57 –



Figure 58 –



Figure 59 –



Figure 60 –



Figure 61 –



Figure 62 –



Figure 63 –



Figure 64 –



Figure 65 –



Figure 66 –



Figure 67 –



Figure 68 –



Figure 69 –



Figure 70 –



Figure 71 –



Figure 72 –



Figure 73 –



Figure 74 –



Figure 75 –



Figure 76 –




Figure 77 –



Figure 78 –



Figure 79 –



Figure 80 –




Figure 81 –



Figure 82 –



Figure 83 –



Figure 84 –



Figure 85 –



Figure 86 –



Figure 87 –



Figure 88 –



Figure 89 –



Figure 90 –



Figure 91 –



Figure 92 –



Figure 93 –



Figure 94 –



Figure 95 –



Figure 96 –



Figure 97 –



Figure 98 –




Figure 99 –



Figure 100 –



Figure 101 –



Figure 102 –



Figure 103 –



Figure 104 –



Figure 105 –



Figure 106 –



Figure 107 –



Figure 108 –



Figure 109 –



Figure 110 –



Figure 111 –



Figure 112 –



Figure 113 –



Figure 114 –



Figure 115 –



Figure 116 –



Figure 117 –



Figure 118 –



Figure 119 –



Figure 120 –



Figure 121 –



Figure 122 –



Figure 123 –



Figure 124 –



Figure 125 –




Figure 126 –



Figure 127 –



Figure 128 –



Figure 129 –



Figure 130 –



Figure 131 –




Figure 132 –



Figure 133 –



Figure 134 –




Figure 135 –



Figure 136 –



Figure 137 –



Figure 138 –



Figure 139 –



Figure 140 –



Figure 141 –




Figure 142 –



Figure 143 –



Figure 144 –



Figure 145 –



Figure 146 –



Figure 147 –



Figure 148 –



Figure 149 –



Figure 150 –



Figure 151 –



Figure 152 –



Figure 153 –



Figure 154 –



Figure 155 –



Figure 156 –



Figure 157 –



Figure 158 –



Figure 159 –



Figure 160 –



Figure 161 –



Figure 162 –



Figure 163 –



Figure 164 –




Figure 165 –



Figure 166 –



Figure 167 –




Figure 168 –



Figure 169 –



Figure 170 –




Figure 171 –



Figure 172 –



Figure 173 –



Figure 174 –




Figure 175 –




Figure 176 –



Figure 177 –



Figure 178 –




Figure 179 –



Figure 180 –



Figure 181 –



Figure 182 –




Figure 183 –




Figure 184 –



Figure 185 –



Figure 186 –



Figure 187 –



Figure 188 –




Figure 189 –




Figure 190 –




Figure 191 –



Figure 192 –



Figure 193 –



Figure 194 –



Figure 195 –



Figure 196 –




Figure 197 –



Figure 198 –



Figure 199 –



Figure 200 –



Figure 201 –



Figure 202 –



Figure 203 –




Figure 204 –



Figure 205 –



Figure 206 –



Figure 207 –



Figure 208 –



Figure 209 –



Figure 210 –



Figure 211 –



Figure 212 –



Figure 213 –




Figure 214 –



Figure 215 –



Figure 216 –



Figure 217 –



Figure 218 –



Figure 219 –




Figure 220 –



Figure 221 –



Figure 222 –



Figure 223 –



Figure 224 –



Figure 225 –



Figure 226 –




Figure 227 –



Figure 228 –



Figure 229 –



Figure 230 –



Figure 231 –



Figure 232 –



Figure 233 –



Figure 234 –



Figure 235 –



Figure 236 –



Figure 237 –



Figure 238 –




Figure 239 –



Figure 240 –



Figure 241 –



Figure 242 –



Figure 243 –



Figure 244 –



Figure 245 –



Figure 246 –



Figure 247 –



Figure 248 –



Figure 249 –



Figure 250 –




Figure 251 –



Figure 252 –



Figure 253 –



Figure 254 –



Figure 255 –



Figure 256 –



Figure 257 –



Figure 258 –



Figure 259 –



Figure 260 –



Figure 261 –



Figure 262 –



Figure 263 –



Figure 264 –



Figure 265 –




Figure 266 –



Figure 267 –



Figure 268 –



Figure 269 –



Figure 270 –



Figure 271 –



Figure 272 –



Figure 273 –



Figure 274 –




Figure 275 –



Figure 276 –



Figure 277 –



Figure 278 –



Figure 279 –



Figure 280 –



Figure 281 –



Figure 282 –




Figure 283 –




Figure 284 –



Figure 285 –




Figure 286 –




Figure 287 –



Figure 288 –




Figure 289 –



Figure 290 –



Figure 291 –



Figure 292 –




Figure 293 –



Figure 294 –



Figure 295 –



Figure 296 –



Figure 297 –




Figure 298 –



Figure 299 –



Figure 300 –



Figure 301 –



Figure 302 –



Figure 303 –



Figure 304 –



Figure 305 –



Figure 306 –



Figure 307 –



Figure 308 –



Figure 309 –



Figure 310 –



Figure 311 –



Figure 312 –

Appendix D-2

5 Albert Street, Randwick

Internal of units




Figure 1 –



Figure 2 –



Figure 3 –



Figure 4 –



Figure 5 –



Figure 6 –



Figure 7 –



Figure 8 –



Figure 9 –



Figure 10 –



Figure 11 –



Figure 12 –



Figure 13 –



Figure 14 –



Figure 15 –



Figure 16 –



Figure 17 –



Figure 18 –



Figure 19 –



Figure 20 –




Figure 21 –




Figure 22 –




Figure 23 –



Figure 24 –



Figure 25 –



Figure 26 –




Figure 27 –



Figure 28 –



Figure 29 –




Figure 30 –



Figure 31 –




Figure 32 –



Figure 33 –



Figure 34 –




Figure 35 –




Figure 36 –



Figure 37 –



Figure 38 –




Figure 39 –




Figure 40 –



Figure 41 –



Figure 42 –



Figure 43 –



Figure 44 –



Figure 45 –



Figure 46 –



Figure 47 –



Figure 48 –



Figure 49 –



Figure 50 –



Figure 51 –



Figure 52 –



Figure 53 –



Figure 54 –



Figure 55 –



Figure 56 –



Figure 57 –




Figure 58 –



Figure 59 –




Figure 60 –




Figure 61 –



Figure 62 –



Figure 63 –



Figure 64 –



Figure 65 –



Figure 66 –



Figure 67 –



Figure 68 –



Figure 69 –



Figure 70 –



Figure 71 –



Figure 72 –



Figure 73 –



Figure 74 –



Figure 75 –




Figure 76 –



Figure 77 –



Figure 78 –



Figure 79 –



Figure 80 –



Figure 81 –



Figure 82 –




Figure 83 –




Figure 84 –



Figure 85 –



Figure 86 –




Figure 87 –



Figure 88 –



Figure 89 –



Figure 90 –



Figure 91 –



Figure 92 –



Figure 93 –



Figure 94 –



Figure 95 –



Figure 96 –



Figure 97 –



Figure 98 –



Figure 99 –



Figure 100 –



Figure 101 –



Figure 102 –



Figure 103 –



Figure 104 –



Figure 105 –



Figure 106 –



Figure 107 –



Figure 108 –



Figure 109 –



Figure 110 –



Figure 111 –



Figure 112 –




Figure 113 –




Figure 114 –



Figure 115 –



Figure 116 –



Figure 117 –



Figure 118 –



Figure 119 –



Figure 120 –



Figure 121 –



Figure 122 –




Figure 123 –



Figure 124 –



Figure 125 –



Figure 126 –



Figure 127 –



Figure 128 –



Figure 129 –



Figure 130 –



Figure 131 –



Figure 132 –



Figure 133 –



Figure 134 –



Figure 135 –



Figure 136 –



Figure 137 –



Figure 138 –



Figure 139 –



Figure 140 –



Figure 141 –



Figure 142 –




Figure 143 –



Figure 144 –



Figure 145 –



Figure 146 –



Figure 147 –



Figure 148 –



Figure 149 –



Figure 150 –



Figure 151 –




Figure 152 –



Figure 153 –



Figure 154 –



Figure 155 –



Figure 156 –



Figure 157 –



Figure 158 –



Figure 159 –



Figure 160 –



Figure 161 –



Figure 162 –



Figure 163 –



Figure 164 –



Figure 165 –



Figure 166 –




Figure 167 –



Figure 168 –



Figure 169 –



Figure 170 –



Figure 171 –



Figure 172 –



Figure 173 –




Figure 174 –



Figure 175 –



Figure 176 –



Figure 177 –



Figure 178 –



Figure 179 –



Figure 180 –



Figure 181 –



Figure 182 –



Figure 183 –



Figure 184 –



Figure 185 –




Figure 186 –



Figure 187 –



Figure 188 –



Figure 189 –



Figure 190 –



Figure 191 –



Figure 192 –



Figure 193 –



Figure 194 –



Figure 195 –



Figure 196 –



Figure 197 –



Figure 198 –



Figure 199 –



Figure 200 –



Figure 201 –




Figure 202 –




Figure 203 –




Figure 204 –




Figure 205 –



Figure 206 –



Figure 207 –



Figure 208 –



Figure 209 –



Figure 210 –



Figure 211 –



Figure 212 –




Figure 213 –



Figure 214 –



Figure 215 –



Figure 216 –



Figure 217 –



Figure 218 –



Figure 219 –



Figure 220 –




Figure 221 –



Figure 222 –



Figure 223 –



Figure 224 –



Figure 225 –



Figure 226 –



Figure 227 –



Figure 228 –



Figure 229 –



Figure 230 –



Figure 231 –



Figure 232 –



Figure 233 –



Figure 234 –



Figure 235 –



Figure 236 –



Figure 237 –



Figure 238 –



Figure 239 –



Figure 240 –



Figure 241 –



Figure 242 –



Figure 243 –



Figure 244 –




Figure 245 –




Figure 246 –



Figure 247 –



Figure 248 –



Figure 249 –



Figure 250 –




Figure 251 –



Figure 252 –



Figure 253 –



Figure 254 –



Figure 255 –



Figure 256 –



Figure 257 –



Figure 258 –



Figure 259 –



Figure 260 –



Figure 261 –



Figure 262 –



Figure 263 –



Figure 264 –



Figure 265 –



Figure 266 –



Figure 267 –



Figure 268 –



Figure 269 –



Figure 270 –

Appendix E-1

External and Common Areas

12 Milford St, Randwick



Figure 1 –



Figure 2 –



Figure 3 –



Figure 4 –



Figure 5 –



Figure 6 –



Figure 7 –



Figure 8 –



Figure 9 –



Figure 10 –




Figure 11 –



Figure 12 –



Figure 13 –



Figure 14 –



Figure 15 –



Figure 16 –



Figure 17 –



Figure 18 –



Figure 19 –



Figure 20 –



Figure 21 –



Figure 22 –



Figure 23 –



Figure 24 –



Figure 25 –



Figure 26 –



Figure 27 –



Figure 28 –



Figure 29 –



Figure 30 –



Figure 31 –




Figure 32 –



Figure 33 –



Figure 34 –




Figure 35 –




Figure 36 –



Figure 37 –



Figure 38 –



Figure 39 –



Figure 40 –



Figure 41 –



Figure 42 –



Figure 43 –



Figure 44 –



Figure 45 –



Figure 46 –




Figure 47 –




Figure 48 –



Figure 49 –



Figure 50 –




Figure 51 –




Figure 52 –



Figure 53 –



Figure 54 –



Figure 55 –



Figure 56 –



Figure 57 –



Figure 58 –




Figure 59 –



Figure 60 –



Figure 61 –



Figure 62 –



Figure 63 –



Figure 64 –




Figure 65 –



Figure 66 –



Figure 67 –



Figure 68 –



Figure 69 –



Figure 70 –



Figure 71 –



Figure 72 –



Figure 73 –




Figure 74 –



Figure 75 –



Figure 76 –




Figure 77 –



Figure 78 –



Figure 79 –



Figure 80 –



Figure 81 –



Figure 82 –



Figure 83 –




Figure 84 –




Figure 85 –



Figure 86 –




Figure 87 –



Figure 88 –



Figure 89 –



Figure 90 –



Figure 91 –



Figure 92 –



Figure 93 –




Figure 94 –




Figure 95 –



Figure 96 –



Figure 97 –



Figure 98 –



Figure 99 –



Figure 100 –



Figure 101 –



Figure 102 –



Figure 103 –



Figure 104 –



Figure 105 –



Figure 106 –




Figure 107 –



Figure 108 –



Figure 109 –



Figure 110 –



Figure 111 –



Figure 112 –



Figure 113 –



Figure 114 –



Figure 115 –



Figure 116 –



Figure 117 –



Figure 118 –



Figure 119 –



Figure 120 –



Figure 121 –



Figure 122 –



Figure 123 –



Figure 124 –



Figure 125 –



Figure 126 –



Figure 127 –




Figure 128 –




Figure 129 –



Figure 130 –




Figure 131 –



Figure 132 –



Figure 133 –




Figure 134 –



Figure 135 –



Figure 136 –




Figure 137 –




Figure 138 –




Figure 139 –



Figure 140 –



Figure 141 –



Figure 142 –



Figure 143 –



Figure 144 –




Figure 145 –



Figure 146 –



Figure 147 –



Figure 148 –




Figure 149 –



Figure 150 –



Figure 151 –



Figure 152 –



Figure 153 –



Figure 154 –



Figure 155 –



Figure 156 –



Figure 157 –



Figure 158 –




Figure 159 –




Figure 160 –



Figure 161 –



Figure 162 –



Figure 163 –



Figure 164 –



Figure 165 –




Figure 166 –



Figure 167 –




Figure 168 –



Figure 169 –



Figure 170 –



Figure 171 –



Figure 172 –



Figure 173 –



Figure 174 –



Figure 175 –



Figure 176 –



Figure 177 –




Figure 178 –



Figure 179 –




Figure 180 –



Figure 181 –



Figure 182 –



Figure 183 –



Figure 184 –



Figure 185 –



Figure 186 –



Figure 187 –



Figure 188 –



Figure 189 –



Figure 190 –



Figure 191 –



Figure 192 –



Figure 193 –



Figure 194 –




Figure 195 –




Figure 196 –




Figure 197 –



Figure 198 –




Figure 199 –



Figure 200 –



Figure 201 –



Figure 202 –



Figure 203 –



Figure 204 –



Figure 205 –




Figure 206 –



Figure 207 –



Figure 208 –




Figure 209 –



Figure 210 –



Figure 211 –



Figure 212 –



Figure 213 –



Figure 214 –



Figure 215 –



Figure 216 –



Figure 217 –



Figure 218 –




Figure 219 –



Figure 220 –



Figure 221 –



Figure 222 –




Figure 223 –



Figure 224 –



Figure 225 –




Figure 226 –



Figure 227 –



Figure 228 –



Figure 229 –



Figure 230 –



Figure 231 –



Figure 232 –



Figure 233 –



Figure 234 –



Figure 235 –



Figure 236 –




Figure 237 –



Figure 238 –



Figure 239 –



Figure 240 –



Figure 241 –



Figure 242 –



Figure 243 –



Figure 244 –



Figure 245 –



Figure 246 –



Figure 247 –




Figure 248 –



Figure 249 –



Figure 250 –



Figure 251 –



Figure 252 –



Figure 253 –




Figure 254 –



Figure 255 –



Figure 256 –




Figure 257 –




Figure 258 –



Figure 259 –



Figure 260 –



Figure 261 –



Figure 262 –




Figure 263 –




Figure 264 –



Figure 265 –



Figure 266 –



Figure 267 –



Figure 268 –




Figure 269 –




Figure 270 –



Figure 271 –



Figure 272 –



Figure 273 –



Figure 274 –



Figure 275 –



Figure 276 –



Figure 277 –



Figure 278 –



Figure 279 –



Figure 280 –



Figure 281 –



Figure 282 –



Figure 283 –



Figure 284 –



Figure 285 –



Figure 286 –



Figure 287 –



Figure 288 –



Figure 289 –



Figure 290 –



Figure 291 –



Figure 292 –



Figure 293 –



Figure 294 –



Figure 295 –



Figure 296 –



Figure 297 –



Figure 298 –



Figure 299 –



Figure 300 –



Figure 301 –



Figure 302 –



Figure 303 –



Figure 304 –



Figure 305 –



Figure 306 –



Figure 307 –



Figure 308 –



Figure 309 –



Figure 310 –



Figure 311 –



Figure 312 –



Figure 313 –




Figure 314 –




Figure 315 –



Figure 316 –



Figure 317 –



Figure 318 –



Figure 319 –



Figure 320 –



Figure 321 –



Figure 322 –



Figure 323 –



Figure 324 –



Figure 325 –



Figure 326 –



Figure 327 –



Figure 328 –



Figure 329 –



Figure 330 –



Figure 331 –



Figure 332 –



Figure 333 –



Figure 334 –



Figure 335 –



Figure 336 –



Figure 337 –



Figure 338 –



Figure 339 –



Figure 340 –



Figure 341 –



Figure 342 –



Figure 343 –



Figure 344 –



Figure 345 –



Figure 346 –



Figure 347 –



Figure 348 –



Figure 349 –



Figure 350 –



Figure 351 –



Figure 352 –



Figure 353 –



Figure 354 –



Figure 355 –



Figure 356 –



Figure 357 –



Figure 358 –



Figure 359 –



Figure 360 –



Figure 361 –



Figure 362 –



Figure 363 –



Figure 364 –



Figure 365 –



Figure 366 –



Figure 367 –



Figure 368 –



Figure 369 –



Figure 370 –



Figure 371 –



Figure 372 –



Figure 373 –



Figure 374 –



Figure 375 –



Figure 376 –



Figure 377 –



Figure 378 –



Figure 379 –



Figure 380 –



Figure 381 –



Figure 382 –



Figure 383 –



Figure 384 –



Figure 385 –



Figure 386 –



Figure 387 –



Figure 388 –



Figure 389 –



Figure 390 –



Figure 391 –



Figure 392 –



Figure 393 –



Figure 394 –



Figure 395 –



Figure 396 –



Figure 397 –



Figure 398 –



Figure 399 –



Figure 400 –



Figure 401 –



Figure 402 –



Figure 403 –



Figure 404 –



Figure 405 –



Figure 406 –



Figure 407 –



Figure 408 –



Figure 409 –



Figure 410 –



Figure 411 –



Figure 412 –



Figure 413 –



Figure 414 –



Figure 415 –



Figure 416 –



Figure 417 –

Appendix E-2

External and Common Areas

12 Milford St, Randwick



Figure 1 –



Figure 2 –



Figure 3 –



Figure 4 –




Figure 5 –



Figure 6 –




Figure 7 –



Figure 8 –



Figure 9 –



Figure 10 –




Figure 11 –



Figure 12 –



Figure 13 –



Figure 14 –



Figure 15 –



Figure 16 –




Figure 17 –




Figure 18 –



Figure 19 –



Figure 20 –



Figure 21 –



Figure 22 –



Figure 23 –



Figure 24 –



Figure 25 –



Figure 26 –



Figure 27 –



Figure 28 –



Figure 29 –



Figure 30 –



Figure 31 –



Figure 32 –



Figure 33 –



Figure 34 –



Figure 35 –



Figure 36 –



Figure 37 –




Figure 38 –




Figure 39 –



Figure 40 –




Figure 41 –



Figure 42 –



Figure 43 –



Figure 44 –



Figure 45 –




Figure 46 –




Figure 47 –



Figure 48 –



Figure 49 –



Figure 50 –



Figure 51 –




Figure 52 –



Figure 53 –



Figure 54 –




Figure 55 –



Figure 56 –



Figure 57 –



Figure 58 –



Figure 59 –



Figure 60 –



Figure 61 –



Figure 62 –



Figure 63 –



Figure 64 –



Figure 65 –



Figure 66 –



Figure 67 –



Figure 68 –



Figure 69 –



Figure 70 –



Figure 71 –



Figure 72 –



Figure 73 –



Figure 74 –



Figure 75 –



Figure 76 –



Figure 77 –



Figure 78 –



Figure 79 –



Figure 80 –



Figure 81 –



Figure 82 –



Figure 83 –




Figure 84 –



Figure 85 –



Figure 86 –



Figure 87 –




Figure 88 –



Figure 89 –



Figure 90 –



Figure 91 –



Figure 92 –



Figure 93 –




Figure 94 –



Figure 95 –



Figure 96 –



Figure 97 –




Figure 98 –




Figure 99 –




Figure 100 –




Figure 101 –




Figure 102 –



Figure 103 –



Figure 104 –




Figure 105 –



Figure 106 –



Figure 107 –



Figure 108 –



Figure 109 –



Figure 110 –



Figure 111 –



Figure 112 –




Figure 113 –



Figure 114 –



Figure 115 –



Figure 116 –




Figure 117 –




Figure 118 –




Figure 119 –



Figure 120 –



Figure 121 –



Figure 122 –



Figure 123 –



Figure 124 –



Figure 125 –



Figure 126 –



Figure 127 –



Figure 128 –



Figure 129 –



Figure 130 –




Figure 131 –



Figure 132 –



Figure 133 –



Figure 134 –



Figure 135 –



Figure 136 –



Figure 137 –



Figure 138 –




Figure 139 –




Figure 140 –



Figure 141 –



Figure 142 –



Figure 143 –




Figure 144 –




Figure 145 –



Figure 146 –



Figure 147 –




Figure 148 –



Figure 149 –



Figure 150 –



Figure 151 –



Figure 152 –



Figure 153 –



Figure 154 –



Figure 155 –




Figure 156 –



Figure 157 –



Figure 158 –



Figure 159 –



Figure 160 –



Figure 161 –



Figure 162 –




Figure 163 –



Figure 164 –




Figure 165 –




Figure 166 –




Figure 167 –



Figure 168 –



Figure 169 –



Figure 170 –



Figure 171 –




Figure 172 –



Figure 173 –



Figure 174 –



Figure 175 –



Figure 176 –



Figure 177 –



Figure 178 –



Figure 179 –



Figure 180 –



Figure 181 –



Figure 182 –



Figure 183 –



Figure 184 –



Figure 185 –



Figure 186 –



Figure 187 –



Figure 188 –



Figure 189 –



Figure 190 –



Figure 191 –



Figure 192 –



Figure 193 –



Figure 194 –




Figure 195 –



Figure 196 –



Figure 197 –



Figure 198 –



Figure 199 –



Figure 200 –



Figure 201 –



Figure 202 –



Figure 203 –



Figure 204 –



Figure 205 –




Figure 206 –




Figure 207 –




Figure 208 –




Figure 209 –



Figure 210 –



Figure 211 –



Figure 212 –



Figure 213 –



Figure 214 –



Figure 215 –



Figure 216 –



Figure 217 –




Figure 218 –




Figure 219 –




Figure 220 –



Figure 221 –



Figure 222 –



Figure 223 –



Figure 224 –



Figure 225 –



Figure 226 –



Figure 227 –



Figure 228 –




Figure 229 –



Figure 230 –



Figure 231 –




Figure 232 –




Figure 233 –



Figure 234 –



Figure 235 –



Figure 236 –



Figure 237 –



Figure 238 –



Figure 239 –



Figure 240 –



Figure 241 –



Figure 242 –



Figure 243 –



Figure 244 –



Figure 245 –



Figure 246 –



Figure 247 –




Figure 248 –



Figure 249 –



Figure 250 –



Figure 251 –



Figure 252 –



Figure 253 –




Figure 254 –



Figure 255 –




Figure 256 –



Figure 257 –



Figure 258 –



Figure 259 –



Figure 260 –



Figure 261 –



Figure 262 –




Figure 263 –



Figure 264 –



Figure 265 –



Figure 266 –



Figure 267 –



Figure 268 –




Figure 269 –



Figure 270 –



Figure 271 –



Figure 272 –



Figure 273 –




Figure 274 –



Figure 275 –



Figure 276 –



Figure 277 –



Figure 278 –



Figure 279 –




Figure 280 –




Figure 281 –



Figure 282 –




Figure 283 –



Figure 284 –




Figure 285 –




Figure 286 –



Figure 287 –



Figure 288 –



Figure 289 –



Figure 290 –



Figure 291 –



Figure 292 –




Figure 293 –



Figure 294 –



Figure 295 –



Figure 296 –



Figure 297 –




Figure 298 –




Figure 299 –



Figure 300 –



Figure 301 –



Figure 302 –



Figure 303 –



Figure 304 –




Figure 305 –



Figure 306 –



Figure 307 –




Figure 308 –



Figure 309 –



Figure 310 –



Figure 311 –



Figure 312 –



Figure 313 –




Figure 314 –



Figure 315 –



Figure 316 –



Figure 317 –



Figure 318 –



Figure 319 –



Figure 320 –




Figure 321 –



Figure 322 –




Figure 323 –



Figure 324 –



Figure 325 –



Figure 326 –



Figure 327 –



Figure 328 –




Figure 329 –



Figure 330 –



Figure 331 –




Figure 332 –



Figure 333 –



Figure 334 –



Figure 335 –



Figure 336 –



Figure 337 –



Figure 338 –



Figure 339 –



Figure 340 –



Figure 341 –



Figure 342 –



Figure 343 –



Figure 344 –



Figure 345 –



Figure 346 –



Figure 347 –



Figure 348 –



Figure 349 –




Figure 350 –



Figure 351 –



Figure 352 –




Figure 353 –



Figure 354 –



Figure 355 –



Figure 356 –



Figure 357 –



Figure 358 –



Figure 359 –



Figure 360 –



Figure 361 –



Figure 362 –




Figure 363 –




Figure 364 –



Figure 365 –



Figure 366 –



Figure 367 –



Figure 368 –



Figure 369 –




Figure 370 –




Figure 371 –



Figure 372 –



Figure 373 –




Figure 374 –



Figure 375 –



Figure 376 –



Figure 377 –



Figure 378 –




Figure 379 –



Figure 380 –



Figure 381 –



Figure 382 –



Figure 383 –



Figure 384 –



Figure 385 –



Figure 386 –



Figure 387 –



Figure 388 –




Figure 389 –




Figure 390 –



Figure 391 –



Figure 392 –



Figure 393 –



Figure 394 –



Figure 395 –



Figure 396 –



Figure 397 –



Figure 398 –



Figure 399 –



Figure 400 –



Figure 401 –



Figure 402 –



Figure 403 –



Figure 404 –




Figure 405 –



Figure 406 –



Figure 407 –



Figure 408 –



Figure 409 –



Figure 410 –



Figure 411 –



Figure 412 –



Figure 413 –




Figure 414 –



Figure 415 –



Figure 416 –



Figure 417 –



Figure 418 –



Figure 419 –



Figure 420 –



Figure 421 –



Figure 422 –



Figure 423 –




Figure 424 –



Figure 425 –



Figure 426 –



Figure 427 –



Figure 428 –



Figure 429 –



Figure 430 –



Figure 431 –



Figure 432 –



Figure 433 –



Figure 434 –




Figure 435 –



Figure 436 –



Figure 437 –




Figure 438 –



Figure 439 –




Figure 440 –



Figure 441 –



Figure 442 –



Figure 443 –



Figure 444 –



Figure 445 –



Figure 446 –



Figure 447 –




Figure 448 –



Figure 449 –



Figure 450 –



Figure 451 –




Figure 452 –




Figure 453 –




Figure 454 –



Figure 455 –



Figure 456 –



Figure 457 –



Figure 458 –




Figure 459 –



Figure 460 –



Figure 461 –



Figure 462 –



Figure 463 –



Figure 464 –



Figure 465 –



Figure 466 –



Figure 467 –



Figure 468 –



Figure 469 –



Figure 470 –



Figure 471 –



Figure 472 –



Figure 473 –



Figure 474 –




Figure 475 –



Figure 476 –



Figure 477 –



Figure 478 –



Figure 479 –



Figure 480 –



Figure 481 –



Figure 482 –



Figure 483 –



Figure 484 –



Figure 485 –



Figure 486 –



Figure 487 –




Figure 488 –



Figure 489 –



Figure 490 –



Figure 491 –



Figure 492 –



Figure 493 –



Figure 494 –




Figure 495 –




Figure 496 –



Figure 497 –




Figure 498 –



Figure 499 –



Figure 500 –



Figure 501 –



Figure 502 –



Figure 503 –



Figure 504 –



Figure 505 –



Figure 506 –



Figure 507 –



Figure 508 –



Figure 509 –




Figure 510 –




Figure 511 –




Figure 512 –



Figure 513 –



Figure 514 –



Figure 515 –



Figure 516 –



Figure 517 –



Figure 518 –



Figure 519 –



Figure 520 –



Figure 521 –



Figure 522 –



Figure 523 –




Figure 524 –



Figure 525 –



Figure 526 –



Figure 527 –



Figure 528 –



Figure 529 –



Figure 530 –



Figure 531 –



Figure 532 –



Figure 533 –



Figure 534 –



Figure 535 –



Figure 536 –



Figure 537 –



Figure 538 –



Figure 539 –



Figure 540 –



Figure 541 –




Figure 542 –




Figure 543 –



Figure 544 –



Figure 545 –




Figure 546 –



Figure 547 –




Figure 548 –



Figure 549 –



Figure 550 –



Figure 551 –



Figure 552 –



Figure 553 –



Figure 554 –



Figure 555 –



Figure 556 –



Figure 557 –



Figure 558 –




Figure 559 –



Figure 560 –



Figure 561 –



Figure 562 –



Figure 563 –



Figure 564 –



Figure 565 –




Figure 566 –



Figure 567 –



Figure 568 –



Figure 569 –



Figure 570 –



Figure 571 –



Figure 572 –



Figure 573 –



Figure 574 –



Figure 575 –




Figure 576 –



Figure 577 –



Figure 578 –



Figure 579 –



Figure 580 –



Figure 581 –



Figure 582 –



Figure 583 –




Figure 584 –



Figure 585 –



Figure 586 –



Figure 587 –



Figure 588 –




Figure 589 –




Figure 590 –



Figure 591 –



Figure 592 –



Figure 593 –



Figure 594 –




Figure 595 –



Figure 596 –



Figure 597 –




Figure 598 –



Figure 599 –



Figure 600 –




Figure 601 –



Figure 602 –



Figure 603 –



Figure 604 –



Figure 605 –




Figure 606 –



Figure 607 –



Figure 608 –



Figure 609 –



Figure 610 –



Figure 611 –



Figure 612 –



Figure 613 –




Figure 614 –



Figure 615 –




Figure 616 –




Figure 617 –




Figure 618 –



Figure 619 –



Figure 620 –



Figure 621 –




Figure 622 –



Figure 623 –



Figure 624 –



Figure 625 –



Figure 626 –



Figure 627 –




Figure 628 –



Figure 629 –



Figure 630 –



Figure 631 –



Figure 632 –




Figure 633 –



Figure 634 –




Figure 635 –



Figure 636 –




Figure 637 –



Figure 638 –




Figure 639 –




Figure 640 –



Figure 641 –



Figure 642 –



Figure 643 –



Figure 644 –




Figure 645 –




Figure 646 –



Figure 647 –




Figure 648 –



Figure 649 –



Figure 650 –



Figure 651 –



Figure 652 –



Figure 653 –



Figure 654 –



Figure 655 –



Figure 656 –



Figure 657 –



Figure 658 –



Figure 659 –



Figure 660 –



Figure 661 –



Figure 662 –



Figure 663 –



Figure 664 –



Figure 665 –



Figure 666 –



Figure 667 –



Figure 668 –



Figure 669 –



Figure 670 –




Figure 671 –



Figure 672 –



Figure 673 –



Figure 674 –




Figure 675 –



Figure 676 –



Figure 677 –



Figure 678 –




Figure 679 –



Figure 680 –



Figure 681 –



Figure 682 –



Figure 683 –



Figure 684 –



Figure 685 –



Figure 686 –



Figure 687 –



Figure 688 –




Figure 689 –




Figure 690 –



Figure 691 –



Figure 692 –



Figure 693 –



Figure 694 –



Figure 695 –



Figure 696 –



Figure 697 –



Figure 698 –



Figure 699 –




Figure 700 –



Figure 701 –



Figure 702 –



Figure 703 –



Figure 704 –




Figure 705 –



Figure 706 –




Figure 707 –




Figure 708 –



Figure 709 –



Figure 710 –



Figure 711 –



Figure 712 –



Figure 713 –



Figure 714 –



Figure 715 –



Figure 716 –



Figure 717 –



Figure 718 –



Figure 719 –




Figure 720 –



Figure 721 –



Figure 722 –



Figure 723 –



Figure 724 –



Figure 725 –



Figure 726 –



Figure 727 –




Figure 728 –



Figure 729 –




Figure 730 –



Figure 731 –



Figure 732 –



Figure 733 –



Figure 734 –




Figure 735 –



Figure 736 –



Figure 737 –



Figure 738 –



Figure 739 –



Figure 740 –



Figure 741 –



Figure 742 –



Figure 743 –



Figure 744 –



Figure 745 –



Figure 746 –




Figure 747 –



Figure 748 –



Figure 749 –



Figure 750 –



Figure 751 –



Figure 752 –




Figure 753 –



Figure 754 –



Figure 755 –



Figure 756 –



Figure 757 –



Figure 758 –



Figure 759 –



Figure 760 –



Figure 761 –



Figure 762 –




Figure 763 –




Figure 764 –



Figure 765 –



Figure 766 –



Figure 767 –



Figure 768 –



Figure 769 –



Figure 770 –



Figure 771 –



Figure 772 –



Figure 773 –



Figure 774 –



Figure 775 –



Figure 776 –




Figure 777 –




Figure 778 –




Figure 779 –



Figure 780 –



Figure 781 –



Figure 782 –



Figure 783 –



Figure 784 –



Figure 785 –



Figure 786 –




Figure 787 –



Figure 788 –



Figure 789 –




Figure 790 –



Figure 791 –



Figure 792 –



Figure 793 –



Figure 794 –




Figure 795 –




Figure 796 –



Figure 797 –



Figure 798 –



Figure 799 –




Figure 800 –




Figure 801 –



Figure 802 –



Figure 803 –



Figure 804 –



Figure 805 –




Figure 806 –




Figure 807 –




Figure 808 –



Figure 809 –



Figure 810 –




Figure 811 –




Figure 812 –




Figure 813 –



Figure 814 –



Figure 815 –



Figure 816 –



Figure 817 –



Figure 818 –



Figure 819 –



Figure 820 –



Figure 821 –



Figure 822 –




Figure 823 –



Figure 824 –



Figure 825 –



Figure 826 –



Figure 827 –




Figure 828 –




Figure 829 –



Figure 830 –



Figure 831 –



Figure 832 –



Figure 833 –



Figure 834 –



Figure 835 –



Figure 836 –



Figure 837 –



Figure 838 –



Figure 839 –



Figure 840 –



Figure 841 –



Figure 842 –



Figure 843 –



Figure 844 –



Figure 845 –



Figure 846 –



Figure 847 –



Figure 848 –




Figure 849 –




Figure 850 –



Figure 851 –



Figure 852 –




Figure 853 –




Figure 854 –



Figure 855 –



Figure 856 –



Figure 857 –



Figure 858 –



Figure 859 –



Figure 860 –



Figure 861 –



Figure 862 –



Figure 863 –



Figure 864 –



Figure 865 –



Figure 866 –



Figure 867 –



Figure 868 –



Figure 869 –



Figure 870 –



Figure 871 –



Figure 872 –



Figure 873 –




Figure 874 –




Figure 875 –



Figure 876 –




Figure 877 –



Figure 878 –



Figure 879 –



Figure 880 –



Figure 881 –



Figure 882 –



Figure 883 –



Figure 884 –



Figure 885 –



Figure 886 –



Figure 887 –



Figure 888 –



Figure 889 –




Figure 890 –




Figure 891 –



Figure 892 –



Figure 893 –



Figure 894 –



Figure 895 –



Figure 896 –



Figure 897 –



Figure 898 –



Figure 899 –



Figure 900 –



Figure 901 –



Figure 902 –



Figure 903 –



Figure 904 –



Figure 905 –



Figure 906 –



Figure 907 –




Figure 908 –



Figure 909 –




Figure 910 –



Figure 911 –



Figure 912 –



Figure 913 –



Figure 914 –



Figure 915 –



Figure 916 –



Figure 917 –



Figure 918 –



Figure 919 –



Figure 920 –



Figure 921 –



Figure 922 –



Figure 923 –



Figure 924 –



Figure 925 –



Figure 926 –



Figure 927 –




Figure 928 –



Figure 929 –




Figure 930 –




Figure 931 –



Figure 932 –




Figure 933 –



Figure 934 –




Figure 935 –



Figure 936 –



Figure 937 –



Figure 938 –



Figure 939 –



Figure 940 –



Figure 941 –




Figure 942 –



Figure 943 –




Figure 944 –



Figure 945 –



Figure 946 –



Figure 947 –



Figure 948 –




Figure 949 –




Figure 950 –




Figure 951 –




Figure 952 –



Figure 953 –



Figure 954 –




Figure 955 –




Figure 956 –




Figure 957 –



Figure 958 –



Figure 959 –



Figure 960 –



Figure 961 –



Figure 962 –




Figure 963 –




Figure 964 –



Figure 965 –



Figure 966 –



Figure 967 –




Figure 968 –



Figure 969 –



Figure 970 –



Figure 971 –



Figure 972 –



Figure 973 –




Figure 974 –



Figure 975 –



Figure 976 –



Figure 977 –



Figure 978 –



Figure 979 –



Figure 980 –



Figure 981 –




Figure 982 –




Figure 983 –



Figure 984 –



Figure 985 –



Figure 986 –



Figure 987 –



Figure 988 –



Figure 989 –



Figure 990 –



Figure 991 –




Figure 992 –




Figure 993 –




Figure 994 –



Figure 995 –



Figure 996 –




Figure 997 –



Figure 998 –



Figure 999 –



Figure 1000 –



Figure 1001 –



Figure 1002 –



Figure 1003 –



Figure 1004 –




Figure 1005 –




Figure 1006 –



Figure 1007 –



Figure 1008 –



Figure 1009 –



Figure 1010 –



Figure 1011 –



Figure 1012 –



Figure 1013 –




Figure 1014 –



Figure 1015 –



Figure 1016 –




Figure 1017 –



Figure 1018 –



Figure 1019 –



Figure 1020 –



Figure 1021 –



Figure 1022 –



Figure 1023 –




Figure 1024 –



Figure 1025 –



Figure 1026 –



Figure 1027 –



Figure 1028 –



Figure 1029 –



Figure 1030 –



Figure 1031 –



Figure 1032 –



Figure 1033 –



Figure 1034 –



Figure 1035 –




Figure 1036 –



Figure 1037 –



Figure 1038 –



Figure 1039 –



Figure 1040 –



Figure 1041 –



Figure 1042 –



Figure 1043 –




Figure 1044 –



Figure 1045 –



Figure 1046 –



Figure 1047 –




Figure 1048 –




Figure 1049 –




Figure 1050 –



Figure 1051 –



Figure 1052 –



Figure 1053 –



Figure 1054 –



Figure 1055 –



Figure 1056 –



Figure 1057 –



Figure 1058 –




Figure 1059 –




Figure 1060 –



Figure 1061 –



Figure 1062 –



Figure 1063 –



Figure 1064 –



Figure 1065 –



Figure 1066 –



Figure 1067 –



Figure 1068 –



Figure 1069 –



Figure 1070 –



Figure 1071 –



Figure 1072 –



Figure 1073 –



Figure 1074 –



Figure 1075 –



Figure 1076 –



Figure 1077 –




Figure 1078 –



Figure 1079 –



Figure 1080 –



Figure 1081 –



Figure 1082 –



Figure 1083 –



Figure 1084 –



Figure 1085 –



Figure 1086 –



Figure 1087 –



Figure 1088 –




Figure 1089 –



Figure 1090 –



Figure 1091 –



Figure 1092 –



Figure 1093 –



Figure 1094 –




Figure 1095 –



Figure 1096 –



Figure 1097 –



Figure 1098 –



Figure 1099 –




Figure 1100 –




Figure 1101 –




Figure 1102 –



Figure 1103 –



Figure 1104 –



Figure 1105 –



Figure 1106 –




Figure 1107 –



Figure 1108 –



Figure 1109 –



Figure 1110 –




Figure 1111 –




Figure 1112 –



Figure 1113 –



Figure 1114 –



Figure 1115 –



Figure 1116 –




Figure 1117 –



Figure 1118 –



Figure 1119 –



Figure 1120 –



Figure 1121 –




Figure 1122 –



Figure 1123 –



Figure 1124 –



Figure 1125 –



Figure 1126 –



Figure 1127 –



Figure 1128 –




Figure 1129 –



Figure 1130 –



Figure 1131 –



Figure 1132 –



Figure 1133 –



Figure 1134 –



Figure 1135 –



Figure 1136 –



Figure 1137 –




Figure 1138 –



Figure 1139 –



Figure 1140 –



Figure 1141 –




Figure 1142 –




Figure 1143 –



Figure 1144 –



Figure 1145 –




Figure 1146 –




Figure 1147 –




Figure 1148 –




Figure 1149 –



Figure 1150 –



Figure 1151 –




Figure 1152 –



Figure 1153 –



Figure 1154 –




Figure 1155 –




Figure 1156 –



Figure 1157 –



Figure 1158 –



Figure 1159 –



Figure 1160 –



Figure 1161 –



Figure 1162 –



Figure 1163 –



Figure 1164 –



Figure 1165 –




Figure 1166 –



Figure 1167 –



Figure 1168 –




Figure 1169 –




Figure 1170 –



Figure 1171 –




Figure 1172 –




Figure 1173 –




Figure 1174 –




Figure 1175 –



Figure 1176 –




Figure 1177 –



Figure 1178 –



Figure 1179 –



Figure 1180 –



Figure 1181 –




Figure 1182 –



Figure 1183 –



Figure 1184 –



Figure 1185 –



Figure 1186 –



Figure 1187 –



Figure 1188 –




Figure 1189 –




Figure 1190 –




Figure 1191 –




Figure 1192 –



Figure 1193 –




Figure 1194 –



Figure 1195 –




Figure 1196 –



Figure 1197 –




Figure 1198 –




Figure 1199 –



Figure 1200 –




Figure 1201 –



Figure 1202 –



Figure 1203 –



Figure 1204 –



Figure 1205 –



Figure 1206 –



Figure 1207 –



Figure 1208 –



Figure 1209 –



Figure 1210 –



Figure 1211 –



Figure 1212 –



Figure 1213 –




Figure 1214 –




Figure 1215 –



Figure 1216 –



Figure 1217 –



Figure 1218 –



Figure 1219 –



Figure 1220 –




Figure 1221 –



Figure 1222 –



Figure 1223 –



Figure 1224 –



Figure 1225 –



Figure 1226 –




Figure 1227 –



Figure 1228 –



Figure 1229 –



Figure 1230 –



Figure 1231 –



Figure 1232 –



Figure 1233 –



Figure 1234 –



Figure 1235 –



Figure 1236 –



Figure 1237 –



Figure 1238 –



Figure 1239 –



Figure 1240 –



Figure 1241 –




Figure 1242 –



Figure 1243 –



Figure 1244 –



Figure 1245 –



Figure 1246 –



Figure 1247 –



Figure 1248 –



Figure 1249 –



Figure 1250 –




Figure 1251 –



Figure 1252 –



Figure 1253 –



Figure 1254 –



Figure 1255 –



Figure 1256 –



Figure 1257 –



Figure 1258 –



Figure 1259 –



Figure 1260 –




Figure 1261 –



Figure 1262 –



Figure 1263 –



Figure 1264 –



Figure 1265 –




Figure 1266 –




Figure 1267 –



Figure 1268 –



Figure 1269 –




Figure 1270 –



Figure 1271 –



Figure 1272 –



Figure 1273 –



Figure 1274 –



Figure 1275 –



Figure 1276 –



Figure 1277 –



Figure 1278 –



Figure 1279 –



Figure 1280 –



Figure 1281 –



Figure 1282 –



Figure 1283 –



Figure 1284 –



Figure 1285 –



Figure 1286 –




Figure 1287 –



Figure 1288 –



Figure 1289 –



Figure 1290 –



Figure 1291 –



Figure 1292 –




Figure 1293 –



Figure 1294 –



Figure 1295 –