

# Service protection report

Joseph plumbing

supplier no: 873

Property Address: 22 Collins Crescent, Yagoona, NSW 2199

Client: (A&K Engineering Group P/L)

PNum: 14317787

Collins Cres

The Storm water pipe crosses the left side fence  
at a distance to the back fence = 32.25 m  
Depth to invert = 0.75 m

The sewer line crosses the right  
side fence at a distance to the back  
fence = 30.1  
Depth to invert = 0.8 m

Pipe size: 150 mm

Pipe type: S.G.W.

Strata: Clay

Asset Location method: Electronic Pipe Locator/ Potholing/ Surveying/ Accessing structures

Asset indicators: Peg in ground, paint on fence

I, Housien Nasrallah of Joseph plumbing, being accredited to carry out a Service Protection Report, certify that the information shown on the Report is accurate and has been prepared in accordance with the relevant instructions.

Prepared by: Joseph plumbing

signature:

V. NASRALLAH

Date: 27/06/2022

Housien.nasrallah@gmail.com

Mobile: 0410055075

Abn: 35134685108