Service Protection Report

Property Address: 73 Fenwick Street, Bankstown, NSW 2200

Client: DD Studio Pty Ltd

Notes:

- 1. Contractor to confirm line, level and size of all the existing services (as per note in plan) within the vicinity of any new works and report any conflict to site superintendent prior to any construction commencing
- 2. Joseph Plumbing Pty Ltd is accredited as service protection reporter by Sydney Water
- 3. The location of the assets specified on this report have been taken from existing fence lines and/or surveyors marking or pegs. fence lines may not be true boundary lines and may need to be confirmed by surveyor.
- 4. This plan is not to scale, do not scale from this plan. refer dimensions shown



