

Trail Description and Photo Reference Points – Schuss Advanced Mountain Bike Trail BD1

BD1 – Trail Description and Photo References





BD 1 Photo Point ID / Description	Photo
BD1_P3: The trail follows the contours across the Gondola lift corridor.	
BD1_P4: The trail continues into the native vegetation.	<image/>
BD1_P5: The traverses the native vegetation through the trees into a berm.	



BD 1 Photo Point ID / Description	Photo
BD1_P6: The trail continues downhill. Natural rock feature pictured which creates a more interesting ride.	
BD1_P7: The trail continues through the vegetation.	
BD1_P8: The trail continues downhill with a series of tighter turns.	



BD 1 Photo Point ID / Description	Photo
BD1_P9: The trail continues through gaps in the trees.	
BD1_P10: The trail departs the undisturbed vegetation and heads back into the Gondola lift corridor.	
BD1_P11: The continues downhill within the Gondola corridor.	



BD 1 Photo Point ID / Description	Photo
BD1_P12: The trail heads into a berm.	<image/>
BD1_P13: The trail heads back into the vegetation through the gaps in the trees.	
BD1_P14: The trail heads into a berm within a relatively open area amongst the trees.	



BD 1 Photo Point ID / Description	Photo
BD1_P15: The trail departs the vegetation back onto the Gondola lift corridor.	
BD1_P16: The trail departs the Gondola corridor back into the vegetation.	
BD1_P17: The trail continues downslope following the contours.	



BD 1 Photo Point ID / Description	Photo
BD1_P18: The trail continues through the vegetation.	
BD1_P19: The trail continues toward the mountain access road through an open section between the trees.	
BD2_P20: The trail enters into a berm before crossing the mountain access road and Sidewinder trail.	















20 40 60 80 Ν Meters Map Projection: Universal Transverse Mercator Horizontal Datum: GDA 1994 Grid: GDA 1994 MGA Zone 55

2010 0



PHOTO POINTS

Project: Proposed Schuss BD1 MTB Trail Revision: 3 Date: 29/07/2024

Produced By: BB