

CLARENDON HOMES

Condition of Footpath / Kerb & Gutter Prior to Commencement of Building Works

To: Council/Engineers Department


From: Clarendon Homes

Any Kerb & Gutter: ☒ Yes ☐ No

Damage: ☒ Yes ☐ No

Any Footpath: ☐ Yes ☒ No

Damage: ☐ Yes ☒ No



Inspection Date:	20/11/25
Signature of Surveyor	
B/A No.	
Lot No.	123
Street:	Raine Road
Suburb:	Padstow
Client:	29918279
Job No:	

Note: Each damaged section must be indicated by a cross (X)