

1 September 2025


Duri Service Station
68 Duri St
South Tamworth NSW 2340

Attn: Anil

RE: 6 Monthly Groundwater Inspection Results – August 2025

Dear Anil,

Please find enclosed the results for your 6 monthly Groundwater Monitoring Visual Inspection, conducted at the **Duri Fuels Service Station**, on 29 August 2025.

The 6 monthly groundwater test has been conducted in accordance with Clause 20(1)(a) of the Underground Petroleum Storage System (UPSS) Regulations (2019). The testing included the following procedures:


- Visual assessment to check for a sheen on top of a water sample collected from each monitoring well; and
- Interface probe (IP) monitoring device test.

The testing found monitoring wells MW1 and MW3 contained clean water, with no evidence of petroleum hydrocarbon impact. Monitoring well MW2 was unable to be opened due to the bolts having been concreted over during recent line replacement works. The bolts need to be cleared using a power drill which was not possible at the time of inspection. Please ensure the bolts are cleared prior to the next inspection.

All gauging and visual inspection data has been attached to this letter, including an aerial photo indicating the location of the wells within the site. The next scheduled groundwater testing is due for completion at your site in **February 2026**.

If you have any questions regarding these works or would like to discuss any other matters, please do not hesitate to contact me using the details given below.

Yours sincerely,



AURORA ENVIRONMENTAL CONSULTING PTY LTD

GROUNDWATER MONITORING TEST RECORD SHEET - 6 MTH VISUAL INSPECTION - AUG 2025



PO Box 165 NEWCASTLE NSW 2300

SITE NAME: Duri Fuels South Tamworth

SAMPLED BY: [REDACTED]

ADDRESS: 68 Duri Road, South Tamworth, NSW

DATE & TIME OF TESTING: 29/08/2025

LOT & DP No: _____

WORKCOVER DANGEROUS GOODS NOTIFICATION NO. AND EXPIRY DATE _____

Monitor Well ID:	Gauging Details				Subjective Physical Description							
	Depth to Bottom (mTOC)	Depth to Water (mTOC)	Depth to PSH: (mTOC)	PSH Thickness (m)	Colour	Odour	Sheen	Volume Bailed from Well (l)	Type of Well	Type of Test	Name of Sampler/Company/ABN	Signature
MW-1	4.5	2.552	-	-	Clear	Nil	Nil	1L	50mm	IFP + Bailer	[REDACTED] / Aurora / ABN #63160133344	[REDACTED]
MW-2	4.5	Unable to be Accessed			-	-	-	-	50mm	IFP + Bailer	[REDACTED] / Aurora / ABN #63160133344	[REDACTED]
MW-3	4.5	1.865	-	-	Clear	Nil	Nil	1L	50mm	IFP + Bailer	[REDACTED] / Aurora / ABN #63160133344	[REDACTED]

NOTE: This form must be kept for at least seven years from the date of the last test recorded.



DURI FUELS
68 Duri St
South Tamworth

UST1

UST2

MW1

Pump

MW2

Pump

UST3

MW3

Pump

Pump