



Photograph 5 – Oil drums looking east.



Photograph 6 – AST looking north



Photograph 7 – Paddocks in the northeastern portion of Lot 201, facing north



Photograph 8 – UST adjacent to hut, facing north



Photograph 9 – Paddock with chicken coup to the left, facing north



Photograph 10 – The rear of the house (Residence 1) in the northeast of Lot 201, facing north.



Photograph 11 – ACM eaves of north eastern house.



Photograph 12 – Storage area in front of the house, facing east.



Photograph 13 – Septic tank west of the northeastern house



Photograph 14 – 2 ASTs south of the house



Photograph 15 – Stable shed in the northeastern portion of Lot 201



Photograph 16 – ACM drainage pipe at the rear of the Stable shed in the northeastern portion of Lot 201



Photograph 17 – Wooden structure in northeastern portion of lot 201, facing northwest.




Photograph 18 – Tyres and steel stockpiled west of the house (Residence 2) in the southeastern portion Lot 201, facing south



Photograph 19 – ACM sheeting stockpiled west of the house in the southeastern portion Lot 201



Photograph 20 – Suspected ACM pipe and steel stockpiles west of the house in the southeastern portion Lot 201, looking east.



Photograph 21 – The second residential area, facing west.



Photograph 22 – Swimming pool and backyard area with a brick building in the background, looking south.



Photograph 23 – House on the northern side of the residential complex, looking north.



Photograph 24 – House on the eastern side of the complex, looking west.



Photograph 25 – Suspected ACM eaves of the brick building on western corner of the complex, looking north.



Photograph 26 – Shed behind the residential complex, looking north west.



Photograph 27 – AST in front of the shed, looking north.



Photograph 28 – Material stored within the shed.



Photograph 29 – Timber feed lots in the paddock north west of the residential complex, looking east.




Photograph 30 – Oil drum within the feed lot in the paddock north west of the residential complex.



Photograph 31 – Large dam in the Western portion of Lot 201, looking north.



Photograph 32 – Northern dam wall of the large dam in the Western portion of Lot 201, looking east.



Photograph 33 – Pumping station on the northern end of the large dam in the western portion of Lot 201.



Photograph 34 – Bare soil north east of the large dam in the Western portion of Lot 201.



Photograph 35 – Remains of the former horse track that occupied the western portion of Lot 201, looking north.



Photograph 36 – Large dam in the northeastern corner of part Lot 202, looking north.



Photograph 37 – Access road that dissects the site, looking east.



Photograph 38 – Access road that dissects the site, looking west.



Photograph 39 – Fill material in the main access road of the site.



Photograph 40 – Fill material in the main access road of the site.



Photograph 41 – Cattle yard in the western of part Lot 202, looking northwest.



Photograph 42 – Residence 3, looking northwest.



Photograph 43 – Rear of residence 3, looking southeast.



Photograph 44 – Stockpiled timber, looking southeast.



Photograph 45 – Scattered soil south of Residence 3, looking north.



Photograph 46 – Stockpiled material south of Residence 3 looking west.



Photograph 47 – Shed southwest of residence 3 looking south.




Photograph 48 – Ground surface of the shed southwest of residence 3.



Photograph 49 – Oil drum inside the shed southwest of residence 3.



Photograph 50 – ACM inside the shed southwest of residence 3.



Photograph 51 – Hay storage in central portion of part Lot 202, north of access road, looking west.



Photograph 52 – Clay/shale stockpiles in central portion of part Lot 202, north of access road, looking west.



Photograph 53 – Bare area in the western portion of part Lot 202, looking west.




Photograph 54 – Two small stockpiles soil in in the central portion of part Lot 202, looking south.

Appendix B – Groundwater Bore Records

Map from the NSW Natural Resource Atlas

Map created with NSW Natural Resource Atlas - <http://www.nratlas.nsw.gov.au>

Wednesday, August 14, 2013



Legend

Symbol	Layer	Custodian
	Cities and large towns renderImage: Cannot build image from features	
	Populated places renderImage: Cannot build image from features	
	Towns	
	Groundwater Bores	
	Catchment Management Authority boundaries	
	Major rivers	
	Topographic base map	



Copyright © 2013 New South Wales Government. Map has been compiled from various sources and may contain errors or omissions. No representation is made as to its accuracy or suitability.