

NON-FRIABLE ASBESTOS CLEARANCE CERTIFICATE – NO AIR MONITORING

SECTION 1. CLEARANCE INSPECTION DETAILS

SECTION 1.1 CLIENT DETAILS

Name of client

DAVID PROTASIEWICZ.

Client contact details

0428 215 710

SECTION 1.2 REMOVAL WORK DETAILS

Date removal work carried out (DD/MM/YYYY)

14-5-2020

SITE ADDRESS WHERE REMOVAL WORK WAS
CARRIED OUT

Unit number/Street number/Property number
(include Lot or DP number if applicable)

3

Street name

BIRCH ROAD

Suburb

LAKE ALBERT WAGGA WAGGA.

State

NSW

Postcode

2650

Details of the specific asbestos removal work area(s)

THE Removal of CONTAMINATED
SOIL AS PER REPORT NO 5706
D. M. MCMAHON PTY LTD.

Name of licensed asbestos removalist and
licence number

DAVID PROTASIEWICZ
206110

Name and contact details of licensed asbestos
removalist supervisor (if different to removalist)

SECTION 1.3 INSPECTION DETAILS

Date of clearance inspection (DD/MM/YYYY)

14-5-2020

Time of clearance inspection (HH:MM)

1.30

SECTION 2. ASBESTOS REMOVAL WORK AREA

SECTION 2.1 VISUAL INSPECTION

Inspection of the specific area detailed in section 1 found no visible asbestos
remaining as a result of the asbestos removal work carried out.

☐ Yes ☒ No

Can the area be reoccupied?

☒ Yes ☐ No

Has additional information been attached? (for example photos, drawings, plans)

☐ Yes ☒ No

SECTION 3. CLEARANCE DECLARATION

I declare that:

- the asbestos removal work area and the surrounding area are free from any visible asbestos
- the transit route and waste routes are free from any asbestos
- all asbestos in the scope of the removal work has been removed.

Name

P+C House Pty Ltd.

ABN

41 201 851 172

Contact number

0418 589 842

Signature

P+C House

Qualifications and experience

NON FRIABLE ASBESTOS
Removal WORK
A.D. 210404.

Date (DD/MM/YYYY)

22.May.20.