

ELECTRICAL FRICTION CONE PENETROMETER TEST RESULTS

Client: HELM PTY LTD
Project: PROPOSED RESIDENTIAL DEVELOPMENT
Location: 177 RUSSELL AVENUE, DOLLS POINT, NSW

Job No.: 29353S


R.L. Surface: ~1.3 m

Data File: J:\29000's\29353S

Date: 6/5/16

Datum: AHD

Operator: T.C.



Interpreted by: T.C.
Checked by: P.S.

ELECTRICAL FRICTION CONE PENETROMETER TEST RESULTS

Client: HELM PTY LTD
Project: PROPOSED RESIDENTIAL DEVELOPMENT
Location: 177 RUSSELL AVENUE, DOLLS POINT, NSW

Job No.: 29353S


R.L. Surface: ~1.3 m

Data File: J:\29000's\29353S

Date: 6/5/16

Datum: AHD

Operator: T.C.



Interpreted by: T.C.
Checked by: P.S.

ELECTRICAL FRICTION CONE PENETROMETER TEST RESULTS

Client: HELM PTY LTD
Project: PROPOSED RESIDENTIAL DEVELOPMENT
Location: 177 RUSSELL AVENUE, DOLLS POINT, NSW

Job No.: 29353S


R.L. Surface: ~1.6 m

Data File: J:\29000's\29353S

Date: 6/5/16

Datum: AHD

Operator: T.C.



Interpreted by: T.C.
Checked by: P.S.

ELECTRICAL FRICTION CONE PENETROMETER TEST RESULTS

Client: HELM PTY LTD
Project: PROPOSED RESIDENTIAL DEVELOPMENT
Location: 177 RUSSELL AVENUE, DOLLS POINT, NSW

Job No.: 29353S


R.L. Surface: ~1.6 m

Data File: J:\29000's\29353S

Date: 6/5/16

Datum: AHD

Operator: T.C.



ELECTRICAL FRICTION CONE PENETROMETER TEST RESULTS

Client: HELM PTY LTD
Project: PROPOSED RESIDENTIAL DEVELOPMENT
Location: 177 RUSSELL AVENUE, DOLLS POINT, NSW

Job No.: 29353S


R.L. Surface: ~1.6 m

Data File: J:\29000's\29353S

Date: 6/5/16

Datum: AHD

Operator: T.C.



Interpreted by: T.C.
Checked by: P.S.



AERIAL IMAGE SOURCE: GOOGLE EARTH PRO 7.1.5.1557
AERIAL IMAGE ©: 2015 GOOGLE INC.

Title:

SITE LOCATION PLAN

Project:

177 RUSSEL AVENUE,
DOLLS POINT, NSW

Report No:

29353S

Figure No:

1

This plan should be read in conjunction with the JK Geotechnics report.


JK Geotechnics






PLANT DATE: 24/05/2018 12:33:32 PM DWG FILE: JK GEOTECHNICAL\JK GEOTECHNICAL\2008\20080524\24052401.DWG

CROSS SECTION AA




- | | | |
|-------------|------------|-----------|
| CLAYEY SAND | SILTY CLAY | SANDSTONE |
| CORE LOSS | SILTY SAND | |
| SAND | FILL | |

CROSS SECTION BB



- | | |
|-------------|------------|
| CLAYEY SAND | SILTY CLAY |
| CORE LOSS | FILL |
| SAND | SANDSTONE |



CROSS SECTION AA & BB

Project: 177 RUSSEL AVENUE,
DOLLS POINT, NSW

Report No: 29353S

Figure No: 3

JK Geotechnics

