Attachment 1 - Preliminary Site Investigation report

Preliminary Site Investigation

Site Name and Address

6-12 Dumaresq Street, Campbelltown, NSW, 2560 Lot 1-11 SP 63212

Report Number

PSI-2560

Date

14.11.18



PROJECT DETAILS

Business Name:

NEO Consulting Pty Ltd

Project Number: PSI-2560

Project Title:

Preliminary Site Investigation 6-12 Dumaresq Street, Campbelltown, NSW, 2560

Report Completed for

XTS Group Pty Ltd Terry Bassal

Report Completed by

NEO Consulting Pty Ltd ABN: 26 615 633 988 PO Box 279 Riverstone

NSW 2765

e: admin@neoconsulting.com.au

Written By

Shahid Javed Environmental Engineer

Reviewed By

Nick Caltabiano Project Manager

Review Date: 14th November 2018

File Name: PSI-2560 Report Status: FINAL

Document Details

Project Number	PSI-2560	Document Number	1
Document Title	Preliminary Site Investigation		
Site Address	6-12 Dumaresq Street, Campbelltown, NSW, 2560		
Report Prepared for	XTS Group Pty Ltd		
File Name		PSI-2560	

Document status and review

Revision	Prepared by	Reviewed by	Date issue
Draft	Shahid Javed	Nick Caltabiano	07.11.18
Draft	Shahid Javed	Nick Caltabiano	14.11.18



1.0 INTRODUCTION & SITE IDENTIFICATION

This report presents the results of a combined Preliminary Site Investigation (PSI) undertaken by NEO Consulting Pty Ltd (NEO) at the Site. This report was commissioned by Terry Bassal from XTS Group Pty Ltd to address potential onsite contamination identified and has been undertaken in accordance with clause 7 of the State Environmental Planning Policy No 55 – Remediation of Land. The Site comprises of many individual lots (at the time of reporting).

The locality of the Site is presented in Figure 1 and a detailed layout of the Site and its features is included in Figure 2 within Appendix A. The individual registered lot is graphically shown below (image source: www.maps.six.nsw.gov.au) boundaries shown are approximate:

The footprint area of investigation is approximately 1,277m². The Site is described as being generally rectangular in shape and has a street frontage to Dumaresq Street (western boundary). Taken from a central location within the property, the Site has the following geographical coordinates (as measured on the NSW Department of Lands): 34°04′01.0″ S, 150°48′45.1″ E.



1.1 Objectives

The objective of this investigation was to assess for the likelihood of contamination to exist on the Site based on a preliminary investigation.

1.2 Scope of Works

To achieve the objectives, NEO undertook the following scope of works;

- review of available geology, hydrogeology and topographical maps;
- review of historical aerial photographs;
- land title ownership record searches;
- NSW OEH contaminated land register search
- NSW Department of Primary industries, Office of Water registered groundwater bore search (500m radius of the Site);
- Site inspection and walkover to observe current Site conditions and surrounding land uses;
- Review proposed; plans and future land use.
- Interpretation of data and reporting;
- Undertake entire report in accordance with clause 7 of the State Environmental Planning Policy
 No 55 Remediation of Land



2.0 REGIONAL GROUND SETTING

2.1 Regional Geology

The 1:100,000 Wollongong Port Hacking Geological Series Sheet 9029-9129 (Geological Survey of New South Wales, Edition 1, 1985) indicates that the Site locality is underlain by Middle Triassic Ashfield Shale. Channel and flood plain alluvium; gravel, sand, silt, clay; may be locally calcreted.

2.2 Regional Topography and Drainage

A review of nearby surface water bodies and the surrounding topography indicates that surface water run-off will likely flow north; parallel to Dumaresq Street. Intermediate and local flow systems in Cainozoic volcanics or Mesozoic sediments.

2.3 Regional Hydrogeology

A search for registered groundwater monitoring bores within a 500m radius of the Site was undertaken using the NSW Office of Water Groundwater Bore map data on the 7th November 2018. No registered or discontinued groundwater monitoring bores were identified during the search within a 500m radius of the site. NEO did identify 4 registered bores within 650m North East of the site a review of the Drillers notes found that silty clay was reached after fill from a depth between 0.6-3.50m and Shale between 3.5-9m.

2.4 Acid Sulfate Soils

The NSW eSpade Acid Sulfate Soil Risk Map indicates that the Site is located in an area of no known occurrence of acid sulfate soil (ASS) materials and that land management activities are not likely to be affected by ASS materials.

2.5 NSW EPA Sensitive Map search

A review of the site address with the NSW EPA Sensitive maps. The site is not located within a sensitive zone.

3.0 SITE HISTORY

3.1 Land Titles

A search of historical land title ownership records search was carried out for the site with original subdivision paperwork found in Appendix B.

3.2 NSW Office of Environment and Heritage Contaminated Land Record

NEO conducted a search NSW Office of Environment (OEH) contaminated land record information on the 7th November 2018. The search did not identify any contaminated land records for the Site or properties located adjacent to the Site.

4.0 SITE WALKOVER

A Site walkover was conducted on the 5th of November 2018 by an Environmental Engineer of NEO Consulting. At the time of the walkover, the weather was cloudy but warm. A two-storey complex with Gymnasium and Squash Centre on top floor and small business shops either side of entrance/arcade walkway at street level. Adjoining property to the south is Australia Post. The Arcade is situated in a commercial area of Campbelltown amongst the busy shopping area and railway transport to the north across Hurley Street. Observations made during the walkovers are presented in Sections 4.1 to 4.12.



4.1 Site Comments & Anecdotal Information

Observations made at the time of the walkovers are presented below:

The entire site is comprised of a building structure;

4.2 Site Activities

At the time of the inspection the building was occupied by various Commercial and Retail businesses.

4.3 Chemical Spills and Losses

No evidence of significant chemical spills, losses or staining was observed across the Site. No anecdotal information or historical information regarding historical spills at the Site was revealed.

4.4 Underground and Aboveground Storage Tanks

No above ground or underground storage tanks were observed at the property, historic or active. During the inspection, NEO did not observe any structures suggesting their former installation at the site. Further the presence for storage is unlikely based on historical information and interpreted land uses.

4.5 Phytotoxicity

There was no evidence of phytotoxic impact (e.g. stress or dieback) as there is no vegetation on Site.

4.6 Complaint & Incident History

NEO is not aware of any complaints or environmental incidents at the Site.

4.7 Surrounding Land Use

During the Site walkover, it was observed that the general land use surrounding the Site is retail/commercial.

Boundary	Land Use	
East	Car Park	
South	Commercial business	
West	Dumaresq St	
North	Commercial business	

5.0 DATA RELIABILITY

During the preliminary investigation conducted at the Site, NEO sought information from the following sources:

- Land History Search;
- Department of Land and Property Information (LPI);
- DNR / DPI Acid Sulfate Maps;
 - Campbelltown Council;
- NSW OEH;
- Clause 7 of the SEPP 55.
- NSW Office of Water, 'All Groundwater Map'; and
- Observations made in the field during the Site walkover.

NEO considers that the data is generally representative of past and present Site conditions and observations made personally by us.



6.0 SITE ASSESSMENT CRITERIA

To assist with further assessment and post-remediation validation works, Site criteria have been adopted. These criteria were adopted based on the following published guidance documents:

- NEPM 'National Environmental Protection (Assessment of Site Contamination) Measure 1999 (April 2013), EPHC 2013, Canberra, incorporating CRC Care 2012.
- Clause 7 of the SEPP 55.
- NSW DEC 2005, Contaminated Sites: Guidelines for Assessing Former Orchards and Market Gardens', ISBN 1741370191, Department of Environment and Conservations NSW.
- NSW DEC 2006, 'Contaminated Sites: Guidelines for the NSW Site Auditor Scheme (2nd edition)' ISBN 1741378591, Department of Environment and Conservation NSW.
- NSW OEH 2011, 'Contaminated Sites: Guidelines for Consultants Reporting on Contaminated Sites', ISBN 0 7310 3892 4, NSW Office of Environment and Heritage.
- Western Australian Department of Health 2009, 'Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia, dated May 2009. A discussion on the adoption of criteria is presented in the following sections.

7.0 CONCLUSIONS

NEO concludes that; based on the desktop investigation, Site inspections, observations collected during Site works which were undertaken in accordance with clause 7 of the State Environmental Planning Policy No 55 – Remediation of Land. The Site can be considered suitable for proposed development:

- A HAZMAT survey should be completed prior to any potential demolition of structures at the Site.
 An appropriately licensed HAZMAT and demolition contractor should be engaged for all HAZMAT and demolition works at the Site;
- A waste classification should be prepared for any soil materials being disposed off-site in accordance with NSW EPA 2014 Waste Classification Guidelines Part 1;
- During any potential re-development, care should be taken to segregate the waste streams. Each
 waste stream should be assessed for its suitability for re-use individually and subsequent validation
 samples, screening records, results or qualitative information reported for inclusion in the site
 validation report;

Further, in the event that any further contaminating materials or other un-expected finds (ie. burial pits) are identified during redevelopment, an appropriately experienced consultant should be engaged to attend site. The works should cease immediately in the area of the discovery.


This report should be read in conjunction with its limitations presented in this report.



8.0 REFERENCES

- NEPC 2013, 'National Environment Protection (Assessment of Site Contamination) Amendment Measure 2013 No. 1' Federal Register of Legislative Instruments F2013L00768.
- NSW DEC 2005, Contaminated Sites: Guidelines for Assessing Former Orchards and Market Gardens', ISBN 1 74137 019 1, Department of Environment and Conservations NSW.
- NSW DEC 2006, 'Contaminated Sites: Guidelines for the NSW Site Auditor Scheme (2nd edition)'
 ISBN 1 74137 859 1, Department of Environment and Conservation NSW.
- NSW EPA 1994, 'Contaminated Sites: Guidelines for Assessing Service Station Sites', ISBN 07310 3712 X, NSW Environment Protection Authority.
- NSW OEH 2011, 'Contaminated Sites: Guidelines for Consultants Reporting on Contaminated Sites', ISBN 0 7310 3892 4, NSW Office of Environment and Heritage.





Project Number: PSI-2560

Figure 1:

Google map view – location of site showing surrounding area.



Figure 2: Satellite view of site and surrounding area.





CONVERSION TABLE ADDED IN REGISTRAR GENERAL'S DEPARTMENT DP: 543368 METRES FEET INCHES 0.019 0.254 0.279 0.457 0.454 0.914 0.914 0.940 1.118 1.276 5.042 3.658 6.058 6 1/4 9 1/2 9 11 5/4 9 11 3/4 12 -16 8 5/8 33 -63 -65 10 1/4 66 -75 -86 11 1/2 86 6 95 10 1/4 122 4 1/2 123 6 132 6 1/4 135 8 1/2 217 3 240 10 287 9 1/2 19.202 20.117 22.860 26.200 26.355 29,216 29,216 37,300 37,643 40,392 41,364 66,218 73,406 87,719 3 10 9 1/2 SQ M AC RD P - - 36 1/4 916.9 - 1 10 1/2 1277

I, Jack Hayward Watson, Registrar General for New South Wales, certify that this negative is a photograph made as a permanent record of a document in my custody this 28th day of July, 1976.

Sandatson

PLAN FORM 2

Signatures and seals only.

This negative is a photograph made as a permanent

15th JANUARY, 1990

record of a document in the custody of the

Registrar General this day.

10 20 30 40 50 60 70Table of mm 110 120 130 140

Plan Drawing only to appear in this space -

*OFFICE USE ONLY

DP 785774

Req:R998968 Ref:58909 /S

COUNCIL'S CERTIFICATE SURVEYOR'S CERTIFICATE PLAN OF SUBDIVISION OF LOT 2 DP543368 AND The Council of the *City *Municipality *Shire of CAMPBELLTOWN having satisfied itself that the requirements of the Strate Titles Act, 1973 lother than the requirements for the registration of plans) have been complied with, approves of the proposed SP63212 EASMENT FOR OVERHANG 2 WIDE OVER LOT 101 DP 621693 Mun./Shire City LGA : CAMPBELLTOWN Locality : CAMPBELLTOWN Dermanery St and lot 101, DP 62 1693 which forms a boundary of a proposed fat, shown in the accepanying floor plan, exists; CITY C.A. : SEE CERTIFICATE any wall, floor, calling or structural cubic space, by reference to Date 22 OCTOBER 1997 Parish : ST PETER County: (UMBERIAND Purpose: STRATA PLAN 67 of 199 U 8222 . 11 Ref. Map: Reduction Ratio 1: 300 other than a public place, in respect of which eaves Lengths are in metres Last Plan: DP 543368 THE OWNERS - STRATA PLAN Nº 63212 Name of, and *address for service of notices on, the "Nº 6-12" DUMARESQ ST body corporate * Address required on CAMPBELLTOWN NSW 2560 original strata plan only. sheets. Signatures, seals and statements of intention to create easements or restrictions as to user. AWN - DENOTES AWNING EASEMENT FOR O UNDERGROUND PURSUANT TO SECTION 88B OF THE CONVEYANCING ACT, 1919. MAINS 2 WIDE AS AMENDED & SECTION 7(3) STRATA TITLES (FREEHOLD (ST 57 572) DEVELOPMENT) ACT, 1973, IT IS INTENDED TO CREATE: 101 1. EASEMENT FOR OVERHANG 2 WIDE B EASEMENT FOR D P 621693 OVERHANG 2 WIDE. (AWN (0.18) /AWN) 1.57 Signed in my presence for and on behalf of especial frustee Company ommon Seal of the Council of the City of Campbelltown was hereto AMILE (A.C.N. COC.CO) COT.) by its / Horneys Morron Inge w (0.03) Krotester Emilio Gonzalez affixed by virtue of a resolution Aug-2000 ш the first country interior to me and each of whom declares that ne/she α passed by Council on the 20th and appropried by the Board of Citoplans of that company as an STOREY BRICK BUILDING et. 17 of the monthly for the curresps of the Force of Attorney (12/2010/1997 10 glotter on the BRA 182 NO 367...) and that METAL DECKING ROOF S II SHOPS WITH "FEELING FIT" hes no notice of the revocation of higher powers. SQUASH & FITNESS CENTRE 4 (Makuer OVER WITH MEZZANINE. Elghalure of Witness Signature of Attorney Truitis Corner "No. 6 ~ 12" (0.03) F iname of Wilmoss Signature of Attorney (AWN) (1.59) 0063212 DUMARESQ

SURVEYOR'S REFERENCE: 60497 . 02L01 CHECKLIST

BY LAWS ADOPTED FOR THIS SCHEME

Table of mm

Plan Drawing only to appear in this

563368

DP

do 28.8.2000

