

Site Inspection Photos – 4559 Burley Griffin Way CUNNINGAR

Aerial Context Map showing Development Site on Lot 7017 DP 1301321 No. 4559 Burley Griffin Way Cunningar



Location of site inspection photos






Figure 1 - View North along existing Access Road– 29 March 2018



Figure 2 - View looking east over Development site from Access Road– 29 March 2018





Figure 4 - View South along Access Road to Racecourse and Airfield entrance – 29 March 2018



Figure 5 - View North to Burley Griffin Way from Development site (near south western boundary) – 24 January 2018



Figure 6 - View North to Burley Griffin Way from the Development Site – 24 January 2018



Figure 7 - View South towards Racecourse from Development Site (near south western corner)) – 24 January 2018




Figure 8 - View of Trees lining western boundary of the Development site – 24 January 2018



Figure 9 - View North along Access Road adjacent to south western corner of Development site



Figure 10 - View from northern boundary of Development Site looking west along Burley Griffin Way – 24 January 2018




Figure 11 - View from northern boundary of Development Site looking east along Burley Griffin Way – 24 January 2018



Figure 12 - View North along western boundary of Development Site to intersection of access road and Burley Griffin Way – 24 January 2018