
## **SCHEDULE OF CONSERVATION WORKS**

Burwood Uniting Church 134A Burwood Road, Burwood NSW

July 2019, Issue C





BURW	BURWOOD UNITING CHURCH, BURWOOD			
ISSUE	DESCRIPTION	DATE	ISSUED BY	
Α	Draft for Review	29/4/16	DM	
В	Issued for DA Submission	19/10/18	DM	
C	Issued for Resubmission	22/7/19	DM	

GBA Heritage Pty Ltd

Level 1, 71 York Street

Sydney NSW 2000, Australia

T: (61) 2 9299 8600

F: (61) 2 9299 8711

E: gba@gbaheritage.com

W: www.gbaheritage.com ABN: 56 073 802 730

ACN: 073 802 730

Nominated Architect: Graham Leslie Brooks

NSW Architects Registration 3836

## **CONTENTS**

1.0	INTRODUCTION	4
1.1	REPORT OVERVIEW	4
1.2	REPORT OBJECTIVES	4
1.3	HERITAGE SIGNIFICANCE	
2.0	PHOTOGRAPHS AND PLANS	6
3.0	CONSERVATION APPROACH	14
3.1	CONSERVATION PHILOSOPHY	14
3.2	CONSERVATION PROCESS	
3.3	INVESTIGATIONS AND REPORTS	15
3.4	COMPETENT DIRECTION AND SUPERVISION	15
3.5	CAREFUL APPROACH	15
3.6	NEW WORK AFFECTING HERITAGE FABRIC	16
3.7	A NOTE ON THE TOBIN VENTILATION SYSTEM	16
4.0	SCHEDULES	17
4.1	THE CHURCH: EXTERIOR	18
4.2	THE CHURCH : INTERIOR	
4.3	THE SCHOOL HALL : EXTERIOR	
4.4	THE SCHOOL HALL : INTERIOR	31
4.5	THE FENCE AND GATES	33

OUTLINE CONSERVATION METHODOLOGIES	34
PROTECTIVE WORKS	34
MAKE GOOD WORKS	34
REPAIR OF DAMAGE FROM REDUNDANT FIXINGS AND SERVICES	35
ROOFING	35
STONEWORK	36
BRICKWORK	.38
PLASTERWORK	.38
CONCRETE	39
TIMBERWORK	.39
METALWORK	39
LEADLIGHT AND STAINED GLASS	40
PAINTWORK	40
STORMWATER	41

5.0 5.1 5.2 5.3 5.4 5.5 5.6 5.7 5.8 5.9 5.10 5.11 5.12 5.13