

## **STATEMENT OF HERITAGE IMPACT**

Burwood Uniting Church

134A-134C Burwood Road and 29A-33A George Street, Burwood

Stage One / Concept Development Application

July 2019, Issue D



---

**134A-134C BURWOOD ROAD AND 29A-33A GEORGE STREET, BURWOOD**

---

ISSUE	DESCRIPTION	DATE	ISSUED BY
A	Preliminary Draft	4/4/16	DM
B	Draft for Review	9/2/18	DM
C	Issued for DA Submission	19/10/18	DM
D	Issued for Resubmission	22/7/19	DM

---

GBA Heritage Pty Ltd  
Level 1, 71 York Street  
Sydney NSW 2000, Australia  
T: (61) 2 9299 8600  
F: (61) 2 9299 8711  
E: [gba@gbaheritage.com](mailto:gba@gbaheritage.com)  
W: [www.gbaheritage.com](http://www.gbaheritage.com)  
ABN: 56 073 802 730  
ACN: 073 802 730

Nominated Architect: Graham Leslie Brooks - NSW Architects Registration 3836

# CONTENTS

<b>1.0</b>	<b>INTRODUCTION</b>	<b>5</b>
1.1	REPORT OVERVIEW	5
1.2	REPORT OBJECTIVES	5
1.3	METHODOLOGY AND STRUCTURE	5
1.4	SITE IDENTIFICATION	6
1.5	HERITAGE MANAGEMENT FRAMEWORK	6
1.6	REPORT LIMITATIONS	7
1.7	AUTHORSHIP	7
1.8	COPYRIGHT	7
<b>2.0</b>	<b>HISTORICAL SUMMARY</b>	<b>8</b>
2.1	BRIEF HISTORY OF THE LOCALITY	8
2.2	THE CONGREGATIONAL CHURCH	10
2.3	EARLY OWNERSHIP OF THE SITE	10
2.4	THE FIRST CHURCH (1869-1879)	12
2.5	REPLACEMENT CHURCH (1880)	12
2.6	EVOLUTION OF USE	14
2.7	THE ARCHITECT, THOMAS ROWE	15
<b>3.0</b>	<b>SITE DESCRIPTION</b>	<b>16</b>
3.1	URBAN CONTEXT	16
3.2	BUILDINGS ON THE SUBJECT SITE	18
3.3	THE CHURCH	19
3.4	THE SCHOOL HALL	22
3.5	THE FRONT FENCE AND GATES	25
3.6	CONDITION AND INTEGRITY	25
<b>4.0</b>	<b>ASSESSMENT OF CULTURAL SIGNIFICANCE</b>	<b>26</b>
4.1	INTRODUCTION	26
4.2	ESTABLISHED SIGNIFICANCE OF THE SUBJECT SITE	26
4.3	COMPARATIVE ANALYSIS	26
4.4	ANALYSIS OF CULTURAL SIGNIFICANCE	28
4.5	REVISED STATEMENT OF SIGNIFICANCE	29
4.6	GRADING OF SIGNIFICANCE	30
4.7	VIEWS	34
4.8	CURTILAGE ANALYSIS	36
4.9	ARCHAEOLOGICAL POTENTIAL	37
4.10	ESTABLISHED SIGNIFICANCE OF HERITAGE ITEMS IN THE VICINITY	37