

PROJECT DETAILS

JOB NUMBER	KE2515	CLEARANCE DATE	1 Dec 2020
CLIENT	AGH Demolition & Asbestos Removal	REPORT DATE	1 Dec 2020
CONTACT NAME & NUMBER	Brett Gibson - 0407243482		
SITE ADDRESS	360A Alderson Place, Tralee NSW 2620		
SCOPE OF CLEARANCE	Removal of visible non friable asbestos sheet debris and contaminated soil from AEC 6 and south west side of site. See attached plan.		
ASBESTOS CONTRACTOR	AGH Demolition & Asbestos Removal	SUPERVISOR	Tony Pustavrh
ASBESTOS ASSESOR	Ged Keane	LICENSE NUMBER	LAA001142
LEGISLATION	Asbestos removal clearance certificate issued under regulations 473 & 474 of the Work Health Safety Regulation 2011		

VISUAL CLEARANCE

	YES	NO	N/A
Did inspection of the removal area detailed above find no visible asbestos remaining as a result of the asbestos removal work carried out?	☒	☐	☐
Has all accessible non friable asbestos containing material been removed?	☒	☐	☐
Are photographs attached for all phases of the clearance inspection?	☒	☐	☐

CONCLUSION

A thorough a visual inspection after completion of the above scope of works at the site location stated above and found no visible asbestos residue from asbestos removal work in the area, or in the vicinity of the area, where the work was carried out. **Note: Asbestos may be buried at depth in AEC 6.**

The asbestos removal work area can now be dismantled and the area safely reoccupied.

Photographs from the site inspection are attached at Appendix A.

Ged Keane



Director & Principal Hygienist

APPENDIX A - PHOTOS



Removal area



Removal area



Removal area



Removal Area



Removal Area



Removal area

APPENDIX A - PHOTOS-1



Removal area



Removal area



Removal area



Removal Area



Removal Area



Removal area

APPENDIX B - SITE PLAN

