

	02 05/11/2015 J.G. 01 02/03/2015 J.G.		J.G.	H.H. LOT NUM		LOT NUMBE	BER AMENDED - SUBJECT LAND		
			J.G.	H.	Н.	TOP OF CONDUITS ADDED IN SELECTE MONITORING POINTS			D WA
	No. DATE SURVEYED				/N	DESCRIPTION			
CLIENT FULL TILT CONSTRUCTIONS PTY LTD									REF
PROPERTY No. 75 OLD PITTWATER ROAD, BROOKVALE									
D/	ATUM	A.H.D		SCALE	1:40	0 @ B1	DATE	06/02/2015	SHE
SI	JRVEY	^{ED} J.G.	I	DRAWN	H.H.		DWG No.	19372-03	RE

H.H. CORRECTION TO TOTAL SITE AREA


INVESTIGATION OF "DIAL BEFORE YOU DIG" UNDERGROUND SERVICES HAS BEEN MADE. DETECTION OF UNDERGROUND SERVICES IS NOT AN INTEGRAL PART OF THIS SURVEY. ALL RELEVANT AUTHORITIES SHOULD BE NOTIFIED PRIOR TO ANY EXCAVATION ON OR NEAR THE SITE

DEVELOPERS & EXCAVATORS MAY BE HELD FINANCIALLY RESPONSIBLE BY THE ASSET OWNER SHOULD THEY DAMAGE UNDERGROUND NETWORKS.

CARELESS DIGGING CAN: - CAUSE DEATH OR SERIOUS INJURY TO WORKERS AND THE GENERAL PUBLIC - INCONVENIENCE USERS OF ELECTRICITY, GAS, WATER AND COMMUNICATIONS - LEAD TO CRIMINAL PROSECUTION AND DAMAGES CLAIMS - CAUSE EXPENSIVE FINANCIAL LOSSES TO BUSINESS

- CUT OFF EMERGENCY SERVICES - DELAY PROJECT COMPLETION TIMES WHILE THE DAMAGE IS REPAIRED MINIMISE YOUR RISK AND DIAL BEFORE YOU DIG. TEL. 1100





J.G.

03 12/05/2016

40

BE PLANNED ON OR NEAR THE BOUNDARIES, THE BOUNDARIES SHOULD BE CLEARLY MARKED ON SITE.

NOTES:

2) ALL AREAS AND DIMENSIONS HAVE BEEN COMPILED FROM PLANS MADE AVAILABLE AT THE LAND TITLES OFFICE.

1) CAUTION: SHOULD ANY DEVELOPMENT OR CONSTRUCTION

- 3) ORIGIN OF LEVELS ON A.H.D. IS TAKEN FROM p.m. 8734 rl 13.73 a.h.d.
- 4) CONTOUR INTERVAL 0.25 METRE.
- 5) CONTOURS ARE INDICATIVE OF GROUND FORM ONLY. ONLY SPOT LEVELS SHOULD BE USED FOR CALCULATIONS OF QUANTITIES WITH CAUTION.
- 6) TREE SPREADS ARE DIAGRAMMATIC ONLY AND ARE NOT SYMMETRICAL.
- 7) UNDERGROUND (NON VISIBLE) SERVICE LINES HAVE BEEN SHOWN FROM "DIAL BEFORE YOU DIG" SERVICE AUTHORITY RECORDS & ARE DIAGRAMMATIC ONLY IN REGARD TO THEIR POSITION & WIDTH UNLESS STATED OTHERWISE.
- 8) SPOT LEVELS ARE ACCURATE.
- 9) BEARINGS SHOWN ARE ON M.G.A.-(MAP GRID of AUSTRALIA.)
- 10) THE POSITION OF THE EASTERN BOUNDARY ALONG THE WESTERN SIDE OF BROOKVALE CREEK HAS BEEN SCANNED FROM D.P. 204107 AND IS APPROXIMATE
- 11) PLANT AND INDUSTRIAL EQUIPMENT HAS NOT BEEN SURVEYED

